

Maintenance History (All work types) - FT232

Custom Date Range: 1/1/2023 - 4/14/2026

Work Order ID	Description	Direct Labor \$	Sublet Vendor Labor \$	Part \$	Total \$	Total Labor Hrs	Status Date
57378	1 - A SERVICE 2 - REPLACE BATTERIES	\$243.75	\$0.00	\$392.77	\$636.52	3.25	3/1/2023
57986	1 - CVIP 2 - ADJUST CLUTCH	\$487.50	\$0.00	\$21.84	\$509.34	6.50	4/5/2023
58375	1 - A SERVICE	\$318.75	\$0.00	\$99.74	\$418.49	4.25	4/26/2023
58875	1 - ENGINE SWAP	\$1,875.00	\$0.00	\$39.05	\$1,914.05	25.00	6/7/2023
59510	1 - A SERVICE	\$300.00	\$0.00	\$30.78	\$330.78	4.00	7/13/2023
60291	1 - A SERVICE 2 - REPLACE AXLE #1 LEFT SIDE SHOCK	\$262.50	\$0.00	\$155.68	\$418.18	3.50	8/22/2023
61016	1 - A SERVICE	\$225.00	\$0.00	\$42.66	\$267.66	3.00	10/6/2023
61777	1 - A SERVICE	\$187.50	\$0.00	\$76.72	\$264.22	2.50	11/16/2023
61899	1 - REPLACE AXLE #3 LEFT SIDE WHEEL SEAL	\$150.00	\$0.00	\$67.92	\$217.92	2.00	11/22/2023
62492	1 - A SERVICE	\$225.00	\$0.00	\$0.00	\$225.00	3.00	1/4/2024
63659	1 - A SERVICE	\$187.50	\$0.00	\$77.56	\$265.06	2.50	3/18/2024
63718	1 - CVIP	\$300.00	\$0.00	\$19.64	\$319.64	4.00	3/21/2024
64868	1 - A-SERVICE	\$318.75	\$0.00	\$60.72	\$379.47	4.25	5/27/2024
65776	1 - A SERVICE	\$337.50	\$0.00	\$81.75	\$419.25	4.50	7/2/2024
66856	1 - A SERVICE	\$187.50	\$0.00	\$47.17	\$234.67	2.50	8/22/2024
67566	1 - A SERVICE	\$187.50	\$0.00	\$81.75	\$269.25	2.50	10/1/2024
68105	1 - REPAIR HEADLIGHTS	\$112.50	\$0.00	\$0.00	\$112.50	1.50	10/29/2024
68308	1 - A SERVICE	\$337.50	\$0.00	\$33.63	\$371.13	4.50	11/12/2024
69153	1 - A SERVICE 2 - REPLACE LEFT SIDE BOX LIGHT	\$262.50	\$0.00	\$82.23	\$344.73	3.50	1/13/2025
69166	1 - SECURE DASH VALVE 2 - ADJUST CLUTCH	\$112.50	\$0.00	\$0.00	\$112.50	1.50	1/14/2025
69392	1 - REPLACE STARTER	\$112.50	\$0.00	\$560.66	\$673.16	1.50	1/22/2025
70600	1 - A SERVICE	\$187.50	\$0.00	\$34.80	\$222.30	2.50	4/2/2025
70722	1 - CVIP 2 - REPLACE AXLE #3 LEFT SIDE WHEEL SEAL	\$337.50	\$0.00	\$71.02	\$408.52	4.50	4/7/2025

71677	1 - A SERVICE 2 - REPAIR LIGHTS 3 - REPLACE AXLE #2 LEFT SIDE WHEEL SEAL	\$431.25	\$0.00	\$150.75	\$582.00	5.75	5/23/2025
72528	1 - ROTATE FUEL HOSE 2 - ADJUST CLUTCH 3 - REPLACE DRIVERS SEAT 4 - WELDING	\$281.25	\$0.00	\$72.77	\$354.02	3.75	7/10/2025
72582	1 - A SERVICE	\$187.50	\$0.00	\$35.65	\$223.15	2.50	7/16/2025
73455	1 - A SERVICE	\$187.50	\$91.75	\$84.78	\$364.03	2.50	8/29/2025
74171	1 - A SERVICE	\$187.50	\$84.41	\$37.40	\$309.31	2.50	10/15/2025
76507	1 - CARSTAR: PAINT	\$0.00	\$4,007.00	\$0.00	\$4,007.00	0.00	3/11/2026
75789	1 - CVIP 2 - REMOVE RADIO AND GPS 3 - REPAIR HOLES IN FRAME/LOOSE LINES 4 - REPLACE AXLE #2 AND #3 TORUQE RODS 5 - REPLACE ENGINE MOUNTS 6 - REPLACE AXLE #1 SHOCK BUSHINGS 7 - REPLACE AXLE #3 LEFT SIDE WHEEL SEAL	\$1,968.75	\$0.00	\$354.81	\$2,323.56	26.25	1/30/2026
76558	1 - CLEAR FINISH POLISHING: FULL TRUCK	\$0.00	\$1,199.00	\$0.00	\$1,199.00	0.00	4/15/2026
76548	1 - PHOENIX CUSTOM AUTO DESIGNS: SUPPLY AND INSTALL DECALS	\$0.00	\$137.95	\$0.00	\$137.95	0.00	4/15/2026
Totals:		\$10,725.00	\$9,486.69	\$2,814.26	\$23,025.95	143.00	