

A.H.M.S. Inc.
 Project Allocation Detail 04/01/2022 to 03/27/2026

R12-13
 MAY

Date	Description	Source	JE#	Amount	Cumulative
7273 trican opi 600 inspect					
5010 Materials					
10/21/2022	Quincie Oilfield Products	108177	J2897	839.85	839.85
Total 7273 trican opi 600 inspect				<u>839.85</u>	
7441 core completions gd 600 G016695					
5010 Materials					
04/26/2023	Resource Bearing Ltd	001796	J510	5,737.02	5,737.02
10/01/2023	Resource Bearing Ltd	001786	J3831	6,217.44	11,954.46
07/17/2024	Resource Bearing Ltd	002098	J1419	883.32	12,837.78
08/19/2024	Wajax Industrial Components LP	20241202	J1965	120.21	12,957.99
08/27/2024	ASA Alloys	I339695	J1912	177.50	13,135.49
				<u>13,135.49</u>	
Total 7441 core completions gd 600 G016695				<u>13,135.49</u>	
7442 core completions gd 600 G13766-3					
5010 Materials					
04/26/2023	Resource Bearing Ltd	001795	J511	5,737.02	5,737.02
10/01/2023	Resource Bearing Ltd	001786	J3831	6,217.44	11,954.46
08/19/2024	Wajax Industrial Components LP	20241202	J1965	120.20	12,074.66
08/27/2024	ASA Alloys	I339695	J1912	177.50	12,252.16
				<u>12,252.16</u>	
Total 7442 core completions gd 600 G13766-3				<u>12,252.16</u>	
8083 diamond valley change fluid end					
5010 Materials					
03/27/2025	Quincie Oilfield Products	116419	J4645	562.50	562.50
03/28/2025	Source Hose & Industrial LTD	sn1-2833	J4607	61.66	624.16
04/10/2025	Resource Bearing Ltd	002474	J223	3,412.66	4,036.82
				<u>4,036.82</u>	
Total 8083 diamond valley change fluid end				<u>4,036.82</u>	



DATE: **april 4 2023**
 Customer: **core**
 LAST UPDATED: **March 26, 2026**

TRIPLE

UNIT #	MAKE/MODEL	P.E.	F.E.	Placed on Unit:	P.O.#	W.O. #
	GD 600 C	13766-3				7442

DESCRIPTION OF WORK:

inspect power end, found covers and seals missing, all bearings damaged, fluid end cracked and missing parts, Estamite on repair \$ 32000.00 to \$34000.00 see other report.

CHECKLIST:

- Pinion
- Pinion Bearings
- Bull Gear
- Bull Gear Bearings
- Gearbox
- Crankshaft
- Main Bearings
- Connecting Rods
- Connecting Rod Bearings
- Connecting Rod Bushings
- Crossheads
- Wristpins
- Crosshead Guides
- Power End Seal Covers
- Power End Seals
- Pinion Seal
- Rotary Union Seal
- Rotary Union
- Tach Drive Adapter
- PLUNGERS
- Plunger Size
- PLUNGER STUDS
- Oil Lines

NOTES:

ok
replace
ok
replace
ok, missing pinion cover
some wear
replace
ok
replace
ok
replace 1
replace 1
ok
missing
missing
missing
replace
replace
na
missing
?
missing
replace damaged ones