



DATE June 26/26

KM 177908

HRS 1

UNIT NUMBER 5B440

COMPLAINT: second containment valves + hot over

CAUSE: \_\_\_\_\_

CORRECTION: low lights out Had to send header out to reset  
found leaking hub cap - Replaced + oil top up  
Replaced fire extinguisher on pup, not fully charged anymore  
Replaced head first axle service valve  
Replaced 1RHS tire's (dunks)  
Torqued every wheel I had off to 50ftlb

Stocked Parts:

4195 hub cap  
fire extinguisher  
BH229859 X1

Repairs done by

Compy B

Date:

June 26/26

Authorized by:

[Signature]

R14-23:32  
LEAD: PUP  
SEP



DATE JUNE 24, 2020

KM 177,908

HRS \_\_\_\_\_

UNIT NUMBER SB 440 A & B

COMPLAINT: NEED TO INSTALL A MANUAL VALVE FOR LEAD & PUP

CAUSE: \_\_\_\_\_

CORRECTION: \* I INSTALL THE MANUAL VALVE FOR THE LEAD & PUP. UPON INSTALLING THE MANUAL VALVE FOR THE PUP I CAN'T TO SEAL IT PROPERLY, WE TRIED IT A COUPLE OF TIMES AND HAD TO WELD IT BUT NO LUCK. WE SEND IT TO BEN'S FOR HIM TO RE-WELD IT. NOW IT IS OK AND WE INSTALL IT TO THE PUP. (MANUAL VALVE & THE COUPLERS)

\* I FABRICATE A BRACKET FOR THE MUDFLAPS AND MARKER LIGHT FOR THE LEAD, INSTALL THE MUDFLAP AND YELLOW 2 1/2 MARKER LIGHT.

\* REAR ~~TOP~~ ~~MARKER~~ TAIL LIGHT IS NOT WORKING I TESTED IT AND DOESN'T HAVE A POWER. I CHECK THE WIRE GOING BACK TO JUNCTION BOX AND FOUND OUT THAT SOME WIRING'S ARE CORRODED. I REMOVE THE CORRODED PART AND RECONNECT IT AND NOW IT IS OK. (LEAD)

\* UPON CHECKING ON THE PUP I NOTICE 1 ~~MARKER~~ LIGHT ON PASSENGER SIDE HAS A BROKEN LIGHT (RED ONE) I REMOVE AND REPLACE IT. NOW IT IS ALL OK.

|              |           |              |
|--------------|-----------|--------------|
| 61004        | 1pc.      | } LEAD & PUP |
| FG1014       | 1pc.      |              |
| TTFAAL4MT    | 2pcs.     |              |
| 401NA        | 3pcs.     |              |
| LED2500-12AP | 1pc.      | } LEAD       |
| PT6020       | 1pc.      |              |
| GR2500       | 1pc.      |              |
| LD276R       | 1pc - PUP |              |

Repairs done by JOHN MARTIN

Date: JUNE 24, 2020

Authorized by: [Signature]