

629-2
SEP

2006 Kenworth unit 93-088 Summary of recent MAJOR work completed

Date	Discription of Work	approx cost	In house repairs	Third Party	Third Part Invoice number
Jan 17 2024	Primer pump an\fd fule filter	77.06		Inland KW	75879RGP
Feb 19 2024	Install wiper motor and replacement arm.	638.14	No	CJ's Repair	4066
Feb 13 2024	wiper motor installed by CJ's	536.89	No	Inland KW	77546RGP
Jan 18 2024	Ignition Switch and SWMK MBL NID motor assembly	690.60	Yes		
Dec 23 2023	Wiper Idler	141.42	Yes		
Dec 20 2023	Wiper blade assembly	278.80	Yes		
July 28 2023	AC repairs	426.13	Yes		
June 14 2023	Kit Heat Exchanger	975.00	Yes		
April 17 2023	Throttle Pedal	679.83	Yes		
	Total	4,443.87			
	Price does not include shop labour if RTL did the repairs				