

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3405	Suspension	18/11/2025	18/11/2025	1,034,079	0	0		Blue Collar Diesel Batteries were isolated and a visual inspection confirmed excessive movement in the right-hand front suspension bush. Access required removal and safe draining of the RHS fuel tank. The seized bush could not be removed with a hydraulic puller, so it was carefully cut out using oxyacetylene without damaging the housing. The bore was cleaned, a new bush was pressed in and torqued to specification, and the fuel tank was refitted and reconnected. Final checks confirmed correct installation with no free play, and all suspension components were greased	\$1,907.87 1849

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-1804	C - 100k	11/11/2025	11/11/2025	1,033,146 26,073	0	0		Internal Workshop Completed "C" service.	\$0.00
R-3297	Coolant System	22/10/2025	22/10/2025	1,029,904	0	0		Internal Workshop Drained coolant from radiator, removed radiator shroud and radiator supports, removed surrounding hardware and radiator itself. Pressure tested radiator to confirm diagnosis - correct. Installed hardware onto new radiator, installed radiator and surrounding hardware, filled and burped cooling system, topped up coolant and pressure tested system to confirm there were no faults - none found. Tested all components - all in working condition.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3295	Coolant System	15/10/2025	15/10/2025	1,034,110	0	0		Internal Workshop Pressure tested cooling system and found coolant leaking from brittle bottom radiator hose. Drained coolant and installed new parts, filled coolant and burped system until thermostat opened, topped up coolant and pressure tested. Tested all components - all in working condition.	\$0.00
T-478	Drive	12/09/2025	12/09/2025	1,028,299	0	0		Internal Workshop Removed wheels, removed and repaired inner tire. Torqued wheel nuts to specification, tested all components - all in working condition.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-479	Drive	03/09/2025	03/09/2025	1,027,497	0	0		Internal Workshop Found 1st drive outer passenger side tire to be flat, removed and repaired punctured tire. Torqued wheel nuts to spec, tested all components - all in working condition.	\$0.00
R-1737	ringfeeder	07/02/2025	07/02/2025	1,024,251	0	0	941	had ring feeder repaired by archer mechanical	\$0.00
R-1736	Tarp	07/02/2025	07/02/2025	1,024,251	0	0	942		\$0.00
R-1385	fuel leak.	18/12/2024	18/12/2024	1,022,482	0	0	663		\$0.00
R-1225	tailgate	02/12/2024	02/12/2024	1,018,073	0	0	574		\$0.00
R-1224	guages	02/12/2024	02/12/2024			0	575		\$0.00
R-611	wheel nut indicators	10/09/2024	10/09/2024	1,008,456		0		Internal Workshop Replace all 60 missing wheel nut indicators	\$0.00
S-519	A - 5k	09/09/2024	09/09/2024	1,008,456 -1,996,416		0		Ely Cameron	\$0.00
S-518	C - 100k	02/09/2024	02/09/2024	1,007,073 1,007,073		0		Ely Cameron	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-576	Air System, tail gate	01/08/2024	01/08/2024	1,001,972		0		Orkhan Combe Found air operated ram seized Blow out with brake clean and compressed air Lubricate lock pin rail under rear bin	\$0.00
S-422	A - 5k	27/05/2024	27/05/2024	992,589 9,333	0	0		Internal Workshop Carry out A service on truck and dog	\$80.00
R-530	Chassis	17/05/2024	17/05/2024	991,117	0	0		Internal Workshop Remove and replace with new one	\$0.00
R-500	ELECTRICAL	09/04/2024	09/04/2024	986,973	0	0		Internal Workshop Replace unit with new	\$0.00
R-499	Hydraulics	03/04/2024	03/04/2024	986,274	0	0		Internal Workshop Clean and checked found loose fittings behind ringfeeder. Tightened and tested	\$0.00
S-390	A - 5k	19/03/2024	19/03/2024	983,256 18,265	0	0		Internal Workshop Complete A service and check brakes	\$0.00