

00240711

Invoice #:

306 Truck & Trailer Repair

Site 411 Comp 3 RR4 Saskatoon SK S7K 3J7 (306) 341-4300

shop@306truckrepair.ca

306truckrepair.ca

Technician: Parie Date:

7/14/24

	Y Knott Trucking Ltd	2008 Odomo VIN: Unit:	Pete eter: 905301	Dump Truck License:	
Hrs.	Labor Description				Total
30.0	Headgasket replaced liner protusion checked	i i	1		3,000.00
2.0	Air dryer replaced				200.00
Qty.	Part Description		Unit	Price	Total
1.0	Injector Testing		88	2.35	882.35
3.0	injector		85	2.94	2,558.82
1.0	Rad mounts		69	69.60	
1.0	Injector Cam retainer washer		12	122.35	
2.0	coolant hose clamps		14	14.73	
12.0	coolant		12	2.65	151.80
1.0	engine oil		23	6.13	236.13
1.0	engine oil filter		64.71		64.71
1.0	Air Dryer		46	0.53	460.53
-			Pa	arts Total:	4,575.75
Customer provided new head			La	Labor Total:	
	partie hew he	00	SI	nop Supplies:	224.00
			S	ub Total:	7,775.75
				ST (810903286RT0001): ST (7534951):	399.99 479.99
			Total:	8,879.73 Paid:	8,879.73
			547 E	Balance:	0.00

BALANCE is due upon reciept. FINANCE CHARGES will apply if balance is unpaid one month from closing date of statement. FINANCE CHARGE is computed by a periodic rate of 11/2% per month which is an ANNUAL PERCENTAGE RATE of 18% applied to the balance after deducting current payments and/or credits appearing on this statement. Balance will be charged to Credit Card on file unless prior arrangement is made. In the event Customer's account is sent to collections due to non-payment, Customer agrees to reimburse Company for all related costs and lawyers' fees.