

**Anarchy Mechanical Ltd**  
 #100 - 10609 79 Ave  
 CLAIRMONT, AB. T8X5G9  
 Phone: 780-814-8555 Fax: 780-814-8599

5394

Org. Est. # 006141

**J & G HAULING SERVICES LTD - RYAN BERNATH**  
 10274 85A ST  
 GRANDE PRAIRIE, AB T8X 0K2  
 Home 780-882-9943 ryan

2014 Peterbilt - 388 - Paccar MX-13 PCI 6 CYL  
 Lic # : A54336 Odometer In : 559586  
 Unit # : 102  
 VIN # : 1XPWDP9X2 ED238423  
 Engine Hrs In : 14150.6 Engine Hours Out : 0.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Shop Supplies		264.00		#1 DIFF - R&I Remove the drive line and diff, there was no oil found in diff. Had to steam housing and remove wheel hubs. Steam and inspect wheel ends. Inspect output shaft and bearings. All bearings, all need to be replaced. Pull output shaft, replace bearings and wheel end bearings. Install new diff and top up oil. Install new u-joint on stud shaft. Install new gasket and axles then torqued. Set brakes and torque wheels. Hazardous Material	2,640.00 105.60

Org. Estimate 1,185.03 Revisions 0.00 Current Estimate 1,185.03

Labor:	2,640.00
Parts:	264.00
HazMat:	105.60
SubTotal:	3,009.60
Tax:	150.48
Total:	3,160.08
Bal Due:	\$3,160.08

[ Payments - ]

Customer Number : 344

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. A mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is up to the supplier's discretion or one year which ever applies. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Labor will be charged unless covered by supplier for all warranty claims. Anarchy Mechanical Ltd. is only responsible for warranty of parts supplied and installed by Anarchy Mechanical Ltd. staff. Any and all progressive damage caused by continued operation, past component failure is the sole responsibility of the customer. Anarchy Mechanical Ltd. will cover workmanship for 30 days or 100 hours, unless otherwise stated on the original invoice.

\*\*\*YOUR WHEELS MUST BE RE-TORQUED AFTER 50KM. FAILURE TO DO SO COULD RESULT IN DAMAGE TO YOUR VEHICLE OR INJURY WHICH ANARCHY MECHANICAL WILL NOT BE HELD LIABLE FOR\*\*\*

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [info@aml.expert](mailto:info@aml.expert)

**Anarchy Mechanical Ltd**  
 #100 - 10609 79 Ave  
 CLAIRMONT, AB. T8X5G9  
 Phone: 780-814-8555 Fax: 780-814-8599

**4135**

Org. Est. # 004744

**J & G HAULING SERVICES LTD - RYAN BERNATH**  
 10274 85A ST  
 GRANDE PRAIRIE, AB T8X 0K2  
 Home 780-882-9943 ryan

2014 Peterbilt - 388 - Paccar MX-13 PCI 6 CYL  
 Lic # : Odometer In : 484689  
 Unit # : 102  
 VIN # : 1XPWDP9X2 ED238423  
 Engine Hrs In : 12087.0 Engine Hours Out : 0.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
REBUILT TRANSMISSION RTLO18918BPH	1.00	5,187.50	5,187.50	TRANSMISSION - R&I Removed transmission from unit and inspected. Found cracks starting to form on gears, a new transmission is needed. When removing yolk to swap, yolk was seized. Replaced old yoke with a new one. Temp sensor was seized. Installed a new sensor. PTO gears were damaged, replaced PTO. Shimmed as necessary to achieve 0.009" backlash. Installed a new transmission and connected components as required. Filled transmission with new oil. Adjusted clutch, attempted to adjust linkage for free play and found the linkage was stripped. Replaced linkage and adjusted. Test drive unit and checked over - OK.	2,201.00
SCREW-TAPPING TRUSS XREC HWC07496	12.00	3.75	45.00	TRANSMISSION SERIAL# 13586	
NUT-SPEED U 1/4-20X0.03-0 HWC07100	12.00	6.48	77.76		
18.9L CHEV.DELO SYN.TRAN.SAE CHE22303905	1.00	357.24	357.24	CLUTCH - R&I Replaced the clutch and clutch brake. The clutch release bearing was destroyed from the clutch brake.	130.20
PTO ASSY 2 GEAR 8BOLT 225TQ 489XQAHX-A3XK	1.00	1,531.26	1,531.26	CLUTCH HOUSING - R&I Transferred housing to new transmission.	248.00
YOKE - END HALF ROUND 250-4-271-1	1.00	328.73	328.73	FLYWHEEL-R&I Remove flywheel to have resurfaced and re-installed.	62.00
SENDER-TEMPERATURE Q21-1002	1.00	166.19	166.19	FLYWHEEL GRIND	126.00
CLUTCH-15.5" 2050 TQ 7 SP 108925-25AM	1.00	1,346.25	1,346.25	CRANKSHAFT OIL SEAL - R&I - REAR Extracted leaking rear engine seal and installed a new seal.	224.75
LEVER-CLUTCH SHAFT E55-6020	1.00	115.08	115.08	Hazardous Material	85.98
LINK-CLUTCH LWR AL HEXBAR 06-01150-360	1.00	50.94	50.94		
END ELASTOMERIC ROD J21270-14	1.00	79.60	79.60		
END TIE ROD, MALE 06-00984	1.00	100.19	100.19		
SEAL RING-CRANKSHAFT REAR 1876190PE	1.00	237.05	237.05		
Shop Supplies			299.20		

Email Address: [info@aml.expert](mailto:info@aml.expert)

**Anarchy Mechanical Ltd**  
 #100 - 10609 79 Ave  
 CLAIRMONT, AB. T8X5G9  
 Phone: 780-814-8555 Fax: 780-814-8599

4135

Org. Est. # 004744

**J & G HAULING SERVICES LTD - RYAN BERNATH**  
 10274 85A ST  
 GRANDE PRAIRIE, AB T8X 0K2  
 Home 780-882-9943 ryan

2014 Peterbilt - 388 - Paccar MX-13 PCI 6 CYL

Lic #: Odometer In : 484689  
 Unit #: 102  
 VIN #: 1XPWDP9X2 ED238423  
 Engine Hrs In : 12087.0 Engine Hours Out : 0.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

Org. Estimate: 13,649.92 Revisions: 0.00 Current Estimate: 13,649.92

Labor:	2,865.95
Parts:	9,921.99
Sublet:	126.00
HazMat:	85.98

SubTotal:	12,999.92
Tax:	650.00
Total:	13,649.92
Bal Due:	\$13,649.92

[Payments - ]

Customer Number : 344

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 1000 hours whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Anarchy Mechanical is only responsible for warranty of parts supplied and installed by Anarchy Mechanical staff. Any and all progressive damage caused by continued operation, past component failure is the sole responsibility of the customer.

\*\*\*YOUR WHEELS MUST BE RE-TORQUED AFTER 50KM. FAILURE TO DO SO COULD RESULT IN DAMAGE TO YOUR VEHICLE OR INJURY WHICH ANARCHY MECHANICAL WILL NOT BE HELD LIABLE FOR\*\*\*

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [info@aml.expert](mailto:info@aml.expert)