# **Core Diesel Maintenance Pty Ltd**

Shed 1 Four Mile Road East Maryborough QLD 4650 ABN 32 162 144 014 Tel: 07 4184 9445

Email: accounts@corediesel.com.au Website: www.corediesel.com.au



"The Diesel Professionals"

**Mobile** 

0407 160 932

### **Tax Invoice**

14,773 Inv. No. 24/1/25 Order No. Xq34 Sales ID **Date Client Details Vehicle Details** Rego: XQ34QZ Odo: 302719 **Ref:** 14/08/2024 Cornwall Logging Pty Ltd Make/Model: VOLVO FM12 Lot 1 Industrial Ave Type: Commercial Year: 2021 Maryborough Qld 4650 VIN#: YV5XG40G3MD212199 Hours: 7082 ABN: 11 010 509 985

Work Done

Work

07 4121 5211

#### **Truck Laptop Diagnosis Scan**

C628

Dor - 20/01/2025

Account

Labour Repairs -

Complaint: Abs Malfunction - Check Wheel Bearing Error

Home

Cause: Wheel Bearing Failure, Brake Pads Worn Out

#### Correction:

Removed And Stripped Down All 4 Front Wheels. Removed And Replaced All 4 Pads And Both Rotors On Second Steer Axle. Removed And Stripped Down All 4 Steer Callipers. Re Kit Callipers And Refit. Removed Rh Second Steer Stub Axle. Replace Stub Axle, King Pin And Hub Assembly. Reassembled All Brakes. Replaced Damaged Backing Plates. Fit Hub Caps With New O'rings. Refit Wheels. Torqued To Spec. Started And Run Truck. Connected Scan Tool, Checked And Cleared Fault Codes. Cleared Service Reminder. Test Drove And All Tested Ok. Degreased And Washed Down Truck.

### Services, Parts & Labour

#### Mechanical

Description	Unit Price	Tax	Total (Inc)
Labour Repairs	\$6,750.00	\$675.00	\$7,425.00
Brake Pad Kit	\$425.00	\$85.00	\$935.00
Slide Kit Bushes	\$148.43	\$59.37	\$653.08
Hub	\$2,801.54	\$280.15	\$3,081.69
Bearing	\$1,053.21	\$315.96	\$3,475.59
Shield	\$195.75	\$39.15	\$430.65
Shield	\$195.75	\$39.15	\$430.65
Wheel Speed Sensor	\$162.33	\$16.23	\$178.56
King Pin Kit	\$653.02	\$65.30	\$718.32
Steering Knuckle	\$3,477.44	\$347.74	\$3,825.18
Brake Disc Kit	\$508.90	\$101.78	\$1,119.58

Seal	\$45.34	\$18.13	\$199.48
O Ring	\$30.08	\$12.03	\$132.35
Freight Charge	\$268.18	\$26.82	\$295.00
Workshop Consumables/ Waste Levy	\$17.09	\$1.71	\$18.80
Degrease / Wash Down Engine Bay/ Wash Down Vehicle	\$13.91	\$1.39	\$15.30
		\$2,084.91	\$22,934.23

#### Fixed Price

Description	Unit Price	Tax	Total (Inc)
Truck Laptop Diagnosis Scan	\$93.00	\$9.30	\$102.30
Equipment Usage		Included	
		\$9.30	\$102.30

## **Vehicle Report**

### 21/01/24

### **Parts Requried**

- 4 X Brake Pad Kits
- 4 X Caliper Slide Kits
- 2 X Rotors
- 1 X Full Hub Assy Rh Second Steer
  1 X Steering Knuckle Rh Second Axle
  1 X Set Of Backing Plates
  1 X Abs Sensor

- 3 X Wheel Brg Kits
- 4 X Hub Cap Ö'rings
- 4 X Wheel Brg Seals 1 X King Pin Kit

Financial Summary					
Total (Ex. Tax)	\$20,942.32	Terms	30 days		
Tax Total	\$2,094.21	Paid	\$0.00		
Rounding	\$0.02				
Total (Inc. Tax)	\$23,036.55	Balance	\$23,036.55		

# Thank You For Supporting A Local Business!

Bsb: 124 080 A/c: 21948359