



Box 129  
 Highway 6 & 22  
 Southey, SK S0G 4P0  
 Phone: 306-726-2155  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> <b>Invoice Date:</b> 8/27/2024 <b>Location:</b> <b>Work Order Number:</b> <b>Payment Type:</b>  <b>Page:</b> 1 of 5
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2017 JD 615P PICKUP PLATFORM		1H00615PAH0795446	1H00615PAH0795446	

**/HEADER615P F Internal**

COMPLAINT:  
 01 GREENLIGHT SERVICE INSPECTION HEADER

CORRECTION:

<b>Labor: \$249.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$249.00</b>
------------------------	----------------------	-------------------------	---------------------	----------------------------

**/GLOPCLEAN615P Internal**

COMPLAINT:  
 02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:



Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	28.80	28.80	\$28.80	N

<b>Labor: \$480.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$28.80</b>	<b>Sub-Total: \$508.80</b>
------------------------	----------------------	-------------------------	----------------------	----------------------------



**Gen3- Internal**

COMPLAINT:  
 03 ADJUST BELT TRACKING/ LACING IS STARTING TO RUN A LITTLE SIDEWAYS

CORRECTION:

ADJSUTED BELT TENSION AND THAT SEEMED TO MAKE THE TRACKING ISSUE BETTER, RAN HEADER AFTER AND EVERYTHING SOUNDED GOOD AND FUNCTIONED AS IT SHOULD, NO LOUD NOISE OR ANYTHING

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N

<b>Labor: \$708.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$42.48</b>	<b>Sub-Total: \$750.48</b>
------------------------	----------------------	-------------------------	----------------------	----------------------------



Box 129  
 Highway 6 & 22  
 Southey, SK S0G 4P0  
 Phone: 306-726-2155  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> <b>Invoice Date:</b> 8/27/2024 <b>Location:</b> <b>Work Order Number:</b> <b>Payment Type:</b>  <b>Page:</b> 2 of 5
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2017 JD 615P PICKUP PLATFORM		1H00615PAH0795446	1H00615PAH0795446	

**/7010A615P F Internal**  
 COMPLAINT:  
 04 PICKUP TEETH REPLACE

CORRECTION:  
 replaced 5 pick up teeth

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
A-1000378	Bolt W/Nut	1.00	0.63	0.63	\$0.63	N
H86248	FINGER	5.00	4.01	4.01	\$20.05	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
<b>Labor: \$53.10</b>		<b>Parts: \$20.68</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$3.19</b>
						<b>Sub-Total: \$76.97</b>

**/142149615P F Internal**  
 COMPLAINT:  
 05 REMOVE AND REPLACE PICK UP WHEEL BEARINGS

CORRECTION:  
 INCLUDED R&R WHEEL  
 popped wheel off then knocked bearings out, after i buffed inside of bearing house to clean it up, then i installed the new bearing  
 after i reinstalled wheels back on to the header

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AM102888	Ball Bearing	4.00	32.43	32.43	\$129.72	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
<b>Labor: \$88.50</b>		<b>Parts: \$129.72</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$5.31</b>
						<b>Sub-Total: \$223.53</b>



Box 129  
 Highway 6 & 22  
 Southey, SK S0G 4P0  
 Phone: 306-726-2155  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 8/27/2024	<b>Location:</b> [REDACTED]	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> [REDACTED]	<b>Page:</b> 3 of 5
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2017 JD 615P PICKUP PLATFORM		1H00615PAH0795446	1H00615PAH0795446	

**/120637615P Internal**  
 COMPLAINT:  
 06 TENSION FEED DRUM DRIVE CHAIN

CORRECTION:  
 adjusted tension on feaddrum

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
<b>Labor: \$70.80</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$4.25</b>	<b>Sub-Total: \$75.05</b>		

**/170495615P F Internal**  
 COMPLAINT:  
 07 LUBRICATE AUGER DRIVE CHAIN

CORRECTION:  
 LUBED AUGER DRIVE CHAIN

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
<b>Labor: \$44.25</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.66</b>	<b>Sub-Total: \$46.91</b>		

**/140621615P F Internal**  
 COMPLAINT:  
 08 GREASE HEADER

CORRECTION:  
 GREASED ENTIRE HEADER

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129  
 Highway 6 & 22  
 Southey, SK S0G 4P0  
 Phone: 306-726-2155  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/27/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 4 of 5
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2017 JD 615P PICKUP PLATFORM		1H00615PAH0795446	1H00615PAH0795446	

<b>/140621615P F Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.50	3.50	\$3.50	N
<b>Labor: \$58.41</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.50</b>	<b>Sub-Total: \$61.91</b>	

**/940010615P F Internal**  
 COMPLAINT:  
 09 CALIBRATE HEADER

CORRECTION:  
 CALIBRATED HEADER



<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------





Box 129  
 Highway 6 & 22  
 Southey, SK S0G 4P0  
 Phone: 306-726-2155  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone:  
Prv Phone:

Bus Phone:  
Prv Phone:

Invoice Number:  
 Invoice Date: 8/27/2024  
 Location:  
 Work Order Number:  
 Page: 5 of 5

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD 615P PICKUP PLATFORM		1H00615PAH0795446	1H00615PAH0795446	

/940010615P F Internal							
SEVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N	
<b>Labor: \$88.50</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.31</b>	<b>Sub-Total: \$93.81</b>			

Customer PO No:  
 Tax Exempt No:  
 Advisor:

<b>Labor:</b>	\$1,840.56
<b>Parts:</b>	\$150.40
<b>OL&amp;M:</b>	\$0.00
<b>Misc:</b>	\$95.50
<b>Grand Total:</b>	\$2,086.46

\*\*\* DOCUMENT COPY \*\*\*

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	147504			USED AG EQUIPMENT
06 40	382	1	774569			INTERNAL LABOR-AG
00 00	178	16	774569			WORK IN PROCESS PARTS -MJ
06 40	482	1	774569			COS INTERNAL LABOR-AG
06 40	544	1	774569			SUPPLIES EXPENSE
06 30	366	2	774569			JD PARTS-COUNTER
00 00	166	6	774569			JD PARTS-MOOSE JAW
06 30	466	2	774569			JD PARTS-COUNTER

**TERMS AND CONDITIONS**

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: .....Date: .....