



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 1 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

Gen1- Internal

COMPLAINT:
01 CHECK OVER FOR SLAES

CORRECTION:
2108 SEP HRS 2/26/2025

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	56.82	56.82	\$56.82	N
Labor: \$946.95	Parts: \$0.00	OL&M: \$0.00	Misc: \$56.82	Sub-Total: \$1,003.77		

/150214S680 Internal

COMPLAINT:
02 CLEAN AND PAINT BURNT FEED ACCELERATOR PULLEY

CORRECTION:
TOOK BELTS OF THEN CLEANED PULLEY UP THEN I PAINTED IT ONCE THE PAINT WAS DRY I DID ONE MORE COAT THEN REINSTALLED THE BELTS ONCE SECOND COAT WAS DRY

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY25624	Paint Ag/CCE Green Spray Bomb	1.00	23.54	23.54	\$23.54	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF25	ENVIRO FEE	1.00	0.25	0.25	\$0.25	N
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
Labor: \$44.25	Parts: \$23.54	OL&M: \$0.00	Misc: \$2.91	Sub-Total: \$70.70		

/101711501S680 Internal

COMPLAINT:
03 REPLACE RIGHT HAND SIDE REVERSER SHAFT BEARING

CORRECTION:



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/31/2025 Location: 06 Work Order Number: Payment Type: Account Page: 2 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/101711501S680 Internal

PULLED SHIELD OF THEN UNIDID TENSION ON DRIVE CHAIN , THEN PULLED THE GEAR OFF THE SHAFT, IT WAS SEIZED SO IT TOOK A LITTLE BIT OF SOAKING AND TAPPING TO GET IT OFF BUT I GOT IT OFF THEN I UNIDID THE LOCK COLLAR AND PULLED IT OFF THEN UNIDID THE 3 BOLTS RETAINING THE BEARING AFTER THAT WAS DONE I PULLED BEARING OFF AND REPLACED WITH NEW ONE AND REINSTALLED EVERYTHING ELSE IN REVERSE ORDER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH231479	BEARING WITH HOUSING	1.00	374.95	374.95	\$374.95	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
Labor: \$442.50		Parts: \$374.95		OL&M: \$0.00		Misc: \$26.55
						Sub-Total: \$844.00

/160041S680 Internal

COMPLAINT:
 04 REPLACE SMALL COUPLING IN MULTI COUPLER (1 SMALL AND 1 LARGE)

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE60983	Multicoupler Combine Side 1/2"	1.00	301.61	301.61	\$301.61	N
AXE60984	Multicoupler Combine Side 3/8"	1.00	271.82	271.82	\$271.82	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$573.43		OL&M: \$0.00		Misc: \$5.31
						Sub-Total: \$667.24

/15172S680 Internal

COMPLAINT:
 05 REPLACE FRONT FEEDER HOUSE SHIELD

CORRECTION:

TOOK SIDE OFF THEN TOOK TOP COVER OF THEN INSTALLED NEW COVER AND REINSTALLED SIDES



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/31/2025 Location: 06 Work Order Number: Payment Type: Account Page: 3 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/15172S680 Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE13354	DEFLECTOR.	1.00	304.32	304.32	\$304.32	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N

Labor: \$265.50 Parts: \$304.32 OL&M: \$0.00 Misc: \$15.93 Sub-Total: \$585.75

/10180250S680 Internal

COMPLAINT:
 06 LEVEL, ADJUST AND CALIBRATE CONCAVES

CORRECTION:
 PLACE ROTOR GEARCASE IN NEUTRAL.REMOVE ROTOR COVERS.LEVEL CONCAVE.
 LEAVELED AND CLAIBRATED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N

Labor: \$221.25 Parts: \$0.00 OL&M: \$0.00 Misc: \$13.28 Sub-Total: \$234.53

GEN7- Internal

COMPLAINT:
 07 WELD CRACKS IN "Z" BAR SUPPORT GUSSETS

CORRECTION:
 LOWERD CONCAVE THEN PULLED Z BAR OFF, TOOK IT OVER TO THE WELDER AND CLEANED THE CRACKED AREA UP
 THEN I WELDED IT AND THEN CLEANED IT UP A BIT ONCE IT WAS COOLED DOWN I PAINTED IT UP, THEN REINSTALLED Z
 BAR ONTO THE CONCAVE AND TIGTEND UP TO SPEC

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 3/31/2025	Location: 06	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: Account	Page: 4 of 15
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

GEN7- Internal

11M7017	Cotter Pin M3.2 X 32	2.00	0.56	0.56	\$1.12	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N

Labor: \$354.00 Parts: \$1.12 OL&M: \$0.00 Misc: \$21.24 Sub-Total: \$376.36

GEN8- Internal

COMPLAINT:

08 STRAIGHTEN REAR SHOE AUGER BEARING SUPPORT (BENT & HOLDING OUTER RIGHT HAND AUGER BACK FROM PROPER MESH AT DRIVE GEAR)

CORRECTION:

TOOK THE 4 BOLTS OUT HOLDING THE SHOE AUGER IN, THEN I PULLED THE AUGER OUT, AFTER I CLEANED UP THE BUILT UP STRAW THAT WAS IN BEHIND THE SHOE AUGER THEN I PLAYED WITH GETTING THE ARM STRAIGHT IT TOOK SOME TIME I HAD TO HEAT IT UP AND BENT IT BACK IN A COUPLE SPOT BUT I GOTTA IT AS GOOD AS YOU COULD GET IT THEN I REINSTALLED THE AUGER AND TIGTEN IT UP THEN I WENT AND MADE SURE THE BEVEL GEARS WERE IN MESH PROPELRY AND MADE SURE THAT THE GEARS WERE GAPPED ENOUGH

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N

Labor: \$354.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$21.24 Sub-Total: \$375.24

/110081S680 Internal

COMPLAINT:

10 R&R SIEVE AND CHAFFER TO CHECK FOR CRACKS

CORRECTION:

TOOK A COUPLE COVERS OFF THEN I PULLED SIEVE AND CHAFFER, THEN I BLEW THEM OFF ONCE THE WERE CLEANED I INSPECTED FOR CRACKS THEN I WENT IN THE COMBINE AND MADE SURE THE FRAMES WASN'T CRACKED, AFTER I REINSTALLED THE SEIVE AND CHAFFER AND CALIBRATED, THEN I INSTALLED ANY COVER I HAD TO TAKE OFF

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 5 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/110081S680 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
Labor: \$531.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$31.86	Sub-Total: \$562.86	

GEN11- Internal
 COMPLAINT:
 11 WELD CRACKING AT RIGHT HAND CHOPPER LIFT ACTUATOR MOUNT

CORRECTION:
 LIFTED CHOPPER UP A LITTLE THEN GOT A RACHETS STARP AND HAD IT SO IT WAS LIFTING UP A LITLLE ON THE CHOOPER TO ALLOW ME TO PULL THE PIN OUT, I RETRACTED THE ACTUATOR THEN I CLEANED THE SURFACE UP, THEN BROUGHT THE WELDER OVER, WELDED UP THE CRACK THEN CLEANED AREA UP, AFTER I PAINTED IT ONCE THE PAINT WAS DRY I DID ONE MORE COAT THEN REINSTALLED THE ACTUATOR

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43	

GEN12- Internal
 COMPLAINT:
 12 STRAIGHTEN TWISTED ENGINE/GULL WING MOUNTING FRAME SUPPORT

CORRECTION:
 UNWID WIRE HARNESS ON LIGHT, THEN TOOK THE HARDWARE OUT OF THE BRACKETS HOLDING THE GULL WING ON THEN TOOK THE SHOOKS OFF AFTER I HAD SOMEONE HELP ME TAKE THE GULL WING OFF THEN I STARTED BENDING THE BRACKET BACK, HAD TO HEAT IT UP AND BEND IT BACK, TOOK A BIT TO GET IT THERE BUT I WAS ABLE TO GET IT BENT BACK THEN I HAD SOMEONE HELP ME THROW THE GULL WING BACK ON THEN I STARTED REISNATLLED THE BRACKETS AND THE SHOCKS AS I WAS DOING THAT I NOTICE THAT IT WAS STARTING TO BEND BACK TO HOW IT WAS ORIGINALLY, EVERY TIME THE GULL WING WOULD MOVE IT WOULD BEND DOWN A BIT MORE, TOOK THE GULL WING OFF THEN HAD GAVIN WELD A CHUNK OF STEAL ON THE TOP TO KEEP IT FROM BENDING FORWARD THEN PAINTED IT UP AFTER IT WAS DONE I REISNATLLED THE GULL WING GOT THE SHOCKS ON ADJUSTED A BIT TO GET GULL WING STRAIGHT WITH THE OTHER THEN I TIGHTENED UP THE BRACKETS AFTER I REISNATLLED THE WIRING HARNESS FOR THE LIGHT AND MADE SURE THE GULL WING WOULD OPEN AND CLOSED AND LATCH PROPELRY





Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 6 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

GEN12- Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY25624	Paint Ag/CCE Green Spray Bomb	1.00	23.54	23.54	\$23.54	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	63.72	63.72	\$63.72	N
Labor: \$1,062.00		Parts: \$23.54	OL&M: \$0.00	Misc: \$63.72	Sub-Total: \$1,149.26	

GEN13- Internal

COMPLAINT:
 13 CALIBRATE MOISTURE METER TEMPERATURE SENSOR

CORRECTION:
 CALIBRATED MOISTURE METER TEMP SENSOR

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$93.81	

/110015S680 Internal

COMPLAINT:
 14 ADJUST CLEAN GRAIN PADDLE CHAIN

CORRECTION:
 ADJUSTED CLEAN GRAIN PADDLE CHAIN

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.12	2.12	\$2.12	N
Labor: \$35.40		Parts: \$0.00	OL&M: \$0.00	Misc: \$2.12	Sub-Total: \$37.52	



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/31/2025 Location: 06 Work Order Number: Payment Type: Account Page: 7 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/142820S680 Internal

COMPLAINT:

15 REPLACE RETHRESHER IDLER SPROCKETS (TENSIONER SPROCKET)

CORRECTION:

REPLACED IDLER SPROCKETS, PULLED COVER OFF THEN UNIDID TENSION AFTER I TOOK BOTH SPROCKETS OFF AND THEN INSTALLED NEW ONES AND TIGHTEND UP THEN I REINSTALL THE CHAIN AND TENSIONED UP, THEN REINSTALLED THE COVER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
A-AH89428	Idler Sprocket	2.00	67.27	67.27	\$134.54	N
H114395	SPACER	1.00	8.33	8.33	\$8.33	N
H216427	Spacer	1.00	20.80	20.80	\$20.80	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	6.37	6.37	\$6.37	N
Labor: \$106.20		Parts: \$163.67		OL&M: \$0.00		Misc: \$6.37
						Sub-Total: \$276.24

GEN16- Internal

COMPLAINT:

16 REPLACE MISSING BUBBLE UP AUGER CLOSURE CLAMP

CORRECTION:

REPLACED MISSING LATCH, INSTALLED LATCHED ON TO BRACKET THEN TIGHTEND UP

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7081	Cotter Pin M2.4 X 20	2.00	0.41	0.41	\$0.82	N
14M7550	Hex Lock Nut M6	2.00	1.53	1.53	\$3.06	N
H161342	LEVER	1.00	58.86	58.86	\$58.86	N
H161346	U-BOLT	1.00	14.42	14.42	\$14.42	N
H161581	PIN	1.00	18.29	18.29	\$18.29	N



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 8 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

GEN16- Internal

RV810A	Pin Fastener	1.00	9.06	9.06	\$9.06	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N

Labor: \$88.50 Parts: \$104.51 OL&M: \$0.00 Misc: \$5.31 Sub-Total: \$198.32

/10180140S680 Internal

COMPLAINT:

17 REPLACE THRESHING SEPARATOR ELEMENTS (1 MATCHED SET)(BROKEN ELEMENT 4TH ROW FROM FRONT)

CAUSE:

lowered concave then pulled z bar out, then i changed the broken row of element's, took hardware out then pulled old element's out then i put locktight on a new bolt and started it then installed the other three and tighten up then did the same for the other 2 then i torqued to spec

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH216677	Threshing Elements Std Rows 3-5	1.00	556.79	556.79	\$556.79	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N

Labor: \$221.25 Parts: \$556.79 OL&M: \$0.00 Misc: \$13.28 Sub-Total: \$791.32

/120014S680 Internal

COMPLAINT:

18 GREASE COMBINE

CORRECTION:

GREASED COMBINE

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 9 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/120014S680 Internal
 TY6341 SD POLYUREA GREASE 1.00 10.87 10.87 \$10.87 N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N

Labor: \$177.00 Parts: \$10.87 OL&M: \$0.00 Misc: \$10.62 Sub-Total: \$198.49

/110006S680 Internal
 COMPLAINT:
 19 CLEAN CAB AND RECIRC. FILTERS AND PLASTIC GRATE

CORRECTION:
 CLEANED FILTERS AND GRATE

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N

Labor: \$88.50 Parts: \$0.00 OL&M: \$0.00 Misc: \$5.31 Sub-Total: \$93.81

/120060S680 Internal
 COMPLAINT:
 20 REPLACE ENGINE AIR FILTERS

CORRECTION:
 REPLACED ENGINE AIR FILTERS AND MARKED WITH HOURS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE11090	Primary Air Filter	1.00	462.31	462.31	\$462.31	N
HXE11091	Secondary Air Filter	1.00	326.21	326.21	\$326.21	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind





Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 10 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/120060S680 Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N	
Labor: \$88.50		Parts: \$788.52		OL&M: \$0.00		Misc: \$5.31	
						Sub-Total: \$882.33	

/120000S680 Internal
 COMPLAINT:
 21 CHANGE ENGINE OIL AND FILTER

CORRECTION:
 DRAINED AND CHANGED ENGINE OIL



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
RE572785	Engine Oil Filter	1.00	151.62	151.62	\$151.62	N	
TY26673	3.78L 15W40 PLUS 50 II	1.00	37.78	37.78	\$37.78	N	
TY26674	946ML 15W40 PLUS 50 II	2.00	9.92	9.92	\$19.84	N	
TY26679	18.9L 15W40 PLUS 50 II	2.00	170.86	170.86	\$341.72	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N	
EF15	ENVIRO FEE	2.00	0.15	0.15	\$0.30	N	
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N	
EF50	ENVIRO FEE	1.00	0.50	0.50	\$0.50	N	
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N	
Labor: \$132.75		Parts: \$550.96		OL&M: \$0.00		Misc: \$15.77	
						Sub-Total: \$699.48	

/120018S680 Internal
 COMPLAINT:
 22 REPLACE FUEL FILTERS, AND CLEAN FUEL PRE-SCREEN



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 11 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/120018S680 Internal
 CORRECTION:
 REPLACED FILTERS AND CLEANED BOWLS AND PRE SCREEN

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ112918	Secondary Engine Fuel Filter (Long)	1.00	236.20	236.20	\$236.20	N
DZ130550	Primary Engine Fuel Filter	1.00	232.48	232.48	\$232.48	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$468.68		OL&M: \$0.00		Misc: \$9.97
						Sub-Total: \$611.40

/1007009S680 Internal
 COMPLAINT:
 23 REPLACE HYDRAULIC FILTERS

CORRECTION:
 REPLACED HYD FILTERS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
A52523	Ring	1.00	26.30	26.30	\$26.30	N
AH128449	Hydraulic Oil Filter	1.00	147.41	147.41	\$147.41	N
AN207368	Hydraulic Oil Filter Element	1.00	195.07	195.07	\$195.07	N
AXE12964	Hydraulic Oil Reservoir Filter	1.00	177.71	177.71	\$177.71	N
N309233	O-Ring	1.00	28.00	28.00	\$28.00	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	3.00	1.00	1.00	\$3.00	N



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 12 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/1007009S680 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$574.49	OL&M: \$0.00	Misc: \$10.97	Sub-Total: \$718.21	

/120512S680 Internal
 COMPLAINT:
 24 CHECK AND TOP ALL FLUIDS

CAUSE:
 checked fluids and topped up

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	6.90	6.90	\$6.90	N
Labor: \$115.05		Parts: \$0.00	OL&M: \$0.00	Misc: \$6.90	Sub-Total: \$121.95	

/140486S680 Internal
 COMPLAINT:
 25 ADJUST ALL BELTS AND CHAINS TENSIONS

CORRECTION:
 ADJUSTED ALL BELTS AND CHAINS TENSION

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62	

/110377S680 Internal
 COMPLAINT:



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/31/2025 Location: 06 Work Order Number: Payment Type: Account Page: 13 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/110377S680 Internal
 26 RERUN AFTER REPAIRS

CORRECTION:
 RAN COMBINE WITH WADE , COMBINE RAN GOOD OTHER THEN THE VIBRATION FROM THE ROTOR, WADE WAS THINKING ALL YOU MIGHT HAVE TO DO IS CLEAN THE ELEMENTS OUT

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62		

GEN27- Internal
 COMPLAINT:
 27 DIAGNOSE VIBRATION ON ROTOR AFTER ELEMENT IS REPLACED COULD BE THE COUNTER SHAFT OR BEARING

CORRECTION:
 CLEANED BEHIND RUB BARS, RAN THE COMBINE AND STILL SHOOK, CHECKING ROTOR BEARING, ROTOR BEARING WAS BAD, REPLACED IT. RE RAN THE COMBINE AND NOW THE CONCAVES ARE HITTING. BROUGHT THE COMBINE BACK IN TO LEVEL THE CONCAVES AGAIN. LEVELED THE CONCAVES.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
26H105	Shaft Key 3/8" X 2 1/8" X 1 3/8" Trimmed	2.00	6.99	6.99	\$13.98	N
AXE42868	Bearing with Housing	1.00	586.76	586.76	\$586.76	N
H165447	LOCK NUT	2.00	20.81	20.81	\$41.62	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$1,902.75	Parts: \$642.36	OL&M: \$0.00	Misc: \$96.00	Sub-Total: \$2,641.11		

/GLOPCLEANS680 Internal
 COMPLAINT:
 28 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 14 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/GLOPCLEANS680 Internal

CORRECTION:

WASH COMPLETE MACHINE(OPEN & WASH BEHIND ALL SHIELDS) WAX IF REQUIRED REMOVE ANY OTHER DEALER DECALS INSTALL SCE DEALERSHIP DECALS ALL FACTORY SAFETY AND MODEL DECALS IN GOOD CONDITION REMOVE CAB FLOORMAT AND CLEAN MAT AND FLOOR CLEAN SEAT AND REMOVE STAINS IF NECESSARY VACUUM CAB THOROUGHLY CLEAN INSTRUMENT PANEL, OPERATOR CONTROLS, UPHOLSTERY, AND AIR DELIVERY LOUVERS CLEAN WINDOWS AND MOLDINGS(OPEN WINDOWS TO CLEAN EDGESWHERE APPLICABLE) ELIMINATE ANY CAB ODORS AND INSTALL AIR FRESHENER IF REQUIRED PAINT AREAS THAT ARE BADLY SCRATCHED/DAMAGED-INCLUDING BUCKETS, GRAPPLES, WHEELS, EXHAUST, PLATFORM AUGERS(COMPLETE AUGER), CHOPPER FINS, FEEDERHOUSE DRUMS, BALER PICKUPS

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------





Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/31/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 15 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JD S680 COMBINE	3289	1H0S680SAC0747306	1H0S680SAC0747306	

/GLOPCLEANS680 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	91.73	91.73	\$91.73	N
Labor: \$1,528.80	Parts: \$0.00	OL&M: \$0.00	Misc: \$91.73	Sub-Total: \$1,620.53		

Customer PO No: [REDACTED]
Tax Exempt No: [REDACTED]
Advisor: [REDACTED]

Labor: \$9,768.15
Parts: \$5,161.75
OL&M: \$0.00
Misc: \$581.00
Grand Total: \$15,510.90

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	147747			USED AG EQUIPMENT
06 40	382	1	822863			INTERNAL LABOR-AG
00 00	178	16	822863			WORK IN PROCESS PARTS -MJ
06 40	482	1	822863			COS INTERNAL LABOR-AG
06 40	544	1	822863			SUPPLIES EXPENSE
06 30	366	2	822863			JD PARTS-COUNTER
00 00	166	6	822863			JD PARTS-MOOSE JAW
06 30	375	3	822863			PARTS SPECIAL HANDLING
06 30	466	2	822863			JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: