



H.F. NODES CONSTRUCTION

#23 Terex TS-14G Scraper

9:50 AM 29/06/2010

AUCTAL HOURS FRONT 6223

REAR 4713

1:14 PM 02/07/2010

HOURS 747 NEXT SERVICE DUE AT 897

SERVICE TECH TRAVIS

REPLACED THE AIR FILTERS

REPLACED THE TRANSMISSION FILTERS

CUT OPEN THEY CLEAN

CLEARED THE CODES

CHECKED MACHINE OVER

1:39 PM 27/07/2010

HOURS

SERVICE TECH RANDY;

MAIN WIRING HARNESS ON THE MACHINE FRONT SHORTED OUT

REPLACED HARNESS ENGINE WOULD NOT START

4:32 PM 11/08/2010



HOURS

SERVICE TECH WATEROUS

REPROGRAMED THE ECU AND GOT MACHINE RUNNING

7:40 AM 14/10/2010

HOURS 868 NEXT SERVICE DUE AT 1118

SERVICE TECH ROB

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

CHECKED MACHINE OVER

8:30 AM 16/03/2011

HOURS 908 NEXT SERVICE DUE AT 1118

SERVICE TECH RANDY

CHECKOVER

REPLACED FRT DRIVE COUPLING

8:05 AM 26/04/2011

HOURS 962 NEXT SERVICE DUE AT 1181

SERVICE TECH RANDY;

CHECKED MACHINE OVER

7:56 AM 7/1/2011



H.F. NODES CONSTRUCTION

HOURS 1083 NEXT SERVICE DUE AT 1181

SERVICE TECH RANDY;

CHECKED MACHINE OVER

REPLACED THE CRANK SEAL ON THE FRONT ENGINE

REPAIRED THE OIL LEAKS ON THE REAR ENGINE

1:15 PM 8/12/2011

HOURS 1115 NEXT SERVICE DUE AT 1365

SERVICE TECH TRAVIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

7:34 AM 2/9/2012

hours 1378 next service due at 1628

SERVICE TECH RANDY;

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

INSTALLED A NEW FOOT VALVE FROM GEAR O RAMA

REPAIRED THE AIR LEAKS ON THE BOWL

5:28 PM 2/16/2012

HOURS 1377 NEXT SERVICE DUE AT 1628

SERVICE TECH JASON AND MYKE



H.F. NODES CONSTRUCTION

REPLACED THE HINGE ON THE EJECTOR

9:29 AM 6/26/2012

HOURS 1436 NEXT SERVICE DUE AT 1686

SERVICE TECH CHRIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

5:11 PM 6/29/2012

HOURS 1461 NEXT SERVICE DUE AT 1686

SERVICE TECH CAM

CHECKED MACHINE OVER

REPLACED THE RIGHT HAND STEERING CYLINDER

9:09 AM 10/1/2012

HOURS

SERVICE TECH TRAVIS

REPLACED THE ENGINE COOLING FAN WITH NEW ONE FROM HIWAY EQUIPMENT

4:49 PM 10/5/2012

HOURS 1503 NEXT SERVICE DUE AT 1686

SERVICE TECH TRAVIS



H.F. NODES CONSTRUCTION

CHECKED MACHINE OVER

INSTALLED THE BOWL HEATERS

INSTALLED THE TARPS

3:57 PM 4/22/2013

HOURS 1540 NEXT SERVICE DUE AT 1686

SERVICE TECH RYAN

CHECKED MACHINE OVER

FIRE EXT APRIL 2013

REPLACED THE AIR DRYER FILTER

1:59 PM 5/13/2013

HOURS 1540 NEXT SERVICE DUE AT 1686

SERVICE TECH RYAN

CHECKED MACHINE OVER

REPLACED THE AIR DRYER FILTER

FIRE EXT APRIL 2013

9:40 AM 8/8/2013

HOURS

SERVICE TECH GORDON

BRING MACHINE INTO SHOP

FAN BLADE BROKE ON THE FRONT ENGINE AND CUT A HOLE IN THE RAD



H.F. NODES CONSTRUCTION

REMOVE THE HOOD AND GRILL

REMOVE THE RAD ASSEMBLY

INSTALLED A NEW RAD OUT OF STOCK

REPLACED THE FAN

7:10 AM 9/2/2013

HOURS

SERVICE TECH RANDY

REPLACED THE CAM SENSER ON THE FRONT ENGINE

10:36 AM 9/12/2013

HOURS 1729 NEXT SERVICE DUE AT 1979

SERVICE TECH DEAN

SERVICED THE ENGINES 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

11:28 AM 11/28/2013

HOURS 1960

SERVICE TECH RANDY

REPLACED THE AIR DRYER FILTER

7:19 PM 4/7/2014

HOURS 2750 NEXT SERVICE DUE AT 3000



H.F. NODES CONSTRUCTION

SERVICE TECH GORDON

SERVICED THE ENGINES 15/40

REPLACD THE OIL AIR AND FUEL FILTERS

1:46 PM 8/8/2014

HOURS 2628 NEXT SERVICE DUE AT 2750

SERVICE TECH RYAN

CHECKED THE MACHINE OVER

FIRE EXT APRIL 2014

MACHINE HAS TECHKING ON THE FRONT

5:41 PM 09/09/2015

HOURS 2722 NEXT SERVICE DUE AT 2977

SERVICE TECH RYAN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE PINION SEAL ON THE DROP BOX

REPLACED THE EXHAUST FLANGE ON THE REAR ENGINE TURBO

INSTALLED A NEW IDLER BEARING AND BELT ON THE REAR ENGINE

FIRE EXT MAY 2015

10:01 AM 04/02/2016



H.F. NODES CONSTRUCTION

HOURS 2838 NEXT SERVICE DUE AT 2977

SERVICE TECH RANDY

CHECKED MACHINE OVER

REPLACED THE HYD HOSES IN THE NECK

INSTALLED RIGHT FRONT BRAKE POT

FIRE EXT MAY 2015

CHANGED OIL IN THE TRANSMISSION

REPLACED THE HEATER MOTOR

9:45 AM 09/02/2016

SERVICE TECH JASON

REPAIRED THE TRANSMISSION STUMP PAN

REPAIRED THE GAURD ON THE SIDE ARM ON THE BOWL

9:55 AM 27/11/2016

HOURS

SERVICE TECH RYAN

OPERATOR COMPLAINED THAT THE REAR ENGINE KEEPS QUITTING

CHECKED OUT THE CODES

REPLACED THE THROTTLE PEDAL

CHECKED THE WIRING ON THE ECM

6:43 AM 12/12/2016



H.F. NODES CONSTRUCTION

HOURS 2982 NEXT SERVICE DUE AT 3232

SERVICE TECH GORDON

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

8:39 AM 25/01/2017

HOURS 3092

SERVICE TECH GORDON AND COLE

REMOVED THE REAR TRANSMISSION NO 4

INSTALLED THE REPAIRED TRANSMISSION NO 7

REBEARING AND RESEALED THE DRIVE ASSEMBLY

CHANGED OIL IN THE REAR DIFF

REMOVED THE YOKE ON THE FRONT DIFF AND REPLACED THE SEAL

REPAIRED THE WIRING ON THE NECK

REPLACED THE POOR HYD LINES

REPLACED THE FRONT ENGINE CRANK SEAL

REPLACED THE HEATER HOSES

REPLACED THE CUTTING EDGES AND ROUTER

JASON INSTALLED WEAR PLATES ON THE INSIDE OF THE BOWL

NEIL REPAIRED THE WIRING ON THE NECK AND THE SIDE OF THE BOWL

1:23 PM 24/04/2017

HOURS 3103 NEXT SERVICE DUE AT 3232



SERVICE TECH SLADE

REMOVED THE BOWL HEATER

REPLACED THE ROLLAR ON THE EJECTOR ARM

CHECKED MACHINE OVER

GREASED THE DRIVE LINE

CHECKED ENGINE CODES

REPLACED THE THROTTLE SWITCHES

REPAIRED THE A/C

INSTALLED A NEW TEMP SWITCH 71R2250

KNOB NO 71R4050

REPAIR THE WIRING ON THE NECK AND TRANSMISONS

REPLACED THE ROLLAR FOR THE EJECTOR ARM

INSTALLED A NEW WEAR PLATE ON THE EJECTOR ARM

CALIBRATED THE TRANSMISONS

CLEARED THE CODES

INSTALLED A NEW TRANSMISSON SHIFT CONTROLLER

1:52 PM 18/09/2017

HOURS 3268 NEXT SERVICE DUE AT 3518

SERVICE TECH COLE

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT APRIL 2017



11:25 AM 28/11/2017

HOURS

SERVICE TECH SLADE

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

CHECKED THE TRANSMISSION CODES

REPAIRED A BROKEN WIRE

CALIBRATE THE TRANSMISSIONS

REBEARINGED THE OUTPUT HOUSING DRIVE HOUSING

REPLACED THE PULLEY FOR THE FAN DRIVE ON THE REAR ENGINE

PART NO 1818607C1 GEAR O RAMA

7:10 AM 25/07/2018

HOURS 3544 NEXT SERVICE DUE AT 3723

SERVICE TECH AYDEN

CHECKED MACHINE OVER

FIRE EXT MAY 2018

5:47 PM 24/08/2018

HOURS 3561 NEXT SERVICE DUE AT 3723

SERVICE TECH AYDEN

CHECKED MACHINE OVER



FIRE EXT MAY 2018

12:49 PM 18/10/2018

HOURS 3578 NEXT SERVICE DUE AT 3723

SERVICE TECH NEIL

CHECKED MACHINE OVER

REPLACED THE LEAKING HYD HOSE

REMOVED THE PINS ON THE APRON

CLEAN UP SO THEY WILL TAKE GREASE

REPAIRED THE OIL LEAK ON THE REAR COMPRESSOR

FIRE EXT MAY 2018

3:21 PM 21/08/2019

HOURS 3618 NEXT SERVICE DUE AT 3723

SERVICE TECH COLE

HAULED MACHINE IN FOM JOB

THE INPUT BEARING ON THE FRONT TRANSMISSION FAILED

REMOVED THE FRONT COVER

REPLACED THE FRONT COVER

TEST RUN GOOD

REPAIRED THE OIL LEAKS

REAIRED THE AIR LEAKS

FIRE EXT JUNE 2019



H.F. NODES CONSTRUCTION

4:06 PM 13/09/2019

HOURS 3701 NEXT SERVICE DUE AT 3951

SERVICE TECH AYDEN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT JUNE 2020

1:48 PM 09/10/2019

HOURS 3730 NEXT SERVICE DUE AT 3951

SERVICE TECH SLADE

REPLACED THE FRONT ENGINE HARNESS

REPLACED THE INTERFACE HARNESS

EXCHANGED ECM FROM REAR OF #24

1:26 PM 06/11/2019

HOURS 3754 NEXT SERVICE 3951

SERVICE TECH COLE

CHECKED THE MACHINE OVER

FOUND LOT OF CUTTINGS IN THE OIL ON THE FRONT DIFF

REMOVED THE FRONT DIFF

DEASSEMBLED FOUND THE SPIDER GEARS AND AXLE GEARS HAD FAILED

INSTALLED NEW ONES



H.F. NODES CONSTRUCTION

ASSEMBLED THE DIFF AND INSTALLED

CHANGED OIL IN THE PLANETRYYS

REPAIRED THE WIRING HARNESS ON THE SIDE OF THE BOWL

CHANGED OIL IN THE TRANSMISSON AND FILTERS

REPAIRED THE STUMP PANS

FIRE EXT JUNE 2019

9:54 AM 09/09/2020

HOURS 3775 NEXT SERVICE DUE AT 3951

SERVICE TECH COLE

WASHED RADS, FRONT AND REAR.

CHECKED OVER/GREASED.

FIRE EXT OCT/2019

8:06 AM 22/01/2021

HOURS 3799 NEXT SERVICE DUE AT 3951

SERVICE TECH COLE

INSTALLED GREASE FITTINGS ON THE BRAKE CAMS

DROPPED THE EDGES AND SWAPPED THE ROUTER BITS

GREASED THE MACHINE

CHANGED OIL IN THE GEAR BOX

INSTALLED THE OLD ECM ON THE REAR ENGINE

REPAIRED THE KEEPER PINS ON THE STEERING CYLINDERS



H.F. NODES CONSTRUCTION

DRILLED HOLES IN THE DRAFT TUBE FOR WATER TO GET OUT

FIRE EXT DEC 2020

2:31 PM 08/07/2021

HOURS 3799

SERVICE TECH MURRAY

INSTALLED A USED ECM OFF OF THE SPARE BUGGY

NO CODES

CHECKED THE A/C 48

7:47 AM 27/08/2021

HOURS 3887 NEXT SERVICE DUE AT 3951

SERVICE TECH AYDEN

CHECKED THE MACHINE OVER

BLEW AIR FILTERS OUT

GREASED THE MACHINE

DUCT TAPPED THE HEATER DUCT IN THE CAB

FIRE EXT AUG 2021

11:26 AM 14/09/2021

HOURS 3954 NEXT SERVICE DUE AT 4259

SERVICE TECH AYDEN

SERVICED THE ENGINES 15/40



H.F. NODES CONSTRUCTION

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT AUG 2021

11:48 AM 22/09/2021

HOURS 3975 NEXT SERVICE DUE AT 4259

SERVICE TECH AYDEN

SERVICED THE ENGINES 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT AUG 2021

7:15 AM 26/06/2023

HOURS 4199 NEXT SERVICE DUE AT 4499

SERVICE TECH MURRAY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

RECHARGED THE A/C

THE REAR ENGINE HAD SOME COOLANT IN THE OIL PAN

FIRE EXT AUG 2022

7:57 AM 15/08/2023

HOURS 4259 NEXT SERVICE DUE AT 4499

SERVICE TECH MURRAY

FIRE EXTINGUISHER AUG 2023



H.F. NODES CONSTRUCTION

REPLACED LEAKING FITTING OFF CHARGE PUMP ON REAR TRANSMISSION

REPLACED BROKEN SPRING ON REAR TRANS PRESSURE RELIEF AND ADDED SHIM

CALIBRATED FRONT AND REAR TRANSMISSION

11:57 AM 19/09/2024

HOURS 4279 NEXT SERVICE DUE AT 4499

SERVICE TECH AYDEN

CHECKED THE MACHINE OVER

REPAIRED A FEW HYD OIL LEAKS

REPLACED THE IDLER PULLEY AND FAN BELT ON THE REAR ENGINE

REPAIRED THE LEAK ON THE REAR TRANSMISSION FILL TUBE

FIRE EXT MAY 2024