

rb RITCHIE BROS. Diagnostic Report
Auctioneers™

2011 International WorkStar 7400

Test Information	
Engine	International DT466/Maxxforce DT (7.6)
Engine Serial	INT *466224241011696M10CARB ESS EXEMPT*5008953068--
VIN	1HTWGAAT4BJ385826
Driveline	Class 8 6x4
Body	Truck MDHD: Conventional
Test Time	June 11, 2026, 3:30 p.m.
File Length	34.189 s

Usage		
Label	Value	Units
Engine Odometer	59,191	mi
Odometer (Instrument Cluster #1)	59,397	mi
Engine Total Hours of Operation	8,354.5	h

Engine On/Off
Engine running

Check Engine Light
No check engine lights on

Emissions Deleted/Tampered
No

Faults				
<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Brakes - System Controller	Manufacturer Assignable SPN (last entry)	Condition Exists	127
Active	Body Controller	Tail Lamp/License Plate Lamp Circuit (Brown)	Current Below Normal	1
Previous	Brakes - System Controller	J1939 Network #1. Primary Vehicle Network	Failure	1
Previous	Body Controller	Brake Switch	Erratic, Intermittent, or Incorrect	8
Previous	Body Controller	Manufacturer Assignable SPN	Abnormal Update Rate	1
Previous	Body Controller	Operator Input device for Cab Climate Control	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Cab HVAC Mode Control Actuator	Erratic, Intermittent, or Incorrect	1
Previous	Body Controller	Disengage Differential Lock Request - Central Rear	Erratic, Intermittent, or Incorrect	54