
Trailer – Rego R54864
Maintenance

Date:	Work Completed:
3/6/2008	Fit two float tyres
20/8/2008	Fit 4 new float tyres
22/4/2010	Fit new float mudflaps
24/6/2010	Fit 2 float tyres
4/5/2010	Fit 2 float tyres
27/9/2010	Wire up belly tank pump
8/11/2010	Fit new float battery to terminals
17/2/2011	Fit one new float tyre
1/6/2013	Repair mast rest
26/6/2013	Purchased tyres for stock
1/8/2013	Fit tyres
10/6/2014	Service and repairs
10/11/2014	Fix ramp solinoid
17/12/2014	Fix tyres
24/3/2015	Repair trailer ramps system
14/5/2015	Adjust wheel bearings, replace radius rod bushes, clear defects
21/1/2016	Check wheel bearings and replace leaking wheel seals
8/2/2016	Repairs to trailer
24/2/2016	Swap tyre brands
27/4/2016	RH Rear axle brake booster replaced
17/5/2016	2 tyres + 1 tyre
8/10/2016	4 tyres
23/11/16	Check and repair loading ramps pump
21/6/2017	Repair bent truck tyre rim
31/7/17	Southside – Check and repair brakes/adjustment
03/07/18	Southside Truck Centre – Supply and Fit 1 x Steer Tyre (Blacklion BLH51)
05/07/18	Southside Truck Centre – Supply and Fit all new trailer Bushes and clear defects
23/08/2018	Plateau Tyres – 8 x 255/70R22.5 Triangle TR656 Tyres
23/08/2018	Lismore Tyre Co. – 8 x 255/70R22.5 Blacklion BLH51 Steer Tyres
28/02/2019	Southside truck centre – Removed and replaced Rocker Box in suspension
19/11/2019	Southside Trucks – Check and Repair trailer suspension as needed
21/05/2020	Hydraulink – Supply and fit couplers, flow control valve, steel pipes and hoses to ramp control valve
24/06.2020	Southside Truck Centre – Fix air leak
14/07/2022	Southside Truck Centre – Axle 1,2 & 3 Radius rod excess m'ment, front & rear end, bush torque rod reyc, 1 x 14 SA UNF Nyloc nuts G5
09/06/2023	4 x 255/70R22.5 S/Cargo SC216 19PR
26/06/2023	8 x 255/70R22.5 Trailer Tyres
19/07/2023	SouthSide Trucks - Defect Repairs
05/02/2025	Paul Nielsens – RAM Reseal
17/07/2025	Southside Trucks – Install new mudflaps and red and yellow warning signs