

INVOICE

Submitted 9/21/2025

HK Diesel Repair Co. Inc.
74502 Range Road 173
High Prairie, AB T0G1E0
(780)-536-0131
Hkdieselrepair@gmail.com



Diesel Repair Co. Inc.

Customer Billing Info:

Little Smoky Transport
PO Box 393
High Prairie, AB T0G 1E0
judywilkinson393@gmail.com

Invoice #:

100415

Due Date:

Within 30 days

Unit #:

216

KM:

1,034,095

HRS:

18,649

Date of repair: 8/22/2025

Description	Qty	Unit price	Total price
Service- oil and filter, grease, fuel filters and cab filter.			\$0.00
inspect unit for defects-- unit has some defects, repairs listed below and fluid levels are ok except PS fluid was low			\$0.00
Add lucas oil stabilizer			\$0.00
power steering leak-- hose fitting o-ring damaged--- replaced both pressure and return o-rings--- fill system and test for leaks--- no leaks present after repair.			\$0.00
air fitting on TPV leaking--- replaced 3/8x3/8 PC fitting.			\$0.00
replaced steer shocks			\$0.00
			\$0.00
PARTS:			\$0.00
ATF /L	1.5	\$10.50	\$15.75
3/8 x 3/8 PC fiitng	1	\$12.50	\$12.50
lucas oil stabl.	1	\$60.99	\$60.99
total Labour /hr	5	\$87.00	\$435.00
			\$0.00

Payment Options:

Cheques made payable to HK Diesel Repair Co. Inc.

Interac E-transfers to hkdieselrepair@gmail.com

Subtotal \$524.24

GST/HST 5% \$26.21

TOTAL \$550.45

All past due accounts are subject to 2% monthly interest charge*

GST/HST# 73628 3748 RT0001

Thank You for Your Business