

rb RITCHIE BROS. Diagnostic Report
Auctioneers®

2020 Freightliner 106 Medium Duty

Test Information	
Engine	Cummins L9 (9.0)
Engine Serial	CMMNS*6L u17D0890000000*74560658
VIN	3ALHCYFEXLDMC5815
Driveline	Class 8 6x4
Body	Truck
Test Time	June 19, 2026, 9:18 a.m.
File Length	45.3202 s

Usage			
Label	Value	Units	
Engine Odometer	192,927	mi	
Odometer (Instrument Cluster #1)	192,961	mi	
Engine Total Hours of Operation	6,634.9	h	
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	0	%	

Engine On/Off
Engine running

Check Engine Light
● MIL - Emissions malfunction

Emissions Deleted/Tampered
No

Faults				
<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Engine #1	Engine Fuel Leakage 1	High-moderate severity	1
Previous	Body Controller	Manufacturer Assignable SPN	Voltage Below Normal	4
Previous	Body Controller	Windshield Wiper Motor Speed	Current Below Normal	5
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	6
Previous	Body Controller	Source Address 71	Data Error	126
Previous	Body Controller	Source Address 3	Data Error	7
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	1
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	4
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	126
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	117
Previous	Body Controller	High-Low Beam Switch	Data Error	8
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	3
Previous	Body Controller	Windshield Wiper Motor ON/OFF	Not Responding Properly	1
Previous	Body Controller	Turn Signal Switch	Data Error	8
Previous	Body Controller	Front Operator Washer Switch	Data Error	5
Previous	Body Controller	Front Operator Wiper Switch	Data Error	5
Previous	Proprietary	Source Address 33	Data Error	5
Emissions Active	Engine #1	Engine Fuel Leakage 1	High-moderate severity	1
Permanent	Engine #1	Engine Fuel Leakage 1	High-moderate severity	1