

RO3-17

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No. 19546
 Date 09/26/2025
 Page 1

Sold to:
K. McIntosh & Sons
 E

Ship to:
 K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			2012 Kenworth T800	GP		
			1XKPD40X2CJ955203 583473Kms Unit #2			
4225	Each	1.00	3688113CUM Plug Sear Cover	GP	39.17	39.17
	Each	1.00	3685173CUM Seal Oil	GP	167.70	167.70
	Each	1.00	Freight	GP	20.00	20.00
	Each	1.00	4026684P Gasket Oil Pan ISX	GP	290.48	290.48
	Each	1.00	4336659 Stat ISX/ N14 Dual Housing	GP	63.98	63.98
	Each	1.00	3682673 Gasket Stat ISX Single	GP	27.36	27.36
	Each	1.00	132071 Gasket Kit Front ISX SOHC	GP	447.65	447.65
	Each	1.00	3084879 Thermostat Seal	GP	7.80	7.80
	Each	1.00	89448DYG Tensioner HD	GP	426.88	426.88
74050	Each	3.00	ANTIFREEZE	GP	12.61	37.83
EHC-Antifreeze	PER JUG	3.00	EHC Antifreeze	GP	1.28	3.84
	Each	2.00	51003A Seal	GP	2.86	5.72
140	Each	1.00	O-Ring, 70 Duro Buna	GP	1.00	1.00
326	Each	2.00	O Ring	GP	1.14	2.28
54145	Each		O Ring	GP	1.50	1.50
HD0580	Per Litre	37.80	15 W 40 CK-4 HD Engine Oil	GP	7.15	270.27
HD0560 Jug	Per Litre	14.19	15W-40 CK-4 HD Engine Oil	GP	8.06	114.37
EHC-REGULAR	Per Litre	52.99	EHC	GP	0.19	10.07
LF14000NN	Each	1.00	Filter Lube Oil	GP	66.23	66.23
4240	Each	1.00	EHC filter	GP	1.25	1.25
ATFD3MC12	per litre	1.00	ATF D3M 12x1 Petro Can	GP	7.78	7.78
	Each	1.00	469.09M2107 A/C O- Ring	GP	0.57	0.57
	Each	2.00	469.09568905 A/C O-Ring	GP	1.50	3.00
	Each	1.00	469.09015 A/C O-Ring	GP	0.67	0.67
	Each	1.00	4952540 Pan Oil ISX Frt/ Rear Sump	GP	773.50	773.50
4225	Each	1.00	Freight	GP	40.00	40.00
	Each	1.00	4952629CUM Thermostat	GP	256.70	256.70
0120	Hour	19.00	Labour Mechanics	GP	120.00	2,280.00
0115	%	19.00	Shop Supplies	GP	3.60	68.40

Look into oil leak on front of engine. wash engine and run. oil started coming out of engine barring plug. found plug was cut with a groove. filled groove on front cover. order new plug. run truck and found leak was still there. remove rad and dampener. crank seal looked good. look front cover and front structure. found front cover seal was pretty flat and structure seal was seperating. clean front structure and install with new gasket. c/o both thermostats per customer request. install all gears in front

Comment: Due Upon Receipt: 2% compounded Interest charged on overdue accounts. Feb1.2023 - 3% CC Charge

Continue...

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No. 19546
 Date 09/26/2025
 Page 2

Sold to:
 K. McIntosh & Sons

Ship to:
 K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			housing, set clearance on cam gear to .004, install front cover with new gasket, install rad and accesory mounts, install wqater pump with new o- rings, install new oil pan as old one was rusted badly, fill with oil and coolant, run truck no visible leaks			
			recharge a/c system, remove and replace accessory tensioner, test drive truck			
			Subtotal.			5,436.00
			GP - GST 5%, PST 6%			271.80
			GST/HST			326.15
			PST			
Comment: Due Upon Receipt 2% compounded Interest charged on overdue accounts. Feb1,2023 - 3% CC Charge					Total Amount	6,033.95
					Amount Paid	0.00
					Amount Owing	6,033.95

Kalm Mechanical & Welding

Box 430
50 1st Avenue East
Outlook, Saskatchewan S0L 2N0
Canada
Ph: 1-306-867-1008
Fax: 1-306-867-1009

INVOICE

Invoice No. 18704
Date 06/27/2025
Page 1

Sold to:
K. McIntosh & Sons

Ship to:
K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			2012 Kenworth T800	GP		
			1XKDD40X2CJ955203 Unit #2			
4225	Each	1.00	RADS10301TRP Radiator Kenworth	GP	1,135.44	1,135.44
BW5086	Each	1.00	Freight	GP	35.00	35.00
708	Each	1.00	Coolant Spin On With BTA Plus Formula	GP	65.80	65.80
ATFD3MC12	per litre	2.00	10 Min Rad Flush	GP	7.54	15.08
EHC-REGULAR	Per Litre	2.00	ATF D3M 12x1 Petro Can	GP	7.78	15.56
4240.1	Each	1.00	EHC	GP	0.19	0.38
74050	Each	1.00	EHC filter	GP	0.55	0.55
EHC-Antifreeze	PER JUG	14.00	ANTIFREEZE	GP	12.61	176.54
6873	Each	2.00	EHC Antifreeze	GP	1.28	17.92
0120	Hour	8.75	68-73mm Single Bolt Clamp	GP	8.37	16.74
0115	%	8.75	Labour Mechanics	GP	120.00	1,050.00
			Shop Supplies	GP	3.60	31.50
			Drain coolant, remove shroud, fan, condensor and overflow tank, set up crane and remove rad, reinstall all parts, flush rad with water 4 times, refill rad with new coolane and change out coolant filter			
			Subtotal			2,560.51
			GP - GST 5% PST 6%			128.04
			GST/HST			153.62
			PST			
					Total Amount	2,842.17
					Amount Paid	0.00
Comment: Due Upon Receipt: 2% compounded Interest charged on overdue accounts. Feb1,2023 - 3% CC Charge					Amount Owing	2,842.17

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No.: 16830
 Date: 10/18/2024
 Page: 1

Sold to:

K. McIntosh & Sons
 811-005

Ship to:

K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
124	Each	2	2012 Kenworth 1XKDD40X2CJ955203 564228kms Unit #2	GP		
125	Each	1	Labour PMVI (PST Exempt)	G	120.00	240.00
	Each	1	SGI Sticker	GP	15.75	15.75
225	Each	1	K1289130RBXW ABS Modulator	GP	425.23	425.23
T3030STD120	Each	1	Freight	GP	17.50	17.50
	Each	1	Spring Brake, 30/30 Eversure Intraax Undermount - Long Rod	GP	102.83	102.83
1759	Each	1	Pigtail	GP	6.95	6.95
12455	Each	1	Shear Adapter	GP	14.56	14.56
20	Hour	2	Labour Mechanics	GP	120.00	240.00
15	%	2	Shop Supplies	GP	3.60	7.20
			Change out RRear brake pot, diagnose and repair ABS issue, found modulator on passenger side no good and change out modulator			
			Subtotal:			1,070.02
			G - GST 5%			
			GP - GST 5%, PST 6%			
			GST/HST			53.51
			PST			49.80
					Total Amount	1,173.33
					Amount Paid	0.00
					Amount Owning	1,173.33
Comment: Due Upon Receipt: 2% compounded Interest charged on overdue accounts. Feb1,2023 - 3% CC Charge						

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No.: 17897
 Date: 03/28/2025
 Page: 1

Sold to:
K. McIntosh & Sons

Ship to:
 K. McIntosh & Sons

Business No.: 726275522

2012 Kenworth.

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			Unit #2 Kenworth ESN 79512243	GP		
4225	Each	1.00	3685173CUM Seal, Oil	GP	146.18	146.18
	Each	1.00	Freight	GP	20.00	20.00
	Each	1.00	5414049CUM Gasket Fuel Pump	GP	54.95	54.95
RK351AL	Each	1.00	Ki. Rebuild LH	GP	538.00	538.00
9500-014mm	Each	4.00	Metric Bonded Seal	GP	2.31	9.24
9500-020MM	Each	2.00	Bonded Seal, Metric	GP	2.31	4.62
3828036	Each	1.00	Wheel Set Front Axle STD 2036	GP	64.87	64.87
ATFD3MC12	per litre	2.00	ATF D3M 12x1 Petro Can	GP	7.78	15.56
EHC-REGULAR	Per Litre	3.50	EHC	GP	0.19	0.67
PSN74050F	Each	2.00	ANTIFREEZE	GP	12.61	25.22
EHC-Antifreeze	PER JUG	2.00	EHC Antifreeze	GP	1.28	2.56
0120	Hour	13.75	Labour Mechanics	GP	120.00	1,650.00
0115	%	13.75	Shop Supplies	GP	3.60	49.50
			Drain coolant, remove rad, crank pulley and balancer, replace crank seal, reinstall balancer, pully and rad, fill with coolant, c/o fuel pump gasket and change bonded seals, remove %th wheel hitch and install rebuild kit, clean grease off, remove front right drive axle and replace wheel seal, reinstall hub and wheel, fill hub with oil			
TRSY759DRM	Each	1.50	Traxon Synthetic 75W90 205L Pail	GP	11.90	17.85
			Subtotal:			2,599.22
			GP - GST 5%, PST 6%			129.96
			GST/HST			155.94
			PST			
					Total Amount	2,885.12
					Amount Paid	0.00
					Amount Owning	2,885.12
Comment:	Due Upon Receipt: 2% compounded Interest charged on overdue accounts. Feb1,2023 - 3% CC Charge					

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No. 18430
 Date 05/23/2025
 Page 1

Sold to:
 K. McIntosh & Sons

Ship to:
 K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
181.10032666	Each		2012 Kenworth T800	GP		
1707018X	Each		1XKDD40X2CJ955203 Unit #2			
0120	Hour	1	Pinion Seal	GP	47.58	47.58
0115	%	1	Bearing Retainer Kit SPL170	GP	32.37	32.37
		2	Labour Mechanics	GP	120.00	240.00
		2	Shop Supplies	GP	3.60	7.20
			Remove and replace pinion seal, heat strap kit bolts to remove, clean surfaces and check gear oil			
			Subtotal:			327.15
			GP - GST 5%, PST 6%			16.36
			GST/HST			19.62
			PST			
					Total Amount	363.13
					Amount Paid	0.00
					Amount Owing	363.13
<p>Comment: Due Upon Receipt: 2% compounded interest charged on overdue accounts. Feb1,2023 - 3% CC Charge</p>						

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No.: 18179
 Date: 04/30/2025
 Page: 1

Sold to:
K. McIntosh & Sons

Ship to:
 K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			2012 Kenworth T800 1XKDD40X2CJ955203 567964kms Unit #02	GP		
0124	Each	2.00	Labour PMVI (PST Exempt)	G	120.00	240.00
0125	Each	1.00	SGI Sticker	GP	15.75	15.75
3828036	Each	1.00	Wheel Set Front Axle. STD 2036	GP	64.87	64.87
3929131	Each	1.00	Wheel Set. Drive. Oil Seal. Grit Guard	GP	77.87	77.87
XSS714709E2K	Each	1.00	Brake, Eaton 16.5x7 ESII	GP	80.34	80.34
SSD6722	Each	1.00	Brake Drum 16.5 x 7.00 10 Hole 11.25 BC8.78 Pilot	GP	155.93	155.93
TRSY759DRM	Each	3.00	Traxon Synthetic 75W90 205L Pail	GP	11.90	35.70
EHC-REGULAR	Per Litre	3.00	EHC	GP	0.19	0.57
0120	Hour	3.25	Labour Mechanics	GP	120.00	390.00
0115	%	3.25	Shop Supplies	GP	3.60	11.70
			Remove and replace RH steer wheel seal, remove and replace RH front drive wheel seal, brakes and drum			
			Subtotal:			1,072.73
			G - GST 5%			
			GP - GST 5%, PST 6%			
			GST/HST			53.65
			PST			49.96
					Total Amount	1,176.34
					Amount Paid	0.00
Comment: Due Upon Receipt: 2% compounded Interest charged on overdue accounts. Feb1,2023 - 3% CC Charge					Amount Owning	1,176.34