

RO3-19

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No.: 20130
 Date: 11/28/2025
 Page: 1

Sold to:
 K. McIntosh & Sons

Ship to:
 K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			2016 Peterbilt 389 1XPXD49XGD305563	GP		
0124	Each	2.0	242046kms Unit #35	GP	120.00	240.00
0125	Each	1.0	Labour PMVI (PST Exempt)	GP	15.75	15.75
M13109	Each	1.0	SGI Sticker	GP	28.82	28.82
M136001KUB	Each	1.0	Kenworth Exhaust Mount	GP	40.43	40.43
	Each	1.0	Exhaust Bushing Kit Poly Peterbilt	GP	224.04	224.04
4225	Each	1.0	TQRAA2-584 Torque Rod	GP	20.00	20.00
0120	Hour	1.5	Freight	GP	120.00	180.00
0115	%	1.5	Labour Mechanics	GP	3.60	5.40
			Shop Supplies			
			Change out rear diff torsion bar, change out RH stack bushing and rod, weld crack on hitch			
			Subtotal:			754.44
			GP - GST 5%, PST 6%			37.72
			GST/HST			45.27
			PST			
					Total Amount	837.43
					Amount Paid	0.00
					Amount Owing	837.43
Comment: Due Upon Receipt: 2% compounded Interest charged on overdue accounts. Feb1,2023 - 3% CC Charge						

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No.: 16835
 Date: 10/18/2024
 Page: 1

Sold to:
 K. McIntosh & Sons

Ship to:
 K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
0124	Each	2.00	2016 Peterbilt 1XxD49x6GD305563	GP		
0125	Each	1.00	228050kms Unit #35	G	120.00	240.00
	Each	1.00	Labour PMVI (PST Exempt)	GP	15.75	15.75
4225	Each	1.00	SGI Sticker	GP	76.96	76.96
28049	Each	1.00	210737 Seal	GP	17.50	17.50
707018X	Each	1.00	Freight	GP	16.45	16.45
929131	Each	2.00	NUT	GP	32.37	64.74
RSY759DRM	Each	1.00	Bearing Retainer Kit SPL170	GP	74.29	74.29
EHC-REGULAR	Per Litre	1.50	Wheel Set, Drive, Oil Seal, Grit Guard	GP	11.90	17.85
SS714709E2K	Each	1.50	Traxon Synthetic 75W90 205L Pail	GP	0.15	0.23
SSD6722	Each	1.00	EHC	GP	79.43	79.43
	Each	1.00	Brake, Eaton 16.5x7 ESII	GP	155.93	155.93
	Hour	6.25	Brake Drum 16.5 x 7.00 10 Hole 11.25			
	%	6.25	BC8.78 Pilot			
			Labour Mechanics	GP	120.00	750.00
			Shop Supplies	GP	3.60	22.50
			Drop intermediate shaft and remove yoke to replace output seal on front diff, install pinion seal and yoke, reinstall driveshaft, change out LH rear axle wheel seal, replace drum and brakes, old drum and hub were very siezed on			
			Subtotal:			1,531.63
			G - GST 5%			
			GP - GST 5%, PST 6%			
			GST/HST			76.59
			PST			77.51
					Total Amount	1,685.73
					Amount Paid	0.00
					Amount Owing	1,685.73

Comment: Due Upon Receipt: 2% compounded Interest charged on overdue accounts. Feb1,2023 - 3% CC Charge

Kalm Mechanical & Welding

Box 430
 50 1st Avenue East
 Outlook, Saskatchewan S0L 2N0
 Canada
 Ph: 1-306-867-1008
 Fax: 1-306-867-1009

INVOICE

Invoice No.: 18194
 Date: 04/30/2025
 Page: 1

Sold to:

K. McIntosh & Sons

Ship to:

K. McIntosh & Sons

Business No.: 726275522

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
0124	Each		<i>2016</i> 2015 Peterbilt 1XPXD49X6GD305563	GP		
0115	%	2.0	232984kms Unit #35			
M13109	Each	1.0	Labour PMVI (PST Exempt)	G	120.00	240.00
M136001KUB	Each	1.0	Shop Supplies	GP	3.60	3.60
0120	Hour	1.0	Kenworth Exhaust Mount	GP	28.82	28.82
0115	%	1.5	Exhaust Bushing Kit Poly Peterbilt	GP	40.43	40.43
		1.5	Labour Mechanics	GP	120.00	180.00
		1.5	Shop Supplies	GP	3.60	5.40
			Fix wire for rear RH lamp, change LH stack bushings and pins, adjust hitch and clean battery			
			Subtotal:			498.25
			G - GST 5%			
			GP - GST 5%, PST 6%			
			GST/HST			24.91
			PST			15.50
					Total Amount	538.66
Comment: Due Upon Receipt: 2% compounded Interest charged on overdue accounts. Feb1,2023 - 3% CC Charge					Amount Paid	0.00
					Amount Owing	538.66