

RITCHIE BROS. Diagnostic Report
 Auctioneers[®]
2018 Freightliner 106 Medium Duty
Test Information

Engine	Cummins L9 (9.0)
Engine Serial	CMMNS*6L u17D0890000000*74089314
VIN	3ALHCYFE4JDJK7665
Driveline	Class 8 6x4
Body	Truck MDHD: Conventional
Test Time	May 9, 2025, 12:46 p.m.
File Length	16.319 s

Usage

Label	Value	Units
Engine Odometer	237,630	mi
Odometer (Instrument Cluster #1)	237,687	mi
Engine Total Hours of Operation	10,071.75	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	57	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Body Controller	High-Low Beam Switch	Data Error	1
Previous	Body Controller	Turn Signal Switch	Data Error	1
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	3
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	111
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	1
Previous	Body Controller	Engine Starter Motor Relay Control	Current Below Normal	2
Previous	Body Controller	Manufacturer Assignable SPN	Voltage Below Normal	1
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Erratic, Intermittent, or Incorrect	1