

Equipment Maintenance Summary

Hamm 3412 Sheepsfoot CP-13

Timeframe: 01/01/2014 → 04/01/2026

Scope: Both Maintenance and Repair

Generated: April 1, 2026 9:22 AM

Description	Start	End	Hours/KM	Type	Rule	Created
Replaced Manual Pump that Lifts Engine Cover Oil Change Needed in 25 Hours	02/03/2015 12:00 AM	02/03/2015 12:00 AM	475/-	Repair		02/05/2015 11:13 AM
Change Engine Oil and Filter, Fuel Filter, Air Filter, Greased Fittings Mechanic = Shawn	02/12/2015 12:00 AM	02/12/2015 12:00 AM	484/-	Maintenance	Compaction Maintenance	02/18/2015 12:49 PM
Loose Hose Clamp - Tightened and top up coolant Replaced A/C Belt - Straightened bend scrapers Mechanic = Carl & Terry	04/21/2015 12:00 AM	04/21/2015 12:00 AM	488/-	Repair		05/07/2015 11:34 AM
Changed Air Filter, Check Wiring as Fault Codes are Coming Up - Drain water/fuel seperator (did not replace) - Reinstall bolt on bracket not installed from SMS Mechanic = Terry & Colin	07/05/2016 12:00 AM	07/05/2016 12:00 AM	802/-	Repair		07/07/2016 2:02 PM
Changed Engine Oil & Filter, Air Filter, Fuel Filter, Cab Filters, Steering Filter, Water Separator, Hydraulic Filter, Diff Oil, Drum Oil Mechanic = Joe	08/08/2016 12:00 AM	08/08/2016 12:00 AM	830/-	Maintenance	Compaction Maintenance	08/11/2016 11:22 AM
Replaced AC Belt Mechanic = Joe	08/08/2016 12:00 AM	08/08/2016 12:00 AM	830/-	Repair		08/11/2016 11:24 AM
Check Fire Extinguisher, Lights, Beacon, First Aid Kit, Spill Kit, Back Up Alarm, Decals, High Vis Decals, Unit ID Numbers, Decibel decals, Isolation switch, Repair RH Door weather stripping, Washed Mechanic = Shawn	08/10/2016 12:00 AM	08/10/2016 12:00 AM	831/-	Repair		08/11/2016 11:27 AM
Install new battery - Checked for proper charging = OK Mechanic = Terry	08/19/2016 12:00 AM	08/19/2016 12:00 AM	845/-	Repair		08/31/2016 11:27 AM
Change Engine Oil & Filter (5W40) Mechanic = Carl	02/22/2017 12:00 AM	02/22/2017 12:00 AM	880/-	Maintenance	Compaction Maintenance	02/22/2017 3:16 PM
Replace Fuse in Head Liner to get AM/FM radio working Mechanic = Carl	02/22/2017 12:00 AM	02/22/2017 12:00 AM	880/-	Repair		02/22/2017 3:18 PM

Repair rear wiper, take switch apart and clean contacts, repair plug at motor and zip tie to lock it - Flush front washer hoses - Check Fire Ext. Lights, Wipers, Beacon, Seat Belts, Spill Kit, First Aid Kit, AC, Fluid Levels = OK - Blow out Rad - Repair arm rest on pass side Mechanic = Terry	05/01/2017 12:00 AM	05/01/2017 12:00 AM	886/-	Repair		05/03/2017 5:13 PM
				Repair Request Check over and prep for PCS Allan Check service due at 1380hr, Check sheet for PCS, Check A/C works, May 1, 2017 7:40 AM by Carl Hewitt		
Change Engine Oil & Filter (5W40), Air Filter Mechanic = Joe	09/15/2017 12:00 AM	09/15/2017 12:00 AM	1,406/-	Maintenance	Compaction Maintenance	09/19/2017 9:46 AM
Fountain Tire WO Attached - Replaced Driver Side Tire and Tube and Filled with Calcium Chloride - Onsite at Reach 1	12/22/2017 12:00 AM	12/22/2017 12:00 AM	1,584/-	Repair		01/03/2018 4:10 PM
ECM needs to be removed and sent to SMS to be Re-Flashed - Completed by SMS Jan 23-18	01/23/2018 12:00 AM	01/23/2018 12:00 AM	1,586/-	Repair		03/04/2018 9:10 PM
				Repair Request ECM ECM needs to be removed and sent to SMS to be Re-Flashed August 31, 2016 11:31 AM by Carl Hewitt		
SMS came to Floral. Cleaned relay. Work Order attached.	02/14/2018 12:00 AM	02/14/2018 12:00 AM	1,590/-	Repair		03/12/2018 11:26 AM
Change Engine Oil & Filter (10W40 PetroCan Synthetic), Air Filters, Fuel Filters, Drum Oil (SMS Supplied Hamm Oil), Hydraulic Screens Mechanic = Steven	10/09/2018 12:00 AM	10/09/2018 12:00 AM	2,300/-	Maintenance	Compaction Maintenance	10/17/2018 9:40 PM

Change Engine Oil & Filter (10W40 PetroCan Synthetic), Air Filters, Fuel Filters, Drum Oil (SMS Supplied Hamm Oil), Hydraulic Screens Mechanic = Steven	10/09/2018 12:00 AM	10/09/2018 12:00 AM	2,300/-	Maintenance	Compaction Maintenance	10/17/2018 9:40 PM
Replaced Battery and Tie Down Mechanic = Jace	04/17/2019 12:00 AM	04/17/2019 12:00 AM	2,487/-	Repair		04/26/2019 10:00 PM
Repair Air Filter Sensor Plug - Install Locking Isolation Switch Mechanic = Blake & Mickenzie	06/11/2019 12:00 AM	06/11/2019 12:00 AM	2,737/-	Repair		06/17/2019 12:01 PM
Change Engine Oil & Filter (15L 10W40 PetroCan Duron UHP Synthetic), Air Filter - Greased Mechanic = Blake & Mickenzie	06/11/2019 12:00 AM	06/11/2019 12:00 AM	2,737/-	Maintenance	Compaction Maintenance	06/19/2019 12:02 PM
Replaced Front and Rear Lights with LED - Replaced Beacon Mechanic = Mickenzie & Jace	10/24/2019 12:00 AM	10/24/2019 12:00 AM	3,137/-	Repair		11/17/2019 10:22 PM
Replaced Hydraulic Hoses from Pump to Drum Mechanic = Blake & Mickenzie	05/15/2020 12:00 AM	05/15/2020 12:00 AM	3,330/-	Repair		05/19/2020 11:10 AM
Change Engine Oil & Filter (15L 10W40 PetroCan Duron UHP Synthetic), Outer Air Filter, 3 Fuel Filters - Greased Mechanic = Blake & Mickenzie	05/15/2020 12:00 AM	05/15/2020 12:00 AM	3,330/-	Maintenance	Compaction Maintenance	05/19/2020 11:12 AM
Change Engine Oil & Filter (15L 10W40 PetroCan Duron UHP Synthetic), Outer Air Filter, 3 Fuel Filters - Greased Mechanic = Blake & Mickenzie	05/15/2020 12:00 AM	05/15/2020 12:00 AM	3,330/-	Maintenance	Compaction Maintenance	05/19/2020 11:12 AM
There are 2 Bent Scraper Bars, Flipped and Adjusted all Scraper Bars - Drum hydraulic line leaking, Replaced 7 Hoses on Drum and Topped up Hydrostatic Oil Mechanic = Mickenzie	05/21/2020 12:00 AM	05/21/2020 12:00 AM	3,330/-	Repair		06/05/2020 11:12 AM
				Repair Request 2 Bent Scraper Bars - Hyd Leak There are 2 Bent Scraper Bars - Drum hydraulic line leaking November 17, 2019 10:23 PM by Chris Bildfell		

Change 2 Fuel Filters Mechanic = Mickenzie	05/21/2020 12:00 AM	05/21/2020 12:00 AM	3,330/-	Maintenance		06/05/2020 11:13 AM
Replace Horn and Repair Wiring - Repair High Speed Vibration Wiring - Top Up Drum Oil (8L Wirtgen 80W90) - Replace Fire Ext - Repair Wiper Arm - Replace Inner & Outer Air Filters - Clean Contacts on Cap Light Switches - Check AC = OK Replace Missing Cleaner Front Right - Check and Top Up Fluids - Replace Switch for Rear Wiper - Sweep Cab - Check Fire Ext, Back Up Alarm, Lights, Mirrors, Recirc Heater, Belts (Replaced Accessory Belt), Install Lockable Isolation Switch - Remove Wheels and Replaced Studs and Lug Nuts, Clean Hubs on Both Sides, Torque Lug Nuts to 450 Ft/Lbs - Apply Unit Id Stickers, Reflective Tape - Clean Battery Posts - Repair Weather Stripping RHS - Replace Weather Stripping LHS - Install Skid Plates - Replace Broken 2-Way Radio Antenna - Repair Fan Controls- Repair Left Side Window Latch - Wrap AC Line with Loom - Replaced #5 Hydraulic Hose - Tighten Hose Clamp on Rad Hose - Remove Sun Visor - Install New Vent Cap Mechanic = Steven	03/22/2021 12:00 AM	03/22/2021 12:00 AM	3,479/-	Repair		04/15/2021 10:17 AM
Repair wiring to condenser fans. Replace air conditioning relay. =Steven	N/A	N/A	3,509/-	Repair		07/15/2021 12:08 PM
Checked wiring and replaced 30amp fuses with proper 15amp Steven	07/23/2021 12:00 AM	07/23/2021 12:00 AM	3,545/-	Maintenance		08/23/2021 7:50 AM
Give unit 2000 hr service, replacing 3 hoses, BHP check over, replaced all rubber isolators on drum, Steve and Jon	04/07/2022 7:00 AM	04/07/2022 7:00 AM	-/-	Maintenance	Compaction Maintenance	04/07/2022 4:13 PM
Give unit 2000 hr service, replacing 3 hoses, BHP check over, replaced all rubber isolators on drum, Steve and Jon	04/07/2022 7:00 AM	04/07/2022 7:00 AM	-/-	Maintenance	Compaction Maintenance	04/07/2022 4:13 PM
Recharge a/c system Devin	06/05/2022 12:00 AM	06/05/2022 12:00 AM	3,862/-	Repair		06/05/2022 10:21 AM
Adjusted and replaced bent scrapers Blake, Jace	N/A	N/A	4,105/-	Repair		08/05/2022 7:30 AM
Change engine oil, oil filter, fuel filters, air filter	09/07/2022 12:00 AM	09/07/2022 12:00 AM	4,208/-	Maintenance	Compaction Maintenance	09/09/2022 7:24 AM

Replaced horn Blake, Carter	N/A	N/A	4,284/-	Repair		09/28/2022 2:13 PM
Removed all hardware and removed drum drive gearbox. Installed new gearbox and mounted right drive hardware to machine. Installed drum drive motor, refilled drive gearbox with special oil. Installed and readjusted all scrapers. Test drove machine and checked drive operation - all normal. Romeo/ Tanner/ Evan	11/17/2022 12:00 AM	N/A	4,333/-	Repair		11/22/2022 1:42 PM
Oil and filter change 4697hrs	09/19/2023 12:00 AM	09/19/2023 12:00 AM	4,697/-	Maintenance	Compaction Maintenance	09/19/2023 10:24 AM
Replace damaged final drive with new one, fill with witgren oil, diagnose faulty wiper motor, repair headlights	05/01/2024 12:00 AM	05/15/2024 12:00 AM	4,829/-	Repair		05/15/2024 1:28 PM
Replaced reverse alarm with new alarm. Mechanic - Kalan	05/22/2024 12:00 AM	05/22/2024 12:00 AM	4,819/-	Repair		05/22/2024 1:36 PM
Replaced vibration motor shaft, coupler and 2x snap rings. Changed vibration motor housing oil, both sides. Tanner	N/A	N/A	4,918/-	Repair		06/12/2024 9:45 AM
Repair coolant hose	06/27/2024 12:00 AM	06/27/2024 12:00 AM	4,998/-	Repair		06/28/2024 10:34 AM
Remove and weld on bracket for exhaust pipe	N/A	N/A	5,075/-	Repair		07/15/2024 4:48 PM
Change oil Oil filter Air filter	07/30/2024 12:00 AM	07/30/2024 12:00 AM	5,176/-	Maintenance	Compaction Maintenance	07/30/2024 1:54 PM
Engine oil and filter replaced Fuel water separator and 2x fuel filter replaced Engine air filter replaced Cabin air filter replaced Vibrator oil replaced Differential oil replaced Hydraulic oil and filter replaced AM/FM radio replaced Block heater replaced. Thomas, Rylan	09/11/2024 7:00 AM	09/20/2024 1:30 PM	5,477/-	Maintenance	Compaction Maintenance	09/20/2024 1:33 PM
Installed new drum drive gearbox, refilled with HAMM special oil. Checked operation- all normal. Readjusted sheepsfoot drum scrapers. Replaced battery and installed new isolation switch. Romeo/ Erick	11/15/2024 12:00 AM	N/A	5,485/-	Repair		11/29/2024 3:35 PM

1.Installed new knob for AC 2.Fixed radio 3. installed new beacon 4.Removed WELDED exhaust and returned to OEM 5.replaced Starter 6.Replaced hood lift cylinders 7.installed heat guards on exhaust Tom, Tanner and Erik	04/27/2025 12:00 AM	05/07/2025 12:00 AM	5,485/-	Repair		05/07/2025 4:49 PM
Replaced entire fuse panel circuit board.	N/A	N/A	5,561/-	Repair		06/07/2025 8:15 AM
Replaced right hand mirror.	N/A	N/A	5,734/-	Repair		07/28/2025 7:12 AM
Replaced hydro line from drive motor to control, main flow line.	N/A	N/A	5,877/-	Repair		08/23/2025 8:08 AM
Engine oil and filter replaced Engine air filter inner+outer replaced Fuel filter primary+secondary replaced Cabin air filter replaced Clarence, Kalen	09/08/2025 12:00 AM	09/08/2025 12:00 AM	5,927/-	Maintenance	Compaction Maintenance	09/09/2025 8:58 AM
Changed drum drive gearbox oil. Checked vibrator housing oil levels Thomas/Romeo	09/24/2025 12:00 AM	09/24/2025 12:00 AM	5,927/-	Maintenance		09/29/2025 9:15 AM
Found wiring harness rubbed through, repaired harness. Mechanic = Tom	11/24/2025 12:00 AM	11/24/2025 12:00 AM	6,050/-	Repair		11/24/2025 7:21 AM