

Asset:
Hitachi AH500 Articulated Dump Truck

Location:
No Address Found

Current Tracker Hours:
16966

Current Tracker Kms:
0

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
6779	Adjust all hyd pressure settings. Pump, steering, Hoist, Brake	28/08/2025	16966	0	23/10/2025	Equipment breakdown	Closed	Robert Badowski
6467	install rims and tyres	30/07/2025	0	0	05/08/2025	Maintenance	Closed	Alistair Ross
5908	Engine not starting	13/06/2025	0	0	21/07/2025	Repairs	Closed	Robert Badowski John Fitzgerald
5763	Front struts	28/05/2025	0	0	30/07/2025	Repairs	Closed	John Fitzgerald
2206	Repair Leaking Fire Suppression	07/05/2024	0	0	21/02/2024	Repairs	Closed	Operations
1634	Transmission Replacement	07/11/2023	0	0	07/07/2023	Equipment breakdown	Closed	Operations
1627	Replace fan belts	07/11/2023	0	0	02/01/2024	Maintenance	Closed	Operations
1542	Fire Suppression Related Costs	25/10/2023	0	0	02/01/2024	Maintenance	Closed	Chubb Fire Tech
1485	Tyre Related Costs	24/10/2023	0	0	29/12/2023	Maintenance	Closed	Operations
1464	Hitachi - Parts - coolant - Optibelt	24/10/2023	0	0	12/10/2023	Maintenance	Closed	Operations
1263	Hitachi - Engine mounting Kit	12/09/2023	0	0	06/09/2023	Maintenance	Closed	Operations
1244	Hitachi Parts - Speed Sensor Turbine	11/09/2023	0	0	12/06/2023	Maintenance	Closed	Operations
1199	Replace Transmission/ Full of metal	01/09/2023	0	0	29/07/2024	Equipment breakdown	Closed	Operations
1058	Overhaul Centre Axle Ass	21/07/2023	0	0	11/09/2023	Maintenance	Closed	Operations
771	500hr Service - 16468hrs	20/03/2023	0	0	20/02/2023	Routine Service	Closed	Dylan Williams
758	Repairs & Maintenance	15/03/2023	0	0	02/02/2023	Routine Service	Closed	Alistair Ross
757	Repairs & Maintenance	15/03/2023	0	0	01/02/2023	Routine Service	Closed	Alistair Ross