

Repairs were done when WEAR noticed
Truck never broke down

EB06-1

Major Repairs to 2015 F550 Truck.

Oil Changes done by Ford every
8000 km.

oil + fuel filters changed
each time

Truck Deleted about 2016

2020

Thermostat replaced

Vacuum pump replaced.

Air-bags installed and Air levelling Kit

238,945 km Body Control Module replaced

Replaced starter motor

2021

Re sealed Oil Pan

Replaced Drivers side airbag

Replaced Fan Clutch.

NOX Sensor Calibrated

Backup alarm replaced.

New Brakes - front pads and rotors // rear rotors and calipers

CVIP Replaced: Inner axle seals

Left + Right axle shaft U joints

Steering Shocks

Replaced main radiator

2022

Alternator replaced

324,638 km Batteries replaced

New 5th wheel Kingpin installed.

New backup alarm

Replaced Serpentine belt and wiring harness alternator to battery

Radio Replaced (Sirius Radio)

2022 Repairs cont'd.

357,094 km Replaced oil in front & rear diffs and trans/per case

Replaced Transmission filter and oil

Replaced front brake pads and rotors

Serviced brake calipers

Replaced rear brake pads & rotors

Replaced power steering pressure line

Replaced - both front inner axle seals

- axle U joints

- inner and outer hub seals

- track ball joint and bushing

- right outer lower tie rod, set toe, aligned steering

383,328 Replaced both springs left & right side

Replaced water pump

2023 Replaced: front and rear shocks

- charge air hose, rad hose, intercooler hose

- drive belt

- both front hubs

- starter motor

- new thermostat and coolant hose

- gasket by oil filter adapter assembly

- seals on oil pan and crankshaft

418,820 km

- new starter, new batteries

Major Repairs cont'd FS50

CVRP 2023 Replaced jaws on 5th wheel
Replaced upper draglink end and right tie rod end
and track bar end at deffs
Replaced overload wear pads
Replaced exhaust pipe under cab
Replaced front driveshaft

2024

433,500km Replaced air bag air compressor
Replaced broken Steering dampener assembly
Replaced A/C Compressor and Schrader valves and AC clutch

Truck to Grorgi's Auto body for detailing

Owner dies

451,480km New power steering pump.