

W/O No	Asset No	Asset Description	Finished Date/Time	Job Type
3725	SP007	Screen	07/30/2010	PM Service
3809	SP007	Screen	07/22/2010	B/dwn Unpl
4028	SP007	Screen	07/24/2010	B/dwn Unpl
4029	SP007	Screen	07/19/2010	B/dwn Unpl
4347	SP007	Screen	08/20/2010	PM Service
4348	SP007	Screen	09/05/2010	PM Service
4419	SP007	Screen	08/04/2010	B/dwn Unpl
4494	SP007	Screen	08/05/2010	Component
4495	SP007	Screen	08/04/2010	B/dwn Unpl
4525	SP007	Screen	08/05/2010	B/dwn Unpl
4560	SP007	Screen	06/04/2011	Plnd/Maint
4569	SP007	Screen	08/08/2010	Plnd/Maint
4788	SP007	Screen	03/24/2011	B/dwn Unpl
4907	SP007	Screen	08/14/2010	Inspection
4910	SP007	Screen	08/14/2010	Plnd/Maint
5096	SP007	Screen	08/01/2010	B/dwn Unpl
5131	SP007	Screen	08/13/2010	B/dwn Unpl
5133	SP007	Screen	08/15/2010	B/dwn Unpl
5471	SP007	Screen	09/22/2010	PM Service
5524	SP007	Screen	12/27/2010	B/dwn Unpl
5549	SP007	Screen	08/20/2010	B/dwn Unpl
5552	SP007	Screen	08/22/2010	B/dwn Unpl
5971	SP007	Screen	08/25/2010	Plnd/Maint
6088	SP007	Screen	10/17/2010	PM Service
6191	SP007	Screen	09/04/2010	B/dwn Unpl
6211	SP007	Screen	08/20/2010	B/dwn Unpl
6212	SP007	Screen	08/21/2010	B/dwn Unpl
6213	SP007	Screen	09/05/2010	B/dwn Unpl
6214	SP007	Screen	09/05/2010	B/dwn Unpl
6215	SP007	Screen	09/07/2010	B/dwn Unpl
6457	SP007	Screen	09/09/2010	B/dwn Unpl
6458	SP007	Screen	09/10/2010	B/dwn Unpl
6460	SP007	Screen	09/12/2010	B/dwn Unpl
6461	SP007	Screen	09/13/2010	B/dwn Unpl
6462	SP007	Screen	09/13/2010	B/dwn Unpl
6567	SP007	Screen	09/12/2010	B/dwn Unpl
6592	SP007	Screen	09/15/2010	B/dwn Unpl
6666	SP007	Screen	12/04/2010	Plnd/Maint
6686	SP007	Screen	09/19/2010	B/dwn Unpl
7371	SP007	Screen	02/15/2011	PM Service
8107	SP007	Screen	03/12/2011	PM Service
8889	SP007	Screen	11/29/2010	Component
10302	SP007	Screen	01/19/2011	Plnd/Maint

11201 SP007	Screen	12/27/2010 Plnd/Maint
11212 SP007	Screen	12/27/2010 Plnd/Maint
11468 SP007	Screen	01/07/2011 Component
11950 SP007	Screen	01/11/2011 B/dwn Unpl
11951 SP007	Screen	01/12/2011 Inspection
12269 SP007	Screen	01/19/2011 B/dwn Unpl
12414 SP007	Screen	01/23/2011 B/dwn Unpl
12597 SP007	Screen	01/25/2011 B/dwn Unpl
12732 SP007	Screen	01/29/2011 B/dwn Unpl
12993 SP007	Screen	03/01/2011 Plnd/Maint
13005 SP007	Screen	02/06/2011 PM Service
13036 SP007	Screen	02/03/2011 B/dwn Unpl
13107 SP007	Screen	02/06/2011 B/dwn Unpl
13329 SP007	Screen	02/07/2011 B/dwn Unpl
13935 SP007	Screen	02/21/2011 B/dwn Unpl
14474 SP007	Screen	02/26/2011 B/dwn Unpl
14511 SP007	Screen	02/26/2011 B/dwn Unpl
14512 SP007	Screen	02/23/2011 B/dwn Unpl
14514 SP007	Screen	02/25/2011 B/dwn Unpl
14638 SP007	Screen	03/02/2011 B/dwn Unpl
14726 SP007	Screen	03/03/2011 B/dwn Unpl
14727 SP007	Screen	03/03/2011 Inspection
14741 SP007	Screen	03/02/2011 B/dwn Unpl
14799 SP007	Screen	03/04/2011 B/dwn Unpl
14863 SP007	Screen	03/24/2011 B/dwn Unpl
14940 SP007	Screen	03/24/2011 B/dwn Unpl
14959 SP007	Screen	03/06/2011 Plnd/Maint
15490 SP007	Screen	04/17/2011 PM Service
15588 SP007	Screen	03/15/2011 B/dwn Unpl
15589 SP007	Screen	03/12/2011 B/dwn Unpl
15592 SP007	Screen	03/11/2011 B/dwn Unpl
16041 SP007	Screen	03/09/2011 B/dwn Unpl
16250 SP007	Screen	03/27/2011 B/dwn Unpl
16251 SP007	Screen	03/26/2011 B/dwn Unpl
16252 SP007	Screen	03/26/2011 B/dwn Unpl
16253 SP007	Screen	03/24/2011 B/dwn Unpl
16492 SP007	Screen	03/23/2011 B/dwn Unpl
16493 SP007	Screen	03/16/2011 B/dwn Unpl
16494 SP007	Screen	03/18/2011 Plnd/Maint
16495 SP007	Screen	03/20/2011 B/dwn Unpl
16510 SP007	Screen	07/18/2011 Plnd/Maint
16513 SP007	Screen	03/28/2011 B/dwn Unpl
16523 SP007	Screen	03/29/2011 Damage
16697 SP007	Screen	03/31/2011 Plnd/Maint

17445 SP007	Screen	04/09/2011 Plnd/Maint
17600 SP007	Screen	05/15/2011 PM Service
17704 SP007	Screen	04/07/2011 B/dwn Unpl
17705 SP007	Screen	04/08/2011 B/dwn Unpl
17706 SP007	Screen	04/07/2011 B/dwn Unpl
17759 SP007	Screen	04/13/2011 B/dwn Unpl
17895 SP007	Screen	04/15/2011 B/dwn Unpl
18596 SP007	Screen	04/29/2011 Plnd/Maint
19170 SP007	Screen	04/29/2011 Plnd/Maint
19176 SP007	Screen	05/08/2011 Plnd/Maint
19180 SP007	Screen	05/08/2011 B/dwn Unpl
19276 SP007	Screen	05/08/2011 B/dwn Unpl
19443 SP007	Screen	05/29/2011 PM Service
19596 SP007	Screen	07/10/2011 Plnd/Maint
20123 SP007	Screen	05/22/2011 Plnd/Maint
20401 SP007	Screen	05/25/2011 B/dwn Unpl
21154 SP007	Screen	06/05/2011 B/dwn Unpl
21475 SP007	Screen	07/05/2011 Plnd/Maint
21584 SP007	Screen	06/09/2011 B/dwn Unpl
21929 SP007	Screen	05/16/2011 Plnd/Maint
22631 SP007	Screen	07/07/2011 Plnd/Maint
22676 SP007	Screen	06/25/2011 B/dwn Unpl
23184 SP007	Screen	07/07/2011 B/dwn Unpl
23212 SP007	Screen	07/21/2011 PM Service
23710 SP007	Screen	08/30/2011 PM Service
23742 SP007	Screen	09/19/2011 PM Service
24177 SP007	Screen	10/26/2011 PM Service
24628 SP007	Screen	07/22/2011 Plnd/Maint
28774 SP007	Screen	09/09/2011 B/dwn Unpl
29308 SP007	Screen	09/13/2011 Plnd/Maint
29328 SP007	Screen	09/14/2011 B/dwn Unpl
30133 SP007	Screen	10/01/2011 B/dwn Unpl
30324 SP007	Screen	01/13/2012 PM Service
30562 SP007	Screen	09/26/2011 Plnd/Maint
32045 SP007	Screen	10/15/2011 B/dwn Unpl
32307 SP007	Screen	10/13/2011 Plnd/Maint
32308 SP007	Screen	10/15/2011 B/dwn Unpl
32750 SP007	Screen	10/25/2011 B/dwn Unpl
33081 SP007	Screen	10/29/2011 B/dwn Unpl
33333 SP007	Screen	12/28/2011 Plnd/Maint
34315 SP007	Screen	11/13/2011 Plnd/Maint
34750 SP007	Screen	11/19/2011 B/dwn Unpl
34914 SP007	Screen	04/06/2012 PM Service
35099 SP007	Screen	11/23/2011 B/dwn Unpl

37103 SP007	Screen	12/11/2011 Plnd/Maint
37911 SP007	Screen	02/29/2012 Plnd/Maint
37912 SP007	Screen	02/28/2012 Plnd/Maint
37913 SP007	Screen	02/29/2012 Plnd/Maint
37914 SP007	Screen	02/29/2012 Plnd/Maint
37929 SP007	Screen	02/22/2012 Plnd/Maint
37988 SP007	Screen	02/24/2012 Plnd/Maint
38397 SP007	Screen	02/29/2012 Plnd/Maint
39870 SP007	Screen	02/29/2012 Plnd/Maint
41825 SP007	Screen	03/12/2012 Plnd/Maint
42838 SP007	Screen	03/06/2012 Plnd/Maint
43285 SP007	Screen	03/12/2012 B/dwn Unpl
43796 SP007	Screen	03/13/2012 B/dwn Unpl
43912 SP007	Screen	03/31/2012 Inspection
44651 SP007	Screen	03/24/2012 B/dwn Unpl
44661 SP007	Screen	03/22/2012 Plnd/Maint
44753 SP007	Screen	07/31/2012 Plnd/Maint
44754 SP007	Screen	04/06/2012 Plnd/Maint
44819 SP007	Screen	04/15/2012 PM Service
45288 SP007	Screen	04/15/2012 Plnd/Maint
45609 SP007	Screen	05/03/2012 PM Service
45899 SP007	Screen	04/07/2012 B/dwn Unpl
45900 SP007	Screen	04/07/2012 Plnd/Maint
46147 SP007	Screen	07/31/2012 Inspection
46414 SP007	Screen	04/10/2012 Plnd/Maint
46552 SP007	Screen	07/26/2013 Plnd/Maint
46554 SP007	Screen	07/31/2012 Plnd/Maint
47407 SP007	Screen	04/21/2012 Plnd/Maint
47408 SP007	Screen	04/21/2012 B/dwn Unpl
47409 SP007	Screen	06/11/2012 Plnd/Maint
47435 SP007	Screen	04/22/2012 B/dwn Unpl
47448 SP007	Screen	04/22/2012 B/dwn Unpl
47726 SP007	Screen	04/30/2012 Plnd/Maint
47915 SP007	Screen	06/03/2012 PM Service
48048 SP007	Screen	04/29/2012 Plnd/Maint
48685 SP007	Screen	05/04/2012 Plnd/Maint
48686 SP007	Screen	05/04/2012 Plnd/Maint
48687 SP007	Screen	05/04/2012 Plnd/Maint
49229 SP007	Screen	06/19/2012 PM Service
49287 SP007	Screen	05/10/2012 B/dwn Unpl
49978 SP007	Screen	05/09/2012 PM Service
50136 SP007	Screen	05/19/2012 Plnd/Maint
50152 SP007	Screen	05/31/2012 Plnd/Maint
50376 SP007	Screen	05/21/2012 Plnd/Maint

50377 SP007	Screen	05/10/2012 B/dwn Unpl
50637 SP007	Screen	05/23/2012 B/dwn Unpl
51200 SP007	Screen	09/21/2012 PM Service
51430 SP007	Screen	06/01/2012 B/dwn Unpl
51432 SP007	Screen	06/11/2012 B/dwn Unpl
51585 SP007	Screen	06/03/2012 B/dwn Unpl
52109 SP007	Screen	06/07/2012 Plnd/Maint
52834 SP007	Screen	07/31/2012 Plnd/Maint
54436 SP007	Screen	07/31/2012 Plnd/Maint
54496 SP007	Screen	06/30/2012 B/dwn Unpl
54918 SP007	Screen	10/04/2012 PM Service
54946 SP007	Screen	03/16/2013 PM Service
55691 SP007	Screen	08/18/2013 PM Service
58124 SP007	Screen	07/31/2012 Plnd/Maint
58551 SP007	Screen	09/22/2012 Plnd/Maint
58669 SP007	Screen	08/16/2012 Plnd/Maint
58695 SP007	Screen	08/20/2012 Plnd/Maint
58696 SP007	Screen	09/22/2012 Plnd/Maint
59324 SP007	Screen	07/31/2012 Safety
60113 SP007	Screen	08/20/2012 Safety
60312 SP007	Screen	09/06/2012 Plnd/Maint
60313 SP007	Screen	09/02/2012 Plnd/Maint
60623 SP007	Screen	09/02/2012 B/dwn Unpl
60649 SP007	Screen	09/13/2012 Plnd/Maint
62142 SP007	Screen	09/05/2012 B/dwn Unpl
63000 SP007	Screen	09/22/2012 B/dwn Unpl
63098 SP007	Screen	09/13/2012 B/dwn Unpl
63106 SP007	Screen	09/13/2012 B/dwn Unpl
63120 SP007	Screen	03/17/2014 Inspection
63919 SP007	Screen	09/19/2012 B/dwn Unpl
64140 SP007	Screen	09/22/2012 Plnd/Maint
64177 SP007	Screen	09/21/2012 B/dwn Unpl
64414 SP007	Screen	09/26/2012 B/dwn Unpl
65388 SP007	Screen	10/05/2012 Plnd/Maint
71720 SP007	Screen	12/05/2012 Plnd/Maint
71721 SP007	Screen	03/16/2013 Plnd/Maint
75364 SP007	Screen	01/09/2013 Plnd/Maint
77063 SP007	Screen	09/03/2013 B/dwn Unpl
77183 SP007	Screen	03/31/2013 Plnd/Maint
77647 SP007	Screen	04/12/2013 Plnd/Maint
78003 SP007	Screen	08/23/2013 B/dwn Unpl
78684 SP007	Screen	03/16/2013 B/dwn Unpl
79534 SP007	Screen	03/16/2013 Plnd/Maint
79542 SP007	Screen	03/16/2013 Plnd/Maint

86914 SP007	Screen	08/23/2013 B/dwn Unpl
88274 SP007	Screen	05/17/2013 Plnd/Maint
89779 SP007	Screen	05/17/2013 Plnd/Maint
92398 SP007	Screen	07/05/2013 Plnd/Maint
93124 SP007	Screen	07/10/2013 Plnd/Maint
93710 SP007	Screen	07/15/2013 Plnd/Maint
93941 SP007	Screen	08/23/2013 Plnd/Maint
94342 SP007	Screen	09/11/2013 PM Service
94371 SP007	Screen	09/12/2013 PM Service
94416 SP007	Screen	08/23/2013 PM Service
94467 SP007	Screen	04/29/2014 Purchasing
94790 SP007	Screen	07/25/2013 Plnd/Maint
94804 SP007	Screen	07/25/2013 B/dwn Unpl
94818 SP007	Screen	07/26/2013 B/dwn Unpl
95932 SP007	Screen	08/07/2013 B/dwn Unpl
95969 SP007	Screen	08/10/2013 B/dwn Unpl
96052 SP007	Screen	08/13/2013 Plnd/Maint
97071 SP007	Screen	08/21/2013 Plnd/Maint
97126 SP007	Screen	09/22/2013 Plnd/Maint
97791 SP007	Screen	08/28/2013 Plnd/Maint
98622 SP007	Screen	09/12/2013 PM Service
98831 SP007	Screen	09/12/2013 Plnd/Maint
99027 SP007	Screen	09/12/2013 Plnd/Maint
99081 SP007	Screen	10/04/2013 PM Service
99102 SP007	Screen	10/04/2013 PM Service
99721 SP007	Screen	10/24/2013 B/dwn Unpl
100243 SP007	Screen	09/28/2013 Safety
100380 SP007	Screen	10/04/2013 PM Service
100391 SP007	Screen	10/04/2013 PM Service
100550 SP007	Screen	12/07/2013 Plnd/Maint
100698 SP007	Screen	10/11/2013 PM Service
100701 SP007	Screen	03/27/2014 PM Service
100703 SP007	Screen	04/10/2014 PM Service
100844 SP007	Screen	09/26/2013 Plnd/Maint
100845 SP007	Screen	10/06/2013 Plnd/Maint
100846 SP007	Screen	10/07/2013 Plnd/Maint
100915 SP007	Screen	10/07/2013 Plnd/Maint
100916 SP007	Screen	10/07/2013 Plnd/Maint
101093 SP007	Screen	05/01/2014 PM Service
101342 SP007	Screen	10/11/2013 Plnd/Maint
101344 SP007	Screen	10/11/2013 Plnd/Maint
101345 SP007	Screen	10/11/2013 Plnd/Maint
101346 SP007	Screen	10/11/2013 Plnd/Maint
101347 SP007	Screen	10/11/2013 Plnd/Maint

101586 SP007	Screen	10/12/2013 Plnd/Maint
102208 SP007	Screen	03/17/2014 Plnd/Maint
103144 SP007	Screen	11/02/2013 Plnd/Maint
105741 SP007	Screen	03/17/2014 B/dwn Unpl
106189 SP007	Screen	03/17/2014 Plnd/Maint
107029 SP007	Screen	04/24/2014 Purchasing
108519 SP007	Screen	04/26/2014 Plnd/Maint
108777 SP007	Screen	02/21/2014 Plnd/Maint
110089 SP007	Screen	03/17/2014 Plnd/Maint
110097 SP007	Screen	03/17/2014 Plnd/Maint
110562 SP007	Screen	03/17/2014 Plnd/Maint
111712 SP007	Screen	03/17/2014 Plnd/Maint
111952 SP007	Screen	03/17/2014 Safety
116009 SP007	Screen	03/31/2014 Plnd/Maint
116145 SP007	Screen	04/12/2014 Plnd/Maint
116272 SP007	Screen	05/15/2014 PM Service
116283 SP007	Screen	04/03/2014 Inspection
117227 SP007	Screen	06/04/2014 PM Service
117231 SP007	Screen	07/03/2014 PM Service
117311 SP007	Screen	04/29/2014 Plnd/Maint
117486 SP007	Screen	04/29/2014 Plnd/Maint
117820 SP007	Screen	05/01/2014 Inspection
117870 SP007	Screen	04/28/2014 Plnd/Maint
117883 SP007	Screen	04/24/2014 B/dwn Unpl
117887 SP007	Screen	04/26/2014 Inspection
118028 SP007	Screen	05/03/2014 B/dwn Unpl
118386 SP007	Screen	05/15/2014 Plnd/Maint
118449 SP007	Screen	07/15/2014 Plnd/Maint
118572 SP007	Screen	07/15/2014 Plnd/Maint
119303 SP007	Screen	05/16/2014 Plnd/Maint
119305 SP007	Screen	05/15/2014 Plnd/Maint
119308 SP007	Screen	05/15/2014 Plnd/Maint
119583 SP007	Screen	05/21/2014 Inspection
119590 SP007	Screen	05/21/2014 Plnd/Maint
119711 SP007	Screen	07/21/2014 PM Service
119806 SP007	Screen	07/15/2014 Plnd/Maint
119969 SP007	Screen	07/15/2014 Plnd/Maint
120812 SP007	Screen	07/26/2014 PM Service
121251 SP007	Screen	06/05/2014 Plnd/Maint
121363 SP007	Screen	06/03/2014 B/dwn Unpl
121364 SP007	Screen	06/11/2014 Plnd/Maint
121544 SP007	Screen	07/01/2014 Plnd/Maint
121889 SP007	Screen	08/14/2014 PM Service
122353 SP007	Screen	06/25/2014 Plnd/Maint

123294 SP007	Screen	09/29/2014 PM Service
123646 SP007	Screen	11/01/2014 PM Service
124174 SP007	Screen	06/11/2014 B/dwn Unpl
124175 SP007	Screen	06/21/2014 B/dwn Unpl
124176 SP007	Screen	06/26/2014 B/dwn Unpl
124177 SP007	Screen	06/30/2014 B/dwn Unpl
124461 SP007	Screen	07/27/2014 Plnd/Maint
124528 SP007	Screen	11/22/2014 PM Service
124546 SP007	Screen	09/01/2014 Plnd/Maint
124699 SP007	Screen	08/01/2014 B/dwn Unpl
124701 SP007	Screen	08/03/2014 Plnd/Maint
124703 SP007	Screen	08/16/2014 Plnd/Maint
124841 SP007	Screen	08/04/2014 Plnd/Maint
125852 SP007	Screen	10/24/2014 Plnd/Maint
125904 SP007	Screen	03/27/2015 Plnd/Maint
127679 SP007	Screen	10/24/2014 Plnd/Maint
128124 SP007	Screen	12/22/2014 Plnd/Maint
128369 SP007	Screen	10/03/2014 Plnd/Maint
128479 SP007	Screen	09/25/2014 B/dwn Unpl
128592 SP007	Screen	11/19/2014 Plnd/Maint
129178 SP007	Screen	10/25/2014 Plnd/Maint
129253 SP007	Screen	10/28/2014 Plnd/Maint
129747 SP007	Screen	10/16/2014 B/dwn Unpl
129748 SP007	Screen	10/23/2014 B/dwn Unpl
130584 SP007	Screen	12/07/2014 B/dwn Unpl
130610 SP007	Screen	03/08/2015 B/dwn Unpl
130978 SP007	Screen	11/15/2014 Plnd/Maint
131302 SP007	Screen	12/01/2014 PM Service
131327 SP007	Screen	12/15/2014 PM Service
131369 SP007	Screen	01/02/2015 PM Service
131605 SP007	Screen	03/08/2015 Plnd/Maint
131775 SP007	Screen	02/05/2015 PM Service
131799 SP007	Screen	04/15/2015 Safety
131962 SP007	Screen	11/28/2014 B/dwn Unpl
132455 SP007	Screen	02/01/2015 Plnd/Maint
132977 SP007	Screen	03/08/2015 Plnd/Maint
133070 SP007	Screen	11/08/2014 B/dwn Unpl
133293 SP007	Screen	03/26/2015 B/dwn Unpl
133706 SP007	Screen	02/25/2015 PM Service
134143 SP007	Screen	01/02/2015 Plnd/Maint
134144 SP007	Screen	02/22/2015 Plnd/Maint
134220 SP007	Screen	12/27/2014 B/dwn Unpl
134221 SP007	Screen	01/04/2015 B/dwn Unpl
134225 SP007	Screen	12/09/2014 B/dwn Unpl

134258 SP007	Screen	12/29/2014 Plnd/Maint
134471 SP007	Screen	03/08/2015 Plnd/Maint
134489 SP007	Screen	02/24/2015 Plnd/Maint
134658 SP007	Screen	03/08/2015 PM Service
134795 SP007	Screen	01/20/2015 B/dwn Unpl
134851 SP007	Screen	01/18/2015 Plnd/Maint
135014 SP007	Screen	03/08/2015 B/dwn Unpl
135103 SP007	Screen	03/15/2015 Plnd/Maint
135241 SP007	Screen	01/26/2015 Plnd/Maint
135366 SP007	Screen	02/04/2015 Plnd/Maint
135473 SP007	Screen	03/08/2015 B/dwn Unpl
135542 SP007	Screen	02/14/2015 B/dwn Unpl
135873 SP007	Screen	03/22/2015 PM Service
135875 SP007	Screen	04/04/2015 PM Service
136175 SP007	Screen	04/15/2015 Plnd/Maint
136258 SP007	Screen	03/22/2015 Plnd/Maint
136442 SP007	Screen	02/05/2015 Plnd/Maint
136454 SP007	Screen	12/14/2014 B/dwn Unpl
136959 SP007	Screen	03/08/2015 Plnd/Maint
137255 SP007	Screen	02/25/2015 Plnd/Maint
137283 SP007	Screen	04/04/2015 Purchasing
137300 SP007	Screen	02/27/2015 Plnd/Maint
137803 SP007	Screen	04/08/2016 Safety
138090 SP007	Screen	04/02/2016 PM Service
138168 SP007	Screen	02/05/2015 Plnd/Maint
138169 SP007	Screen	02/09/2015 Plnd/Maint
138175 SP007	Screen	12/01/2014 Plnd/Maint
138192 SP007	Screen	03/13/2015 Plnd/Maint
138236 SP007	Screen	03/08/2015 Plnd/Maint
138239 SP007	Screen	03/08/2015 Plnd/Maint
138303 SP007	Screen	03/22/2015 Plnd/Maint
138827 SP007	Screen	12/05/2016 PM Service
138981 SP007	Screen	04/04/2015 B/dwn Unpl
138984 SP007	Screen	04/10/2016 B/dwn Unpl
139021 SP007	Screen	03/02/2015 B/dwn Unpl
139027 SP007	Screen	03/26/2015 Plnd/Maint
139294 SP007	Screen	04/11/2015 Plnd/Maint
139445 SP007	Screen	04/06/2015 B/dwn Unpl
139608 SP007	Screen	04/09/2015 B/dwn Unpl
140024 SP007	Screen	04/17/2019 PM Service
140610 SP007	Screen	04/08/2016 Plnd/Maint
140611 SP007	Screen	04/10/2016 Plnd/Maint
140614 SP007	Screen	04/10/2016 Plnd/Maint
140616 SP007	Screen	04/17/2019 Plnd/Maint

140617 SP007	Screen	04/10/2016 Plnd/Maint
140618 SP007	Screen	04/10/2016 Plnd/Maint
140619 SP007	Screen	04/17/2019 Plnd/Maint
140620 SP007	Screen	04/10/2016 Plnd/Maint
140621 SP007	Screen	04/02/2016 Plnd/Maint
154864 SP007	Screen	04/08/2016 Plnd/Maint
156807 SP007	Screen	04/08/2016 Plnd/Maint
165532 SP007	Screen	12/14/2016 PM Service
165880 SP007	Screen	02/16/2017 Plnd/Maint
169054 SP007	Screen	05/14/2018 Plnd/Maint
169148 SP007	Screen	02/27/2017 Plnd/Maint
169673 SP007	Screen	03/10/2017 Plnd/Maint
172691 SP007	Screen	04/17/2019 B/dwn Unpl
173466 SP007	Screen	04/17/2019 Plnd/Maint
176640 SP007	Screen	07/18/2017 B/dwn Unpl
182761 SP007	Screen	02/20/2021 Plnd/Maint
184112 SP007	Screen	05/17/2017 Plnd/Maint
189697 SP007	Screen	04/17/2019 Plnd/Maint
203648 SP007	Screen	04/17/2019 Plnd/Maint
205954 SP007	Screen	04/11/2019 Safety
206204 SP007	Screen	04/18/2019 PM Service
206205 SP007	Screen	04/18/2019 PM Service
206206 SP007	Screen	04/18/2019 PM Service
206208 SP007	Screen	04/18/2019 PM Service
206212 SP007	Screen	04/18/2019 PM Service
206213 SP007	Screen	04/18/2019 PM Service
216393 SP007	Screen	09/11/2019 Plnd/Maint
221086 SP007	Screen	01/14/2020 Plnd/Maint
233712 SP007	Screen	03/23/2023 Plnd/Maint
244773 SP007	Screen	02/25/2021 Plnd/Maint
246525 SP007	Screen	03/01/2021 PM Service
246528 SP007	Screen	03/01/2021 PM Service
246539 SP007	Screen	03/01/2021 PM Service
246622 SP007	Screen	03/31/2021 B/dwn Unpl
247570 SP007	Screen	03/31/2021 PM Service
249902 SP007	Screen	12/05/2022 PM Service
252963 SP007	Screen	08/09/2022 PM Service
260325 SP007	Screen	02/17/2024 PM Service
266233 SP007	Screen	08/22/2022 Plnd/Maint
266676 SP007	Screen	08/22/2022 Plnd/Maint
282902 SP007	Screen	07/25/2023 Plnd/Maint
292378 SP007	Screen	01/24/2024 Plnd/Maint

Description

Str SC Track Screen 1000hr

SP007 - Wont start, Isolated then started machine

SP007 - Tighten loose track belt and hose

SP007 - Wont start, check for faults

Str SC Track Screen 250hr

Str SC Track Screen 500hr

SP007 - repair wing conveyor,

SP007 - Damage wing conveyor

SP007 - Hydraulic hose leaking

SP007 - Bottom screen deck broken

SP007 - fit quick fill fuel linesR.Davis - Job closed due to age, no info

SP007 - replace ring gear and inspect coupling AND BROKEN SCREEN DECK

SP007 - fuel solenoid fault

SP007 - defects

SP007 - carry out electrical service

SP007 - Alternator fault

SP007 - Defect day

SP007 - Bearing housing loose on lift conveyor head polly

Str SC Track Screen 250hr

SP007 - wing conveyor damaged

13

SP007 - Repair lift conveyor & tail drum skirt.

Changed out water pump & replaced orings & seals. drained coolant from sump & flushed engine with c ...

Str SC Track Screen 2000hr

SP007 - Repairs to rollers - x1 damaged, x1 fallen out

SP007 - Curtain broken

SP007 - Tear in belt on oversized conveyor

SP007 - Repair hopper supports

SP007 - Change skirt

SP007 - Fit hydraulic motor on belt feeder

SP007 - Push skirt back in place & re-tighten clamp

SP007 - RPM & temp gauge faults

SP007 - Conveyor not starting

SP007 - Fabricate & install new screen clamps

SP007 - Fines conveyor u/speed fault

SP007 - Belt tracking to one side

SP007 - Not holding charge

SP007 - Install fire supression

SP007 - Repair cracks in screen deck

Str SC Track Screen 250hr

Str SC Track Screen 500hrAs per service sheet

Remove main feed conveyor and remove screen and send to burton for overhaul. carry out overhaul on ...

SP007 - Rebuild Product Conveyor

SP007 - Modify Guards, Fab & Drill Plates
SP007 - Install Valve Banks, connect hydraulic hoses, run up & test for leaks
SP007 Reset pressures and belt speeds after valve banks have been overhauled
SP007 - Replace fuel stop solenoid
SP007 - Replace Missing Guards
Engine cutting out
SP007.Exhaust muffler loose
SP007.Hydraulic leak
SP007 LOOSE SKIRT AND CLAMP BAR.REFITTED SKIRT AND CLAMP BAR WITH NEW BOLTS RETIGHTEN BOLTS ON NIC
SP007.Exciter bearing control side leaking grease
SP007 - Preventative Maintenance
SP007.Discharge conveyor stopping
SP007.Blown hydraulic hose on control side rear leg
SP007.Product conveyor stopping
Refit guard around the exciter on the control side of the screen.
SP007.Low hydraulic oil
SP007.Screen speed going too fast
SP007.leaking hydraulic quick connect fitting
SP007.bogged lift conveyor.
SP007.Hydraulic leak
SP007.Skirts missing from lift conveyor
Sp007.fault
SP007.Engine noise
SP007.Low hydraulic oil
SP007. Engine making knocking.
SP007 - faulty oil pressure switch
SP007.Prevenative Maintenance
Str SC Track Screen 1000hr
Skirt on lift conveyerChanged skirt on lift conveyer
Feeder belt slippingadjusted feeder belt and tracked
Feeder conveyer belt adjuster broken, skirt clamp missing and wedgesRepair belt adjusterFab a ...
SP007 - Replace worn skirts
SP007.Missing skirts
SP007.Bogged side conveyor
SP007.No oil in motor
SP007.Replace spinner
SP007.Missing skirts on lift conveyer
SP007.Missing skirts
SP007.Electrical service
SP007.Hydraulic leak from stacket quick connection
SP007.Drill rod in feed hopper tearing belt
SP007.Split in side conveyor belt
BROCKEN AIR CLEANER ON CONTROL BOX. SOURCED NEW PRE FILTER AND INSTALLED
SP007 - Remove & Replace Starter Motor, order in spare starter to replenish stocksCheck starter m ...

Side conveyer belt repairsInstall new belt using flexco hinge jointCut belt to length 21,85 ...
Str SC Track Screen 250hr
SP007.Remove toggle plate from lift conveyor
SP007.Bogged lift conveyor
SP007.Screen box came off springs
Burning electrical smell coming from electrical cabinet.
SP007.Wont start
SP007.Screen hydraulic motor leaking.
SP007.Preventative maintenance
SP007.Preventative maintenance
SP007.Blocked screen
SP007.Machine wont start
Str SC Track Screen 500hr
Change out hyd hoses
Starter motor sticky / DefectsStarter motor pinion seizedReplaced starter with 2nd hand start ...
SP007.Discharge conveyor lanyard broken
Oversize conveyor hyd motor leakFront seal on motor leakingChange out motor with 1 x OMV500 ...
SP007 - Inspect operation of Tacho
Tramming remote reciver cardRemoved reciver card from machine and spoke to datekOrganise to s ...
SP007 - Check for machine not startingCheck starting operation.Diagnose fault to starter rela ...
SP007 - New engine being ordered by Burton - Expected arrival to site approx 7/7/2011. Arrange chan ...
Radiator sensor fault Found fault with murphy coolant level switchsensor bridged. But still h ...
SP007 - Remove and refit new engine
Str SC Track Screen 250hr
Str SC Track Screen 500hr service completed
Str SC Track Screen 250hr service completed
Str SC Track Screen 1000hr service completed
SP007.Prep machine to send off site
SP007 Repaired wiring loom & horn alarm
SP007 Carried out eletrical inspection/PM service of machine
SP007 Replaced contact blocks on start & stop P/B
SP007-Remove & replace faulty starter motor
SP007 - See work Order #38397 Service completed during Burton Shutdown.
SP007-Installation of umbylical cable to provide 24vdc power supply for ST005 wigher
SP007 Rectify hydraulic surging on screen. Tightened hoses & replaced filters in storage tank & hig ...
SP007 Repair oversize conveyor. Replaced worn rollers, chute, repaired arm stoppers, patched hole o ...
SP007 Replace wear plates inside hopper
SP007 Change out screens
SP007 Replace worn conveyor skirt
SP007 De-mobilisation of screen
SP007 Re-commission screen to go back into operation
SP007 Replace skirt on main lift conveyor & weld wear plate on. Also re-bolted skirt rail down wit ...
Str SC Track Screen 500hr
SP007 Replace blown engine oil hose & gaskets

SP007 Replace nylon plate to belt guide bracket

SP007 - Burton Shut, Feeder conveyor, removed feeder belt & skirts, removed & replaced worn, siezed ...

SP007 - Burton Shut, Hydraulic Oils, Hoses, Fittings, Motors & Valve Banks

SP007 - Burton Shut, Feed Hopper, removed hopper from machine, stripped & cut out layers of wear pl ...

SP007 - Burton Shut Chubb Fire removed old fire suppression system & installed complete new system. ...

SP007 - Burton Shut, Checked wiring & conduit on emergencyE stops, replaced emergency E stop N/C co ...

SP007 - Burton Shut, Removed screens from both decks, removed old capping rubber, repaired 2 x cros ...

SP007 - Burton Shut, Drained engine oil, replaced filters, removed & replaced engine radiator fan & ...

SP007 - Burton Shut, Remove 2 x track plates & split track chain, removed siezed bolts from drive s ...

SP007 - Burton Shut, Mask up hydraulic lines, hoses, door handles, hand rails & signage, sand rough ...
commissioning

Pirtek completed job

Screen was smashed. Fitted new screen

March Rema tip top inspections

Screen change and repairs

Electrical service

SP007 - Skirt extensions were fitted when machine arrived at pre-strip.

SP007 - Check Hydraulic pressures & belt speeds on conveyor belts

Str SC Track Screen 250hr

SP007 Screw reducing nipple to hydraulic oil tank lid and fit quick release nipple and dust cap.

Str SC Track Screen 2000hr

SP007 - No start, diagnose and repair. found starter motor u/s. Replaced and tested.

SP007 - eletrical service

FRC annaul inspection

Side conveyor slowing down under load.

SP007 - Repair rear access door & brackets above tail drum of lift conveyor so that it can be unbol ...

SP007 No trades details or spares added to Mex, underspeed on lift conveyor is fully functional.

Defects- Hole in side conveyor hopper - Skirts in side conveyor - Curtian f ...

Fan belts brokenReplace broken fan belts

Stock order- Fan belts

SP007 - Replace side conveyor adjusting bolts

Screen feeder boggedRepair skirt and un-bog feeder conveyorAdjust skirt and repair on side co ...

April conv belt inspections

Str SC Track Screen 250hr includes valve set

SP007 - Defects 27-4-12See tasks for details.

Side conveyor repairsMade and bolted plates to arms to close pivot on conveyor so belt tracks s ...

Discharge scraper hangingRepair rubber in scraper, Replace bolts

Side conveyor skirts and curtianReplaced curtian on side conveyorDropped skirts downReploac ...

Str SC Track Screen 500hr

Cut out plow from side conveyorOxy cut out belt plowTracked side conveyor belt

Replace control side side conv

SP007 - Replace fittings on check valve on lift conveyor

May Rema tip top conv inspections

SP007 - Replace leaking speed controls for side conveyors and replace o-ring ontop for low pressure ...

SP007 - Side conveyor non control side bogging due to rollers sagging forward and allowing rock to po ...
 Replace broken screen, remove old screen and instal new screen
 Str SC Track Screen 250hr
 SP007 - Non control side screen bearing locked up
 Screen Bearings Stock Order
 Tension loose alternator belt
 Elec - lift conveyor - install underspeed prox, control panel - fit new latches
 stock order Altenator belts
 Decommission Unit for transport off site
 June belt inspections and repairs
 Str SC Track Screen 1000hr
 Str SC Track Screen 250hr ALL SERVICE HOURS WORKED ARE AGAINST 77647. MEX INSPECTION SHEET WAS NOT ...
 Str SC Track Screen 500hr
 July Belt Inspections
 SP007 - Boiler maker repairs (See Tasks)
 SP007 - Repair Hydraulic Leaks (See Task List)
 SP007 - Electrical Checks & repairs (See Tasks)
 SP007 - Replace Skirts & Rollers (See Tasks)
 SP007 - Level 1 Fire Supression Service - Chubb
 SP007 - Make Up New Gates
 SP007 - Stock Order 40mm Screens, Fit new Screens
 SP007 - Commishion Circuit, Live Testing & Adjusting
 SP007 - Crusher Remote Not Working
 SP007 - Feeder Belt, Remove & Replace (Outlaw Coatings & Conveyors)
 SP007 - Engine Not Turning Over
 SP007 - Circuit Breaker Faulting
 SP007 - Machine Stopped, changed out emergency stop lanyard, fond mechanism siezed, repaired.
 SP007 - Rock Jammed in Drum
 SP007 - Design & Install Scraper for Conveyor
 SP007 - Check all lanyards for fault & test, found corroded contacts in safety switch, replace fault ...
 SP007 - Removed guard, removed 3mm plate from guard, cut & weld in 50 x 50mm mesh & refitted guard.
 SP007 - Bogged Side Conveyor Non Control Side, removed rocks jammed in side conveyor, cleared machi ...
 SP007 - Feeder Belt Slipping
 SP007 - Demob Screen - prestarted, put on washpad & cleaned. prepare conveyor for demob. repair cra ...
 SP007 - Set Up Machine Ready For Service. Unfloded side conveyors, raised walkways around screen & ...
 SP007 - Side Conveyor, Fabricate New Side Conveyor.
 SP007 - Removed guards, backed off belt tensioners, cut old belt & nailed new belt to the old belt, ...
 SP007 - Replace engine oil cooler hose. Work order closed with no hours as this repair was done at ...
 SP007 - Screens received
 SP007 - Removed & replaced skirts on lift conveyor, removed support leg & replaced damaged fitting ...
 SP007 - Repair oil leak om engine
 SP007 Changeout screen bearings. AS WELL AS TASKS, THE FOLLOWING WAS ALSO DONE; Removed feeder belt ...
 SP007 Replace feeder conveyor belt. BELT REPLACED BY FENNER DUNLOP AT DUBLIN
 SP007 Replace non control side tail drum bearings. WORK ORDER CLOSED WITH NO HOURS. ALL HOURS ARE A ...

SP007 - Fabricate hyd hose for stacker and fit

SP007 - Unfold at Burton yard, run whole plant, fully inspect, fullt clean, fold up ready for despa ...

SP007 The repairs carried out on this task list were completed under work order 77647

SP007 - Prepare machine for site compliance Gove NT and commision - fitted guards changed hyraulic ...

Weld grizzlies to machine - Track CVI belt, welded on Broken Swivel Brackets on grizzlies

install rubber matts on top deck of screen - made up and installed slide mats on top deck start to ...

SP007 - Order in LED lights and electrical spares

Cancelled due to incorrect work order closure resulting in incorrect PM activation - Str SC Track S ...

Cancelled due to incorrect work order closure resulting in incorrect PM activation - Str SC Track S ...

SP007 - Spare parts order for filters

SP007 - Critical Spares - Order via National Plant Dept as per Critical Spares List reviewed by sit ...

SP007 - Cut out grizzley's

SP007 - Remove steel in screen deck

SP007 - Lift conveyor broken

SP007 - Repair hydraulic leak at valve bank

SP007 - Make up hose for leak at valve bank

6monthly fire suppression test & tag

SP007 - Remove grizzly from rear of machine

SP007 - Repair walkways, handrails & guards - advised to close by Jasper - MO cant find job reports ...

SP007 - Adjust alternator belts

Str SC Track Screen 250hr

Fix discharge conveyor running problem and fit poly ripple screens. Bully and Johhno did the screen ...

SP007 Make new rubber curtain for non control side conveyor

Cancelled due to changes to PM Policies resulting from standard review - Str SC Track Screen 2000 ...

Cancelled due to changes to PM Policies resulting from standard review - Str SC Track Screen 250hr

SP007- Starter motor not engaging, Removed hydraulic pumps,span fly wheel 180 degrees, put pumps ba ...

SP007 - Replace Emergency Stop Button and Enclosure - Replaced emergency stop button and enclosure

Cancelled due to changes to PM Policies resulting from standard review - Str SC Track Screen 500hr

Cancelled due to changes to PM Policies resulting from standard review - Str SC Track Screen 250hr

SP007 - Replace Battery's - Batteries was replaced with the ones out of SP003, cant find any job rep ...

Str SC Track Screen 2000hr

Str SC Track Screen 250hr

Str SC Track Screen 500hr

SP007- Replace Hydraulic oil tank sight glass

SP007- fit snorkel to air intake- Fabricated brackets and joined two pieces of pipe to extend the a ...

SP007-Replace top screen matt- made up clamps to holdddown screens in the centre to stop them vibrat ...

SP007- replace Taco. Electritians replaced taco and found the problem was not the taco but the alte ...

SP007- Fix lanyard and fit work lights

Str SC Track Screen 250hr

SP007-ELEC- Fit anderson plugs to machine to make jump starting easier

SP007-Screen- Replace broken screen matt on top deck - Removed bottom screen on top deckand replace ...

SP007-Engine- Check fire suppression bollte bracket, found loose strap and tightened up strap

SP007-Hydraulics-Screen motor hosses leaking, found hoses rubbing on frame work, tied conv over hos ...

SP007-Feeder- Rollers in feeder seized up, found rollers wasnt seized just the belt wasnt touching ...

SP007- Elec-Alternator not charging propper, replaced brushes and regulator on alternator
SP007 - Engine-Replace radiator fan. Work completed by Fernando at Cloudbreak
SP007-Electrical-Install imbilical cord between SC011 and SP007. Installed interface cable to shut ...
SP007 - Prepare machine for demob off site as per task list
SP007 - Electrical Upgrades For New Project
SP007 - Critical spares order for Cloudbreak EXWA0014 - ok to close as per DS
SP007 - Prepare screen for site use at Cloudbreak & Commission - ok to close as per DS
SP007 Replace fuel transfer pump.
SP007 - Defects - repairs to brackets, rear skirt holder, bent supports
SP007 - Replace Starter Motor
SP007 - Defects to do list tasks
SP007 - Purchase 14mm D type Flex Mats
SP007 - Purchase replacement OEM Manual for machine
SP007 Carry out skirt repairs to screen dischrge rubber curtain,removed old clamping bar and replac ...
SP007 Works off task list for plant conveyors, welded stuaff clamps to hold screen motor hoses, rem ...
Str SC Track Screen 1000hr
SP007 Electrical checks while plant is down - completetd elec checks
Str SC Track Screen 250hr - service completed
Str SC Track Screen 500hr. uncompleted tasks due to manning and time restraints. PC
SP007 Tasks off to do list that have been completed during previous services/ pre-starts/ other wor ...
INSPECT HYDRAULIC HOSE LEAKS
SP007 Carry out weekly electrical inspections
SP007- replace screen and capping rubber. - replace screen and copping rubber
SP007 - Weekly Elec Inspection -inspection carried out as per service checklist
SP007 - Weekly Elec Inspections - weekly elec inspections carried out as per service sheet
SP007- replace holed screen.
SP007 Fit 16mm flexi mats to pos #2, 3, 4 and 5 on the top deck. Measure for hand rails to be fitte ...
SP007 Order in a new starter motor.
SP007- Order and replace Electrical cabinet air filter
SP007-ELECTRICAL- weekly electrical inspections as per service checklist
SP007-BELT SCRAPERS-inspect and replace all belt scrapers
SP007-SCREEN- fix leak on screen motor hydraulic fittings
SP007 Replace discharge conveyor lanyard switches. Electrical checks as per inspection sheet - carr ...
SP007 Fit longer alternator bracket. - change out bracket on alternator had to grind back edge of n ...
Str SC Track Screen 250hr
SP007 Order 16mm app poly ripple screens
SP007 Intermittent problem with feeder conveyor. PROBLEM NEDED UP BEING A FAULTY PVG VALVE DIN PLUG ...
Str SC Track Screen 2000hr. HYDRAULIC TANK SIGHTGLASS CHANGED. TASKS NOT COMPLETED DUE TO MANNING /
SP007 - Replace Skirts - change out skirts and alter mounts bracket to hold bigger side skirt above ...
SP007 - Alternator u/s - Changed out alernator
SP007 - Weekly Elec Checks - carried out weekley elec check as per chekc sheet
SP007 JUNE SHUT Re-configure screen mats to suit non control side conveyor installation of NC004 - ...
Str SC Track Screen 250hr
SP007 Make and fit hand rails for SP006/ SP007 to be fitted onto the discharge belt so that fitters ...

Str SC Track Screen 500hr - Service Complete

Str SC Track Screen 250hr

Replace faulty relay on feeder belt circuit.

Replace broken screen on top deck.

Found wiring getting hot. Removed cables, replaced cables.

Replace rollers, tension belt, track belt.

SP007 various tasks off defects list. - fit rubber skirt to existing skirt (rear) to cover hole an ...

Str SC Track Screen 1000hr

SP007 order in 16mm poly ripple screen mats

SP007 Replace starter motor - Replaced Starter Motor

SP007 C/S side conveyor loosen and re-adjust- (JV - JS 3/8) changed rollers, repair seized conveyor ...

SP007 replace pos #1, 2, 4 and 5 screen mats bottom deck - (JV 01/8) Changed screen mats. (MG 16/8) ...

SP007 replace all new lanyard switches and underspeed - (RP 3/8) Install new underspeed sensor/lany ...

SP007 Changeout screen mats to suit application at BC Iron

SP007 Re-location of lanyard brackets and defects. ORDER CLOSED WITHOUT ANY JOB SHEETS. WORKS HAVE ...

SP007 - Fit piano wires to top deck

SP007-stock order 3.15mm screens

SP007 - Prepare for remove

SP007 - Piano wires broken

SP007 Order in outer air filters

SP007 order in 7" top spin filters

SP007 Order in a new alternator with a new pulley. WESTRAC SUPPLIED ALTERNATOR AND PULLEY IN THIS W ...

SP007 Replace both batteries and check starter motor fault

SP007 replace engine oil hoses coming from oil filter to and from engine block

SP007 Order in starter motor and one for spare. Order in a spare 24V alternator

SP007-Wont start. Took starter motor out of PP001 to get SP007 going. When the new starter motors o ...

Replace top deck screen

Str SC Track Screen 250hr (Perkins)

Str SC Track Screen 500hr (Perkins). NOT ALL CHECKS DONE DUE TO MANNING AND CRUSHING REQUIREMENTS

Str SC Track Screen 250hr (Perkins)

SP007 - Left arm belt change - Non Control Side - ok to close as per Paul Casamento

Str SC Track Screen 2000hr (Perkins). Mechanical checks not carried out due to production requireme ...

Fire Suppression System Service and Inspection (Standard Job)inspected - completed by PWR in de ...

REPLACE POS1 SCREEN MAT

SP007 - Order and supply of bearing assemblies

SP007 defects and modify alternator bracket to allow more adjustment. New part on order are still 3 ...

SP007 Engine not running. Work carried out by Geoff Shephard.

SP007-Repair oil leak from engine cover gasket

Str SC Track Screen 250hr (Perkins). Also repaired by Harvs and Joch on N/S feeder conveyor sightgl ...

replace top deck screen mat

Stock order 3.15 screens x 10

diagnose and rectify starting problem / electrical fault

Engine not startingFault was esr relay contacts not operating , replaced coil

Batteries flat Belts loose / retightened tested charging ok

adjust skirts on lift conveyor install 4 drop curtains under screen box
SP007 Supply new discharge conveyor head drum assy - ok to close as per Paul Casamento
SP007 - Discharge Belt Replace - ok to close as per PC
Str SC Track Screen 500hr (Perkins) - carried out service #27 - Nil stk#32 Very low topped up ...
SP007 - Side Conveyor Belt Change - ok to close as per PC
SP007 - Replace worn capping rubber. Removed side clamp bars lifted & removed old capping rubber & ...
SP007 - Replace Impact Rollers - ok to close as per Paul Casamento
SP007 - Stock Order Conveyor Belts inspected - belts were received and changed.
SP007 changeout all top deck screens on monday 26th january - carry out screen change on top deck
SP007 repair controller by datek
SP007 - Screens
SP007 - Flow Control Valve Stock Order
Str SC Track Screen 250hr (Perkins) carried out 250hr service. flushed engine with diesel. fitte ...
Str SC Track Screen 1000hr (Perkins). ENGINE SERVICE DONE BY NULLAGINE CONTRACTING
SP007 - Screen & Capping Rubber order capping rubber has arrived and is in stock.
SP007 - Worn Alternator Pulley, Order in replacement & 1 x spare checked and closed as part of a ...
SP007 - Completed Electrical Checks - Completed electrical checks as per checklist
SP007 - Repair oversize conveyor lanyard wiring - broken electrical cable to lanyard replaced
SP007 - Supply of Conveyor Belt through Fenner Dunlop (1200w, 5x1.25, 3ply, 30mtrs) - ok to close a ...
SP007 - Fit new lights and interlock repairs
SP007 - Air filter order - MARCH - ok to close as per PC
SP007 - Replace faulty LH tracking solenoid
SP007 - relocate fuel fill hose to avoid manual handling and pulling hose around machine. NOT REQUIR ...
Str SC Track Screen 250hr (Perkins). SERVICE AND MECH CHECKS WERE ALL DONE UNDER ENGINE SCOPE WORK ..
SP007 - Repair lift conveyor belt, super screw join - cover strip fitted over superscrew
SP007 - Weld repairs to screen discharge chute and conveyor beam - Welded wear plate in chute and ...
SP007 - Replaced u/s bearing on discharge conveyor head drum - groove worn in shaft about 5mm deep ...
SP007 Changeout top deck 3.12mm wire woven to 3.12mm poly ripple. - replace old screen mats with ne ...
SP007 - Fit new alternator bracket and replace lift conveyor scraper - remove old bracket, make new ...
SP007 - Replace Lift Conveyor Belt - Replaced by Fenner Dunlop - ok to close as per PC
SP007 Order in new oil filter housing fittings and hoses done as parts of a 250hr service w/o 1358 ...
SP007 - 500Hr service carried out - Unable to locate service sheet paperwork.
SP007 - Replace hyd pump drive coupling - ok to close as per PC
SP007 - Repair Lift Conveyor Scraper - THIS WORK COMPLETED UNDER WORK ORDER 140611 AT ALICE SPRINGS ...
SP007 - E-Stop Faulty Investigate - Fault find and replace faulty contacts
SP007 - Download PLC Programs from SP007 to electricians lap top - Download current PLC programs fr ...
SP007 - Lanyard Signs
SP007 - Replace underspeed return roller - Replaced roller with impact roller, modified metso hange ...
SP007 - replace discharge control side head drum bearing replaced control side head drum bearing ...
Str SC Track Screen 250hr (Perkins)
SP007 - start and alternator (belts also) need replacing. THIS WORK WAS DONE UNDER WORK ORDER 140621 ...
SP007 - all conveyor belts need replacing. CLOSED BY PC
SP007 - rollers/skirts/bearing/impact roller-beds need att. ALL THIS WORK WAS DONE ON BELT CHNGE WOR ...
SP007 - screenbox bearings needs replacing, counter weights cleaned and freed up

SP007- tracking issues need att. solenoids and coils need to be checked and set up properly. track ...

SP007- discharge head drum need replacing (in stock). THIS WORK WAS DONE UNDER WORK ORDER 140611. C ...

SP007- needs undercarriage rebuild. all rollers and guides are u/s

SP007- valve banks need rebuild. leaking. CLOSED BY PC

SP007- engine needs a tune up. crack in block(in to do list have not seen). CLOSED BY PC

SP007 - Prep For Sealing Agg Alice Springs. CLOSED BY PC

SP007 FIT 15MM POLY RIPPLE SCREENS TO TOP DECK AND 40MM WIRE WOVEN SCREENS TO BOTTOM DECK. CLOSI

SP007 - Order Spares for Alice Springs. Stock Recieved

Stock Recieved

SP007 - Spares for Kulgera. Fab and fit liners in head chute.

SP007 - Replace two hoses. Outsourced to Hosetek. Completed 27/02/2017

SP007 - Order 2000Hr Service Kit. Stock Recieved

Replace blown Hydraulic hose

SP007 - Injector Failure

SP007- order hydraulic pump drive coupling

SP007 - Belt Repair Order Super Screw. Stock Recieved

SP007- Order New Head Board Feed Hopper For Screen Box

SP007 - Spares for Kulgera

SP007 Prep For Carrapateena

Fire Suppression System Service and Inspection - Level 3 / 5 Yearly (Standard Job). See attached do ...

Str SC Track Screen 2000hr (Perkins). Closed off due to hour meter change.

Str SC Track Screen 1000hr (Perkins) Closed off due to hour meter change.

Str SC Track Screen 500hr (Perkins) Closed off due to hour meter change.

Str SC Track Screen 250hr (Perkins) Closed off due to hour meter change.

Str SC Track Screen 2000hr (Perkins) Closed off due to hour meter change.

Str SC Track Screen 500hr (Perkins) Closed off due to hour meter change.

SP007 Demob Pack up machine and get ready for demob from how crush left machine and refit left hand ...

SP007 - Prep for Plenty

SP007 - FILTERS FOR SERVICE

SP007 - Hydraulic Pump Fault, Remove & Replace Pump

SP007- Str SC Track Screen 2000hr (Perkins) - Closed off due to activator error

SP007- Str SC Track Screen 1000hr (Perkins) - Closed off due to activator error

SP007- Str SC Track Screen 250hr (Perkins) - Closed off due to activator error

Alternator Failed U/S - Starter+Starter Relay Is Failing,Alternator P/N #MG307 Mahle 24v 55A St ...

SP007- Str SC Track Screen 500hr (Perkins) - See attached

SP007 - Str SC Track Screen 250hr (Perkins) Is being closed out in conjunction with work order 2529 ...

SP007 - Str SC Track Screen 2000hr (Perkins) as per service sheet @7983hrs- Waiting on parts to re ...

Str SC Track Screen 500hr (Perkins) DUE 8,500HR

SP007 - Order Discharge Folding Hydraulic Cylinder (Damaged In Transport.) Stock Recieved

SP007 - Oder Parts & Consumables For Carpentaria Hwy Job Setup

SP007 - Carry out 12 monthly fire suppression serviceCompleted by Chubb Darwin/Vern 25/06/2023

SP007 - Carry out 6 month fire suppression service***Completed by Chubb Darwin***

3H...

A...

ED B...