



Plant Service Record

Date: 01/11/2024

**Plant Id:** WTC25      **Description:** WTC25 Volvo A40F ADT  
**Rego Number:**      **Make:** Volvo  
**Model:** A40F      **Serial Number:** VCE0A40FL00051631

Service Date	SMU	Description of Service	Service Completed By	Company	Phone	Labour Hours
09/01/2024	16023	Inspect brake system for clogged filter, found brake disk material when filter was cut open. Test brake system and found excessive wear in POS 1 & 2. Dismantle hubs and inspect brake disks, found friction disk worn past wear indicators, remove and replace friction disk as required, reseal with new due cones and O-rings, refill with oil and test operation, operating correctly. from Ad-hoc checklist TTU-001244	Taylah Tuckey	-	-	0.00
30/11/2023	15950	Mudgee engineering welded a sacrificial plate over the lifted edge. from Ad-hoc checklist MCR-001184	Michael Craig	-	-	0.00
13/11/2023	15902	Tested brake circuit found pressure low on brake tests. Tested the brake accumulators individually all were at half pressure. Replaced all 12 accumulators and bled up system and tested all within spec from Ad-hoc checklist TTU-001171	Taylah Tuckey	-	-	0.00
13/11/2023	15902	Two way radio	Michael Craig	-	-	0.00
13/11/2023	15902	Tested radio works fine. Just the screen is hard to read from Ad-hoc checklist MCR-001162	Michael Craig	-	-	0.00

23/10/2023	15892	Two way radio	Michael Craig	-	-	0.00
22/09/2023	15792	wiring fault repaired in rear harness from Ad-hoc checklist MGE-001046	Matthew Gersbach	-	-	0.00
10/08/2023	15758	repaired oil leaks on engine block, and replaced centre and rear axle suspension blocks from Ad-hoc checklist TTU-000825	Taylah Tuckey	-	-	0.00
09/08/2023	15758	A40F	Michael Craig	WTC Group Aust Pty Ltd	0413292335	0.00
04/07/2023	15579	Found plug to aircon compressor had come loose, reattached and tested okay, Blew out condenser from Ad-hoc checklist MCR-000308	Michael Craig	-	-	0.00
19/06/2023	15474	A40F	Michael Craig	WTC Group Aust Pty Ltd	0413292335	0.00
18/05/2023	14996	6 x o rings & valves from Ad-hoc checklist TTU-84	Taylah Tuckey	-	-	0.00
18/05/2023	14996	6 x rims for NDT from Ad-hoc checklist TTU-88	Taylah Tuckey	-	-	0.00
18/05/2023	15199	Tighten loose transmission filter. Tighten up seat base and replace seat height valve from Ad-hoc checklist MCR-000064	Michael Craig	-	-	0.00
18/05/2023	15239	repaired faulty temp sensor from Ad-hoc checklist MGE-000120	Matthew Gersbach	-	-	0.00
18/05/2023	15239	repaired steering fault and tested from Ad-hoc checklist MGE-000121	Matthew Gersbach	-	-	0.00
18/05/2023	15239	removed tyres to send rims away for NDT from Ad-hoc checklist MGE-000122	Matthew Gersbach	-	-	0.00
18/05/2023	15239	fitted new door glass due to damage from Ad-hoc checklist MGE-000123	Matthew Gersbach	-	-	0.00
18/05/2023	15239	fitted new seat from Ad-hoc checklist MGE-000124	Matthew Gersbach	-	-	0.00
18/05/2023	15275	Replace seat valve from Ad-hoc checklist MCR-000241	Michael Craig	-	-	0.00
18/05/2023	15342	Change out alternator from Ad-hoc checklist MCR-000291	Michael Craig	-	-	0.00
04/05/2023	15275	Tyres and rims	Michael Craig	-	-	0.00
16/01/2023	14874	Air conditioner	Matthew Gersbach	-	-	0.00
21/10/2022	14500	-	-	-	-	0.00