



Tax Invoice

30/07/2026

Invoice #:

9782

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 652436
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

COMPLETE REPAIRS AS REQUESTED
-REMOVE AND REPLACE ENGINE BRAKE SOLENOIDS
-REMOVE AND REPLACE FAN BELTS

Labour	2.00	\$150.00	\$30.00	\$330.00
--------	------	----------	---------	----------

SUBLET AIR CONDITIONING REPAIRS

COMPLETE REPAIRS AS REQUESTED
-REMOVE AND REPLACE COMPRESSOR AND SUCTION FITTING. REGAS SYSTEM, TEST OPERATION ALL OK

Labour	1.00	\$1117.50	\$111.75	\$1229.25
VALVE, SOLENOID 12V S/L CUM	2.00	\$833.85	\$166.77	\$1834.47
BELT V -12PK2215	1.00	\$135.85	\$13.59	\$149.44
AIR CON BELT GATES 6PK1615	1.00	\$102.46	\$10.25	\$112.71
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$3,348.51

Freight \$35.00

GST \$338.36

Total \$3,721.87

Payment Terms: 30DAYSAEOM

Balance Due \$3,721.87

Direct Debit: BSB - 083 526 A/C No. 48 748 9185
Email: accounts@wrendiesel.com.au



Tax Invoice

04/02/2026

Invoice #:

9369

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 639753
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

COMPLETE REPAIRS AS REQUESTED

-REMOVE AND REPLACE LEFT REAR DRIVE BRAKE BOOSTER, ADJUST BRAKE, TEST OPERATION, ALL OK

Labour	1.00	\$150.00	\$15.00	\$165.00
BRAKE BOOSTER TYPE 30/30	1.00	\$105.55	\$10.56	\$116.11
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$280.55

GST \$28.06

Total \$308.61

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$308.61

Direct Debit: BSB - 083 526 A/C No. 48 748 9185
Email: accounts@wrendiesel.com.au



Tax Invoice

23/02/2026

Invoice #:

9374

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 642638
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

PERFORM 'B' SERVICE AS REQUIRED, REPLACE ENGINE OIL AND FILTERS, CHECK AND TOP UP ALL FLUID LEVELS, CHECK AIR FILTER AND REPLACE IF NEEDED, CHECK BRAKES AND ADJUST IF NEEDED, CHECK CLUTCH AND ADJUST IF NEEDED, CHECK LIGHTS AND REPAIR IF NEEDED, GREASE ALL LUBRICATION POINTS, AND VISUAL CHECK OF VEHICLE

--REMOVE AND REPLACE RIGHT FRONT DRIVE SHOCK ABSORBER
--TIGHTEN SPEEDO IN DASH

--REPAIR LIGHTS

--REMOVE AND REPLACE 4 CABIN ROOF LIGHTS

--REPLACE BLOWN MIRROR LIGHT GLOBE

--REPAIR AIR LEAKS

---NSPECT HORTON, FOUND FAILED SEALS, AND WORN OUT

--REMOVE ALL SURROUNDING COMPONENTS, REMOVE HORTON FROM VEHICLE. DISASSEMBLE AND REBUILD. REFIT TO VEHICLE WITH NEW MAIN BELT AND TENSIONER

--TEST OPERATION, ALL OK

--REMOVE AND REPLACE LEAKING SOLENOID TO HORTON AIR LINE

--REMOVE AND REPLACE GOVERNOR VALVE TO TANK AIR LINES

--REMOVE AND REPLACE FIREFALL PASS THROUGH MANIFOLDS

--REMOVE AND REPLACE 2 AIR TANK DRAIN COCKS

--REMOVE AND REPLACE 2 PRESSURE CHECK VALVES

Labour	16.00	\$150.00	\$240.00	\$2640.00
ENG OIL CU PREM BLUE 8600-1324IBC	45.00	\$7.25	\$32.63	\$358.88
COOLANT CASTROL PREM 50 COOL PL	3.00	\$6.86	\$2.06	\$22.64
AIR FILTER AF1968M	1.00	\$125.00	\$12.50	\$137.50
CABIN AIR FILTER KW 25189011	1.00	\$52.00	\$5.20	\$57.20
OIL FILTER LF14000NN	1.00	\$69.95	\$7.00	\$76.95
FUEL FILTER FF5776	1.00	\$75.25	\$7.53	\$82.78
FUEL FILTER K37-1009	1.00	\$38.96	\$3.90	\$42.86
AIR OIL SEPARATOR AS2474	1.00	\$21.25	\$2.13	\$23.38
GREASE PREMIUM HD	1.00	\$15.00	\$1.50	\$16.50
SHOCK ABSORBER KIT k374-41 A/G200/400	1.00	\$356.03	\$35.60	\$391.63
GLOBE 12V3W	1.00	\$1.75	\$0.18	\$1.93
LAMP-ROOF MARKER LED AMBER	5.00	\$89.65	\$44.83	\$493.08
HORTON REPAIR KIT MAJOR F35008SD	1.00	\$797.34	\$79.73	\$877.07



Tax Invoice

29/01/2026

Invoice #:

9339

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 639261
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

COMPLETE REPAIRS AS REQUESTED

-DIAGNOSE AND REPAIR AFTER TREATMENT FAULT LIGHT ON, SCAN VEHICLE FOUND BLOCKED PUMP.
REPLACE FILTERS, ULTRASONIC CLEAN INJECTOR. PERFORM ADBLUE PUMP FLUSH, CLEAR FAULTS, TEST
DRIVE, ALL OK

-DIAGNOSE AND REPAIR VEHICLE OVERHEATING

--INSPECT RADIATOR, FOUND BLOCKED WITH DEBRIS.REMOVE ALL SURROUNDING COMPONENTS,
REMOVE AFTER-COOLER. BLOW OUT AND PRESSURE CLEAN AFTER-COOLER AND RADIATOR. REFIT AFTER-
COOLER TO VEHICLE, REFIT ALL SURROUNDING COMPONENTS. PRESSURE CLEAN ENGINE BAY

-REPAIR REAR DIFF TEMP GAUGE FAULTS, REPAIR CONNECTOR, TEST OPERATION, ALL OK

Labour	7.00	\$150.00	\$105.00	\$1155.00
AIR OIL SEPARATOR AS2474	1.00	\$21.25	\$2.13	\$23.38
ADBLUE FILTER IN TANK- O RING HHW0116	1.00	\$69.40	\$6.94	\$76.34
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$1,165.65

GST \$116.57

Total \$1,282.22

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$1282.22

Direct Debit: BSB - 083 526 A/C No. 48 748 9185
Email: accounts@wrendiesel.com.au



Tax Invoice

04/04/2025

Invoice #:

8593

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 622512
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

PERFORM 'B' SERVICE AS REQUIRED, REPLACE ENGINE OIL AND FILTERS, CHECK AND TOP UP ALL FLUID LEVELS, CHECK AIR FILTER AND REPLACE IF NEEDED, CHECK BRAKES AND ADJUST IF NEEDED, CHECK CLUTCH AND ADJUST IF NEEDED, CHECK LIGHTS AND REPAIR IF NEEDED, GREASE ALL LUBRICATION POINTS, AND VISUAL CHECK OF VEHICLE

- REMOVE AND REPLACE EXHAUST BRACKET BUSHES
- REMOVE AND REPLACE LOWER SHOCK BUSHES
- REMOVE AND REPLACE PARK LIGHT GLOBE

Labour	5.00	\$130.00	\$65.00	\$715.00
ENG OIL CU PREM BLUE 8600-1324IBC	45.00	\$7.25	\$32.63	\$358.88
AIR FILTER AF1968M	1.00	\$95.00	\$9.50	\$104.50
CABIN AIR FILTER KW 25189011	1.00	\$52.00	\$5.20	\$57.20
OIL FILTER LF14000NN	1.00	\$69.95	\$7.00	\$76.95
FUEL FILTER FF5776	1.00	\$73.95	\$7.40	\$81.35
FUEL FILTER K37-1009	1.00	\$38.96	\$3.90	\$42.86
AIR OIL SEPARATOR AS2474	1.00	\$20.95	\$2.10	\$23.05
GREASE PREMIUM HD	1.00	\$12.50	\$1.25	\$13.75
GLOBE 12V5W	1.00	\$2.60	\$0.26	\$2.86
BUSHING ANTI VIBRATION MT K066-338	2.00	\$37.21	\$7.44	\$81.86
BUSH RUBBER K066-310	4.00	\$11.75	\$4.70	\$51.70
WORKSHOP AND ENVIRONMENTAL LEVY	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$1,488.58

GST \$148.88

Total \$1,637.46

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$1637.46



Tax Invoice

22/01/2025

Invoice #:

8388

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 602082
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

PERFORM 'B' SERVICE AS REQUIRED, REPLACE ENGINE OIL AND FILTERS, CHECK AND TOP UP ALL FLUID LEVELS, CHECK AIR FILTER AND REPLACE IF NEEDED, CHECK BRAKES AND ADJUST IF NEEDED, CHECK CLUTCH AND ADJUST IF NEEDED, CHECK LIGHTS AND REPAIR IF NEEDED, GREASE ALL LUBRICATION POINTS, AND VISUAL CHECK OF VEHICLE
-REPLACE MIRROR LIGHT GLOBE
-REPLACE LEFT STEER SHOCK BUSHES

Labour	4.00	\$130.00	\$52.00	\$572.00
ENG OIL CU PREM BLUE 8600-1324IBC	45.00	\$7.25	\$32.63	\$358.88
COOLANT CASTROL PREM 50 COOL PL	2.00	\$6.86	\$1.37	\$15.09
AIR FILTER AF1968M	1.00	\$89.95	\$9.00	\$98.95
CABIN AIR FILTER KW 25189011	1.00	\$52.00	\$5.20	\$57.20
OIL FILTER LF14000NN	1.00	\$69.52	\$6.95	\$76.47
FUEL FILTER K37-1009	1.00	\$38.96	\$3.90	\$42.86
FUEL FILTER FF5776	1.00	\$72.85	\$7.29	\$80.14
AIR OIL SEPARATOR AS2474	1.00	\$19.95	\$2.00	\$21.95
GREASE PREMIUM HD	1.00	\$12.50	\$1.25	\$13.75
GLOBE 12V5W	1.00	\$2.60	\$0.26	\$2.86
BUSH - SHOCK ABSORBER 73D2002	4.00	\$24.74	\$9.90	\$108.86
WORKSHOP AND ENVIRONMENTAL LEVY	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$1,342.26

GST \$134.25

Total \$1,476.51

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$1476.51

Invoice Notes

FURTHER REPAIRS NEEDED
-TURN TABLE BALL RACE WORN



Tax Invoice

18/11/2024

Invoice #:

8257

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 578733
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

PERFORM 'B' SERVICE AS REQUIRED, REPLACE ENGINE OIL AND FILTERS, CHECK AND TOP UP ALL FLUID LEVELS, CHECK AIR FILTER AND REPLACE IF NEEDED, CHECK BRAKES AND ADJUST IF NEEDED, CHECK CLUTCH AND ADJUST IF NEEDED, CHECK LIGHTS AND REPAIR IF NEEDED, GREASE ALL LUBRICATION POINTS, AND VISUAL CHECK OF VEHICLE

- REMOVE AND REPLACE RIGHT BONNET INDICATOR, REPAIR WIRING
- REPLACE MISSING DUST SHEILD
- REMOVE AND REPLACE HEIGHT VALVE ROD ENDS

Labour	4.50	\$130.00	\$58.50	\$643.50
ENG OIL CU PREM BLUE 8600-1324IBC	45.00	\$7.25	\$32.63	\$358.88
COOLANT CASTROL PREM 50 COOL PL	2.00	\$6.86	\$1.37	\$15.09
AIR FILTER AF1968M	1.00	\$89.95	\$9.00	\$98.95
CABIN AIR FILTER KW 25189011	1.00	\$52.00	\$5.20	\$57.20
OIL FILTER LF14000NN	1.00	\$69.52	\$6.95	\$76.47
FUEL FILTER K37-1009	1.00	\$38.96	\$3.90	\$42.86
FUEL FILTER FF5776	1.00	\$72.85	\$7.29	\$80.14
AIR OIL SEPARATOR AS2474	1.00	\$19.95	\$2.00	\$21.95
GREASE PREMIUM HD	1.00	\$12.50	\$1.25	\$13.75
DUST SHIELD SET- MERITOR REAR A1-3236Q2123	1.00	\$132.25	\$13.23	\$145.48
ROD END BERNG VS5G-8- 5/16 FEMALE KW	4.00	\$39.95	\$15.98	\$175.78
LAMP TURN SIGNAL REPEATER	1.00	\$90.92	\$9.09	\$100.01
WORKSHOP AND ENVIRONMENTAL LEVY	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$1,688.67

GST \$168.89

Total \$1,857.56

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$1857.56

Invoice Notes

FURTHER REPAIRS NEEDED



Tax Invoice

14/10/2024

Invoice #:

8192

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 **Mob** 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 568722
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

COMPLETE REPAIRS AS REQUESTED

-DIAGNOSE AND REPAIR ENGINE FAULT LIGHT ON

-SCAN VEHICLE, FOUND CAMSHAFT POSITION SENSOR FAULTS

-REMOVE ALL SURROUNDING COMPONENTS, REMOVE CAM POSITION SENSOR, CLEAN ALL SURFACES, FIT NEW SENSOR, CLEAN CONNECTOR, RE ASSEMBLE, REFILL COOLANT

-CLEAR FAULTS, TEST DRIVE, ALL OK

Labour	2.00	\$130.00	\$26.00	\$286.00
POSITION SENSOR 5594276	1.00	\$87.09	\$8.71	\$95.80
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$372.09

GST \$37.21

Total \$409.30

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$409.30

Direct Debit: BSB - 083 526 A/C No. 48 748 9185
Email: accounts@wrendiesel.com.au



Tax Invoice

15/08/2024

Invoice #:

8077

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 556008
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

ELECTRICAL REPAIRS

- REPAIR VEHICLE NOT SELECTING GEARS IN WET CONDITIONS
- CHECK WIRING FROM ENGINE LOOM TO GEARBOX COMPUTER FOR INTERMITTENT BRAKE/GEAR CHANGE FAULT.
- REPAIR MULTIPLE UNRELATED RUBS NEAR BELL HOUSING
- DIAGNOSE WIRING FAULT FROM BRAKE SWITCH TO ENGINE ECU. RE WIRE AS REQUIRED.TEST OK
- REPAIR MULTIPLE BROKEN WIRES IN DOOR FOR WINDOW
- REPLACE OIL PRESS SENSOR FOR GAUGE
- REMOVE AND REPLACE MIRROR HEATER SWITCH

Labour	1.00	\$1011.25	\$101.13	\$1112.38
MIRROR SWITCH	1.00	\$96.40	\$9.64	\$106.04
SENDER SP052- KW	1.00	\$92.54	\$9.25	\$101.79
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$1,225.19

GST \$122.52

Total \$1,347.71

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$1347.71

Direct Debit: BSB - 083 526 A/C No. 48 748 9185
Email: accounts@wrendiesel.com.au



Tax Invoice

05/08/2024

Invoice #:

8002

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 556008
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

PERFORM 'B' SERVICE AS REQUIRED, REPLACE ENGINE OIL AND FILTERS, CHECK AND TOP UP ALL FLUID LEVELS, CHECK AIR FILTER AND REPLACE IF NEEDED, CHECK BRAKES AND ADJUST IF NEEDED, CHECK CLUTCH AND ADJUST IF NEEDED, CHECK LIGHTS AND REPAIR IF NEEDED, GREASE ALL LUBRICATION POINTS, AND VISUAL CHECK OF VEHICLE
-DIAGNOSE AND REPAIR COOLANT LEAKS. REMOVE AND REPLACE TOP RADIATOR HOSES, REPLACE HEATER TAP, REFILL AND TOP UP COOLANT

DIAGNOSE VEHICLE NOT SELECTING GEAR AFTER WASHING ENGINE BAY

-SCAN VEHICLE, FOUND NO BRAKE SWITCH SIGNAL TO ENGINE ECU
-REMOVE AND REPLACE BRAKE HOBBS SWITCH
-REPAIR CONNECTIONS AND TEST WIRING TO ECU, TEST OK, CHECK LOOM FOR RUBS
-FIT AND REMOVE TEST ECU
-DRY OUT LOOM AND TEST DRIVE VEHICLE. REPAIR AT LATER DATE

Labour	12.00	\$130.00	\$156.00	\$1716.00
ENG OIL CU PREM BLUE 8600-1324IBC	45.00	\$7.25	\$32.63	\$358.88
GEAR OIL DYNADRIE SYN 80W90	2.00	\$11.98	\$2.40	\$26.36
AIR FILTER AF1968M	1.00	\$89.95	\$9.00	\$98.95
CABIN AIR FILTER KW 25189011	1.00	\$52.00	\$5.20	\$57.20
OIL FILTER LF14000NN	1.00	\$69.52	\$6.95	\$76.47
FUEL FILTER FF5776	1.00	\$70.35	\$7.04	\$77.39
FUEL FILTER K37-1009	1.00	\$38.54	\$3.85	\$42.39
AIR OIL SEPARATOR AS2474	1.00	\$19.95	\$2.00	\$21.95
GREASE PREMIUM HD	1.00	\$12.50	\$1.25	\$13.75
SILICONE RADIATOR HOSE 2' PER CM	16.00	\$2.83	\$4.53	\$49.81
SILICONE RADIATOR HOSE 2 1/2' PER CM	16.00	\$2.37	\$3.79	\$41.71
5/8 HEATER TAP V404P-10-6	1.00	\$21.49	\$2.15	\$23.64
MISCELLANEOUS HYDRAULIC FITTINGS	1.00	\$13.20	\$1.32	\$14.52
HOBBS SWITCH	1.00	\$112.50	\$11.25	\$123.75
WORKSHOP AND ENVIRONMENTAL LEVY	1.00	\$25.00	\$2.50	\$27.50



Tax Invoice

02/05/2024

Invoice #:

7742

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 524473
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

COMPLETE REPAIRS AS REQUESTED

-REMOVE AND REPLACE KING PINS AND ALL ASSOCIATED COMPONENTS, REPLACE BUSHES AND REAM, PRESSURE CLEAN AND INSPECT ALL COMPONENTS, CHECK WHEEL BEARINGS, RE FIT WITH NEW SEALS AND GASKETS, REFIT BRAKE ASSEMBLIES, ADJUST BEARINGS AND REFIT WHEELS

REPAIR DRIVE BRAKES

-STRIP REAR BRAKE ASSEMBLIES, REMOVE HUBS, DRUMS, LININGS, AND ALL HARDWARE, PRESSURE CLEAN AND INSPECT ALL COMPONENTS

-INSPECT S CAMS FOUND UNSERVICEABLE, FIT NEW S-CAMS WITH NEW BUSHES AND SEALS

-INSPECT WHEEL BEARINGS AND FIT TO HUBS WITH NEW WHEEL SEALS AND ADJUST. FIT NEW BRAKE LININGS AND HARDWARE, REFIT HUB ASSEMBLIES TO VEHICLE, FIT NEW DRUMS, REFIT ALL WHEELS, ADJUST BRAKES

DIAGNOSE AND REPAIR AFTER TREATMENT SYSTEM FAULTS

-SCAN VEHICLE FOUND BLOCKED AD BLUE PUMP

-PERFORM AD BLUE SYSTEM FLUSH, ULTRA SONIC CLEAN INJECTOR AND REFIT, RE PRIME SYSTEM AND TEST, CLEAR FAULTS, ALL OK

Labour	22.00	\$130.00	\$286.00	\$3146.00
KING PIN KIT BRASS KW409- T350	1.00	\$690.42	\$69.04	\$759.46
REAM KING PIN (PER PIN)	2.00	\$69.00	\$13.80	\$151.80
WHEEL SEAL STEER SKF 35066	2.00	\$32.55	\$6.51	\$71.61
GASKET 6 HL 330-3009 HUB CAP 5.5'PCD	2.00	\$4.85	\$0.97	\$10.67
KW NYLON TIE DOUBLE	8.00	\$2.00	\$1.60	\$17.60
S-CAM 28SPL 11.6 LH 2210W537FW	2.00	\$118.45	\$23.69	\$260.59
S CAM 28SPL -RH 2210V7536FW	2.00	\$118.45	\$23.69	\$260.59
KIT, CAMSHAFT REPAIR MERITOR	2.00	\$44.38	\$8.88	\$97.64
OIL SEAL SKF DRIVE 47697 ROCKWELL	4.00	\$34.50	\$13.80	\$151.80
BRAKE SHOE KIT DRIVE 4707QP MERITOR	4.00	\$135.00	\$54.00	\$594.00
BRAKE DRUM DR190- 16.5 x 7' 10 STUD	4.00	\$145.00	\$58.00	\$638.00
KIT ROLLER RETAINER BOLT-ON FB3415	4.00	\$5.63	\$2.25	\$24.77
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50



Tax Invoice

28/03/2024

Invoice #:

7639

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 512742
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

PERFORM 'B' SERVICE AS REQUIRED, REPLACE ENGINE OIL AND FILTERS, CHECK AND TOP UP ALL FLUID LEVELS, CHECK AIR FILTER AND REPLACE IF NEEDED, CHECK BRAKES AND ADJUST IF NEEDED, CHECK CLUTCH AND ADJUST IF NEEDED, CHECK LIGHTS AND REPAIR IF NEEDED, GREASE ALL LUBRICATION POINTS, AND VISUAL CHECK OF VEHICLE

-FOUND STEERING BOX PITMAN ARM BOLT TIGHT BUT WORN AND LOOSE ON SPLINE. REMOVE AND REPLACE PITMAN ARM

-REMOVE AND REPLACE RIGHT STEER WHEEL SEAL. DEGREASE AND PRESSURE CLEAN ALL COMPONENTS, INSPECT AND REFIT WHEEL BEARINGS, RE ASSEMBLE, ADJUST BEARING AND BRAKE

-DIAGNOSE AND REPAIR ABS FAULTS. SCAN VEHICLE, FOUND FAILED LEFT REAR WHEEL SPEED SENSOR. REMOVE AND REPLACE WHEEL SPEED SENSOR. FOUND BRAKE ROLLERS, ANCHOR PINS AND BUSHES BADLY WORN. REMOVE AND REPLACE COMPONENTS, REFIT LININGS, DRUM AND WHEELS, ADJUST BRAKE, CLEAR FAULT, ALL OK

-REMOVE AND REPLACE 2 REAR AXLE AIR BAGS

Labour	10.00	\$130.00	\$130.00	\$1430.00
ENG OIL CU PREM BLUE 8600-1324IBC	45.00	\$7.25	\$32.63	\$358.88
AIR FILTER AF1968M	1.00	\$89.75	\$8.98	\$98.73
CABIN AIR FILTER KW 25189011	1.00	\$52.00	\$5.20	\$57.20
OIL FILTER LF14000NN	1.00	\$69.52	\$6.95	\$76.47
FUEL FILTER FF5776	1.00	\$69.98	\$7.00	\$76.98
FUEL FILTER K37-1009	1.00	\$38.54	\$3.85	\$42.39
AIR OIL SEPARATOR AS2474	1.00	\$19.95	\$2.00	\$21.95
GREASE PREMIUM HD	1.00	\$12.50	\$1.25	\$13.75
ARM PITMAN	1.00	\$1254.14	\$125.41	\$1379.55
AIR BAG KW C81-1004- 9 INCH	2.00	\$537.21	\$107.44	\$1181.86
ABS WSS 90DEG 0486000128100 SENSOR CABLE	1.00	\$165.85	\$16.59	\$182.44
WHEEL SEAL STEER SKF 35066	1.00	\$32.55	\$3.26	\$35.81
GASKET -HUB CAP STEER 330-3024	1.00	\$4.85	\$0.49	\$5.34
ANCHOR PIN BUSH FB3207	2.00	\$2.61	\$0.52	\$5.74
KIT ROLLER RETAINER BOLT-ON FB3415	2.00	\$5.59	\$1.12	\$12.30
ROLLER BRAKE STANDARD FB3403	2.00	\$4.62	\$0.92	\$10.16
WORKSHOP AND ENVIRONMENTAL LEVY	1.00	\$25.00	\$2.50	\$27.50



Tax Invoice

07/03/2024

Invoice #:

7595

PAUL WREN DIESEL MECHANIC PTY. LTD.

18 NEERIM CRESCENT

WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440

Email ACCOUNTS@WRENDIESEL.COM.AU

Web WWW.WRENDIESEL.COM.AU

A.B.N. 18 093 001 104

Fax 0353391788

GDP TRANSPORT PTY LTD

65 BALD HILLS ROAD

CRESWICK, VIC 3363

(03) 5345 2150

0407 700 257

Registration

GDP020

Make

KENWORTH 403

Model

KW 403 PM

Colour

WHITE

Odometer

505058

VIN

451577

Build Date

02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

DIAGNOSE AND REPAIR ENGINE OVER HEATING

-REMOVE ALL SURROUNDING COMPONENTS, REMOVE AFTER COOLER. PRESSURE CLEAN AFTER COOLER AND RADIATOR. RE ASSEMBLE

-REMOVE AND REPLACE THERMOSTAT AND ALL ASSOCIATED COMPONENTS. REFILL AND TOP UP COOLANT

Labour	6.00	\$130.00	\$78.00	\$858.00
COOLANT CASTROL PREM 50 COOL PL	2.00	\$6.86	\$1.37	\$15.09
THERMOSTAT 180' CU 4318947-ISX-ISX EGR	1.00	\$143.63	\$14.36	\$157.99
GASKET THERMOSTAT HUS CUM 3682673 ISX	1.00	\$96.68	\$9.67	\$106.35
SEAL THERMOSTAT CUMMINS 3084879	1.00	\$55.40	\$5.54	\$60.94
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$1,114.43

GST \$111.44

Total \$1,225.87

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$1225.87

Direct Debit: BSB - 083 526 A/C No. 48 748 9185

Email: accounts@wrendiesel.com.au



Tax Invoice

30/01/2024

7490

Invoice #:

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 491328
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

PERFORM 'B' SERVICE AS REQUIRED, REPLACE ENGINE OIL AND FILTERS, CHECK AND TOP UP ALL FLUID LEVELS, CHECK AIR FILTER AND REPLACE IF NEEDED, CHECK BRAKES AND ADJUST IF NEEDED, CHECK CLUTCH AND ADJUST IF NEEDED, CHECK LIGHTS AND REPAIR IF NEEDED, GREASE ALL LUBRICATION POINTS, AND VISUAL CHECK OF VEHICLE
-REPLACE DAMAGED BONNET MOUNT
-REPLACE BLOWN GLOBE
-REPLACE MISSING BRAKE DUST COVER

Labour	4.00	\$130.00	\$52.00	\$572.00
ENG OIL CU PREM BLUE 8600-1324IBC	45.00	\$7.25	\$32.63	\$358.88
COOLANT CASTROL PREM 50 COOL PL	3.00	\$6.86	\$2.06	\$22.64
AIR FILTER AF1968M	1.00	\$89.75	\$8.98	\$98.73
CABIN AIR FILTER KW 25189011	1.00	\$52.00	\$5.20	\$57.20
OIL FILTER LF14000NN	1.00	\$69.52	\$6.95	\$76.47
FUEL FILTER FF5776	1.00	\$69.98	\$7.00	\$76.98
FUEL FILTER K37-1009	1.00	\$38.54	\$3.85	\$42.39
AIR OIL SEPARATOR AS2474	1.00	\$19.95	\$2.00	\$21.95
GREASE PREMIUM HD	1.00	\$12.50	\$1.25	\$13.75
DUST SHIELD SET- MERITOR REAR A1-3236Q2123	1.00	\$118.36	\$11.84	\$130.20
GLOBE 12V5W	1.00	\$2.50	\$0.25	\$2.75
PAD HOOD SUPPORT L63 1021	1.00	\$236.71	\$23.67	\$260.38
WORKSHOP AND ENVIRONMENTAL LEVY	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$1,601.64

GST \$160.16

Total \$1,761.80

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$1761.80

Invoice Notes

FURTHER REPAIRS NEEDED



Tax Invoice

16/11/2023

Invoice #:

7339

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 468754
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

- PERFORM 'B' SERVICE AS REQUIRED, REPLACE ENGINE OIL AND FILTERS, CHECK AND TOP UP ALL FLUID LEVELS, CHECK AIR FILTER AND REPLACE IF NEEDED, CHECK BRAKES AND ADJUST IF NEEDED, CHECK CLUTCH AND ADJUST IF NEEDED, CHECK LIGHTS AND REPAIR IF NEEDED, GREASE ALL LUBRICATION POINTS, AND VISUAL CHECK OF VEHICLE
-REPAIR LIGHTS, REPLACE MIRROR LIGHT GLOBE, REAR BRAKE LIGHT GLOBE, AND NUMBER PLATE LIGHT
-REPLACE WIPER WASHER JET
-TIGHTEN CABIN CROSS MEMBER
-REMOVE AND REPLACE FRONT CABIN MOUNTS
-REMOVE AND REPLACE DRAG LINK
-REMOVE AND REPLACE BONNET HINGE BUSHES AND ASSOCIATED COMPONENTS
-REPAIR AIR LEAKS, REMOVE AND REPLACE AIR TANK DRAIN COCK

-REMOVE AND REPLACE FRONT DIFF
-CLEAN ALL SURFACES, RESEAL AND REFIT
-REMOVE THROUGH SHAFT. REMOVE AND REPLACE THROUGH SHAFT BEARINGS, REPLACE SEAL AND RE ASSEMBLE
-DISASSEMBLE JACKSHAFT. CLEAN, LUBRICATE AND RE ASSEMBLE
-REFILL OIL. TEST DRIVE, ALL OK

Labour	22.00	\$130.00	\$286.00	\$3146.00
ENG OIL CU PREM BLUE 8600-1324IBC	45.00	\$7.25	\$32.63	\$358.88
TRANSMISSION OIL R/RANGER SAE50	4.00	\$24.85	\$9.94	\$109.34
GEAR OIL DYNADRIE SYN 80W90	18.00	\$11.98	\$21.56	\$237.20
AIR FILTER AF1968M	1.00	\$89.75	\$8.98	\$98.73
CABIN AIR FILTER KW 25189011	1.00	\$52.00	\$5.20	\$57.20
OIL FILTER LF9070	1.00	\$76.40	\$7.64	\$84.04
FUEL FILTER FF5776	1.00	\$69.98	\$7.00	\$76.98
FUEL FILTER K37-1009	1.00	\$38.54	\$3.85	\$42.39
AIR OIL SEPARATOR AS2474	1.00	\$19.95	\$2.00	\$21.95
GREASE PREMIUM HD	1.00	\$12.50	\$1.25	\$13.75
LED LICENCE PLATE LIGHT INSERT 91660	1.00	\$33.75	\$3.38	\$37.13
GLOBE 12V5W	1.00	\$2.50	\$0.25	\$2.75
SEAL-OIL D404O/PUT	1.00	\$46.52	\$4.65	\$51.17
SEALANT TOYOTA	1.00	\$59.23	\$5.92	\$65.15



Tax Invoice

18/10/2023

Invoice #:

7249

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer/Hrs 461460 / 24175
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

COMPLETE REPAIRS AS REQUESTED

-DIAGNOSE AND REPAIR COOLANT LEAKS. FOUND LEAKING WATER PUMP. REMOVE AND REPLACE WATER PUMP, CLEAN ALL SURFACES, REPLACE O RING. REFILL AND TOP UP COOLANT. TEST DRIVE, ALL OK

-REPAIR DIFF OIL LEAKS. REMOVE AND REPLACE FRONT DIFF INPUT SHAFT SEAL. TOP UP DIFF OIL

Labour	5.00	\$130.00	\$65.00	\$715.00
COOLANT CASTROL PREM 50 COOL PL	3.00	\$6.86	\$2.06	\$22.64
GEAR OIL DYNADRIE SYN 80W90	4.00	\$11.98	\$4.79	\$52.71
CORE WATER PUMP- CU 5719759	1.00	\$1256.84	\$125.68	\$1382.52
SEAL O RING CU 3684384	1.00	\$52.75	\$5.28	\$58.03
SEAL-DSH DDH40	1.00	\$112.85	\$11.29	\$124.14
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$2,165.94

Freight \$25.00

GST \$219.09

Total \$2,410.03

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$2410.03

Invoice Notes

FURTHER REPAIRS NEEDED

-FRONT DIFF INPUT SHAFT EXCESSIVE MOVEMENT.

-LAST DRIVESHAFT BEFORE FRONT DIFF SEIZED

Direct Debit: BSB - 083 526 A/C No. 48 748 9185
Email: accounts@wrendiesel.com.au



Tax Invoice

02/10/2023

Invoice #:

7214

PAUL WREN DIESEL MECHANIC PTY. LTD.
18 NEERIM CRESCENT
WENDOUREE, VIC 3355

Phone (03) 5339 1088 Mob 0439 983 440
Email ACCOUNTS@WRENDIESEL.COM.AU
Web WWW.WRENDIESEL.COM.AU
A.B.N. 18 093 001 104
Fax 0353391788

GDP TRANSPORT PTY LTD
65 BALD HILLS ROAD
CRESWICK, VIC 3363

Registration GDP020
Make KENWORTH 403
Model KW 403 PM
Colour WHITE
Odometer 456836
VIN 451577

(03) 5345 2150
0407 700 257

Build Date 02/2014

Item	Description	Quantity	Unit Price	GST	Total
------	-------------	----------	------------	-----	-------

LABOUR

COMPLETE REPAIRS AS REQUESTED
-INSPECT HORTON, FOUND FAILED BEARINGS
-REMOVE ALL SURROUNDING COMPONENTS, REMOVE HORTON FROM VEHICLE. DISASSEMBLE AND
REBUILD. REFIT TO VEHICLE
-REPLACE SEIZED BOOST CLAMP
-TEST OPERATION, ALL OK

Labour	6.00	\$130.00	\$78.00	\$858.00
HORTON REPAIR KIT MAJOR F35008SD	1.00	\$795.38	\$79.54	\$874.92
CLAMP BOOST - 4 1/2	1.00	\$26.82	\$2.68	\$29.50
WORKSHOP SUPPLIES	1.00	\$25.00	\$2.50	\$27.50

Subtotal \$1,627.20

GST \$162.72

Total \$1,789.92

Payment Terms: 30DAYSAEOM

Balance Due \$0.00

Paid Cash \$1789.92

Invoice Notes

FURTHER REPAIRS NEEDED
-WATER PUMP WEEPING - OWNER TO MONITOR

Direct Debit: BSB - 083 526 A/C No. 48 748 9185
Email: accounts@wrendiesel.com.au