



Raven RV Ltd
evan@ravenrv.ca | (403) 647-4277
GST/HST: 785971300RT0001

Invoice #20698

Issue date
Apr 1, 2026

A08-7

Haulmark

***MAILING ADDRESS:**

Box 821, Coaldale, Alberta T1M 1M7*

We appreciate your business, If you were satisfied with our service please leave us a 5 star google review

~~Customer Information~~

2% Late Fee after 30 Days

Customer

Jay Reeder
Southern connections inc.
Southernconnectionsinc@gmail.com
(403) 795-6622

Invoice Details

PDF created April 1, 2026
\$974.41

Payment

Due May 1, 2026
\$974.41

Items	Quantity	Price	Amount
licence plate light 090900	1	\$21.22	\$21.22
Labour replace the white metal beside rear door, adjust the other side	1.8 hr	\$155.00/hr	\$279.00
inspection	1	\$155.00	\$155.00
Labour re-wire the break away system to charge correctly.	1.0 hr	\$155.00/hr	\$155.00
Labour replace the clearance lights and licence plate light	1.0 hr	\$155.00/hr	\$155.00
peterson clearance light	6	\$6.65	\$39.90
clearance light backing plate	4	\$6.54	\$26.16
door holder	1	\$13.41	\$13.41
AP product entry door handle	1	\$65.12	\$65.12
Subtotal			\$909.81



Pay online

To pay your invoice go to <https://squareup.com/u/ytMRHIOT>
Or open the camera on your mobile device and place the QR code in the camera's view.

Page 1 of 2





Raven RV ltd
evan@ravenrv.ca | (403) 647-4277
GST/HST: 785971300RT0001

Invoice #20698

Issue date
Apr 1, 2026

shop supplies. (2%)	\$18.20
GST	\$46.40

Total Due \$974.41



Pay online
To pay your invoice go to <https://squareup.com/u/ytMRHIOT>
Or open the camera on your mobile device and place the QR code in the camera's view.



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture