



Chinook Equipment Ltd.  
4305 14 Ave N  
Lethbridge County, AB T1J 5X8  
403.329.6011  
www.ChinookEquipment.ca  
GST# 784146730 RT0001

# SERVICE INVOICE

E10-29

Invoice: 01-50020  
Date: 2/19/2026

PO:  
CustId: CONNECTIONSO

Cust Email: southernconnectionsinc@gmail.com  
Phone: (403) 795-6622  
Salesperson: ChrisS  
User: ChrisS

Bill To:

Ship To:

Southern Connections

*TJ A91 / Key  
AR Led  
Seat*

Opened: 12/4/2025  
Work Order No: 01-51462  
Pickup Date:  
Unit No: 19812  
Unit Serial: ASWT11928  
Unit Desc: COMPACT TRACK LOADER  
Unit Meter: 1,820.4 Hours

Responsible Tech: SawyerM  
My Ref: 51462  
Delivery Date:  
Unit Make: Bobcat  
Unit Model: T870  
Unit Tag:

*196110*

## T870 - INSPECTION, PROVIDE ESTIMATE

Item	Type	Description	Qty	Tax	Price	Discount	Net Price
INSPECTION	SL	<p>INSPECTION</p> <ul style="list-style-type: none"> <li>-inspected machine thoroughly</li> <li>-made a list of all recommended repairs</li> <li>-Complete door assembly, 1000 hr service</li> <li>-Battery, -Tracks, -Seat does not inflate, -Cab dome light bulb</li> <li>-Left window lock, -Drive belt, -Drive belt tensioner</li> <li>- RH tilt cylinder re-seal</li> </ul> <p>Installed a new door and window frame. Removed the drive belt tensioner but encountered difficulty in removing the tensioner from the unit. Consequently, the flywheel was removed from the engine, during which it was discovered that the rear main seal was beginning to leak. Performed a major service on the unit, which included replacing the air filters. It was noted that the bottom of the air filter box is missing the locking tab, and a new air filter box is required. The engine oil was drained and the engine oil filter was replaced. The engine oil was then refilled to full capacity with 12 liters of engine oil. The hydraulic oil return filter and the hydraulic charge filter were replaced, along with an updated cap. The fuel filter was also replaced and the fuel system was primed.</p> <ul style="list-style-type: none"> <li>-still have to replace the drive motor oil, going to have to wait until rear main seal is here in order to put back together drive belt assy</li> <li>-removed old air cleaner box and installed the new one</li> <li>-Removed and installed rear seal, installed flywheel torqued to 50lbs/ft with a 45 degree torque turn</li> <li>-installed battery, -topped up hyd fluid, -tightened engine mounts</li> <li>-removed bobtach, greased and reinstalled.</li> <li>-topped up coolant</li> <li>-drained filled final drive oil</li> <li>-inspected for air ride seat not working--</li> <li>-had found seat will not air up</li> <li>-had found good power going to seat</li> <li>-removed seat from unit</li> <li>-inspected harness, -plugged in all connectors</li> <li>-tested seat and had found seat will still not air up</li> <li>-had tested for power coming out of seat switch had found good power out of switch to compressor, verified ground is good</li> <li>-got new compressor for seat, -removed seat cushion and mounting plate</li> <li>-removed old compressor and installed new one, -put seat back together</li> <li>-installed seat back into unit and function tested, good</li> <li>-resealed tilt cylinder, -installed tilt cylinder</li> <li>-removed and replaced tracks, adjusted, tested.</li> <li>-adjusted door latch</li> <li>-washed.</li> </ul>	29.8001	Y	\$160.00		\$4,768.02
		Customer Pay Compact Shop					

[REDACTED]

[REDACTED]

[REDACTED]



Chinook Equipment Ltd.  
 4305 14 Ave N  
 Lethbridge County, AB T1J 5X8  
 403.329.6011  
 www.ChinookEquipment.ca  
 GST# 784146730 RT0001

# SERVICE INVOICE

E10-29

Invoice: 01-50020  
 Date: 2/19/2026

PO:  
 CustId: CONNECTIONSO

Cust Email: southernconnectionsinc@gmail.com  
 Phone: (403) 795-6622  
 Salesperson: ChrisS  
 User: ChrisS

Bill To:

Ship To:

46923666	PA	BCA - ELEMENT FILTER	1.0000	Y	\$59.88	\$0.89	\$58.99
7400454	PA	BCA - FILTER FUEL	1.0000	Y	\$102.80	\$0.04	\$102.76
ENV+8	MC	Environmental Fee	1.0000	Y	\$1.25		\$1.25
7343102	PA	BCA - FILTER OIL ENGINE	1.0000	Y	\$42.01	\$0.62	\$41.39
ENV-8	MC	Environmental Fee	1.0000	Y	\$0.55		\$0.55
6727475	PA	BCA - CAP HYDRAULIC	1.0000	Y	\$49.91	\$0.74	\$49.17
7414582	PA	BCA - FILTER HYDRAULIC W/O-RING	1.0000	Y	\$112.80	\$1.67	\$111.13
ENV+8	MC	Environmental Fee	1.0000	Y	\$1.25		\$1.25
7496373	PA	BCA - CAP CANISTER HYDRAULIC	1.0000	Y	\$107.05	\$1.58	\$105.47
7176099	PA	BCA - FILTER, AIR FRESH 10	2.0000	Y	\$49.47	\$1.48	\$97.46
7024981	PA	BCA - OIL, SYNTHETIC DRIVE MOTOR 4	2.0000	Y	\$32.88	\$0.94	\$64.82
6983128	PA	BCA - ANTIFREEZE/COOLANT, PG 53/47 PREMIX GAL	4.0000	Y	\$43.46		\$173.84
7269857	PA	BCA - BATTERY WET 1000 CCA	1.0000	Y	\$356.93	\$5.27	\$351.66
7523437	PA	BCA - M-SERIES DOOR ASSEMBLY	1.0000	Y	\$2,968.89	\$343.87	\$2,625.02
46897210	PA	BCA - TRACK RUBBER (450X86X58)	2.0000	Y	\$2,286.70		\$4,573.40
7229539	PA	BCA - "LIGHT, CAB HEADLINER"	1.0000	Y	\$39.47	\$0.58	\$38.89
46913280	PA	BCA - KIT SEAL CYLINDER	1.0000	Y	\$116.44	\$1.75	\$114.69
7286651	PA	BCA - "FILTER, AIR"	1.0000	Y	\$423.07	\$148.07	\$275.00
10W30	PA	OTH - 10W30 OIL, BULK	13.0000	Y	\$8.70		\$113.10
ENV OIL	MC	Environmental Oil	13.0000	Y	\$0.10		\$1.30
7256708	PA	BCA - "COVER, DUST"	1.0000	Y	\$27.68		\$27.68
7409546	PA	BCA - SEAL OIL	1.0000	Y	\$54.68		\$54.68
BOBHYD	PA	BCA - FLUID HYDRAULIC MAX COOL	2.0000	Y	\$10.10		\$20.20
ENV OIL	MC	Environmental Oil	2.0000	Y	\$0.10		\$0.20
6687885	PA	BCA - GREASE, HP EXTREME 10	2.0000	Y	\$11.95		\$23.90
7011180	PA	BCA - COMPRESSOR, AIR SEAT	1.0000	Y	\$436.32		\$436.32
Freight	MC	Parts Freight	1.0000	Y	\$25.40		\$25.40
	SS		1.0000	Y	\$250.00		\$250.00

Segment Total: **\$14,507.54**

Labor:	\$4,768.02
Parts:	\$9,459.57
Misc Charges:	\$29.95
Shop supplies:	\$250.00





Chinook Equipment Ltd.  
 4305 14 Ave N  
 Lethbridge County, AB T1J 5X8  
 403.329.6011  
 www.ChinookEquipment.ca  
 GST# 784146730 RT0001

# SERVICE INVOICE

Invoice: 01-50020  
 Date: 2/19/2026

PO:  
 CustId: CONNECTIONSO

Cust Email: southernconnectionsinc@gmail.com  
 Phone: (403) 795-6622  
 Salesperson: ChrisS  
 User: ChrisS

Bill To: [REDACTED]

Ship To: [REDACTED]

Totals		<b>Sub Total:</b>	<b>\$14,507.54</b>
	GST:	\$725.38	
		<b>Total Tax:</b>	<b>\$725.38</b>
		<b>Invoice Total:</b>	<b>\$15,232.92</b>

Forms of Payment		
Type	Description	Amount
Cheque		\$15,232.92
<b>Total Forms of Payment:</b>		<b>\$15,232.92</b>

Balance Due On This Invoice: \$0.00

Thank you for your business.





## Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

---

Brennan LeBlanc  
Divisional Operations Manager  
Western Canada Agriculture