



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

R01-2
Nov

Branch		
PROVOST		*REPRINT*
Date	Time	Page
03/18/26	22:20:52 (B)	01
Account No	Phone No	Inv No
		W15835
Ship Via		Purchase Order
Tax ID No		
		Salesperson
		326

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019734	X9 1000 COMBINE MY	1E	1H0X910XPR0830834	08/02/26	
	X9 1000	174		08/01/28	750 X

GST# 895703353

SEGMENT# 1 C 334 10-900-010 01/08/26 01/08/26

BRI INSPECTION

17.33 HRS

Repair:

PERFORMED COMBINE AND HEADER INSPECTION

ADDITIONAL DESCRIPTION:

1. BRI INSPECTION (10-900-010)
PERFORM INSPECTION AS PER CHECKLIST.

16001000

LABOR 2205.00
SEGMENT TOTAL==> 2205.00

SEGMENT# 2 C 334 NA 01/22/26 01/22/26

CONTROL SYSTEM

1.00 HRS

LINE 2-PERFORM 1 NEW SOFTWARE UPDATE 1HR

16001000

LABOR 173.25
SEGMENT TOTAL==> 173.25

SEGMENT# 3 C 334 NA 01/22/26 01/22/26

FEEDER HOUSE AREA

3.00 HRS

LINE 5-ADJUST FEEDER HOUSE DRIVE CHAIN 0.50HRS

LINE 9-REPLACE PRO DRIVE FILTER (RE577250) 1HR

LINE 14-ADJUST STONE TRAP DOOR TO CLOSE TIGHTER 1.50HRS

EF4663	RECYC FEE OIL	1	1.05	1.05
--------	---------------	---	------	------

RE577250	Hydraulic Filte	1	146.28	146.28
----------	-----------------	---	--------	--------

Hydraulic Filter

16001000

PARTS 147.33
LABOR 525.00
SEGMENT TOTAL==> 672.33

CONTINUED ON PAGE 02

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1801 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch PROVOST		
Date 03/18/26	Time 22:20:52 (B)	Page 02
Account No	Phone No	Inv No W15835
Ship Via		Purchase Order
Tax ID No		
		Salesperson 326

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019734	X9 1000 COMBINE MY	1E	1H0X910XPR0830834	08/02/26	
	X9 1000	174		08/01/28	750 X

SEGMENT# 4 C 334 NA 01/22/26 01/30/26
LEFT HAND SIDE 8.50 HRS

Repair:

COMPLETE REPAIRS FOR INSPECTION
DIAGNOSE FAULT CODES FOR ACTIVE CONCAVE
HAD FAULTS 517080.07 RIGHT FRONT CONCAVE MOVEMENT NOT
DETECTED AND FAULT CODE 521308.07 LEFT FRONT CONCAVE
MOVEMENT NOT DETECTED.
VISUALLY INSPECTED LINKAGE AND CYLINDERS TO MAKE SURE THERE
WAS NO BENDING OR DAMAGE.
REMOVED CHAFF AND DEBRIS TO PREVENT BINDING STILL WAS
FAULTING.
LEVELED CONCAVES AND COMPLETED CONCAVE THRESHING CLEARANCE
CALIBRATION AND CONCAVE LEVEL CALIBRATION FOR BOTH SIDES.
WOULD NOT MOVE FULL RANGE OF MOTION WITH OUT CODING
PERFORMED LEFT AND RIGHT HAND CONCAVE AIR REMOVAL PROCEDURE
AND RE-LEVELED CONCAVE MOVED CONCAVE FROM 0MM- 40MM STILL
WOULD FAULT.
INSPECTED FAULTED POSTION SENSORS AND FOUN CHAFF INSIDE
SENSOR AND BOLTS LOOSE ON SENSOR MOUNT CAUSING THE SENSOR
TO READ INACCURATE.
CLEANED SENSORS INSPECTED FOR DAMAGE RE-LEVELED CONCAVES
AND PERFORMED CONCAVE LEVEL CALIBRATION AND CONCAVE
THRESHING CALIBRATION PASSED CALIBRATION AND CONCAVES WOULD
OPEN WITH FULL RANGE OF MOTION WITH OUT CODING.

ADDITIONAL DESCRIPTION:

LINE 55-ADJUST FRONT END DRIVE BELT 0.50HRS
LINE 66-LEVEL CONCAVES BOTH SIDES 4HRS
LINE 73-DIAGNOSE TIME FOR FAULT CODE ACTIVE ON BOTH SIDES OF

CONTINUED ON PAGE 03

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch		
PROVOST		
Date	Time	Page
03/18/26	22:20:52 (B)	03
Account No	Phone No	Inv No
		W15835
Ship Via		Purchase Order
Tax ID No		
		Salesperson
		326

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019734	X9 1000 COMBINE MY	1E	1H0X910XPR0830834	08/02/26	
	X9 1000	174		08/01/28	750 X

HYDRAULIC ACTIVE CONCAVE

LINE 88-GREASE VARIABLE SPEED DRIVE 0.50HRS

-GREASE FRONT END DRIVE 0.50HRS

LINE 89-GREASE ROTOR DRIVE 0.50HRS

LINE 99-OIL LEAK AT HYDRAULIC FITTINGS ON CHOPPER GEAR

CASE. TIME TO DIAGNOSE

LINE 117-ADJUST TAILINGS ELEVATOR CHAIN 1HR

-GREASE UNLOADING ELBOW GEAR CASE 0.50HRS

16001000

LABOR 1487.50

SEGMENT TOTAL==> 1487.50

SEGMENT# 5 C 334	NA	01/22/26	01/22/26
RIGHT HAND SIDE		7.00 HRS	

Repair:

Adjusted clean grain elevator chain

Removed water separator

Cleaned out water separator

Put water water separator back onto unit

Installed rotary screen belt

Checked voltage for separator grate actuator

Voltage present

Removed and swapped actuators

Old actuator did not respond to command in new location

Second actuator responded to command where old actuator was

Actuator needs replacing

ADDITIONAL DESCRIPTION:

LINE 159-ADJUST CLEAN GRAIN ELEVATOR CHAIN 1HR

LINE 166-DRAIN WATER SEPERATOR AND CLEAN SEDIMENT BOWL
0.50HRS

LINE 173-REPLACE ROTARY SCREEN VACUUM BELT 1.50HRS

CONTINUED ON PAGE 04

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4483

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch		
PROVOST		
Date	Time	Page
03/18/26	22:20:52 (B)	04
Account No	Phone No	Inv No
		W15835
Ship Via	Purchase Order	
Tax ID No		
		Salesperson
		326

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019734	X9 1000 COMBINE MY	1E	1H0X910XPR0830834	08/02/26	
	X9 1000	174		08/01/28	750 X
LINE 196-DIAGNOSE REMOTE SEPARATOR GRATES NOT WORKING 4HRS					
HXE168680	ROTARY SCREEN	1		87.06	87.06
				PARTS	87.06
				LABOR	691.25
16001000			SEGMENT TOTAL==>		778.31

SEGMENT# 6 C 334	NA	01/22/26	01/22/26		
TRACKS/WHEELS & TIRES				2.00	HRS
LINE 200-CHECK FINAL DRIVE OILS, TOP UP IF NEEDED 1HR					
LINE 204-TORQUE WHEELS 1HR					
EF4664	RECYC FEE OIL	1	.12	.12	
TY6296	GL-5/80w-90	1	15.58	15.58	
			PARTS	15.70	
			LABOR	301.00	
16001000			SEGMENT TOTAL==>		316.70

SEGMENT# 7 C 334	NA	01/22/26	01/22/26		
ENGINE COMPARTMENT				5.50	HRS
LINE 211-ADJUST LADDER 1HR					
LINE 213-VAC FAN DRIVE BELT FRAYED, REPLACE 1HR					
LINE 217-CLEAN OUT RADIATOR 1HR					
LINE 218-TOP UP COOLANT 0.50HRS					
LINE 220-BLOW OUT PRIMARY ENGINE AIR FILTER 0.50HRS					
LINE 230-BLOW OUT/ CLEAN ALTERNATORS 0.50HRS					
LINE 233-CHANGE ENGINE OIL + FILTER 1HR					
EF4663	RECYC FEE OIL	1	1.05	1.05	
EF4666	RECYC FEE OIL	3	2.40	7.20	
HXE125617	FAN DRIVE BELT	1	106.96	106.96	
RE572785	Oil Filter	1	127.80	127.80	
TY26575	COOL-GARD TM	1	27.03	27.03	

CONTINUED ON PAGE 05

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-872-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1801 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch		
PROVOST		
Date	Time	Page
03/18/26	22:20:52 (B)	05
Account No	Phone No	Inv No
		W15835
Ship Via	Purchase Order	
Tax ID No		
		Salesperson
		326

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019734	X9 1000 COMBINE MY	1E	1H0X910XPR0830834	08/02/26	
	X9 1000	174		08/01/28	750 X
TY26679	PLUS-50 TM E	3		159.28	477.84
	Plus-50 II Oil 15W40 CJ4/SN				
			PARTS		747.88
			LABOR		962.50
	16001000		SEGMENT TOTAL==>		1710.38

SEGMENT# 8 C 334	NA	01/22/26	01/22/26		
GRAIN TANK SECTION					.50 HRS
<u>Repair:</u>					
Filled gearcase with oil					
<u>ADDITIONAL DESCRIPTION:</u>					
LINE 276-TOP UP GEAR CASE OIL 0.50HRS					
EF4664	RECYC FEE OIL	1	.12		.12
TY6296	GL-5/80w-90	1	15.58		15.58
			PARTS		15.70
			LABOR		78.75
	16001000		SEGMENT TOTAL==>		94.45

SEGMENT# 9 C 334	NA	01/22/26	01/22/26		
CAB SECTION					1.00 HRS
LINE 283-REPLACE CAB AIR FILTER 0.50HRS					
-REPLACE RECIRCULATING FILTER 0.50HRS					
AXE70605	AIR FILTER	1	37.71		37.71
TA32591	Air Filter	1	112.80		112.80
			PARTS		150.51
			LABOR		152.25
	16001000		SEGMENT TOTAL==>		302.76

SEGMENT#10 C 334	NA	01/22/26	01/22/26		
BP15 HEADER SRL# 830214					1.00 HRS
CONTINUED ON PAGE 06					

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4483

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch PROVOST		
Date 03/18/26	Time 22:20:52 (B)	Page 06
Account No	Phone No	Inv No W15835
Ship Via		Purchase Order
Tax ID No		
		Salesperson 326

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019734	X9 1000 COMBINE MY	1E	1H0X910XPR0830834	08/02/26	
	X9 1000	174		08/01/28	750 X
PICKUP BELT					
LINE 16-ADJUST PICKUP HEIGHT 0.50HRS					
LINE 19-REPLACE 1 BENT WINDROW HOLD DOWN 0.50HRS					
AH231461	FINGER	1		32.91	32.91
EF4665	RECYC FEE OIL	1		.48	.48
TY26815	80w90	1		50.44	50.44
14M7298	FLANGE NUT	1		1.88	1.88
				PARTS	85.71
				LABOR	105.00
16001000			SEGMENT TOTAL==>		190.71

SEGMENT#11 C 334 NA 01/22/26 02/04/26
FEED AUGER 4.50 HRS

Repair:

COMPLETE REPAIRS AS PER INSPECTION

ADDITIONAL DESCRIPTION:

LINE 22-ADJUST FLIGHTING HEIGHT 1HR
LINE 25-ADJUST FINGER TIMING 1HR
LINE 29-ADJUST CROSS AUGER CHAIN 0.50HRS
LINE 31-ADJUST FLOOR STRIPPER 1HR
LINE 32-ADJUST REAR STRIPPER 1HRR

	LABOR	343.00
16001000	SEGMENT TOTAL==>	343.00

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	1249.89	
LABOR	7024.50	

CONTINUED ON PAGE 07

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To: IN STORE PICKUP

Invoice To:

Branch PROVOST		
Date 03/18/26	Time 22:20:52 (B)	Page 07
Account No	Phone No	Inv No W15835
Ship Via		Purchase Order
Tax ID No		
		Salesperson 326

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019734	X9 1000 COMBINE MY	1E	1H0X910XPR0830834	08/02/26	
	X9 1000	174		08/01/28	750 X
			SERV ACCESORIES		100.00
			INTERNAL TOTAL		8374.39

1-877-813-3373

WWW.BRILTD.COM

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____