## **Cummins South Pacific Pty. Ltd.**

ABN NO. 42006332949

## **WORKSHOP TAX INVOICE INVOICE NUMBER**



Laverton 191-195 Boundary Road Laverton North Vic 3026 Ph: 03 8368 0800

COPY

INVOICE DATE

07/08/20

1

PAGE

**Invoice To** 

Account Number Z000049 WARRANTY LOCAL (AUST) WARRANTY (AUST)

Engine Model:	SIGNATURE/ISX/QSX	Eng No:	79895994	Equip Make:	KENWORTH
FleetNo:	78	Reg No:	XQ08CB	Cust Ord NO:	
Date in Service:	25/04/16	KLMS:		HRS:	
Repair Date:	07/08/20	Chassis NO:	456375	Currency:	AUD
C.O.No.	6458705	Work ordNo.		Facility	322

## Complaint:

C clip came off turbo wastegate

Cause:

Turbo wastegate lever bent & C clip missing.

Correction:

PG382 / 322 Laverton CSS Number: CSS-00731637

ECM Klms: 1123156 km

OEM Hourmeter:

ECM Engine RUN time Hours: 15281 hrs

ECM Fuel Burn: 578746 Lts

CA#4464 Expiry:24/04/21

Maintence Inv#7769727 04/05/2018 555447 Kms

Visually inspected turbo. Found waste gate actuator rod had fallen off, no clip on lever, lever bent. Carried out turbo waste-gate campaign C2261. Removed turbo, set up new & then fitted. Waste-gate travel 0.054" at 31psi. Ran, washed & road tested to verify repairs.

Description	Operation	Unit price	Qty	Extension		
Labour						
	LABOUR TOTAL					
Material						
4298242	STUD		1			
5327754RX	RECON TURBO HE600WG (F	EPR)	1			
3818824	NUT REGULAR HEXAGON		4			

Div

## Cummins South Pacific Pty. Ltd. WORKSHOP TAX INVOICE



Laverton 191-195 Boundary Road Laverton North Vic 3026 Ph: 03 8368 0800

Fax: 03 9360 0438

Invoice To

Account Number Z000049

**INVOICE NUMBER** 

INVOICE DATE PAGE 07/08/20

2

Description	Operation	Unit price	Qty	Extension	
		MATERIAL TOTA	L		
		SUB-TOTAL INVOICE TOTAL	SUB-TOTAL INVOICE TOTAL		