

1/7/2020	1,200,391.00	Repair	R/R Trailer brake hob switch R/R Trailer & maxi brake control valve -3.0 hours
1/16/2020	1,204,710.00	B Service +	B Service \$195.00 Repair lights 2.0 hours
2/25/2020	1,212,410.00	Repairs	R/R compressor unit - 3.0 hours
3/14/2020	1,221,105.00	A Service	A Service \$75.00
3/28/2020	1,228,812.00	B Service	B Service \$195.00
4/28/2020	1,242,477.00	B Service	B Service \$195.00
5/4/2020	1,243,019.00	Repair	Remove & replace steering box – 3.0 hours
7/13/2020	1,256,700.00	A Service	A Service \$75.00
9/14/2020	1,268,877.00	Repairs	R/R Suzi coils – 1.0 hour
9/26/2020	1,274,877.00	B Service	B Service \$195.00
11/21/2020	1,299,110.00	A Service	A Service \$75.00
12/9/2020	1,305,474.00	RCI	RCI Inspection \$100.00
2/16/2021	1,320,370.00	Repair	R/R Cabin air bags -2.0 hours
3/5/2021	1,329,349.00	B Service +	B Service \$195.00 Fit new headlights -1.0 hour
5/26/2021	1,357,453.00	Repair	R/R Horton Fan Line R/R R/H Bonnet block, replace radiator cap.
6/9/2021	1,365,170.00	A Service	A Service Fault Report: Diff Leak
7/7/2021	1,378,582.00	B Service	B Service
9/16/2021	1,390,000.00	Repairs	Remove & replace Governor lines Remove & replace Hi/Low protection valve Fit deckplate
11/6/2021	1,392,565.00	A Service	Replaced globes in R/H mirror, Repair wiring for L/H/R side light NB: Needs good wash
11/28/2021	1,395,453.00	C Service	See job card, all oil & filters replaced
1/21/2022	1,397,268.00	B Service	See job card
3/2/2022	1,416,110.00	A Service + Repairs	See invoice Torque & Diesel 00014701
3/7/2022	1,417,467.00	Repairs	See invoice Fleet Pro 550351
5/14/2022	1,426,707.00	A Service + Repairs	See job card for details.
8/1/2024	1,437,744.00	Repairs	Replace Batteries Invoice 20066