



## Vehicle History Detail



Fleet #	ZGI471
Registration	ZGI471
Make	Kenworth
Model	T909
VIN / Chassis #	6F5000000CA447407

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		<b>STRIP</b> R-12882	CHS Broadbent Toowoomba		\$0.00
19/08/2025	1,823,865 kms	<b>AC Repair</b> R-12792 Pressure tested AC Replaced compressor to condenser hose Replaced drier Cleaned out evap	CHS Broadbent Toowoomba		\$145.75
03/07/2025	1,818,806 kms	<b>REPAIRS</b> R-12480 Replace Oil filler cap. Replace Heater control			\$459.70
18/06/2025	1,816,533 kms	<b>REPAIRS</b> R-12378 REMOVE & REPLACE CLUTCH	TRUCKS ON THE RUN	20252770	\$3,609.55
16/06/2025	1,000,000 kms	<b>REPAIRS</b> R-12330 HYDRAULINK - REPLACE GEARBOX, POWER STEERING & FUEL LINES	TRUCKS ON THE RUN		\$4,915.02
12/06/2025	1,816,527 kms	<b>C - C Service</b> S-21264 Completed C Service Repair driving lights. Repair side lights. Replaced air filter. Serviced Ice Pack. Replaced torque rod bushes on top of Front diff. Replaced air drier filter. Engine tune up.	CHS Broadbent Toowoomba		\$8,418.80
02/06/2025	1,812,517 kms	<b>New Steer Tyres</b> T-5280 Fitted 2 GITI GSR259 295/80r22.5 Steer Tyres	CHS Broadbent Toowoomba, Tyreright Oakey		\$1,571.44
07/05/2025	1,809,227 kms	<b>Rear Bumper</b> R-12085 Replace and paint rear bumper.	CHS Broadbent Toowoomba		\$0.00
02/05/2025	1,000,000 kms	<b>REPAIRS</b> R-12010 R/R - door weathershields	CHS Broadbent Toowoomba		\$1,125.39
04/04/2025	1,806,279 kms	<b>Air Conditioning</b> R-11888 Replace AC hose from Condenser to receiver dryer. replace drier. Clean out evap.	CHS Broadbent Toowoomba		\$0.00
03/03/2025	1,805,689 kms	<b>B - Oils &amp; Filters</b> S-20545 Service Ice Pack. Replace radiator. Replace all boost hoses. Replace Coolant hoses. Replace radiator mounts. Replace fan. Repair Ice pack fan.	CHS Broadbent Toowoomba		\$3,054.64
24/02/2025	1,806,000 kms	<b>Radiator</b> R-11604 Recore radiator with 6 row and clean out radiator	CHS Broadbent Toowoomba		\$6,105.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
04/02/2025	1,799,324 kms	<b>Air Fittings, REPAIRS</b> R-11500 Replace air hookup valve, replace air drain valve, replace trailer supply fitting, Repair air leak on Air drier,	CHS Broadbent Toowoomba		\$101.97
01/02/2025	1,798,035 kms	<b>A - Grease &amp; Brake Adj</b> S-20250 Replace light socket	CHS Broadbent Toowoomba		\$0.00
20/12/2024	1,786,567 kms	<b>B - Oils &amp; Filters</b> S-19963 Completed B Service Service Icepack	CHS Broadbent Toowoomba		\$212.66
29/11/2024	1,781,716 kms	<b>Clutch Adjust</b> R-11118 Adjust clutch for more free travel.	CHS Broadbent Toowoomba		\$0.00
15/11/2024	1,780,056 kms	<b>Annual Primemover Inspection</b> I-966 Completed Annual Inspection	CHS Broadbent Toowoomba		\$0.00
15/11/2024	1,780,056 kms	<b>air leaks, Steering</b> R-11007 Repair Air Leaks, Replace Steel Shaft on steering arm, Light repairs.	CHS Broadbent Toowoomba		\$1,774.28
09/11/2024	1,779,815 kms	<b>Air Conditioning</b> R-10960 Replace Evap TX valve, Replace HVAC Box, Replace Fresh Mixing Motor, Replace HOT hose, Replace Compressor, Adjust Clutch.	CHS Broadbent Toowoomba		\$1,157.95
25/10/2024	1,778,639 kms	<b>A - Grease &amp; Brake Adj</b> S-19357 Completed A Service Replace Water Pump, Replace lower heater tap, Replace Treadle Roller.	CHS Broadbent Toowoomba		\$1,576.92
12/10/2024	1,768,171 kms	<b>B - Oils &amp; Filters</b> S-19236 Completed B Service Service Ice Pack, Hard Wire LH Spotlight,	CHS Broadbent Toowoomba		\$377.50
08/10/2024	1,768,000 kms	<b>PTO PUMP</b> R-10752 R/R - PTO			\$779.67
21/09/2024	1,757,159 kms	<b>A - Grease &amp; Brake Adj</b> S-19002 Completed A Service	CHS Broadbent Toowoomba		\$4,711.35
26/08/2024	1,744,818 kms	<b>B - Oils &amp; Filters</b> S-18772 Replace Headlights, Service Ice Pack, Replace Drive guard,	CHS Broadbent Toowoomba		\$1,118.58
15/08/2024	1,736,249 kms	<b>Driving Lights install, Windscreen Wiper Blades</b> R-10412 R/R - Driving Lights	CHS Broadbent Toowoomba		\$0.00
14/08/2024	1,733,811 kms	<b>New Steer Tyres</b> T-4576 Fitted 2 Kumho KAR88+ 385/65R22.5 Steer Tyres	CHS Broadbent Toowoomba, Tyrreright Oakey		\$1,080.00
09/08/2024	1,733,811 kms	<b>WINDSCREEN</b> R-10366 Fitted RH windscreen	Instant Windscreen		\$740.00
06/08/2024	1,729,974 kms	<b>A - Grease &amp; Brake Adj</b> S-18518 Completed A Service	CHS Broadbent Toowoomba		\$819.94
16/07/2024	1,720,675 kms	<b>B - Oils &amp; Filters</b> S-18344 Completed B Service Repair Ice Pack wiring, Repair Coolant leak in cab,	CHS Broadbent Toowoomba		\$993.97

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/07/2024	1,715,275 kms	<b>New Drive Tyres</b> T-4547 Fitted 8 Haulstar HD610 Drive tyres	CHS Broadbent Toowoomba, Tyeright Oakey		\$2,000.00
28/06/2024	1,710,986 kms	<b>A - Grease &amp; Brake Adj</b> S-18177 Completed A Service	CHS Broadbent Toowoomba		\$583.33
21/06/2024	1,708,094 kms	<b>coolant leak , Ice Pack</b> R-10146	CHS Broadbent Toowoomba		\$0.00
06/06/2024	1,699,356 kms	<b>Alternator, Alternator Belts</b> R-10067 R/R - Alternator	CHS Broadbent Toowoomba		\$537.61
06/06/2024	1,699,369 kms	<b>C - C Service</b> S-17970 Completed C Service Changed Diff Oils and filter Replaced transmission oil and filter R/R - Governor Valve Replaced Alternator Engine Tune Up Replaced Tensioners and idlers Repalced Air Cleaners Reapirod dash lights	CHS Broadbent Toowoomba		\$1,297.24
30/05/2024	1,699,356 kms	<b>King Pin</b> R-9981	CHS Broadbent Toowoomba		\$1,013.47
30/05/2024	1,699,356 kms	<b>Wheel Alignment</b> R-10018	Toowoomba Truck Alignments		\$539.00
30/05/2024	1,699,356 kms	<b>B - Oils &amp; Filters</b> S-17912 Fitted new engine oil cooler	CHS Broadbent Toowoomba		\$5,110.94
07/05/2024	1,687,754 kms	<b>A - Grease &amp; Brake Adj</b> S-17721 2nd Air Bag LHS Replaced. Replaced Temp Gauge.	CHS Broadbent Toowoomba		\$829.91
19/04/2024	1,678,578 kms	<b>B - Oils &amp; Filters</b> S-17577 King Pins need Attention. Radiator has oil appearing in the coolant.	CHS Broadbent Toowoomba		\$394.33
09/04/2024	1,672,201 kms	<b>Fuel Lines</b> R-9756 REMOVE & REPLACE 2 FUEL LINES ON TRUCK DSR 23146	Enzed		\$1,498.83
03/04/2024	1,669,912 kms	<b>cab mounts, CAC, engine mounts</b> R-9726 R/R - CAC R/R - Cab mounts R/R - Engine Mounts	CHS Broadbent Toowoomba		\$5,412.78
02/04/2024	1,669,522 kms	<b>A - Grease &amp; Brake Adj</b> S-17425 Completed A Service	CHS Broadbent Toowoomba		\$0.00
08/03/2024	1,659,915 kms	<b>Horton Fan</b> R-9598 Rekit Horton fan hub fitted new belts blow out and wash radiator	CHS Broadbent Toowoomba		\$972.80
02/03/2024	1,656,049 kms	<b>B - Oils &amp; Filters</b> S-17159	CHS Broadbent Toowoomba		\$395.98
22/02/2024	1,649,126 kms	<b>FUEL ISSUE</b> R-9499 Blocked Fuel Filter Inlet Check Valve	Cummins		\$775.76
16/02/2024	1,647,895 kms	<b>New Drive Tyres</b> T-4229 Fitted 8 Haulstar HD306 11r22.5 Drive Tyres	CHS Broadbent Toowoomba, Tyeright Oakey		\$2,000.00
14/02/2024	1,647,895 kms	<b>New Steer Tyres</b> T-4201 Fitted and Balanced 2 Kumho KAR88+ 385/65 22.5 Steer Tyres	CHS Broadbent Toowoomba, Tyeright Oakey		\$1,100.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
09/02/2024	1,647,895 kms	<b>A - Grease &amp; Brake Adj</b> S-16928 Completed A Service replaced spotlight bracket replaced light socket on rear of truck replaced wiper blades replaced top bonnet supports replaced batteries welded mudguard	CHS Broadbent Toowoomba		\$760.82
13/01/2024	1,635,673 kms	<b>B - Oils &amp; Filters</b> S-16712 Completed B Service serviced ice pack	CHS Broadbent Toowoomba		\$677.31
08/12/2023	1,626,145 kms	<b>A - Grease &amp; Brake Adj</b> S-16423 Completed A Service replaced steer hub caps replaced air compressor	CHS Broadbent Toowoomba		\$4,206.78
18/11/2023	1,615,386 kms	<b>B - Oils &amp; Filters</b> S-16227 Completed B Service replace A/C belt, tensioner and idler repair exhaust leak at dpf injector replaced ac evaporator & tx replaced ac dryer	CHS Broadbent Toowoomba		\$1,413.20
31/10/2023	1,607,726 kms	<b>C - C Service</b> S-16028 Completed C Service kitted air dryer replaced tensioners cleaned cool pack and tested cac completed engine tune up repaired air leaks around rear hook up, on fire wall, under cab replaced upper radiator hose from thermostat	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$1,529.92
12/10/2023	1,602,975 kms	<b>A - Grease &amp; Brake Adj</b> S-15888 Completed A Service replaced mud flaps on the front of drive	CHS Broadbent Toowoomba		\$0.00
12/10/2023	1,602,975 kms	<b>Annual Primemover Inspection</b> I-709 Completed Annual Inspection	CHS Broadbent Toowoomba		\$0.00
29/09/2023	1,597,305 kms	<b>Air Leak, oil leak</b> R-8777 replaced trailer air fittings replaced tema fittings replaced oil pressure sensor	CHS Broadbent Toowoomba		\$0.00
15/09/2023	1,592,629 kms	<b>B - Oils &amp; Filters</b> S-15631 Completed B Service repaired drivers door window adjusted clutch replaced starter solenoid blow out radiator	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$748.20
31/08/2023	1,585,936 kms	<b>Starter Motor</b> R-8668 Fitted new starter motor	Black Trucks		\$1,124.42
11/08/2023	1,582,371 kms	<b>A - Grease &amp; Brake Adj</b> S-15290 Completed A Service replaced stereo adjusted clutch resealed breather thread in tanks replaced wiper blades	CHS Broadbent Toowoomba		\$0.00
14/07/2023	1,573,243 kms	<b>B - Oils &amp; Filters</b> S-15043 Completed B service replace 3x deck plate locks blow radiator out R/R drive shock absorbers	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$4,970.83
16/06/2023	1,564,659 kms	<b>A - Grease &amp; Brake Adj</b> S-14769 Completed A Service replaced torque rod bushes on drive replaced steer shock bushes repaired boost guage hose	CHS Broadbent Toowoomba		\$476.61
20/05/2023	1,553,707 kms	<b>B - Oils &amp; Filters</b> S-14545 Completed B Service replaced drive mud flaps repaired coolant leak pressure test cooling system service ice pack replace gearbox temp sender replace steering box	CHS Broadbent Toowoomba		\$5,743.12
20/04/2023	1,542,869 kms	<b>A - Grease &amp; Brake Adj</b> S-14282 Completed A Service repaired ice pack cover	CHS Broadbent Toowoomba		\$0.00
24/03/2023	1,533,686 kms	<b>B - Oils &amp; Filters</b> S-13993 Completed B Service serviced ice pack repaired icepack cover cleaned radiator	CHS Broadbent Toowoomba, TRUCKLINE		\$408.44

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
21/02/2023	1,521,204 kms	<b>A - Grease &amp; Brake Adj</b> S-13684 Completed A Service	CHS Broadbent Toowoomba		\$0.00
31/01/2023	1,511,811 kms	<b>Bonnet Mount, drivers seat, Icepack, tacho</b> R-7875 Replaced drivers seat replaced icepack mounts repaired air leaks repaired cold coolant weep compressor supply hose fitting replaced boost hoses repaired vanity plate brackets reraced steering column replaced steer slack adjusters replaced bonnet mounts and pivot bushes	CHS Broadbent Toowoomba		\$3,287.73
31/01/2023	1,511,811 kms	<b>B - Oils &amp; Filters</b> S-13468 Completed B Service replaced driver seat replaced ice pack mounts repaired air leaks repair coolant cold weep compressor supply fitting replaced boost hoses repair vanity plate brackets replace slack adjusters on steer replace bonnet mounts and pivot mounts	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$526.20
18/01/2023	1,511,811 kms	<b>A - Grease &amp; Brake Adj</b> S-13309 Completed A Service repaired cold coolant leak	CHS Broadbent Toowoomba		\$0.00
08/12/2022	1,499,026 kms	<b>New Drive Tyres</b> T-3322 Fitted 8 Goodyear G667+ Drive tyres	CHS Broadbent Toowoomba, Tyres 4U		\$3,999.78
05/12/2022	1,499,026 kms	<b>B - Oils &amp; Filters</b> S-12958 Complete B service replaced track rod bushes replaced cab mounts replaced air filters Fitted Engel Fridge 40 Ltr Ser No OOT-0168	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$1,559.39
08/11/2022	1,492,320 kms	<b>New Steer Tyres</b> T-3244 Fitted 2 Bridgestone R249 385/65	CHS Broadbent Toowoomba, Tyres 4U		\$1,697.50
31/10/2022	1,489,014 kms	<b>C - C Service</b> S-12604 Completed C service repaired coolant leaks completed engine tune up replaced diff oils replaced drive bearings repaired vanity panel bracket steering pressures within OEM tolerances cac pressure tested	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$1,442.53
29/10/2022	1,489,014 kms	<b>Engine Tune Up</b> R-6948 Completed Engine Tune Up	CHS Broadbent Toowoomba		\$0.00
24/10/2022	1,489,013 kms	<b>B - Oils &amp; Filters</b> S-12567 completed B service	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$340.18
07/10/2022	1,489,013 kms	<b>Annual Primemover Inspection</b> I-391 Completed Annual Inspection	CHS Broadbent Toowoomba		\$0.00
27/09/2022	1,482,192 kms	<b>A - Grease &amp; Brake Adj</b> S-12271 Completed A Service replaced dog bones replaced 2 boost hoses resealed power divider	CHS Broadbent Toowoomba		\$0.00
18/08/2022	1,469,168 kms	<b>B - Oils &amp; Filters</b> S-11919 Completed B Service Adjusted Clutch Replaced turntable feet bushes	TTS - Toowoomba Truck Spares		\$568.38
29/07/2022	1,459,791 kms	<b>A - Grease &amp; Brake Adj</b> S-11737 Completed A Service Replaced cruise control bulb replaced drivers door lock barrel	CHS Broadbent Toowoomba		\$0.00
01/07/2022	1,449,364 kms	<b>B - Oils &amp; Filters</b> S-11479 Completed B Service Wheel Aligned	CHS Broadbent Toowoomba		\$328.65

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/06/2022	1,449,598 kms	<b>Sensors, Suspension</b> R-6830 Fitted new front springs replaced shackle pins and bushes Check wiring to crankcase pressure sender and cleared fault code	CHS Broadbent Toowoomba		\$2,243.24
08/06/2022	1,442,226 kms	<b>A - Grease &amp; Brake Adj</b> S-11254 Completed A Service R/R - Front and Rear engine mounts repair air leaks in truck replaced FRH drive wheel seal replaced bottom radiator mounts replaced radiator strut rubbers replaced ECM temp sender replaced Drive HCV and rose joints replaced engine fan replaced bunk stop rubbers replaced cab HCV replaced front LH shock absorber rubbers repaired wiring to brake lights in rear bumper adjusted clutch replaced indicator stalk replaced 2 cab airbags replaced crankcase filter	CHS Broadbent Toowoomba		\$3,438.58
09/05/2022	1,430,000 kms	<b>B - Oils &amp; Filters</b> S-10979 Completed B service	CHS Broadbent Toowoomba		\$291.43
22/04/2022	1,424,510 kms	<b>A - Grease &amp; Brake Adj</b> S-10848 Completed A Service - refitted air cleaner lights, replaced steering shaft, repaired air leaks, replaced RH dog box lock, bungs in radiator header tank not designed to give accurate coolant level Fitted 2 new windscreens	CHS Broadbent Toowoomba		\$589.80
16/03/2022	1,411,236 kms	<b>B - Oils &amp; Filters</b> S-10540 Completed B Service - repaired drivers door, blew radiator out, replaced bottom diff track rod bushes, Fitted 4 new batteries Super Crank 1000CCA	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$1,454.09
02/02/2022	1,400,727 kms	<b>A - Grease &amp; Brake Adj</b> S-10223 Completed A Service R/R - Bonnet Rubbers R/R - Hoses on EGR	CHS Broadbent Toowoomba		\$86.90
12/01/2022	1,391,525 kms	<b>B - Oils &amp; Filters</b> S-9990 Carried out C Service - Replaced heater control unit, replaced pitman arm bolt replaced 5 x perished drive airbags repair to electrical fault in icepack Drivers side window cracked	CHS Broadbent Toowoomba		\$277.19
12/01/2022	1,391,525 kms	<b>C - C Service</b> S-9848 Carried out C Service - Replaced heater control unit, replaced pitman arm bolt replaced 5 x perished drive airbags repair to electrical fault in icepack Drivers side window cracked	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$3,754.04
20/12/2021	1,385,896 kms	<b>B - Oils &amp; Filters</b> S-9810 Completed B Service, Replaced radiator cap, replaced front L.H drive airbags, Small crack drivers windscreen, Requires full set of drive airbags, LH bonnet helper spring assembly missing.	CHS Broadbent Toowoomba		\$277.48
20/12/2021	1,385,896 kms	<b>New Drive Tyres</b> T-2706 Fitted 8 new Haulstar HD510 Drive tyres	CHS Broadbent Toowoomba, Tyeright Oakey		\$2,119.98
07/12/2021	1,381,215 kms	<b>A - Grease &amp; Brake Adj</b> S-9653 Completed A Service on complete unit. Replaced 2 X C.A.C hoses, Blew out radiator and C.A.C, NEEDS NEW DRIVE TYRES	CHS Broadbent Toowoomba		\$0.00
01/11/2021	1,372,741 kms	<b>A - Grease &amp; Brake Adj</b> S-9414 Completed A Service Repaired wiring to RH high beam KJM - repaired A/C and fitted remote tipping	CHS Broadbent Toowoomba		\$0.00
19/10/2021	1,367,014 kms	<b>B - Oils &amp; Filters</b> S-9194 Completed B Service Blew out and pressure cleaned CAC and Radiator R/R - Bonnet Stops	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$277.19

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
01/10/2021	1,361,647 kms	<b>Annual Primemover Inspection</b> I-14 Completed Annual Inspection as per checklist	CHS Broadbent Toowoomba		
28/09/2021	1,359,925 kms	<b>A - Grease &amp; Brake Adj</b> S-8987 Complete A service R/R bolts in LH rear mudflap Fitted new headlights R/R driver door seal	CHS Broadbent Toowoomba		\$1,190.57
17/09/2021	1,000,000 kms	<b>Derating</b> R-5757 Plugged in computer and check why the truck derated Found exhaust gas pressure faults Inspect all wiring, plug between sensor & ECM Remove and clean boost sensor, remove differential pressure sensor Fitted second hand exhaust gas pressure sensor Take for test drive	VIC Workshop		\$0.00
07/09/2021	1,350,948 kms	<b>New Steer Tyres</b> T-2554 Fitted 2 new Bridgestone R249 Steer Tyres	CHS Broadbent Toowoomba, Tyeright Oakey	OKSI0064039	\$1,470.02
06/09/2021	1,350,948 kms	<b>B - Oils &amp; Filters</b> S-8815 Completed B Service R/R - Air Compressor R/R - Air Drier Cartridge R/R - Air Compressor Hot Line	CHS Broadbent Toowoomba		\$3,053.05
11/08/2021	1,341,710 kms	<b>A - Grease &amp; Brake Adj</b> S-8545 Completed A Service R/R - Steer King Pings Wheel Aligned	CHS Broadbent Toowoomba		\$855.87
16/07/2021	1,331,972 kms	<b>B - Oils &amp; Filters</b> S-8302 Completed B Service.	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares	584194	\$263.94
30/06/2021	1,323,053 kms	<b>A - Grease &amp; Brake Adj</b> S-8155 Completed A service. Repaired drivers door rattle. Replaced leaking drive airbag.	CHS Broadbent Toowoomba	2224408	\$239.05
25/06/2021	1,323,053 kms	<b>General Repair</b> R-5434 New deck plate locks installed.			
03/06/2021	1,313,033 kms	<b>B - Oils &amp; Filters</b> S-7925 Completed B Service. Replaced front bonnet mounts. Replaced jack shaft thru shaft seal and yoke. Replaced tow eye bush.	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$2,885.40
22/05/2021	1,306,910 kms	<b>A - Grease &amp; Brake Adj</b> S-7826 Completed A Service. ** Requires 6 new deck plate locks **	CHS Broadbent Toowoomba		
01/05/2021	1,295,304 kms	<b>C - C Service</b> S-7561 Completed C Service. Rekitted horton fan. Replaced alternator. Adjusted clutch. Rekitted turntable. Replaced governor valve. CAC remove, clean and pressure check. Diff oil and filter change. Steer wheel bearing replacement. Transmission oil and filter change.	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares	2181598	\$4,724.43
01/05/2021	1,295,304 kms	<b>Engine Tune Up</b> R-5021 Engine tune up.			
09/04/2021	1,284,913 kms	<b>B - Oils &amp; Filters</b> S-7410 Completed B Service. (Shocks are in spec.) (Steering uni's are in spec.) Tire right - Flipped steers on rims.	CHS Broadbent Toowoomba	570823	\$233.23
26/03/2021	1,280,575 kms	<b>B - Oils &amp; Filters</b> S-7310 Completed B Service. Replaced wiper blades.	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares	568272	\$302.19

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
15/03/2021	1,272,456 kms	<b>A - Grease &amp; Brake Adj</b> S-7211 Completed A Service. Replaced door lock barrel.	CHS Broadbent Toowoomba		
15/02/2021	1,258,620 kms	<b>B - Oils &amp; Filters</b> S-6924 Completed B service and repairs.	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares	563161	\$281.97
01/02/2021	1,250,095 kms	<b>A - Grease &amp; Brake Adj</b> S-6752 Completed A Service.	CHS Broadbent Toowoomba		
18/01/2021	1,242,641 kms	<b>Bonnet Mount</b> R-4883 Bonnet mounts replaced.			
08/01/2021	1,239,156 kms	<b>B - Oils &amp; Filters</b> S-6561 Completed A/B Service. Replaced both wiper heads. Adjusted bonnet.	CHS Broadbent Toowoomba	2095140	\$460.97
11/12/2020	1,229,859 kms	<b>A - Grease &amp; Brake Adj</b> S-6241 Completed A Service.	CHS Broadbent Toowoomba	2074810	\$431.86
20/11/2020	1,219,279 kms	<b>B - Oils &amp; Filters</b> S-6118 Fitted Flashing Light and Hard wire In Rebush Turntable, New Bushes, Ductiles Pins and Bines Fit Oversize Sign Replace Cab Filter	VIC Workshop	2063792	\$1,684.39
12/11/2020	1,213,833 kms	<b>Brake Light Switch</b> R-4409 Fitted New Brake Light Switch	CHS Broadbent Toowoomba		
02/11/2020	1,210,059 kms	<b>A - Grease &amp; Brake Adj</b> S-5899 Completed A Service	CHS Broadbent Toowoomba	976274	\$84.59
06/10/2020	1,200,178 kms	<b>C - C Service</b> S-5674 Completed C Service	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares	548281	\$1,193.14
26/09/2020	1,197,672 kms	<b>A - Grease &amp; Brake Adj</b> S-5622 Completed A Service	CHS Broadbent Toowoomba		
16/09/2020	1,197,108 kms	<b>Pressure Check</b> T-1862	Tyreright Oakey	OKSI0054830	\$3.52
31/08/2020	1,190,432 kms	<b>B - Oils &amp; Filters</b> S-5351 Completed B Service Fitted new exhaust stacks	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares	542803	\$668.97
28/08/2020	1,183,278 kms	<b>New Steer Tyres</b> T-1822 Fitted 2 new GITI 385/65/R22.5 GSR259	Tyres 4U	XX756113	\$1,238.09
21/08/2020	1,173,944 kms	<b>EGR Cooler, Turbo, Turbo Actuator</b> R-4110 Fitted new turbo and actuator Fitted new EGR Cooler	Cummins Toowoomba	8709353	\$4,311.23
11/08/2020	1,180,482 kms	<b>A - Grease &amp; Brake Adj</b> S-5191 Completed A Service replace bulb in LH high beam adjust clutch brake replaced steering shaft unis spotlights u/s updated to hard kore led spotties	CHS Broadbent Toowoomba	1985832	\$1,276.00
22/07/2020	1,173,670 kms	<b>New Drive Tyres</b> T-1717 Fitted 8 new Advance GL266 Drive Tyres	Tyres 4U	OKSI53417	\$3,015.94



Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
21/07/2020	1,173,966 kms	<b>Air Conditioning</b> R-3959 R/R - Heater Core	CHS Broadbent Toowoomba		
08/07/2020	1,169,640 kms	<b>B - Oils &amp; Filters</b> S-4892 Completed B Service Checked cab mounts and cab suspension	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares	1962842	\$668.59
15/06/2020	1,160,398 kms	<b>A - Grease &amp; Brake Adj</b> S-4705 Completed A Service Fitted new Crankcase Element	CHS Broadbent Toowoomba		
29/05/2020	1,153,994 kms	<b>Steer Rotation</b> T-1560	Bridgestone		\$103.40
18/05/2020	1,148,689 kms	<b>Break Down</b> R-3664 Intake Temp Sensor Faulty	Cummins		\$1,011.98
16/05/2020	1,148,522 kms	<b>B - Oils &amp; Filters</b> S-4490 Completed B Service R/R - Windscreen washer motor	Vanfit Diesel	527736	\$358.91
14/05/2020	1,148,522 kms	<b>Turbo, Turbo Actuator</b> R-3599 replace turbo and actuator refer to vanfit invoice repair notes	CHS Broadbent Toowoomba, Vanfit Diesel	1906468	\$7,797.86
02/05/2020	1,139,000 kms	<b>A - Grease &amp; Brake Adj</b> S-4385 R/R - Bonnet mounts R/R - exhaust bushes , v band clamp and gasket c/o RHR slack adjuster R/R - 2 lower bonnet bar to chassis mount bushes Completed A Service	Vanfit Diesel		\$531.85
23/04/2020	1,000,000 kms 2 hrs	<b>Fuel Tank</b> R-3443 remove breather assembly fit new			
15/04/2020	1,129,933 kms	<b>B - Oils &amp; Filters</b> S-4249	TTS - Toowoomba Truck Spares		\$297.59
17/03/2020	1,120,904 kms	<b>A - Grease &amp; Brake Adj</b> S-3983	CHS Broadbent Toowoomba		\$270.00
24/02/2020	1,113,000 kms	<b>air leaks, Horton Fan</b> R-3099 Truck broken down in range Towed to Toowoomba yard Replace blown ppv under cab Full overhaul Horton fan Adjust clutch Re fit drive shaft from Tow	Vanfit Diesel		\$1,544.40
14/02/2020	1,110,000 kms	<b>B - Oils &amp; Filters</b> S-3706 Split and grease and check all couplings	TTS - Toowoomba Truck Spares		\$306.35
24/01/2020	1,106,000 kms	<b>air dryer rekit, cab mounts, Differential Oil and Filter Change, Diff reseal, Power Steering, Starter Motor, Suspension, turntable</b> R-2882 Replace diff oils and filter Re seal front diff replace top torsion rod bushes on drive Rekit airdryer Replace starter motor Replace cab mounts Replace power steering pump Fit re kitted turntable assembly	CHS Broadbent Toowoomba		\$7,328.71
17/01/2020	1,100,000 kms	<b>C - C Service</b> S-3401 Replace lh front wheel seal Replace mudflaps on bullbar	TTS - Toowoomba Truck Spares		\$1,808.97
07/01/2020	1,094,531 kms	<b>Engine Rebuild</b> R-2794 Completed Engine Rebuild	Superior Diesel Tech		\$25,437.08
06/01/2020	1,096,500 kms	<b>Batteries</b> R-2754 Replace x 4 batteries	CHS Broadbent Toowoomba		\$704.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
07/11/2019	1,087,000 kms	<b>B - Oils &amp; Filters</b> S-2853 Carry out B service Coolant leak on floor repair Airbag rear trailer LHM replace	TTS - Toowoomba Truck Spares		\$83.51
16/10/2019	1,075,807 kms	<b>A - Grease &amp; Brake Adj</b> S-2676	CHS Broadbent Toowoomba		\$985.34
16/10/2019	1,075,807 kms	<b>Air Conditioning, air leaks</b> R-2085 Remove and replace compressor, evaporator, tx valve, thermostat, receiver dryer Service system R134a - 1.5kg Rectify Air Leaks	CHS Broadbent Toowoomba		\$1,714.85
03/10/2019		<b>Registration</b> O-865			\$12,697.05
23/09/2019	1,065,000 kms	<b>B - Oils &amp; Filters</b> S-2456 Replaced Cab airbags,shocks and bump stops Replaced headlight inserts Repaired wiring to A/C	TTS - Toowoomba Truck Spares		\$1,244.15
27/08/2019	1,058,050 kms	<b>A - Grease &amp; Brake Adj</b> S-2273	CHS Broadbent Toowoomba		\$165.00
27/07/2019	1,046,791 kms	<b>Clutch</b> R-1514 Adjusted Clutch	CHS Broadbent Toowoomba		\$0.00
26/07/2019	1,046,791 kms	<b>B - Oils &amp; Filters</b> S-1996	CHS Broadbent Toowoomba, TTS - Toowoomba Truck Spares		\$272.19
05/07/2019	1,000,000 kms	<b>Dash cam</b> R-1939	Ashdown Ingram	7670723366	\$93.50
27/06/2019	1,035,000 kms	<b>A - Grease &amp; Brake Adj</b> S-1880 Completed A Service as per checklist			\$76.52
15/06/2019	1,031,931 kms	<b>dpf, Turbo</b> R-1423 Replace turbo and actuator Replace dpf filter and re calibrate system, complete burn off with computer	CHS Broadbent Toowoomba		\$7,772.86
30/05/2019		<b>Strip &amp; Fit, Wheel Balance</b> T-723	Tyrright Oakley	OKSI0042122	\$130.02
20/05/2019	1,025,000 kms	<b>Engine Tune Up</b> R-1356 Carry out engine tune	CHS Broadbent Toowoomba		
14/05/2019	1,025,000 kms	<b>B - Oils &amp; Filters</b> S-1696	TTS - Toowoomba Truck Spares		\$83.51
14/05/2019	1,025,000 kms	<b>New - Steer</b> T-602 fitted 2 B/S R249 Steer tyres	Bridgestone		\$1,650.00
29/04/2019	1,015,000 kms	<b>Brake Reline, Drive Wheel Bearing Replacement</b> R-1308 Rear drive bearing and brake overhaul	CHS Broadbent Toowoomba	481523	\$734.32
28/04/2019	1,015,000 kms	<b>A - Grease &amp; Brake Adj</b> S-1627 Carry out A service as per checklist	CHS Broadbent Toowoomba	1608875	\$1,918.51
26/03/2019	1,005,000 kms	<b>Fan Belts, Tensioner and Idlers</b> R-1207 R/R - Belt Tensioners, Idler bearings and fan belts	CHS Broadbent Toowoomba		
26/03/2019	1,005,000 kms	<b>Air Filter</b> R-1208 R/R - Air Filters	CHS Broadbent Toowoomba		

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
26/03/2019	1,005,000 kms	<b>Air Drier Filter Change</b> R-1209 R/R - Air Drier filter	CHS Broadbent Toowoomba		
26/03/2019	1,005,000 kms	<b>Power Steering Oil and filter change</b> R-1210 Changed oil and filter	CHS Broadbent Toowoomba		
26/03/2019	1,005,000 kms	<b>Steer Wheel Bearing Oil change</b> R-1211 Changed hub oil in steer wheels	CHS Broadbent Toowoomba		
26/03/2019	1,005,000 kms	<b>Coolant Filter Change</b> R-1212 R/R - Coolant Filter	CHS Broadbent Toowoomba		
26/03/2019	1,005,000 kms	<b>Crankcase Filter</b> R-1213 R/R - Crankcase filter	CHS Broadbent Toowoomba		
26/03/2019	1,005,000 kms	<b>B - Oils &amp; Filters</b> S-1507 Completed B Service as per checklist	CHS Broadbent Toowoomba	477647	\$1,310.25
26/03/2019	1,005,000 kms	<b>C - C Service</b> S-1508 Completed C Service as per checklist	CHS Broadbent Toowoomba		
16/03/2019	995,000 kms	<b>A - Grease &amp; Brake Adj</b> S-1468 Completed A Service as per checklist	CHS Broadbent Toowoomba		
16/03/2019	995,000 kms	<b>Electrical</b> R-1193 Replaced blown EGR pressure hoses perform a manual DPF regen clear all codes	CHS Broadbent Toowoomba		
06/03/2019	985,471 kms	<b>Coolant Top Up</b> R-1128 Top up coolant 15 litres	CHS Broadbent Toowoomba		
04/03/2019	987,367 kms	<b>New - Drives</b> T-465	Tyres 4U		\$3,668.50
26/02/2019		<b>New Drive Tyres</b> T-545	Tyres 4U	595874	\$3,366.00
26/02/2019		<b>Strip &amp; Fit</b> T-545	Tyrright Oakey	OKSI0039666	\$275.07
23/02/2019	985,000 kms	<b>Clutch</b> R-1098 Adjusted Clutch	CHS Broadbent Toowoomba		
23/02/2019	985,000 kms	<b>B - Oils &amp; Filters</b> S-1378 Completed B Service as per checklist	CHS Broadbent Toowoomba		
05/02/2019	975,000 kms	<b>A - Grease &amp; Brake Adj</b> S-1309 Completed A Service as per checklist	CHS Broadbent Toowoomba	471452	\$429.00
22/01/2019	964,301 kms	<b>Engine</b> R-988 R/R EGR cooler replaced sump gasket	CHS Broadbent Toowoomba	469801	\$2,931.66
22/01/2019	964,301 kms	<b>Scales</b> R-989 Fit scales to drive	CHS Broadbent Toowoomba		

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
22/01/2019	964,301 kms	<b>Drive Line</b> R-990 Fitted new centre bearing	CHS Broadbent Toowoomba		
22/01/2019	964,301 kms	<b>Engine</b> R-987 Fitted new rear main engine seal	CHS Broadbent Toowoomba		
22/01/2019	964,301 kms	<b>Clutch</b> R-986 Replaced clutch and fork kit machine fly wheel	CHS Broadbent Toowoomba		
22/01/2019	964,301 kms	<b>B - Oils &amp; Filters</b> S-1254 Completed B Service as per checklist	CHS Broadbent Toowoomba		\$6,263.93
<b>181 Records</b>				<b>Total:</b>	<b>\$245,835.82</b>