

MAINTENANCE MANAGEMENT RECORD			
BODY TYPE:		TRUCK	
MAKE:		MACK	
YEAR OF MANUFACTURE:		2016	
VEHICLE ID No. (VIN)		6FMN12H69GD807757	
ENGINE NUMBER:		MP8635530	
LICENSE NUMBER:		SB78ML	
CONFIGURATION CODE:		3 AXLE TRUCK + TRAILER COMB > 6 AXLES	
MASS:		9820	
LAST SERVICE:		27/03/24 (391,000km) SCOTT CHRISTENSEN	
NEXT SERVICE DUE:		27/09/2024 (401,000km)	
NHVAS LABEL NUMBER:		A050881 (22/02/2017 MASS/MAINTENANCE)	
DATE	COMPANY	DESCRIPTION	KM'S
29/05/2017	SOUTH CENTRAL TRUCKS	BASIC SERVICE - CHANGE ENGINE OIL & FILTERS, CARRY OUT ALL CHECKS & ADJUSTMENTS, CHECK ALL LEVELS & LIGHT OPERATIONS, DRAIN AIR SYSTEM OF CONTAMINATION, GREASE VEHICLE	
12/09/2017	SCOTT CHRISTENSEN	REMOVE AND REPLACE DAMAGED HYDRAULIC FITTING FOR TRAILER, REPLACED BROKEN BOLT IN BOTTOM RING FEEDER	
14/09/2017	SCOTT CHRISTENSEN	TRAILER - REMOVE AIR LINES AND HYDRAULIC LINES FROM DRAW BAR, REMOVE AND REPAIR DRAW BAR WELD IN TOW EYE	
16/12/2017	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHECK ALL LEVELS, CHANGE ALL FILTERS, CHECK LIGHTS AND BATTERIES. GREASE ALL POINTS, CHECK BRAKES AND STEERING JOINTS REPLACED 7X SUB FRAME BOLTS	53,374
10/03/2018	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK BRAKES, CHECK LIGHTS AND BATTERIES, GREASE ALL POINTS	64,536
21/05/2018	SOUTH CENTRAL TRUCKS	ANNUAL SERVICE, CHANGE ENGINE OIL AND FILTERS, MAKE ALL CHECKS AND ADJUSTMENTS, CHECK ALL LEVELS AND LIGHT OPERATIONS, DRAIN AIR SYSTEM OF CONTAMINATION, GREASE VEHICLE	75,000
15/06/2018	SOUTH CENTRAL TRUCKS	REPAIR RH TAIL LIGHT	
14/08/2018	TRUCK POWER AUTO ELECTRICAL	REPLACE FAULTY HEAVY DUTY TRAILER SOCKET AT REAR OF TRUCK	
8/09/2018	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHECK ALL LEVELS, CHANGE ALL FILTERS, GREASE ALL POINTS, CHECK LIGHTS AND BATTERIES	91,827
20/09/2018	SCOTT CHRISTENSEN	CHANGE RING FEEDER HANDLE	
9/11/2018	SOUTH CENTRAL TRUCKS	REPLACE CABIN AIR FILTER AND WIPER BLADES, CARRY OUT BASIC SERVICE	100,185
21/01/2019	TRUCK POWER AUTO ELECTRICAL	SUPPLY AND FIT WIRELESS REVERSE CAMERA KIT TO TRUCK AND TRAILER	

25/01/2019	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, GREASE ALL POINTS, CHECK BRAKS AND STEERING JOINTS	110552
29/04/2019	SOUTH CENTRAL TRUCKS	CARRY OUT ANNUAL SERVICE, CHANGE OIL AND DIFF OIL, CHANGED POWER STEERING OILS AND FILTERS, GREASE ALL POINTS, ADJUST BRAKES CHECK LIGHTS, WHEEL BEARINGS AND TENSION SUSPENSION COMPONENTS, CHECK ALL DRIVE BELTS, HOSES, MOUNTS, DRAIN AIR TANKS	12205
8/06/2019	SCOTT CHRISTENSEN	SERVICED TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS. CHECK BRAKES AND STEERING JOINTS, CHECK LIGHTS AND BATTERIES, GREASE ALL POINTS.	129,585
15/07/2019	SOUTH CENTRAL TRUCKS	FITTING WIND SCREEN	
24/07/2019	SOUTH CENTRAL TRUCKS	BRAKE LIGHTS STAYED ON OVER THE WEEKEND AND FLATTENED THE TRUCK BATTERY. BRAKE LIGHTS ARE OFF NOW. PUT VEHICLE INTO WORKSHOP. CONNECTED TECH TOOL AND SHEKED FOR FAULT CODES. NO FAULTS FOUND. STARTED VEHICLE AND BUILT UP AIR. CHECKED LIGHTS OKAY. DRAINED AIR AND CHEKED OLAY. CHECKED ELECTRICAL CONNECTIONS ON BOTH TRAILERS AND ELECTRICAL PLUG OLAY. REMOVED BRAKE PEDAL IN CABLE. CHECKED AND FOUND BRAKE PEDAL STOP AT REAR WAS DAMAGED. REMOVED AND REPLACED RUBBER. GGREASED POSTON FOR PEDAL AND REFIT ALL REMOVED. ROAD TESTED AND RECHEDKED ALL OLAY. PLEASE NOTE: FOUND REART DII HOUSING LEAKING OIL ***	
31/07/2019	TRUCK POWER AUTO ELECTRICAL	CHECK FAULT WITH INDICATOR CIRCUIT. FIND FAULTY FLASHER UNIT. REPLACE AND RE-TEST OK. REPLACE BROKEN TRAILER SOCKET AT REAR OF TRUCK FOR TRAILER LIGHTS CHECK	
5/08/2019	SCOTT CHRISTENSEN	TOPPED UP REAR DIFF OIL AND CHECKED FOR LOOSE BOLTS LEADING TO BAD OIL LEAK AT BOTTOM OF DIFF. DRAINED DIFF OIL, LOCKED UP DIFF LOCK FORK, REMOVED AXLES AND DRAINED OIL FROM HUBS. REMOVED JACK SHAFT AND X2 BRAKE BOOSTERS, REMOVED DIFF CENTRE AND CLEANED GASKET FROM BOTH MATING SURFACES. BUFFED BOLTS, RAN 5/8 UNC TAP THROUGH HOLES, APPLIED SEALANT TO MATING SURFACE ON DIFF HOUSING AND REFITTED DIFF CENTRE. TENSIONED BOLTS AND NUTS TO 180FT/LBS, REPLACED 1X LEAKING BRAKE BOOSTER AND FITTED BOTH BRAKE BOOSTERS. REFITTED JACK SHAFT AND TENSIONED BOLTS TO 130 FT/LBS, RE FITTED AXLES AND TENSIONED TO 175 FT/LBS. FILLED DIFF CENTRE WITH 85W/140 GEAR OIL.	137,451

7/08/2019	TRUCK POWER AUTO ELECTICS	1X H7 DIRECT FIT LED GLOBE KIT. 2X LED WEDGE GLOBE KIT T10 5W. 1X 12V CONT DUTY SOLENOID. 1X 12V 2 PIN FLASHER CAN. SUNDRIES	
10/10/2019	TRUELINE TRUCK REPAIR CENTRE	SET CASTOR AND FIT WEDGE TO FRONT LEFT AXLE. SET TOE ON STEER AXLE. STRAIGHTEN STEERING WHEEL. ROTATE FRONT WHEELS FROM LEFT TO RIGHT	146408
24/10/2019	SOUTH CENTRAL TRUCKS	X2 COVER	
16/11/2019	SOUTH CENTRAL TRUCKS	X1 FILTER CARTRIDGE	
16/11/2019	SCOTT CHRISTENSEN	DRAINED AND RE FILLED ENGINE OIL. CHANGED ALL FILTERS. CHECKED ALL LEVELS. CHECKED LIGHTS AND BATTERIES. CHECKED ALL BRAKES. GREASED ALL POINTS	152,548
19/11/2019	SOUTH CENTRAL TRUCKS	X1 MICROPHONE	
2/12/2019	SOUTH CENTRAL TRUCKS	PARTS: HARNESS, LEFT DOOR X1	
3/12/2019	TRUCK POWER AUTO ELECTRICAL	2.5HR LABOUR. 2 PIN DEUTSCH KIT X1. LED P21W BA15S GLOBE - 2 PACK X2. SUNDRIES X2. REMOVE AND REPLACE FAULTY DRIVERS DOOR WIRING LOOM FOR ELECTRIC WINDOWS. RE-CHECK OPERATIONS. SUPPLY GLOBES FOR REAR TAIL LIGHTS	
7/01/2020	MAXITRANS	DIAGNOSE AND REPAIR RAZOR *OPERATION FAULT - BATTERY FOUND TO BE FAULTY	
10/01/2020	TRUCK POWER AUTO ELECTRICS	REMOVE AND REPLACE FAULTY LED MINI BEACON FROM ROOFTOP ASSEMBLY. TEST OK. REMOVE AND REPLACE GLOBES IN TRUCK TAIL LIGHTS WITH LE'S. TEST OK.	
17/01/2020	ADELAIDE INDEPENDENT BANDAG	ROTATE TYRES - DRIVE POSITION, CRISS CROSS	160,235
23/01/2020	MAXITRANS	DIAGNOSE RAZOR FAULT. FOUND CHARGER TO BE FAULTY. REPLACED AND TESTED.	
28/01/2020	SOUTH CENTRAL TRUCKS	X1 FILTER KIT	
31/01/2020	SOUTH CENTRAL TRUCKS	X1 EXPANSION TANK	
31/01/2020	SCOTT CHRISTENSEN	service truck. Drain and refill engine oil. Check all levels. Change all filters. Checked brakes. Checked lights and batteries. Greased all points. Removed and replaced coolant header tank. Fitted new drain cable on purge tank. Fitted missing bolt to air cleaner.	162,645

7/02/2020	SOUTH CENTRAL TRUCKS	CHECK AND RECTIFY DRIVER WINDOW INOP. DRIVERS SIDE WINDOW NOT GOING UP OR DOWN. OPERATOR HAS SWITCHED OVER THE CIRCUIT BREAKERS AND THE WIRING HARNESSES REPLACED BUT HAS MADE NO DIFFERENCE. PUT VEHICLE INTO WORKSHOP. CHECKED AND FOUND SAID WINDOW INOP. SWAPPED SWITCHES AND RECHECKED OPERATION, NO CHANGE. REMOVED DOOR CARD AND CHECKED POWER AT THE REGULATOR, OKAY. REMOVED AND RELACED REGULATOR. REFIT DOOR CARD AND RECHECKED WINDOW OPERATION, ALL OKAY.	163,480
6/03/2020	cmv	x1 premium wash 22Lts	
25/03/2020	MAXITRANS	trailer arrived with lileaking tailgate ram. Found broken air fitting but could not remove. Replaced tailgate ram an tetested - ok.	170,105
25/03/2020	ADELAIDE INDEPENDENT BANDAG	lh steer position : strip and fit own partworn 11r22.5 tyre x1. balance powder/beads x1	
8/04/2020	SOUTH CENTRAL TRUCKS	Carry out basic service. Change engine oil and filters. Take oil samples if required. Carry out all checks and adjustments. Check all levels and light operations. Drain air system of contamination. Grease vehicle. Check over and ready for delivery. Clean work area. **faults found during service*** Exhaust flex pipe clamps leaking. front diff seal leaking. PTO weeping. back reflectors worn out. radius rod for front axle lhs has play. - Carry out Valve Set - Remove rocker cover and air trunking. carry out valve and injector adjustment as per Mack specifications. clean head surface and rocker cover. refit cover and trunking. checked over for leak after vehicle washed and road tested. all ok.	172,250
18/05/2020	SOUTH CENTRAL TRUCKS	connect ech tool and check clutch faults. Diagnose fault. Put vehicle into workshop. Connected tech tool and checked fault codes. Found active system clutch system fault. Carried out pwm valve test. Found valve was leaking. Removed pwm valve and put compressed air into clutch cylinder and tested for leaks. no leaks coming from clutch cylinder. removed and replaced pwm valve. carried out pwm valve leak test again and all ok. carried out clutch cylinder test ok. carried out clutch wear test and found clutch has 2mm of life left. customer has been notified. checked over after road test ok. check wants to take off in 5th gear fully loaded intermittently. wont select back to 2nd gear unless you do it manually. using tech tool checked parameters. found truck highest start gear in auto and mannual 6th gear. changed parameter to 2nd gear. checked function. all ok. check truck only doing 96km/h as per gps. speedo says its doing 100. carried out k factor test in yard. found programmed spec lower then calculated spec. changed k factor. road tested vehicle and checked speed. all ok.	177,901

5/06/2020	ADELAIDE INDEPENDENT BANDAG	LH front outer drive : puncture repair - 11r22.5 x1. rad110 tl patch x1. remove and replace wheels x1.	181,148
12/06/2020	ADELAIDE INDEPENDENT BANDAG	Supply and fit to drive positions : 11r22.5 bdr-ht bandag (stk) x8. 11r22.5 stock casing x8. 170mm valve extention x2.	182,017
12/06/2020	SOUTH CENTRAL TRUCKS	Parts - switch x1.	
17/06/2020	SOUTH CENTRAL TRUCKS	Parts - filter kit x1.	
19/06/2020	SCOTT CHRISTENSEN	Service truck. Drain and refill engine oil. Check all levels. Change all filters. Checked all lights and batteies. Greased all points. Removed and replaced rear brake shoes and drums	183,557
23/06/2020	SOUTH CENTRAL TRUCKS	Parts - filter cartridge x1. valve x1.	
14/08/2020	HAULMARK TRAILERS	INVESTIGATE VEHICLE NOT STARTING - STARTER MOTOR RELAY REPLACED - BATTERY ISOLATOR SWITCH CORRODED - WE WILL REPLACE BATTERY ISOLATOR SWITCH	190819
23/09/2020	SOUTH CENTRAL TRUCKS	CARRY OUT BASIC SERVICE, CHECK EXHAUST MANIFOLD FOR ANY OTHER EXHAUST LEAKS , CHECK AND RECTIFY FRONT DIFF SEAL LEAKING, CHECK AND RECTIFY WIRE COMING OUT OF DRIVE BELT, REPLACE CABIN AIR FILTER, RECTIFY RHS 7 INCH MIRROR BROKEN, RECITFY FAULTY REAR RH SLACK ADJUSTER FAULTY, RECTIFY EXHAUST FLEX PIPE CLAMP LEAKING	196423
14/08/2020	SOUTH CENTRAL TRUCKS	STARTER MOTOR	
2/10/2020	MAXITRANS	RAZOR MOUNTING BROKEN	
22/10/2020	TRUCK POWER ELECTRICS	LABOUR: REMOVE & REPLACE BROKEN HEAVY DUTY TRAILER SOCKET, TEST TRAILER LIGHTING	
28/01/2021	SCOTT CHRISTENSEN	Repaired leaking hub seal on RHR drive hub. Removed wheels, brake drum amd shoes, cleaned brake drum, axle, hub and tyre. Removed oil from brake backing plate. Fitted new brake shoes, fitted wheel bearings and seal to hub, fitted hub. Tensioned wheel bearings, fitted axle and brake drum, tensioned axle nuts. Fitted wheel and tensioned nut to 500ft pounds. Checked diff oil, strapped up loose wiring for diff sender	216,272
12/02/2021	SCOTT CHRISTENSEN	MECHAINCS REPORT-DRAINED & REFILLED ENGINE OIL- CHANGED ALL FILTERS-CHECKED ALL LEVELS-CHECKED LIGHTS & BATTERIES-CHECKED & AJUSTED BRAKES- GREASED ALL GREASE NIPPLES	219,630
17/04/2021	SCOTT CHRISTENSEN	SERVICED TRUCK, DRAINED AND REFILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED LIGHTSAND BATTERIES, GREASED ALL POINTS	229858
7/05/2021	ADELAIDE INDEPENDENT BANDAG	REPAIR PUNCTURE	232932

17/05/2021	SOUTH CENTRAL TRUCK & BUS	CHECK DRIVERS WINDOW STUCK DOWN	233,561
21/05/2021	TRUCK POWER AUTO ELECTRICS	LABOUR :REPLACE BROKEN UHF ANTENNA ON MIRROR MOUNT FIT NEW ELEVATED SPRING BASE ANTENNA & WHIP REPAIR BROKEN WIRING TO DRIVERS SIDE LOAD LIGHT. TEST OK	
15/06/2021	SCOTT CHRISTENSEN	DRAINED AND REFILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED LIGHTS AND BATTERIES, CHECKED AND ADJUSTED BRAKES GREASED ALL NIPPLES	239749
5/07/2021	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT 1 X 11R22.45 TYRE - RH REAR OUTER	
26/08/2021	TRUCKPOWER	REPLACED FAULTY LED STROBE LIGHT, REPLACED FAULTY LED SIDE MARKER LIGHT - REAR PASSANGER SIDE.	N/A
22/09/2021	TRUCKPOWER	REMOVE AND REPLACE FAULTY RADIO, INSTALL NEW BLUETOOTH EXTERNAL MICROPHONE, SUPPLY NEW CABIN FILTER	N/A
14/10/2021	SOUTH CENTRAL TRUCKS	REFER TO HYPERLINK FOR DETAILS	260,369
8/12/2021	SOUTH CENTRAL TRUCKS	ANNUAL BIG SERVICE - REFER TO HYPERLINK FOR DETAILS	267,602
9/12/2021	MAXITRANS	REFER TO HYPERLINK FOR DETAILS	N/A
23/03/2022	ADELAIDE INDEPENDENT BANDAG	PUNCTURE REPAIR RH FRONT OUTER	N/A
28/03/2022	SCOTT CHRISTENSEN	DRAINED AND RE-FILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED LIGHT AND BATTERIES, CHECKED AND ADJUSTED BRAKES. GREASED ALL GREASE NIPPLES, REPLACED HYDRAULIC COUPLING O RINGS. STEERING BOX AND FRONT SPRINGS NEED TO BE REPLACED	282534
3/05/2022	SOUTH CENTRAL TRUCK & BUS	AIR LEAK UNDER EXHAUST BRAKE OPERATION NOT WASTE GATE. DOUT TEST CONDUCTED. FOUND BAD LEAK AT PIPE CLAMP ON EPG FLAP HOUSING DUE TO LOOSE CLAMP. REMOVED CLAMP AND CLEANED SURFACES. FITTED NEW CLAMP AND CARRIED OUT TEST AGAIN. CHECKED AND FOUND OK. CLEARED FAULT CODES. NO ROAD TEST DONE.	287,684
4/05/2022	ADELAIDE INDEPENDENT	SUPPLY AND FIT ALL TYRES	288347
25/05/2022	SOUTH CENTRAL TRUCKS	CHECK HYPER LINK FOR DETAILS	289919
10/06/2022	SCOTT CHRISTENSEN	CHECK HYPER LINK FOR DETAILS	292,674
21/07/2022	ADELAIDE INDEPENDENT	SUPPLY AND FIT LH REAR OUTER	299618
25/07/2022	TRUCK POWER AUTO	REMOVE AND REPLACE REAR TAIL LIGHT ASSY	N/A
3/08/2022	SCOTT CHRISTENSEN	REMOVED AND REPLACED REAR AXLE BRAKES AND BRAKE DRUMS, FITTED NEW BRAKE SHOES, FITTED WHEELS, TORQUED WHEEL NUTS AND ADJUSTED BRAKES	

19/08/2022	SCOTT CHRISTENSEN	DRAINED AND REFILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED ALL LIGHTS AND BATTERIES, CHECKED AND ADJUSTED BRAKES, GREASED ALL NIPPLES	302,650
21/09/2022	TRUCK POWER ELECT	REPAIRED BATTERY SWITCH & TERMINAL EXTENTION STUD 3/8 STUD UNF .	N/A
		MOUNT NEW ISOLATER AND WIRE UP USING EXTENTION STUD . TEST OK	
		REPAIR WIRING TO DRIVERS SIDE MIRROR MOUNTED LOAD LIGHT . TEST OK.	
7/10/2022	SOUTH CENTRAL & T	SEE HYPERLINK	308486
13/10/2022	ADELAIDE INDEPEND	SUPPLY AND FIR ON TRUCK SB78ML 2 WHEELS, BALANCE OF WHEELS, CASING FOR RETREADING AND PUNCTURE REPAIR	308713
13/10/2022	ADELAIDE INDEPEND	WHEEL BALANCE SUPPLIED/FITTED 2 NEW TYRES PUNCTURE REPAIR	308713
11/10/2022	SOUTH CENTRAL TRU	CHECK HYPERLONK FOR DEATSILS	308,516
25/11/2022	SCOTT CHRISTENSEN	CHANGED OIL, CHANGED ALL FILTERSCHECKED ALL LEVELS CHECKED AND ADJUSTED BRAKES.	317,110
		REMOVED AND REPLACED TAIL AGTE PILOT VALVE	
19/01/2023	ADELAIDE INDEPEND	SUPPLY AND FIT DRIVE TYRES WITH 11R22.5 BDR-HT BANDAG. SUPPLY AND FIT LH FRONT WITH 11R22.5	375385
17/02/2023	ADELAIDE INDEPEND	SUPPLY AND FIT RH FRONT INNER	333426
27/02/2023	SCOTT CHRISTENSEN	REPAIRS ON TRUCK SB78ML: CHANGED OIL, FILTERS, CHECKED LIGHTS, ADJUSTED BRAKES, GREASED WHERE NEEDED, REPAIRED AND REFIT HYDRALUIC FUEL TANK. REPLAVED BRAKE BOOSTER LH. REPLACED HOSES, REPLACED BRAKES, LH STEER AXLE ADJUSTERS, REPLACED ALL 4 AIR BAGS, REPLACED 3 GLOBES, TOPPED UP DIFF OIL	333,444
19/04/2023	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES	343,598
30/05/2023	SOUTH CENTRAL TRU	RECTIFY TRUCK DERATING, FOUND AIRLEAK IN WASTEGATE, REPLACED VALVES AND PIPE KIT AND 1X BOOST ORING	349,866
6/06/2023	TRUCK POWER AUTO	LED BEACON STROBE - SHORT, SUNDRIES	N/A
19/06/2023	ADELAIDE INDEPEND	DRIVE ROTATION	354,396
21/06/2023	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS. CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES. CHECK AND ADJUST BRAKES, GREASE ALL NIPPLES	354,634
14/07/2023	ADELAIDE INDEPEND	SUPPLY AND FIT X 2 STEER TYRES, WHEEL BALANCE X 2	358439
24/08/2023	COMPLETE ALIGNME	replace pivot and centre bushes on first drive oxy cut to removed seized eccentrics	362, 405
7/08/2023	SCOTT CHRISTENSEN	SEE HYPERLINK	362,388
7/09/2023	ADELAIDE INDEPEND	SUPPLY AND FIT X8 TYRES TO DRIVES, WHEEL BALANCE X2 STEERS	364114

13/09/2023	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL NIPPLES, REPLACE 1X ROOF LIGHT GLOBE, ADJUST 2X AUTO ADJUSTER AT REAR OF TRUCK	365137
7/11/2023	AERIAL TARPS	REMOVE AND REPLACE 2X SIDE CABLES TO TRUCK AND REMOVE AND REPLACE 1X SIDE CABLE AND ADJUST 2X BOWS TO TRAILER	
18/12/2023	SCOTT CHRISTENSEN	REPLACED LH REAR WHEEL SEAL AND BRAKES, REMOVE AND REPLACE 4X SLACK ADJUSTERS, REMOVED HYDRAULIC HOSE FROM TRUCK TO TRAILER, GOT NEW HOSE MADE, FIT NEW HOSE, FIXED AIR LEAK ON TRAILER, REPLACED ALL FOUR REAR AXLE BRAKE ADJUSTERS FROM AUTO TO MANUAL, TENSIONED 30 WHEEL NUTS TO 500FT/LBS	381264
12/01/2024	SOUTH CENTRAL TRU	SEE HYPERLINK	
26/01/2024	TRUCK POWER AUTO	CHECK FAULT WITH CHECK ENGINE LIGHT STAYING ON, CODES RELATED TO NOX SENSORS FAULT, DEALER PREVIOUSLY REPLACED EXHAUST BACK PRESSURE SENSOR, BUT NOT OUTLET NOX SENSOR, ADVISE REPLACEMENT OF NOX SENSOR AND CLEARING OF CODES	
17/01/2024	SCOTT CHRISTENSEN	REMOVE ALTERNATOR TENSIONER, REMOVE RH CAB SHOCKER, REMOVE GUARDS, REMOVE EXHAUST FLEX HOSES, REMOVE AND REPLACE ROOF LIGHT GLOBES, TIGHTENED TURBO ACTUATOR HOSE CLAMPS, REPLACE ALTERNATOR TENSIONER, REPLACERH CAB SHOCKER, REPLACE EXHAUST FLEX HOSES, REPLACE SEIZED BOLT, REMOVE FUEL TANK STEPS AND LOOSENED TANK STRAP TO REMOVE AND REPLACE WARPED STRAP RUBBER, PUT STEPS BACK ON AND TIGHTENED TANK STRAP	
15/03/2024	ADELAIDE INDEPEND	SUPPLY AND FIT TO STEERS X 2, WHEEL BALANCE X2, BALANCE WEIGHTS X 2, SUPPLY AND FIT TO REAR AXLE 4X DOWN CASING	391037
27/03/2024	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES, REMOVE BROKEN EXHAUST PIPES, FIT EXHAUST, FIX AIR LEAK	391,000
4/04/2024	SCOTT CHRISTENSEN	SEE HYPERLINK	
1/05/2024	TRUCK POWER AUTO	CHECK FAULT WITH RADIO BLUETOOTH NOT CONNECTING, RESET PHONE CONFIGURATION, RECONNECT PHONE TO DEVICE	
24/05/2024	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES, TIGHTENED BATTERY TERMINAL, NOTICE RH FRONT AXLE AUTO ADJUSTER IS NOT WORKING	

6/06/2024	MAXITRANS	REPLACE MUDFLAPS & TENSION RAZR, UNIT RETURNED WITH RAZOR FAULT, SUSPECT BATTERY CHECKED OVER AND FOUND RAZOR CONTROLLER FAULTY BATTERY AND CHARGING SYSTEM TESTED OK, REPLACE AND WIRE UP CONTROLLER CHECK OPERATION ALL OK	
4/07/2024	ADELAIDE INDEPENDENT	SUPPLY AND FIT TO LH FRONT X2 BANDAG CUSTOMERS OWN CASINGS	408971
19/07/2024	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES, REPLACED 2X ROOF LIGHT GLOBES, REPLACED RH FRONT PARKER GLOBE, ADJUSTED RH FRONT AUTO ADJUSTER DUE TO NOT WORKING	412756
5/09/2024	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES	424205
23/09/2024	ADELAIDE INDEPENDENT	SUPPLY AND FIT TO RH FRONT 2X BANDAG	429324
5/10/2024	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES	438976
23/10/2024	SCOTT CHRISTENSEN	PICK UP SLACK ADJUSTER FROM MACK TRUCKS, REMOVE AND REPLACE RH FRONT SLACK ADJUSTER, ADJUST BRAKES	
25/10/2024	SCOTT CHRISTENSEN	DRIVE OUT AND PICK UP AIR DRYER FROM MACK TRUCKS, REMOVED AND REPLACED AIR DRYER	
5/11/2024	MAXITRANS	REPLACE TARP CABLES BOTH SIDES & PULLEY	
29/11/2024	TRUCK POWER AUTOC	REMOVE AND REPLACE STEERING WHEEL HORN CONTACT, REMOVE AND REPLACE FAULTY INDICATOR SWITCH ASSEMBLY, PARTS SUPPLIED BY AK	
25/11/2024	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES, REMOVED OLD TAIL GATE RAM, INSTALLED NEW RAM	449676
18/12/2024	KEITH MUNCHENBERG	REPLACE 3X BATTERIES & 6X TERMINALS	
24/12/2024	ADELAIDE INDEPENDENT	SUPPLY AND FIT REAR AXLE 4X BANDAG OWN CASINGS	
11/02/2025	ADELAIDE INDEPENDENT	STEERS AND DRIVE OUTERS, RE-TENSION WHEEL NUTS/WHEEL, 2ND TRAILER DRIVE OUTERS, RE-TENSION WHEEL NUTS / WHEELS	
14/02/2025	TRUCK POWER AUTOC	SUPPLY AND FIT NEW AM/FM ANTENNA AND LEAD TO DRIVERS DOOR MIRROR BRACKET	
14/02/2025	SCOTT CHRISTENSEN	TRUCK SERVICE, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES, REMOVED AND REPLACED RINGFEEDER, REMOVED AND REPLACED AIR DRYER FILTER, REMOVED AND REPLACED AIR CLEANER, REPLACED HYDRAULIC FITTINGS	
20/02/2025	LANGTREE MACHINE	SEE HYPERLINK	460,058
9/04/2025	TRUCK POWER AUTOC	CHECK AND FIND FAULTY UHF RADIO, SOURCE REPLACEMENT UNIT AND FIT	475,959

23/04/2025	TRUCK POWER AUTO	SUPPLY AND FIT REVERSE CAMERA KIT TO TRUCK, SUPPLY AND FIT ADDITIONAL CAMERA CABLE AND TRAILER SUZI COIL KIT, SUPPLY AND FIT ADDITIONAL CAMERA AND CABLE TO DOG TRAILER	
6/05/2025	SCOTT CHRISTENSEN	TRUCK SERVICE, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES, REPLACED SUPPLIED BONNET LATCH, REPLACED WATER TANK TAP, UNBLOCKED FRONT DRIVE AXLE DIFF BREATHER, FITTED SUPPLIED AIR LINE FITTING TO DIESEL TANK BREATHER	478,532
8/05/2025	ADELAIDE INDEPEND	SUPPLY AND FIT TO LH FRONT 2X BANDAG, OWN CASINGS	
22/05/2025	SCOTT CHRISTENSEN	REPLACED BROKEN FRONT GUARD STRAP ON LH FRONT STEER AXLE FIXED STRAP AND BRACKETS HOLDING MUDFLAP	
1/06/2025	CMC FABRICATION &	FIT AND WELD ALUMINIUM SHEETS IN BACK OF TIPPER TRAILERS PLUS PARTS	
11/06/2025	ADELAIDE INDEPEND	service callx1 RH rear inner puncture repx1 radial patch x1 remove replace wheel x1	
16/06/2025	SCOTT CHRISTENSEN	SEE HYPERLINK	489,949
FITTING OF ALUMINIMUM FLOOR PLATES AND WELDING			
24/06/2025	FABRICATION & WEL	ON TIRPPER TRAILERS	
30/06/2025	SCOTT CHRISTENSEN	REMOVED REPLACE LH REAR DRIVE AXLE BOOSTER	493,916
14/07/2025	ADELAIDE INDEPEND	SERVICE CALL SUPPLY FIT POSITON: STEERS 295/80R22.5 112R YOKOHAMA BALANCE POWDER/BEADS EPA SCRAP TYRE DISPOSAL -295/80R22.5	
22/07/2025	SCOTT CHRISTENSEN	TRUCK SERVICE DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES, REMOVE AND REPLACE EXHAUST FLEX	501,936
18/08/2025	ADELAIDE INDEPEND	SUPPLY & FIT LH REAR DRIVE 2XBANDAG, 2X STOCK CASING, TO LH MIDDLE OUTER, STRIP & FIT RUN OUT TYRE X1, UNBOLD & BOLT ON TYRE X1, SCRAP TYRE DISPOSAL X 2	506509
28.08.2025	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES, REMOVE AND REPLACED BOTH SIDE DOOR SEALS	512212
04.09.2025	SCOTT CHRISTENSEN	MECHANICS REPORT, REPLACED NUMBER PLATE AT REAR OF TRUCK. ADJUST DRIVERS DOOR AND PASSENGERS DOOR HINGE	513472
23.10.2025	SCOTT CHRISTENSEN	TRUCK SERVIE, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES. REPLACED ROOF LIGHT GLOBE, FERIT REPAIRED SUN VISOR BRACKET TO ROOF	

31.10.2025	ADELAIDE INDEPEND	SUPPLY FIT DRIVES, 11R22.5 B729 BANDAG OWN CASINGS, CASINGS FOR RETREADING, STRIP AND FIT OWN 11R22.5 PARTWORN, REMOVE AND RPLACE WHEELS/TYRES, FITTED FROM REMOVED TYRES FROM SB 78ML	527228
28/11/2025	SCOTT CHRISTENSEN	MECHANICS REPORT. TRUCK SERVICE. DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHAECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES. REMOVED AND FITTED NEW TARP CABLE TO LH SIDE, WELDED ON STOPPERS TO STOP CABLE BRACKETS BENDING	536966
12/01/2026	SCOTT CHRISTENSEN	TRUCK SERVICE, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES	548947
28/01/2026	TRUCK POWER	LABOUR, JBS 130LED AMBER LED STROBE BEACON, 105100-00 AMBER LENS T/S AEROLITE BARS, SUNDRIES	552958
25/02/2026	SCOTT CHRISTENSEN	MECHANICS REPORT, TRUCK SERVICE, DRAIN & REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES. REPLACED 2 X AIR LINE FITTINGS UNDER RADIATOR DUE TO LEAKING AIR WHEN BRAKES WERE APPLIED, REPLACED GLOBE L/H BONNET INDICATOR, REPLACED L/H REAT TAIL LIGHT DUE TO CONTACT BAR INSIDE LIGHT BRAKING, REPLACE 1 X ROOF LIGHT GLOBES, CHANGED BROKEN P LIP ON HYDRAULIC TANK HOSE	561656
12/03/2026	TRUCK POWER	DIAGNOSTIC CHECK - CHECK ENG/WARNING LIGHTS. CLEAR ALL INACTIVE CODES/ CHECK WABCO ABS AND CLEAR/RECHECK WARNING SYSTEMS - ROAD TEST VEHICLE. OK	
29/04/2026	SCOTT CHRISTENSEN	SERVICE+ NHVR CHECKLIST -SEE HYPERLINK	572,785
14/05/2026	SCOTT CHRISTENSEN	DIFF ASSEMBLY	574,281
1/06/2026	CMV TRUCK & TRAIL	BEARING KIT	
2/06/2026	CMV TRUCK & TRAIL	TRANSMAX AXEL	
28/07/2026	SCOTT CHRISITENSEN	TRUCK SERVICE-SEE LINK	585,467
30/07/2026	SOUTH CENTRAL TRU	GASKET - SEE LINK	