

278 - CAT 637E Scraper:278E

Date	Name	Duration	Notes
28/03/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Clean water from cylinders, repair injectors, repalce wiring harness./Refit rear engine & test run.
29/03/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Clean water from cylinders, repair injectors, repalce wiring harness./Refit rear engine & test run.
31/03/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove radiator, repalce hyd. hoses./Remeove turbo & exhaust pipes, look up & order parts, assemble
04/04/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	Remove radiator, repalce hyd. hoses./Remeove turbo & exhaust pipes, look up & order parts, assemble
05/04/2011	Wilde, David - TWC WORKSHOP MANAGER	9.00	Remove radiator, repalce hyd. hoses./Remeove turbo & exhaust pipes, look up & order parts, assemble
07/04/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit bonnets & guards, replace rear flow switch, replace rear engine panel and repair wiring.
08/04/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	R&R rear eng harness and clamps, repair AC
09/04/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	Refit bonnets & guards, replace rear flow switch, replace rear engine panel and repair wiring.
12/04/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	Check start relay and remove, R&R cutting edges/tynes, replace start solinoid
13/04/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Check start relay and remove, R&R cutting edges/tynes, replace start solinoid
14/04/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Fit belly guards, charge batteries, check lights
15/04/2011	Knapman, Kenneth - TWC MECHANIC	2.00	Fabricate UHF mounts
15/04/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	Fit belly guards, charge batteries, check lights
16/04/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Fit belly guards, charge batteries, check lights
20/04/2011	Knapman, Kenneth - TWC MECHANIC	6.00	Fabricate UHF mounts
20/04/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Fit belly guards, charge batteries, check lights
21/04/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	Check oil levels & fit adaptors.
21/04/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Fabricate laser frames
27/04/2011	Knapman, Kenneth - TWC MECHANIC	6.00	Fabricate laser frames
28/04/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Manufacture hungry boards
02/05/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Manufacture hungry boards
03/05/2011	Knapman, Kenneth - TWC MECHANIC	3.00	Manufacture hungry boards
04/05/2011	Knapman, Kenneth - TWC MECHANIC	2.50	Manufacture hungry boards
05/05/2011	Wilde, David - TWC WORKSHOP MANAGER	4.25	30581hrs: Chk & repair rear trans. electrical fault. R & R 2 hoses.
12/05/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Load hungry boards for painting
22/05/2011	Bell, Daniel - TWC Manager	0.25	FGR
04/06/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	31,770hrs: travel to/from jobsite, replace seals & broken bolts./R & R hyd. hose
08/06/2011	Knapman, Kenneth - TWC MECHANIC	3.50	Service machine
08/06/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	31,770hrs: travel to/from jobsite, replace seals & broken bolts./R & R hyd. hose
09/06/2011	Knapman, Kenneth - TWC MECHANIC	2.00	Weld & fit bonnet locks./R & R throttle pedal, make up guard, fir front laser cable, chk for air le
09/06/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Repairs to bonnets, adjust radiator mounts, chk oil leaks & order parts, fit laser cable./Remove pu
10/06/2011	Knapman, Kenneth - TWC MECHANIC	7.50	Weld & fit bonnet locks./R & R throttle pedal, make up guard, fir front laser cable, chk for air le
14/06/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	Repairs to bonnets, adjust radiator mounts, chk oil leaks & order parts, fit laser cable./Remove pu
14/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Weld & fit bonnet locks./R & R throttle pedal, make up guard, fir front laser cable, chk for air le
15/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Weld & fit bonnet locks./R & R throttle pedal, make up guard, fir front laser cable, chk for air le
15/06/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Repairs to bonnets, adjust radiator mounts, chk oil leaks & order parts, fit laser cable./Remove pu
16/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Repairs/maintenance - Gouge off push pad lugs & ball, bearing mount, weld in new parts + hungry bo
16/06/2011	Wilde, David - TWC WORKSHOP MANAGER	8.50	Refit steering lines & clamps, pressure test trans, refit 2 front brake boosters, chk & repair air
17/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Repairs/maintenance - Gouge off push pad lugs & ball, bearing mount, weld in new parts + hungry bo
17/06/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Refit steering lines & clamps, pressure test trans, refit 2 front brake boosters, chk & repair air
18/06/2011	Wilde, David - TWC WORKSHOP MANAGER	6.00	Refit steering lines & clamps, pressure test trans, refit 2 front brake boosters, chk & repair air
20/06/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Refit steering lines & clamps, pressure test trans, refit 2 front brake boosters, chk & repair air
21/06/2011	Knapman, Kenneth - TWC MECHANIC	1.50	Repairs/maintenance - Gouge off push pad lugs & ball, bearing mount, weld in new parts + hungry bo
21/06/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit steering lines & clamps, pressure test trans, refit 2 front brake boosters, chk & repair air
05/07/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R blown hose.
05/07/2011	Bell, Daniel - TWC Manager	2.00	Replace blown hydraulic hose.
08/07/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Westrac - hyd. hose repair
12/07/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	30,992hrs; Chk & tighten rear injector lines/32,000hrs; service
13/07/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	30,992hrs; Chk & tighten rear injector lines/32,000hrs; service
14/07/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Collect parts
14/07/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R hyd. hose & flashing light bulb. Chk for air leaks.
19/07/2011	Bell, Daniel - TWC Manager	3.50	Replace hydraulic hose.

Date	Name	Duration	Notes
26/07/2011	Bell, Daniel - TWC Manager	2.00	Weld rear radiator guard, reapeace foot/hand throttle.
26/07/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	31061hrs: Replace nut & adjust rear belts, replace throttle hand control, repair air leaks.
04/08/2011	Bell, Daniel - TWC Manager	1.00	Check noise in engine.
09/08/2011	Knapman, Kenneth - TWC MECHANIC	2.50	Unload & inspect, remove belly guards & sump & inspect./Assist remove radiator
09/08/2011	Bell, Daniel - TWC Manager	1.00	Troubleshoot noise in engine.
09/08/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	Unload machine from float, part wash down, chk engine noise, remove injector, test & refit./Remove
10/08/2011	Bell, Daniel - TWC Manager	2.00	Check noise in engine.
10/08/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Unload machine from float, part wash down, chk engine noise, remove injector, test & refit./Remove
10/08/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Unload & inspect, remove belly guards & sump & inspect./Assist remove radiator
11/08/2011	Bell, Daniel - TWC Manager	3.00	Remove & strip engine for repair.
12/08/2011	Bell, Daniel - TWC Manager	9.50	Remove & strip engine for repair.
12/08/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Dismantle engine & inspect parts.
13/08/2011	Bell, Daniel - TWC Manager	4.50	Remove & strip engine for repair.
15/08/2011	Knapman, Kenneth - TWC MECHANIC	1.50	Strap engine blocks to pallets & arrange transport to Brisbane.
31/08/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove mudguards for repair
07/09/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	R & R rods in steering rams.
08/09/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Fit steering cylinder seals
12/09/2011	Bell, Daniel - TWC Manager	1.00	Remove & reseal hitch cylinder
12/09/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	Repair hitch ram/assemble & refit to machine.
13/09/2011	Bell, Daniel - TWC Manager	3.50	Remove & reseal hitch cylinder
13/09/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repair hitch ram/assemble & refit to machine.
14/09/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Repair hitch ram/assemble & refit to machine.
14/09/2011	Bell, Daniel - TWC Manager	9.50	Remove & reseal hitch cylinder
15/09/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R grease line fittings./Clean parts & assemble engine
15/09/2011	Bell, Daniel - TWC Manager	9.50	Assemble engine
16/09/2011	Bell, Daniel - TWC Manager	9.50	Assemble engine
17/09/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	R & R grease line fittings./Clean parts & assemble engine
17/09/2011	Bell, Daniel - TWC Manager	9.50	Assemble engine
19/09/2011	Bell, Daniel - TWC Manager	7.50	Assemble engine
19/09/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	R & R grease line fittings./Clean parts & assemble engine
20/09/2011	Bell, Daniel - TWC Manager	8.50	Assemble engine
20/09/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	R & R grease line fittings./Clean parts & assemble engine
21/09/2011	Bell, Daniel - TWC Manager	9.50	Assemble engine
21/09/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	R & R grease line fittings./Clean parts & assemble engine
22/09/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	Clean up parts & assemble engine./Fit fuel pump, turbo & exhaust pipes, refit hyd. lines.
22/09/2011	Bell, Daniel - TWC Manager	9.50	Assemble engine
23/09/2011	Bell, Daniel - TWC Manager	9.50	Assemble engine
26/09/2011	Knapman, Kenneth - TWC MECHANIC	6.00	Continue engine & trans rebuild.
26/09/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Clean up parts & assemble engine./Fit fuel pump, turbo & exhaust pipes, refit hyd. lines.
27/09/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean up parts & assemble engine./Fit fuel pump, turbo & exhaust pipes, refit hyd. lines.
29/09/2011	Bell, Daniel - TWC Manager	8.50	Assemble engine
06/10/2011	Bell, Daniel - TWC Manager	0.00	Assemble engine, clean engine bay for painting. Remove transmission
10/10/2011	Bell, Daniel - TWC Manager	3.00	Assemble engine, clean engine bay for painting. Remove transmission
10/10/2011	Knapman, Kenneth - TWC MECHANIC	3.50	Fit engine harness/Disconnect steering cylinders, drain final drive & undo cover plate, purchase ba
11/10/2011	Bell, Daniel - TWC Manager	3.00	Assemble engine, clean engine bay for painting. Remove transmission
12/10/2011	Knapman, Kenneth - TWC MECHANIC	4.50	Fit engine harness/Disconnect steering cylinders, drain final drive & undo cover plate, purchase ba
12/10/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Drain, diff, trans & hyd. oils
13/10/2011	Knapman, Kenneth - TWC MECHANIC	3.50	Start trans. removal/Work on trans.
13/10/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove trans. & diff./Order parts
14/10/2011	Knapman, Kenneth - TWC MECHANIC	2.50	Start trans. removal/Work on trans.
14/10/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove trans. & diff./Order parts
18/10/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Start trans. removal/Work on trans.
18/10/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove trans. & diff./Order parts
18/10/2011	Bell, Daniel - TWC Manager	8.50	Disassemble transmission, tranfer case & diff.

Date	Name	Duration	Notes
19/10/2011	Bell, Daniel - TWC Manager	5.00	Disassemble transmission, transfer case & diff.
20/10/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Assemble diff.
24/10/2011	Knapman, Kenneth - TWC MECHANIC	7.00	31109 hrs: Disassemble steering & implement pump & transmission, scavenger pump, order parts, clean
25/10/2011	Knapman, Kenneth - TWC MECHANIC	6.00	31109 hrs: Disassemble steering & implement pump & transmission, scavenger pump, order parts, clean
26/10/2011	Knapman, Kenneth - TWC MECHANIC	9.50	31109 hrs: Disassemble steering & implement pump & transmission, scavenger pump, order parts, clean
27/10/2011	Knapman, Kenneth - TWC MECHANIC	8.50	Reassemble steering/implement pump, oversee planetary assy./Assemble torque converter & start trans
27/10/2011	Griffin, Reece - Plant Mechanic	8.00	Continue rebuild on diff & transfer case
28/10/2011	Knapman, Kenneth - TWC MECHANIC	7.00	Reassemble steering/implement pump, oversee planetary assy./Assemble torque converter & start trans
29/10/2011	Knapman, Kenneth - TWC MECHANIC	5.00	Reassemble steering/implement pump, oversee planetary assy./Assemble torque converter & start trans
29/10/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean up parts & assemble trans./31109hrs: refit engine.
31/10/2011	Knapman, Kenneth - TWC MECHANIC	2.50	Reassemble steering/implement pump, oversee planetary assy./Assemble torque converter & start trans
02/11/2011	Bell, Daniel - TWC Manager	1.50	Install engine & surrounding parts.
02/11/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean up parts & assemble trans./31109hrs: refit engine.
03/11/2011	Knapman, Kenneth - TWC MECHANIC	5.50	31109hrs: Install engine ancillaries
03/11/2011	Griffin, Reece - Plant Mechanic	7.50	Install engine & connect components
03/11/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	Assemble engine & radiator to machine.
04/11/2011	Bell, Daniel - TWC Manager	5.50	Install engine & surrounding parts.
04/11/2011	Griffin, Reece - Plant Mechanic	5.50	Install engine & connect components
14/11/2011	Bell, Daniel - TWC Manager	5.50	Assemble transmission.
15/11/2011	Bell, Daniel - TWC Manager	3.00	Assemble transmission.
16/11/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Assemble trans.
17/11/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	31,109hrs: Assemble transmission./Assemble trans hyd. & diff to trans.
18/11/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	31,109hrs: Assemble transmission./Assemble trans hyd. & diff to trans.
21/11/2011	Griffin, Reece - Plant Mechanic	5.50	Installation of valves into transmission & obtain parts/Continue work on transmission./Bolt trans.
22/11/2011	Griffin, Reece - Plant Mechanic	3.50	Installation of valves into transmission & obtain parts/Continue work on transmission./Bolt trans.
22/11/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	31,109hrs: Assemble transmission./Assemble trans hyd. & diff to trans.
23/11/2011	Griffin, Reece - Plant Mechanic	2.00	Installation of valves into transmission & obtain parts/Continue work on transmission./Bolt trans.
24/11/2011	Griffin, Reece - Plant Mechanic	2.50	Chk'd trans. for loose circlip.
29/11/2011	Griffin, Reece - Plant Mechanic	7.50	Install transmission etc
29/11/2011	Bell, Daniel - TWC Manager	7.50	Install transmission R & I fuel pump
29/11/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	Assemble trans & diff to machine./Prepare to start machine, locate oil leak, remove fuel pump & rep
30/11/2011	Bell, Daniel - TWC Manager	10.50	Install transmission R & I fuel pump
30/11/2011	Griffin, Reece - Plant Mechanic	2.00	Install transmission etc
30/11/2011	Wilde, David - TWC WORKSHOP MANAGER	6.00	Assemble trans & diff to machine./Prepare to start machine, locate oil leak, remove fuel pump & rep
05/12/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove radiator for repairs./Assemble radiator & fit to machine./Pressure test trans & assemble gua
06/12/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove radiator for repairs./Assemble radiator & fit to machine./Pressure test trans & assemble gua
07/12/2011	Griffin, Reece - Plant Mechanic	7.50	Replace fan shroud, pressure test trans., replace trans. guards & viewing plate.
07/12/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Remove radiator for repairs./Assemble radiator & fit to machine./Pressure test trans & assemble gua
08/12/2011	Bell, Daniel - TWC Manager	7.50	Install guards, remove old step mounts and weld on new step mounts. Prep machine for painting.
08/12/2011	Griffin, Reece - Plant Mechanic	2.00	Refit guards to machine/Remove push & pull off machine.
08/12/2011	Wilde, David - TWC WORKSHOP MANAGER	7.50	31,109hrs: Refit bonnets & guards./Drain fuel tank, remove old parts & replace fast fill pipes.
09/12/2011	Griffin, Reece - Plant Mechanic	1.50	Refit guards to machine/Remove push & pull off machine.
09/12/2011	Bell, Daniel - TWC Manager	9.50	Install guards, remove old step mounts and weld on new step mounts. Prep machine for painting.
12/12/2011	Bell, Daniel - TWC Manager	8.50	Install guards, remove old step mounts and weld on new step mounts. Prep machine for painting.
13/12/2011	Bell, Daniel - TWC Manager	7.50	Install guards, remove old step mounts and weld on new step mounts. Prep machine for painting.
14/12/2011	Bell, Daniel - TWC Manager	5.50	Install guards, remove old step mounts and weld on new step mounts. Prep machine for painting.
14/12/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	31,109hrs: Refit bonnets & guards./Drain fuel tank, remove old parts & replace fast fill pipes.
15/12/2011	Griffin, Reece - Plant Mechanic	2.00	Install new collets on valves
19/12/2011	Griffin, Reece - Plant Mechanic	1.00	Install new collets on valves
19/12/2011	Wilde, David - TWC WORKSHOP MANAGER	7.50	Wash down scraper
19/12/2011	Bell, Daniel - TWC Manager	4.50	Weld on step mounts. Order new hoses. Fab push pad
20/12/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Wash down scraper
21/12/2011	Griffin, Reece - Plant Mechanic	2.50	Removed grease lines
21/12/2011	Bell, Daniel - TWC Manager	5.00	Weld on step mounts. Order new hoses. Fab push pad

Date	Name	Duration	Notes
05/01/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Remanufacture of push pad/Weld push pad to machine./Remove broken studs, tap broken threads
06/01/2012	Knapman, Kenneth - TWC MECHANIC	3.50	Remanufacture of push pad/Weld push pad to machine./Remove broken studs, tap broken threads
11/01/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Remanufacture of push pad/Weld push pad to machine./Remove broken studs, tap broken threads
12/01/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Fit mudguard.
17/01/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove all bonnets & guards.
19/01/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Remove broken brake shoe stud, start drilling holes for grease line modification./Fit scraper brake
19/01/2012	Griffin, Reece - Plant Mechanic	6.50	Remove wheels & final drives/planetary's, remove r/h & l/h brake drums, commence replacement of bra
19/01/2012	Bell, Daniel - TWC Manager	3.00	Remove brake shoe pivot pin. RHSR. Replace fuel & air hose on draft arm
19/01/2012	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove rear wheels, inspect wheel bearings & brakes, clean up parts./ Replace r/h rear brake shoes
20/01/2012	Knapman, Kenneth - TWC MECHANIC	6.00	Remove broken brake shoe stud, start drilling holes for grease line modification./Fit scraper brake
20/01/2012	Wilde, David - TWC WORKSHOP MANAGER	6.50	Remove rear wheels, inspect wheel bearings & brakes, clean up parts./ Replace r/h rear brake shoes
23/01/2012	Griffin, Reece - Plant Mechanic	4.50	Remove wheels & final drives/planetary's, remove r/h & l/h brake drums, commence replacement of bra
23/01/2012	Knapman, Kenneth - TWC MECHANIC	4.00	Remove broken brake shoe stud, start drilling holes for grease line modification./Fit scraper brake
23/01/2012	Bell, Daniel - TWC Manager	5.00	Remove brake shoe pivot pin. RHSR. Replace fuel & air hose on draft arm
23/01/2012	Wilde, David - TWC WORKSHOP MANAGER	7.50	Remove rear wheels, inspect wheel bearings & brakes, clean up parts./ Replace r/h rear brake shoes
24/01/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove rear wheels, inspect wheel bearings & brakes, clean up parts./ Replace r/h rear brake shoes
25/01/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove rear wheels, inspect wheel bearings & brakes, clean up parts./ Replace r/h rear brake shoes
25/01/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Remove broken brake shoe stud, start drilling holes for grease line modification./Fit scraper brake
26/01/2012	Wilde, David - TWC WORKSHOP MANAGER	4.50	Wash down./Repair bowl, remove old air lines, refit clamps to hyd. lines.
31/01/2012	Knapman, Kenneth - TWC MECHANIC	7.50	Gouge off side plate on bowl, obtain steel, cut & fit new plate.
01/02/2012	Knapman, Kenneth - TWC MECHANIC	7.50	Gouge off side plate on bowl, obtain steel, cut & fit new plate.
01/02/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	Wash down./Repair bowl, remove old air lines, refit clamps to hyd. lines.
06/02/2012	Knapman, Kenneth - TWC MECHANIC	4.00	Weld repairs to bowl & bonnet, gouge off wear plates on radiator protector./Make up draft arm hose
07/02/2012	Knapman, Kenneth - TWC MECHANIC	7.00	Weld repairs to bowl & bonnet, gouge off wear plates on radiator protector./Make up draft arm hose
07/02/2012	Wilde, David - TWC WORKSHOP MANAGER	7.50	Remove air & hy. lines, remove seals & O rings from control valve./Refit rear trans wiring & air li
08/02/2012	Griffin, Reece - Plant Mechanic	7.50	Remove old hitch hoses & make new ones, cleaned accumulator plates
08/02/2012	Knapman, Kenneth - TWC MECHANIC	6.50	Weld repairs to bowl & bonnet, gouge off wear plates on radiator protector./Make up draft arm hose
08/02/2012	Bell, Daniel - TWC Manager	3.00	Engrave & install ID plates
08/02/2012	Wilde, David - TWC WORKSHOP MANAGER	7.50	Remove air & hy. lines, remove seals & O rings from control valve./Refit rear trans wiring & air li
09/02/2012	Knapman, Kenneth - TWC MECHANIC	6.00	Repairs to guards & bonnets/Continue repairs on mudguards & hoses./Dismantle cab covers & remove se
09/02/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace hyd. hoses/ Make up & replace hitch hoses./Replace hitch hoses & remove cab windows.Fill hy
10/02/2012	Knapman, Kenneth - TWC MECHANIC	7.50	Repairs to guards & bonnets/Continue repairs on mudguards & hoses./Dismantle cab covers & remove se
10/02/2012	Wilde, David - TWC WORKSHOP MANAGER	6.50	Replace hyd. hoses/ Make up & replace hitch hoses./Replace hitch hoses & remove cab windows.Fill hy
11/02/2012	Knapman, Kenneth - TWC MECHANIC	6.50	Repairs to guards & bonnets/Continue repairs on mudguards & hoses./Dismantle cab covers & remove se
11/02/2012	Wilde, David - TWC WORKSHOP MANAGER	7.00	Replace hyd. hoses/ Make up & replace hitch hoses./Replace hitch hoses & remove cab windows.Fill hy
13/02/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Repairs to guards & bonnets/Continue repairs on mudguards & hoses./Dismantle cab covers & remove se
13/02/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Replace hyd. hoses/ Make up & replace hitch hoses./Replace hitch hoses & remove cab windows.Fill hy
14/02/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Repairs to guards & bonnets/Continue repairs on mudguards & hoses./Dismantle cab covers & remove se
15/02/2012	Bell, Daniel - TWC Manager	2.00	Order parts & prepare parts for painting.
15/02/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Repairs to guards & bonnets/Continue repairs on mudguards & hoses./Dismantle cab covers & remove se
16/02/2012	Knapman, Kenneth - TWC MECHANIC	5.00	Weld repair on cab crack, gouge & weld steering link, heat & wrap.
16/02/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove steering link for repairs.
17/02/2012	Griffin, Reece - Plant Mechanic	0.50	Install linkage
17/02/2012	Bell, Daniel - TWC Manager	1.50	Fit steering link.
07/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Refit windows & a/c box.
08/03/2012	Wilde, David - TWC WORKSHOP MANAGER	10.00	Assemble machine parts./Assemble grease lines to hitch, fit transfers/ Assemble machine parts.
09/03/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Pick up windows, make plates for revolving light mounting, purchase bolts./ Fit guards & other pain
09/03/2012	Wilde, David - TWC WORKSHOP MANAGER	10.00	Assemble machine parts./Assemble grease lines to hitch, fit transfers/ Assemble machine parts.
10/03/2012	Knapman, Kenneth - TWC MECHANIC	8.00	Pick up windows, make plates for revolving light mounting, purchase bolts./ Fit guards & other pain
12/03/2012	Griffin, Reece - Plant Mechanic	9.50	Assemble lights, commence installation of grease lines./Continue with grease lines & lights & fix e
12/03/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Pick up windows, make plates for revolving light mounting, purchase bolts./ Fit guards & other pain
12/03/2012	Wilde, David - TWC WORKSHOP MANAGER	6.00	Assemble machine parts./Assemble grease lines to hitch, fit transfers/ Assemble machine parts.
13/03/2012	Griffin, Reece - Plant Mechanic	9.50	Assemble lights, commence installation of grease lines./Continue with grease lines & lights & fix e
13/03/2012	Knapman, Kenneth - TWC MECHANIC	8.00	Pick up windows, make plates for revolving light mounting, purchase bolts./ Fit guards & other pain

Date	Name	Duration	Notes
13/03/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Assemble machine parts./Assemble grease lines to hitch, fit transfers/ Assemble machine parts.
14/03/2012	Griffin, Reece - Plant Mechanic	9.50	Assemble lights, commence installation of grease lines./Continue with grease lines & lights & fix e
14/03/2012	Wilde, David - TWC WORKSHOP MANAGER	9.50	Assemble machine parts./Assemble grease lines to hitch, fit transfers/ Assemble machine parts.
15/03/2012	Griffin, Reece - Plant Mechanic	5.00	Assist install "E" stops./Install cab components/ Install guards & batteries./ Collect parts, haveb
16/03/2012	Griffin, Reece - Plant Mechanic	1.50	Assist install "E" stops./Install cab components/ Install guards & batteries./ Collect parts, haveb
16/03/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Finish install of grease lines & blocks, fir grease cartridges & pack up tools./ Go to Major metals
17/03/2012	Griffin, Reece - Plant Mechanic	2.00	Assist install "E" stops./Install cab components/ Install guards & batteries./ Collect parts, haveb
17/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Fit guards to draft arms, connect laser box & radio./ Fit belly guards
20/03/2012	Griffin, Reece - Plant Mechanic	1.50	Assist install "E" stops./Install cab components/ Install guards & batteries./ Collect parts, haveb
20/03/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Finish install of grease lines & blocks, fir grease cartridges & pack up tools./ Go to Major metals
21/03/2012	Griffin, Reece - Plant Mechanic	3.00	Assist install "E" stops./Install cab components/ Install guards & batteries./ Collect parts, haveb
21/03/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Finish install of grease lines & blocks, fir grease cartridges & pack up tools./ Go to Major metals
21/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit guards to draft arms, connect laser box & radio./ Fit belly guards
22/03/2012	Griffin, Reece - Plant Mechanic	1.50	Relocate fire extinguisher, install door rubbers./ Chk all oil levels & magnetic plugs
22/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Fit door seals./ Chk final drive plugs & oil leaks, renmove & replace rear throttle control.
23/03/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Make guards./ Oder seal
27/03/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Make guards./ Oder seal
28/03/2012	Griffin, Reece - Plant Mechanic	1.00	Relocate fire extinguisher, install door rubbers./ Chk all oil levels & magnetic plugs
28/03/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit door seals./ Chk final drive plugs & oil leaks, renmove & replace rear throttle control.
29/03/2012	Knapman, Kenneth - TWC MECHANIC	4.00	Borrow pipe bender, manufacture guard rail & return pipe bender./Manufacture guard rails/ Continue
29/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	31,130hrs: Chk & adjust high idle./ Chk rear trans fault & drop front belly guard, repair alternato
30/03/2012	Griffin, Reece - Plant Mechanic	1.00	Chk non operation of rear transmission.
30/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	31,130hrs: Chk & adjust high idle./ Chk rear trans fault & drop front belly guard, repair alternato
02/04/2012	Knapman, Kenneth - TWC MECHANIC	5.50	Borrow pipe bender, manufacture guard rail & return pipe bender./Manufacture guard rails/ Continue
03/04/2012	Knapman, Kenneth - TWC MECHANIC	5.50	Borrow pipe bender, manufacture guard rail & return pipe bender./Manufacture guard rails/ Continue
04/04/2012	Knapman, Kenneth - TWC MECHANIC	4.00	Borrow pipe bender, manufacture guard rail & return pipe bender./Manufacture guard rails/ Continue
05/04/2012	Knapman, Kenneth - TWC MECHANIC	6.50	Make guard rails./ Fit guard rails to test.
11/04/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Make guard rails./ Fit guard rails to test.
14/04/2012	Griffin, Reece - Plant Mechanic	2.00	250hr service./ Checked A/C and general machine chk.
14/04/2012	Knapman, Kenneth - TWC MECHANIC	0.75	Finish guard rails./ Disassemble hyd. hose.
14/04/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	31,250hrs service./Make up hose & fir to machine, repair A/C cable
16/04/2012	Griffin, Reece - Plant Mechanic	1.50	250hr service./ Checked A/C and general machine chk.
16/04/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Finish guard rails./ Disassemble hyd. hose.
16/04/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	31,250hrs service./Make up hose & fir to machine, repair A/C cable
19/04/2012	Griffin, Reece - Plant Mechanic	1.00	Chk final drive plugs.
01/05/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	31,330hrs: Chk & repair wiring to A/C.
09/05/2012	Bell, Daniel - TWC Manager	7.50	Remove rear power pack.
09/05/2012	Knapman, Kenneth - TWC MECHANIC	6.50	Remove power pack from scraper, disassemble power pack, remove fuel pump & deliver for repair, sepa
09/05/2012	Wilde, David - TWC WORKSHOP MANAGER	5.00	Remove rear eng. & trans. & disassemble, loo up & order parts.
10/05/2012	Griffin, Reece - Plant Mechanic	5.00	Work on transmission & collect parts.
10/05/2012	Knapman, Kenneth - TWC MECHANIC	8.00	Disassemble torque converter & reassemble, begin transmission disassembly./ Measure clutch discs, d
10/05/2012	Bell, Daniel - TWC Manager	10.50	Engine & tranmission repairs.
10/05/2012	Wilde, David - TWC WORKSHOP MANAGER	9.50	Dismantle rear trans. & clean up parts./Clean parts & assemble trans./ Reassemble trans. & clean pa
11/05/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Disassemble torque converter & reassemble, begin transmission disassembly./ Measure clutch discs, d
11/05/2012	Bell, Daniel - TWC Manager	7.00	Engine & tranmission repairs.
11/05/2012	Wilde, David - TWC WORKSHOP MANAGER	4.50	Dismantle rear trans. & clean up parts./Clean parts & assemble trans./ Reassemble trans. & clean pa
12/05/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Disassemble torque converter & reassemble, begin transmission disassembly./ Measure clutch discs, d
14/05/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Disassemble torque converter & reassemble, begin transmission disassembly./ Measure clutch discs, d
14/05/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	Dismantle rear trans. & clean up parts./Clean parts & assemble trans./ Reassemble trans. & clean pa
15/05/2012	Knapman, Kenneth - TWC MECHANIC	7.50	Disassemble torque converter & reassemble, begin transmission disassembly./ Measure clutch discs, d
15/05/2012	Wilde, David - TWC WORKSHOP MANAGER	8.50	Dismantle rear trans. & clean up parts./Clean parts & assemble trans./ Reassemble trans. & clean pa
16/05/2012	Knapman, Kenneth - TWC MECHANIC	9.00	Disassemble torque converter & reassemble, begin transmission disassembly./ Measure clutch discs, d
16/05/2012	Wilde, David - TWC WORKSHOP MANAGER	8.00	Dismantle rear trans. & clean up parts./Clean parts & assemble trans./ Reassemble trans. & clean pa
17/05/2012	Griffin, Reece - Plant Mechanic	5.00	Clean & adjust front wheel bearings.

Date	Name	Duration	Notes
17/05/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Disassemble, clean, reseal & reassemble lock up valve, fit power pack., clean converter parts, prep
17/05/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	Refit brakes & adjust wheel bearings
18/05/2012	Bell, Daniel - TWC Manager	3.50	Pressure clean scraper for weed and seed inspection.
18/05/2012	Griffin, Reece - Plant Mechanic	2.00	Clean & adjust front wheel bearings.
18/05/2012	Knapman, Kenneth - TWC MECHANIC	9.00	Disassemble, clean, reseal & reassemble lock up valve, fit power pack., clean converter parts, prep
18/05/2012	Wilde, David - TWC WORKSHOP MANAGER	5.00	Assemble converter & fit to trans., R & R ejector seals.
19/05/2012	Bell, Daniel - TWC Manager	9.00	Pressure clean scraper for weed and seed inspection.
21/05/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Disassemble, clean, reseal & reassemble lock up valve, fit power pack., clean converter parts, prep
22/05/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Disassemble, clean, reseal & reassemble lock up valve, fit power pack., clean converter parts, prep
12/06/2012	Griffin, Reece - Plant Mechanic	4.00	Organise & load gear for Wandoen site./ Travel to jobsite, wait for access, receive visitor inducti
12/06/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Load gear for diff removal.
12/06/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	31399 hrs:Load parts, chk noise in diff & chk magnetic plugs.
13/06/2012	Griffin, Reece - Plant Mechanic	15.00	Organise & load gear for Wandoen site./ Travel to jobsite, wait for access, receive visitor inducti
14/06/2012	Griffin, Reece - Plant Mechanic	4.50	Strip diff./ Assemble diff./ Assemble crown wheel onto diff etc. then travel to jobsite (Tara)/ Tra
15/06/2012	Griffin, Reece - Plant Mechanic	4.50	Strip diff./ Assemble diff./ Assemble crown wheel onto diff etc. then travel to jobsite (Tara) Tra
18/06/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Repair front diff.
18/06/2012	Griffin, Reece - Plant Mechanic	6.00	Strip diff./ Assemble diff./ Assemble crown wheel onto diff etc. then travel to jobsite (Tara) Tra
19/06/2012	Griffin, Reece - Plant Mechanic	16.00	Strip diff./ Assemble diff./ Assemble crown wheel onto diff etc. then travel to jobsite (Tara) Tra
20/06/2012	Griffin, Reece - Plant Mechanic	6.00	Strip diff./ Assemble diff./ Assemble crown wheel onto diff etc. then travel to jobsite (Tara) Tra
21/06/2012	Griffin, Reece - Plant Mechanic	1.00	Clean kidney loop
03/07/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	Load up drain tubs & parts.
04/07/2012	Wilde, David - TWC WORKSHOP MANAGER	14.50	Travel to Wandoen. Check noise in power train. Remove diff and trans. Travel to Moree.
04/07/2012	Bell, Daniel - TWC Manager	14.50	Travel to Wandoen. Check noise in power train. Remove diff and trans. Travel to Moree.
05/07/2012	Bell, Daniel - TWC Manager	9.50	Disassemble & inspect front diff.
05/07/2012	Wilde, David - TWC WORKSHOP MANAGER	5.50	Dismantle diff & inspect parts, look up & order parts./ Clean up parts & assemble diff./ Complete d
06/07/2012	Dawson, Dale - TWC Mechanic	7.00	Inspect & crack test diff housing & carriers, clean & start reassembly of diff./ Complete diff asse
06/07/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Dismantle diff & inspect parts, look up & order parts./ Clean up parts & assemble diff./ Complete d
07/07/2012	Dawson, Dale - TWC Mechanic	4.00	Inspect & crack test diff housing & carriers, clean & start reassembly of diff./ Complete diff asse
07/07/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Dismantle diff & inspect parts, look up & order parts./ Clean up parts & assemble diff./ Complete d
09/07/2012	Griffin, Reece - Plant Mechanic	4.50	Unload diff & commence install trans. & diff in machine./ Complete install of trans. & diff.
09/07/2012	Dawson, Dale - TWC Mechanic	4.50	Unload diff & commence install of trans. & diff into machine./ Complete install of trans. & diff. c
10/07/2012	Griffin, Reece - Plant Mechanic	8.00	Unload diff & commence install trans. & diff in machine./ Complete install of trans. & diff.
10/07/2012	Dawson, Dale - TWC Mechanic	8.00	Unload diff & commence install of trans. & diff into machine./ Complete install of trans. & diff. c
13/07/2012	Dawson, Dale - TWC Mechanic	2.00	Waited to service machine but unable to due to hours error, reseal apron actuator for apron button.
13/07/2012	Griffin, Reece - Plant Mechanic	2.00	Wait to service machine but unable to due to hours error, repair apron trigger.
25/07/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Modify engine stand.
06/08/2012	Dawson, Dale - TWC Mechanic	2.50	31,494hrs: Complete 500hr service & take SOS, fit new 2way speaker, inspect operation of autogrease
06/08/2012	Griffin, Reece - Plant Mechanic	2.50	31,494hrs: Complete 500hr service including SOS, fit new 2way speaker, inspect operation of auto gr
20/08/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	31,543hrs: Repair leaks on trans., tighten a/c & alternator belts, replace work light./ 31553hrs: C
22/08/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	31,543hrs: Repair leaks on trans., tighten a/c & alternator belts, replace work light./ 31553hrs: C
23/08/2012	Wilde, David - TWC WORKSHOP MANAGER	13.00	Travel to Toowoomba to Wandoan to Tara - R & R a/c compressor & charge system., test run.
29/08/2012	Dawson, Dale - TWC Mechanic	6.00	Travel to jobsite (Woleebee Ck.) - 4 hrs, vac down, inspect & recharge A/C.
29/08/2012	Griffin, Reece - Plant Mechanic	6.00	Travel to jobsite (Woleebee Ck)- 4 hrs, regas A/C system.
02/10/2012	Dawson, Dale - TWC Mechanic	1.50	Complete A/C recharge. gas escaping from low pressure hose at compressor - to be replaced.
04/10/2012	Bell, Daniel - TWC Manager	1.50	Collect A/C gas
05/10/2012	Dawson, Dale - TWC Mechanic	5.50	Travel to Dalby, collect parts & chase up non arrival of parts, return to Tara, travel to Monreagh,
08/10/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Load parts & oil for service./ 31,750hrs service.
09/10/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	Load parts & oil for service./ 31,750hrs service.
16/10/2012	Dawson, Dale - TWC Mechanic	4.00	31799hrs: Repairs - R & R hose on A/C and regass, install new HMU to steer system, oin air leak & r
16/10/2012	Griffin, Reece - Plant Mechanic	4.00	31799hrs: Repairs - R & R A/C hose & regass, install new HMU to steer system, pin air leak & repai
20/10/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk, remove & clean out auto grase system, refit & test run, replace air filters, Travel to Dalby.
26/10/2012	Griffin, Reece - Plant Mechanic	1.00	Prep to repalce injector but injector #3 line snapped./ Fit injector line, trace missfire under loa
26/10/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Look up & order parts, find fuel lines, travel to Goondiwindi & back.
27/10/2012	Griffin, Reece - Plant Mechanic	2.00	Prep to repalce injector but injector #3 line snapped./ Fit injector line, trace missfire under loa

Date	Name	Duration	Notes
08/11/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Replace fuel line #2 & install clamps. 31948hrs
15/11/2012	Dawson, Dale - TWC Mechanic	3.50	Install rear engine injector lines & clamps as per CAT manual. Replace rear engine muffler box. 319
16/11/2012	Dawson, Dale - TWC Mechanic	4.50	Install rear engine injector lines & clamps as per CAT manual. Replace rear engine muffler box. 319
16/11/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	32,000hrs service, replace bolts in rear air tank.
24/11/2012	Dawson, Dale - TWC Mechanic	2.00	R & R fuel pump governor shaft seal & gasket on rear motor, remount air tank on rear, inspect fault
24/11/2012	Griffin, Reece - Plant Mechanic	3.00	Repaired greasing problem & rear fuel pump output shaft leak.
25/11/2012	Dawson, Dale - TWC Mechanic	0.75	R & R fuel pump governor shaft seal & gasket on rear motor, remount air tank on rear, inspect fault
27/11/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	32056hrs: R & R flashing light & battery isolator switch.
28/11/2012	Dawson, Dale - TWC Mechanic	1.00	R & R fuel pump governor shaft seal & gasket on rear motor, remount air tank on rear, inspect fault
07/12/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Check & charge hitch accumulator. 32145hrs
09/12/2012	Griffin, Reece - Plant Mechanic	1.00	Check hydraulic leak order ejector cylinder pipe. 32167hrs Clean out evaporator core
10/12/2012	Griffin, Reece - Plant Mechanic	1.50	Check hydraulic leak order ejector cylinder pipe. 32167hrs Clean out evaporator core
13/12/2012	Griffin, Reece - Plant Mechanic	0.50	32,197hrs: Obtain engine hrs & chk over./ Chk a/c pressure & clean condensor./ 250hrs service & re
16/12/2012	Griffin, Reece - Plant Mechanic	1.00	32,197hrs: Obtain engine hrs & chk over./ Chk a/c pressure & clean condensor./ 250hrs service & re
17/12/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	23,250hrs service.
17/12/2012	Griffin, Reece - Plant Mechanic	3.00	32,197hrs: Obtain engine hrs & chk over./ Chk a/c pressure & clean condensor./ 250hrs service & re
03/01/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	32,250hrs: Chk oil & coolant levels, chk all belts.
07/01/2013	Dawson, Dale - TWC Mechanic	1.00	Inspect machine for faults, order parts.
13/01/2013	Griffin, Reece - Plant Mechanic	1.00	Chk machine over.
17/01/2013	Griffin, Reece - Plant Mechanic	1.50	32,337hrs: Inspect overheating transmission - permitted back to work. / Regas hitch, chk into recur
18/01/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk rear eng. switch./ Chk trans. electrical fault & replace control box./ 32,358hrs: Chk wiring ha
19/01/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fault find trans. electrical fault over phone.
19/01/2013	Griffin, Reece - Plant Mechanic	2.50	32,337hrs: Inspect overheating transmission - permitted back to work. / Regas hitch, chk into recur
21/01/2013	Dawson, Dale - TWC Mechanic	5.00	32,356hrs: Locate & repair transmission drive fault, fit new trans. shift card harness & card, fir
21/01/2013	Griffin, Reece - Plant Mechanic	4.00	32,337hrs: Inspect overheating transmission - permitted back to work. / Regas hitch, chk into recur
22/01/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk rear eng. switch./ Chk trans. electrical fault & replace control box./ 32,358hrs: Chk wiring ha
23/01/2013	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk rear eng. switch./ Chk trans. electrical fault & replace control box./ 32,358hrs: Chk wiring ha
07/02/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk movement in hitch.
10/02/2013	Dawson, Dale - TWC Mechanic	1.00	Complete cushion hitch accumulator recharge, accumulators to be removed & resealed - parts orders.
14/02/2013	Wilde, David - TWC WORKSHOP MANAGER	1.50	32,446hrs: Drain oil from accumulators & recharge & test run.
16/02/2013	Dawson, Dale - TWC Mechanic	2.00	Wait onsite for machine, locate a/c fault - evaporator blocked - cleaned out with air & water./ Loc
17/02/2013	Dawson, Dale - TWC Mechanic	2.00	Wait onsite for machine, locate a/c fault - evaporator blocked - cleaned out with air & water./ Loc
18/02/2013	Dawson, Dale - TWC Mechanic	1.00	Wait onsite for machine, locate a/c fault - evaporator blocked - cleaned out with air & water./ Loc
21/02/2013	Wilde, David - TWC WORKSHOP MANAGER	4.00	32,500hrs service, fit shims to hitch, replace seal on hyd. controls & governor shaft.
21/02/2013	Griffin, Reece - Plant Mechanic	0.50	Rear engine throttle seal./ Complete SOS's for Trans., final drives & diffs./Fill out SOS's
22/02/2013	Griffin, Reece - Plant Mechanic	1.50	Rear engine throttle seal./ Complete SOS's for Trans., final drives & diffs./Fill out SOS's
24/02/2013	Griffin, Reece - Plant Mechanic	1.00	Rear engine throttle seal./ Complete SOS's for Trans., final drives & diffs./Fill out SOS's
19/03/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	32,567Hrs: adjust door latch.
21/03/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	32,583Hrs: R & R radio./ Chk electrical fault & replace circuit breaker, test run.
22/03/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	32,583Hrs: R & R radio./ Chk electrical fault & replace circuit breaker, test run.
29/03/2013	Griffin, Reece - Plant Mechanic	2.50	Inspect seat & replace router edge bolts.
05/04/2013	Dawson, Dale - TWC Mechanic	1.00	Remove ignition barrel from 261 to take to jobsite for 278.
06/04/2013	Dawson, Dale - TWC Mechanic	1.00	Fit ignition switch from 261 to rear motor, fit new bonnet mount rubbers & bolts.
11/04/2013	Griffin, Reece - Plant Mechanic	2.00	Chk for vibration in machine - component filters, bungs, screens.
20/04/2013	Dawson, Dale - TWC Mechanic	3.50	32,789HRS: Complete 250hr service, pressure test & locate coolant leaks, R & R hose between afterco
22/04/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	32,807Hrs: Chk crack in steering bracket & order parts./ Chk & tighten alternator belt, remove stee
23/04/2013	Wilde, David - TWC WORKSHOP MANAGER	5.50	32,807Hrs: Chk crack in steering bracket & order parts./ Chk & tighten alternator belt, remove stee
24/04/2013	Wilde, David - TWC WORKSHOP MANAGER	6.50	32,807Hrs: Chk crack in steering bracket & order parts./ Chk & tighten alternator belt, remove stee
25/04/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove 2 brake boosters./ Look up parts./ Pick up parts, fit brake boosters to machine, adjust brak
26/04/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove 2 brake boosters./ Look up parts./ Pick up parts, fit brake boosters to machine, adjust brak
27/04/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove 2 brake boosters./ Look up parts./ Pick up parts, fit brake boosters to machine, adjust brak
30/04/2013	Griffin, Reece - Plant Mechanic	1.50	32,835HRS: Regas hitch - removed approx 2L oil.
07/05/2013	Wilde, David - TWC WORKSHOP MANAGER	1.50	32,892HRS: Chk for eng. oil leak, drop belly guard & tighten sump bolts, test run.
13/05/2013	Griffin, Reece - Plant Mechanic	0.50	Replace flashing light.

Date	Name	Duration	Notes
19/05/2013	Griffin, Reece - Plant Mechanic	1.00	32,992HRS: Take all SOS
30/05/2013	Griffin, Reece - Plant Mechanic	1.00	33016HRS: Remove bail lift pipe./ Install repaired pipe on bowl lift ram - L/h side.
31/05/2013	Griffin, Reece - Plant Mechanic	1.50	33016HRS: Remove bail lift pipe./ Install repaired pipe on bowl lift ram - L/h side.
12/06/2013	Dawson, Dale - TWC Mechanic	0.50	Go through repairs with Reece.
16/06/2013	Griffin, Reece - Plant Mechanic	0.50	330607HRS: Install rear trans. temp sensors./ Remove 1 steer ram./ Install steer ram.
17/06/2013	Griffin, Reece - Plant Mechanic	1.00	330607HRS: Install rear trans. temp sensors./ Remove 1 steer ram./ Install steer ram.
18/06/2013	Wilde, David - TWC WORKSHOP MANAGER	3.50	Dismantle & reseal 1 steering & hitch rams.
19/06/2013	Griffin, Reece - Plant Mechanic	1.00	330607HRS: Install rear trans. temp sensors./ Remove 1 steer ram./ Install steer ram.
25/06/2013	Griffin, Reece - Plant Mechanic	2.00	Install new grease lines from grease pump & spiral wrap./ Change rear trans oil & breather, clean s
26/06/2013	Griffin, Reece - Plant Mechanic	3.00	Install new grease lines from grease pump & spiral wrap./ Change rear trans oil & breather, clean s
26/06/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts.
29/06/2013	Griffin, Reece - Plant Mechanic	1.50	Fit 2 new hitch pump hoses, remove rear dash board for coolant leak./ Drop flush out of radiator &
30/06/2013	Griffin, Reece - Plant Mechanic	1.00	Fit 2 new hitch pump hoses, remove rear dash board for coolant leak./ Drop flush out of radiator &
02/07/2013	Griffin, Reece - Plant Mechanic	2.00	Fit 2 new hitch pump hoses, remove rear dash board for coolant leak./ Drop flush out of radiator &
04/07/2013	Dawson, Dale - TWC Mechanic	3.50	Remove accumulator for reseal (front) finish install of rear accumulator. R & R radiator pressure r
05/07/2013	Dawson, Dale - TWC Mechanic	3.00	Remove accumulator for reseal (front) finish install of rear accumulator. R & R radiator pressure r
08/07/2013	Dawson, Dale - TWC Mechanic	1.50	Remove accumulator for reseal (front) finish install of rear accumulator. R & R radiator pressure r
09/07/2013	Dawson, Dale - TWC Mechanic	5.00	Remove accumulator for reseal (front) finish install of rear accumulator. R & R radiator pressure r
11/07/2013	Dawson, Dale - TWC Mechanic	1.50	Fit accumulators for suspension.
14/07/2013	Griffin, Reece - Plant Mechanic	1.00	Remove batteries & hoop onto charger./ Swap batteries on charger.
15/07/2013	Griffin, Reece - Plant Mechanic	0.50	Remove batteries & hoop onto charger./ Swap batteries on charger.
21/07/2013	Dawson, Dale - TWC Mechanic	2.00	33072HRS: Charge suspension accumulators & seat accumulator./ Install recharged batteries - still u
30/07/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk over for leaks.
03/08/2013	Dawson, Dale - TWC Mechanic	1.00	Remove a/c air dryer, R & R internals & rekit./ 33072HRS:Fit air dryer after rekit. Repair rear air
04/08/2013	Dawson, Dale - TWC Mechanic	4.00	Remove a/c air dryer, R & R internals & rekit./ 33072HRS:Fit air dryer after rekit. Repair rear air
05/08/2013	Dawson, Dale - TWC Mechanic	4.50	Remove a/c air dryer, R & R internals & rekit./ 33072HRS:Fit air dryer after rekit. Repair rear air
06/08/2013	Dawson, Dale - TWC Mechanic	3.50	Remove a/c air dryer, R & R internals & rekit./ 33072HRS:Fit air dryer after rekit. Repair rear air
07/08/2013	Dawson, Dale - TWC Mechanic	3.50	Remove a/c air dryer, R & R internals & rekit./ 33072HRS:Fit air dryer after rekit. Repair rear air
02/10/2013	Dawson, Dale - TWC Mechanic	1.00	Vac down & charge a/c system.
09/11/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	33075Hrs: Prestart, chk & charge hitch & seal accumulators./ Chk & adjust tyre pressures, blow out
11/11/2013	Griffin, Reece - Plant Mechanic	2.00	33076Hrs: Chk over machine; chk all fluids, pump up all tyres - 80PSI & chk for leaks, test solenoi
11/11/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	33075Hrs: Prestart, chk & charge hitch & seal accumulators./ Chk & adjust tyre pressures, blow out
15/11/2013	Dawson, Dale - TWC Mechanic	1.00	33108Hrs: Repair hyd. oil leak on hyd. pump - rear of trans.
16/11/2013	Griffin, Reece - Plant Mechanic	0.50	Replace blown air compressor hose./ Repair hyd. hose.
20/11/2013	Griffin, Reece - Plant Mechanic	1.00	Replace blown air compressor hose./ Repair hyd. hose.
06/12/2013	Griffin, Reece - Plant Mechanic	1.00	33250HRS: Complete 250hr service to Cat. specs./ 33254HRS: Locate spare hose for ejector door at w
07/12/2013	Griffin, Reece - Plant Mechanic	2.00	33250HRS: Complete 250hr service to Cat. specs./ 33254HRS: Locate spare hose for ejector door at w
09/12/2013	Dawson, Dale - TWC Mechanic	1.00	33282HRS: Locate a/c fault - Found TX valve faulty - replacement arranged./ Evac a/c, R & R receive
11/12/2013	Dawson, Dale - TWC Mechanic	2.00	33282HRS: Locate a/c fault - Found TX valve faulty - replacement arranged./ Evac a/c, R & R receive
11/12/2013	Griffin, Reece - Plant Mechanic	2.00	33250HRS: Complete 250hr service to Cat. specs./ 33254HRS: Locate spare hose for ejector door at w
25/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk hitch for movement. Chk hyd. system./ 33,335HRS: Remove guards & chk for leaks & cracks. refit
28/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk hitch for movement. Chk hyd. system./ 33,335HRS: Remove guards & chk for leaks & cracks. refit
30/01/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Measure H link for oversize, remove l/h side mudguard./33,335HRS: Manufacture grease system bracket
03/02/2014	Knapman, Kenneth - TWC MECHANIC	1.25	Measure H link for oversize, remove l/h side mudguard./33,335HRS: Manufacture grease system bracket
07/02/2014	Dawson, Dale - TWC Mechanic	0.50	Move exhaust stack direction
07/02/2014	Griffin, Reece - Plant Mechanic	0.50	Realign rear exhaust stack./ Repair flashing light, chk machine over, repair brake fault.
11/02/2014	Griffin, Reece - Plant Mechanic	2.50	Realign rear exhaust stack./ Repair flashing light, chk machine over, repair brake fault.
14/02/2014	Dawson, Dale - TWC Mechanic	0.50	Adjust idlers on rear motor./ Blow out radiator
15/02/2014	Dawson, Dale - TWC Mechanic	0.25	Adjust idlers on rear motor./ Blow out radiator
18/02/2014	Griffin, Reece - Plant Mechanic	1.00	Repair push rod bolt threads.
21/02/2014	Dawson, Dale - TWC Mechanic	8.50	Remove covers & guards to effect full reseal on rear radiator, remove cores, clean all components &
21/02/2014	Griffin, Reece - Plant Mechanic	8.00	33,384HRS: Drain coolant, remove guards, disassemble radiator, clean up parts & reassemble radiator
22/02/2014	Dawson, Dale - TWC Mechanic	4.00	Remove covers & guards to effect full reseal on rear radiator, remove cores, clean all components &
22/02/2014	Griffin, Reece - Plant Mechanic	4.00	33,384HRS: Drain coolant, remove guards, disassemble radiator, clean up parts & reassemble radiator

Date	Name	Duration	Notes
28/02/2014	Dawson, Dale - TWC Mechanic	4.50	Locate park brake fault - air system not holding-failing to build pressure. Found relay valve, hose
28/02/2014	Griffin, Reece - Plant Mechanic	7.50	R & R air/fuel ratio diaphragm, remove cab door glass. Plumb up & chk eng. oil pressure. R & R rear
01/03/2014	Griffin, Reece - Plant Mechanic	1.50	R & R air/fuel ratio diaphragm, remove cab door glass. Plumb up & chk eng. oil pressure. R & R rear
03/03/2014	Dawson, Dale - TWC Mechanic	1.50	Locate park brake fault - air system not holding-failing to build pressure. Found relay valve, hose
04/03/2014	Dawson, Dale - TWC Mechanic	2.00	Locate park brake fault - air system not holding-failing to build pressure. Found relay valve, hose
11/03/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk rear trans wiring & refit dash - test run.
14/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Blow out radiators & filters./ 33447HRS: Chk & charge hitch.
15/03/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Blow out radiators & filters./ 33447HRS: Chk & charge hitch.
20/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	33465HRS: Clean out air & cab filters.
25/03/2014	Dawson, Dale - TWC Mechanic	4.50	33500HRS: Drain 20L of hydraulic oil - overfilled by operator 2hrs. Carry out 500hr service 2.5hrs.
26/03/2014	Dawson, Dale - TWC Mechanic	3.50	33500HRS: Drain 20L of hydraulic oil - overfilled by operator 2hrs. Carry out 500hr service 2.5hrs.
29/03/2014	Dawson, Dale - TWC Mechanic	1.00	Inspect & repair high idle on front eng. - not getting full RPM - linkages worn.
29/03/2014	Griffin, Reece - Plant Mechanic	1.00	Inspect & adjust front eng. RPM - linkages worn.
05/04/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & replace rear radiator relief valve./ Remove push pad. Chk front trans wiring & replace trans
06/04/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk & replace rear radiator relief valve./ Remove push pad. Chk front trans wiring & replace trans
07/04/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & replace rear radiator relief valve./ Remove push pad. Chk front trans wiring & replace trans
15/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	33,630HRS: Replace 2way radio./ Chk over for leaks & cracks.
16/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	33,630HRS: Replace 2way radio./ Chk over for leaks & cracks.
22/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Order cutting edge.
25/04/2014	Dawson, Dale - TWC Mechanic	0.50	Locate & repair 2way fault./ 33,690 HRS: Locate power fault on rear motor - batteries u/s. Obtained
26/04/2014	Dawson, Dale - TWC Mechanic	3.00	Locate & repair 2way fault./ 33,690 HRS: Locate power fault on rear motor - batteries u/s. Obtained
02/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Look up & order parts for hitch./ 33,749HRS: Replace seals in cushion hitch cylinder. Replace 2 bump
06/05/2014	Wilde, David - TWC WORKSHOP MANAGER	4.00	Look up & order parts for hitch./ 33,749HRS: Replace seals in cushion hitch cylinder. Replace 2 bump
07/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Look up & order parts for hitch./ 33,749HRS: Replace seals in cushion hitch cylinder. Replace 2 bump
10/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk push pad bolts & hitch pins.
20/05/2014	Dawson, Dale - TWC Mechanic	1.00	Locate cooling system fault - system pressurising on rear motor - cooler head to be removed, drained
22/05/2014	Dawson, Dale - TWC Mechanic	1.00	Fill cooling system & clean radiator of rear motor./ Locate cooling system fault - remove after cool
25/05/2014	Dawson, Dale - TWC Mechanic	9.00	Fill cooling system & clean radiator of rear motor./ Locate cooling system fault - remove after cool
26/05/2014	Dawson, Dale - TWC Mechanic	4.50	Fill cooling system & clean radiator of rear motor./ Locate cooling system fault - remove after cool
29/05/2014	Dawson, Dale - TWC Mechanic	2.50	Unload from L/loader & commence removal of rear power pack./ Complete remove rear power pack & comm
30/05/2014	Dawson, Dale - TWC Mechanic	5.00	Unload from L/loader & commence removal of rear power pack./ Complete remove rear power pack & comm
02/06/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Repair linkage./ Adjust linkage bearings & adjust to specification. Install linkage assy & control
02/06/2014	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove & dismantle hyd. control levers & replace bearings & rod ends./ Replace bowl lever bearings.
02/06/2014	Dawson, Dale - TWC Mechanic	4.00	Unload from L/loader & commence removal of rear power pack./ Complete remove rear power pack & comm
03/06/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove & dismantle hyd. control levers & replace bearings & rod ends./ Replace bowl lever bearings.
03/06/2014	Knapman, Kenneth - TWC MECHANIC	7.50	Repair linkage./ Adjust linkage bearings & adjust to specification. Install linkage assy & control
04/06/2014	Dawson, Dale - TWC Mechanic	7.50	Unload from L/loader & commence removal of rear power pack./ Complete remove rear power pack & comm
04/06/2014	Knapman, Kenneth - TWC MECHANIC	7.50	Repair linkage./ Adjust linkage bearings & adjust to specification. Install linkage assy & control
04/06/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove & dismantle hyd. control levers & replace bearings & rod ends./ Replace bowl lever bearings.
05/06/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Adjust linkages./ Remove brake booster, clean & disassemble. Clean & buff components, set new seals
06/06/2014	Knapman, Kenneth - TWC MECHANIC	5.50	Adjust linkages./ Remove brake booster, clean & disassemble. Clean & buff components, set new seals
10/06/2014	Dawson, Dale - TWC Mechanic	7.00	Clean & inspect engine components & parts etc. Install camshaft & followers, front structure etc, a
10/06/2014	Knapman, Kenneth - TWC MECHANIC	4.00	Adjust linkages./ Remove brake booster, clean & disassemble. Clean & buff components, set new seals
10/06/2014	Wilde, David - TWC WORKSHOP MANAGER	6.00	Replace apron bolts & leaking seals. Clean grease from hitch, wash down.
11/06/2014	Dawson, Dale - TWC Mechanic	5.00	Clean & inspect engine components & parts etc. Install camshaft & followers, front structure etc, a
11/06/2014	Knapman, Kenneth - TWC MECHANIC	5.00	Adjust linkages./ Remove brake booster, clean & disassemble. Clean & buff components, set new seals
12/06/2014	Dawson, Dale - TWC Mechanic	8.50	Clean off engine block, liner etc No. 2, inspect & document damage. Clean eng. components & commenc
12/06/2014	Knapman, Kenneth - TWC MECHANIC	9.50	Replace throttle valve, chk hitch valve pressure & adjust to spec. Remove apron air control hose, r
13/06/2014	Dawson, Dale - TWC Mechanic	9.50	Clean off engine block, liner etc No. 2, inspect & document damage. Clean eng. components & commenc
13/06/2014	Knapman, Kenneth - TWC MECHANIC	7.50	Replace throttle valve, chk hitch valve pressure & adjust to spec. Remove apron air control hose, r
13/06/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Repairs tto draft frame. Chk for air leaks & replace seals./ 33,890HRS: Part service.
16/06/2014	Dawson, Dale - TWC Mechanic	7.50	Clean off engine block, liner etc No. 2, inspect & document damage. Clean eng. components & commenc
16/06/2014	Knapman, Kenneth - TWC MECHANIC	7.50	Replace throttle valve, chk hitch valve pressure & adjust to spec. Remove apron air control hose, r
17/06/2014	Dawson, Dale - TWC Mechanic	3.00	Clean off engine block, liner etc No. 2, inspect & document damage. Clean eng. components & commenc

Date	Name	Duration	Notes
17/06/2014	Knapman, Kenneth - TWC MECHANIC	2.00	Replace throttle valve, chk hitch valve pressure & adjust to spec. Remove apron air control hose, r
17/06/2014	Wilde, David - TWC WORKSHOP MANAGER	5.50	Repairs tto draft frame. Chk for air leaks & replace seals./ 33,890HRS: Part service.
18/06/2014	Dawson, Dale - TWC Mechanic	7.50	Clean off engine block, liner etc No. 2, inspect & document damage. Clean eng. components & commenc
18/06/2014	Knapman, Kenneth - TWC MECHANIC	5.00	Replace throttle valve, chk hitch valve pressure & adjust to spec. Remove apron air control hose, r
19/06/2014	Dawson, Dale - TWC Mechanic	4.50	Fit guards, test & adjust hi & lo idles, adjust as required. R & R brake valve under hitch, R & R d
03/07/2014	Dawson, Dale - TWC Mechanic	0.50	Test main hyd. pressure.
31/07/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	33,887HRS: Remove step & fit bolt to bonnet./ 33,895HRS: Chk tyre pressures, blow out radiators, ch
01/08/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	33,887HRS: Remove step & fit bolt to bonnet./ 33,895HRS: Chk tyre pressures, blow out radiators, ch
08/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	33969hrs Check rear engine start problem. R & R rear starter motor. 34000hrs Carry out front & rear
09/08/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	33969hrs Check rear engine start problem. R & R rear starter motor. 34000hrs Carry out front & rear
11/08/2014	Wilde, David - TWC WORKSHOP MANAGER	3.50	33969hrs Check rear engine start problem. R & R rear starter motor. 34000hrs Carry out front & rear
12/08/2014	Dawson, Dale - TWC Mechanic	0.50	Check hitch gas pressures
13/08/2014	Dawson, Dale - TWC Mechanic	2.50	R&R servo cylinder
13/08/2014	Knapman, Kenneth - TWC MECHANIC	2.00	Repair Scrapper step
19/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	34,048HRS: Chk all belts & replace steering link./ Refit steering bracket & test run. Chk & repair
20/08/2014	Knapman, Kenneth - TWC MECHANIC	2.50	34,048HRS: Weld up crack in spring servo arm.
20/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	34,048HRS: Chk all belts & replace steering link./ Refit steering bracket & test run. Chk & repair
21/08/2014	Dawson, Dale - TWC Mechanic	1.00	34,057: R & R push pad bolts in push pad mount & tension.
21/08/2014	Knapman, Kenneth - TWC MECHANIC	4.50	Manufacture exhaust/air cleaner bracket stay. Remove exhaust/turbo tube & clamp from spare motor. R
27/08/2014	Knapman, Kenneth - TWC MECHANIC	2.50	Repair crack in laser frame.
27/08/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Repairs to laser frame. Chk & adjust rear fan belts.
28/08/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	34138HRS: Replace 2way radio & chk over./ 34208HRS: Replace rear eng induction hose. Repair eng. oi
01/09/2014	Dawson, Dale - TWC Mechanic	0.50	34182HRS: Service/repair E stop.
03/09/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	34138HRS: Replace 2way radio & chk over./ 34208HRS: Replace rear eng induction hose. Repair eng. oi
09/09/2014	Wilde, David - TWC WORKSHOP MANAGER	5.00	34,250HRS: Service, complete SOS, chk & tighten connectors. Test run./ Refit window seal.
10/09/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	34,250HRS: Service, complete SOS, chk & tighten connectors. Test run./ Refit window seal.
11/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk rear trans. fault./ Remove top vertical hitch pin for repairs./ 34,339HRS: Chk & refit window s
12/09/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Gouge, preheat & weld vertical pin, wrap in heat blankets.
12/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk rear trans. fault./ Remove top vertical hitch pin for repairs./ 34,339HRS: Chk & refit window s
15/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk rear trans. fault./ Remove top vertical hitch pin for repairs./ 34,339HRS: Chk & refit window s
17/09/2014	Dawson, Dale - TWC Mechanic	0.50	Connect ET to machine & carry out injector cut out tests to locate hard start fault.
17/09/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk rear trans. fault./ Remove top vertical hitch pin for repairs./ 34,339HRS: Chk & refit window s
20/09/2014	Knapman, Kenneth - TWC MECHANIC	2.50	Remove scraper exhaust & weld repair. / Refit bonnet & exhaust. Remove broken bolts for air tank br
20/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	Remove grease from hitch./ Remove belly guards & wash down machine.
22/09/2014	Knapman, Kenneth - TWC MECHANIC	2.00	Remove scraper exhaust & weld repair. / Refit bonnet & exhaust. Remove broken bolts for air tank br
23/09/2014	Wilde, David - TWC WORKSHOP MANAGER	7.00	Remove grease from hitch./ Remove belly guards & wash down machine.
26/09/2014	Dawson, Dale - TWC Mechanic	1.00	Fit hitch assy./ R & R No.2 fuel pump, pumping element - fault not fixed. Fit new bonnet bolts. Fit
26/09/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Finish installation of hitch cylinder & test run./ 34,373HRS: Chk front radiator for leaks. Wash ou
27/09/2014	Dawson, Dale - TWC Mechanic	3.00	Fit hitch assy./ R & R No.2 fuel pump, pumping element - fault not fixed. Fit new bonnet bolts. Fit
29/09/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Manufacture parts for laser frame modification./ Place machine in shed & begin remanufacture of la
29/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	Finish installation of hitch cylinder & test run./ 34,373HRS: Chk front radiator for leaks. Wash ou
30/09/2014	Knapman, Kenneth - TWC MECHANIC	8.50	Manufacture parts for laser frame modification./ Place machine in shed & begin remanufacture of la
30/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Finish installation of hitch cylinder & test run./ 34,373HRS: Chk front radiator for leaks. Wash ou
01/10/2014	Knapman, Kenneth - TWC MECHANIC	8.00	Manufacture parts for laser frame modification./ Place machine in shed & begin remanufacture of la
02/10/2014	Knapman, Kenneth - TWC MECHANIC	3.00	Remove scotch clips to , heatshrink wiring for 2way & radio. Tidy up wiring. Locate wiring fault in
08/10/2014	Dawson, Dale - TWC Mechanic	1.00	Commence installation of larger E stops to machine.
09/10/2014	Dawson, Dale - TWC Mechanic	1.00	Fit new E stop cover. / Investigate engine misfire. Bring machine into shed for removal of cylinde
09/10/2014	Knapman, Kenneth - TWC MECHANIC	5.50	Clean & install radiator panels & header tank seals. Install radiator & lines etc, fit condensor./
09/10/2014	Wilde, David - TWC WORKSHOP MANAGER	3.50	Replace leaking seals on control valve. / Repairs to eng, look up & order parts./ Look up & order p
10/10/2014	Knapman, Kenneth - TWC MECHANIC	6.50	Clean & install radiator panels & header tank seals. Install radiator & lines etc, fit condensor./
13/10/2014	Dawson, Dale - TWC Mechanic	1.50	Fit new E stop cover. / Investigate engine misfire. Bring machine into shed for removal of cylinde
13/10/2014	Knapman, Kenneth - TWC MECHANIC	8.50	Clean & install radiator panels & header tank seals. Install radiator & lines etc, fit condensor./
14/10/2014	Dawson, Dale - TWC Mechanic	9.00	Fit new E stop cover. / Investigate engine misfire. Bring machine into shed for removal of cylinde
14/10/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace leaking seals on control valve. / Repairs to eng, look up & order parts./ Look up & order p

Date	Name	Duration	Notes
15/10/2014	Dawson, Dale - TWC Mechanic	8.50	Fit new E stop cover. / Investigate engine misfire. Bring machine into shed for removal of cylinde
15/10/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace leaking seals on control valve. / Repairs to eng, look up & order parts./ Look up & order p
16/10/2014	Dawson, Dale - TWC Mechanic	8.00	Finish assembly of front engine, reseal air/fuel ratio control, fit guards & hoses, panels, air int
16/10/2014	Knapman, Kenneth - TWC MECHANIC	4.00	Cut plates for remanufacture of steps, remanufacture steps & bolt to machine.
17/10/2014	Dawson, Dale - TWC Mechanic	2.00	Finish assembly of front engine, reseal air/fuel ratio control, fit guards & hoses, panels, air int
20/10/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk laser system./ Chk & adjust brakes, part wash down.
21/10/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk laser system./ Chk & adjust brakes, part wash down.
27/10/2014	Dawson, Dale - TWC Mechanic	1.00	Strip down ejector door rollers for welding.
29/10/2014	Knapman, Kenneth - TWC MECHANIC	2.00	Build up floor roller.
30/10/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Build up wheel/roller and deliver for machining.
01/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk rear trans system.
06/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.25	Chk over machine./ R & R rear shift card & harness. remove blown hose.
07/11/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk over machine./ R & R rear shift card & harness. remove blown hose.
11/11/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Remove broken control box linkage. Assist replace linkage.
12/11/2014	Dawson, Dale - TWC Mechanic	0.50	34,442HRS: Fit new seat belt.
15/11/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Part 500hr service. Fill out SOS./ Complete SOS samples & look up & order parts.
18/11/2014	Dawson, Dale - TWC Mechanic	0.50	34494HRS: Inspect for noise in machine - found steer pins have movement on barrel ends.
19/11/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Part 500hr service. Fill out SOS./ Complete SOS samples & look up & order parts.
20/11/2014	Dawson, Dale - TWC Mechanic	1.50	34,157HRS: Start on 500hr service & clean radiator./ Inspect a/c - belt slipping. Found bolts miss
20/11/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	34,500HRS: Service./ Chk grease system & clean out plastic. Replace broken apron pin.
24/11/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Make apron pin.
24/11/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	34,500HRS: Service./ Chk grease system & clean out plastic. Replace broken apron pin.
25/11/2014	Dawson, Dale - TWC Mechanic	2.00	34,157HRS: Start on 500hr service & clean radiator./ Inspect a/c - belt slipping. Found bolts miss
09/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	R & R throttle lock valve. Chk air system.
13/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.25	34,678HRS: Chk over. / 34,724HRS: Clean out radiators. Tighten headlight. Chk & replace 2way radio.
17/12/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Remove radiator grill, blow down front & back radiators & replace grill. Repair 2way & headlight mo
17/12/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	34,678HRS: Chk over. / 34,724HRS: Clean out radiators. Tighten headlight. Chk & replace 2way radio.
19/12/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	34,750HRS - Service, load parts & oils, fill out SOS
06/01/2015	Dawson, Dale - TWC Mechanic	1.50	34,759HRS: Fit new roller to R/H side ejector door, fit new wiper assy to rear window, fit pin to s
07/01/2015	Dawson, Dale - TWC Mechanic	2.00	34,759HRS: Fit new roller to R/H side ejector door, fit new wiper assy to rear window, fit pin to s
08/01/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts./ R & R rear trans link solenoid. Chk grease operation. Test run/ 34,833HRS:
09/01/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk rear trans fault & test run.
10/01/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts./ R & R rear trans link solenoid. Chk grease operation. Test run/ 34,833HRS:
13/01/2015	Wilde, David - TWC WORKSHOP MANAGER	4.00	Look up & order parts./ R & R rear trans link solenoid. Chk grease operation. Test run/ 34,833HRS:
20/01/2015	Dawson, Dale - TWC Mechanic	0.50	34,892HRS: R & R cab door handle-latch assy & adjust.
29/01/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	34,966HRS: Change cutting edges & fit tynes./ 35,000HRS part service. / 35,000HRS: Complete service
30/01/2015	Wilde, David - TWC WORKSHOP MANAGER	4.00	34,966HRS: Change cutting edges & fit tynes./ 35,000HRS part service. / 35,000HRS: Complete service
02/02/2015	Wilde, David - TWC WORKSHOP MANAGER	3.00	34,966HRS: Change cutting edges & fit tynes./ 35,000HRS part service. / 35,000HRS: Complete service
06/02/2015	Dawson, Dale - TWC Mechanic	0.50	35,058HRS: Replace failed 2way power supply.
12/02/2015	Knapman, Kenneth - TWC MECHANIC	0.50	35,111HRS: Replace coolant in engine. / Onload oils, remove bowl lift pipes.
12/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk hyd. leaks & repair exhaust system. / Replace seat guide. Chk & charge seat accumulator & repla
13/02/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk hyd. leaks & repair exhaust system. / Replace seat guide. Chk & charge seat accumulator & repla
14/02/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk hyd. leaks & repair exhaust system. / Replace seat guide. Chk & charge seat accumulator & repla
16/02/2015	Dawson, Dale - TWC Mechanic	0.50	Locate rear hyd. oil leak - order parts.
18/02/2015	Knapman, Kenneth - TWC MECHANIC	2.00	35,111HRS: Replace coolant in engine. / Onload oils, remove bowl lift pipes.
19/02/2015	Dawson, Dale - TWC Mechanic	2.50	35,270HRS: Install steel tubes for bowl lift circuit, i new hose. Fit new primer pump to rear motor
19/02/2015	Knapman, Kenneth - TWC MECHANIC	1.00	35,170HRS: Braze holes in pipe.
19/02/2015	Knapman, Kenneth - TWC MECHANIC	2.50	Fit hyd. tubes & hose.
26/02/2015	Knapman, Kenneth - TWC MECHANIC	2.00	35,233HRS: Replace seat valve & adjust. carry out 250hr service. Regas cushion hitch
26/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,250HRS: Service
02/03/2015	Knapman, Kenneth - TWC MECHANIC	1.00	35,233HRS: Replace seat valve & adjust. carry out 250hr service. Regas cushion hitch
02/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	35,250HRS: Service
05/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.25	Blow out radiators. / R & R apron hose - test run. Remove ejector hose & look up parts./ 35,362HRS:
07/03/2015	Dawson, Dale - TWC Mechanic	1.00	Make up hose for apron cylinder 1hr. / 35,332HRS: Collect hose from Westrac, make up hose assy.

Date	Name	Duration	Notes
07/03/2015	Dawson, Dale - TWC Mechanic	0.50	Remove blown hose on L/H side of draft arm. / Fit hose & guards to L/H side draft frame, fill oil.
07/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Blow out radiators. / R & R apron hose - test run. Remove ejector hose & look up parts./ 35,362HRS:
08/03/2015	Dawson, Dale - TWC Mechanic	1.50	Make up hose for apron cylinder 1hr. / 35,332HRS: Collect hose from Westrac, make up hose assy.
08/03/2015	Dawson, Dale - TWC Mechanic	1.00	Remove blown hose on L/H side of draft arm. / Fit hose & guards to L/H side draft frame, fill oil.
09/03/2015	Knapman, Kenneth - TWC MECHANIC	2.00	Disassemble hose for remanufacture. Purchase hose. Remake hose.
10/03/2015	Dawson, Dale - TWC Mechanic	0.50	Remove blown hose on L/H side of draft arm. / Fit hose & guards to L/H side draft frame, fill oil.
11/03/2015	Wilde, David - TWC WORKSHOP MANAGER	4.00	Blow out radiators. / R & R apron hose - test run. Remove ejector hose & look up parts./ 35,362HRS:
20/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.25	Blow out radiators. / 35,441HRS: chk over unit. / Remove bail cylinder for repair. Replace seal on
24/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Blow out radiators. / 35,441HRS: chk over unit. / Remove bail cylinder for repair. Replace seal on
25/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Blow out radiators. / 35,441HRS: chk over unit. / Remove bail cylinder for repair. Replace seal on
26/03/2015	Knapman, Kenneth - TWC MECHANIC	1.00	R & R cylinder bearings & spacers.
26/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Look up & pick up parts. Reassemble bail cylinder. / Refit fuel screen & bleed system. Refit bail c
27/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Look up & pick up parts. Reassemble bail cylinder. / Refit fuel screen & bleed system. Refit bail c
13/04/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	3,547HRS: Chk oil leak at goose neck. / 35,500HRS: Part service. Fill out SOS. R & R 2 hyd. pipes.
14/04/2015	Wilde, David - TWC WORKSHOP MANAGER	3.00	3,547HRS: Chk oil leak at goose neck. / 35,500HRS: Part service. Fill out SOS. R & R 2 hyd. pipes.
15/04/2015	Dawson, Dale - TWC Mechanic	0.50	Complete 250hr service.
24/04/2015	Dawson, Dale - TWC Mechanic	1.00	Test high idle boost fuel pressure.
11/05/2015	Dawson, Dale - TWC Mechanic	1.00	R & R front half batteries. Repair cables. / 32,244HRS: Install fuel pump to rear motor - still har
12/05/2015	Dawson, Dale - TWC Mechanic	2.00	R & R front half batteries. Repair cables. / 32,244HRS: Install fuel pump to rear motor - still har
25/05/2015	Dawson, Dale - TWC Mechanic	1.00	R & R circuit breaker for ignition power.
15/06/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	35,628HRS: Chk steering movement & look up & order parts. Chk for leaks.
16/06/2015	Knapman, Kenneth - TWC MECHANIC	3.50	Remove rear steering pins & bushes for replacement. Finish steering cylinder bush replacements, rep
16/06/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	35,628HRS: Chk laser operation. Chk wiring & replace control box bulbs.
25/06/2015	Knapman, Kenneth - TWC MECHANIC	2.00	R & R a/c blower fan motor.
06/07/2015	Dawson, Dale - TWC Mechanic	2.50	Remove fuel pump from rear engine for install into rear eng. of #279
07/07/2015	Dawson, Dale - TWC Mechanic	1.50	Remove fuel pump from rear engine for install into rear eng. of #279
06/08/2015	Dawson, Dale - TWC Mechanic	3.00	Install rear engine fuel pump.
07/08/2015	Dawson, Dale - TWC Mechanic	3.50	Finalise intall of rear eng. fuel pump. Investigate starting trouble with Aaron from Diesel Gas. Fa
10/08/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	Prestart. Chk & adjust tyre pressures. Chk & adjust brakes.
11/08/2015	Knapman, Kenneth - TWC MECHANIC	3.00	Build up system air to release brakes & chk air system for leak/pressure loss. Move machine to shed
12/08/2015	Dawson, Dale - TWC Mechanic	3.00	Remove seat, repair leak in shock absorber & replace.
12/08/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Remove hyd. cushion hitch cylinder for replacement in seat.
12/08/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	Clean out & wash rear radiator.
26/08/2015	Knapman, Kenneth - TWC MECHANIC	2.00	Chk over machine fluids & tyre pressures. Top up rear diff oil. Adjust tyre pressures.
31/08/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit laser receiver. Chk & repair electrical short.
01/09/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	35,636HRS: Repairs to rear eng. wiring.
02/09/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk radio speakers. Travel to Narromine & collect parts. Return to site.
03/09/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,654HRS: R & R radio speakers.
05/09/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & repair wiring to raer E stop.
12/09/2015	Dawson, Dale - TWC Mechanic	1.50	Remove apron pin, remoce broken bolt retaining the pin, repaired locator lug at site w/shop, refit
13/09/2015	Dawson, Dale - TWC Mechanic	1.50	Investigate electrical fault with rear eng. at starting system - blowing circuit breaker - remove r
14/09/2015	Dawson, Dale - TWC Mechanic	1.00	Chk over unit & clean out radiator.
22/09/2015	Dawson, Dale - TWC Mechanic	1.50	Complete 250hr service.
29/09/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Trans repair advice over phone.
29/09/2015	Dawson, Dale - TWC Mechanic	3.00	Fit bowl tynes to cutting edge, fit new relays for E stop, investigate transmission shift fault. Tr
30/09/2015	Dawson, Dale - TWC Mechanic	4.50	Investigate rear transmission fault - not going down gears from when upshifting - test all componen
02/10/2015	Dawson, Dale - TWC Mechanic	1.00	Inspect eng. oil leak around fuel pump - minor leak under pumo.
09/10/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove rear shut off solenoid & test run.
15/10/2015	Wilde, David - TWC WORKSHOP MANAGER	0.25	35,881HRS: Adjust rear eng. idle speed.
30/10/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,941HRS: Chk hyd. oil leak & repalce seals. Test run.
30/11/2015	Dawson, Dale - TWC Mechanic	4.50	Wash machine ready for repairs in w/shop.
01/12/2015	Dawson, Dale - TWC Mechanic	6.50	Move machine into w/shop, remove 'H' link assy from Queen/King posts for repair to crack in Queen p
01/12/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,981HRS: Fit into w/shop. Remove belly guard, remove top hitch pin.
02/12/2015	Dawson, Dale - TWC Mechanic	2.00	Clean down fuel pump, reseal governor shaft, stop shaft etc, clean top of block fuel pump mounting

Date	Name	Duration	Notes
03/12/2015	Dawson, Dale - TWC Mechanic	6.00	Install fuel pump to front motor & commence 2,000hr service.
04/12/2015	Dawson, Dale - TWC Mechanic	1.00	Complete 2,000hr service.
07/12/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	36,000HRS: Part service.
08/12/2015	Knapman, Kenneth - TWC MECHANIC	7.00	Set up gear to repair cracked Queen post. Gouge out crack & prep for welding. Preheat & weld crack.
09/12/2015	Dawson, Dale - TWC Mechanic	1.00	Partially complete 2,000hr service.
10/12/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Remove remaining top bush in Queen Post.
10/12/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	35,981HRS: Remove grease lines & load cylinder & bush. Part service.
11/12/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Grind back & weld protrusion on Queen Post. Assist locate Queen Post/H link pin to insert.
11/12/2015	Wilde, David - TWC WORKSHOP MANAGER	5.25	35,981HRS: Refit bushes & assemble hitch. Replace H link shim, part service.
11/12/2015	Dawson, Dale - TWC Mechanic	1.50	Assembly of hitch. 2,000hr service, fit drain hose to rear eng.
16/12/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Assist with service. Inspect cracks in chassis under power pack.
17/12/2015	Knapman, Kenneth - TWC MECHANIC	5.00	Set up gear & gouge cracks in chassis. prep & weld cross member bracket.
17/12/2015	Wilde, David - TWC WORKSHOP MANAGER	3.50	Remove rear diff & shift hoses. Look up & order parts.
18/12/2015	Knapman, Kenneth - TWC MECHANIC	6.00	Continue with welding cracks as required & pack up gear.
05/01/2016	Dawson, Dale - TWC Mechanic	1.00	Commence removal of apron cylinder.
05/01/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Assist with diff reinstall.
05/01/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	36,000Hrs - part service. Fill out SOS's. Clean parts & reassemble rear diff to machine.
06/01/2016	Dawson, Dale - TWC Mechanic	4.50	Remove apron cylinder assy, strip down , clean & inspect. Reseal head & piston. More seals & bush
06/01/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Set up gear, gouge & weld crack in ejector door. Weld ejector door, gouge & weld crack in scraper c
06/01/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Refit rear diff to machine. Look up & order parts.
07/01/2016	Dawson, Dale - TWC Mechanic	7.50	Re- assemble apron cylinder, fit to machine, plumb hydraulics & test operation. Remove oil from fro
07/01/2016	Knapman, Kenneth - TWC MECHANIC	5.00	35,981HRS: Grind out crack, heat & weld steering cylinder. Fit apron cylinder, fill rear trans, cle
08/01/2016	Dawson, Dale - TWC Mechanic	5.50	Clean & fit ass. front left hub wheel end. Remove exhaust, inspect & order parts as required. Fill
21/01/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk a/c operation & test for leaks.
22/01/2016	Dawson, Dale - TWC Mechanic	1.00	Investigate fault with a/c - founs compressor shaft seal is U/S - compressor to be replaced.
03/02/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Remove eng. bay guards.
04/02/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Disconnect a/c belt & remove compressor & receiver/drier.
05/02/2016	Dawson, Dale - TWC Mechanic	2.50	Investigate oil leak - located on governor housing of fuel pump. Remove governor housing, air/fuel
08/02/2016	Dawson, Dale - TWC Mechanic	4.00	Fit new a/c compressor & receiver/dryer. Fit guages & vac down & recharge with R134A.
09/02/2016	Wilde, David - TWC WORKSHOP MANAGER	5.00	Chk a/c operation. Remove covers & clean out evaporators. Remove gas & chk evaporators.
15/02/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to a/c system.
17/02/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to a/c system.
18/02/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit bonnets & guards.
18/03/2016	Dawson, Dale - TWC Mechanic	3.00	Reseal ejector ram.
22/03/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Source & order seat parts. Purchase round bar & shape door stop support.
23/03/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Finish manufacture of door stay & fit to cab. Remove push pad, gouge crackedweld of bearing ball, w
04/04/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Chk fluid levels.
04/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & run a/c system.
17/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Grease brakes & adjust rear fan belts.
19/05/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Investigate front trans shift fault - replace gear lever sensor, test run.
31/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart.
15/06/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Load new tyres into side tipper for transport to machine/jobsite.
28/06/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace rear isolator, chk trans fault - replace gear shift card & test run.
29/06/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean mud from mudguards.
30/06/2016	Wilde, David - TWC WORKSHOP MANAGER	3.50	Chk brake fault. Clean mud from wheels.
28/07/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adjust tyre pressures
09/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk electrical fault.
12/08/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk air leaks & replace 2 rear boosters. Adjust brakes, part service.
14/08/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	36,250HRS: Complete service.
23/08/2016	Dawson, Dale - TWC Mechanic	0.50	Repair failed auto grease system.
23/08/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Chk injectors on rear engine.
24/08/2016	Dawson, Dale - TWC Mechanic	8.50	Remove blown hyd. hose, travel to Griffith then Albury to have replacement hose made, return to job
25/08/2016	Dawson, Dale - TWC Mechanic	1.50	Fit trash rack to machine. R & R upper apron control ball joint.
28/08/2016	Dawson, Dale - TWC Mechanic	1.00	Chk over machine, repair bolts in guard- found lift cylinder bush damaged on R/H side.

Date	Name	Duration	Notes
29/08/2016	Dawson, Dale - TWC Mechanic	3.50	Remove blown hyd. hose from under machine cab, install new hose to steer valve. R & R R/H/S lift ra
07/09/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Dismantle 2 brake boosters & inspect. Look up & order parts. Assemble 1 booster & test operation.
13/09/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Reassemble brake booster & test.
19/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & run a/c system.
21/10/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Replace push pad buffer.
27/10/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Recondition spare push pad rod.
27/10/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk & clean rear trans connectors & test run. Chk hyd. leak & order hoses.
28/10/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	36,398HRS: Chk into electrical fault - replace shift card & harness. Refit a/c belt & test run.
29/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	R & R rear start switch.
30/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Refit a/c belt.
31/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace a/c belt.
01/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Refit apron pin.
02/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Clean out rear radiator.
03/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace a/c belt & tighten clutch bolts.
06/11/2016	Dawson, Dale - TWC Mechanic	4.50	Investigate a/c fault - found compressor unbalanced, evac down, R & R compressor & dryer, charge a/
08/11/2016	Dawson, Dale - TWC Mechanic	9.00	36,500HRS: Inspect damaged roller on ejector door, remove roller & organise parts. Complete 500Hr s
09/11/2016	Dawson, Dale - TWC Mechanic	1.50	Install new rollers to ejector door, fit new fan belts.
15/11/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Make replacement hyd. hose.
16/11/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Make replacement hyd. hose.
17/11/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Replace ejector door guide roller & adjust door height.
19/11/2016	Knapman, Kenneth - TWC MECHANIC	5.50	Commence unbolting power pack for removal. Travel to Griffith for parts & return to jobsite 2.5hrs,
22/11/2016	Knapman, Kenneth - TWC MECHANIC	9.50	Wash power pack & unload off trailer in w/shop. Drain trans. fluids. Separate transmission from pow
22/11/2016	Wilde, David - TWC WORKSHOP MANAGER	5.50	Dismantle rear trans & inspect. Look up & order parts.
23/11/2016	Knapman, Kenneth - TWC MECHANIC	6.50	Disassemble transmission, chk torque converter for re-usable status. Disassemble, clean & reassembl
23/11/2016	Wilde, David - TWC WORKSHOP MANAGER	6.50	Dismantle rear trans & inspect. Look up & order parts.
25/11/2016	Knapman, Kenneth - TWC MECHANIC	4.50	Measure converter components for comparison to new parts. Disassemble, clean & chk components for c
26/11/2016	Knapman, Kenneth - TWC MECHANIC	9.00	Disassemble transmission valve assemblies to measure springs. Collect parts from supplier, measure
28/11/2016	Knapman, Kenneth - TWC MECHANIC	9.50	Assemble deep box linkages & driveline output gears. replace bearings & seals. Disassemble compone
28/11/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to rear trans.
29/11/2016	Knapman, Kenneth - TWC MECHANIC	6.00	Assemble convertor, repair sight glass post on trans. tank cover plate.
29/11/2016	Wilde, David - TWC WORKSHOP MANAGER	3.50	Repairs to rear trans. & clean up parts.
30/11/2016	Knapman, Kenneth - TWC MECHANIC	5.00	Clean components & reassemble convertor. Reassemble transmission planetary.
30/11/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Assemble hyd. tank & chk off parts.
01/12/2016	Knapman, Kenneth - TWC MECHANIC	7.50	Assemble transmission.
01/12/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Assemble rear trans. Replace rear circuit breaker & chk wiring.
02/12/2016	Knapman, Kenneth - TWC MECHANIC	9.00	Assemble transmission.
03/12/2016	Knapman, Kenneth - TWC MECHANIC	9.50	Assemble trans & fit to housing, bolt to engine frame, begin replacing hoses & components.
07/12/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Fit hoses & pipes to transmission. pack up equipment.
08/12/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Begin harness replacement on power pack.
16/12/2016	Dawson, Dale - TWC Mechanic	4.00	Remove radiator core & deliver to repairer for cleaning.
20/12/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Re-assemble radiator to power pack.
20/12/2016	Wilde, David - TWC WORKSHOP MANAGER	6.50	Collect radiator cores & re-assemble radiator & guards. Fit clamps to harness.
04/01/2017	Dawson, Dale - TWC Mechanic	1.00	Fit control panel to power pack.
06/01/2017	Dawson, Dale - TWC Mechanic	3.00	Remove #239 power pack & install in #278
06/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove rear eng. & refit #278 power pack.
07/01/2017	Dawson, Dale - TWC Mechanic	0.50	Set up for transmission pressure testing.
07/01/2017	Knapman, Kenneth - TWC MECHANIC	6.50	Pressure test rear trans., assemble corners & pack up gear.
07/01/2017	Wilde, David - TWC WORKSHOP MANAGER	6.50	Pressure test rear trans. Refit axles. Top up oil & test.
09/01/2017	Wilde, David - TWC WORKSHOP MANAGER	6.50	Remove & refit rear eng.
11/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit power pack & fit bonnets.
12/01/2017	Knapman, Kenneth - TWC MECHANIC	10.50	Clean paint off new guides & locate on machine. Weld guides in place, Set up & gouge off L/H lower g
13/01/2017	Knapman, Kenneth - TWC MECHANIC	10.00	Prep weld surfaces. Prep & weld L/H guide rail. prepare & weld channel rail in place.
14/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Unload rear power pack. Remove L/H rear mudguard & radiator guard.
14/01/2017	Bell, Daniel - TWC Manager	10.00	Transport power pack Moree to Griffith.

Date	Name	Duration	Notes
14/01/2017	Knapman, Kenneth - TWC MECHANIC	7.00	Weld ejec tor guides & finish welding guide rails. Move machine out of & back into shed. Gouge off
15/01/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	36,529HRS: Complet service. Adjust alternator belt. Refit power pack, replace HMU - test run.
15/01/2017	Bell, Daniel - TWC Manager	10.00	Transport power pack Moree to Griffith.
15/01/2017	Knapman, Kenneth - TWC MECHANIC	8.50	Weld in ejector door guide rail. Gouge & weld cracks on side rails of engine bay. Fit power pack.
16/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove hyd. hoses.
18/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Prestart, test run rear trans., chk over & grease.
18/01/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Replace converter drain hose (again). fill with oil.
28/03/2017	Wilde, David - TWC WORKSHOP MANAGER	6.00	Chk tyre pressures & hitch acc. Replace hitch pump gasket. remove rear radiator seal.
29/03/2017	Wilde, David - TWC WORKSHOP MANAGER	6.00	Refit rear air tank & fittings. Refit rear eng. front seal & radiator. Clean out a/c system. Replac
31/03/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove tynes & set up laser receiver.
01/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	36,600HRS: Prestart, grease brake & bail points. Blow out radiator. Fuel up.
02/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart & fit tynes.
04/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & blow out radiator.
05/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
06/04/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Source/correlate part No. for hose.
09/04/2017	Dawson, Dale - TWC Mechanic	1.00	R & R apron hose.
13/04/2017	Knapman, Kenneth - TWC MECHANIC	2.50	Repair hyd. hoses.
13/04/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Make up hyd. hoses.
19/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	36,733HRS: Prestart.
20/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
20/04/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	36,750hrs service, fill out SOS
22/04/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	Replace hyd. hoses. Reseal rear starter motor. Chk auto grease system lines. Chk & charge hitch acc
23/04/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	Prestart & replace hyd. hose. Chk rear trans control & hyd pressures. Test run.
24/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
27/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace grease line & pump end & canister.
03/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
04/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
05/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
06/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
08/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
09/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
10/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
10/05/2017	Dawson, Dale - TWC Mechanic	1.00	Reseal trans. housing - leak from bottom.
13/05/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Replace bowl lever rod end. Remove & make up hyd. hose & refit.
28/05/2017	Dawson, Dale - TWC Mechanic	4.50	37,000HRS: Complete 1,000hr service - change all filters, power train oils etc as per dealer specs.
01/06/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Clean & repair battery terminal for rear eng. Start machine.
05/06/2017	Knapman, Kenneth - TWC MECHANIC	2.50	Set up machine for eng. oil services. Drain & replace eng. oil & filters. Clean up.
07/06/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Trace oil leak.
08/06/2017	Knapman, Kenneth - TWC MECHANIC	8.50	Weld cracked ejector cylinder. Reassemble components & lines etc.
09/06/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Top up hydraulics.
18/06/2017	Dawson, Dale - TWC Mechanic	6.50	37,108HRS: Remove ejector door cylinder, strip down & reseal. Re-install cylinder, steel pipes, hos
20/06/2017	Dawson, Dale - TWC Mechanic	3.00	Remove teeth, remove trash rake, lower apron door. Repair E stop fault with rear eng. & assist remo
27/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit laser frame & remove tynes.
28/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean grease fron hitch.
29/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit tynes.
03/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.50	Remove broken cab glass. Replace hitch cyl. seals. Look up & order parts. Replace priming pump.
05/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace cab glass. Replace steering cyl. mount. Replace seat back.
16/07/2017	Knapman, Kenneth - TWC MECHANIC	4.50	Investigate & repair brake release problem. Replace brake booster L/H side.
17/07/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Replace 2 hyd. hoses on hitch.
18/07/2017	Knapman, Kenneth - TWC MECHANIC	1.50	37,250HRS: Service, change fuel & oil filters. Service front engine.
19/07/2017	Knapman, Kenneth - TWC MECHANIC	0.75	Finish service.
22/07/2017	Dawson, Dale - TWC Mechanic	1.50	Investigate front eng. under power/cutting out issue. Found fuel had frozen & blocked off delivery
26/07/2017	Dawson, Dale - TWC Mechanic	2.00	Install 2 new rollers on ejector door & adjust.
27/07/2017	Dawson, Dale - TWC Mechanic	2.00	R & R hyd. hose on hitch from valve to tank.

Date	Name	Duration	Notes
31/07/2017	Dawson, Dale - TWC Mechanic	1.00	Strip down ejector roller, clean & inspect.
09/08/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	37,336HRS: Fit tynes. Adjust rear fan belts & replace solenoid. Adjust tyre pressures.
10/08/2017	Dawson, Dale - TWC Mechanic	1.00	Strip down brake booster.
15/08/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean grease from hitch.
17/08/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	37,366HRS: Prestart, wash hitch.
23/08/2017	Dawson, Dale - TWC Mechanic	1.00	R & R cutting edge.
23/08/2017	Dawson, Dale - TWC Mechanic	3.00	Remove fuel pump from #228 rear eng. & install to #278
24/08/2017	Dawson, Dale - TWC Mechanic	5.50	Finnish removal of fuel pump from #228 & install to rear eng.
28/08/2017	Dawson, Dale - TWC Mechanic	1.00	Investigate starting failure - found fuel frozen in lines.
30/08/2017	Dawson, Dale - TWC Mechanic	2.50	Measure up auto grease hoses for replacement. Remove hoses from auto greaser & make up new ones & f
01/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	37,425HRS: Replace ejector hose & chk exhaust leak.
02/09/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Make up ejector hose. Chk & clean out steering valve drive.
04/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk hyd. leaks & look up parts.
05/09/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk rear brake fault. Look up & order parts. Chk rear guard damage. Repair batteries
06/09/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove bonnet & guards. Repair exhaust leaks. Replace coolant hoses. Refit bonnets & test run. Part
07/09/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	37,500HRS: Part service, fill out SOS.
14/09/2017	Dawson, Dale - TWC Mechanic	0.50	Adjust rear R/H brake - sticking.
15/09/2017	Dawson, Dale - TWC Mechanic	5.00	Remove steering column, rebush & refit - 2.5hrs. Start removal of turbo tubes from manifold to turb
16/09/2017	Dawson, Dale - TWC Mechanic	2.50	Finish install of exhaust manifold to turbo - 1.5hrs. Investigate rear eng. start failure - found b
17/09/2017	Dawson, Dale - TWC Mechanic	1.00	Investigate hyd. oil leak - found control valve leaking.
14/11/2017	Dawson, Dale - TWC Mechanic	2.00	Remove power pack & wash down. remove ejector door.
14/11/2017	Knapman, Kenneth - TWC MECHANIC	8.00	Remove power pack, ejector door, laser frame & cat walk.
14/11/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove laser frame, trash rack & ejector door.
15/11/2017	Dawson, Dale - TWC Mechanic	7.00	Remove ejector cylinder. Wash rear of machine. Inspect for & mark cracks for repair. Remove belly g
15/11/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Acquire steel & commence welding repairs to ejector door.
16/11/2017	Dawson, Dale - TWC Mechanic	4.00	Wash machine. Commence fixing oil leaks in rear power pack.
16/11/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Weld repairs to ejector door. Locate machine into shed & commence removal/disconnection of air line
16/11/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Assist with repairs to bowl.
17/11/2017	Dawson, Dale - TWC Mechanic	4.00	Continue fixing rear power pack oil leaks. Reseal front starter motor.
17/11/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Weld repairs to chassis crossmembers.
20/11/2017	Dawson, Dale - TWC Mechanic	9.50	Install braking air system to rear of machine. Fit hyd. ejector cylinder & hyd. hoses. Refit rear p
20/11/2017	Wilde, David - TWC WORKSHOP MANAGER	6.50	Refit rear diff & ejector ram. Refit rear eng.
21/11/2017	Dawson, Dale - TWC Mechanic	9.50	Fit hydraulics to rear of ejector cylinder system. Finalise install of rear power pack. Fit axles t
21/11/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Look up & order parts & pick up parts.
21/11/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Weld repair to draft arm guard - straighten guard to fit. Drill trash rack mount & bowl trash rack
22/11/2017	Dawson, Dale - TWC Mechanic	3.50	Remove diesel from tank, reseal fittings on fuel guage, replace diesel. Set up machine to refit eye
22/11/2017	Knapman, Kenneth - TWC MECHANIC	5.00	Drain fuel tank to remove guage. Make alterations to laser frame. Disconnect fuel bleed line & repl
23/11/2017	Dawson, Dale - TWC Mechanic	2.50	Remove auto greaser unit, strip down & reseal. Fit trash rack.
23/11/2017	Knapman, Kenneth - TWC MECHANIC	9.00	Weld locator plates to laser frame. Cut ejector door sides to accommodate bowl taper. R & R bowl we
24/11/2017	Knapman, Kenneth - TWC MECHANIC	4.50	Remove exhaust & replace assy.
25/11/2017	Dawson, Dale - TWC Mechanic	1.50	Fit trans cooler hoses etc.
25/11/2017	Knapman, Kenneth - TWC MECHANIC	6.50	Remove & tap trans. shift card cover plate bolts & replace. replace guard bolts. Paint & fit guards
30/11/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R alternator belt & fit belly guards.
05/12/2017	Dawson, Dale - TWC Mechanic	3.50	Remove l/h side bowl lift cylinder, strip down & inspect. Remove apron valve from inside bowl draft
06/12/2017	Dawson, Dale - TWC Mechanic	6.50	Reseal apron valve/assy & fit to machine. Remove R/H side apron cylinder & disassemble. Clean & ins
06/12/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repairs to hyd. cylinders.
07/12/2017	Dawson, Dale - TWC Mechanic	1.00	Remove bushes from bowl lift cylinder rods etc.
07/12/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Commence repairs to scraper guard rail.
09/12/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Unload bowl cylinders.
11/12/2017	Dawson, Dale - TWC Mechanic	5.50	Strip down hydraulic cylinders (2nd hand), inspect clean & reseal assy & fit to machine.
13/12/2017	Dawson, Dale - TWC Mechanic	5.00	Fit hand rails, chk & adjust suspension accumulators. Touch up unpainted areas, evac a/c system, re
14/12/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Load onto float & secure.
18/12/2017	Dawson, Dale - TWC Mechanic	1.00	R & R trigger switch in cab joystick for apron control. Repair switch wiring.
08/01/2018	Dawson, Dale - TWC Mechanic	0.50	Chk over machine tyres & v belts etc.

Date	Name	Duration	Notes
22/01/2018	Knapman, Kenneth - TWC MECHANIC	4.50	Move machine to clients workshop & evac a/c . Replace TX valve, thermostat & hoses. Clean evaporato
22/01/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	Discharge a/c system. Replace TX valve, drier, condensor & hoses. Recharge system & chk pressures.
24/01/2018	Knapman, Kenneth - TWC MECHANIC	1.00	37,794HRS: Fit guards, tighten a/c compressor mounts & tension belt.
24/01/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	37,794HRS: R & R a/c compressor. Evac & recharge. Test run. Refit guards.
25/01/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	37,750HRS: Service. Replace screw on bowl handle. Replace door striker.
29/01/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Dig out cutting edge to fit tynes.
31/01/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Fit control valve cover seals.
01/02/2018	Knapman, Kenneth - TWC MECHANIC	4.50	37,850HRS: Replace control valve spool caps. Replace seat height adjuster valve. Repalce door latch
05/02/2018	Dawson, Dale - TWC Mechanic	4.50	R & R rear transfer pumpfor fuel system. Remove 3 leaking radiator cores.
06/02/2018	Dawson, Dale - TWC Mechanic	0.50	R & R diff oil.
08/02/2018	Dawson, Dale - TWC Mechanic	6.00	Install rear radiator assy, guards, panels & wiring etc. Refill coolant & test run. Clean out front
08/02/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Rebuild scavenger pump.
08/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Collect parts & repair pump.
09/02/2018	Dawson, Dale - TWC Mechanic	2.50	Install scavenger pump, refit hoses & guards etc. Test operation - o/k.
09/02/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Reseal scavenger pump.
10/02/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Unload from float. Fit laser receiver. Test run & chk over.
14/02/2018	Dawson, Dale - TWC Mechanic	3.50	Locate oil leak - travel & pick up parts & return to site. R & R hyd. hose in articulation.
16/02/2018	Dawson, Dale - TWC Mechanic	1.00	Strip down hyd. hose for rebuild.
19/02/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	37,966HRS: Blow out rear radiator & air filter.
21/02/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Reassemble scavenger [ump.
23/02/2018	Wilde, David - TWC WORKSHOP MANAGER	5.50	38,000HRS: Part service.
27/02/2018	Dawson, Dale - TWC Mechanic	1.00	37,972HRS: Chk over machine & test operation.
02/03/2018	Dawson, Dale - TWC Mechanic	2.50	Finalise 2,000hr service, fit seat control valve & set height control.
10/03/2018	Knapman, Kenneth - TWC MECHANIC	1.75	Replace rear engine exhaust & prestart.
13/03/2018	Dawson, Dale - TWC Mechanic	1.50	R & R seat valve, clean cab of oil etc.
15/03/2018	Dawson, Dale - TWC Mechanic	2.50	R & R complete seat base. Clean cab of oil resulting from new Cat. seat valve failure.
17/03/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Disassemble seat for reconditioning.
20/03/2018	Dawson, Dale - TWC Mechanic	1.00	Investigate/repair hyd. faul in driver seat.
22/03/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Repair muffler.
26/03/2018	Dawson, Dale - TWC Mechanic	0.50	Repair throttle lock button.
27/03/2018	Dawson, Dale - TWC Mechanic	1.00	Fit new tie rod ball joint to hyd. blade control.
24/04/2018	Wilde, David - TWC WORKSHOP MANAGER	2.25	R & R seat valve. Clean oil from cab & wash floor mat.
26/04/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	38250 hour service/hitch repairs
01/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	38250 hour service/hitch repairs
02/05/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	38250 hour service/hitch repairs
03/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	38250 hour service/hitch repairs
08/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	38250 hour service/hitch repairs
09/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	38250 hour service/hitch repairs
18/05/2018	Dawson, Dale - TWC Mechanic	1.50	38,276HRS: Chk over scraper for leaks & repair prio to wash down.
21/05/2018	Dawson, Dale - TWC Mechanic	1.00	38,276HRS: Inspect & clear blocked grease system.
23/05/2018	Dawson, Dale - TWC Mechanic	4.00	Effect repairs; engine oil leak - rear engine. R & R leaking air hose. Refit belly guards.
24/05/2018	Dawson, Dale - TWC Mechanic	5.00	Fit guards/belly plates. Pressure test hydraulice, clean radiators, repair auto greaser, Remove & i
25/05/2018	Dawson, Dale - TWC Mechanic	1.00	Refit ejector speed reducer valve & refit guards.
29/05/2018	Wilde, David - TWC WORKSHOP MANAGER	5.00	Prestart, fuel & grease. part wash down.
06/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Shift apron pin.
12/06/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	38,341HRS: Replace seat damper. R & R rear fan bearings.
18/06/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	38,397HRS: Remove & replace Hyd. pipe under hitch - test run.
19/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	38,402HRS: Replace bolt & clamp at rear of hitch.
23/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	34,438HRS: prestart.
26/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	38,470HRS: Replace air drier cartridge.
28/06/2018	Dawson, Dale - TWC Mechanic	1.00	Strip down booster for inspection & reseal.
29/06/2018	Dawson, Dale - TWC Mechanic	2.50	38,500HRS: 500hr service, SOS & repair hyd. oil leak.
05/07/2018	Dawson, Dale - TWC Mechanic	1.00	Investigate & repair hyd. oil leak on control valve.
10/07/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	38,581HRS: Look up & order hoses. Remove & replace 4 hoses. Top up oil & test run.

Date	Name	Duration	Notes
12/07/2018	Dawson, Dale - TWC Mechanic	3.50	make up replacement hyd. hoses.
26/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Make up hyd. hose.
27/07/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	38,704HRS: R & R hyd. hose. prestart. Chk for leaks & chk rear fan belts.
03/08/2018	Dawson, Dale - TWC Mechanic	2.00	38,740HRS: 250hr service & chk over.
09/08/2018	Dawson, Dale - TWC Mechanic	1.50	38,755HRS: Investigate starting fault - found alternator U/S - removed alternator.
10/08/2018	Dawson, Dale - TWC Mechanic	3.50	Fit alternator, refit guards & belly plate(s). Inspect & retension sump bolts. R & R front window.
10/08/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean up booster parts & assemble diaphragms.
13/08/2018	Dawson, Dale - TWC Mechanic	0.50	Cut open oil filters from front engine & inspect.
29/08/2018	Dawson, Dale - TWC Mechanic	1.50	Make up spare hyd. hoses.
07/09/2018	Dawson, Dale - TWC Mechanic	0.50	38,870HRS: Inspect eng. oil on fuel pump.
20/09/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Replace Navman Control box.
20/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	38,869HRS: Chk Navman operation.
24/09/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	38,869HRS: Remove hitch cylinder, part fuel pump.
24/09/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Remove cushion hitch cylinder rod.
25/09/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Assemble hitch cylinder rod assy.
25/09/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to hitch.
26/09/2018	Knapman, Kenneth - TWC MECHANIC	5.00	Replace air/fuel ratio assy. Replace hitch cylinder rod assy. Adjust brakes. R & R shaft seal on th
26/09/2018	Wilde, David - TWC WORKSHOP MANAGER	5.00	38,869HRS: Refit hitch cylinder. Reassemble fuel pump - test run. Adjust brakes & chk over.
27/09/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Meet up with Navman technician to resolve navman failure. Deliver machine to highwar ready for load
27/09/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair Navman & load onto float.
20/10/2018	Knapman, Kenneth - TWC MECHANIC	2.00	Replace hitch hyd. hose.
24/10/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Locate & repair brake sensor fault.
25/10/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Investigate air system fault - not building pressure - order replacement governor valve.
27/10/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Chk radio.
28/10/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Change hyd. & air filters, commence 1,000Hr service. Take SOS.
31/10/2018	Dawson, Dale - TWC Mechanic	2.00	39,027HRS: Engine oil change, change front trans. oil - part of 1,000hr service.
01/11/2018	Dawson, Dale - TWC Mechanic	2.00	39,027HRS: Finish 1,000hr service - R & R rear trans. oil. 39,035HRS: Modify & mount stereo housing
02/11/2018	Dawson, Dale - TWC Mechanic	1.00	39,034HRS: Instal ne music radio in cab.
04/11/2018	Dawson, Dale - TWC Mechanic	3.00	39,032HRS: R & R quick drop valve, reseal , fit new springs & poppet vales.
04/11/2018	Dawson, Dale - TWC Mechanic	1.50	39,033HRS: Test & adjust cushion hitch - nitrogen gas charge, inspect ejector door rollers for move
05/11/2018	Dawson, Dale - TWC Mechanic	5.50	39,043HRS: R & R air governor valve. Set pressure, repair coolant leak on radiator. Clean grease fr
08/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adjust rear fan belts. Chk ejector rollers.
08/11/2018	Dawson, Dale - TWC Mechanic	3.00	39,056HRS: R & R R/H front brake booster.
12/11/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	39,093HRS: Chk trans fault. Adjust rear throttle linkage. Remove blown tyre.
12/11/2018	Dawson, Dale - TWC Mechanic	3.00	39,092HRS: Investigate Trans. fault - repair trans. speed sensor. Remove blown left rear tyre from
13/11/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	39,100HRS: Replace blown rear tyre.
14/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	39,105HRS: Remove guard & wash out 2 radiators.
15/11/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Seat repair - refurbish sissor mechanism. Source parts.
21/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace rear throttle diaphragm. Test run.
26/03/2019	Wilde, David - TWC WORKSHOP MANAGER	9.50	Remove guards & wash down (weed & seed).
26/03/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Remove guards & wash down (weed & seed)
27/03/2019	Wilde, David - TWC WORKSHOP MANAGER	5.50	Continue wash down, refit guards, chk charging circuit & remove alternator.
28/03/2019	Wilde, David - TWC WORKSHOP MANAGER	5.50	Replace alternator & test run. Continue washdown & refit guards.
28/03/2019	Knapman, Kenneth - TWC MECHANIC	5.50	Replace alternator & test run. Wash down & refit guards.
29/03/2019	Wilde, David - TWC WORKSHOP MANAGER	6.00	Refit guards. Blow out filters. Check & drain oil from hitch accumulator & recharge. Chk & adjust t
29/03/2019	Knapman, Kenneth - TWC MECHANIC	6.00	Refit guards, blow out filters. Chk & drain oil from hitch accumulator & recharge. Chk & adjust tyr
02/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR. Fit bolts to cutting edge. Shift apron pin.
04/04/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove tynes.
10/04/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk grease system.
11/04/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace 2 way radio.
15/04/2019	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove & clean out grease valve. Replace hitch accumulator hose.
17/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	39,421HRS: Repair seat ram.
26/04/2019	Dawson, Dale - TWC Mechanic	1.00	39,454HRS: Investigate trans. shift fault - found damages front wiring harnes at speed sensor - rep
01/05/2019	Dawson, Dale - TWC Mechanic	1.00	29,500HRS: Carry out part 500hr service - engine oils .

Date	Name	Duration	Notes
02/05/2019	Dawson, Dale - TWC Mechanic	1.50	39,500HRS: Finalise 500hr service.
03/05/2019	Dawson, Dale - TWC Mechanic	0.50	R & R Auto grease injector piston No. 2.
07/05/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Repair & reassemble seat suspension.
07/05/2019	Dawson, Dale - TWC Mechanic	0.50	Adjust low idle on fuel pump.
08/05/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repair & reassemble seat suspension.
16/06/2019	Dawson, Dale - TWC Mechanic	3.00	R & R trans speed sensor & pressure test cooling system. Chk over unit.
17/06/2019	Dawson, Dale - TWC Mechanic	6.50	Remove rear power pack from unit. Remove coolant/water pump from engine. Chk over machine for faults
19/06/2019	Dawson, Dale - TWC Mechanic	2.50	39,577HRS: Refit rear power pack into machine following chassis repairs
20/06/2019	Dawson, Dale - TWC Mechanic	3.50	Install rear power pack components - driveshaft, guards, fuel lines etc.
25/06/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	39,578HRS: Refit temp sender & coolant. Turn routers. Replace seat cushion. Repair front wiper.
26/06/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart.
26/06/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace seat suspension.
30/06/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	39,611HRS: Replace front wiper motor & arm. Replace boot around bowl levers. Replace rear temp send
01/07/2019	Wilde, David - TWC WORKSHOP MANAGER	0.75	Chk apron operation. Look up & order parts.
02/07/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repairs to rear tyre.
03/07/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Change tyres.
04/07/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	39,619HRS: Replace apron solenoid. R & R rear brake booster.
08/07/2019	Dawson, Dale - TWC Mechanic	5.00	Chk, test, rebuild & retest 3 x brake boosters
10/07/2019	Dawson, Dale - TWC Mechanic	5.00	39,621HRS: Inspect hitch & pin for wear & movement - 1 pin bush heavily worn. Tighten & inspect all
12/07/2019	Dawson, Dale - TWC Mechanic	2.00	Investigate & repair auto greaser.
15/07/2019	Dawson, Dale - TWC Mechanic	1.00	Inspect charging system for batteries due to alternator light bein on.
16/07/2019	Dawson, Dale - TWC Mechanic	4.00	Refit belly guard, drill out broken bolts on belly guard mounts. Look up parts for repairs.
17/07/2019	Dawson, Dale - TWC Mechanic	1.50	Drill out remaining broken bolts for belly guard mounts.
19/07/2019	Dawson, Dale - TWC Mechanic	1.50	39,621HRS: Tap out bolt holes for belly plate, fit new bolts & washers.
20/07/2019	Dawson, Dale - TWC Mechanic	0.50	Refit apron control linkage to control lever.
21/07/2019	Dawson, Dale - TWC Mechanic	2.00	39,621HRS: Fit new Vee belts to rear eng. Chk over machine.
03/08/2019	Knapman, Kenneth - TWC MECHANIC	2.00	Replace cushion hitch seal.
04/08/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair wiring to alternator & test run.
04/08/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Fit engine guard. Repair alternator.
06/08/2019	Knapman, Kenneth - TWC MECHANIC	6.75	Weld repair draft arm.
07/08/2019	Knapman, Kenneth - TWC MECHANIC	4.25	Weld repair draft arm.
08/08/2019	Knapman, Kenneth - TWC MECHANIC	6.00	Replace isolation switch 1.5hrs. Replace steering lines 6.
13/08/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Prestart & chk tyre presures.
19/08/2019	Knapman, Kenneth - TWC MECHANIC	3.50	Remanufacture hoses.
22/08/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart.
29/08/2019	Knapman, Kenneth - TWC MECHANIC	0.25	Prestart
30/08/2019	Knapman, Kenneth - TWC MECHANIC	0.25	Prestart
01/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart, blow out rear air filter.
02/09/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Take SOS
03/09/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	39,750HRS: Part service & fill out SOS
04/09/2019	Knapman, Kenneth - TWC MECHANIC	1.00	39,730HRS: Service front & rear engines.
04/09/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	39,750HRS: Service.
11/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
13/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
18/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	39,813HRS: Prestart/FGR
17/10/2019	Dawson, Dale - TWC Mechanic	4.00	Remove engine bay guards & belly plates & start cleaning down machine ready for repair work.
18/10/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	39,855HRS: Work on repairs to hitch.
19/10/2019	Wilde, David - TWC WORKSHOP MANAGER	7.50	Remove tractor from bowl & remove hitch.
21/10/2019	Dawson, Dale - TWC Mechanic	3.25	Assist with removal of hitch and engine.
21/10/2019	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove hitch & dismantle.
22/10/2019	Dawson, Dale - TWC Mechanic	7.25	Remove engine from machine & wash down. Commence repairs - remove manifold studs & gaskets, oils et
22/10/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Inspect king & queen posts for cracks etc.
22/10/2019	Wilde, David - TWC WORKSHOP MANAGER	9.75	Dismantle hitch, remove bushes & clean up parts.
23/10/2019	Dawson, Dale - TWC Mechanic	5.00	Continue with disassembly of engine. Repair broken manifold studs. Complete engine valve set - part

Date	Name	Duration	Notes
23/10/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Inspect hitch mount for cracks.
23/10/2019	Wilde, David - TWC WORKSHOP MANAGER	6.00	Look up & order parts. Remove bushes from tractor & bowl.
25/10/2019	Knapman, Kenneth - TWC MECHANIC	10.00	Gouge & weld hitch components
25/10/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Repairs to hitch & steering. Chk off parts.
26/10/2019	Knapman, Kenneth - TWC MECHANIC	7.00	Gouge & weld hitch components
26/10/2019	Dawson, Dale - TWC Mechanic	2.00	Sort through pin bushes to send with hitch for machining. Load hitch onto trailer & secure fro tran
28/10/2019	Wilde, David - TWC WORKSHOP MANAGER	4.50	Load up parts and deliver to Goondwindi for repair. Return to w'shop.
29/10/2019	Wilde, David - TWC WORKSHOP MANAGER	5.50	Effect repairs to radiator & electrical wiring. Remove cracked glass. Look up & order parts.
30/10/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Replace cab door window. Look up & order parts & hoses.
01/11/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove steering cylinders & clean up parts.
05/11/2019	Dawson, Dale - TWC Mechanic	4.50	Refit exhaust manifold assy & heat shields.
05/11/2019	Wilde, David - TWC WORKSHOP MANAGER	3.50	Clean up parts & repairs to bowl.
06/11/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Clean up parts & repairs to bowl.
07/11/2019	Dawson, Dale - TWC Mechanic	4.00	39,855HRS: Reseal engine sump.
07/11/2019	Wilde, David - TWC WORKSHOP MANAGER	7.00	Clean parts, dismantle hitch cylinder & inspect. Assist with repairs to bowl.
08/11/2019	Dawson, Dale - TWC Mechanic	7.00	R & R water pump assy. Reseal coolant lines & galleries. R & R thermostats in cylinder heads. Insta
09/11/2019	Dawson, Dale - TWC Mechanic	6.50	Press bushes into frame. Rebuild hitch cylinder.
09/11/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Assemble radiator & repairs to bowl.
11/11/2019	Dawson, Dale - TWC Mechanic	3.00	39,855HRS: press bushes into frame & move tractor from shed.
12/11/2019	Dawson, Dale - TWC Mechanic	1.00	Press bushes into draft frame.
12/11/2019	Wilde, David - TWC WORKSHOP MANAGER	4.50	Clean up parts & fit bushes to bowl.
13/11/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	Repairs to steering rams.
15/11/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove wiring harness for repairs. Look up & order parts.
18/11/2019	Dawson, Dale - TWC Mechanic	3.00	Repair oil leaks, fan hub, brackets & mount.
20/11/2019	Dawson, Dale - TWC Mechanic	3.00	Clean parts - hoses, rams etc for repair. Reseal hyd. cylinders, wash down hitch for reassembly.
21/11/2019	Dawson, Dale - TWC Mechanic	4.50	Wash down hitch after machining completed. Test grease ports for servicability. prep hitch for painti
26/11/2019	Knapman, Kenneth - TWC MECHANIC	4.50	Prep area above transmission to access cracks for repair. Gouge & grind cracks ready for welding.
27/11/2019	Dawson, Dale - TWC Mechanic	1.00	Press bushes into hitch assy.
27/11/2019	Knapman, Kenneth - TWC MECHANIC	7.00	Weld cracks in cushion hitch saddle. Fit bushes to steering links of hitch.
27/11/2019	Wilde, David - TWC WORKSHOP MANAGER	3.50	Dismantle & reseal steering cylinder & refit 2 to machine.
28/11/2019	Dawson, Dale - TWC Mechanic	5.00	Prep hitch & paint. Fit steer links & pins. Buff out holes.
28/11/2019	Knapman, Kenneth - TWC MECHANIC	6.00	Grind back welds on saddle repair. pack up equipment. Replace bearings & seals in steering link.
29/11/2019	Wilde, David - TWC WORKSHOP MANAGER	5.50	Clean up parts & assemble hitch.
29/11/2019	Knapman, Kenneth - TWC MECHANIC	4.50	Fit steering links & pins. Fit cushion hitch components.
30/11/2019	Wilde, David - TWC WORKSHOP MANAGER	5.00	Clean up parts & assemble hitch.
30/11/2019	Dawson, Dale - TWC Mechanic	1.00	Commence removal of cab harness.
02/12/2019	Dawson, Dale - TWC Mechanic	3.00	Assemble hitch, remove accumulator, reseal & refit.
02/12/2019	Wilde, David - TWC WORKSHOP MANAGER	6.50	Assemble hitch & make up replacement hoses.
04/12/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Reman hyd. hoses as required.
04/12/2019	Wilde, David - TWC WORKSHOP MANAGER	5.50	Reman. hyd. hoses & fit greaselines
05/12/2019	Dawson, Dale - TWC Mechanic	1.50	Make up new hyd. hoses as required.
05/12/2019	Wilde, David - TWC WORKSHOP MANAGER	6.50	Assemble hitch & grease lines.
06/12/2019	Dawson, Dale - TWC Mechanic	1.50	Remove rear engine from machine.
06/12/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Reman. hyd hoses, remove tractor control valve & replace seals.
10/12/2019	Knapman, Kenneth - TWC MECHANIC	3.00	Order & collect spare parts, finish fitting seals to control valve.
11/12/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	Make up hoses.
12/12/2019	Wilde, David - TWC WORKSHOP MANAGER	5.50	Refit hitch & replace hoses.
12/12/2019	Knapman, Kenneth - TWC MECHANIC	5.50	Reman. hoses as required. Reseal & bush apron control valve on main control valve. Refit hyd. hoses
12/12/2019	Dawson, Dale - TWC Mechanic	6.00	Install hitch assy. remove cab harness.
13/12/2019	Knapman, Kenneth - TWC MECHANIC	2.50	Identify & remove hoses as required & replace others.
16/12/2019	Knapman, Kenneth - TWC MECHANIC	7.50	Refit hoses. Remove throttle lock rotochamber & replace diaphragm. Replace air valve. Order additio
16/12/2019	Dawson, Dale - TWC Mechanic	8.50	Remove cab machine harness & commence install new harness
16/12/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Make up replacement hyd. hoses.
17/12/2019	Dawson, Dale - TWC Mechanic	3.00	Fill Trans., clean air breathers on trans, test pressures, guel & grease machine.

Date	Name	Duration	Notes
17/12/2019	Knapman, Kenneth - TWC MECHANIC	5.00	Collect parts & continue reman. of hyd. hoses as required.
17/12/2019	Wilde, David - TWC WORKSHOP MANAGER	5.00	Make up replacement hyd. hoses.
18/12/2019	Knapman, Kenneth - TWC MECHANIC	7.50	Collect wiring harness from freight company. Commence fitment to tractor. Collect hoses from suppli
19/12/2019	Dawson, Dale - TWC Mechanic	1.50	Prestart/FGR. Drop belly guards & repair oil leak. Refit guards.
19/12/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Continue fitting harness. Pick up hoses. Fit main control valve & connect hoses.
19/12/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Make up hyd. hoses as required, refit/replace wiring harness.
20/12/2019	Knapman, Kenneth - TWC MECHANIC	7.00	Fit hydraulic line, collect hoses from supplier & order additional hoses.
06/01/2020	Dawson, Dale - TWC Mechanic	7.00	Instal wiring harness to cab. Repair harness retaining guards/brackets in cab.
06/01/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Fit hyd. lines, order & collect hoses/parts.
07/01/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Fit hyd. & lubrication lines. Order parts.
07/01/2020	Dawson, Dale - TWC Mechanic	6.50	Finish install of cab harness, refit all panels & trim covers etc. Install new gear stick harness &
08/01/2020	Dawson, Dale - TWC Mechanic	6.50	Assembly of rear engine - fit crank & measure bearing clearance - found too tight - removed crank
09/01/2020	Dawson, Dale - TWC Mechanic	8.50	Continue with assembly of rear engine.
09/01/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Replace trunions in fron engine. Replace threads - helicoil & keyserts.
09/01/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	39,855HRS: Refit engine.
10/01/2020	Dawson, Dale - TWC Mechanic	7.50	Continue with assembly of rear engine.
10/01/2020	Knapman, Kenneth - TWC MECHANIC	6.00	Fit engine into engine bay & torque down bolts.
13/01/2020	Knapman, Kenneth - TWC MECHANIC	9.50	Continue with front engine installation/plumbing of wiring & hoses etc.
13/01/2020	Wilde, David - TWC WORKSHOP MANAGER	5.50	Continue with refitting of eng./hoses etc.
14/01/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Continue with front engine installation/plumbing of wiring & hoses etc.
14/01/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Continue with refitting of eng./hoses. Remove hoses requiring replacement.
15/01/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Fit hyd. hoses, locate harness, fit engine breathers, fit fan hub.
15/01/2020	Wilde, David - TWC WORKSHOP MANAGER	5.50	Replace hyd. hoses.
16/01/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Secure harness & hydraulic lines in place. Fit a/c hoses, bonnet & grill. Refit radiator, fan & gua
16/01/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit radiator & guards.
17/01/2020	Knapman, Kenneth - TWC MECHANIC	9.50	Continue with rear engine rebuild - continue with electrical & fluids plumbing.
17/01/2020	Wilde, David - TWC WORKSHOP MANAGER	3.50	Refit radiator & guards.
20/01/2020	Knapman, Kenneth - TWC MECHANIC	3.00	Connect tractor unit to bowl.
20/01/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Connet tractor unit to bowl.
22/01/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	Connect hoses & start machine. Remove stands & frame. Clean up & test run. re-assemble rear radiato
23/01/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair to control valve.
28/01/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	Replace 2 hyd. hoses. Prime grease lines & fit. Fill hyd. system & test run machine.
29/01/2020	Dawson, Dale - TWC Mechanic	9.00	Investigate & locate oil leak on front engine - leaking from rear of cylinder block & bell housin
30/01/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit rear power pack.
30/01/2020	Dawson, Dale - TWC Mechanic	5.25	Install rear power pack into machine, plumb up hoses etc, fit drive shaft. Move bowl hoses to avoid
31/01/2020	Dawson, Dale - TWC Mechanic	7.00	R & R harness on draft frame. Locate & repair oil leaks - front eng. transfer pump leaking.
03/02/2020	Knapman, Kenneth - TWC MECHANIC	9.50	Fit bonnets & push pad to machine. Chk hyd. pressures. Refit guards on draft arms. Connect & locate s
03/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace rear trans hose & refit guards
05/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to a/c system & engine wiring.
06/02/2020	Knapman, Kenneth - TWC MECHANIC	5.50	Replace guards. Remove exhaust tube for repair. Re-route hoses.
06/02/2020	Wilde, David - TWC WORKSHOP MANAGER	5.00	clean parts fit belly guards, repair seat suspension, replace temperature gauge, repair exhaust leak
07/02/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Check and repair cabin and and headlight fault
11/02/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Refit 2 Headlights And Test
24/02/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Replace radiator cores.
25/02/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Fit scraper radiator cores & tank, refit hoses, fit water pump tubing to front eng., fit hoses.
28/02/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Gouge & weld up cracks in push pad.
04/03/2020	Knapman, Kenneth - TWC MECHANIC	6.00	Clean, reseal, rerace & reassemble throttle control. Fit coolant hoses & lines. Remove fuel lines c
05/03/2020	Knapman, Kenneth - TWC MECHANIC	6.00	Fit fuel ration control valve diaphragm. Replace fuel lines etc. Investigate electrical issue with
06/03/2020	Knapman, Kenneth - TWC MECHANIC	7.00	Remove broken bolt for hook cylinder mount. Replace injector pump seal, chk & set front eng. high i
09/03/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Drill out belly guard spacers.
10/03/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair E stops.
16/03/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair back-up alarm.
26/11/2020	Knapman, Kenneth - TWC MECHANIC	2.00	39,868HRS: Prestart, chk a/c & cushion hitch. Top up cushion hitch gas pressures.
04/12/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Fit cutting edge & tynes.

Date	Name	Duration	Notes
04/12/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	39,864HRS: Prestart/FGR - Chk all lights, change cutting edge & fit tynes, chk tyre pressures.
07/12/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Top up hyd. oil.
07/12/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	39,866HRS: Replace leaking seal & top up oil.
08/12/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	Chk & tighten hyd. hoses & repair seals in control valve.
09/12/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	Chk & test rear trans fault. Look up parts.
17/12/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk & test rear trans. hyd. pressures.
05/01/2021	Wilde, David - TWC WORKSHOP MANAGER	4.00	39958 hours shift from tip remove rh front wheel and bearings, order new seal
06/01/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	39958 hours shift from tip remove rh front wheel and bearings, order new seal
06/01/2021	Knapman, Kenneth - TWC MECHANIC	6.50	Clean & inspect. Remove cone seal, Replace and reassemble axle/retainer as per spec. fit to machine
07/01/2021	Wilde, David - TWC WORKSHOP MANAGER	6.00	39,958HRS: Remove R/H front wheel & clean up. Look up & order parts. Part 2,000hr service.
08/01/2021	Knapman, Kenneth - TWC MECHANIC	9.50	Replace L/H front brake shoes, fit new wheel bearings & cups & set shim pack.Re-assemble wheel, rem
08/01/2021	Wilde, David - TWC WORKSHOP MANAGER	4.50	Re-assemble final drive & brakes. Part 2,000hr service.
11/01/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	39,961HRS: Prestart & fuel up. Wash final drives. Chk & replace rear shift card. Test run.
11/01/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Investigate/locate electrical fault in power pack transmission & repair.
13/01/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	40,000HRS: Part service.
14/01/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Replace a/c thermostat.
16/01/2021	Knapman, Kenneth - TWC MECHANIC	1.00	40,000HRS: Service.
23/01/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Chk seat pipe hydraulic seal, replace seal, cap for a/c compressor, seal a/c unit.
23/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	40,048HRS: Reseal a/c box. Chk final drive plugs for metal.
01/02/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Remove seat kick panel to investigate hyd.leak. Replace panel. Source parts for repairs.
01/02/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	40,092HRS: Replace grease pump & test run.
04/02/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	40,114HRS: Reapirs to seat suspension mechanism.
04/02/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Change seat height master valve. Change out seat from #239 & install in this machine.
05/02/2021	Knapman, Kenneth - TWC MECHANIC	3.50	Repair hyd. seat. Replace valve & change over electronic seat from #239. Chk transmission oil pres
05/02/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	40,114HRS: R & R seat assy. Chk trans fault. Chk scavenger pump.
08/02/2021	Knapman, Kenneth - TWC MECHANIC	0.75	Travel to jobsite, drain & inspect trans. oil, top up & shift machine for loading.
08/02/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk trans screens. Load onto float & secure & escort to workshop.
09/02/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	Assemble diff lock & seat suspension.
15/02/2021	Knapman, Kenneth - TWC MECHANIC	7.50	36,066HRS: Repairs to seat assy. R & R seat. Chk & fill oils to levels.
15/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	40,120HRS: Part wash down & drain oil.
16/02/2021	Knapman, Kenneth - TWC MECHANIC	5.50	Drain oils. Remove PTO shaft & axles, transmission & diff.
16/02/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	Remove trans & diff assy.
17/02/2021	Knapman, Kenneth - TWC MECHANIC	10.00	40,120HRS: Disassemble transmission, torque converter etc.
18/02/2021	Knapman, Kenneth - TWC MECHANIC	10.00	Disassemble transmission components & inspect for re-use. Disassemble transfer case.
18/02/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	Repairs to trans. & order parts.
22/02/2021	Knapman, Kenneth - TWC MECHANIC	9.50	Disassemble diff & components. Clean transmission housing. Clean & re-assemble pumps for core charg
23/02/2021	Knapman, Kenneth - TWC MECHANIC	9.50	Clean & re-assemble diff lock, re-race diff. spider. Fit bearings to pinion. Commence pinion seal/b
24/02/2021	Knapman, Kenneth - TWC MECHANIC	10.00	Re-assemble diff. & set backlash. Clean components & commence transfer case assembly.
25/02/2021	Knapman, Kenneth - TWC MECHANIC	10.00	Re-assemble diff. Chk off parts for tfr case & torque converter. Commence assembly of the case.
26/02/2021	Knapman, Kenneth - TWC MECHANIC	10.00	Replace tfr case & set end float. Replace filter mount seals & filter after cleaning out metallfilin
01/03/2021	Wilde, David - TWC WORKSHOP MANAGER	4.00	Check rear engine for leaks and remove rear power pack
02/03/2021	Wilde, David - TWC WORKSHOP MANAGER	5.50	Continue removal rear power pack, repair oil and exhaust leaks
03/03/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Fit planetary bearings, washers & pins.
03/03/2021	Wilde, David - TWC WORKSHOP MANAGER	6.50	Repair rear eng. & trans oil leaks. Re-assemble radiator to frame, clean up trans. parts.
04/03/2021	Knapman, Kenneth - TWC MECHANIC	9.50	Continue rebuild: Assemble torque converter & begin assembly of transmission.
04/03/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	Re-assemble cooling system & refit power pack.
05/03/2021	Knapman, Kenneth - TWC MECHANIC	10.00	Re-assemble transmission.
05/03/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to transmission
08/03/2021	Knapman, Kenneth - TWC MECHANIC	7.50	Assemble No.4 Clutch, Remove Trans cover & Clean components for reassembly
08/03/2021	Wilde, David - TWC WORKSHOP MANAGER	5.00	Refit rear power pack. Replace relay valve. Remove front trans cooler & order parts.
09/03/2021	Knapman, Kenneth - TWC MECHANIC	9.50	Assemble transmission, Remove transmission cooler lines for cleaning, Remove old gaskets, Remove bo
09/03/2021	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove & clean out trans. cooler lines & pipes, refit. Clean out diff & trans. compartment.
10/03/2021	Knapman, Kenneth - TWC MECHANIC	8.50	Disassemble, clean & reassemble control valve segments.
11/03/2021	Knapman, Kenneth - TWC MECHANIC	9.50	Finish transmission clutch pack assembly & fit to housing & housing to stand. Disassemble, clean &

<u>Date</u>	<u>Name</u>	<u>Duration</u>	<u>Notes</u>
11/03/2021	Wilde, David - TWC WORKSHOP MANAGER	5.50	Reassemble radiator guards. Remove binnet & chk for exhaust leaks. Repairs to trans.
12/03/2021	Wilde, David - TWC WORKSHOP MANAGER	8.00	Repair exhaust leaks & refit guards. Refit trans oil cooler & guards.
15/03/2021	Wilde, David - TWC WORKSHOP MANAGER	5.50	Fill with coolant and pressure test system for leaks. Refit bonnets and repairs to engine bay door.
16/03/2021	Knapman, Kenneth - TWC MECHANIC	4.50	Check spring lengths of control valves. Check Shim packs. Replace plugs, orings
16/03/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to transmissin and look up /order parts as required
17/03/2021	Knapman, Kenneth - TWC MECHANIC	3.50	Replace springs in control valve. Repair bonnet latch. Collect parts.
17/03/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	Assist with repairs to bonnet & battery box lock downs. Remove batteries & place on charger.
18/03/2021	Knapman, Kenneth - TWC MECHANIC	7.50	Remove battery box cover skid plate & repair. Reseal trans. valve mount block & bolt on. Source tfr
19/03/2021	Wilde, David - TWC WORKSHOP MANAGER	4.00	Refit trans. & diff to machine.
19/03/2021	Knapman, Kenneth - TWC MECHANIC	7.00	Connect tfr case to trans. to diff to tractor. Connect implement/steering pumps. Connect hitch pump
22/03/2021	Knapman, Kenneth - TWC MECHANIC	5.50	Connect hitch, steering & implement pump lines & trans. cooler pipes. Connect steering cylinder. Te
25/03/2021	Knapman, Kenneth - TWC MECHANIC	7.50	Remove battery box cover skid plate & repair. Reseal trans. valve mount block & bolt on. Source tra
26/03/2021	Knapman, Kenneth - TWC MECHANIC	7.00	Connect transfer case to transmission to diff to tractor. Correct implement/steering pumps. Connect
06/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	Pre start and top up oil.. Check trans pressures
07/04/2021	Knapman, Kenneth - TWC MECHANIC	9.00	Set Transmission pressures
07/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	Pressure test trans and make adjustments
08/04/2021	Knapman, Kenneth - TWC MECHANIC	9.00	Set control valve pressures
08/04/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	Pressure test trans
09/04/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit axles and fill with oil. Test run
09/04/2021	Knapman, Kenneth - TWC MECHANIC	9.50	Set control valves. Replace final drives
12/04/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	Transmissions Tests
12/04/2021	Knapman, Kenneth - TWC MECHANIC	5.00	Move equipment to remove machine from Workshop. Torque connector pressure test. Check. Bleed valves
13/04/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Convertor pressure checks
14/04/2021	Knapman, Kenneth - TWC MECHANIC	4.50	Remove control valves & replace transmission control valve springs housing
22/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	Remove Trans
26/04/2021	Knapman, Kenneth - TWC MECHANIC	6.00	Disassemble transmission
27/04/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Disassemble Transmission
30/04/2021	Knapman, Kenneth - TWC MECHANIC	8.00	Disassemble then assemble transmission
01/05/2021	Knapman, Kenneth - TWC MECHANIC	7.00	Assemble transmission. Inspect Torque converter. Mount on strad and wrap. Fix on pallet for transpo
03/05/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Organise and load pallet (with transmission) to Tomago for testing.
04/05/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Pallet transfer case for transport to Tamago
07/06/2021	Knapman, Kenneth - TWC MECHANIC	7.00	Install transmission
07/06/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit trans to Machine
08/06/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Fill hydraulics & transmission.
10/06/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	Prestart & Test run. Top up oil levels
15/06/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Check and gas cushion hitch
22/06/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Fit belly guard
01/07/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	40,130Hrs. Refit grease unit and test run
Total 278 - CAT 637E Scraper:278E		<u>4,252.50</u>	
<b>TOTAL</b>		<b><u>4,252.50</u></b>	