

279 - CAT 637E Scraper:279E

Date	Name	Duration	Notes
22/03/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Look up & order parts
24/03/2011	Knapman, Kenneth - TWC MECHANIC	3.00	Repairs/maintenance
25/03/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Remove ejector door & rollers, refit rear power pack, look up & order parts./ Repair wiring, R & R
26/03/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove ejector door & rollers, refit rear power pack, look up & order parts./ Repair wiring, R & R
28/03/2011	Wilde, David - TWC WORKSHOP MANAGER	6.00	Remove ejector door & rollers, refit rear power pack, look up & order parts./ Repair wiring, R & R
29/03/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove ejector door & rollers, refit rear power pack, look up & order parts./ Repair wiring, R & R
30/03/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove ejector door & rollers, refit rear power pack, look up & order parts./ Repair wiring, R & R
31/03/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	Assemble ejector rollers & adjust, repairs to radiator./ Refit radiator.
04/04/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Assemble ejector rollers & adjust, repairs to radiator./ Refit radiator.
07/04/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Repairs/maintenance, cutting edges and laser frame
11/04/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Repairs/maintenance, cutting edges and laser frame
11/04/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	C&A hitch gases, replace cutting edges
12/04/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	C&A accumulator pressures, repairs to apron, fit cutting edges/tynes, remove draft arm guards, R&R
12/04/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Repairs/maintenance, cutting edges and laser frame
13/04/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	C&A accumulator pressures, repairs to apron, fit cutting edges/tynes, remove draft arm guards, R&R
13/04/2011	Knapman, Kenneth - TWC MECHANIC	8.50	Repairs/maintenance, cutting edges and laser frame
14/04/2011	Knapman, Kenneth - TWC MECHANIC	10.00	Fabricate laser frame for scraper
14/04/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit belly guards, Fab laser frame.
15/04/2011	Knapman, Kenneth - TWC MECHANIC	8.00	Fabricate laser frame for scraper
15/04/2011	Wilde, David - TWC WORKSHOP MANAGER	7.00	Fit belly guards, Fab laser frame.
18/04/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Fit belly guards, Fab laser frame.
19/04/2011	Knapman, Kenneth - TWC MECHANIC	4.00	Fabricate laser frame for scraper
19/04/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Fit belly guards, Fab laser frame.
20/04/2011	Knapman, Kenneth - TWC MECHANIC	2.50	Fabricate laser frame for scraper
20/04/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit belly guards, Fab laser frame.
21/04/2011	Wilde, David - TWC WORKSHOP MANAGER	7.00	Check rear trans electrical system, repair broken wiring./ R & R rear card harness, chk all oil lev
27/04/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Check rear trans electrical system, repair broken wiring./ R & R rear card harness, chk all oil lev
28/04/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Travel to Wathagar, refit drat arm guards, chk front trans. oil level & return to w'shop./Travel to
29/04/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	Travel to Wathagar, refit drat arm guards, chk front trans. oil level & return to w'shop./Travel to
30/04/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	Travel to Wathagar, refit drat arm guards, chk front trans. oil level & return to w'shop./Travel to
05/05/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	27454hrs: R & R rear battery./ Chk exhaust manifold leaks, order parts, return to w'shop.
06/05/2011	Wilde, David - TWC WORKSHOP MANAGER	1.75	27454hrs: R & R rear battery./ Chk exhaust manifold leaks, order parts, return to w'shop.
12/05/2011	Knapman, Kenneth - TWC MECHANIC	8.50	Repair steering pin, travel to keytah & fit to machine, remove grase line & replace with grease nip
14/05/2011	Wilde, David - TWC WORKSHOP MANAGER	4.75	27,522hrs: Remove tynes, 500hr service, replace 3 grease lines, unload waste oil at w'shop.
16/05/2011	Knapman, Kenneth - TWC MECHANIC	4.00	Prepare components & weld A/C door lug in place. Clear up gear, chk 2way for fault. Source bolts to
17/05/2011	Knapman, Kenneth - TWC MECHANIC	6.50	Repair steering pin, travel to keytah & fit to machine, remove grase line & replace with grease nip
18/05/2011	Knapman, Kenneth - TWC MECHANIC	4.50	Repair steering pin, travel to keytah & fit to machine, remove grase line & replace with grease nip
24/05/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Order parts
26/05/2011	Knapman, Kenneth - TWC MECHANIC	3.00	Travel to from Keytah, Replace trans. harness, measure for pins & trashrack steps, replace bolts in
17/06/2011	Bell, Daniel - TWC Manager	5.00	Escort/repair etc.
18/06/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove front radiator & guards/Remove front engine & exhaust manifolds./Clean parts, look up & orde
20/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Remove front engine, make up spreader bar, remove manifolds, flywheel housing & fly wheel, remove s
20/06/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove front radiator & guards/Remove front engine & exhaust manifolds./Clean parts, look up & orde
21/06/2011	Knapman, Kenneth - TWC MECHANIC	7.50	Remove front engine, make up spreader bar, remove manifolds, flywheel housing & fly wheel, remove s
21/06/2011	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove front radiator & guards/Remove front engine & exhaust manifolds./Clean parts, look up & orde
22/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Remove front engine, make up spreader bar, remove manifolds, flywheel housing & fly wheel, remove s
22/06/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Remove front radiator & guards/Remove front engine & exhaust manifolds./Clean parts, look up & orde
23/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Fit flywheel cover & remove, helicoil threads & refit flywheel cover, pick up parts & fit hose, tak
25/06/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R engine harness & compressor air line.
27/06/2011	Knapman, Kenneth - TWC MECHANIC	8.50	Fit flywheel cover & remove, helicoil threads & refit flywheel cover, pick up parts & fit hose, tak
27/06/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Refit sump, reassemble engine & hoses to machine
28/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Fit flywheel cover & remove, helicoil threads & refit flywheel cover, pick up parts & fit hose, tak

Date	Name	Duration	Notes
29/06/2011	Bell, Daniel - TWC Manager	3.50	Install front engine parts.
29/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Fit flywheel cover & remove, helicoil threads & refit flywheel cover, pick up parts & fit hose, tak
30/06/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Remove & repair bonnet, adjust radiator mounts, replace bonnets, replace battery locks & fule filte
30/06/2011	Bell, Daniel - TWC Manager	5.00	Install front engine parts.
01/07/2011	Knapman, Kenneth - TWC MECHANIC	7.50	Remove & repair bonnet, adjust radiator mounts, replace bonnets, replace battery locks & fule filte
02/07/2011	Knapman, Kenneth - TWC MECHANIC	8.00	Remove & repair bonnet, adjust radiator mounts, replace bonnets, replace battery locks & fule filte
02/07/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	Chk & adj. rear fuel pump timing, refit guards, drain & refill front diff & final Dr., R & R starte
04/07/2011	Knapman, Kenneth - TWC MECHANIC	8.00	Remove & repair bonnet, adjust radiator mounts, replace bonnets, replace battery locks & fule filte
04/07/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	Chk & adj. rear fuel pump timing, refit guards, drain & refill front diff & final Dr., R & R starte
05/07/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adj. rear fuel pump timing, refit guards, drain & refill front diff & final Dr., R & R starte
21/07/2011	Bell, Daniel - TWC Manager	2.00	Replace alternator pivot bolt.
26/07/2011	Bell, Daniel - TWC Manager	1.50	Replace alternator pivot bolt.
26/07/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	27869hrs: Chk cutting edges & rear fuel pump leak./ R & R rear fuel pump seal & alternator nut.
27/07/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	27869hrs: Chk cutting edges & rear fuel pump leak./ R & R rear fuel pump seal & alternator nut.
01/08/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Pack up cutting edges/R & R cab door stopper
03/08/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Pack up cutting edges/R & R cab door stopper
20/08/2011	Bell, Daniel - TWC Manager	3.50	Make up parts list for repairs & repair hook, Reseal various leaks around transmission.
20/08/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk front trans. operation, chk steering rods for wear, chk mud guards.
22/08/2011	Bell, Daniel - TWC Manager	6.00	Make up parts list for repairs & repair hook, Reseal various leaks around transmission.
23/08/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Arrange remake of mudguards./Set up cat walks.
23/08/2011	Bell, Daniel - TWC Manager	3.00	Make up parts list for repairs & repair hook, Reseal various leaks around transmission.
24/08/2011	Bell, Daniel - TWC Manager	4.00	Make up parts list for repairs & repair hook, Reseal various leaks around transmission.
24/08/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Arramge remake of mudguards./Set up cat walks.
25/08/2011	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove front trans. & diff., dismantle diff/clean up parts./Reassemble l/h steering cylinder & fit,
25/08/2011	Bell, Daniel - TWC Manager	9.50	Remove & rerace/reseal front transmission.
26/08/2011	Wilde, David - TWC WORKSHOP MANAGER	7.00	Remove front trans. & diff., dismantle diff/clean up parts./Reassemble l/h steering cylinder & fit,
26/08/2011	Bell, Daniel - TWC Manager	9.50	Remove & rerace/reseal front transmission.
29/08/2011	Bell, Daniel - TWC Manager	1.00	Remove & rerace/reseal front transmission.
29/08/2011	Wilde, David - TWC WORKSHOP MANAGER	6.00	Remove front trans. & diff., dismantle diff/clean up parts./Reassemble l/h steering cylindr & fit,
29/08/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Make tool for diff reassembly/Start repair work on steering cylinders, torque converter & planetary
30/08/2011	Knapman, Kenneth - TWC MECHANIC	8.50	Make tool for diff reassembly/Start repair work on steering cylinders, torque converter & planetary
30/08/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Remove front trans. & diff., dismantle diff/clean up parts./Reassemble l/h steering cylinder & fit,
31/08/2011	Bell, Daniel - TWC Manager	8.00	Remove & rerace/reseal front transmission.
31/08/2011	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove front trans. & diff., dismantle diff/clean up parts./Reassemble l/h steering cylinder & fit,
31/08/2011	Knapman, Kenneth - TWC MECHANIC	9.00	Make tool for diff reassembly/Start repair work on steering cylinders, torque converter & planetary
01/09/2011	Knapman, Kenneth - TWC MECHANIC	8.00	Assemble transmission/Fit pinion bearings for diff & continue trans. assembly/Remove steer cylinder
01/09/2011	Wilde, David - TWC WORKSHOP MANAGER	8.00	Assemble transmission
01/09/2011	Bell, Daniel - TWC Manager	8.50	Rebuild trans/transfer case etc.
02/09/2011	Bell, Daniel - TWC Manager	9.50	Rebuild trans/transfer case etc.
05/09/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Assemble transmission/Fit pinion bearings for diff & continue trans. assembly/Remove steer cylinder
05/09/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Assemble transmission
05/09/2011	Bell, Daniel - TWC Manager	9.50	Rebuild trans/transfer case etc.
06/09/2011	Knapman, Kenneth - TWC MECHANIC	2.00	Assemble transmission/Fit pinion bearings for diff & continue trans. assembly/Remove steer cylinder
06/09/2011	Bell, Daniel - TWC Manager	7.50	Rebuild trans/transfer case etc.
07/09/2011	Bell, Daniel - TWC Manager	6.00	Rebuild trans/transfer case etc.
07/09/2011	Knapman, Kenneth - TWC MECHANIC	6.00	Assemble transmission/Fit pinion bearings for diff & continue trans. assembly/Remove steer cylinder
08/09/2011	Bell, Daniel - TWC Manager	5.50	Disassemble hydraulic pumps etc.
09/09/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Commence diff reassembly, order parts./Diff assembly
12/09/2011	Knapman, Kenneth - TWC MECHANIC	9.00	Commence diff reassembly, order parts./Diff assembly
12/09/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to diff
13/09/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Commence diff reassembly, order parts./Diff assembly
14/09/2011	Knapman, Kenneth - TWC MECHANIC	3.50	Commence diff reassembly, order parts./Diff assembly
16/09/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Clean engine parts.
21/09/2011	Knapman, Kenneth - TWC MECHANIC	2.50	Reassemble fan drive & tensioner

Date	Name	Duration	Notes
22/09/2011	Knapman, Kenneth - TWC MECHANIC	6.50	Refit diff, wash parts ready for install to machine, refit tran/diff, axles & begin hose connection
22/09/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Assemble trans & diff to machine./Refill diff & trans oil, refit steering ram, start & top up oil./
24/09/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Assemble trans & diff to machine./Refill diff & trans oil, refit steering ram, start & top up oil./
26/09/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Refit diff, wash parts ready for install to machine, refit tran/diff, axles & begin hose connection
26/09/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	Assemble trans & diff to machine./Refill diff & trans oil, refit steering ram, start & top up oil./
27/09/2011	Knapman, Kenneth - TWC MECHANIC	7.50	Refit diff, wash parts ready for install to machine, refit tran/diff, axles & begin hose connection
27/09/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Assemble trans & diff to machine./Refill diff & trans oil, refit steering ram, start & top up oil./
28/09/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Refit diff, wash parts ready for install to machine, refit tran/diff, axles & begin hose connection
29/09/2011	Bell, Daniel - TWC Manager	1.00	Troubleshoot transmission problem from 3rd-2nd
29/09/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Continue engine repairs & work on transmission problem.
30/09/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Continue engine repairs & work on transmission problem.
30/09/2011	Bell, Daniel - TWC Manager	8.00	Troubleshoot transmission problem from 3rd-2nd
01/10/2011	Knapman, Kenneth - TWC MECHANIC	6.00	Continue engine repairs & work on transmission problem.
03/10/2011	Knapman, Kenneth - TWC MECHANIC	4.00	Continue engine repairs & work on transmission problem.
04/10/2011	Knapman, Kenneth - TWC MECHANIC	3.50	Continue engine repairs & work on transmission problem.
06/10/2011	Bell, Daniel - TWC Manager	0.00	Troubleshoot transmission problem from 3rd-2nd, reseal hitch cylinder
10/10/2011	Bell, Daniel - TWC Manager	1.50	Troubleshoot transmission problem from 3rd-2nd, reseal hitch cylinder
10/10/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Hitch repairs/Work on trans. problem, chase up mudguard rebuild
10/10/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Remove, reseal hitch cylinder & refit.
11/10/2011	Knapman, Kenneth - TWC MECHANIC	3.50	Hitch repairs/Work on trans. problem, chase up mudguard rebuild
11/10/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Test drive to locate fault.
17/10/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove solinoid housing, chk for blockage, ref./Chk trans for air in oil, replace pumps & seals, r
18/10/2011	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove solinoid housing, chk for blockage, ref./Chk trans for air in oil, replace pumps & seals, r
19/10/2011	Bell, Daniel - TWC Manager	1.50	Test transmission pressures
19/10/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Repairs
19/10/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Remove solinoid housing, chk for blockage, ref./Chk trans for air in oil, replace pumps & seals, r
20/10/2011	Knapman, Kenneth - TWC MECHANIC	8.00	27,952 hrs: Continue work on trans. problem, Replace belly guard./Remove Trans/diff assembly & disa
20/10/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	Collect new muguards & chk prefit, remove brackets & guards & clean up for painting./Chk & adjust h
21/10/2011	Knapman, Kenneth - TWC MECHANIC	9.50	27,952 hrs: Continue work on trans. problem, Replace belly guard./Remove Trans/diff assembly & disa
21/10/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Collect new muguards & chk prefit, remove brackets & guards & clean up for painting./Chk & adjust h
22/10/2011	Knapman, Kenneth - TWC MECHANIC	8.00	27,952 hrs: Continue work on trans. problem, Replace belly guard./Remove Trans/diff assembly & disa
22/10/2011	Wilde, David - TWC WORKSHOP MANAGER	6.00	Collect new muguards & chk prefit, remove brackets & guards & clean up for painting./Chk & adjust h
24/10/2011	Knapman, Kenneth - TWC MECHANIC	2.00	27,952 hrs: Continue work on trans. problem, Replace belly guard./Remove Trans/diff assembly & disa
24/10/2011	Bell, Daniel - TWC Manager	1.00	Replace seal in steering cylinder.
31/10/2011	Griffin, Reece - Plant Mechanic	8.50	27953hrs:Jack up machine, chk brakes, drain rear diff & final drive, remove rear tyre./Work on brak
31/10/2011	Knapman, Kenneth - TWC MECHANIC	2.00	Remove l/h brake drums & replace.
31/10/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Remove rear wheel & chk brakes & bearings./R & R S cam & bearings & brake drums./27952hrs: Remove R
01/11/2011	Griffin, Reece - Plant Mechanic	7.50	27953hrs:Jack up machine, chk brakes, drain rear diff & final drive, remove rear tyre./Work on brak
01/11/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	Remove rear wheel & chk brakes & bearings./R & R S cam & bearings & brake drums./27952hrs: Remove R
02/11/2011	Bell, Daniel - TWC Manager	1.00	Install wheel group parts
02/11/2011	Griffin, Reece - Plant Mechanic	2.00	27953hrs:Jack up machine, chk brakes, drain rear diff & final drive, remove rear tyre./Work on brak
02/11/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove rear wheel & chk brakes & bearings./R & R S cam & bearings & brake drums./27952hrs: Remove R
03/11/2011	Knapman, Kenneth - TWC MECHANIC	4.00	Adapt scraper brake grease lines to a grease bank, make plate for grease lines.final drive/ mudguar
03/11/2011	Griffin, Reece - Plant Mechanic	2.00	Start assembly of brakes/ wash machine
03/11/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to rear brakes
04/11/2011	Knapman, Kenneth - TWC MECHANIC	9.50	Adapt scraper brake grease lines to a grease bank, make plate for grease lines.final drive/ mudguar
04/11/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Repairs to rear brakes
05/11/2011	Knapman, Kenneth - TWC MECHANIC	7.00	Adapt scraper brake grease lines to a grease bank, make plate for grease lines.final drive/ mudguar
05/11/2011	Wilde, David - TWC WORKSHOP MANAGER	7.00	Repairs to rear brakes
07/11/2011	Griffin, Reece - Plant Mechanic	4.50	Start assembly of brakes/ wash machine
08/11/2011	Griffin, Reece - Plant Mechanic	4.50	Start assembly of brakes/ wash machine
09/11/2011	Griffin, Reece - Plant Mechanic	6.00	Start assembly of brakes/ wash machine
09/11/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	27952hrs R&R hyd hoses and air lines, wash down
10/11/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Wash down/Remove hitch hoses & repalce, repalce holding valve, repair air leak & fit clamps/Refit h

Date	Name	Duration	Notes
10/11/2011	Bell, Daniel - TWC Manager	4.50	Replace worn air & hydraulic lines. Remove guards & clean under cabin. Replace step mouting lugs.
11/11/2011	Wilde, David - TWC WORKSHOP MANAGER	6.00	Wash down/Remove hitch hoses & repalce, repalce holding valve, repair air leak & fit clamps/Refit h
11/11/2011	Bell, Daniel - TWC Manager	2.00	Replace worn air & hydraulic lines. Remove guards & clean under cabin. Replace step mouting lugs.
12/11/2011	Wilde, David - TWC WORKSHOP MANAGER	7.00	Wash down/Remove hitch hoses & repalce, repalce holding valve, repair air leak & fit clamps/Refit h
14/11/2011	Bell, Daniel - TWC Manager	2.00	Replace worn air & hydraulic lines. Remove guards & clean under cabin. Replace step mouting lugs.
15/11/2011	Bell, Daniel - TWC Manager	4.00	Replace worn air & hydraulic lines. Remove guards & clean under cabin. Replace step mouting lugs.
19/11/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	R & R hitch hoses, wash down./Remove windows & lights, wash parts for painting, deliver machine & p
21/11/2011	Griffin, Reece - Plant Mechanic	2.00	Bolt up A/c box 7 remove lights for painting/Wash guards, remove windows, 2way & stereo, shift mach
22/11/2011	Griffin, Reece - Plant Mechanic	4.00	Bolt up A/c box 7 remove lights for painting/Wash guards, remove windows, 2way & stereo, shift mach
22/11/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	R & R hitch hoses, wash down./Remove windows & lights, wash parts for painting, deliver machine & p
02/12/2011	Griffin, Reece - Plant Mechanic	3.00	Check over machine/Install radiator
05/12/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove guards & move for sand blasting
06/12/2011	Griffin, Reece - Plant Mechanic	2.00	Check over machine/Install radiator
08/12/2011	Griffin, Reece - Plant Mechanic	1.00	Tap threads on machine/Sort out & clean up exchange parts/Grinding push plate base, replace hose &
13/12/2011	Griffin, Reece - Plant Mechanic	4.50	Tap threads on machine/Sort out & clean up exchange parts/Grinding push plate base, replace hose &
13/12/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Clean up parts, look up & price parts.
14/12/2011	Griffin, Reece - Plant Mechanic	7.50	Tap threads on machine/Sort out & clean up exchange parts/Grinding push plate base, replace hose &
14/12/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair cracks in guards
15/12/2011	Griffin, Reece - Plant Mechanic	4.00	Commence degreasing/washing machine
16/12/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Collect parts & chk, repair guards for painting
05/01/2012	Wilde, David - TWC WORKSHOP MANAGER	5.50	27952hrs: Clean out threads & assemble parts./Assemble machine./Assemble rear mud guards to machine
06/01/2012	Wilde, David - TWC WORKSHOP MANAGER	7.00	27952hrs: Clean out threads & assemble parts./Assemble machine./Assemble rear mud guards to machine
11/01/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	27952hrs: Clean out threads & assemble parts./Assemble machine./Assemble rear mud guards to machine
12/01/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit mudguards/ Assemble windows & bonnets./Repairs to l/h mud guard, fit hood lining & flashing I
13/01/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Remove broken studs./Remove l/h brake booster & mounting brackets, press bracket to fit guard, remo
14/01/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Refit mudguards/ Assemble windows & bonnets./Repairs to l/h mud guard, fit hood lining & flashing I
16/01/2012	Griffin, Reece - Plant Mechanic	7.50	Replace guards & windscreen wipers, assist set up quickfill, attach & remove guards, pump tyres, cl
16/01/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Remove broken studs./Remove l/h brake booster & mounting brackets, press bracket to fit guard, remo
16/01/2012	Wilde, David - TWC WORKSHOP MANAGER	5.50	Refit mudguards/ Assemble windows & bonnets./Repairs to l/h mud guard, fit hood lining & flashing I
17/01/2012	Griffin, Reece - Plant Mechanic	5.00	Replace guards & windscreen wipers, assist set up quickfill, attach & remove guards, pump tyres, cl
17/01/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Remove broken studs./Remove l/h brake booster & mounting brackets, press bracket to fit guard, remo
17/01/2012	Wilde, David - TWC WORKSHOP MANAGER	5.50	Refit mudguards/ Assemble windows & bonnets./Repairs to l/h mud guard, fit hood lining & flashing I
18/01/2012	Griffin, Reece - Plant Mechanic	1.50	Replace guards & windscreen wipers, assist set up quickfill, attach & remove guards, pump tyres, cl
18/01/2012	Knapman, Kenneth - TWC MECHANIC	4.50	Remove broken studs./Remove l/h brake booster & mounting brackets, press bracket to fit guard, remo
18/01/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit mudguards/ Assemble windows & bonnets./Repairs to l/h mud guard, fit hood lining & flashing I
19/01/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit hose to fast fill./ Refit grease line & clamps./Clean water & chk if signs fit. Refit & adjust
20/01/2012	Griffin, Reece - Plant Mechanic	7.00	Replace slack adjuster & seals, clean stub axles, remove & clean l/h planetary and reassemble.
20/01/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Fit hose to fast fill./ Refit grease line & clamps./Clean water & chk if signs fit. Refit & adjust
21/01/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit hose to fast fill./ Refit grease line & clamps./Clean water & chk if signs fit. Refit & adjust
24/01/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit hose to fast fill./ Refit grease line & clamps./Clean water & chk if signs fit. Refit & adjust
01/02/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Fit transfers
09/02/2012	Griffin, Reece - Plant Mechanic	2.00	Make up hoses
13/02/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Fit 'E' stops/ Chk rear eng. oil leak & fir auto grease system
14/02/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit 'E' stops/ Chk rear eng. oil leak & fir auto grease system
16/02/2012	Bell, Daniel - TWC Manager	3.00	Fit belly guards, install auto greaser.
17/02/2012	Griffin, Reece - Plant Mechanic	7.00	Fit & tidy up greasing system./ Remove old engine shut off system, P clamp hoses & collect parts,
17/02/2012	Bell, Daniel - TWC Manager	2.00	Fit belly guards, install auto greaser.
20/02/2012	Griffin, Reece - Plant Mechanic	9.50	Fit & tidy up greasing system./ Remove old engine shut off system, P clamp hoses & collect parts,
20/02/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove hyd. valve & reseal & order parts.
21/02/2012	Griffin, Reece - Plant Mechanic	2.50	Fit & tidy up greasing system./ Remove old engine shut off system, P clamp hoses & collect parts,
22/02/2012	Griffin, Reece - Plant Mechanic	8.50	Fit & tidy up greasing system./ Remove old engine shut off system, P clamp hoses & collect parts,
22/02/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Oversee push/pull bar hydraulic repairs.
23/02/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Locate bail problems, order parts./Find bail control valve fault, pressure chks of bail control val
23/02/2012	Griffin, Reece - Plant Mechanic	4.50	Continue repair work.

Date	Name	Duration	Notes
24/02/2012	Knapman, Kenneth - TWC MECHANIC	6.50	Locate bail problems, order parts./Find bail control valve fault, pressure chks of bail control val
27/02/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Locate bail problems, order parts./Find bail control valve fault, pressure chks of bail control val
28/02/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Locate bail problems, order parts./Find bail control valve fault, pressure chks of bail control val
28/02/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk hitch & bail operation & clean out hoses./Repairs to hydraulics.
29/02/2012	Knapman, Kenneth - TWC MECHANIC	3.00	Locate bail problems, order parts./Find bail control valve fault, pressure chks of bail control val
29/02/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk hitch & bail operation & clean out hoses./Repairs to hydraulics.
05/03/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Assist gwydir Hydraulics with pressure testing.
06/03/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Assist gwydir Hydraulics with pressure testing.
15/03/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Remove hyd. test fittings & repalce guard./ Assist Gwydir Hyd. with testing & adjusting of new valv
16/03/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Remove hyd. test fittings & repalce guard./ Assist Gwydir Hyd. with testing & adjusting of new valv
17/03/2012	Griffin, Reece - Plant Mechanic	1.00	Install guards on machine./ Install belly guards, wash down, chk F drive oils & tyre pressures.
17/03/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit guards to draft arm, fit gaskets to fuel pump./ Fit belly guards
21/03/2012	Griffin, Reece - Plant Mechanic	2.50	Install guards on machine./ Install belly guards, wash down, chk F drive oils & tyre pressures.
21/03/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Remove hyd. test fittings & repalce guard./ Assist Gwydir Hyd. with testing & adjusting of new valv
21/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit guards to draft arm, fit gaskets to fuel pump./ Fit belly guards
22/03/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Pick up rolled plate & make up draft arm guard./Remove rotochamber from 239 to repalce failed unit,
27/03/2012	Griffin, Reece - Plant Mechanic	0.50	Attach draft arm guard.
28/03/2012	Griffin, Reece - Plant Mechanic	1.00	Chk all oil levels & magnetic plugs, remove throttle air diaphragm.
28/03/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Pick up rolled plate & make up draft arm guard./Remove rotochamber from 239 to repalce failed unit,
28/03/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk final drive plugs & oil leaks, chk rear trans fault.
29/03/2012	Griffin, Reece - Plant Mechanic	1.00	Chk'd magnetic plugs & all oils./ Remove stereo./ Install new stereo & speakers.
29/03/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	27,980hrs: Chk rear trans. fault & replace rear shift card. Test run./ Adjust cab door latch./ 28,0
30/03/2012	Griffin, Reece - Plant Mechanic	0.50	Chk'd magnetic plugs & all oils./ Remove stereo./ Install new stereo & speakers.
31/03/2012	Griffin, Reece - Plant Mechanic	0.75	Chk'd magnetic plugs & all oils./ Remove stereo./ Install new stereo & speakers.
31/03/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	27,980hrs: Chk rear trans. fault & replace rear shift card. Test run./ Adjust cab door latch./ 28,0
02/04/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Purchase filter & deliver to Bellata, return to W/shop & post SOS samples./ Cut off pipes & plates
02/04/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	27,980hrs: Chk rear trans. fault & replace rear shift card. Test run./ Adjust cab door latch./ 28,0
03/04/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Purchase filter & deliver to Bellata, return to W/shop & post SOS samples./ Cut off pipes & plates
03/04/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	27,980hrs: Chk rear trans. fault & replace rear shift card. Test run./ Adjust cab door latch./ 28,0
05/04/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Make guard rails.
10/04/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Make guard rails.
11/04/2012	Knapman, Kenneth - TWC MECHANIC	4.00	Make guard rails.
12/04/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Manufacture guard rails./Guard rails, locate oil leak./ Order parts, Finish guard rails.
13/04/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Manufacture guard rails./Guard rails, locate oil leak./ Order parts, Finish guard rails.
14/04/2012	Knapman, Kenneth - TWC MECHANIC	1.25	Manufacture guard rails./Guard rails, locate oil leak./ Order parts, Finish guard rails.
16/04/2012	Bell, Daniel - TWC Manager	4.00	Assemble spare engine.
17/04/2012	Bell, Daniel - TWC Manager	5.50	Assemble spare engine.
17/04/2012	Griffin, Reece - Plant Mechanic	4.50	Work on spare 637 engine rebuild
18/04/2012	Griffin, Reece - Plant Mechanic	1.00	Work on spare 637 engine rebuild
18/04/2012	Bell, Daniel - TWC Manager	6.50	Assemble spare engine.
18/04/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Assemble spare engine.
19/04/2012	Griffin, Reece - Plant Mechanic	3.50	Work on spare engine rebuild.
19/04/2012	Griffin, Reece - Plant Mechanic	1.00	Chk for oil in turbo./ Chk plugs & repalce steering hose.
19/04/2012	Bell, Daniel - TWC Manager	7.00	Assemble spare 3408 spare engine long block.
20/04/2012	Griffin, Reece - Plant Mechanic	1.00	Chk for oil in turbo./ Chk plugs & repalce steering hose.
20/04/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace steering hose & mounting blocks./ Clean engine parts./ Assemble spare engine
23/04/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace steering hose & mounting blocks./ Clean engine parts./ Assemble spare engine
24/04/2012	Bell, Daniel - TWC Manager	9.50	Assemble spare 3408 spare engine long block.
24/04/2012	Griffin, Reece - Plant Mechanic	2.00	Install pistons in spare motor & chk bearings.
24/04/2012	Wilde, David - TWC WORKSHOP MANAGER	6.50	Replace steering hose & mounting blocks./ Clean engine parts./ Assemble spare engine
26/04/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Collect parts./ Remanufacture engine stands to suit, laocate in trailer & wels in place, weld spare
26/04/2012	Bell, Daniel - TWC Manager	9.50	Rebuild spare engine (long block)
26/04/2012	Wilde, David - TWC WORKSHOP MANAGER	5.50	Assemble spare engine./ Load eng. onto trailer, travel to jobsire (Auscott), remove power pack & in
27/04/2012	Bell, Daniel - TWC Manager	8.00	Rebuild spare engine (long block)

Date	Name	Duration	Notes
27/04/2012	Griffin, Reece - Plant Mechanic	8.50	Load engine onto trailer, weld & tie down, travel to jobsite (Auscott), remove rear engine from mac
27/04/2012	Knapman, Kenneth - TWC MECHANIC	11.00	Collect parts./ Remanufacture engine stands to suit, laocate in trailer & wels in place, weld spare
27/04/2012	Wilde, David - TWC WORKSHOP MANAGER	10.50	Assemble spare engine./ Load eng. onto trailer, travel to jobsire (Auscott), remove power pack & in
28/04/2012	Bell, Daniel - TWC Manager	5.00	Rebuild spare engine (long block)
28/04/2012	Griffin, Reece - Plant Mechanic	5.00	Load engine onto trailer, weld & tie down, travel to jobsite (Auscott), remove rear engine from mac
28/04/2012	Wilde, David - TWC WORKSHOP MANAGER	7.00	Assemble spare engine./ Load eng. onto trailer, travel to jobsire (Auscott), remove power pack & in
30/04/2012	Griffin, Reece - Plant Mechanic	8.50	Load engine onto trailer, weld & tie down, travel to jobsite (Auscott), remove rear engine from mac
30/04/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Collect parts./ Remanufacture engine stands to suit, laocate in trailer & wels in place, weld spare
30/04/2012	Wilde, David - TWC WORKSHOP MANAGER	9.50	Assemble spare engine./ Load eng. onto trailer, travel to jobsire (Auscott), remove power pack & in
01/05/2012	Griffin, Reece - Plant Mechanic	7.50	Load engine onto trailer, weld & tie down, travel to jobsite (Auscott), remove rear engine from mac
01/05/2012	Knapman, Kenneth - TWC MECHANIC	7.00	Collect parts./ Remanufacture engine stands to suit, laocate in trailer & wels in place, weld spare
01/05/2012	Bell, Daniel - TWC Manager	7.00	Rebuild spare engine (long block)
01/05/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Assemble spare engine./ Load eng. onto trailer, travel to jobsire (Auscott), remove power pack & in
02/05/2012	Bell, Daniel - TWC Manager	4.00	Rebuild spare engine (long block)
02/05/2012	Griffin, Reece - Plant Mechanic	4.50	Load engine onto trailer, weld & tie down, travel to jobsite (Auscott), remove rear engine from mac
02/05/2012	Knapman, Kenneth - TWC MECHANIC	4.50	Collect parts./ Remanufacture engine stands to suit, laocate in trailer & wels in place, weld spare
02/05/2012	Wilde, David - TWC WORKSHOP MANAGER	6.50	Assemble spare engine./ Load eng. onto trailer, travel to jobsire (Auscott), remove power pack & in
03/05/2012	Wilde, David - TWC WORKSHOP MANAGER	9.50	assemble rear trans./ 28177hrs: Chk & repair fuel leak & test run./ Chk front eng. fuel leak, assem
04/05/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	assemble rear trans./ 28177hrs: Chk & repair fuel leak & test run./ Chk front eng. fuel leak, assem
07/05/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	assemble rear trans./ 28177hrs: Chk & repair fuel leak & test run./ Chk front eng. fuel leak, assem
08/05/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Reassemble torque converter, purchase parts./ Fit transmission converter piston & disc, collect par
08/05/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	assemble rear trans./ 28177hrs: Chk & repair fuel leak & test run./ Chk front eng. fuel leak, assem
09/05/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Reassemble torque converter, purchase parts./ Fit transmission converter piston & disc, collect par
09/05/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	assemble rear trans./ 28177hrs: Chk & repair fuel leak & test run./ Chk front eng. fuel leak, assem
12/05/2012	Griffin, Reece - Plant Mechanic	1.00	Bolt on trans. pipes./ Unbolt & unwire power pack.
12/05/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Fit converter/housing to trans., disassemble & clean lockup valve, reassemble & fit to trans./ Asse
12/05/2012	Wilde, David - TWC WORKSHOP MANAGER	4.50	Assemble converter & fit to trans., fit hyd pipes./ Refit trans & hyd. controls to engine, time fue
14/05/2012	Knapman, Kenneth - TWC MECHANIC	8.00	Fit converter/housing to trans., disassemble & clean lockup valve, reassemble & fit to trans./ Asse
14/05/2012	Wilde, David - TWC WORKSHOP MANAGER	5.00	Assemble converter & fit to trans., fit hyd pipes./ Refit trans & hyd. controls to engine, time fue
16/05/2012	Griffin, Reece - Plant Mechanic	3.00	Bolt on trans. pipes./ Unbolt & unwire power pack.
17/05/2012	Griffin, Reece - Plant Mechanic	2.00	Install power pack./ Clean & adjust wheel bearings./ Remove, reseal & replace L/H steering ram, rem
17/05/2012	Wilde, David - TWC WORKSHOP MANAGER	6.00	Remove power pack & refit repaired unit, part wash down./ Complete wash down./ Remove & reseal ste
18/05/2012	Griffin, Reece - Plant Mechanic	7.50	Install power pack./ Clean & adjust wheel bearings./ Remove, reseal & replace L/H steering ram, rem
18/05/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Helicoil sump drain./ Run scraper engine, top up oils, source oil pressure fault in trans. & fix, t
18/05/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove power pack & refit repaired unit, part wash down./ Complete wash down./ Remove & reseal ste
19/05/2012	Griffin, Reece - Plant Mechanic	8.00	Install power pack./ Clean & adjust wheel bearings./ Remove, reseal & replace L/H steering ram, rem
19/05/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove power pack & refit repaired unit, part wash down./ Complete wash down./ Remove & reseal ste
21/05/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Helicoil sump drain./ Run scraper engine, top up oils, source oil pressure fault in trans. & fix, t
21/05/2012	Bell, Daniel - TWC Manager	4.50	Install rear power pack etc.
22/05/2012	Bell, Daniel - TWC Manager	9.50	Install rear power pack etc.
22/05/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Helicoil sump drain./ Run scraper engine, top up oils, source oil pressure fault in trans. & fix, t
31/05/2012	Griffin, Reece - Plant Mechanic	2.00	Assist Dale with spare engine.
08/06/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Pack up parts & reassemble old compressor.
12/06/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	28,262 hrs: R & R rear isolator.
23/06/2012	Griffin, Reece - Plant Mechanic	3.50	Rre install engine mounts.
27/06/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Travel to Narrabri & pick up screen for radiator, return to w/shop.
19/07/2012	Dawson, Dale - TWC Mechanic	5.00	Continue assembly of spare engine, fit oil cooler, heat shields & turbo etc./ Complete assembly of
23/07/2012	Dawson, Dale - TWC Mechanic	4.50	Continue assembly of spare engine, fit oil cooler, heat shields & turbo etc./ Complete assembly of
23/07/2012	Griffin, Reece - Plant Mechanic	2.00	Continue assembly of spare engine.
06/08/2012	Dawson, Dale - TWC Mechanic	2.50	28,477hrs: Complete 500hr service & take SOS, fit new 2way speaker, inspect operation of autogrease
06/08/2012	Griffin, Reece - Plant Mechanic	2.50	28,477hrs: Complete 500hr service including SOS, fit new 2way speaker, inspect operation of auto gr
20/08/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	28,536hrs: Drop belly guards, & repair eng. oil leak, replace bolt in alternator & adjust belts./ 2
21/08/2012	Dawson, Dale - TWC Mechanic	1.50	Look up & order new HMV parts, organise 2 grease lines, a/c tooling and parts for David.
22/08/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	28,536hrs: Drop belly guards, & repair eng. oil leak, replace bolt in alternator & adjust belts./ 2

Date	Name	Duration	Notes
07/09/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Get hose made & take to Warra. Make up hyd. hose. Remove fuel pump from spare parts engine.
10/09/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Get hose made & take to Warra. Make up hyd. hose. Remove fuel pump from spare parts engine.
11/09/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Get hose made & take to Warra. Make up hyd. hose. Remove fuel pump from spare parts engine.
17/09/2012	Griffin, Reece - Plant Mechanic	0.50	Ordered parts. Organised parts for maintenance & fuel pump repair.
19/09/2012	Griffin, Reece - Plant Mechanic	2.00	Ordered parts. Organised parts for maintenance & fuel pump repair.
21/09/2012	Dawson, Dale - TWC Mechanic	2.00	Travel Tara to jobsite .75hrs, remove lift ram & steer ram assy's for resealing. Unloaded hyd. cy
21/09/2012	Griffin, Reece - Plant Mechanic	3.50	Finalise loading of tools/patrs etc for service trip to Tara, Travel to jobsite from Tara, remove
22/09/2012	Dawson, Dale - TWC Mechanic	6.00	Travel Tara to jobsite .75hrs, remove lift ram & steer ram assy's for resealing. Unloaded hyd. cy
22/09/2012	Griffin, Reece - Plant Mechanic	4.50	Finalise loading of tools/patrs etc for service trip to Tara, Travel to jobsite from Tara, remove
24/09/2012	Dawson, Dale - TWC Mechanic	5.50	Travel Tara to jobsite .75hrs, remove lift ram & steer ram assy's for resealing. Unloaded hyd. cy
24/09/2012	Griffin, Reece - Plant Mechanic	4.50	Finalise loading of tools/patrs etc for service trip to Tara, Travel to jobsite from Tara, remove
25/09/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Sort out incorrect parts rec'd
26/09/2012	Bell, Daniel - TWC Manager	2.00	Collect parts for apron cylinder reseal.
26/09/2012	Dawson, Dale - TWC Mechanic	2.25	Travel Tara to jobsite .75hrs, remove lift ram & steer ram assy's for resealing. Unloaded hyd. cy
26/09/2012	Griffin, Reece - Plant Mechanic	2.25	Finalise loading of tools/patrs etc for service trip to Tara, Travel to jobsite from Tara, remove
02/10/2012	Dawson, Dale - TWC Mechanic	0.50	Commence tracing transmission oil leak. Continue tracing oil leak - remove trans. scavenge pump,
03/10/2012	Dawson, Dale - TWC Mechanic	4.00	Commence tracing transmission oil leak. Continue tracing oil leak - remove trans. scavenge pump,
04/10/2012	Knapman, Kenneth - TWC MECHANIC	3.00	Travel to Goondwindi to deliver A/C gas cannister & return to w'shop.
09/10/2012	Bell, Daniel - TWC Manager	5.00	Collect parts from Toowoomba
09/10/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	29,250hrs: Chk seat fault & replace valve, chk grease line for blockage./ Have hose made.
10/10/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	29,250hrs: Chk seat fault & replace valve, chk grease line for blockage./ Have hose made.
12/10/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Prepare hose for remanufacture.
16/10/2012	Dawson, Dale - TWC Mechanic	3.00	Monreagh job site: Pick up parts (Tara) and carry out repairs - Fit cutting teeth adaptor bolts, fi
16/10/2012	Griffin, Reece - Plant Mechanic	3.00	Repairs - fit new cutting teeth adaptor bolts, fit new grease line to auto grease system, install n
17/10/2012	Dawson, Dale - TWC Mechanic	2.00	Monreagh job site: Pick up parts (Tara) and carry out repairs - Fit cutting teeth adaptor bolts, fi
18/10/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Source parts.
19/10/2012	Dawson, Dale - TWC Mechanic	5.00	Load 448 with parts/oils for Tara repairs job, travel to meet up with Tara operator, hand over part
19/10/2012	Wilde, David - TWC WORKSHOP MANAGER	7.00	Travel to Monreag jobsite, chk rear trans. fault. Order parts, chk auto grease system./Travel to Mo
20/10/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Travel to Monreag jobsite, chk rear trans. fault. Order parts, chk auto grease system./Travel to Mo
30/10/2012	Dawson, Dale - TWC Mechanic	8.00	Spare Engine: Install fuel pump onto engine, time fuel pump & install other fuel system components
30/10/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Purchase parts for David./ Spare motor: Assist Dale with running of engine.
31/10/2012	Dawson, Dale - TWC Mechanic	9.50	Spare Engine: Install fuel pump onto engine, time fuel pump & install other fuel system components
31/10/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Purchase parts for David./ Spare motor: Assist Dale with running of engine.
31/10/2012	Griffin, Reece - Plant Mechanic	3.00	Travel to Monreagh site, reseal scraper hitch valve
01/11/2012	Dawson, Dale - TWC Mechanic	2.50	Try to fit fuel pump to rebuilt 3408 engine
13/11/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Assemble & fit fuel pump & install surrounding parts to spare 3408 engine.
13/11/2012	Dawson, Dale - TWC Mechanic	7.00	Troubleshoot & replace #3 pumping element. Replace rear engine fan belts. Check over machine clean
14/11/2012	Dawson, Dale - TWC Mechanic	12.50	Troubleshoot & replace #3 pumping element. Replace rear engine fan belts. Check over machine clean
14/11/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Assemble & fit fuel pump & install surrounding parts to spare 3408 engine.
15/11/2012	Dawson, Dale - TWC Mechanic	4.50	Install rebuilt fuel pump on front engine.28887hrs./ 28,896hrs: R & R cutting edges, R & R air fuel
16/11/2012	Dawson, Dale - TWC Mechanic	2.50	Install rebuilt fuel pump on front engine.28887hrs./ 28,896hrs: R & R cutting edges, R & R air fuel
16/11/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	28,896hrs: R & R cutting edges./ Fill out SOS & look up parts.
17/11/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	28,896hrs: R & R cutting edges./ Fill out SOS & look up parts.
19/11/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Spare engine: Assist with removal of head & valve disassembly./ Manufacture tools & plates to chk f
19/11/2012	Dawson, Dale - TWC Mechanic	4.00	Spare engine: Commence removal of R/H cylinder head to locate water leak into cylinder./ Clean head
20/11/2012	Dawson, Dale - TWC Mechanic	1.00	Spare engine: Commence removal of R/H cylinder head to locate water leak into cylinder./ Clean head
20/11/2012	Griffin, Reece - Plant Mechanic	4.00	Troubleshoot a/c remove fan motors for checking. Order fan motors for 278 & 279
21/11/2012	Dawson, Dale - TWC Mechanic	6.00	Spare engine: Commence removal of R/H cylinder head to locate water leak into cylinder./ Clean head
21/11/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Spare engine: Assist with removal of head & valve disassembly./ Manufacture tools & plates to chk f
24/11/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	Look upo & pick up parts.
26/11/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Spare 3408: Take fuel pump for repair.
30/11/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	29,000hrs: Service as per specs./29005hrs: R & R rear fuel filter housing & test run./ Complete SOS
30/11/2012	Dawson, Dale - TWC Mechanic	3.50	28,997hrs: Complete 1,000hr service to specs.
01/12/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	29,000hrs: Service as per specs./29005hrs: R & R rear fuel filter housing & test run./ Complete SOS

Date	Name	Duration	Notes
04/12/2012	Griffin, Reece - Plant Mechanic	3.50	29,028hrs: Chk A/C problem-blowing hot air, ordered parts. / Chk'd seat valve in machine & replaced
05/12/2012	Griffin, Reece - Plant Mechanic	3.00	29,028hrs: Chk A/C problem-blowing hot air, ordered parts. / Chk'd seat valve in machine & replaced
05/12/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	29,000hrs: Service as per specs./29005hrs: R & R rear fuel filter housing & test run./ Complete SOS
07/12/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace a/c compressor & recharge system. Check & charge hitch accumulator. 29030hrs
07/12/2012	Griffin, Reece - Plant Mechanic	3.50	Replace a/c compressor & regas hitch. 29028hrs
12/12/2012	Griffin, Reece - Plant Mechanic	0.50	Replace a/c compressor & regas hitch. 29028hrs
13/12/2012	Griffin, Reece - Plant Mechanic	0.50	29,088: Obtain engine hours & brief chk over.
03/01/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	29,141hrs: Chk oil & coolant levels, chk all belts.
18/01/2013	Wilde, David - TWC WORKSHOP MANAGER	5.00	29,230hrs: Chk engine noise, R & R injector, test run./ Remove front eng. oil filter, cut open & in
18/01/2013	Griffin, Reece - Plant Mechanic	2.00	29,235hrs: Remove bonnet guards, filter housing, tappet cover & fuel lines, remove injector./ Refit
19/01/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	29,230hrs: Chk engine noise, R & R injector, test run./ Remove front eng. oil filter, cut open & in
21/01/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	29,230hrs: Chk engine noise, R & R injector, test run./ Remove front eng. oil filter, cut open & in
21/01/2013	Dawson, Dale - TWC Mechanic	1.50	Inspect engine fault, engine unserviceable - failure No4 cylinder.
21/01/2013	Griffin, Reece - Plant Mechanic	3.00	29,235hrs: Remove bonnet guards, filter housing, tappet cover & fuel lines, remove injector./ Refit
22/01/2013	Knapman, Kenneth - TWC MECHANIC	7.00	Locate & order parts.
22/01/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	29,230hrs: Chk engine noise, R & R injector, test run./ Remove front eng. oil filter, cut open & in
22/01/2013	Griffin, Reece - Plant Mechanic	2.00	29,235hrs: Remove bonnet guards, filter housing, tappet cover & fuel lines, remove injector./ Refit
23/01/2013	Knapman, Kenneth - TWC MECHANIC	7.00	Deliver pump from tamex to Diesel gas, collect parts & chk off, fit components to spare engine, unl
23/01/2013	Wilde, David - TWC WORKSHOP MANAGER	3.00	29,230hrs: Chk engine noise, R & R injector, test run./ Remove front eng. oil filter, cut open & in
23/01/2013	Dawson, Dale - TWC Mechanic	2.50	Load machine onto float.
24/01/2013	Knapman, Kenneth - TWC MECHANIC	10.50	Remove front engine from machine for replacement, pick up & order parts./ Collect & organise parts
25/01/2013	Knapman, Kenneth - TWC MECHANIC	8.50	Remove front engine from machine for replacement, pick up & order parts./ Collect & organise parts
26/01/2013	Knapman, Kenneth - TWC MECHANIC	7.50	Remove front engine from machine for replacement, pick up & order parts./ Collect & organise parts
29/01/2013	Knapman, Kenneth - TWC MECHANIC	8.00	Remove front engine from machine for replacement, pick up & order parts./ Collect & organise parts
30/01/2013	Dawson, Dale - TWC Mechanic	5.00	Remove, reseal & refit hitch control valve, test a/c system, inspect & test operation of bale arm -
30/01/2013	Knapman, Kenneth - TWC MECHANIC	7.00	Remove front engine from machine for replacement, pick up & order parts./ Collect & organise parts
31/01/2013	Dawson, Dale - TWC Mechanic	4.50	Install belly guards & engine covers, clean out a/c evaporator, refit gear shift console, chk over
31/01/2013	Griffin, Reece - Plant Mechanic	4.00	Remove steer cylinder, reseal & reinstall, locate oil pressure switch fault.
31/01/2013	Knapman, Kenneth - TWC MECHANIC	9.00	Remove r/h sdteer cylinder, disassemble, replace seals, reassemble & reinstall, fit guards, belly g
04/02/2013	Dawson, Dale - TWC Mechanic	3.50	Install belly guards & engine covers, clean out a/c evaporator, refit gear shift console, chk over
04/02/2013	Knapman, Kenneth - TWC MECHANIC	7.00	Remove r/h sdteer cylinder, disassemble, replace seals, reassemble & reinstall, fit guards, belly g
05/02/2013	Dawson, Dale - TWC Mechanic	6.00	Install belly guards & engine covers, clean out a/c evaporator, refit gear shift console, chk over
05/02/2013	Knapman, Kenneth - TWC MECHANIC	8.00	Remove r/h sdteer cylinder, disassemble, replace seals, reassemble & reinstall, fit guards, belly g
06/02/2013	Dawson, Dale - TWC Mechanic	9.50	Install belly guards & engine covers, clean out a/c evaporator, refit gear shift console, chk over
06/02/2013	Knapman, Kenneth - TWC MECHANIC	7.50	Remove r/h sdteer cylinder, disassemble, replace seals, reassemble & reinstall, fit guards, belly g
07/02/2013	Dawson, Dale - TWC Mechanic	3.50	Complete installation of transmission wiring harness, change some plugs & test./ Spare 3408 eng.: A
07/02/2013	Knapman, Kenneth - TWC MECHANIC	1.50	Load engine block onto pallet and dispatch vis Tamex./ Weld repair laser frame & relocate machine t
07/02/2013	Griffin, Reece - Plant Mechanic	1.50	Install apron control lever, chk over machine./ Work on machine.
08/02/2013	Dawson, Dale - TWC Mechanic	3.50	Complete installation of transmission wiring harness, change some plugs & test./ Spare 3408 eng.: A
12/02/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Load engine block onto pallet and dispatch vis Tamex./ Weld repair laser frame & relocate machine t
13/02/2013	Dawson, Dale - TWC Mechanic	1.50	Complete installation of transmission wiring harness, change some plugs & test./ Spare 3408 eng.: A
13/02/2013	Griffin, Reece - Plant Mechanic	1.00	Install apron control lever, chk over machine./ Work on machine.
13/02/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	Unload from float & chk over.
14/02/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	29,243hrs: Chk eng. for leaks & chk oil levels.
15/02/2013	Dawson, Dale - TWC Mechanic	0.50	Take oil sample from rebuilt front motor./ R & R rear ignition barrel out of control panel, inspect
18/02/2013	Dawson, Dale - TWC Mechanic	1.00	Take oil sample from rebuilt front motor./ R & R rear ignition barrel out of control panel, inspect
21/02/2013	Griffin, Reece - Plant Mechanic	4.50	32,500Hrs: 500Hr service, complete SOS's, removed fuel pump seal, throttle shaft dropped, removed g
22/02/2013	Griffin, Reece - Plant Mechanic	3.50	32,500Hrs: 500Hr service, complete SOS's, removed fuel pump seal, throttle shaft dropped, removed g
18/03/2013	Wilde, David - TWC WORKSHOP MANAGER	3.50	29,341Hrs: Remove apron cylinder for repairs, R & R door striker & catch strap./ Refit apron cylind
19/03/2013	Wilde, David - TWC WORKSHOP MANAGER	3.00	29,341Hrs: Remove apron cylinder for repairs, R & R door striker & catch strap./ Refit apron cylind
21/03/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	29,362Hrs: Chk & adjust rear throttle .5hrs, R & R ejector hose 1.5hrs.
29/03/2013	Griffin, Reece - Plant Mechanic	3.00	Fix rear trans shift fault.
09/04/2013	Dawson, Dale - TWC Mechanic	1.50	29,478Hrs: R & R ride hight control valve on seat, charge accumulator.
14/04/2013	Griffin, Reece - Plant Mechanic	3.00	29,527Hrs: 500hrs service./ Fill out SOS

Date	Name	Duration	Notes
16/04/2013	Griffin, Reece - Plant Mechanic	1.00	29,527Hrs: 500hrs service./ Fill out SOS
22/04/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	29,597Hrs: Chk charge system & battery charge, look up & order parts./ Replace 1 battery.
23/04/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	29,597Hrs: Chk charge system & battery charge, look up & order parts./ Replace 1 battery.
23/04/2013	Griffin, Reece - Plant Mechanic	1.00	Remove old steering link./ Install new steering ram link.
24/04/2013	Griffin, Reece - Plant Mechanic	2.00	Remove old steering link./ Install new steering ram link.
25/04/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R brake booster./ Chk e stop wiring, remove guard s& covers, remove rear eng control panel & ch
26/04/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	R & R brake booster./ Chk e stop wiring, remove guard s& covers, remove rear eng control panel & ch
27/04/2013	Wilde, David - TWC WORKSHOP MANAGER	6.50	R & R brake booster./ Chk e stop wiring, remove guard s& covers, remove rear eng control panel & ch
13/05/2013	Griffin, Reece - Plant Mechanic	1.00	Replace front eng. battery, chk edges./ Diagnosed faulty rear trans., tested harness.
14/05/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	Over phone repair to electrical system, look up & order parts.
14/05/2013	Griffin, Reece - Plant Mechanic	2.00	Replace front eng. battery, chk edges./ Diagnosed faulty rear trans., tested harness.
15/05/2013	Dawson, Dale - TWC Mechanic	3.50	Check rear transmission fault - R & R rear trans. card, fault still active - found trans control bo
16/05/2013	Dawson, Dale - TWC Mechanic	1.00	Install raer control box & test operation of machine - O/k./ R & R rear engine control panel harnes
19/05/2013	Griffin, Reece - Plant Mechanic	0.50	Chk trans. fault./ Endeavour to diagnose rear trans fault.
20/05/2013	Griffin, Reece - Plant Mechanic	1.00	Chk trans. fault./ Endeavour to diagnose rear trans fault.
22/05/2013	Dawson, Dale - TWC Mechanic	4.50	Install raer control box & test operation of machine - O/k./ R & R rear engine control panel harnes
31/05/2013	Griffin, Reece - Plant Mechanic	6.00	Wait for intermittant fault to occur 2.5hrs, locate problem when fault occurred 3.5hrs./ Fit soleno
31/05/2013	Wilde, David - TWC WORKSHOP MANAGER	3.50	Chk rear trans wiring & solenoids.
01/06/2013	Griffin, Reece - Plant Mechanic	1.00	Wait for intermittant fault to occur 2.5hrs, locate problem when fault occurred 3.5hrs./ Fit soleno
03/06/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over for repairs.
12/06/2013	Dawson, Dale - TWC Mechanic	0.50	Go through repairs with Reece.
12/06/2013	Griffin, Reece - Plant Mechanic	3.00	Replace rear throttle seal & remove trans. harness off hitch ready to replace.
14/06/2013	Griffin, Reece - Plant Mechanic	3.50	Replaced 2 harnesses on top of hitch./ Install 2 new harnesses from top of hitch along r/h side of
15/06/2013	Griffin, Reece - Plant Mechanic	7.50	Replaced 2 harnesses on top of hitch./ Install 2 new harnesses from top of hitch along r/h side of
16/06/2013	Griffin, Reece - Plant Mechanic	0.50	Replaced 2 harnesses on top of hitch./ Install 2 new harnesses from top of hitch along r/h side of
17/06/2013	Griffin, Reece - Plant Mechanic	4.00	Replaced 2 harnesses on top of hitch./ Install 2 new harnesses from top of hitch along r/h side of
18/06/2013	Wilde, David - TWC WORKSHOP MANAGER	4.00	Dismantle & reseal 2 steering rams.
19/06/2013	Griffin, Reece - Plant Mechanic	3.50	Replaced 2 harnesses on top of hitch./ Install 2 new harnesses from top of hitch along r/h side of
04/07/2013	Dawson, Dale - TWC Mechanic	1.00	R & R hose behind cab for hitch control.
14/07/2013	Griffin, Reece - Plant Mechanic	0.50	Chk treadle valve & air supply to compare to settings in 228
20/07/2013	Dawson, Dale - TWC Mechanic	2.50	R & R hoses from auto greaser to hydraulics, grease injectors & pig tail the 3 hoses through goose
21/07/2013	Dawson, Dale - TWC Mechanic	1.00	R & R hoses from auto greaser to hydraulics, grease injectors & pig tail the 3 hoses through goose
30/07/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk over for leaks.
04/08/2013	Dawson, Dale - TWC Mechanic	3.00	29885HRS: R & R rear eng. starter motor, R & R broken bolts in air tank mount
09/11/2013	Wilde, David - TWC WORKSHOP MANAGER	1.50	29895Hrs: Prestart. Chk & charge hitch & seat accumulators./ Top up oil levels, chk & adjust tyre p
11/11/2013	Griffin, Reece - Plant Mechanic	1.50	29896Hrs: Chk over machine; chk all fluids, pump up all tyres - 80PSI & chk for leaks
11/11/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	29895Hrs: Prestart. Chk & charge hitch & seat accumulators./ Top up oil levels, chk & adjust tyre p
12/11/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	29895Hrs: Prestart. Chk & charge hitch & seat accumulators./ Top up oil levels, chk & adjust tyre p
13/11/2013	Dawson, Dale - TWC Mechanic	1.50	Make up hyd. hose.
13/11/2013	Griffin, Reece - Plant Mechanic	7.00	Remove and replace blown apron hose.
14/11/2013	Griffin, Reece - Plant Mechanic	1.00	Prestart/FGR
14/11/2013	Dawson, Dale - TWC Mechanic	2.00	29915Hrs: R & R cut edge hit teeth/rippers./ 29921Hrs: T'shoot rear trans. faul - R & R front ECU,
15/11/2013	Dawson, Dale - TWC Mechanic	4.00	29915Hrs: R & R cut edge hit teeth/rippers./ 29921Hrs: T'shoot rear trans. faul - R & R front ECU,
15/11/2013	Griffin, Reece - Plant Mechanic	1.00	Prestart/FGR
16/11/2013	Griffin, Reece - Plant Mechanic	1.00	Prestart/FGR
16/11/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk rear trans. fault & drop off parts.
17/11/2013	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
18/11/2013	Griffin, Reece - Plant Mechanic	1.00	Prestart/FGR
19/11/2013	Griffin, Reece - Plant Mechanic	1.00	Prestart/FGR
20/11/2013	Dawson, Dale - TWC Mechanic	1.00	29915Hrs: R & R cut edge hit teeth/rippers./ 29921Hrs: T'shoot rear trans. faul - R & R front ECU,
20/11/2013	Griffin, Reece - Plant Mechanic	1.00	Prestart/FGR
21/11/2013	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
22/11/2013	Dawson, Dale - TWC Mechanic	4.50	29984HRS: Carry out 2000hr service./ Complete 2000hr service to spec's. & pack up waste oil etc.
22/11/2013	Griffin, Reece - Plant Mechanic	5.00	29984HRS: Carry out 2000hr service.

Date	Name	Duration	Notes
25/11/2013	Dawson, Dale - TWC Mechanic	4.00	29984HRS: Carry out 2000hr service./ Complete 2000hr service to spec's. & pack up waste oil etc.
25/11/2013	Griffin, Reece - Plant Mechanic	4.00	Finish 10,000hr service to spec's. & pack up used oil etc.
10/12/2013	Dawson, Dale - TWC Mechanic	5.00	Remove rear eng. fuel pump assy for resealing. Unload pump at w/shop, clean down 7 order parts.
10/12/2013	Griffin, Reece - Plant Mechanic	3.00	Remove rear eng. fuel pump.
14/12/2013	Dawson, Dale - TWC Mechanic	3.00	Install fuel pump to rear motor./ 30096HRS: Locate & repair oil leak - oil pressure too high @ 105
14/12/2013	Griffin, Reece - Plant Mechanic	3.00	30045HRS: Install fuel pump to rear motor.
17/12/2013	Dawson, Dale - TWC Mechanic	2.00	Install fuel pump to rear motor./ 30096HRS: Locate & repair oil leak - oil pressure too high @ 105
06/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & run machine./ Look up & order parts.
07/01/2014	Griffin, Reece - Plant Mechanic	7.50	Commence disassembly of rear eng.. Remove sump, clean up gasket mating surfaces, remove oil pump, c
07/01/2014	Knapman, Kenneth - TWC MECHANIC	3.00	Gouge & weld cracks in bowl, move machine to wasbay.
07/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & run machine./ Look up & order parts.
07/01/2014	Dawson, Dale - TWC Mechanic	1.00	Fit sump to engine./ Start engine, test operation of eng. & test oil pressures.
08/01/2014	Dawson, Dale - TWC Mechanic	2.50	Fit sump to engine./ Start engine, test operation of eng. & test oil pressures.
08/01/2014	Griffin, Reece - Plant Mechanic	9.50	Commence disassembly of rear eng.. Remove sump, clean up gasket mating surfaces, remove oil pump, c
10/01/2014	Dawson, Dale - TWC Mechanic	0.75	Assist work on engine./ Start to reinstall engine - installation cancelled due to crackes being no
10/01/2014	Griffin, Reece - Plant Mechanic	6.50	30101HRS: Install manifold studs in engine, put gasket on, remove air cleaner housing & order parts
11/01/2014	Griffin, Reece - Plant Mechanic	3.00	30101HRS: Install manifold studs in engine, put gasket on, remove air cleaner housing & order parts
13/01/2014	Dawson, Dale - TWC Mechanic	1.00	Assist work on engine./ Start to reinstall engine - installation cancelled due to crackes being no
13/01/2014	Griffin, Reece - Plant Mechanic	4.50	30101HRS: Install manifold studs in engine, put gasket on, remove air cleaner housing & order parts
13/01/2014	Knapman, Kenneth - TWC MECHANIC	2.00	Gouge out & weld up cracks in engine bay. Undercoat weld area.
14/01/2014	Dawson, Dale - TWC Mechanic	1.50	Assist work on engine./ Start to reinstall engine - installation cancelled due to crackes being no
14/01/2014	Griffin, Reece - Plant Mechanic	7.00	30101HRS: Install manifold studs in engine, put gasket on, remove air cleaner housing & order parts
14/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk E stop wiring & start rear engine.
15/01/2014	Dawson, Dale - TWC Mechanic	2.50	Assist work on engine./ Start to reinstall engine - installation cancelled due to crackes being no
15/01/2014	Griffin, Reece - Plant Mechanic	4.50	30101HRS: Install manifold studs in engine, put gasket on, remove air cleaner housing & order parts
21/01/2014	Griffin, Reece - Plant Mechanic	3.00	30101HRS: Assemble-reseal L/H steer ram, mount to machine & run./ Install rear trans harness.
21/01/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Assemble steering ram & refit to machine. pack up reman parts.
22/01/2014	Dawson, Dale - TWC Mechanic	0.50	Install new trans harness.
22/01/2014	Griffin, Reece - Plant Mechanic	2.00	30101HRS: Assemble-reseal L/H steer ram, mount to machine & run./ Install rear trans harness.
23/01/2014	Dawson, Dale - TWC Mechanic	3.50	Locate alternator fault - Alternator light on but alternator charging: Chk & test wiring harness, r
24/01/2014	Dawson, Dale - TWC Mechanic	5.00	Locate alternator fault - Alternator light on but alternator charging: Chk & test wiring harness, r
24/01/2014	Griffin, Reece - Plant Mechanic	2.00	30103HRS: Remove bottom H link pin to inspect bushes. Inspect & order parts to repair movement & rea
24/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Inspect hitch movement, look up & order parts.
30/01/2014	Griffin, Reece - Plant Mechanic	5.50	Remove H link pin, heat bushes, press out bushes, remove front H link pin & jack up dreaft frame./
30/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts. Get Justin Rowe to bore hitch./ Repairs to H link bearings & assemble./ 3010
31/01/2014	Dawson, Dale - TWC Mechanic	4.00	Assembly of hitch, fit hoses to H link, fit bushes hitch posts, assemble hitch.
31/01/2014	Griffin, Reece - Plant Mechanic	6.00	Remove H link pin, heat bushes, press out bushes, remove front H link pin & jack up dreaft frame./
31/01/2014	Knapman, Kenneth - TWC MECHANIC	4.50	Remove handrail for repair, measure king post, Queen post & H link bearing bores. Weld repair & gus
31/01/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Look up & order parts. Get Justin Rowe to bore hitch./ Repairs to H link bearings & assemble./ 3010
03/02/2014	Knapman, Kenneth - TWC MECHANIC	1.75	Remove handrail for repair, measure king post, Queen post & H link bearing bores. Weld repair & gus
03/02/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts. Get Justin Rowe to bore hitch./ Repairs to H link bearings & assemble./ 3010
04/02/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Look up & order parts. Get Justin Rowe to bore hitch./ Repairs to H link bearings & assemble./ 3010
11/02/2014	Griffin, Reece - Plant Mechanic	1.00	Repair flashing light.
14/02/2014	Dawson, Dale - TWC Mechanic	0.50	Adjust idlers on rear motor./ Blow out radiator.
15/02/2014	Dawson, Dale - TWC Mechanic	0.25	Adjust idlers on rear motor./ Blow out radiator.
25/02/2014	Dawson, Dale - TWC Mechanic	1.50	Chk starting fault - Test E stops, restart machine & test operation.
26/02/2014	Knapman, Kenneth - TWC MECHANIC	2.50	Load equipment etc. Weld repair to laser frame.
27/02/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Order steel for repairs to laser frame./ Cut off laser frame, cut & straighten bent section of fram
28/02/2014	Knapman, Kenneth - TWC MECHANIC	9.50	Order steel for repairs to laser frame./ Cut off laser frame, cut & straighten bent section of fram
01/03/2014	Knapman, Kenneth - TWC MECHANIC	9.00	Order steel for repairs to laser frame./ Cut off laser frame, cut & straighten bent section of fram
03/03/2014	Dawson, Dale - TWC Mechanic	1.50	Grind out & weld bail hook frame on rear of machine 1hr, deliver machine to transport contractor ya
13/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & tighten rear fan belts./ Blow out radiators & filters./ 30214HRS: Repairs to a/c system. Chk
14/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & tighten rear fan belts./ Blow out radiators & filters./ 30214HRS: Repairs to a/c system. Chk
15/03/2014	Wilde, David - TWC WORKSHOP MANAGER	4.50	Chk & tighten rear fan belts./ Blow out radiators & filters./ 30214HRS: Repairs to a/c system. Chk

Date	Name	Duration	Notes
19/03/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk & tighten rear fan belts./ Blow out radiators & filters./ 30214HRS: Repairs to a/c system. Chk
20/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	30215HRS: Clean out air & cab filters.
24/03/2014	Dawson, Dale - TWC Mechanic	4.50	250Hr service & complete SOS
02/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	31300HRS: Replace laser receiver cable end.
15/04/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	30,363HRS: Refit push pad.
17/04/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace 2 front bump pads.
24/04/2014	Dawson, Dale - TWC Mechanic	1.00	Remove push pad due to broken bolts in boss mounts./ 30,428 HRS: Chk machie - operator complaining
27/04/2014	Dawson, Dale - TWC Mechanic	2.50	Remove push pad due to broken bolts in boss mounts./ 30,428 HRS: Chk machie - operator complaining
29/04/2014	Knapman, Kenneth - TWC MECHANIC	4.00	Clean push pad. Gouge off bearing blocks. Situate new blocks, preheat & weld in place. Weld other c
02/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Look up & order parts for hyd. control./ 30,482HRS: Chk & repair lights & fan belts./ 30,500HRS: Se
06/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts for hyd. control./ 30,482HRS: Chk & repair lights & fan belts./ 30,500HRS: Se
07/05/2014	Wilde, David - TWC WORKSHOP MANAGER	3.50	Look up & order parts for hyd. control./ 30,482HRS: Chk & repair lights & fan belts./ 30,500HRS: Se
09/05/2014	Wilde, David - TWC WORKSHOP MANAGER	4.00	30,500HRS: Part service & fill out SOS. Chk air leak & replace chk valve./ Repairs to front wiper./
10/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk push pad bolts & hitch pins./ Replace control valve pins.
11/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	30,500HRS: Part service & fill out SOS. Chk air leak & replace chk valve./ Repairs to front wiper./
11/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk push pad bolts & hitch pins./ Replace control valve pins.
12/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	30,500HRS: Part service & fill out SOS. Chk air leak & replace chk valve./ Repairs to front wiper./
15/05/2014	Wilde, David - TWC WORKSHOP MANAGER	6.00	Replace bowl lever rod ends & pins & throttle rod ends. Adjust tyre pressures & rear fan belts. Loa
16/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace bowl lever rod ends & pins & throttle rod ends. Adjust tyre pressures & rear fan belts. Loa
20/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R top vertical pin.
22/05/2014	Dawson, Dale - TWC Mechanic	1.00	Locate starting Fault: Found short in E stop harness - repaired./ Chk hitch pressures, clean a/c fi
24/05/2014	Dawson, Dale - TWC Mechanic	1.00	Locate starting Fault: Found short in E stop harness - repaired./ Chk hitch pressures, clean a/c fi
26/05/2014	Dawson, Dale - TWC Mechanic	1.00	Locate starting Fault: Found short in E stop harness - repaired./ Chk hitch pressures, clean a/c fi
30/06/2014	Dawson, Dale - TWC Mechanic	3.50	Remove hyd. control levers from machine for re-racing & fitting of bell cranks/tie rods./ Re race h
30/06/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove & replace front windscreen.
01/07/2014	Dawson, Dale - TWC Mechanic	3.00	Remove hyd. control levers from machine for re-racing & fitting of bell cranks/tie rods./ Re race h
02/07/2014	Dawson, Dale - TWC Mechanic	2.00	Remove hyd. control levers from machine for re-racing & fitting of bell cranks/tie rods./ Re race h
03/07/2014	Dawson, Dale - TWC Mechanic	3.00	Remove, inspect, rebuild & fit main hyd. relief valve. Fit new poppet & spring. Test hyd. main pres
04/07/2014	Dawson, Dale - TWC Mechanic	2.50	Remove, inspect, rebuild & fit main hyd. relief valve. Fit new poppet & spring. Test hyd. main pres
07/07/2014	Dawson, Dale - TWC Mechanic	1.00	Remove, inspect, rebuild & fit main hyd. relief valve. Fit new poppet & spring. Test hyd. main pres
15/07/2014	Dawson, Dale - TWC Mechanic	1.50	Inspect & repair exhaust leak at turbo, refit guards around turbo.
22/07/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Part washdown. Replace control valve seal & bolts in hitch bracket.
29/07/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Repair muffler cradle.
01/08/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Repair step.
01/08/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	30,621HRS: Chk tyre pressures, blow out radiators, chk over./ 30643HRS: Replace steering. Replace g
04/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	30,621HRS: Chk tyre pressures, blow out radiators, chk over./ 30643HRS: Replace steering. Replace g
05/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	30,621HRS: Chk tyre pressures, blow out radiators, chk over./ 30643HRS: Replace steering. Replace g
08/08/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	30684hrs Build up bail stop.
12/08/2014	Dawson, Dale - TWC Mechanic	1.50	Remove, diagnose & repair A/C System, check hitch gas
13/08/2014	Dawson, Dale - TWC Mechanic	3.50	Install A/C System, vac down, test operation.
13/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up, order parts & pickup
14/08/2014	Dawson, Dale - TWC Mechanic	3.00	30,745HRS: R & R servo cylinder on steer system. R & R A/c circuit braker, inspect fault with rear
14/08/2014	Knapman, Kenneth - TWC MECHANIC	2.50	Remanufacture step.
14/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	31,750HRS: Service./ R & R oil pressure sender & test./ 30,762HRS: Chk all belts & remove & clean o
15/08/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	31,750HRS: Service./ R & R oil pressure sender & test./ 30,762HRS: Chk all belts & remove & clean o
18/08/2014	Dawson, Dale - TWC Mechanic	1.00	30,745HRS: R & R servo cylinder on steer system. R & R A/c circuit braker, inspect fault with rear
19/08/2014	Dawson, Dale - TWC Mechanic	1.50	30,745HRS: R & R servo cylinder on steer system. R & R A/c circuit braker, inspect fault with rear
19/08/2014	Knapman, Kenneth - TWC MECHANIC	2.50	30,762HRS: Remove ejector valve, dismantle, inspect & reassemble & refit to machine.
19/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	31,750HRS: Service./ R & R oil pressure sender & test./ 30,762HRS: Chk all belts & remove & clean o
23/08/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	30,794HRS: R & R exhaust elbow & refit bonnet.
28/08/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	30854HRS: Refix laser cable & chk over./ Chk over & chk front & rear eng. throttle position.
03/09/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	30854HRS: Refix laser cable & chk over./ Chk over & chk front & rear eng. throttle position.
08/09/2014	Knapman, Kenneth - TWC MECHANIC	4.50	Weld latch & locate a/c door. Locate E stop electrical fault.
08/09/2014	Wilde, David - TWC WORKSHOP MANAGER	4.50	30,968HRS: Repair a/c & wiring.

Date	Name	Duration	Notes
11/09/2014	Knapman, Kenneth - TWC MECHANIC	4.50	31,003HRS: Service front eng. & take SOS 1hr. Service rear eng. & take SOS 1.5hrs. Jack up front of
11/09/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	30,997HRS: Turn centre cutting edge, replace oil pressure switch. Remove top vertical pin for repai
13/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	30,997HRS: Turn centre cutting edge, replace oil pressure switch. Remove top vertical pin for repai
15/09/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	30,997HRS: Turn centre cutting edge, replace oil pressure switch. Remove top vertical pin for repai
16/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	30,997HRS: Turn centre cutting edge, replace oil pressure switch. Remove top vertical pin for repai
17/09/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	30,997HRS: Turn centre cutting edge, replace oil pressure switch. Remove top vertical pin for repai
18/09/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repair E stop wiring./ Remove guards & chk for leaks. Remove grease from hitch./ Remove belly guard
19/09/2014	Wilde, David - TWC WORKSHOP MANAGER	4.00	Repair E stop wiring./ Remove guards & chk for leaks. Remove grease from hitch./ Remove belly guard
20/09/2014	Dawson, Dale - TWC Mechanic	0.50	Try to locate cause of engine missfire./ Assist with removing pins./ Tension sump bolts to spec on
20/09/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Remove belly guards. / Remove apron cyl. & disassemble to ascertain wear, reassemble. Remove r/h mu
20/09/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Repair E stop wiring./ Remove guards & chk for leaks. Remove grease from hitch./ Remove belly guard
22/09/2014	Dawson, Dale - TWC Mechanic	0.50	Try to locate cause of engine missfire./ Assist with removing pins./ Tension sump bolts to spec on
22/09/2014	Knapman, Kenneth - TWC MECHANIC	4.00	Remove belly guards. / Remove apron cyl. & disassemble to ascertain wear, reassemble. Remove r/h mu
22/09/2014	Wilde, David - TWC WORKSHOP MANAGER	3.50	Repair E stop wiring./ Remove guards & chk for leaks. Remove grease from hitch./ Remove belly guard
23/09/2014	Dawson, Dale - TWC Mechanic	3.00	Try to locate cause of engine missfire./ Assist with removing pins./ Tension sump bolts to spec on
23/09/2014	Knapman, Kenneth - TWC MECHANIC	9.50	Remove belly guards. / Remove apron cyl. & disassemble to ascertain wear, reassemble. Remove r/h mu
24/09/2014	Dawson, Dale - TWC Mechanic	1.50	Try to locate cause of engine missfire./ Assist with removing pins./ Tension sump bolts to spec on
24/09/2014	Knapman, Kenneth - TWC MECHANIC	8.00	Remove belly guards. / Remove apron cyl. & disassemble to ascertain wear, reassemble. Remove r/h mu
25/09/2014	Dawson, Dale - TWC Mechanic	5.00	Fit water pump, tubes, pipes, manifolds etc. Fill with coolant and commence fitting of panels./ Fit
25/09/2014	Knapman, Kenneth - TWC MECHANIC	6.50	Cut off old extinguisher mount from scraper hook assy. Collect machined parts, make pins. Remove be
25/09/2014	Wilde, David - TWC WORKSHOP MANAGER	9.00	Refit cab door window. Remove top H link & ram. Reseal ram & refir. Look up & order parts.
26/09/2014	Dawson, Dale - TWC Mechanic	1.00	Fit water pump, tubes, pipes, manifolds etc. Fill with coolant and commence fitting of panels./ Fit
29/09/2014	Knapman, Kenneth - TWC MECHANIC	5.50	Cut off old extinguisher mount from scraper hook assy. Collect machined parts, make pins. Remove be
30/09/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Cut off old extinguisher mount from scraper hook assy. Collect machined parts, make pins. Remove be
02/10/2014	Knapman, Kenneth - TWC MECHANIC	4.50	Tidy up refuse from machining of Banana Arm. Remover scraper hook for repairs. Gouge off hook wear
02/10/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove stands & waldways, clean up rubbish.
03/10/2014	Dawson, Dale - TWC Mechanic	2.00	Locate starting fault - Faulty E stop, replacement ordered. T'shoot intermittant trans. fault on re
03/10/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Tidy up refuse from machining of Banana Arm. Remover scraper hook for repairs. Gouge off hook wear
07/10/2014	Dawson, Dale - TWC Mechanic	6.00	Locate starting fault - Faulty E stop, replacement ordered. T'shoot intermittant trans. fault on re
08/10/2014	Dawson, Dale - TWC Mechanic	2.00	Locate starting fault - Faulty E stop, replacement ordered. T'shoot intermittant trans. fault on re
10/10/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Place in shed./ Remove bonnet.
10/10/2014	Dawson, Dale - TWC Mechanic	3.50	Carry out valve set on frontengine./ 31,079hrs: Finish front engine valve set - all required adjust
13/10/2014	Dawson, Dale - TWC Mechanic	6.50	Carry out valve set on frontengine./ 31,079hrs: Finish front engine valve set - all required adjust
13/10/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Place in shed./ Remove bonnet.
15/10/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk hitch gas.
17/10/2014	Dawson, Dale - TWC Mechanic	1.00	31,080HRS: Fit new E stops to Cab & test operation./ Remove, clean, reseal & refit & adjust air-fue
20/10/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk laser system./ Replace dipper switch & fit fire ext. Replace rear light.
21/10/2014	Dawson, Dale - TWC Mechanic	2.50	31,080HRS: Fit new E stops to Cab & test operation./ Remove, clean, reseal & refit & adjust air-fue
21/10/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk laser system./ Replace dipper switch & fit fire ext. Replace rear light.
27/10/2014	Wilde, David - TWC WORKSHOP MANAGER	1.25	Fit tynes.
04/11/2014	Dawson, Dale - TWC Mechanic	0.50	Remove ripper shanks./ Load up & collect parts, travel to site. On arrival, trans fault had ceased,
05/11/2014	Dawson, Dale - TWC Mechanic	1.00	Remove ripper shanks./ Load up & collect parts, travel to site. On arrival, trans fault had ceased,
06/11/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Fit with tynes & inspect machine./ Remove hyd. line & search shed spare parts.
06/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	31,114HRS: Refit tynes.
07/11/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Fit with tynes & inspect machine./ Remove hyd. line & search shed spare parts.
08/11/2014	Dawson, Dale - TWC Mechanic	3.50	Strip down hyd. hose for apron lift, rebuild hose, travel to site, fit hose & test, return to w'sho
10/11/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Make exhaust stay clamps.
13/11/2014	Dawson, Dale - TWC Mechanic	2.00	31,168HRS: R & R steel tube from hitch ride control to bottom king post. Locate accelerator fault -
14/11/2014	Dawson, Dale - TWC Mechanic	0.50	31,168HRS: R & R steel tube from hitch ride control to bottom king post. Locate accelerator fault -
22/11/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	31,250HRS: Service
13/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.25	31,406HRS: Chk over.
17/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	31,452HRS: Blow out radiators.
06/01/2015	Dawson, Dale - TWC Mechanic	3.00	31,485HRS: 500hr service & fir new radio.
08/01/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Direct trans. repairs over phone./ 31,514HRS: Chk & repair broken wiring on compressor. Test & chk

Date	Name	Duration	Notes
09/01/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Direct trans. repairs over phone./ 31,514HRS: Chk & repair broken wiring on compressor. Test & chk
10/01/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Direct trans. repairs over phone./ 31,514HRS: Chk & repair broken wiring on compressor. Test & chk
19/01/2015	Dawson, Dale - TWC Mechanic	1.00	31,610HRS: Fit bolts to seat base. R & R rear eng. fuel filter
22/01/2015	Dawson, Dale - TWC Mechanic	2.00	31,637HRS: R & R corner tips on bowl. Chk, adjust & test nitrogen in suspension accumulators./ Tigh
23/01/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Reassemble spare ejector door floor roller.
24/01/2015	Dawson, Dale - TWC Mechanic	0.50	31,637HRS: R & R corner tips on bowl. Chk, adjust & test nitrogen in suspension accumulators./ Tigh
30/01/2015	Dawson, Dale - TWC Mechanic	1.00	Take SOS on diffs & final drives. / 250hr service on rear eng.
30/01/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over & fuel up. / 31,750HRS: Part service. / Complete service.
03/02/2015	Dawson, Dale - TWC Mechanic	0.50	Take SOS on diffs & final drives. / 250hr service on rear eng.
03/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over & fuel up. / 31,750HRS: Part service. / Complete service.
04/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over & fuel up. / 31,750HRS: Part service. / Complete service.
12/02/2015	Knapman, Kenneth - TWC MECHANIC	0.50	31,845HRS: Gas accumulator. / 31853HRS: Change exhaust-muffler. Change over seat accumulator.
13/02/2015	Knapman, Kenneth - TWC MECHANIC	2.00	31,845HRS: Gas accumulator. / 31853HRS: Change exhaust-muffler. Change over seat accumulator.
13/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace muffler & pipe.
23/02/2015	Dawson, Dale - TWC Mechanic	1.00	Install new head seals to left hand steer ram. / 35,213HRS: Remove broken pin from apron to banana
24/02/2015	Dawson, Dale - TWC Mechanic	2.50	Install new head seals to left hand steer ram. / 35,213HRS: Remove broken pin from apron to banana
26/02/2015	Knapman, Kenneth - TWC MECHANIC	2.50	31,980HRS: Begin 2000hr service (rain interrupted) replace muffler box assembly
26/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	32,000HRS - part service. / Complet service. R & R rear trans cooler hoses - test run.
27/02/2015	Wilde, David - TWC WORKSHOP MANAGER	3.00	32,000HRS - part service. / Complet service. R & R rear trans cooler hoses - test run.
02/03/2015	Knapman, Kenneth - TWC MECHANIC	2.50	31,980HRS: Begin 2000hr service (rain interrupted) replace muffler box assembly
02/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	32,000HRS - part service. / Complet service. R & R rear trans cooler hoses - test run.
05/03/2015	Dawson, Dale - TWC Mechanic	4.50	Locate fault with a/c - failed compressor. Remove compressor & condensor & flush out. R & R receive
05/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace a/c compressor. Blow out radiators. / 32,061HRS: Chk a/c operation. Replace laser receiver
07/03/2015	Dawson, Dale - TWC Mechanic	1.00	Locate fault with a/c - failed compressor. Remove compressor & condensor & flush out. R & R receive
07/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace a/c compressor. Blow out radiators. / 32,061HRS: Chk a/c operation. Replace laser receiver
10/03/2015	Dawson, Dale - TWC Mechanic	1.00	Locate fault with a/c - failed compressor. Remove compressor & condensor & flush out. R & R receive
12/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace 2 fron tyres. / Remove cushion cylinder & dismantle for repair. / Assemble cushion hitch cy
13/03/2015	Wilde, David - TWC WORKSHOP MANAGER	4.00	Replace 2 front tyres. / Remove cushion cylinder & dismantle for repair. / Assemble cushion hitch c
14/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace 2 fron tyres. / Remove cushion cylinder & dismantle for repair. / Assemble cushion hitch cy
17/03/2015	Wilde, David - TWC WORKSHOP MANAGER	5.50	Replace 2 fron tyres. / Remove cushion cylinder & dismantle for repair. / Assemble cushion hitch cy
18/03/2015	Knapman, Kenneth - TWC MECHANIC	7.00	Locate machine into site w'shop, remove hoses & boosters, gouge & weld up crack.
18/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	Replace 2 fron tyres. / Remove cushion cylinder & dismantle for repair. / Assemble cushion hitch cy
19/03/2015	Knapman, Kenneth - TWC MECHANIC	7.50	Set up gear & recommence welding of chassis cross member crack(s) / Complete welding of cracked dif
19/03/2015	Wilde, David - TWC WORKSHOP MANAGER	9.00	Clean up parts & reassemble rear diff. / Refit rear diff to machine. / 32,131HRS: Replace steering
19/03/2015	Dawson, Dale - TWC Mechanic	2.50	Remove l/h rear brake booster from wheel for welding. Chk over machine & assist with welding clean
20/03/2015	Wilde, David - TWC WORKSHOP MANAGER	6.50	Clean up parts & reassemble rear diff. / Refit rear diff to machine. / 32,131HRS: Replace steering
20/03/2015	Knapman, Kenneth - TWC MECHANIC	4.50	Set up gear & recommence welding of chassis cross member crack(s) / Complete welding of cracked dif
24/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	Clean up parts & reassemble rear diff. / Refit rear diff to machine. / 32,131HRS: Replace steering
25/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean up parts & reassemble rear diff. / Refit rear diff to machine. / 32,131HRS: Replace steering
11/04/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adjust L/H rear tyre pressure.
17/04/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	32,210HRS: Chk over unit.
24/04/2015	Dawson, Dale - TWC Mechanic	1.00	32,242HRS: R & R broken idle screw in fuel pump. R & R governor control housing
24/04/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	32,242HRS: Chk front eng. high idle & fuel pressures & boost.
04/05/2015	Dawson, Dale - TWC Mechanic	1.50	Remove fuel pump from rear engine. / Unload & clean fuel pump, drop off for repair.
05/05/2015	Dawson, Dale - TWC Mechanic	0.50	Remove fuel pump from rear engine. / Unload & clean fuel pump, drop off for repair.
25/05/2015	Dawson, Dale - TWC Mechanic	1.00	32,250HRS: Investigate power fault to cab - could not fault.
26/05/2015	Dawson, Dale - TWC Mechanic	1.50	32,261HRS: 250hr service.
28/05/2015	Dawson, Dale - TWC Mechanic	0.50	Fill out SOS
30/05/2015	Dawson, Dale - TWC Mechanic	0.50	Organise parts required.
01/06/2015	Dawson, Dale - TWC Mechanic	1.00	Fit new hyd. hose & new breaker.
11/06/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean dirt from machine. Load onto float.
15/06/2015	Dawson, Dale - TWC Mechanic	7.00	Chk rear eng for any faults to cause rear eng. to stop running on intermittant basis. Chk harnesses
16/06/2015	Dawson, Dale - TWC Mechanic	5.50	Repaired trans leak at front of scraper, repaired bolt holes for step, pump up tyres. Remove fuel p
16/06/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	32,283HRS: Chk laser operation & clean contacts. Clean rear battery terminals.

Date	Name	Duration	Notes
17/06/2015	Dawson, Dale - TWC Mechanic	4.50	Clean manifold mounting face of head, clean exhaust manifold & take for facing. Tap bolt/stud holes
18/06/2015	Dawson, Dale - TWC Mechanic	3.50	Install exhaust manifold assy to rear eng. Fit turbo.
30/06/2015	Dawson, Dale - TWC Mechanic	5.00	Fit pump. Investigate fuel pump with continuing hard start fault on rear engine
02/07/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	32,285HRS: Chk & repair wiring to Navman. Replace control box.
15/07/2015	Knapman, Kenneth - TWC MECHANIC	3.00	Weld cracks in ejector door & push pad block.
10/08/2015	Wilde, David - TWC WORKSHOP MANAGER	3.00	Prestart. Chk & adjust tyre pressures. Adjust rear throttle. Adjust brakes. Replace L/H rear brake
12/08/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	Clean out & wash rear radiator.
25/08/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Replace cab interior lights.
28/09/2015	Dawson, Dale - TWC Mechanic	1.00	Inspect E stop circuit for wiring & power.
08/10/2015	Dawson, Dale - TWC Mechanic	1.50	Install trans control box for rear trans, investigate shift fault with rear transmission.
08/10/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit rear switch box & chk faults.
09/10/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk & replace rear shift card & clean connectors. Test run.
09/10/2015	Dawson, Dale - TWC Mechanic	2.00	Investigate transmission fault - R & R shift card - fault rectified & tested ok.
24/11/2015	Dawson, Dale - TWC Mechanic	0.50	Chk over machine.
05/01/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Place machine into w'shop & grind out cracks in scraper bail hook.
06/01/2016	Knapman, Kenneth - TWC MECHANIC	3.00	Grind out cracks in apron & weld, polish & paint repair. Move machine to wash bay & clean steering
06/01/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R leaking seal in steering ram.
22/01/2016	Dawson, Dale - TWC Mechanic	3.00	Investigate/repair fault with a/c - Evac & fill with nitrogen, chk for leaks - none found, evac nit
01/02/2016	Knapman, Kenneth - TWC MECHANIC	2.00	Move machine into w'shop, hook up a/c guages & chk system. Remove a/c compressor, belts & receiver/
01/02/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk a/c system. Recover gas. Remove dryer & compressor.
02/02/2016	Wilde, David - TWC WORKSHOP MANAGER	5.00	32,298HRS: Remove a/c box & clean out. Fit seals & reassemble to machine.
03/02/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Refit a/c box & connect hoses. Adjust alternator belt.
04/02/2016	Dawson, Dale - TWC Mechanic	1.00	Fit a/c compressor.
04/02/2016	Dawson, Dale - TWC Mechanic	0.50	Recharge a/c with 1.8kg gas.
07/03/2016	Dawson, Dale - TWC Mechanic	1.00	Fit shift card in rear motor.
11/03/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Remove head from ejector cylinder, replace seals & reinstall.
11/03/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk rear trans drive.
14/03/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove rear batteries for charging
16/03/2016	Knapman, Kenneth - TWC MECHANIC	2.00	Fit batteries, clean battery compartment & leads, chk trans. for drive.
17/03/2016	Knapman, Kenneth - TWC MECHANIC	2.00	Remove CPU cover, blow out water, buff cover, seal surface, replace cover & bonnet.
21/03/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Remove fuel supply tube to filter from tfr pump. Replace seal. Chk sump for leak. Locate seal. Drai
22/03/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Remove bracket & bolts in cab. Replace missing bolts in guards.
23/03/2016	Dawson, Dale - TWC Mechanic	2.00	Move machine into w'shop, remove rear bonnets & exhaust assy, inspect turbo - no failure or oil lea
23/03/2016	Knapman, Kenneth - TWC MECHANIC	2.00	32,300HRS: Remove push pad, gouge & weld cracks, reassemble.
24/03/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Finish assembly of push pad.
04/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Prestart & run a/c system. Chk oil leak at turbo.
07/04/2016	Dawson, Dale - TWC Mechanic	4.50	Remove turbo, inspect & clean parts. Install new reman. turbo charge & test operation.
12/04/2016	Dawson, Dale - TWC Mechanic	4.00	Remove injectors 1, 2 & 3 for testing due to oil/fuel build up in exhaust system. Refit to machine.
18/04/2016	Dawson, Dale - TWC Mechanic	0.50	Install shift card to rear trans. & test.
21/04/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Remanufacture exhaust pipe.
07/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
17/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Grease brakes & adjust rear fan belts.
18/05/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit tynes & chk rear fault.
19/05/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart, replace rear shift card & harness, test run.
31/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & chk front batteries.
29/06/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean mud from mudguards.
28/07/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adjust tyre pressures
29/07/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	32,468HRS: R & R front batteries.
12/08/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Part service.
14/08/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	32,500HRS: Complete service.
21/08/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Prep power pack for transport to Griffith.
22/08/2016	Dawson, Dale - TWC Mechanic	2.00	Unbolt rear power pack ready for removal.
22/08/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Unload power pack.
23/08/2016	Dawson, Dale - TWC Mechanic	5.00	Install replacement rear power pack into machine. Repair damaged E stop harness.

Date	Name	Duration	Notes
23/08/2016	Knapman, Kenneth - TWC MECHANIC	4.50	Replace rear power pack.
27/08/2016	Dawson, Dale - TWC Mechanic	1.00	Remount R/H rear guard - bolts coming out.
29/08/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Failed rear motor: Drain coolant & oil from motor, remove radiator & guards.
29/08/2016	Dawson, Dale - TWC Mechanic	1.00	Remove broken bolts from belly plate, fit new bolts.
30/08/2016	Dawson, Dale - TWC Mechanic	1.50	Install new air valves for full RPM control.
31/08/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove fuel pump for repairs.
01/09/2016	Dawson, Dale - TWC Mechanic	8.00	Strip down power pack to rebuild with reman long block.
01/09/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Look up & order parts, collect parts, clean parts, dismantl radiator.
02/09/2016	Dawson, Dale - TWC Mechanic	5.50	Disassemble engine & commence rebuild wth replacement block.
05/09/2016	Dawson, Dale - TWC Mechanic	8.50	Continue wth engine rebuild.
05/09/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to radiator & engine.
06/09/2016	Dawson, Dale - TWC Mechanic	8.50	Continue wth engine rebuild.
08/09/2016	Dawson, Dale - TWC Mechanic	7.00	Finalise assembly of engine rebuild - fit harness guards, alternator, air cleaner assy, etc. Follow
12/09/2016	Dawson, Dale - TWC Mechanic	4.50	Install fuel pump & components, install radiator assy to power pack with fan guards, panels etc.
12/09/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to radiator & find parts.
13/09/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Collect radiator core from repairer & put on transport.
21/09/2016	Dawson, Dale - TWC Mechanic	7.50	Clean & assemble radiator assy following core repairs, fit top tank & bolt down, fill with coolant
22/09/2016	Dawson, Dale - TWC Mechanic	4.00	Remove radiator assy & remove leaking cores - repair failure. Pack up cores & send to Dalby for fur
23/09/2016	Dawson, Dale - TWC Mechanic	2.50	Clean up radiator parts & start re-assembly.
26/09/2016	Dawson, Dale - TWC Mechanic	4.00	Finish re-assembly of radiator, fill with coolant, pressure test & run up engine. pack away tools.
18/10/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Load power pack onto trailer & secure.
19/10/2016	Wilde, David - TWC WORKSHOP MANAGER	5.00	R & R rear power pack.
19/10/2016	Knapman, Kenneth - TWC MECHANIC	5.50	R & R rear power pack.
20/10/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & replace circuit breaker. Test run & chk oil levels. Reconnect shutdown wiring.
27/10/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk rear trans. fault. Remove & clean out control box.
28/10/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Organise refurbishment of rod for push pad buffer.
28/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Adjust rear fan belts, adjust air/fuel ratio.
30/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove blown hose.
02/11/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Refit ejector hose & hitch hose - test run.
17/11/2016	Knapman, Kenneth - TWC MECHANIC	2.50	R & R broken bolt from R/H rear mudguard. organise filters & take SOS
18/11/2016	Knapman, Kenneth - TWC MECHANIC	3.50	250hr service. pack up oil & equipment.
14/01/2017	Knapman, Kenneth - TWC MECHANIC	2.00	Prep weld area.
15/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.25	32,786HRS: Complet service. Chk all belts
18/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart, test run, chk over & grease.
28/03/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk tyre pressures & adjust hitch acc. pressures
29/03/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean out a/c system & cab.
31/03/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove tynes & set up laser receiver.
01/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	32,791HRS: Prestart, grease brake & bail points. Blow out radiator. Fuel up.
02/04/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	32,8802HRS: Prestart, fit tynes, replace apron lift rod end.
04/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Prestart & blow out radiator. Repair throttle control.
05/04/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Prestart, replace blown hose.
06/04/2017	Dawson, Dale - TWC Mechanic	8.00	Locate blown hose, fill machine with hyd. oil & take machine to compound. Remove hose. Travel to Gr
07/04/2017	Dawson, Dale - TWC Mechanic	0.50	Fit replacement ejector hose.
09/04/2017	Dawson, Dale - TWC Mechanic	4.00	Inspect machine, lower belly guards, remove blown hose, travel to Griffith for new hose & return, f
10/04/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Begin hose disassembly, order stem.
11/04/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Remanufacture ejector door hose.
12/04/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Cut out steel for ejector door.
19/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	32,909HRS: Prestart.
22/04/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace rear muffler assy. Chk hyd. hoses. Chk & charge hitch accumulator.
23/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & repair seat adjuster.
03/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
04/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
04/05/2017	Dawson, Dale - TWC Mechanic	5.00	Organise parts & oils for 1,000hr service & load onto service truck. Complete service - 33,000HRS.
05/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR

Date	Name	Duration	Notes
05/05/2017	Dawson, Dale - TWC Mechanic	2.50	Investigate gear change fault - R & R down shift solenoid, clean all plugs on harness, chk wiring e
06/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
08/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
08/05/2017	Dawson, Dale - TWC Mechanic	1.50	Fill out SOSreports for 1,000hr service. Inspect brake booster - not releasing. Inspect guard due t
09/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
09/05/2017	Dawson, Dale - TWC Mechanic	3.00	Investigate rear trans. fault - shift card. remove broken mount bolt for rear R/H guard & refit. Re
10/05/2017	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
17/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace steering hose.
03/06/2017	Knapman, Kenneth - TWC MECHANIC	2.00	Change worn out ejector lever ball joint. R & R broken bolt in grease pump.
09/06/2017	Knapman, Kenneth - TWC MECHANIC	5.50	33,252HRS: Set up for & service rear & front engines. Complete SOS & clean up after services.
14/06/2017	Dawson, Dale - TWC Mechanic	1.50	Investigate fuel fault - fuel pressure down to 5PSI - removed transfer pump.
15/06/2017	Dawson, Dale - TWC Mechanic	5.50	Finish install of fuel transfer pump, fit injector lines brackets etc., flush & clean fuel lines &
16/06/2017	Dawson, Dale - TWC Mechanic	4.00	33,250HRS: Investigate poor eng. performance - found fuel supply low. Check for fuel supply restric
17/06/2017	Dawson, Dale - TWC Mechanic	4.00	33,250HRS: Finish install of fuel line hoses from tank to filter housing, prime fuel, change primin
20/06/2017	Dawson, Dale - TWC Mechanic	0.50	Remove teeth from bowl.
21/06/2017	Dawson, Dale - TWC Mechanic	1.00	Remove trash rack & apron pin.
22/06/2017	Dawson, Dale - TWC Mechanic	2.00	R & R blown hose - hyd. pump output.
27/06/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	33,325HRS: Chk rear trans fault & replace shift card - test run. Refit laser frame.
28/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean grease from hitch.
29/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit tynes.
01/07/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace tyne boot.
02/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove & make up 2 new steering hoses & refit. Chk & adjust seat suspension. Chk & adjust tyre pres
05/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove hitch cylinder & dismantle.
06/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean up hitch parts.
10/07/2017	Knapman, Kenneth - TWC MECHANIC	2.50	Locate parts & equipment - hitch cylinder. Clean & commence assembly.
11/07/2017	Knapman, Kenneth - TWC MECHANIC	4.75	Fit seal to cylinder head & piston & complete assembly. Remove 'H' link. Clean & pack up tools.
15/07/2017	Knapman, Kenneth - TWC MECHANIC	5.00	Replace 'H' link, remove tynes.
17/07/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Top up trans. oil.
18/07/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Remove tynes.
20/07/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Chk over machine, replace alternator retaining nut.
24/07/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Clean up H link.
26/07/2017	Knapman, Kenneth - TWC MECHANIC	5.50	prep "H" link for welding & weld up.
27/07/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Cut off braces. Grind off excess material from welding of crack & bracewelds pallet.
09/08/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	33,472HRS: Prestart & grease. Adjust rear fan belts.
12/08/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Investigate trans. fault.
13/08/2017	Wilde, David - TWC WORKSHOP MANAGER	3.50	33,500HRS: Service. Chk & replace rear trans. shift card.
15/08/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	33,521HRS: Complete service.
17/08/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	33,528HRS: Prestart, wash hitch.
01/09/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	33,605HRS: Replace ejector roller. Clean out 2nd roller & repack grease.
05/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk rear guard damage. Chk trans oil leaks. look up & order parts.
08/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts.
14/11/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Unload from float & move to workshop yard. Chk over.
27/11/2017	Dawson, Dale - TWC Mechanic	3.50	Remove & commence repairs to rear power pack.
27/11/2017	Wilde, David - TWC WORKSHOP MANAGER	5.00	33,737HRS: Remove rear power pack & part wash down.
28/11/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Remove laser frame, hungry board, trash rack, ejector door & ram. Commence repairs to trash rack &
28/11/2017	Dawson, Dale - TWC Mechanic	7.50	Remove ejector door & cylibder, wash rear power pack & commence repairs to power pack - reseal fuel
28/11/2017	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove Trash rack. Laser frame & Ejector door. Clean up parts. Look up & order replacement parts.
29/11/2017	Dawson, Dale - TWC Mechanic	9.00	Drain fuel from tank, reseal quick fill & reseal guarge on tank. R & R air brakeline system on rear
29/11/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Drill out trash rack mount holes & trash rack, straighten trash rack & commence weld repair of ejec
29/11/2017	Wilde, David - TWC WORKSHOP MANAGER	5.00	Dismantle & clean up parts. order replacement parts as required.
30/11/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Staighthen & fit trash rack. Weld repairs to ejector door. Locvate trash rack & bore mounts to 32mm.
30/11/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	Repairs to lift cylinders. Look up & order parts.
01/12/2017	Knapman, Kenneth - TWC MECHANIC	10.00	Set & gouge out dreaft arm crack. Prep area, preheat & weld draft arm. Remove rear right scraper gu
01/12/2017	Dawson, Dale - TWC Mechanic	4.00	Remove hyd. cylinders, strip down, inspect & reseal. Refit together, fit quick drop valves, fit 1 t

Date	Name	Duration	Notes
04/12/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Weld repairs to ejector door & install R/H lift cylinder.
04/12/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove, reseal & refit sequence valve.
05/12/2017	Dawson, Dale - TWC Mechanic	4.00	Fit L/H bowl lift cylinder, fit hyd. hoses, fill oil & test operation.
06/12/2017	Dawson, Dale - TWC Mechanic	3.00	Rebush end caps for bowl lift cylinders. Tidy up hoses etc.
06/12/2017	Knapman, Kenneth - TWC MECHANIC	8.00	Gouge out bearings of bowl lift cylinder mounting blocks. Gouge off & prep push pad side plate. Cut
07/12/2017	Dawson, Dale - TWC Mechanic	1.00	R & R bowl lift ram bearings in end caps that mount cylinders to machine.
07/12/2017	Knapman, Kenneth - TWC MECHANIC	9.00	Fit floor rollers to ejector door. Locate in machine & adjust. Remove door, make adjustments & refi
07/12/2017	Wilde, David - TWC WORKSHOP MANAGER	3.50	Wash & clean up parts.
08/12/2017	Dawson, Dale - TWC Mechanic	1.50	Remove hoses etc. from artic to separate bown from tractor.
08/12/2017	Knapman, Kenneth - TWC MECHANIC	9.00	Finish repair to guard rail & weld repair to ejector door. Prepair tractor for separation from scra
08/12/2017	Wilde, David - TWC WORKSHOP MANAGER	8.50	Wash down. Disconnect tractor from bowl.
09/12/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Disconnect tractor from bowl & shift into w'shop.
11/12/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Remove cushion hitch assy. Begin disassembly of hitch.
11/12/2017	Dawson, Dale - TWC Mechanic	1.50	Remove hitch out of machine.
12/12/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Dismantle hitch assy, remove ejector door & trash rack from shed. Remove bushes from hitch assy etc
12/12/2017	Wilde, David - TWC WORKSHOP MANAGER	7.50	Dismantle hitch for reapirs.
13/12/2017	Dawson, Dale - TWC Mechanic	2.50	Measure up bearing holes for wear/expansion. Load cushion hitch onto trailer for transport for repa
13/12/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Preheat & weld crack in king post.. Prep Queen post for new buffer pad. Preheat & weld new buffer p
13/12/2017	Wilde, David - TWC WORKSHOP MANAGER	9.00	Remove bushes & clean up parts.
14/12/2017	Dawson, Dale - TWC Mechanic	3.00	Evac a/c system, R & R TX valve, recharge system & test - a/c vent temp running at 13°C
14/12/2017	Knapman, Kenneth - TWC MECHANIC	6.00	Remove 'H' linkbushes & measure holes. Remove bottom bush of hitch cylinder & steering links. Measu
14/12/2017	Wilde, David - TWC WORKSHOP MANAGER	5.00	Clean up parts & remove bushes. Look up & order parts.
15/12/2017	Dawson, Dale - TWC Mechanic	2.00	Remove steer control valve.
15/12/2017	Knapman, Kenneth - TWC MECHANIC	8.00	Continue making hitch hoses.
15/12/2017	Wilde, David - TWC WORKSHOP MANAGER	5.00	Remove & replace hyd. hoses under cab. Look up & order parts.
16/12/2017	Dawson, Dale - TWC Mechanic	5.50	Strip down steer control valve & reseal, re-assemble valve (awaiting additional seals)
16/12/2017	Knapman, Kenneth - TWC MECHANIC	5.50	Continue making hitch hoses.
16/12/2017	Wilde, David - TWC WORKSHOP MANAGER	5.50	R & R replace hyd. hoses. Look up & order parts. Remove bushes.
18/12/2017	Dawson, Dale - TWC Mechanic	0.50	Chk through hoses for replacement.
18/12/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	Clean & grease bowl. Part wash down. Remove handrail & steps & guards.
19/12/2017	Dawson, Dale - TWC Mechanic	2.50	Install new hoses.
19/12/2017	Knapman, Kenneth - TWC MECHANIC	3.50	Continue making hitch hoses.
19/12/2017	Wilde, David - TWC WORKSHOP MANAGER	5.50	Look up & order parts, collect parts from supplier & refit hyd. hoses.
20/12/2017	Dawson, Dale - TWC Mechanic	6.50	Install hoses & steer valve under cab & plumb up.
20/12/2017	Knapman, Kenneth - TWC MECHANIC	7.50	Make hyd. hoses for hitch.
20/12/2017	Wilde, David - TWC WORKSHOP MANAGER	6.00	Clean up hitch parts. Pick up & chk off parts.
21/12/2017	Knapman, Kenneth - TWC MECHANIC	7.00	Purchase hose & manufacture replacement hoses. Remove control valve & clean. Look up & order parts.
21/12/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Replace hoses under hitch.
08/01/2018	Dawson, Dale - TWC Mechanic	3.00	Assemble cushion titch - King & Queen Posts.
08/01/2018	Knapman, Kenneth - TWC MECHANIC	7.00	Reseal control valve.
08/01/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	Clean up parts & assemble hitch.
09/01/2018	Dawson, Dale - TWC Mechanic	1.00	Press bushes into steer linkages.
09/01/2018	Knapman, Kenneth - TWC MECHANIC	11.00	Heat & weld plate to King Post for buffer pad. Continue resealing control valve. Make up hyd. hoses
09/01/2018	Wilde, David - TWC WORKSHOP MANAGER	10.50	Clean up parts & assemble hitch.
10/01/2018	Dawson, Dale - TWC Mechanic	8.00	Pressbushes into steer linkages & assemble hitch in readiness for installation. Press bushes into f
10/01/2018	Knapman, Kenneth - TWC MECHANIC	9.50	Reseal cushion hitch valve & install. Disassemble accumulators for resealing. Reassemble accumulato
10/01/2018	Wilde, David - TWC WORKSHOP MANAGER	6.50	Assemble hitch.
11/01/2018	Dawson, Dale - TWC Mechanic	9.00	Assemble hitch, install hoses & pipes & clamps. Collect parts. Set up hitch & install in unit. Fit
11/01/2018	Knapman, Kenneth - TWC MECHANIC	10.00	Fit hyd. lines & linkages to control valve. Hook up hitch assy for lift. Fit hitch assy to tractor,
12/01/2018	Dawson, Dale - TWC Mechanic	4.50	Assembly of hoses, hitch & pipes etc.. Press bushes into frame.
12/01/2018	Knapman, Kenneth - TWC MECHANIC	6.00	Fit hydraulic & electrical lines. Fit steering servo. Remove o/head crane & block hitch.
13/01/2018	Dawson, Dale - TWC Mechanic	4.50	Fit tractor & bowl back together, connect hoses, grease lines etc.
13/01/2018	Knapman, Kenneth - TWC MECHANIC	7.50	Fit auto grease lines to hitch. Prep for tractor connection to scraper. Parts pick up. Press in bus
15/01/2018	Knapman, Kenneth - TWC MECHANIC	3.50	Continue connecting hitch cables & hyd. & grease lines.

Date	Name	Duration	Notes
16/01/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Zip tie grease, Hyd. & electrical lines.
17/01/2018	Knapman, Kenneth - TWC MECHANIC	10.50	Filter Hyd. oil back into tank & top up. Bleed fuel system, start machine & chk over. Wash walk are
18/01/2018	Knapman, Kenneth - TWC MECHANIC	9.50	Fit air tank cover plates (replace pressure relief valve). Swap 2 hitch hoses & fit drive line. Dis
19/01/2018	Knapman, Kenneth - TWC MECHANIC	10.50	Fit belly guards. Drill& tap out broken bolts. Fit power pack bonnet & brake lights. Fit guard rail
20/01/2018	Knapman, Kenneth - TWC MECHANIC	8.50	Clean oil pan & plate, fit oil pick up, gasket & tubing. Refit power pack, fit hook, bonnet, fuel &
22/01/2018	Knapman, Kenneth - TWC MECHANIC	3.50	Replace fire extinguisher, bonnet grommets & bolts. Zip tie electricals, adjust haud. lines. Fit ai
22/01/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	Refit air intake & fire extinguisher. Remove broken pipe brackets. Grease hitch & replace line.
23/01/2018	Knapman, Kenneth - TWC MECHANIC	2.50	R & R broken stud. Replace tube seal. Bleed steering servo & rear belly guard.
23/01/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Bleed steering system & refit belly guard.
24/01/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Straighten cab belly guard & fit to machine. Apply new CAT stickers to draft arm.
24/01/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	Fit new CAT decals to machine. Chk & repair lights.
25/01/2018	Knapman, Kenneth - TWC MECHANIC	9.00	34,750HRS: - Service. Fit mount screws to trans hold switch. Chk lights, order parts. Make & paint
25/01/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	33,746HRS: Prestart, chk & adjust ejector clearances. Test run rear trans.
29/01/2018	Dawson, Dale - TWC Mechanic	3.50	33,745HRS: R & R turbo coolant hoses. R & R door latch, chk over machine & fuel up.
31/01/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Refit shaker clock to machine.
06/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to cooling system.
07/02/2018	Dawson, Dale - TWC Mechanic	2.00	Eash out radiator & repair 2way radio.
07/02/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	Chk cooling system fault. Wash out radiator. Chk grease fault & tighten fillings. Test run.
10/02/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	33,787HRS: Chk start fault & replace starter motor - test run. Refit belly guards & replace screw i
11/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk rear trans fault & test wiring. Replace shift card & test run.
12/02/2018	Dawson, Dale - TWC Mechanic	2.50	Investigate rear trans drive - very intermittant failure - chk harness, start to change out control
12/02/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk rear trans. fault & test wiring.
13/02/2018	Dawson, Dale - TWC Mechanic	6.50	Continue investigation of trans. electrical fault in rear power pack. Fault has become fixed - insp
14/02/2018	Dawson, Dale - TWC Mechanic	2.00	Install new shift card - test operation - send machine to work. No faults apparent with rear trans.
19/02/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	33,847HRS: Blow out rear radiator & air filter.
23/02/2018	Dawson, Dale - TWC Mechanic	6.50	R & R fuel pump on rear engine & complete 2,000Hr service.
23/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	33,895HRS: R & R 4 bowl cylinder hoses. Test run & chk over.
27/02/2018	Dawson, Dale - TWC Mechanic	1.00	33,878HRS: Chk over machine & repair radio. Test operation.
02/03/2018	Dawson, Dale - TWC Mechanic	3.00	Investigate electrical fault. R & R 2 control harnesses, clean plugs due to moisture incursion in p
03/03/2018	Dawson, Dale - TWC Mechanic	1.50	R & R rear engine alternator & batteries.
06/03/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Weld on supports for outlet.
10/03/2018	Knapman, Kenneth - TWC MECHANIC	0.25	Prestart.
10/03/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	33,918HRS: Prestart & chk drive in rear trans.
13/03/2018	Dawson, Dale - TWC Mechanic	0.50	Chk over machine.
15/03/2018	Dawson, Dale - TWC Mechanic	0.50	Repair hyd. oil leak on Artic hose.
19/03/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	34,000HRS: Take SOS.
20/03/2018	Dawson, Dale - TWC Mechanic	1.50	Carry out part 2,000hr service - engines, hydraulics, SOS.
26/03/2018	Dawson, Dale - TWC Mechanic	1.00	Investigate trans. fault - shift card U/S - R & R card.
27/03/2018	Dawson, Dale - TWC Mechanic	1.00	R & R rear eng. oil filter. Repair grease line hitch.
03/04/2018	Dawson, Dale - TWC Mechanic	3.00	Install air tank, adjust brakes etc. Complete trans. oil change (part of 2,000hr service) front & r
09/04/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace oil pressure sender & test run.
24/04/2018	Dawson, Dale - TWC Mechanic	6.50	34,171HRS: Removal of harness over hitch & draft frame. Reinstall harness & guards.
26/04/2018	Dawson, Dale - TWC Mechanic	4.50	Wheel and ejector ram repair
27/04/2018	Dawson, Dale - TWC Mechanic	9.00	Wheel and ejector ram repair
28/04/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	2000 hrs service/hitch repair
01/05/2018	Wilde, David - TWC WORKSHOP MANAGER	4.50	2000 hrs service/hitch repair
03/05/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Brake booster
03/05/2018	Dawson, Dale - TWC Mechanic	0.00	Wheel and ejector ram repair
03/05/2018	Wilde, David - TWC WORKSHOP MANAGER	4.50	brake repair
11/05/2018	Dawson, Dale - TWC Mechanic	2.50	Rebuild brake booster & refit to L/H front of machine.
24/05/2018	Dawson, Dale - TWC Mechanic	2.50	Investigate & repair apron switch, complete chk over all fluids, have R/H tyre resealed & repair he
30/05/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	34,166HRS: Prestsr/FGR. R & R rear fan belts.
14/06/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	34,250HRS: Service machine. Chk & repair grease system. Adjust hitch height. Chk radio wiring.
23/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	34,328HRS: Prestart & adjust rear fan belts.

Date	Name	Duration	Notes
25/06/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Order linkage ball joints.
26/06/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	34,359HRS: Replace control rod end & air drier cartridge.
03/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Order Parts.
05/07/2018	Dawson, Dale - TWC Mechanic	0.50	SOS on power train.
05/07/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	Clean parts & re-assemble 2 brake boosters.
12/07/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	Dismantle & clean up bowl cylinders. Reseal & re-assemble.
13/07/2018	Dawson, Dale - TWC Mechanic	3.50	34,500HRS: 500hr service. Replace front & rear fan belts.
16/07/2018	Dawson, Dale - TWC Mechanic	3.00	R & R apron trunion balls. Remove broken bolt from cap, repair 2way - replace 2way.
16/07/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Weld caps on trunions.
18/07/2018	Dawson, Dale - TWC Mechanic	1.00	R & R rear eng. shift card.
23/07/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Cut spare plates for welding to apron trunions.
24/07/2018	Dawson, Dale - TWC Mechanic	4.50	R & R throttle control linkages. Inspect/investigate trans. intermittent fault. R & R down shift so
27/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	34,579HRS: R & R a/c filters. Chk over.
30/07/2018	Dawson, Dale - TWC Mechanic	1.00	Make up replacement hyd. hoses.
03/08/2018	Dawson, Dale - TWC Mechanic	1.00	R & R HMU.
10/08/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Assemble bowl cylinder.
14/08/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Make up hyd. hose.
15/08/2018	Dawson, Dale - TWC Mechanic	2.00	34,649HRS: R & R hyd. hose on L/H side draft arm. Fit guards & fill oil.
17/08/2018	Dawson, Dale - TWC Mechanic	2.50	Make up spare hyd. hoses.
18/08/2018	Wilde, David - TWC WORKSHOP MANAGER	4.50	Dismantle & clean up parts. Replace rod & reassemble.
20/08/2018	Dawson, Dale - TWC Mechanic	2.00	34,669HRS: Install apron cylinder.
07/09/2018	Dawson, Dale - TWC Mechanic	3.00	34,710HRS: Remove steering & hitch cylinders.
07/09/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	Dismantle hitch cylinder. Look up & price parts. Clean up steering cylinders.
10/09/2018	Dawson, Dale - TWC Mechanic	3.50	34,710HRS: Clean steer ram, strip down, inspect, reseal & reassemble & refit to machine.
11/09/2018	Dawson, Dale - TWC Mechanic	2.50	34,710HRS: Reseal R/H steer ram.
20/09/2018	Knapman, Kenneth - TWC MECHANIC	3.50	Replace cushion hitch cylinder & steering cylinders.
20/09/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	34,710HRS: Refit steering & hitch cylinders. Test run.
19/10/2018	Knapman, Kenneth - TWC MECHANIC	1.00	R & R shift card in rear power pack.
20/10/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Investigate/trace transmission harness fault.
21/10/2018	Knapman, Kenneth - TWC MECHANIC	3.50	34,750HRS: Part service on rear rear engine. Clean up, prep for & complete 2nd half of service. Fil
25/10/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Weld up pin retainer for bail assy
31/10/2018	Dawson, Dale - TWC Mechanic	5.00	34,838HRS: Remove fan & harmonic balancer from rear engine. Investigate cause of hard steering/steer
01/11/2018	Dawson, Dale - TWC Mechanic	3.50	34,858HRS: Install new fan, harmonic balancer etc to rear engine. Fit guards. Fit 2 new temp sender
05/11/2018	Dawson, Dale - TWC Mechanic	1.50	Chk over - chk all rollers, follow up parts for repairs.
07/11/2018	Dawson, Dale - TWC Mechanic	1.00	34,864HRS: Inspect over rear engine for possible causes of dirt entry due to bad SOS.
07/11/2018	Dawson, Dale - TWC Mechanic	0.50	34,865HRS: Install new linkage for cushion hitch ride control.
08/11/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Repair steering column. Chk & adjust rear fan belts. Repair inner guard.
08/11/2018	Dawson, Dale - TWC Mechanic	1.50	34,875HRS: Remove R/H front inner guard & repair.
10/11/2018	Dawson, Dale - TWC Mechanic	4.50	34,890HRS: Investigate oil leak - found eng. oil filter hose leaking. Remove hose, travel to Swan H
12/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	34,906HRS: Replace accumulator valve & recharge.
12/11/2018	Dawson, Dale - TWC Mechanic	0.50	Refuel & clean out front & rear radiators.
13/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	34,915HRS: Remove guard & wash out 2 radiators.
15/11/2018	Dawson, Dale - TWC Mechanic	1.00	Disassemble brake booster.
16/11/2018	Dawson, Dale - TWC Mechanic	2.50	Rebuild brake booster.
19/11/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	34,970HRS: Chk & adjust tyre pressures. Chk hitch & seat accumulator pressures. Replace trans. temp
21/11/2018	Wilde, David - TWC WORKSHOP MANAGER	6.50	35,000HRS: Part service. Replace front shift card & rear control box. Test run.
26/03/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove guards & wash down (weed & seed).
26/03/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Remove guards & wash down (weed & seed)
27/03/2019	Wilde, David - TWC WORKSHOP MANAGER	5.00	Remove guards & wash down (weed & seed).
28/03/2019	Wilde, David - TWC WORKSHOP MANAGER	5.00	Continue with washdown & refit guards.
28/03/2019	Knapman, Kenneth - TWC MECHANIC	5.00	Wash down & refit guards.
29/03/2019	Knapman, Kenneth - TWC MECHANIC	1.25	Load onto float. Under frame inspection.
30/03/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	35,122HRS: Fit tynes & replace rear fan belts.
30/03/2019	Knapman, Kenneth - TWC MECHANIC	2.00	35,122HRS: Fit tynes & replace rear fan belts.

Date	Name	Duration	Notes
02/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR. Shift apron pin.
11/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,204HRS: R & R bowl cylinder hose.
16/04/2019	Wilde, David - TWC WORKSHOP MANAGER	4.50	35,250HRS: Service. Change centre cutting edge.
26/04/2019	Dawson, Dale - TWC Mechanic	1.00	35,295HRS: Repair rear engine oil leak.
27/04/2019	Dawson, Dale - TWC Mechanic	1.50	35,304HRS: Remove blown hyd. hosefrom R/H draft frame ejector circuit.
28/04/2019	Dawson, Dale - TWC Mechanic	4.00	35,304HRS: Travel to supplier & have replacement hyd. hose made, return to site & fit new hose. Ref
02/05/2019	Dawson, Dale - TWC Mechanic	0.50	Investigate & repair electrical fault in transmission.
04/05/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Assemble seat suspension.
11/06/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Dismantle seat for repair.
13/06/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Dismantle seat suspension. Look up & order parts for repair.
14/06/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Reassemble seat suspension.
15/06/2019	Dawson, Dale - TWC Mechanic	5.00	Repair oil leaks on hyd. syste.. R & R air control switch on joy stick for apron.
16/06/2019	Dawson, Dale - TWC Mechanic	3.50	Repair oil leaks on articulation hoses. Chk & adjust tyre pressures. Charge hitch pressures & press
17/06/2019	Dawson, Dale - TWC Mechanic	1.50	R & R seat base in cab.
19/06/2019	Dawson, Dale - TWC Mechanic	2.50	35,423HRS: Fit guards in eng. bay. Repair leak in rear air tank.R & R master switch in front engine
25/06/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	35,432HRS: Replace seat back cushion. Chk & reseal rear relief valve. Fit pin to push pad.
26/06/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart.
30/06/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,467HRS: Replace rear radiator relief valve assy.
01/07/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	35,486HRS: R & R radiator relief valve. Chk apron operation & carry out part service.
02/07/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	35,489HRS: Part service.
03/07/2019	Wilde, David - TWC WORKSHOP MANAGER	3.50	35,500HRS: Complete service. Replace rear throttle diaphragm & adjust. Adjust door catch & seat val
04/07/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	35,500HRS: Replace apron solenoid & test run.
11/07/2019	Dawson, Dale - TWC Mechanic	2.50	39,490HRS: R & R adaptor tube between turbo & muffler box - leaking.
20/07/2019	Dawson, Dale - TWC Mechanic	3.50	Repair broken hand rail, R & R bolt in rear eng. aftercooler. Refit bonnet to eng.
01/08/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove rear power pack.
02/08/2019	Knapman, Kenneth - TWC MECHANIC	7.25	Remove rear power pack. Gouge out cracks in chassis etc.
03/08/2019	Knapman, Kenneth - TWC MECHANIC	5.00	Remove fuel ratio control, helicoil retaining bolt hole & replace control housing. Replace throttle
04/08/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	Repair oil leaks on rear engine.
04/08/2019	Knapman, Kenneth - TWC MECHANIC	3.00	Repair crack in cross member. Remove hyd. tank for crack repair. Remove harness for repair.
05/08/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit hyd. tank & refit rear power pack to machine.
05/08/2019	Knapman, Kenneth - TWC MECHANIC	7.00	Weld trans. oil resevoir crack & refit to power pack. Refit power pack into machine.
06/08/2019	Wilde, David - TWC WORKSHOP MANAGER	2.50	Repair rear harness & test run. Wash out rear radiator.
06/08/2019	Knapman, Kenneth - TWC MECHANIC	1.25	Prestart. Repair & refit wiring harness to machine.
08/08/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Replace isolation switch.
21/08/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit tynes.
22/08/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart.
27/08/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Replace coolant flow switch on rear engine.
28/08/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Trace electrical fault.
29/08/2019	Knapman, Kenneth - TWC MECHANIC	0.25	Prestart.
29/08/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Replace seat O ring seal for seat oil fill.
30/08/2019	Knapman, Kenneth - TWC MECHANIC	0.25	Prestart.
31/08/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Top up transmission oil & refill oil bottles.
01/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart, blow out rear air filter.
03/09/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove push pad & order parts.
03/09/2019	Knapman, Kenneth - TWC MECHANIC	2.50	Remove push pad for repair. Cut off bearing & prep for welding on new part.
04/09/2019	Knapman, Kenneth - TWC MECHANIC	2.00	Weld bearing to push pad.
05/09/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Re-install push pad onto machine.
11/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	35,658HRS: Prestart/FGR
12/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	35,667: Prestart & adjust rear fan belts.
15/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
16/09/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & adjust gear position sensor.
17/09/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,701HRS: Prestart & repair electrical fault.
18/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	35,709HRS: Prestart
19/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR

Date	Name	Duration	Notes
24/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.75	35,724HRS: prestart & remove tynes.
25/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
11/10/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean down machine.
12/10/2019	Wilde, David - TWC WORKSHOP MANAGER	4.50	Clean down machine.
11/11/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove belly guard & chk for leaks.
21/11/2019	Dawson, Dale - TWC Mechanic	1.00	Investigate start fault found in neutral start - switch sticky - repaired.
28/11/2019	Dawson, Dale - TWC Mechanic	2.00	Remove rear power pack and commence washing.
28/11/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Remove power pack.
02/12/2019	Dawson, Dale - TWC Mechanic	0.50	Deliver radiator for servicing.
02/12/2019	Dawson, Dale - TWC Mechanic	1.00	Investigate oil leak - sump leaking. Parts ordered for repair.
04/12/2019	Dawson, Dale - TWC Mechanic	1.00	Remove belly guards.
09/12/2019	Dawson, Dale - TWC Mechanic	4.00	Reseal sump on rear eng., install rear power pack.
10/12/2019	Dawson, Dale - TWC Mechanic	4.50	Finalise installation of rear engine & prep for transport. Investigate rear trans. fault - repair
10/12/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk rear trans fault & change wiring. Chk cutting edges.
11/12/2019	Dawson, Dale - TWC Mechanic	5.00	Remove power pack & commence strip down. Investigate trans. shift fault.
13/12/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	35,758HRS: Chk oil pressure fault. Drop guards & repair wiring. Test run & refit guards.
14/12/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk electrical fault & test run.
18/12/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Investigate rear eng. starting fault. Repair wiring to rear solenoid.
20/12/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
07/01/2020	Dawson, Dale - TWC Mechanic	0.50	Investigate trans. overheating issue - found temp. sender U/S.
08/01/2020	Dawson, Dale - TWC Mechanic	1.00	Remove radiator guards & grill, clean out radiator.
30/01/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,807HRS: R & R rear throttle diaphragm & test run.
17/02/2020	Knapman, Kenneth - TWC MECHANIC	1.50	35,812HRS: Remove radiator.
17/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove front & rear radiators for repair.
18/02/2020	Knapman, Kenneth - TWC MECHANIC	6.50	Remove radiators & front eng. water pump. Remove guards, replace gauge.
18/02/2020	Wilde, David - TWC WORKSHOP MANAGER	3.50	Remove front radiator. Look up & order parts. Replace front & rear senders.
19/02/2020	Knapman, Kenneth - TWC MECHANIC	6.50	Drop guard to access coolant sender. Remove coolant tubing & thermostat. Replace Temp senders. Repl
19/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.50	Repairs to front & rear cooling systems.
20/02/2020	Knapman, Kenneth - TWC MECHANIC	2.00	Fit water pump parts.
20/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace temp. senders & repair coolant leaks.
21/02/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Refit front eng. temp. senders & refit bonnet.
24/02/2020	Wilde, David - TWC WORKSHOP MANAGER	3.50	Clean up parts & reassemble rear radiator.
28/02/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	Connect rear electrical cables & test run. Refit rear guards.
02/03/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	Clean up parts & re-assemble front radiator to machine. Refit guards.
03/03/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove coolant & fuel lines for replacement. Refit radiator guards. Reseal fuel pump.
04/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit fuel lines & fuel pump.
05/03/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Fill coolant & prestart. Chk E stop fault. Remove belly guards & clean.
06/03/2020	Wilde, David - TWC WORKSHOP MANAGER	8.50	35,813HRS: Wash down / repair drive train oil leaks / fit bonnets & belly guards / remove broken bo
10/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace bolts in bail cylinder mount. Refit guards. Repair E stops.
11/03/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	33,813HRS: Chk grease system & clean out injectors.
12/03/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	33,813HRS: Replace grease injectors & test run.
02/07/2020	Knapman, Kenneth - TWC MECHANIC	4.00	35,850HRS: Remove rear power pack. drain engine for sump replacement.
03/07/2020	Knapman, Kenneth - TWC MECHANIC	8.50	35,850HRS: Remove R/H side rear mudguard stay & remove broken bolt. Remove bowl & draft arm guards.
06/07/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Strip guards & undercoat & paint. Paint draft arms. Remove transmission cooler. Assist refit of sum
07/07/2020	Knapman, Kenneth - TWC MECHANIC	6.50	R & R coolant hoses. Clean transmission cooler & refit. Connect lines.
07/07/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace cooling system seals & gaskets. Reseal starter motor.
08/07/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Repair adaptor socket & fit dipstick assay. Fit transmission cooler plug. Remove trans. control valv
08/07/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair hyd. oil leaks.
09/07/2020	Knapman, Kenneth - TWC MECHANIC	6.50	Replace trans. control valve spring & fit to powerpack. Fill with coolant & engine oil. Refit power
09/07/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	Assist with refit of rear engine into machine.
10/07/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Fit guards to bowl, replace air line through draft arm, replace bonnet etc.
10/07/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Finalise assembly of power pack into machine & replace faulty air lines.
14/07/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Fit tube to ejector valve cylinder.
15/07/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Part service.

Date	Name	Duration	Notes
20/07/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R air dryer cartridge. prestart & warm up engines.
24/07/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	35,818HRS: Remove trans. sav. pump, dismantle & inspect. Refir pump & test run.
28/07/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Clean valley of front engine & locate oil leak.
29/07/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove belly guard & replace 2 cooler hoses.
24/11/2020	Knapman, Kenneth - TWC MECHANIC	3.00	Move into w'shop, connect a/c guages. Connect battery charger. Test a/c system.
24/11/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	35,823HRS: Chk & repair a/c system. price parts.
25/11/2020	Knapman, Kenneth - TWC MECHANIC	4.00	Degas a/c, remove a/c box, dismantle & clean/wash parts.
26/11/2020	Knapman, Kenneth - TWC MECHANIC	2.50	Straighten a/c box. Collect parts.
27/11/2020	Knapman, Kenneth - TWC MECHANIC	3.50	Reassemble a/c box with new evaporator, thermostat contraol & TX valve.
30/11/2020	Knapman, Kenneth - TWC MECHANIC	6.00	Vacuum a/c system, add gasConnect heater & a/c lines. Drain Hyd. oil. Disconnect implement/steering
02/12/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Disconnect a/c, tool & cap outlets. Pack up charger.
04/12/2020	Knapman, Kenneth - TWC MECHANIC	7.00	Repalce window latch & stay. Fit cutting edge tynes, change out transfer pump. Cap apron trunnion.
04/12/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	35,826HRS: Prestart/FGR - Chk all lights, change cutting edge & fit tynes, chk tyre pressures.
07/12/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,828HRS: Shift pin in apron. Chk front fault light and order part.
14/12/2020	Knapman, Kenneth - TWC MECHANIC	2.00	R & R fuel line (taken from spare eng. in storage). Replace push pad pin.
14/12/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	35,872HRS: R & R broken fuel line. look up & order parts.
17/12/2020	Knapman, Kenneth - TWC MECHANIC	3.00	Adjust & set transmission spool.
12/01/2021	Knapman, Kenneth - TWC MECHANIC	2.00	35,927HRS: Prestart. Repair hyd. oil leak on seat. Fill hyd. tank. Replace push pad pin & retainer.
12/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	35,930HRS: Chk & repair hyd. leak.
14/01/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Chk tractor final drive plugs & chk possible drive line fault.
15/01/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Replace leaking seat pipe. Chk diff & trans plugs for metal.
23/01/2021	Knapman, Kenneth - TWC MECHANIC	3.50	36,006HRS: load oils etc, travel to jobsite, carryout service & chk final drive magnetic plugs for
23/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	36,000HRS: Service.
28/01/2021	Knapman, Kenneth - TWC MECHANIC	1.50	To jobsite, relocate H link pin & return to w'shop.
29/01/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Clean threads of cushion hitch 'H' link caps. Loctite retaining bolts & tension
29/01/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Replace compressor oil sender switch for E stop.
29/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	36,039HRS: Chk & tighten hitch bolts. Chk batteries. Chk eng. oil leak.
30/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	36,043HRS: R & R front batteries.
01/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	36,046HRS: Chk noise in drive train & chk magnetic plus for metal particles.
02/02/2021	Knapman, Kenneth - TWC MECHANIC	2.50	Chk diff plug for metal particles. Remove blown hyd. hose.
02/02/2021	Wilde, David - TWC WORKSHOP MANAGER	2.50	36,051HRS: Remove blown ejector hose. Chk drive shaft.
03/02/2021	Knapman, Kenneth - TWC MECHANIC	2.50	Make up new hose, collect drive shaft from repairer, travel to jobsite & fit items to machine.
03/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	36,051HRS: Replace ejector hose & drive shaft. Drive machine to w'shop.
04/02/2021	Wilde, David - TWC WORKSHOP MANAGER	6.00	36,065HRS: Part wash down. Remove Trans. & diff ass.
04/02/2021	Knapman, Kenneth - TWC MECHANIC	7.50	Prep for Transmission & diff removal.
05/02/2021	Knapman, Kenneth - TWC MECHANIC	5.00	Remove Trans./diff assy. Separate & disassemble diff. order parts.
05/02/2021	Wilde, David - TWC WORKSHOP MANAGER	5.00	Remove diff & trans. Clean up & inspect parts. Order parts.
08/02/2021	Knapman, Kenneth - TWC MECHANIC	6.50	Disassemble diff components, clean & reassemble.
09/02/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Reassemble diff components.
10/02/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	Reassemble diff.
13/02/2021	Wilde, David - TWC WORKSHOP MANAGER	4.00	Refit axles, covers & belly guards. Connect steering. Assemble seat suspension.
13/02/2021	Knapman, Kenneth - TWC MECHANIC	6.00	Fit guards, hydraulic hoses, steering cylinder. Fill hydraulics oil.
15/02/2021	Wilde, David - TWC WORKSHOP MANAGER	4.50	36,066HRS: Prestart, fill hyd. trans. & diff. oil. Repairs to seat.
16/02/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Chk over machine.
19/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R grease system mount & canister. Repair fuel tank vent.
06/04/2021	Knapman, Kenneth - TWC MECHANIC	5.50	Instal transmission, Change pump, Screens, Fill with oil. Connect pressure guages and start. Check
09/04/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	36118Hrs - Remove tynes and refill bolts to cutting edge
12/04/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	36124Hrs - Check converter outlet pressure and gear change
26/04/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Fit Grease charge pump (Exchange)
26/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	36,141Hrs. Pre start and shit to Workshop. Part wash down.
27/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	36,143Hrs. Wash down and clean windows. Get fire extinguisher checked
27/04/2021	Knapman, Kenneth - TWC MECHANIC	2.00	36,143Hrs. Manufacture and Weld in place Apron TR Union, Retainer plates. Weld repair to safety rai
29/04/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	Shift to rail siding and check oil leaks. Look up and order parts
30/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	36,150Hrs. Remove tyre. Remove worn pipes and clamps. Repair mounting boss

<u>Date</u>	<u>Name</u>	<u>Duration</u>	<u>Notes</u>
03/05/2021	Knapman, Kenneth - TWC MECHANIC	6.00	Travel to Penny's Lane. Fit pipes and hoses. Return to Depot
03/05/2021	Wilde, David - TWC WORKSHOP MANAGER	7.00	36,150Hrs. Refit hyd pipes and hoses and inner guard. Test run
04/05/2021	Knapman, Kenneth - TWC MECHANIC	2.50	Repair / Reseal Grease system
04/05/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	36,150Hrs. Pre start and refit tyre. Clean up mud from site.
12/05/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	36,184Hrs. Remove and replace 2 rear brake boosters and adjust brakes. Test 3 boosters
13/05/2021	Knapman, Kenneth - TWC MECHANIC	4.50	Dismantle 3 brake boosters & inspect. Repair 1 & discard remaining 2.
15/05/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to trans & hyd. over phone.
19/05/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	36,230HRS: Chk bolts in rear radiator.
28/05/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Wait at jobsite entrance for escort onto site. Check fault on machine to be rectified.
21/06/2021	Wilde, David - TWC WORKSHOP MANAGER	5.75	36,250Hrs Service. Check over. Replace bowl level rod end. Look up and order parts. Unload waste oi
29/06/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Unload
29/06/2021	Wilde, David - TWC WORKSHOP MANAGER	3.25	36,281Hrs. Pre start. Shift off site. Load onto float and chain on. Unload at Depot. Part wash down
29/06/2021	Wilde, David - TWC WORKSHOP MANAGER	0.75	Escort to Depot
02/07/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace seat belt and seat back. Check front eng fuel leak. Replace clamp on A/C.
		<u>3,921.75</u>	
	TOTAL	<u>3,921.75</u>	

Total 279 - CAT 637E Scraper:279E