

265 - Cat 627G Scraper:265E

Date	Name	Duration	Notes
05/07/2010	Wilde, David - TWC WORKSHOP MANAGER	5.50	Refit belly guards, replace rear eng. harness, complete 250hr service/Wash down/R & R cutting edges
06/07/2010	Wilde, David - TWC WORKSHOP MANAGER	4.50	Refit belly guards, replace rear eng. harness, complete 250hr service/Wash down/R & R cutting edges
07/07/2010	Wilde, David - TWC WORKSHOP MANAGER	4.50	Refit belly guards, replace rear eng. harness, complete 250hr service/Wash down/R & R cutting edges
09/07/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	Check machine with Downer fitter.
20/07/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	Check electrical connections & tighten, check & remove fault codes
24/07/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	11294hrs - Check A/C & heater operation,check auto grease system
30/08/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	11407 hrs. Check E stops wiring, replace 1 connector. Replace drain valve on rear air tank./ make u
31/08/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	11407 hrs. Check E stops wiring, replace 1 connector. Replace drain valve on rear air tank./ make u
03/09/2010	Wilde, David - TWC WORKSHOP MANAGER	0.50	11439 hrs, check for oil leaks & check rear fan belt (Q988C)
17/09/2010	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R solinoid, check & remove codes, test run.
20/09/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	11500 hr service
24/09/2010	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace fuel filter(s)/11502 hrs, check brake adjustment.
29/09/2010	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace fuel filter(s)/11502 hrs, check brake adjustment.
05/10/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	11557hrs: R & R park brake valve & test, check grease system.
13/10/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	11646hrs; Replace hazzard & wiper switches, check over
27/10/2010	Wilde, David - TWC WORKSHOP MANAGER	2.50	11692hrs: Check electrical fault & remove E stop harness & get repaired, refit & test.
05/11/2010	Wilde, David - TWC WORKSHOP MANAGER	2.50	Load parts & oils: 11750hrs: Service.
11/11/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	Calibrate joystick & test run.
16/12/2010	Wilde, David - TWC WORKSHOP MANAGER	2.00	11869hrs: fit GPS gear/ Change cutting edge, replace rear fan belts, chk final drives & tyre pressu
17/12/2010	Wilde, David - TWC WORKSHOP MANAGER	7.50	11869hrs: fit GPS gear/ Change cutting edge, replace rear fan belts, chk final drives & tyre pressu
01/02/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	12,000hrs: Complete SOS samples
07/02/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	12,000hrs: Complete service, fit GPS cables & receiver, return to w/shop & uload waste oil etc./Chk
09/02/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	12,000hrs: Complete service, fit GPS cables & receiver, return to w/shop & uload waste oil etc./Chk
21/02/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Calibrate joystick
24/02/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R front eng. batteries./Ph. directions to repair engine injector, look up & order parts.
28/02/2011	Bell, Daniel - TWC Manager	6.50	Replace rear engine fuel injector #5
28/02/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	R & R front eng. batteries./Ph. directions to repair engine injector, look up & order parts.
01/03/2011	Bell, Daniel - TWC Manager	1.50	Replace rear engine fuel injector #5
03/03/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	R & R 2 hyd. hoses
19/03/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	12,250hr service & part washdown.
16/05/2011	Bell, Daniel - TWC Manager	2.00	FGR t/shoot electrical system.
16/05/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	Repairs to trans. fault.
25/05/2011	Bell, Daniel - TWC Manager	1.50	Replace seat etc.
09/06/2011	Bell, Daniel - TWC Manager	2.00	500hr service
11/06/2011	Bell, Daniel - TWC Manager	2.00	500hr service
11/06/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	12500hrs: Complete service./Complete SOS samples
14/06/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	12500hrs: Complete service./Complete SOS samples
24/06/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & charge hitch accumulator.
07/07/2011	Bell, Daniel - TWC Manager	2.00	Carry out 250hr service
07/07/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	12750hrs service. R & R ejector roller & rear step.
14/07/2011	Bell, Daniel - TWC Manager	0.00	Replace ejector door roller floor
15/07/2011	Bell, Daniel - TWC Manager	1.00	Replace ejector door roller floor
27/07/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & charge hitch
30/07/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Collect & fit cushions to seat.
15/08/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Load parts & oil./13,000 hrs service, Remove, repair & refit seat.
16/08/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	Load parts & oil./13,000 hrs service, Remove, repair & refit seat.
16/08/2011	Bell, Daniel - TWC Manager	7.50	Carry out 1000hr service
17/08/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Load parts & oil./13,000 hrs service, Remove, repair & refit seat.
18/08/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & charge hitch accumulator, look up & order parts, fill out SOS samples.
19/08/2011	Bell, Daniel - TWC Manager	1.50	Replace cushion hitch accumulator
19/08/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	R & R hitch accumulator & recharge.
17/10/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Fill out Mat sheets

Date	Name	Duration	Notes
14/11/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	13,085hrs: Remove & dismantle hitch cylinder, clean up parts./Assemble hitch cylinder & fit to mach
15/11/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	13,085hrs: Remove & dismantle hitch cylinder, clean up parts./Assemble hitch cylinder & fit to mach
17/11/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Wash down.
09/01/2012	Griffin, Reece - Plant Mechanic	3.00	Prep ready for transport to jobsite
14/02/2012	Bell, Daniel - TWC Manager	4.50	Travel to & from Auscott Narrabri. Replace seat suspension.
17/02/2012	Bell, Daniel - TWC Manager	3.00	Fabricate laser mount.
29/02/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to hydraulics.
01/03/2012	Knapman, Kenneth - TWC MECHANIC	6.00	13,200hrs: Drain hydraulic tank through kidney loop, remove implement/steering pump & return to w/s
02/03/2012	Knapman, Kenneth - TWC MECHANIC	8.50	13,200hrs: Drain hydraulic tank through kidney loop, remove implement/steering pump & return to w/s
03/03/2012	Knapman, Kenneth - TWC MECHANIC	0.50	13,200hrs: Drain hydraulic tank through kidney loop, remove implement/steering pump & return to w/s
10/03/2012	Griffin, Reece - Plant Mechanic	1.75	Carry out service
10/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	13,250 hrs service./ Chk fuel leak, look up & order parts./ 13,268hrs: Replace fuel filter housing,
12/03/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	13,250 hrs service./ Chk fuel leak, look up & order parts./ 13,268hrs: Replace fuel filter housing,
13/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	13,250 hrs service./ Chk fuel leak, look up & order parts./ 13,268hrs: Replace fuel filter housing,
24/03/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk hitch gas.
29/03/2012	Griffin, Reece - Plant Mechanic	1.00	Install new injector line.
29/03/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R #1 injector line & clamp./ 13423hrs: R & R hitch pump, clean out screen & test run.
02/04/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R #1 injector line & clamp./ 13423hrs: R & R hitch pump, clean out screen & test run.
04/04/2012	Bell, Daniel - TWC Manager	2.00	Reseal & replace hitch pump fitting.
11/04/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Repair adjust cushion hitch.
11/04/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk hitch pressure & operation, adjust linkage
12/04/2012	Wilde, David - TWC WORKSHOP MANAGER	6.00	Chk & repair electrical fault, look up & order parts./ 13,500hrs service./ Replace hitch hose.
13/04/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Take SOS samples from final drives & both engines, repair fuel cap./ Disassemble hyd. hose.
14/04/2012	Griffin, Reece - Plant Mechanic	2.50	500hr service
14/04/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & repair electrical fault, look up & order parts./ 13,500hrs service./ Replace hitch hose.
16/04/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Take SOS samples from final drives & both engines, repair fuel cap./ Disassemble hyd. hose.
16/04/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & repair electrical fault, look up & order parts./ 13,500hrs service./ Replace hitch hose.
19/04/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	R & R hitch harness, chk oil leak & remove drive shaft, look up & order parts./ Replace drive shaft
20/04/2012	Griffin, Reece - Plant Mechanic	0.50	Install new hoses under machine & re install shaft.
20/04/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	R & R hitch harness, chk oil leak & remove drive shaft, look up & order parts./ Replace drive shaft
01/05/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	13,550hrs: R & R steering valve.
08/05/2012	Griffin, Reece - Plant Mechanic	2.00	travel & meet David with ET Coms adaptor.
08/05/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Chk hyd. pressures & change relief valve, calibrate joystick.
09/05/2012	Griffin, Reece - Plant Mechanic	6.50	travel & meet David with ET Coms adaptor.
11/05/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Calibrate implement solenoids & chk coils.
28/05/2012	Wilde, David - TWC WORKSHOP MANAGER	7.50	Load parts, tools etc. Travel to Auscott Narrabri check hyd pump pressures & seal in reducing valve
29/05/2012	Wilde, David - TWC WORKSHOP MANAGER	6.50	Load parts, tools etc. Travel to Auscott Narrabri check hyd pump pressures & seal in reducing valve
29/05/2012	Griffin, Reece - Plant Mechanic	7.50	Assist Dave change out hyd pumps
12/06/2012	Griffin, Reece - Plant Mechanic	2.00	Calibrate joystick.
30/06/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	13,750hrs: carry out service (Auscott) & return to w/shop.
02/07/2012	Dawson, Dale - TWC Mechanic	1.00	R & R centre cutting edge.
04/07/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Drop belly guard. Source oil leak. Remove hose. purchase oils and hose. Replace radio.
05/07/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Look up parts for steering lines, finish hose reassembly/installation, order parts from Hastings.
26/07/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Manufacture screen mount./Drop belly guards & return machine to wash bay.
30/07/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Manufacture screen mount./Drop belly guards & return machine to wash bay.
31/07/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Manufacture screen mount./Drop belly guards & return machine to wash bay.
02/08/2012	Griffin, Reece - Plant Mechanic	0.50	Chk final drive oils./ Re routed auto grease system.
03/08/2012	Dawson, Dale - TWC Mechanic	4.50	Inspect trans. oil, leak found between 2 housings, fit new shift card to rear trans, fir new fuel f
03/08/2012	Griffin, Reece - Plant Mechanic	2.50	Chk final drive oils./ Re routed auto grease system.
06/08/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Look up & order parts, replace rear step./ Remove follow up adjuster, reseal & refit./ 13,817hrs: R
07/08/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Look up & order parts, replace rear step./ Remove follow up adjuster, reseal & refit./ 13,817hrs: R
08/08/2012	Wilde, David - TWC WORKSHOP MANAGER	9.00	Look up & order parts, replace rear step./ Remove follow up adjuster, reseal & refit./ 13,817hrs: R
09/08/2012	Dawson, Dale - TWC Mechanic	7.00	Drain trans. oils, remove rear housing, reseal & refit, refill oils, fit belly plate etc, oressure
09/08/2012	Griffin, Reece - Plant Mechanic	4.00	22,356hrs:Put guards on scape, start to assemble grease lines./ Install belly guards on machine./ R

Date	Name	Duration	Notes
09/08/2012	Wilde, David - TWC WORKSHOP MANAGER	5.50	13,817hrs: R & R transfer case seals, remove guards & loosen bolts./ Remove & replace cab mounts,
10/08/2012	Dawson, Dale - TWC Mechanic	8.50	Drain trans. oils, remove rear housing, reseal & refit, refill oils, fit belly plate etc, oressure
10/08/2012	Wilde, David - TWC WORKSHOP MANAGER	9.50	13,817hrs: R & R transfer case seals, remove guards & loosen bolts./ Remove & replace cab mounts,
10/08/2012	Griffin, Reece - Plant Mechanic	7.00	22,356hrs:Put guards on scape, start to assemble grease lines./ Install belly guards on machine./ R
11/08/2012	Dawson, Dale - TWC Mechanic	4.50	Drain trans. oils, remove rear housing, reseal & refit, refill oils, fit belly plate etc, oressure
11/08/2012	Wilde, David - TWC WORKSHOP MANAGER	4.50	13,817hrs: R & R transfer case seals, remove guards & loosen bolts./ Remove & replace cab mounts,
13/08/2012	Dawson, Dale - TWC Mechanic	1.50	Drain trans. oils, remove rear housing, reseal & refit, refill oils, fit belly plate etc, oressure
13/08/2012	Griffin, Reece - Plant Mechanic	2.00	22,356hrs:Put guards on scape, start to assemble grease lines./ Install belly guards on machine./ R
21/08/2012	Knapman, Kenneth - TWC MECHANIC	6.00	Remove apron cylinder base mount & bearings. order parts./ Press in bushes for banana arm, fit catw
22/08/2012	Dawson, Dale - TWC Mechanic	0.50	Measure up apron cylinder bearing bosses for wear, cylinder to be removed & repaired.
22/08/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Remove apron cylinder base mount & bearings. order parts./ Press in bushes for banana arm, fit catw
23/08/2012	Dawson, Dale - TWC Mechanic	2.00	Remove apron cylinder for reboring of bearing bosses./ Cleaned, reseal & reassemble apron cylinder,
23/08/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Remove & disassemble apron cylinder./ Remove draft arm mounts, disconnect air, oil & fuel lines to
24/08/2012	Knapman, Kenneth - TWC MECHANIC	3.50	Remove & disassemble apron cylinder./ Remove draft arm mounts, disconnect air, oil & fuel lines to
24/08/2012	Dawson, Dale - TWC Mechanic	3.00	Remove apron cylinder for reboring of bearing bosses./ Cleaned, reseal & reassemble apron cylinder,
27/08/2012	Knapman, Kenneth - TWC MECHANIC	3.50	Remove & disassemble apron cylinder./ Remove draft arm mounts, disconnect air, oil & fuel lines to
27/08/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	13,817hrs: Refit apron pipe & clamps, fill hyd. tank
30/08/2012	Dawson, Dale - TWC Mechanic	1.00	Go through Navman installation with Navman technician to try and fix fault./ Remove apron door for
31/08/2012	Dawson, Dale - TWC Mechanic	4.00	Go through Navman installation with Navman technician to try and fix fault./ Remove apron door for
03/09/2012	Dawson, Dale - TWC Mechanic	6.00	Go through Navman installation with Navman technician to try and fix fault./ Remove apron door for
03/09/2012	Knapman, Kenneth - TWC MECHANIC	3.50	Straighten apron side, remove bearing caps, begin gouging off apron bearing./ Gouge off & weld on n
03/09/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to apron./ 13,820hrs: Chk a/c pressures & hitch acc. pressures, chk & repair all lights & w
04/09/2012	Knapman, Kenneth - TWC MECHANIC	9.00	Straighten apron side, remove bearing caps, begin gouging off apron bearing./ Gouge off & weld on n
05/09/2012	Dawson, Dale - TWC Mechanic	7.00	Go through Navman installation with Navman technician to try and fix fault./ Remove apron door for
05/09/2012	Griffin, Reece - Plant Mechanic	3.00	Adjusted brakes, chk over machine, a/c, accumulator pressure, lights, alarms, cab & switches.
05/09/2012	Knapman, Kenneth - TWC MECHANIC	4.50	Straighten apron side, remove bearing caps, begin gouging off apron bearing./ Gouge off & weld on n
05/09/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	Repairs to apron./ 13,820hrs: Chk a/c pressures & hitch acc. pressures, chk & repair all lights & w
06/09/2012	Griffin, Reece - Plant Mechanic	7.00	Change all diff & final drive oils, complete service on front & back diffs & all final drives
06/09/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	Wash down. Chk brake release
07/09/2012	Dawson, Dale - TWC Mechanic	0.50	Fit new seat belt.
11/09/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	Wash down. Chk brake release
23/09/2012	Bell, Daniel - TWC Manager	2.00	Final check over machines & load for transport.
17/10/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	Look up & order parts.
21/11/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	14,000hrs service
21/11/2012	Griffin, Reece - Plant Mechanic	3.00	14,000hrs service
22/11/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	Look up & order parts
19/12/2012	Dawson, Dale - TWC Mechanic	1.50	Clean radiator cores (front & rear), inspect horn, R & R grease nipple.
10/01/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	14,248hrs: Chk overheating, blow out rear radiator & tighten rear fan belts./ Chk & repair wiring h
12/01/2013	Griffin, Reece - Plant Mechanic	4.00	14,272hrs: Regas hitch - not regreasing - injector faulty, chk hitch sensor problem
14/01/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	14,248hrs: Chk overheating, blow out rear radiator & tighten rear fan belts./ Chk & repair wiring h
17/01/2013	Knapman, Kenneth - TWC MECHANIC	2.00	250hrs service
17/01/2013	Griffin, Reece - Plant Mechanic	2.00	Carry out 250hr service.
14/02/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	14,500hrs: Part service./ Complete SOS's/ 14,453Hrs: Replace bolts in laser cable, adjust rear fan
14/02/2013	Dawson, Dale - TWC Mechanic	1.50	14,448Hrs; R & R air filters, trans filters, complete SOS.
15/02/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	14,500hrs: Part service./ Complete SOS's/ 14,453Hrs: Replace bolts in laser cable, adjust rear fan
20/02/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	14,500hrs: Part service./ Complete SOS's/ 14,453Hrs: Replace bolts in laser cable, adjust rear fan
25/02/2013	Griffin, Reece - Plant Mechanic	1.50	Remove lasers & poles ready for transport.
28/02/2013	Griffin, Reece - Plant Mechanic	5.50	Remove L/H front wheel guard, remove rear engine guards & bonnets./ Remove drive shaft, remove rear
28/02/2013	Knapman, Kenneth - TWC MECHANIC	1.00	Attempt to remove bail hook./Gouge out scraper hook pins./ Make part for hitch./ Manufacture transm
01/03/2013	Dawson, Dale - TWC Mechanic	9.50	Commence disassembly for repairs - drain oils from rear components, remove rear engine, remove doo
01/03/2013	Griffin, Reece - Plant Mechanic	9.50	Remove L/H front wheel guard, remove rear engine guards & bonnets./ Remove drive shaft, remove rear
01/03/2013	Wilde, David - TWC WORKSHOP MANAGER	8.00	14,490Hrs: Remove rear eng. assy & look up parts./ Remove radiator & hitch./ Remove all oils, trans
01/03/2013	Knapman, Kenneth - TWC MECHANIC	3.00	Attempt to remove bail hook./Gouge out scraper hook pins./ Make part for hitch./ Manufacture transm
02/03/2013	Dawson, Dale - TWC Mechanic	3.50	Commence disassembly for repairs - drain oils from rear components, remove rear engine, remove doo

Date	Name	Duration	Notes
02/03/2013	Griffin, Reece - Plant Mechanic	2.50	Remove L/H front wheel guard, remove rear engine guards & bonnets./ Remove drive shaft, remove rear
02/03/2013	Wilde, David - TWC WORKSHOP MANAGER	8.00	14,490Hrs: Remove rear eng. assy & look up parts./ Remove radiator & hitch./ Remove all oils, trans
02/03/2013	Knapman, Kenneth - TWC MECHANIC	1.50	Attempt to remove bail hook./Gouge out scraper hook pins./ Make part for hitch./ Manufacture transm
04/03/2013	Griffin, Reece - Plant Mechanic	7.50	Remove L/H front wheel guard, remove rear engine guards & bonnets./ Remove drive shaft, remove rear
04/03/2013	Dawson, Dale - TWC Mechanic	9.50	Commence disassembly for repairs - drain oils from rear components, remove rear engine, remove doo
04/03/2013	Wilde, David - TWC WORKSHOP MANAGER	7.50	14,490Hrs: Remove rear eng. assy & look up parts./ Remove radiator & hitch./ Remove all oils, trans
04/03/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Attempt to remove bail hook./Gouge out scraper hook pins./ Make part for hitch./ Manufacture transm
05/03/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Attempt to remove bail hook./Gouge out scraper hook pins./ Make part for hitch./ Manufacture transm
05/03/2013	Griffin, Reece - Plant Mechanic	8.50	Remove L/H front wheel guard, remove rear engine guards & bonnets./ Remove drive shaft, remove rear
05/03/2013	Wilde, David - TWC WORKSHOP MANAGER	7.50	14,490Hrs: Remove rear eng. assy & look up parts./ Remove radiator & hitch./ Remove all oils, trans
05/03/2013	Dawson, Dale - TWC Mechanic	10.00	Commence disassembly for repairs - drain oils from rear components, remove rear engine, remove doo
06/03/2013	Griffin, Reece - Plant Mechanic	9.50	Remove L/H front wheel guard, remove rear engine guards & bonnets./ Remove drive shaft, remove rear
06/03/2013	Knapman, Kenneth - TWC MECHANIC	4.00	Attempt to remove bail hook./Gouge out scraper hook pins./ Make part for hitch./ Manufacture transm
06/03/2013	Wilde, David - TWC WORKSHOP MANAGER	9.00	14,490Hrs: Remove rear eng. assy & look up parts./ Remove radiator & hitch./ Remove all oils, trans
07/03/2013	Griffin, Reece - Plant Mechanic	8.50	Dismantle cushion hitch, remove bearings from hitch & chassis, tapped out for measuring & washed hi
07/03/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Repalce motor fan bearings, rear eng. oil seal, air cleaner, turbo hose. Remove water pump, make up
07/03/2013	Wilde, David - TWC WORKSHOP MANAGER	8.50	Dismantle & tag all hoses./ Remove & tag Hyd. hoses, look up & order parts, refit ejector ram./ Ass
08/03/2013	Dawson, Dale - TWC Mechanic	8.00	Disassemble rear final drive, remove brakes assy, clean & fit new S cams & bearings./ Strip down fi
08/03/2013	Griffin, Reece - Plant Mechanic	9.50	Dismantle cushion hitch, remove bearings from hitch & chassis, tapped out for measuring & washed hi
08/03/2013	Knapman, Kenneth - TWC MECHANIC	7.50	Repalce motor fan bearings, rear eng. oil seal, air cleaner, turbo hose. Remove water pump, make up
08/03/2013	Wilde, David - TWC WORKSHOP MANAGER	6.50	Dismantle & tag all hoses./ Remove & tag Hyd. hoses, look up & order parts, refit ejector ram./ Ass
09/03/2013	Dawson, Dale - TWC Mechanic	4.50	Disassemble rear final drive, remove brakes assy, clean & fit new S cams & bearings./ Strip down fi
09/03/2013	Griffin, Reece - Plant Mechanic	4.00	Dismantle cushion hitch, remove bearings from hitch & chassis, tapped out for measuring & washed hi
09/03/2013	Knapman, Kenneth - TWC MECHANIC	5.00	Repalce motor fan bearings, rear eng. oil seal, air cleaner, turbo hose. Remove water pump, make up
09/03/2013	Wilde, David - TWC WORKSHOP MANAGER	5.00	Dismantle & tag all hoses./ Remove & tag Hyd. hoses, look up & order parts, refit ejector ram./ Ass
11/03/2013	Griffin, Reece - Plant Mechanic	7.50	Dismantle cushion hitch, remove bearings from hitch & chassis, tapped out for measuring & washed hi
11/03/2013	Knapman, Kenneth - TWC MECHANIC	8.00	Repalce motor fan bearings, rear eng. oil seal, air cleaner, turbo hose. Remove water pump, make up
11/03/2013	Dawson, Dale - TWC Mechanic	9.50	Disassemble rear final drive, remove brakes assy, clean & fit new S cams & bearings./ Strip down fi
11/03/2013	Wilde, David - TWC WORKSHOP MANAGER	9.00	Dismantle & tag all hoses./ Remove & tag Hyd. hoses, look up & order parts, refit ejector ram./ Ass
12/03/2013	Dawson, Dale - TWC Mechanic	9.00	Disassemble rear final drive, remove brakes assy, clean & fit new S cams & bearings./ Strip down fi
12/03/2013	Knapman, Kenneth - TWC MECHANIC	6.00	Repalce motor fan bearings, rear eng. oil seal, air cleaner, turbo hose. Remove water pump, make up
12/03/2013	Wilde, David - TWC WORKSHOP MANAGER	5.50	Dismantle & tag all hoses./ Remove & tag Hyd. hoses, look up & order parts, refit ejector ram./ Ass
12/03/2013	Griffin, Reece - Plant Mechanic	5.00	Dismantle cushion hitch, remove bearings from hitch & chassis, tapped out for measuring & washed hi
13/03/2013	Dawson, Dale - TWC Mechanic	8.50	Disassemble rear final drive, remove brakes assy, clean & fit new S cams & bearings./ Strip down fi
13/03/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Repalce motor fan bearings, rear eng. oil seal, air cleaner, turbo hose. Remove water pump, make up
14/03/2013	Dawson, Dale - TWC Mechanic	10.00	Complete assembly of fron diff & set diff bearing pre-load & backlash, commence cleaning & inspecti
14/03/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Fit brake air lines, fit two brake valves & slack adjusters, remove & refurbish brake relay valve,
14/03/2013	Wilde, David - TWC WORKSHOP MANAGER	8.00	Reassemble r/h front wheel & final drive, remove l/h front final drive, clean up parts./ Replace pi
15/03/2013	Dawson, Dale - TWC Mechanic	10.50	Complete assembly of fron diff & set diff bearing pre-load & backlash, commence cleaning & inspecti
15/03/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Fit brake air lines, fit two brake valves & slack adjusters, remove & refurbish brake relay valve,
15/03/2013	Wilde, David - TWC WORKSHOP MANAGER	8.50	Reassemble r/h front wheel & final drive, remove l/h front final drive, clean up parts./ Replace pi
16/03/2013	Knapman, Kenneth - TWC MECHANIC	4.50	Fit brake air lines, fit two brake valves & slack adjusters, remove & refurbish brake relay valve,
16/03/2013	Wilde, David - TWC WORKSHOP MANAGER	4.50	Reassemble r/h front wheel & final drive, remove l/h front final drive, clean up parts./ Replace pi
18/03/2013	Dawson, Dale - TWC Mechanic	8.50	Complete assembly of fron diff & set diff bearing pre-load & backlash, commence cleaning & inspecti
18/03/2013	Knapman, Kenneth - TWC MECHANIC	8.50	Fit brake air lines, fit two brake valves & slack adjusters, remove & refurbish brake relay valve,
19/03/2013	Knapman, Kenneth - TWC MECHANIC	6.00	Fit brake air lines, fit two brake valves & slack adjusters, remove & refurbish brake relay valve,
19/03/2013	Dawson, Dale - TWC Mechanic	9.00	Complete assembly of fron diff & set diff bearing pre-load & backlash, commence cleaning & inspecti
19/03/2013	Griffin, Reece - Plant Mechanic	5.00	Install rear trans on engine & plumb hoses, start to attach trans/hyd tank./ Install wiring harness
20/03/2013	Dawson, Dale - TWC Mechanic	10.50	Complete assembly of fron diff & set diff bearing pre-load & backlash, commence cleaning & inspecti
20/03/2013	Griffin, Reece - Plant Mechanic	9.50	Install rear trans on engine & plumb hoses, start to attach trans/hyd tank./ Install wiring harness
20/03/2013	Knapman, Kenneth - TWC MECHANIC	1.00	Fit brake air lines, fit two brake valves & slack adjusters, remove & refurbish brake relay valve,
21/03/2013	Dawson, Dale - TWC Mechanic	10.50	Remove engine components from old 3406E & install to new 3406E, reseal with new O ring gaskets etc,
21/03/2013	Griffin, Reece - Plant Mechanic	9.25	Assemble retarder housing, reseal scavenger pump, oredor parts, disassemble retarder control valv
21/03/2013	Knapman, Kenneth - TWC MECHANIC	4.50	Press in bushes of Queen post, order seals for hitch valve, disassemble hitch cylinder, source & pu

Date	Name	Duration	Notes
22/03/2013	Dawson, Dale - TWC Mechanic	6.50	Remove engine components from old 3406E & install to new 3406E, reseal with new O ring gaskets etc.
22/03/2013	Griffin, Reece - Plant Mechanic	7.50	Assemble retarder housing, reseal scavenger pump, order parts, disassemble retarder control valve
23/03/2013	Knapman, Kenneth - TWC MECHANIC	6.00	Press in bushes of Queen post, order seals for hitch valve, disassemble hitch cylinder, source & pu
25/03/2013	Knapman, Kenneth - TWC MECHANIC	8.00	Press in bushes of Queen post, order seals for hitch valve, disassemble hitch cylinder, source & pu
26/03/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Press in bushes of Queen post, order seals for hitch valve, disassemble hitch cylinder, source & pu
27/03/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Press in bushes of Queen post, order seals for hitch valve, disassemble hitch cylinder, source & pu
28/03/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Make tool for tensioning horizontal hitch pins, tension pins, fit hyd. hoses to control valve, repl
28/03/2013	Wilde, David - TWC WORKSHOP MANAGER	9.50	Assemble hitch & hoses, assemble trans. to diff./ Continue assembly of engine etc.
02/04/2013	Dawson, Dale - TWC Mechanic	8.50	Continue assembly of engine.
02/04/2013	Knapman, Kenneth - TWC MECHANIC	8.50	Make tool for tensioning horizontal hitch pins, tension pins, fit hyd. hoses to control valve, repl
02/04/2013	Wilde, David - TWC WORKSHOP MANAGER	9.50	Assemble hitch & hoses, assemble trans. to diff./ Continue assembly of engine etc.
03/04/2013	Dawson, Dale - TWC Mechanic	10.50	Continue assembly of engine.
03/04/2013	Knapman, Kenneth - TWC MECHANIC	8.50	Make tool for tensioning horizontal hitch pins, tension pins, fit hyd. hoses to control valve, repl
04/04/2013	Dawson, Dale - TWC Mechanic	9.00	Continue assembly of engine./ Fit spiders & uni's to drive shaft, reshim torque bar for diff, fit h
04/04/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Fit bailhook to machine, make hyd. hoses & fit to machine, collect parts & fit hoses to machine, re
05/04/2013	Knapman, Kenneth - TWC MECHANIC	7.50	Fit bailhook to machine, make hyd. hoses & fit to machine, collect parts & fit hoses to machine, re
05/04/2013	Dawson, Dale - TWC Mechanic	6.50	Continue assembly of engine./ Fit spiders & uni's to drive shaft, reshim torque bar for diff, fit h
06/04/2013	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove & chk L/H rear wheel shim clearance. Refit fuel lines & hoses./ assemble engine into machine
08/04/2013	Griffin, Reece - Plant Mechanic	2.00	Install rear axle housing, fill diff with oil.
08/04/2013	Knapman, Kenneth - TWC MECHANIC	6.50	Fit bailhook to machine, make hyd. hoses & fit to machine, collect parts & fit hoses to machine, re
08/04/2013	Wilde, David - TWC WORKSHOP MANAGER	8.00	Remove & chk L/H rear wheel shim clearance. Refit fuel lines & hoses./ assemble engine into machine
09/04/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Fit bailhook to machine, make hyd. hoses & fit to machine, collect parts & fit hoses to machine, re
09/04/2013	Wilde, David - TWC WORKSHOP MANAGER	9.50	Remove & chk L/H rear wheel shim clearance. Refit fuel lines & hoses./ assemble engine into machine
10/04/2013	Knapman, Kenneth - TWC MECHANIC	6.00	Fit bailhook to machine, make hyd. hoses & fit to machine, collect parts & fit hoses to machine, re
10/04/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove & chk L/H rear wheel shim clearance. Refit fuel lines & hoses./ assemble engine into machine
11/04/2013	Dawson, Dale - TWC Mechanic	7.00	Assembly of hoses & organise parts, fit axles to finals, fill finals with oil./ Assembly of machine
11/04/2013	Wilde, David - TWC WORKSHOP MANAGER	9.50	Assemble tractor to bowl & connect hoses & wiring./ Refit hoses, chk & fill all oil compartments, t
12/04/2013	Dawson, Dale - TWC Mechanic	8.50	Assembly of hoses & organise parts, fit axles to finals, fill finals with oil./ Assembly of machine
12/04/2013	Wilde, David - TWC WORKSHOP MANAGER	6.50	Assemble tractor to bowl & connect hoses & wiring./ Refit hoses, chk & fill all oil compartments, t
13/04/2013	Wilde, David - TWC WORKSHOP MANAGER	5.50	Assemble tractor to bowl & connect hoses & wiring./ Refit hoses, chk & fill all oil compartments, t
15/04/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Make mount for Trimble box./ Assist with removal of flywheel, assit with reinstallation of retarder
15/04/2013	Wilde, David - TWC WORKSHOP MANAGER	5.50	Assemble tractor to bowl & connect hoses & wiring./ Refit hoses, chk & fill all oil compartments, t
16/04/2013	Knapman, Kenneth - TWC MECHANIC	2.50	Make mount for Trimble box./ Assist with removal of flywheel, assit with reinstallation of retarder
16/04/2013	Wilde, David - TWC WORKSHOP MANAGER	3.50	Assemble tractor to bowl & connect hoses & wiring./ Refit hoses, chk & fill all oil compartments, t
17/04/2013	Knapman, Kenneth - TWC MECHANIC	8.50	Make mount for Trimble box./ Assist with removal of flywheel, assit with reinstallation of retarder
17/04/2013	Wilde, David - TWC WORKSHOP MANAGER	9.50	Assemble tractor to bowl & connect hoses & wiring./ Refit hoses, chk & fill all oil compartments, t
18/04/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Remove broken stud, fir pipe to machine.
18/04/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit GPS & shift sensor./ Refit belly guards, change rear eng. oil & filters, test run, chk all ligh
19/04/2013	Wilde, David - TWC WORKSHOP MANAGER	5.00	Fit GPS & shift sensor./ Refit belly guards, change rear eng. oil & filters, test run, chk all ligh
13/05/2013	Dawson, Dale - TWC Mechanic	3.00	Complete calibration of joy stick & hydraulic solenoid, locate & repair fault with trans. gear loc
29/05/2013	Dawson, Dale - TWC Mechanic	1.50	Locate & repair Navman wiring error.
04/06/2013	Knapman, Kenneth - TWC MECHANIC	1.00	Chk tyre pressures & fluid levels, move to Wood's yard ready for transport./ Travel to jobsite, top
05/06/2013	Knapman, Kenneth - TWC MECHANIC	1.50	Chk tyre pressures & fluid levels, move to Wood's yard ready for transport./ Travel to jobsite, top
06/06/2013	Dawson, Dale - TWC Mechanic	2.00	Chk operation of rear motor coolant flow sensor, inspect E stop on rear motor - not working.
13/06/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	Collect machine from Wood's yard. Chk over & take SOS. / 14,513HRS: Calibrate joystick & valves. Ch
14/06/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Calibrate joystick./ Assist with hyd. pressure chks./ Assist locate & repair quick drop fault.
14/06/2013	Wilde, David - TWC WORKSHOP MANAGER	4.50	Collect machine from Wood's yard. Chk over & take SOS. / 14,513HRS: Calibrate joystick & valves. Ch
17/06/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Calibrate joystick./ Assist with hyd. pressure chks./ Assist locate & repair quick drop fault.
17/06/2013	Wilde, David - TWC WORKSHOP MANAGER	6.00	Collect machine from Wood's yard. Chk over & take SOS. / 14,513HRS: Calibrate joystick & valves. Ch
18/06/2013	Dawson, Dale - TWC Mechanic	7.50	Work on quick drop fault & hydraulics, electrical tests.
18/06/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	Collect machine from Wood's yard. Chk over & take SOS. / 14,513HRS: Calibrate joystick & valves. Ch
19/06/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Calibrate joystick./ Assist with hyd. pressure chks./ Assist locate & repair quick drop fault.
20/06/2013	Dawson, Dale - TWC Mechanic	1.50	Complete joystick calibration & hyd. control valve solinoid calibration.
01/07/2013	Dawson, Dale - TWC Mechanic	3.00	R & R hydraulic sequence valve from hyd. control valve, test & set pressure.

Date	Name	Duration	Notes
15/07/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk fluid levels & charge batteries./ Replace trans light.
16/07/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk fluid levels & charge batteries./ Replace trans light.
19/07/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk oil & fuel levels, remove rear batteries & leads, look up & order parts, shift to Woods' yard./
22/07/2013	Griffin, Reece - Plant Mechanic	1.50	Put new batteries in rear engine.
22/07/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk oil & fuel levels, remove rear batteries & leads, look up & order parts, shift to Woods' yard./
13/08/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over for leaks & tighten rear belts.
20/08/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Travel to job, R & R water trap bowl & bleed fuel system, test run.
18/09/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk oil & coolant levels, start & run.
09/11/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & charge hitch accumulator./ 14530Hrs: Fit laser receiver & post.
11/11/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & charge hitch accumulator./ 14530Hrs: Fit laser receiver & post.
19/11/2013	Dawson, Dale - TWC Mechanic	0.50	14607HRS: Test & adjust a/c gas levels.
25/11/2013	Dawson, Dale - TWC Mechanic	1.00	Locate fault with GPS - chk'd wiring loom, changed harness to module, changed module - fault still
25/11/2013	Griffin, Reece - Plant Mechanic	1.00	Locate GPS fault - chk'd wiring looms, swapped over - no change with fault./ Locate & repair starti
26/11/2013	Dawson, Dale - TWC Mechanic	0.75	Locate fault with GPS - chk'd wiring loom, changed harness to module, changed module - fault still
26/11/2013	Griffin, Reece - Plant Mechanic	0.75	Locate GPS fault - chk'd wiring looms, swapped over - no change with fault./ Locate & repair starti
27/11/2013	Dawson, Dale - TWC Mechanic	1.00	Locate fault with GPS - chk'd wiring loom, changed harness to module, changed module - fault still
27/11/2013	Griffin, Reece - Plant Mechanic	1.00	Locate GPS fault - chk'd wiring looms, swapped over - no change with fault./ Locate & repair starti
28/11/2013	Dawson, Dale - TWC Mechanic	1.00	Repaired oil leak on bowl lift cylinder hose./ 14667HRS: Install GPS cable & test operation. Clean
28/11/2013	Dawson, Dale - TWC Mechanic	1.00	Unwrap old GPS harnes of pigtail & fit to new harness./14675HRS: Locate start fault - repair wirin
02/12/2013	Dawson, Dale - TWC Mechanic	2.00	Repaired oil leak on bowl lift cylinder hose./ 14667HRS: Install GPS cable & test operation. Clean
03/12/2013	Dawson, Dale - TWC Mechanic	1.00	Unwrap old GPS harnes of pigtail & fit to new harness./14675HRS: Locate start fault - repair wirin
03/12/2013	Griffin, Reece - Plant Mechanic	1.00	14657HRS: Locate & repair start fault - loose wire to starter motor.
11/12/2013	Dawson, Dale - TWC Mechanic	2.00	14750HRS: Complete 250hr service.
11/12/2013	Griffin, Reece - Plant Mechanic	2.00	14750HRS: Complete 250hr service.
25/01/2014	Dawson, Dale - TWC Mechanic	6.50	Inspect machine, repair brake lights, repair 2 worklights, R & R outer cutting edges, complete wash
25/01/2014	Griffin, Reece - Plant Mechanic	6.50	14809HRS: Inspect machine, repair brake lights, complete washdown & clean cab.
25/01/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Load up pressure cleaner & travel to Togo. Unload & travel to Moree
05/02/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk over.
11/02/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace bolts in seat.
18/02/2014	Dawson, Dale - TWC Mechanic	6.50	Chk noise coming from rear eng. Found blown exhaust manifold gasket on No 1 cylinder, organise & co
18/02/2014	Griffin, Reece - Plant Mechanic	4.50	R & R blown exhaust manifold gasket on rear eng.
14/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Blow out radiators & filters./ Chk & repair wiring to flashing light. Chk rear eng. isolator./ 1496
17/03/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Blow out radiators & filters./ Chk & repair wiring to flashing light. Chk rear eng. isolator./ 1496
18/03/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Blow out radiators & filters./ Chk & repair wiring to flashing light. Chk rear eng. isolator./ 1496
20/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	14978HRS: Clean out air & cab filters.
23/03/2014	Dawson, Dale - TWC Mechanic	8.50	15003HRS: 1000Hr service & complete SOS./ 15015HRS: R & R fuel lines from transfer to magnetic tube
24/03/2014	Dawson, Dale - TWC Mechanic	1.00	Inspect fuel leak in rear eng. - fuel line rubbed through - machine tagged & parked up until repair
25/03/2014	Dawson, Dale - TWC Mechanic	1.50	15003HRS: 1000Hr service & complete SOS./ 15015HRS: R & R fuel lines from transfer to magnetic tube
29/03/2014	Dawson, Dale - TWC Mechanic	1.50	15037HRS: R & R hyd. hose on bowl lift cylinder.
29/03/2014	Griffin, Reece - Plant Mechanic	1.50	15,037HRS: R & R hyd. hose on bowl lift cylinder./ Move position of bowl lift cylinder to avoid clo
31/03/2014	Griffin, Reece - Plant Mechanic	0.50	15,037HRS: R & R hyd. hose on bowl lift cylinder./ Move position of bowl lift cylinder to avoid clo
02/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	15074HRS: Repair fuel leak on rear eng.
07/04/2014	Dawson, Dale - TWC Mechanic	1.50	Get 2 new tyres from storage area & load onto trailer. Fuel ute ready to transport to Griffith.
07/04/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Organise beadbreakerto go to Griffith.
07/04/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to tyre./ 15103HRS: Remove & clean up & refit L/H front tyre.
08/04/2014	Wilde, David - TWC WORKSHOP MANAGER	5.00	Repairs to tyre./ 15103HRS: Remove & clean up & refit L/H front tyre.
08/04/2014	Griffin, Reece - Plant Mechanic	1.50	Fit new tyre to L/H front of machine.
15/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	15,132HRS: Chk laser receiver & cable.
24/04/2014	Dawson, Dale - TWC Mechanic	0.50	Repair diesel leak on fuel system of rear motor./ Calibrate joystick.
28/04/2014	Dawson, Dale - TWC Mechanic	0.50	Repair diesel leak on fuel system of rear motor./ Calibrate joystick.
01/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Look up & order hyd. hose./ R & R hyd. hose.
06/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order hyd. hose./ R & R hyd. hose.
08/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	15260HRS: Replace receiver cable connector./ Chk & repair auto grease system./ Chk & grease hitch.
11/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	15260HRS: Replace receiver cable connector./ Chk & repair auto grease system./ Chk & grease hitch.

Date	Name	Duration	Notes
12/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	15260HRS: Replace receiver cable connector./ Chk & repair auto grease system./ Chk & grease hitch.
13/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	15260HRS: Replace receiver cable connector./ Chk & repair auto grease system./ Chk & grease hitch.
20/05/2014	Dawson, Dale - TWC Mechanic	1.00	Remove front wheel/tyre./ R & R front right tyre, clean cab, clean machine, repair auto grease syst
20/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	Remove L/H front tyre./ 15,333hrs: Change R/H front tyre, chk & charge hitch, wash down.
21/05/2014	Dawson, Dale - TWC Mechanic	5.00	Remove front wheel/tyre./ R & R front right tyre, clean cab, clean machine, repair auto grease syst
21/05/2014	Wilde, David - TWC WORKSHOP MANAGER	6.00	Remove L/H front tyre./ 15,333hrs: Change R/H front tyre, chk & charge hitch, wash down.
23/05/2014	Dawson, Dale - TWC Mechanic	2.50	Chk over lights, buzzers etc, R & R reverse alarm. R & R fire extinguishers./
16/06/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	15,414HRS: Chk & adjust rear fan belts. Turn centre cutting edge, chk GPS cable.
21/06/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	15,450HRS: R & R steering hose. Repair wiring on flashing light./ 15,471HRS: Locate electrical faul
24/06/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	15,450HRS: R & R steering hose. Repair wiring on flashing light./ 15,471HRS: Locate electrical faul
27/06/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	15,500HRS: Complete service. Fill out SOS. Repair coolant leak.
04/07/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	15,550HRS: Chk rear harness fault & clean connectors. Chk 2way operation./ 15,554HRS: R & R router
05/07/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	15,550HRS: Chk rear harness fault & clean connectors. Chk 2way operation./ 15,554HRS: R & R router
07/07/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	15,550HRS: Chk rear harness fault & clean connectors. Chk 2way operation./ 15,554HRS: R & R router
14/07/2014	Dawson, Dale - TWC Mechanic	1.50	15,600HRS: R & R rear motor throttle control valve & air chamber. Locate fault & complete front eng
16/07/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	15,613HRS: Refit hand rail. Chk throttle lock for air leaks.
23/07/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk cutting edges.
31/07/2014	Dawson, Dale - TWC Mechanic	1.00	Clean off dirt etc.
26/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	15,661HRS: Turn centre cutting edge. Chk ejector circuit.
29/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	15665HRS: Chk & adjust hitch gas. Calibrate joy stick. Chk for fault codes./ make up cutting edge &
01/09/2014	Dawson, Dale - TWC Mechanic	2.00	15675HRS: Refuel from fuel trailer, R & R cutting edge, gas cushion hitch./ Fill fuel trailer, refu
01/09/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	15665HRS: Chk & adjust hitch gas. Calibrate joy stick. Chk for fault codes./ make up cutting edge &
02/09/2014	Dawson, Dale - TWC Mechanic	1.50	15675HRS: Refuel from fuel trailer, R & R cutting edge, gas cushion hitch./ Fill fuel trailer, refu
02/09/2014	Dawson, Dale - TWC Mechanic	1.00	Refuel & R & R cutting edge./ Refuel & R & R cutting edge
03/09/2014	Dawson, Dale - TWC Mechanic	1.00	Refuel & R & R cutting edge./ Refuel & R & R cutting edge
04/09/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Wash down.
05/09/2014	Wilde, David - TWC WORKSHOP MANAGER	4.00	Wash down.
15/10/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	chk hitch gas.
17/10/2014	Dawson, Dale - TWC Mechanic	3.00	15,700HRS: Complete valve set on front eng. & fit guards etc./ Complete engine valve set on rear en
20/10/2014	Dawson, Dale - TWC Mechanic	5.50	15,700HRS: Complete valve set on front eng. & fit guards etc./ Complete engine valve set on rear en
20/10/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Get fire ext. chk'd. Chk laser system./ Refit fire ext. & chk lights.
21/10/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Get fire ext. chk'd. Chk laser system./ Refit fire ext. & chk lights.
23/10/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Set up base station & test reurn systems.
31/10/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit GPS & laser receiver.
06/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.25	15,739HRS: Chk over machine./ 15,750HRS: Service./ Chk electrical faults, clean out front & rear ra
08/11/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	15,739HRS: Chk over machine./ 15,750HRS: Service./ Chk electrical faults, clean out front & rear ra
10/11/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	15,739HRS: Chk over machine./ 15,750HRS: Service./ Chk electrical faults, clean out front & rear ra
11/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & clean rear trans connectors.
13/11/2014	Dawson, Dale - TWC Mechanic	1.00	Unit running hot - cleaned out radiators.
13/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & repair GPS Cable
21/11/2014	Knapman, Kenneth - TWC MECHANIC	2.00	Weld laser frame & plate post.
27/11/2014	Knapman, Kenneth - TWC MECHANIC	1.00	R & R cutting edge./ 15,940HRS: Load-unload welding gear. Remove circuit breaker bracket, weld & re
27/11/2014	Dawson, Dale - TWC Mechanic	0.50	Inspect machine data system with ET for any faults.
01/12/2014	Knapman, Kenneth - TWC MECHANIC	5.00	R & R cutting edge./ 15,940HRS: Load-unload welding gear. Remove circuit breaker bracket, weld & re
01/12/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	15,940HRS: Chk & adjust rear fan belts. Chk & repair rear electrical fault. Look up & order parts.
06/12/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	16,000HRS service. Chk hitch gas & replace bowl cylinder bushes./ 16,000HRS: Remove GPS cable. Comp
06/12/2014	Dawson, Dale - TWC Mechanic	4.50	Complete 2000hr service. R & R bushes in lift ram for bowl.
08/12/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	16,000HRS service. Chk hitch gas & replace bowl cylinder bushes./ 16,000HRS: Remove GPS cable. Comp
09/12/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	16,000HRS service. Chk hitch gas & replace bowl cylinder bushes./ 16,000HRS: Remove GPS cable. Comp
15/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.25	16,010hrs: Blow out radiators.
09/01/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	16,108HRS: Chk & clean rear trans plug./ 16,127hrs: Chk rear eng start problem. R & R starter motor
13/01/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	16,108HRS: Chk & clean rear trans plug./ 16,127hrs: Chk rear eng start problem. R & R starter motor
14/01/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	16,108HRS: Chk & clean rear trans plug./ 16,127hrs: Chk rear eng start problem. R & R starter motor
16/01/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & clean out GPS connectors.

Date	Name	Duration	Notes
28/01/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	16,220HRS: Remove & chk joystick for ware. order parts.
30/01/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Remove joystick for replacement - reinstall old joystick - new part incompatible./ Disassemble floo
03/02/2015	Knapman, Kenneth - TWC MECHANIC	2.50	Remove joystick for replacement - reinstall old joystick - new part incompatible./ Disassemble floo
17/02/2015	Dawson, Dale - TWC Mechanic	0.50	Clean out radiator.
27/02/2015	Knapman, Kenneth - TWC MECHANIC	1.50	16,490HRS: Begin 500hr service. Replace filters, take engine & trans SOS>
28/02/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk hitch gas.
09/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.75	Chk & clean GPS cable. Blow out radiators. / 5,177HRS: Chk over & blow out radiators./ Remove push
10/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & clean GPS cable. Blow out radiators. / 5,177HRS: Chk over & blow out radiators./ Remove push
11/03/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Remove push pad & return to w'shop.
11/03/2015	Knapman, Kenneth - TWC MECHANIC	7.00	Remove broken studs, run thread tap through stud holes. Order parts.
11/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & clean GPS cable. Blow out radiators. / 5,177HRS: Chk over & blow out radiators./ Remove push
12/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Refit push pad. / Chk & adjust brakes. Replace grease system adaptor plate
13/03/2015	Dawson, Dale - TWC Mechanic	3.00	R & R seat back cushion, remove joystick, rebuild with new pivot-bearing assy, refit to machine, in
16/03/2015	Dawson, Dale - TWC Mechanic	1.00	R & R seat back cushion, remove joystick, rebuild with new pivot-bearing assy, refit to machine, in
17/03/2015	Dawson, Dale - TWC Mechanic	2.50	R & R seat back cushion, remove joystick, rebuild with new pivot-bearing assy, refit to machine, in
18/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit push pad. / Chk & adjust brakes. Replace grease system adaptor plate
20/03/2015	Dawson, Dale - TWC Mechanic	3.00	Remove split steel tube, take to w'shop, clean & weld up, return & refit to machine. / Investigate
25/03/2015	Dawson, Dale - TWC Mechanic	1.00	Remove split steel tube, take to w'shop, clean & weld up, return & refit to machine. / Investigate
26/03/2015	Dawson, Dale - TWC Mechanic	0.50	Chk fault codes 30.248.09 & 27.248.09 etc - chkd harness, isolated restart procedure - faults clea
02/04/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Travel to Ski Park jobsite, inspect crack in ejector door & return to w'shop.
10/04/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R rear fan belts. / 16,750hrs: Service.
15/04/2015	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R rear fan belts. / 16,750hrs: Service.
18/04/2015	Dawson, Dale - TWC Mechanic	3.00	Remove joystick control & disassemble, fit new rubber boot to control, reassemble, refit & test. R
20/04/2015	Dawson, Dale - TWC Mechanic	1.50	Remove joystick control & disassemble, fit new rubber boot to control, reassemble, refit & test. R
28/04/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	16,780HRS: Take SOS, change oil filter on rear eng.
06/05/2015	Dawson, Dale - TWC Mechanic	1.50	Removal of panels, guards & bonnet, GPS cables.
06/05/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Gouge out & weld crack in ejector door.
06/05/2015	Wilde, David - TWC WORKSHOP MANAGER	5.00	Wash down. Remove guards & covers. Fit GPS cable.
07/05/2015	Knapman, Kenneth - TWC MECHANIC	2.50	Weld repairs to bonnet & paint.
07/05/2015	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R GPS harness & test run. / Fit GPS cable. Refit guards & reassemble cab. Test run. Refit cab w
08/05/2015	Wilde, David - TWC WORKSHOP MANAGER	4.50	R & R GPS harness & test run. / Fit GPS cable. Refit guards & reassemble cab. Test run. Refit cab w
08/05/2015	Dawson, Dale - TWC Mechanic	4.00	Complete engine valve set on rear motor. / Locate & repair sensor fault with transmission guage.
11/05/2015	Wilde, David - TWC WORKSHOP MANAGER	4.50	R & R GPS harness & test run. / Fit GPS cable. Refit guards & reassemble cab. Test run. Refit cab w
13/05/2015	Dawson, Dale - TWC Mechanic	0.50	Complete engine valve set on rear motor. / Locate & repair sensor fault with transmission guage.
13/05/2015	Wilde, David - TWC WORKSHOP MANAGER	3.50	R & R GPS harness & test run. / Fit GPS cable. Refit guards & reassemble cab. Test run. Refit cab w
15/05/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove old GPS harness. Rap new harness.
16/05/2015	Dawson, Dale - TWC Mechanic	1.00	Fit bonnet & muffler, bolt doen repaired threads in bonnet mount.
16/05/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	Refit GPS cable & test run.
18/05/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & adjust tyre pressures. Chk hitch gas, chk & repair lights. Repair hose clamps.
19/05/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace rubber hose clamps. Replace bulbs & chk lights.
29/06/2015	Dawson, Dale - TWC Mechanic	1.50	R & R gear shift control stick. R & R rear engine oil breather - leaking.
28/07/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Check front transmission screens and test run machine.16866hrs
30/07/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Check trans pressures & operation. Take trans oil sample.16867hrs
03/08/2015	Dawson, Dale - TWC Mechanic	4.00	Test all front transmission oil pressures - all with in specs. Replace RHSF brake booster
05/08/2015	Dawson, Dale - TWC Mechanic	1.00	Test all front transmission oil pressures - all with in specs. Replace RHSF brake booster
16/09/2015	Dawson, Dale - TWC Mechanic	3.50	17,000HRS: 1,000hr service as per dealer specs. Remove GPS harness.
16/09/2015	Knapman, Kenneth - TWC MECHANIC	4.00	17,000HRS: Complete 1,000hr service.
17/09/2015	Dawson, Dale - TWC Mechanic	3.50	Repair GPS control harness & test.
17/09/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Fill out SOS paperwork.
18/09/2015	Dawson, Dale - TWC Mechanic	1.50	17,000HRS: Install repaired GPS harness.
13/10/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Change cutting edge & measure bowl side sheeting for replacement.
14/10/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Obtain steel sheeting to replace wear plates in bowl.
15/02/2016	Dawson, Dale - TWC Mechanic	4.00	Investigate reported missfire with front eng. Complete injector cut out test under load, at idle, h
18/03/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	17,122HRS: R & R centre cutting edge.

Date	Name	Duration	Notes
23/03/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk isolator & starter motor.
24/03/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	17,142HRS: R & R starter motor. Test run, refit guards.
14/04/2016	Knapman, Kenneth - TWC MECHANIC	7.50	Modify/remanufacture muffler. Gouge off bowl side plates. Purchase BIS plate, grind off welds in bo
14/04/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	Part wash down to remove grease from hitch.
15/04/2016	Knapman, Kenneth - TWC MECHANIC	8.50	Cut & fit wear sheets to bowl sides, weld in place.
18/04/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Finish welding side plates in bowl, heat & straighten corner tips of apron, weld cracks, fit cutti
18/04/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	Partial wash down, repair air leaks.
19/04/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Assist chk fuel supply lines.
19/04/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove & clean out fuel lines & fittings. Bleed fuel system.
22/04/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk engine performance, fuel pressure & fule lines for restrictions.
04/05/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk front trans pressures.
17/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Grease brakes & adjust rear fan belts.
22/05/2016	Dawson, Dale - TWC Mechanic	4.00	Investigate faulte codes 27.248.02, 30.248.09 & 37.248.09 - No CAT Data link - chk harness connecti
24/05/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Cut replacement plate for step & repair.
31/05/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Repairs to seat.
02/06/2016	Wilde, David - TWC WORKSHOP MANAGER	2.75	Chk & clean harness connectors. Chk fault codes & look up & order parts.
29/06/2016	Wilde, David - TWC WORKSHOP MANAGER	4.50	Clean mud from mudguards. Replace harness through bowl.
30/06/2016	Wilde, David - TWC WORKSHOP MANAGER	2.25	Prestart & clean mud from wheels.
05/07/2016	Knapman, Kenneth - TWC MECHANIC	3.00	17,358HRS: Change cutting edge. Remove & disassemble joystick to chk (& replace) bail switch Chk ha
05/07/2016	Wilde, David - TWC WORKSHOP MANAGER	3.50	17,358HRS: Chk & repair trans. harness. Replace bail switch. Chk rear fan belts.
07/07/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair joystick.
12/07/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & replace rear start switch.
19/07/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Repair & refit scraper step.
20/07/2016	Knapman, Kenneth - TWC MECHANIC	5.00	Remove cutting edge. Gouge off weld on adaptors. Continue harness replacement.
20/07/2016	Wilde, David - TWC WORKSHOP MANAGER	6.00	Repairs to joystick. Repair flashing light. Chk all lights. Replace rear trans harness.
21/07/2016	Dawson, Dale - TWC Mechanic	5.00	Remove rear harness, change circuit breakers/relays, reinstall rear engine harness.
21/07/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace centre cutting edge.
22/07/2016	Dawson, Dale - TWC Mechanic	5.50	Install machine harnesses ar rear of scraper engine & control panel, re route harness to avoid rubb
22/07/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Remove apron cylinder mount for repair of crack, weld repair crack & refit mount to machine.
22/07/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Replace rear harness, Chk machine operation & light function.
25/07/2016	Dawson, Dale - TWC Mechanic	5.50	Remove machine hitch on top of draft frame to underside of cab, remove tyre on front L/H side + mu
25/07/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Jack up unit for tyre removal for weld repair to guard. Cut off belly plate mount tabs, make up new
25/07/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove L/H front tyre guard, remove old harnesses, look up & order parts.
26/07/2016	Dawson, Dale - TWC Mechanic	0.25	Pressure test pumps, hyd. steer & hyd. main.
30/07/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Weld tyne adaptors to cutting edge of bucket. Replace dash light globes.
22/08/2016	Dawson, Dale - TWC Mechanic	4.50	17,533HRS: Complete 500hr service, take SOS
23/08/2016	Dawson, Dale - TWC Mechanic	1.00	Complete diff/final drive SOS from 500hr service. Compete SOS reports.
23/08/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Take SOS
24/08/2016	Dawson, Dale - TWC Mechanic	1.50	Remove ejector door, load onto float & secure door & rear engine from #279
24/08/2016	Knapman, Kenneth - TWC MECHANIC	5.00	Remove & load ejector door.
25/08/2016	Dawson, Dale - TWC Mechanic	4.50	Inspect unit - chk auto greaser working, inspect hitch, repair oil leaks on rear engine around fuel
26/08/2016	Dawson, Dale - TWC Mechanic	2.00	Temporary installation of GPS radio until new bracket made. Make new bracket & mount to radio.
27/08/2016	Dawson, Dale - TWC Mechanic	0.50	Mount new GPS radio bracket & mount GPS
28/08/2016	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
29/08/2016	Knapman, Kenneth - TWC MECHANIC	8.50	Commence repairs to broken ejector door.
30/08/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Continue with repairs to ejector door.
30/08/2016	Dawson, Dale - TWC Mechanic	0.50	Investigate laser fault - R & R laser.
30/08/2016	Dawson, Dale - TWC Mechanic	2.00	Investigate machine shutting down + no drive found - plug in ET - no communication found - clean al
31/08/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Assist with removal of fuel pump from engine.
01/09/2016	Knapman, Kenneth - TWC MECHANIC	6.50	Continue with ejector door repairs.
02/09/2016	Knapman, Kenneth - TWC MECHANIC	6.50	Continue with ejector door repairs.
02/09/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Assist with ejector door repairs.
05/09/2016	Knapman, Kenneth - TWC MECHANIC	9.50	Continue with ejector door repairs.
06/09/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Continue with ejector door repairs.

Date	Name	Duration	Notes
07/09/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Cut & fit bracing plate for rear of ejector door.
09/09/2016	Knapman, Kenneth - TWC MECHANIC	4.50	Continue with repairs to ejector door.
09/09/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to ejector door.
12/09/2016	Dawson, Dale - TWC Mechanic	1.00	Remove rollers from ejector door for rebuilding.
12/09/2016	Knapman, Kenneth - TWC MECHANIC	5.50	Prep ejector door for undercoat/primer & paint.
12/09/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Dismantle & clean up parts. Reassemble 2 ejector door rollers.
13/09/2016	Dawson, Dale - TWC Mechanic	3.00	Rebuild ejector door rollers.
13/09/2016	Knapman, Kenneth - TWC MECHANIC	4.50	Remove guide & floor rollers from ejector door. Purchase paint & prep door for topcoat & paint door
13/09/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove ejector rollers & dismantle. Clean up parts & replace bearings.
23/09/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Measure, cut & weld transport pedestals on ejector door. Fit guide rollers.
18/10/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Load ejector door onto trailer & secure.
18/10/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Rrepaired ejector door - Load onto trailer & strap down. Load rebuilt power pack onto trailer & se
20/10/2016	Knapman, Kenneth - TWC MECHANIC	4.50	Remove ejector door. Replace ejector door.
20/10/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R ejector door.
21/10/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Weld travel pedestals to replaced ejector door & strap on to trailer. Refit laser frame, Laser & GP
21/10/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit laser frame & adjust guide rollers.
28/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Shift cushion on seat
01/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace blown hose.
02/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Clean out rear radiator.
04/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace GPS cable.
10/11/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R fan belts.
17/11/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Investigate source of hyd/steering noise.
17/11/2016	Knapman, Kenneth - TWC MECHANIC	3.00	17,776HRS: Carry out 250hr service.
24/11/2016	Knapman, Kenneth - TWC MECHANIC	8.00	Remove steer cylinder from #270 to replace #265's. Remove steer cylinder. Disassemble, replace seal
24/11/2016	Wilde, David - TWC WORKSHOP MANAGER	9.50	Replace seals on hitch & L/H steering ram. Part wash down & chk over. Remove apron lift for repairs
25/11/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Remove R/H steering cylinder for resealing. Clean, replace seals & reassemble. Remove bearings fro
25/11/2016	Wilde, David - TWC WORKSHOP MANAGER	5.00	Remove, reseal & refit R/H steering ram. Wash out rear radiator. Chk & adjust hitch gas pressure.
26/11/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Fit banana arm & dog bone.
26/11/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit apron lift & top up hyd. oil.
29/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace 2 trans. pressure nipples
02/12/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Adjust rear fan belts.
03/12/2016	Wilde, David - TWC WORKSHOP MANAGER	5.00	Chk electrical faults & test solenoids. Look up & order parts.
04/12/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Replace ECM. Test wiring & test run.
05/12/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk rear harness & repair. Refit & test run. Chk & adjust hyd. pressures.
05/12/2016	Dawson, Dale - TWC Mechanic	1.00	Investigate hyd. fault - found harness failure - repaired.
07/12/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	17,867HRS: Replace rear throttle valve.
08/12/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & repair fuel leak - test run.
09/12/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk charge rate & replace rear alternator.
10/12/2016	Dawson, Dale - TWC Mechanic	0.50	Fit alternator to powerpack in shed.
14/12/2016	Dawson, Dale - TWC Mechanic	1.50	make up new hose for draft frame & load machine onto float for transport to jobsite.
15/12/2016	Dawson, Dale - TWC Mechanic	3.00	Fit new draft frame hose & steel tube, fit new diff lock switch, calibrate gear shift.
17/12/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Straighten hyd. pipe.
03/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	17,977HRS: Prestart, chk a/c, tighten bolts in cutting edge, chk hitch & tyre pressures, take SOS
06/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fill out SOS.
07/01/2017	Dawson, Dale - TWC Mechanic	1.00	Pressure test steering - hard to steer - HMV u/s.
09/01/2017	Dawson, Dale - TWC Mechanic	1.50	18,025HRS: Complete eng. oil change - part of 2,000hr sample, pressure test steer system.
11/01/2017	Dawson, Dale - TWC Mechanic	1.50	R & R HMU - test operation.
12/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts.
19/01/2017	Dawson, Dale - TWC Mechanic	1.50	Wash machine.
20/01/2017	Dawson, Dale - TWC Mechanic	2.00	Wash machine.
20/01/2017	Dawson, Dale - TWC Mechanic	5.00	Drain hyd. oil. Remove, strip down & inspect hyd. pump, install new cartridges in pump & refit pump
20/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove front R/H tyre.
21/01/2017	Dawson, Dale - TWC Mechanic	5.00	Remove hyd. tank cover, R & R O rings & rubber suction hose on inside of tank. Drain diff. & final
21/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove L/H rear final drive & wheel. Chk parts for wear. Complete 18,000Hrs service.

Date	Name	Duration	Notes
23/01/2017	Dawson, Dale - TWC Mechanic	9.50	R & R 2 front tyres. Fill diffs & final drives with oil. Fit hyd. tank plate, seal off tank & fill
23/01/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Get 2 new tyres from storage ready for replacement on machine.
23/01/2017	Wilde, David - TWC WORKSHOP MANAGER	6.50	Look up & order parts. Clean up & inspect parts. Replace 2 front tyres.
24/01/2017	Dawson, Dale - TWC Mechanic	9.50	Remove rear power pack. Clean left rear spindle, rebuild & refit left final drive assy & set bearing
24/01/2017	Knapman, Kenneth - TWC MECHANIC	5.50	Lift rear power pack out of machine & mount on stand. Move power pack to washbay & clean. Remove/d
24/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove rear power pack & dismantle radiator.
25/01/2017	Knapman, Kenneth - TWC MECHANIC	8.00	Remove & replace engine.
25/01/2017	Dawson, Dale - TWC Mechanic	3.50	Pressure test & set pressures to spec. for steer & hydraulics. Inspect fuel pump oil leaks, remove
25/01/2017	Wilde, David - TWC WORKSHOP MANAGER	6.50	Assemble rear trans & engine.
27/01/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Clean off old gaskets, fit components to new power pack eng. Collect parts & continue assembly of e
27/01/2017	Wilde, David - TWC WORKSHOP MANAGER	5.00	Assemble rear eng & trans. Chk rear frame for cracks. Look up & order parts.
27/01/2017	Knapman, Kenneth - TWC MECHANIC	1.00	R & R engine (Brought Fwd from previous week)
30/01/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Weld repairs to ejector door & cross member cracks in scraper. Fit muffler.
30/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk for air leaks & replace air valve. Tighten fittings.
31/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Assemble rear radiator wiring.
03/02/2017	Knapman, Kenneth - TWC MECHANIC	2.00	Assemble fan & mount radiator assy on power pack.
04/02/2017	Knapman, Kenneth - TWC MECHANIC	5.00	Fit radiator assy to power pack. Connect hoses & lines to cooler. Connect electricals. Fill with co
06/02/2017	Knapman, Kenneth - TWC MECHANIC	4.50	Fit power pack back into machine, shorten & fit exhaust stack. Fit push/pull hook, locate fault wi
06/02/2017	Dawson, Dale - TWC Mechanic	5.00	Install rear power pack, fill oils etc, locate coolant flow sensor fault.
06/02/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Refit rear power pack. Look up & order parts.
10/02/2017	Dawson, Dale - TWC Mechanic	3.50	Fit 2 new uni joints to rear power pack drive shaft, refit shaft & guard. R & R rear eng. coolant f
30/03/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	18,092HRS: Chk rear throttle control & order parts.
01/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	18,095HRS: Prestart, grease brake & bail points. Blow out radiator. Fuel up.
02/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & clean GPS connectors.
04/04/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk & clean GPS cable connectors. Repair cable. Blow out radiator.
07/04/2017	Dawson, Dale - TWC Mechanic	1.00	Repair failed auto greaser, R & R ejector.
08/04/2017	Dawson, Dale - TWC Mechanic	1.00	GPS fault - inspect harness & plugs - unable to locate fault.
19/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	18,226HRS: Prestart. Tighten rear fan belts.
20/04/2017	Dawson, Dale - TWC Mechanic	1.50	Disassemble grease injector modules, clean & inspect 3, make up 1 working module out of the 3.
24/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	18,250HRS: Service & fill out SOS.
27/04/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	18,250HRS: Service, adjust alt. belt.
02/05/2017	Dawson, Dale - TWC Mechanic	0.50	Repair damage to GPS harness.
03/05/2017	Dawson, Dale - TWC Mechanic	3.00	Investigate air leak on air compressor circuit - found governor valve has failed. R & R valve follo
03/05/2017	Dawson, Dale - TWC Mechanic	1.50	Cut to fill as directed.
09/05/2017	Dawson, Dale - TWC Mechanic	5.00	Remove GPS pole, fit GPS to pole, weld & refit to machine. Investigate GPS failure - found break in
14/05/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Change over GPS screen & radio. Remove sensor cable & make up. Repair electrical fault to laser.
15/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	Refit sensor cable.
17/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace GPS cable.
25/05/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove apron lift.
26/05/2017	Dawson, Dale - TWC Mechanic	3.50	Set machine up for fitting of banana bar, remove bush from apron cylinder for replacement - unable
31/05/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Dig out mud from front R/H guard. Chk oils, adjust front alternator & a/c belts.
01/06/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Chk brake release & order parts.
02/06/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Chk/research brake issues.
03/06/2017	Knapman, Kenneth - TWC MECHANIC	2.00	Replace park brake switch. Chk park solenoids - front & back. Put old switch back in.
05/06/2017	Knapman, Kenneth - TWC MECHANIC	1.50	SOS eng. & trans. oils. Drop front eng. oil & change filter. Clean up from service.
06/06/2017	Knapman, Kenneth - TWC MECHANIC	2.50	Rear engine service & clean up
07/06/2017	Knapman, Kenneth - TWC MECHANIC	3.50	18,500HRS: Set up for & complete 500hr service.
08/06/2017	Dawson, Dale - TWC Mechanic	1.00	Organise/order parts required.
09/06/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Chk trans. screens.
14/06/2017	Dawson, Dale - TWC Mechanic	1.00	Install new ejector cylinder & refill oil.
15/06/2017	Dawson, Dale - TWC Mechanic	1.50	Locate hyd. leak - remove L/H draft arm covers - R & R hyd. hoses for ejector cylinder.
16/06/2017	Dawson, Dale - TWC Mechanic	2.00	18,582HRS: Fill hyd. oil, clean ddraft frame area, refit covers & test operation.
17/06/2017	Dawson, Dale - TWC Mechanic	1.50	18,590HRS: Investigate park brake release failure on rear boosters - found faulty air valve - R & R
20/06/2017	Dawson, Dale - TWC Mechanic	1.50	Make up/strip down spare ejector door hoses.

Date	Name	Duration	Notes
28/06/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & clean GPS cable connectors.
29/06/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove covers & chk fuel leak.R & R fuel line. Test run, refit covers.
30/06/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Cut bedside channel & fill hard stand pad.
30/06/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Drain & refill rear eng. coolant.
01/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk park brake operation. Look up & order parts.
02/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk wiring to park brake. Test solenoid. Calibrate joystick. Chk & adjust tyre pressures.
04/07/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace ejector pipe. Make up hyd. hose. Replace front brake valve & test run.
15/07/2017	Knapman, Kenneth - TWC MECHANIC	1.75	18,750HRS: Service front engine.
16/07/2017	Knapman, Kenneth - TWC MECHANIC	1.00	18,750HRS: Service rear engine.
24/07/2017	Dawson, Dale - TWC Mechanic	3.00	Remove broken laser pole, cut off damage & refit. Make up new laser pole, remove GPS mounting from
27/07/2017	Dawson, Dale - TWC Mechanic	2.50	R & R cab gear shift lever, wire up new plug, remove fan motor assy for repair, order parts.
08/08/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	18,880HRS: Re-assemble fan motor & refit to unit - test run. Prestart & fuel up.
09/08/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	18,889HRS: Prestart & grease. Adjust rear fan belts.
16/08/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	18,945HRS: Remove dash & repair light bracket.
17/08/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	18,950HRS: Prestart. Calibrate joystick & test run.
25/08/2017	Dawson, Dale - TWC Mechanic	2.50	19,000HRS: Part service - complete SOS, change eng. oils.
26/08/2017	Dawson, Dale - TWC Mechanic	1.50	Continue with 1,000hr service.
27/08/2017	Dawson, Dale - TWC Mechanic	7.25	Finalise 1,000hr service. Remove dash & install new indicator lights & carrier modules. Test operat
28/08/2017	Dawson, Dale - TWC Mechanic	2.00	Clean out hyd. lines/holes as a result of piston pump failure.
29/08/2017	Dawson, Dale - TWC Mechanic	2.00	Fit piston pump for hitch & kidney loop oil for hydraulics.
01/09/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Clean blade sensor connectors.
07/09/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean GPS cable connectors. Chk cable for shorts, order parts.
14/09/2017	Dawson, Dale - TWC Mechanic	0.50	Collect hyd. oil & top up machine.
17/09/2017	Dawson, Dale - TWC Mechanic	1.50	R & R GPS harness for slope centre. Blow out radiator.
20/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk fault codes over phone.
13/10/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Remove L/H rear guard. Disassemble & grind apart. Begin straightening components.
16/10/2017	Dawson, Dale - TWC Mechanic	3.00	Fit front & rear V belts, R & R hyd. seal hitch valve.
16/10/2017	Knapman, Kenneth - TWC MECHANIC	9.50	Straighten L/H rear mud guard components. Weld mud guard components back together & fit to machine.
16/10/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	19,190HRS: Refit rear mudguard & replace trash rack bolts.
17/10/2017	Knapman, Kenneth - TWC MECHANIC	6.00	Finish repairs to trash rack/laser frame & wash machine. Remove tractor air cleaner housing & repla
17/10/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace bolts in laser frame. Chk & charge hitch acc. Load onto float.
20/10/2017	Knapman, Kenneth - TWC MECHANIC	2.50	Travel to/from jobsite(s)
20/10/2017	Knapman, Kenneth - TWC MECHANIC	2.50	Chk door latch mechanism, change leaking seal.
23/10/2017	Knapman, Kenneth - TWC MECHANIC	2.75	Travel to/from jobsite(s)
23/10/2017	Knapman, Kenneth - TWC MECHANIC	2.75	Fit piston, poppet & seal to control valve & clean shed floor.
27/10/2017	Dawson, Dale - TWC Mechanic	3.00	19,250HRS: Carry out service.
28/10/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	Chk hyd. fault & clean out sequence valve. R & R apron switch. Test run.
30/10/2017	Dawson, Dale - TWC Mechanic	1.50	Calibrate joystick & solenoids.
02/11/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	19,266HRS: Remove broken laser post. Chk rear fan belts.
08/11/2017	Dawson, Dale - TWC Mechanic	3.00	Investigate hyd. fault - removed hose & found poppet valve had become lodged inside hyd. circuit. R
09/11/2017	Dawson, Dale - TWC Mechanic	5.00	Drain oil from hydraulics, remove control valve, repair & reassemble, refit to machine. Refill oil
09/11/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Repair GPS pole.
13/11/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace 2way handpiece.
16/11/2017	Dawson, Dale - TWC Mechanic	1.00	Investigate gear selection fault - found no output speed on trans., calibrate speed sensor.
23/11/2017	Dawson, Dale - TWC Mechanic	2.00	Investigate hitch fault - remove hitch, fit replacement pump, reassemble & test - Ok.
25/11/2017	Dawson, Dale - TWC Mechanic	1.00	Repair damage to door - R & R broken bolts.
18/12/2017	Dawson, Dale - TWC Mechanic	5.00	19,507HRS: Complet 500 hr service & SOS on all components. Investigate trans. fault - found front s
18/12/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Deliver parts to Bellata for collection & return to w'shop.
19/12/2017	Dawson, Dale - TWC Mechanic	1.00	Fit new light & repair non working lights. R & R strip out R/H side final drive plug.
20/12/2017	Dawson, Dale - TWC Mechanic	1.00	Inspect oil leak - found leak coming from trans. breather.
08/01/2018	Dawson, Dale - TWC Mechanic	1.50	Chk brakes, locate air leak - R & R right front booster, chk over machine tyres & v belts etc.
08/01/2018	Dawson, Dale - TWC Mechanic	1.00	Strip down failed brake booster & order parts for repairs.
15/01/2018	Knapman, Kenneth - TWC MECHANIC	6.00	Investigate/trace brake/air system fault,j
15/01/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Remove part from #279 to replace faulty part on #265

Date	Name	Duration	Notes
24/01/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	19,706HRS: Chk machine for leaks.
05/02/2018	Dawson, Dale - TWC Mechanic	2.00	19,786HRS: 250hr service.
06/02/2018	Dawson, Dale - TWC Mechanic	0.50	Organise new hand controller for bowl - supplied parts for repair incorrect.
08/02/2018	Dawson, Dale - TWC Mechanic	1.50	Clean out radiators. Investiagte intermittant front eng. misfire - no fault apparent.
15/02/2018	Dawson, Dale - TWC Mechanic	1.00	19,809HRS: R & R front L/H brake booster
16/02/2018	Dawson, Dale - TWC Mechanic	1.50	Disassemble, clean & reassemble brake booster.
17/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	19,816HRS: Remove laser mast & GPS wiring.
19/02/2018	Dawson, Dale - TWC Mechanic	0.50	Organise & collect parts.
19/02/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Remanufacture laser post.
22/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	19,836HRS: Blow out rear radiator & chk fault codes.
24/02/2018	Dawson, Dale - TWC Mechanic	1.50	Fit new control lever & calibrate.
05/03/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	19,885HRS: Chk over. Remove apron cylinder, dismantle & inspect.
06/03/2018	Dawson, Dale - TWC Mechanic	2.00	Removal of hyd hitch pump. Investigate electrical fault.
06/03/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Repair laser post. Fit pump. Remove apron cylinder bearings & pallet cylinder ready for transport.
06/03/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit hitch pump & hoses.
07/03/2018	Dawson, Dale - TWC Mechanic	7.50	Remove hyd. control valve from machine, strip down, clean, reassemble & refit. Refil oil. Fit repla
08/03/2018	Dawson, Dale - TWC Mechanic	4.00	Wire up new flashing light. R & R air valve service brake valve. Locate & repair air leak.
09/03/2018	Knapman, Kenneth - TWC MECHANIC	2.00	Weld repairs to apron cylinder mount.
10/03/2018	Dawson, Dale - TWC Mechanic	5.00	Assemble apron cylinder & fit to machine.
12/03/2018	Dawson, Dale - TWC Mechanic	7.00	Calibrate control valve, reseal auto greaser, pressure test hitch gas. Set apron sequesnce valve pr
14/03/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk back up alarm & rear belts..
16/03/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Replace hitch compensator valve seal & gasket.
17/03/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to hitch pump.
19/03/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	Chk & adjust front alt. belt.
21/03/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	19,936HRS: Prestart
04/04/2018	Dawson, Dale - TWC Mechanic	3.50	19,995HRS: R & R rear eng. batteries & make up new harness.
07/04/2018	Dawson, Dale - TWC Mechanic	7.00	20,014HRS: Carry out 2,000hr service to specs & take SOS
16/04/2018	Dawson, Dale - TWC Mechanic	3.00	Complete valve set.
16/04/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	20,018HRS: Chk & clean electrical connectors. Test run.
17/04/2018	Dawson, Dale - TWC Mechanic	1.00	Remove GPS components to send to Trangie jobsite.
23/04/2018	Dawson, Dale - TWC Mechanic	0.50	Filling out SOS
24/04/2018	Dawson, Dale - TWC Mechanic	0.50	Filling out SOS
03/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	Repairs
08/05/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs
06/06/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	20,080HRS: Repair laser cable & test run & chk over unit.
20/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	34,296HRS: Prestart
20/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	R & R broken grease nipple.
26/06/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	20,250HRS: Service & chk tyre pressures.
28/06/2018	Dawson, Dale - TWC Mechanic	1.00	Disassemble brake boosters for resealing.
03/07/2018	Dawson, Dale - TWC Mechanic	0.50	Calibrate joystick & control valve.
04/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk active code fault.
05/07/2018	Dawson, Dale - TWC Mechanic	1.00	20,351HRS: Investigate & repair fault in joystick control.
21/07/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	20,500HRS: Service. Chk & adjust rear fan belts. Fit earth strap to rear radiator.
23/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fill out SOS
25/07/2018	Dawson, Dale - TWC Mechanic	2.50	20,505HRS: R & R rear eng. coolant. R & R rear Vee belts & fit earth strap from radiator to eng. bl
27/07/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	20,527HRS: Replace eng. bay door latch.
27/08/2018	Dawson, Dale - TWC Mechanic	1.00	20,710HRS: R & R blown steer hose.
28/08/2018	Dawson, Dale - TWC Mechanic	1.50	20,718HRS: R & R steer ram hoses. Investigate/repair auto grease system fault.
29/08/2018	Dawson, Dale - TWC Mechanic	3.00	20,718HRS: Make up 4 steer hoses.
06/09/2018	Dawson, Dale - TWC Mechanic	2.50	Strip down, inspect, clean & reassemble 6 x grease injectors.
12/09/2018	Wilde, David - TWC WORKSHOP MANAGER	5.50	20,744HRS: Remove belly guards & partial wash down.
13/09/2018	Dawson, Dale - TWC Mechanic	1.00	2,0750HRS: Commence 250Hr service.
14/09/2018	Dawson, Dale - TWC Mechanic	9.00	20,744HRS: Move macine into shed. Remove guards, remove hyd. oil, R & R main hyd. control valve, mo
15/09/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	20,750HRS: Complete service & fill out SOS.

Date	Name	Duration	Notes
17/09/2018	Dawson, Dale - TWC Mechanic	2.00	20,745HRS: Complete hyd. control valve calibration & test operation of all functions.
19/09/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	20,750HRS: Fit belly guards, chk hitch accumulator.
21/09/2018	Dawson, Dale - TWC Mechanic	4.50	20,747HRS: R & R cushion hitch rod assy - leaking.
24/09/2018	Dawson, Dale - TWC Mechanic	2.00	Prestart, check over machine & adjust oils. Assist load & secure onto float.
25/09/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Assemble hitch cylinder Rod assy. Order seals.
28/09/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Begin assembly of hitch cylinder, box up barrel.
20/10/2018	Knapman, Kenneth - TWC MECHANIC	2.00	20,788HRS: 250hr service.
29/10/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Investigate/locate electrical fault. Disconnect switch from system & order replacement.
01/11/2018	Dawson, Dale - TWC Mechanic	1.00	2,007HRS: Investigate eng. miss in front eng.
02/11/2018	Dawson, Dale - TWC Mechanic	1.50	2,011HRS: Investigate engine missfire - found fuel regulator U/S - clean regulator & refit to fuel
04/11/2018	Dawson, Dale - TWC Mechanic	1.00	20,917HRS: R & R fuel system regulator with new regulator valve.
05/11/2018	Dawson, Dale - TWC Mechanic	0.50	Inspect & refit bushes into eyes on hyd. lift rams.
05/11/2018	Dawson, Dale - TWC Mechanic	1.00	Investigate eng. misfire - fault intermittant - possibly faulty injector.
06/11/2018	Dawson, Dale - TWC Mechanic	5.00	20,935: Investigate engine missfire - found No.3 injector at fault - fault intermittant, ordered ne
09/11/2018	Dawson, Dale - TWC Mechanic	4.00	20,956HRS: R & R No.3 injector of front eng. & test operation. Repair GPS receiver cord. 20,960HRS:
11/11/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	21,000HRS: Service.
11/11/2018	Dawson, Dale - TWC Mechanic	3.50	21,000HRS: 1,000hr service.
13/11/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Wash & blow out rear radiator.
15/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	21,022HRS: R & R inside door handle.
16/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	Remove guards & repair fuel tank.
16/11/2018	Dawson, Dale - TWC Mechanic	2.00	Rebuild brake booster.
17/11/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	21,022HRS: R & R fuel line.
19/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	Wash out & dry rear radiator.
20/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk hyd. oil leak & order parts.
04/12/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Look up & order parts. Repair apron cylinder.
05/12/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Look up & order parts. Repair apron cylinder.
18/12/2018	Dawson, Dale - TWC Mechanic	8.50	21,165HRS: Drain hyd. system, clean out top of tank in filter housing. Make up 2 new hoses & fit t
08/01/2019	Knapman, Kenneth - TWC MECHANIC	8.50	Move to welding bay, remove batteries and cut out damaged bump frame fro replacement. Straighten be
09/01/2019	Knapman, Kenneth - TWC MECHANIC	7.50	Repairs to bumper.
09/01/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Part wash down.
10/01/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Continue reman. of bumper.
10/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Repairs to cab electrical system.
11/01/2019	Knapman, Kenneth - TWC MECHANIC	6.50	Continue reman. of bumper.
11/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.50	21,164HRS: Replace hood lining & speakers. Test run.
14/01/2019	Knapman, Kenneth - TWC MECHANIC	8.50	Repairs/refurbishment of mudguards, fit shrouds & bonnet.
14/01/2019	Wilde, David - TWC WORKSHOP MANAGER	7.50	Remove guards & wash down. Re-assemble apron cylinder & refit, refit guards.
14/01/2019	Dawson, Dale - TWC Mechanic	3.00	Re-assemble apron cylinder & refit to machine.
15/01/2019	Knapman, Kenneth - TWC MECHANIC	8.00	Repairs/refurbishment of mudguards, fit shrouds & bonnet.
15/01/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Fit apron cylinder & hoses. Test run. Fill hyd. oil tank fit belly guards.
16/01/2019	Knapman, Kenneth - TWC MECHANIC	6.50	Continue with mudguard repairs etc.
16/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Wash out radiator, clean air filter.
17/01/2019	Knapman, Kenneth - TWC MECHANIC	8.50	Continue with repair/refurbishment of mudguards.
18/01/2019	Knapman, Kenneth - TWC MECHANIC	3.00	Continue with repairs to mudguards & bump pad.
19/01/2019	Knapman, Kenneth - TWC MECHANIC	4.00	Continue with repairs to mudguards & bump pad.
21/01/2019	Knapman, Kenneth - TWC MECHANIC	7.50	Remove & straighten bail.
22/01/2019	Knapman, Kenneth - TWC MECHANIC	7.50	Carry out weld repairs to gooseneck.
22/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	21,164HRS: Remove pipes & hoses, repair cracks & refit pipes. Order parts.
23/01/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Clear off skid plate.
23/01/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Replace clamps on hyd. pipes & wash down.
24/01/2019	Knapman, Kenneth - TWC MECHANIC	7.50	Move into shed, prep machine for gouging off push pad support base. Gouge off push pad & prep area
24/01/2019	Wilde, David - TWC WORKSHOP MANAGER	2.50	Wash hitch, look up & order parts.
24/01/2019	Dawson, Dale - TWC Mechanic	1.00	R & R hyd. pilot filter housing, reseal & refit.
25/01/2019	Knapman, Kenneth - TWC MECHANIC	4.50	Refit guards to machine..
29/01/2019	Knapman, Kenneth - TWC MECHANIC	6.00	Continue push pad repair

Date	Name	Duration	Notes
07/02/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	21,164HRS: Prestart & fuel up. Load onto float & secure. Adjust rear belts.
08/02/2019	Dawson, Dale - TWC Mechanic	1.00	Investigate a/c failure - low on gas - test operation.
12/02/2019	Dawson, Dale - TWC Mechanic	1.00	Clean out rear engine radiator.
13/02/2019	Dawson, Dale - TWC Mechanic	2.50	Remove wire from around left rear wheel. Inspect piston pump screen for metal - all ok. R & R rear
19/02/2019	Dawson, Dale - TWC Mechanic	2.00	21,211HRS: Investigate & repair a/c - remove covers, clean out evaporator, reseal covers & refit.
04/03/2019	Knapman, Kenneth - TWC MECHANIC	3.50	21,277HRS: Service machine.
07/03/2019	Dawson, Dale - TWC Mechanic	2.00	Clean/wash out radiator with pressure cleaner & compressed air. Replace broken GPS pole bolt, adjus
09/03/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	21,327hrs: Replace batteries & chk charging system. Replace screen in hyd. tank.
23/03/2019	Dawson, Dale - TWC Mechanic	4.50	Carry out full weed & seed clean of machine.
01/04/2019	Dawson, Dale - TWC Mechanic	1.00	Travel to jobsite & unload scraper.
03/04/2019	Dawson, Dale - TWC Mechanic	0.50	Tighten bolts on cutting edge.
29/04/2019	Knapman, Kenneth - TWC MECHANIC	4.00	Remove, reseal & refit L/H bowl lift cylinder
29/04/2019	Wilde, David - TWC WORKSHOP MANAGER	8.00	21,500HRS: Service. Remove, reseal & refit L/H bowl lift cylinder.
30/04/2019	Knapman, Kenneth - TWC MECHANIC	4.00	Finish service & repairs to hyd. leaks.
30/04/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	21,500HRS: Complete service & repair oil leaks.
01/05/2019	Wilde, David - TWC WORKSHOP MANAGER	3.50	Repair oil leaks & replace rear fan belts.
02/05/2019	Wilde, David - TWC WORKSHOP MANAGER	3.50	Repairs to rear cooling system. Fill out SOS.
03/05/2019	Wilde, David - TWC WORKSHOP MANAGER	2.50	Replace rear water pump & coolant. Chk for leaks.
22/05/2019	Dawson, Dale - TWC Mechanic	6.00	Remove, repair & refit R/H bowl lift ram. Repair front eng. fuel leak.
23/05/2019	Dawson, Dale - TWC Mechanic	6.00	R & R R/H bowl lift ram - replace shaft & reseal. repair fuel leak on front engine.
24/06/2019	Dawson, Dale - TWC Mechanic	3.50	21,522HRS: Prestart, chk accumulators, tyre pressures, repair grease line - leaking/defective on fr
01/07/2019	Dawson, Dale - TWC Mechanic	0.50	Assist with tranmission disassembly.
02/07/2019	Knapman, Kenneth - TWC MECHANIC	5.50	Weld on tynes adaptors to cutting edge.
03/07/2019	Dawson, Dale - TWC Mechanic	1.00	R & R cutting edge.
03/07/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Fit cutting edge.
26/07/2019	Dawson, Dale - TWC Mechanic	2.50	Chk over machine, adjust tyre pressures, calibrate joystick, repair grease system & grease.
30/07/2019	Dawson, Dale - TWC Mechanic	1.00	Collect service kit & load ute for jobsite work.
31/07/2019	Dawson, Dale - TWC Mechanic	2.00	21729HRS: Carry out 750Hr service. Fit clamp to steer hyd. tube on king post hitch. Chk tyre pressu
31/07/2019	Dawson, Dale - TWC Mechanic	1.50	Remove apron cylinder support bracket from #239 to replace cracked unit on #265
01/08/2019	Dawson, Dale - TWC Mechanic	4.00	R & R cracked apron support bracket from cylinder to draft frame. R & R rear engine alternator. pac
05/08/2019	Dawson, Dale - TWC Mechanic	3.50	21,777HRS: Inspect coolant leak on rear radiator. R & R coolant system relief valve assy. Take mach
07/08/2019	Dawson, Dale - TWC Mechanic	0.50	Complete SOS reports.
09/08/2019	Dawson, Dale - TWC Mechanic	1.50	Load & organise parts for scraper. Remove parts from #239. Fit alternator & steer hose to #239
09/08/2019	Dawson, Dale - TWC Mechanic	1.50	R & R steer hose, chk tyres, chk hitch gas, locate & repair air leak.
26/08/2019	Dawson, Dale - TWC Mechanic	3.50	21,810.6HRS: Travel to machine & R & R cutting edge, clean bulk material from machine, load onto fl
28/08/2019	Dawson, Dale - TWC Mechanic	2.00	Make up spare hoses.
30/08/2019	Dawson, Dale - TWC Mechanic	4.50	Weld up crack in apron cylinder saddle.
09/09/2019	Dawson, Dale - TWC Mechanic	3.00	Prestart. Repair grease line, reseal trans. filter housing, refuel, load onto float & chain down.
12/09/2019	Dawson, Dale - TWC Mechanic	1.50	R & R cutting edge - fit stinger edge. R & R alternator belt.
16/09/2019	Dawson, Dale - TWC Mechanic	1.00	Organise GPS components
16/09/2019	Dawson, Dale - TWC Mechanic	1.00	Fit & test GPS system.
24/09/2019	Dawson, Dale - TWC Mechanic	1.00	Investigate/repair electrical fault in rear motor.
27/09/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Blow out radiator.
01/10/2019	Dawson, Dale - TWC Mechanic	1.00	21,988HRS: R & R cutting edge & chk tyre pressures.
04/10/2019	Dawson, Dale - TWC Mechanic	4.00	Take all SOS's, clean out rear radiator, drain front diff (overfull), add 20L coolant to rear eng.
08/10/2019	Dawson, Dale - TWC Mechanic	1.50	21,980HRS: Complete SOS reports from service. Unload equipment.
09/10/2019	Dawson, Dale - TWC Mechanic	1.00	21,985HRS: Clean out radiator, drop off water to site for rear radiator.
23/10/2019	Dawson, Dale - TWC Mechanic	3.50	Remove rear engine from machine & commence disassembly for repairs.
23/10/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove rear powerpack.
24/10/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Clean up & inspect parts. Look up & order parts required.
24/10/2019	Dawson, Dale - TWC Mechanic	8.50	Disassemble rear engine. Remove cylinder head - found fault in No.1 cylinder - leaking coolant past
25/10/2019	Dawson, Dale - TWC Mechanic	7.50	Clean engine components, install No1 reman liner kit, inspect & test bearing clearances. Commence r
26/10/2019	Dawson, Dale - TWC Mechanic	5.00	22,255HRS: Continue re-assembly of engine - fit cylinder head.
28/10/2019	Dawson, Dale - TWC Mechanic	1.00	Continue with engine re-assembly.

Date	Name	Duration	Notes
28/10/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Begin gouging off apron arms.
28/10/2019	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove apron & chk air system. Look up & order parts.
29/10/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Measue up apron for steel requirements & order steel.
29/10/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace air valves & test run. Collect parts.
29/10/2019	Dawson, Dale - TWC Mechanic	2.00	Assemble rear engine.
30/10/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R relay & release valves. Chk for air leaks.
31/10/2019	Knapman, Kenneth - TWC MECHANIC	3.00	Gouge left hand side of apron fro removal & replacement.
01/11/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Remove R/H apron side & straighten out to use as template. Mark our & cut plate for replacement arm
02/11/2019	Knapman, Kenneth - TWC MECHANIC	6.50	Remanufacture apron arm(s)
02/11/2019	Wilde, David - TWC WORKSHOP MANAGER	6.50	Assist with repairs to apron.
04/11/2019	Dawson, Dale - TWC Mechanic	8.50	Finish re-assembly of engine components/engine. Fill cooling system with flushing fluid. Plumb up f
04/11/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Continue reman. of apron.
05/11/2019	Dawson, Dale - TWC Mechanic	5.00	Flush engine cooling system twice. Remove radiator & oil coolers for cleaning out.
05/11/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Continue reman. of apron.
06/11/2019	Dawson, Dale - TWC Mechanic	9.50	Continue with repairs to rear power pack - fit oil cooler, trans & engine reseal, reseal trans. oil
06/11/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Continue reman. of apron.
07/11/2019	Dawson, Dale - TWC Mechanic	3.00	22,055HRS: Assemble rear eng. radiator & pressure test.
08/11/2019	Dawson, Dale - TWC Mechanic	2.50	Finish fitting guards, panels etc to rear eng.
11/11/2019	Dawson, Dale - TWC Mechanic	4.00	Move machine into shed, drain oils from final drives, diff, trans. & remove transmission & diff fro
11/11/2019	Wilde, David - TWC WORKSHOP MANAGER	6.00	22,056HRS: Complete service. Remove trans. & diff. assy.
12/11/2019	Dawson, Dale - TWC Mechanic	3.50	Clean up parts, complete 2000Hr service on trans. , clean work area.
13/11/2019	Dawson, Dale - TWC Mechanic	8.00	Strip down & rebuild front diff.
14/11/2019	Dawson, Dale - TWC Mechanic	9.00	Finish rebuild on diff & set to CAT Specs.. Fit diff to transmission & re-install into machine, ref
15/11/2019	Dawson, Dale - TWC Mechanic	6.00	R & R ejector door cylinder, fill fron t trans., diff & final drives with oil. Test function of tra
18/11/2019	Dawson, Dale - TWC Mechanic	0.50	R & R artic. hoses.
18/11/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Gouge off mould board.
19/11/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Finish removal of mould board & prep for replacement.
19/11/2019	Dawson, Dale - TWC Mechanic	4.50	Remove artic. hoses, reman & reinstall into machine.
20/11/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Continue reman of mould board.
21/11/2019	Knapman, Kenneth - TWC MECHANIC	9.50	Replace mouldboard. Apron repair/reman.
22/11/2019	Knapman, Kenneth - TWC MECHANIC	6.50	Repair ejector door.
22/11/2019	Dawson, Dale - TWC Mechanic	6.50	Order parts. Refit rear power pack. Repair oil leaks, valve set front engine. Drop belly plate. R &
23/11/2019	Dawson, Dale - TWC Mechanic	6.50	Finish install of rear power pack. Refit bonnets, guards etc. Refit ejector door & set up rollers.
25/11/2019	Knapman, Kenneth - TWC MECHANIC	7.00	Repair apron cylinder saddle.
26/11/2019	Knapman, Kenneth - TWC MECHANIC	4.00	Repairs to apron cylinder saddle & deliver for machining. Cut plates for apron bails
27/11/2019	Dawson, Dale - TWC Mechanic	8.50	Remove belly guards, reseal front engine starter motor, refit apron bracket & hyd. hoses. Remove ba
27/11/2019	Knapman, Kenneth - TWC MECHANIC	2.50	Weld trunion caps. Remove banana arm & dog bone. Replace apron cylinder saddle.
28/11/2019	Dawson, Dale - TWC Mechanic	2.50	Fit belly plates, fit walkway to press/repair bushes/holes.
28/11/2019	Knapman, Kenneth - TWC MECHANIC	2.50	Remove bearings from banana arm & deliver for machining. press bushes into apron cylinder. Set up c
29/11/2019	Knapman, Kenneth - TWC MECHANIC	5.00	Fit pin locators then refit apron to machine. Remove from shed for testing & return to shed.
29/11/2019	Dawson, Dale - TWC Mechanic	8.50	Strip down engine & inspect for failed components. Remove radiator assy & strip down radiator. Wash
30/11/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit laser frame.
02/12/2019	Dawson, Dale - TWC Mechanic	1.50	Chk cushion accumulators & charge. Chk tyre pressures & fluids.
04/12/2019	Wilde, David - TWC WORKSHOP MANAGER	2.50	Refit apron to machine & finish repairs/reassembly of machine.
04/12/2019	Dawson, Dale - TWC Mechanic	1.00	Assist finalise repairs.
04/12/2019	Knapman, Kenneth - TWC MECHANIC	1.50	Assist finalise repairs.
06/01/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	22,207HRS: Chk & repair lights. Replace GPS Cable.
22/01/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	22,231HRS: Unload machine from float, remove radiator guards & part wash unit.
23/01/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	22,231HRS: Remove intercooler & clean out coolers.
29/01/2020	Wilde, David - TWC WORKSHOP MANAGER	7.50	22,250HRS: Service. Repair air leaks & replace relay & coil valve.
03/02/2020	Wilde, David - TWC WORKSHOP MANAGER	3.50	Wash down & chk grease system.
04/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.25	Repairs to grease system.
05/02/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repairs to grease system.
11/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace 2 Grease Injectors And Check System

Date	Name	Duration	Notes
26/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.50	Dismantle ejector cylinder. look up & order parts.
03/03/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Gouge slinger mounts off blade, cut wear plates for former tips.
04/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk a/c operation & clean out vents.
05/03/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Remove tyre adaptors from damaged edge.
17/03/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Turn cutting edge.
25/04/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to electrical fault (phone directions)
16/05/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to transmission (phone instructions to jobsite fitter). Look up & order parts.
18/05/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to transmission (phone instructions to jobsite fitter).
19/05/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to transmission (phone instructions to jobsite fitter). Look up & order parts.
27/05/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to electrical system & order parts.
27/05/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to electrical system & order parts.
28/07/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	22,616HRS: R & R harness through bowl.
29/07/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Move unit into shed.
30/07/2020	Knapman, Kenneth - TWC MECHANIC	3.50	Remove front R/H drive to access hyd. tank. Remove inspection panel and grind back panel to access
30/07/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	22,616HRS: Remove tyre & repair hyd. tank order parts.
31/07/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Weld repair to hyd. tank. Replace seals/o-rings & hose in tank.
31/07/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	22,616HRS: Remove broken bolts in bowl & refit guards.
03/08/2020	Knapman, Kenneth - TWC MECHANIC	5.50	Replace hyd. tank sight glass & inspection panel. Fill with oil. Rotate & refit R/H drive tyre.
03/08/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	22,616HRS: refit tyre.
04/08/2020	Knapman, Kenneth - TWC MECHANIC	4.50	Finalise rotation of front tyres. Repair & refit draft arm guards.
04/08/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	22,616HRS: Chk trans pressure.
19/08/2020	Knapman, Kenneth - TWC MECHANIC	3.50	Gouge & weld apron cylinder saddle.
19/08/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	22,617HRS: Remove apron cylinder mount for repair.
20/08/2020	Knapman, Kenneth - TWC MECHANIC	2.50	Prep & install apron cradle to goose neck.
20/08/2020	Knapman, Kenneth - TWC MECHANIC	1.00	To jobsite, replace retaining bolts in bucket teeth.
02/10/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Carry out 22,750HRS service.
02/10/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	22,750HRS: Service.
07/10/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace clamps on intercooler. Chk rear throttle control.
09/10/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Change cutting edge & fit slinger teeth.
09/10/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit new cutting edge & tynes.
10/10/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	22,814HRS: Repairs to Trans. gusrd. Remove tynes. Chk rear eng. fan belts.
20/10/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Unload unit from float & move into w/shop. Chk tyre pressures.
21/10/2020	Knapman, Kenneth - TWC MECHANIC	2.00	Fit rotochamber, regulator & hose to rear engine.
26/10/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Change trans. filter & dismantle rear throttle control. Look up & order parts.
27/10/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Add Extender to rear radiator. Reseal rear throttle control.
09/11/2020	Wilde, David - TWC WORKSHOP MANAGER	7.50	22,866HRS: Re-shim horizontal pin. Chk over & partial wash down.
10/11/2020	Wilde, David - TWC WORKSHOP MANAGER	5.00	22,866HRS: remove seat suspension for repairs. order parts. Chk & charge hitch accumulator. Clean
10/11/2020	Knapman, Kenneth - TWC MECHANIC	6.50	Remove seat assy. Disassemble & weld cracked seat base. Re-assemble cushion to seat. Order bearing
11/11/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	22,866HRS: Replace hitch seal & assemble cab.
11/11/2020	Knapman, Kenneth - TWC MECHANIC	3.00	Re-assemble seat base with new bushes & bearings and refit to machine. Refit seat to base.
12/11/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	22,866HRS: Part wash down & test run.
04/12/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR
15/12/2020	Wilde, David - TWC WORKSHOP MANAGER	1.25	22,935HRS: Chk rear trans fault & change dash. test run.
13/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	23,000HRS: Part service.
17/01/2021	Wilde, David - TWC WORKSHOP MANAGER	5.50	23,000HRS: Service.
19/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	23,000HRS: Fill out SOS's
21/01/2021	Knapman, Kenneth - TWC MECHANIC	0.50	23,047HRS: Replace cutting edges.
23/01/2021	Knapman, Kenneth - TWC MECHANIC	0.50	23,057HRS: Change outer cutting edges.
23/01/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	23,057HRS: R & R outside cutting edges.
29/01/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Change routers.
29/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	23,090HRS: Chk hitch operation. Refit harness to clamps. Replace router bits.
01/02/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Replace cushion hitch harness.
01/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	23,105HRS: R & R hitch harness & test.
06/02/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Replace cutting edge & remove GPS screen mushroom, recliner & post. Lower mast.

<u>Date</u>	<u>Name</u>	<u>Duration</u>	<u>Notes</u>
06/02/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	23,144HRS: Remove GPS gear. Replace centre cutting edge. Part wash down.
05/03/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	2350Hrs - Service as required
28/04/2021	Wilde, David - TWC WORKSHOP MANAGER	2.50	Wash down and have fire extinguisher tagged. Replace fast fill bolls. Check tyre pressure and load
12/05/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	Check grease unit and change out. Test run
13/05/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Dismantle grease assy unit to locate failure point. Have replacement unit pressure tested.
13/05/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	23,414HRS: Refit grease unit & test run.
18/05/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk oil leak & remove grease unit.
19/05/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	23,456HRS: Repair oil leak on grease unit & refit & test run.
21/06/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	23,557Hrs. Fit GPS screen. Part Service
22/06/2021	Wilde, David - TWC WORKSHOP MANAGER	5.00	23,500Hrs service. Replace rear fan belts
23/06/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	23,500Hr. Fill out SOS Samples
01/07/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Dig out tyres fr Jukes to change out
01/07/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	23,556Hrs. Travel to Gurley. Pre Start. Load onto float. Travel back to Depot. Get 2 tyres replaced
02/07/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove cutting edge
03/07/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	Fit cutting edge & tyres. Replace cab air filters
22/07/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to trans fault over phone
24/07/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair trans fault
		<u>2,876.00</u>	
	TOTAL	<u>2,876.00</u>	

Total 265 - Cat 627G Scraper:265E