

289 - Kenworth Prime Mover:289E

Date	Name	Duration	Notes
21/12/2012	Knapman, Kenneth - TWC MECHANIC	3.50	Purchase parts, drain diffs & trans - refill. Fit grease line to thrust bearing and front spring pi
21/12/2012	Wilde, David - TWC WORKSHOP MANAGER	5.50	19,000 hours service, chk over & refit clamps.
02/01/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	Collect parts in Toowoomba
08/01/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over & order parts.
08/01/2013	Dawson, Dale - TWC Mechanic	0.50	Fit new radiator overflow hose & adjust /inspect brake wear & serviceability.
24/01/2013	Dawson, Dale - TWC Mechanic	0.50	19,133hrs: Fit new radiator cap & temp. guage.
24/01/2013	Griffin, Reece - Plant Mechanic	0.50	Replace radistor cap & temp. guage, install accessory power socket.
25/01/2013	Dawson, Dale - TWC Mechanic	0.50	R & R diff & final drive oils.
05/02/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	19,160hrs: Chk mud guard brackets.
08/02/2013	Griffin, Reece - Plant Mechanic	5.00	19,180Hrs: R & R air compressor (drive gear teeth worn & will soon need to be replaced) - includes
08/02/2013	Wilde, David - TWC WORKSHOP MANAGER	4.00	19,180hrs: Chk noise in engine, replace idler pulley bearings, remove air compressor & order parts.
09/02/2013	Griffin, Reece - Plant Mechanic	1.00	19,180Hrs: R & R air compressor (drive gear teeth worn & will soon need to be replaced) - includes
10/02/2013	Griffin, Reece - Plant Mechanic	1.50	19,180Hrs: R & R air compressor (drive gear teeth worn & will soon need to be replaced) - includes
15/02/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	19,233Hrs: Chk air tank brackets & order parts.
20/02/2013	Griffin, Reece - Plant Mechanic	1.50	Refit air tank bracket, chk over unit, make new air line.
23/02/2013	Griffin, Reece - Plant Mechanic	3.00	Service truck & chk trans. & diff oils.
16/03/2013	Griffin, Reece - Plant Mechanic	0.50	Chk ball race movement
06/04/2013	Dawson, Dale - TWC Mechanic	1.00	Locate trans. shift fault - order parts for repair / 19,500KM: Complete service.
09/04/2013	Dawson, Dale - TWC Mechanic	1.50	Locate trans. shift fault - order parts for repair / 19,500KM: Complete service.
09/04/2013	Griffin, Reece - Plant Mechanic	1.50	19,500Hrs: 500hr service./ Chk for loose or broken bolts.
10/04/2013	Griffin, Reece - Plant Mechanic	1.00	19,500Hrs: 500hr service./ Chk for loose or broken bolts.
11/04/2013	Griffin, Reece - Plant Mechanic	0.50	Replace headlight globe./ Repair hyd. tipper alarm system.
17/04/2013	Griffin, Reece - Plant Mechanic	2.00	Replace headlight globe./ Repair hyd. tipper alarm system.
17/04/2013	Dawson, Dale - TWC Mechanic	1.50	19,591HRS: Fit new mudguard to r/h rear wheel end, locate & repair hoist alarm light fault.
18/04/2013	Dawson, Dale - TWC Mechanic	0.50	R & R headlight.
25/04/2013	Griffin, Reece - Plant Mechanic	1.50	Sign in to jobsite, 19,663Hrs: Replace drive tyre./ have tyre repalce in Dalby & refit spare to tr
26/04/2013	Griffin, Reece - Plant Mechanic	1.00	Sign in to jobsite, 19,663Hrs: Replace drive tyre./ have tyre repalce in Dalby & refit spare to tr
01/05/2013	Griffin, Reece - Plant Mechanic	1.00	Sign in to jobsite, 19,663Hrs: Replace drive tyre./ have tyre repalce in Dalby & refit spare to tr
04/05/2013	Dawson, Dale - TWC Mechanic	1.50	19,750HRS: Complete 250hr service, adjust V belts etc./ Repair clearance lights.
05/05/2013	Dawson, Dale - TWC Mechanic	0.50	19,750HRS: Complete 250hr service, adjust V belts etc./ Repair clearance lights.
12/05/2013	Griffin, Reece - Plant Mechanic	0.50	Put bonnet springs on.
16/05/2013	Griffin, Reece - Plant Mechanic	1.00	Install air filters & replace bonnet slides./ Replace headlight bulbs & chk bonnet latch./ Replace
20/05/2013	Griffin, Reece - Plant Mechanic	0.50	Install air filters & replace bonnet slides./ Replace headlight bulbs & chk bonnet latch./ Replace
21/05/2013	Griffin, Reece - Plant Mechanic	4.50	Install air filters & replace bonnet slides./ Replace headlight bulbs & chk bonnet latch./ Replace
22/05/2013	Dawson, Dale - TWC Mechanic	1.00	Chk over unit, adjust trailer brakes.
23/05/2013	Dawson, Dale - TWC Mechanic	1.00	19889KLM: Drain coolant , remove coolant supply hose for replacement./ Install new coolant supply h
24/05/2013	Dawson, Dale - TWC Mechanic	2.00	19889KLM: Drain coolant , remove coolant supply hose for replacement./ Install new coolant supply h
26/05/2013	Dawson, Dale - TWC Mechanic	1.00	19889KLM: Drain coolant , remove coolant supply hose for replacement./ Install new coolant supply h
29/05/2013	Griffin, Reece - Plant Mechanic	1.00	19,925KLM: Put water tank on truck, replace r/h tail light & wiper blades.
30/05/2013	Griffin, Reece - Plant Mechanic	1.50	Repalced 2 mudguard bolts. / Install UHF aerial.
04/06/2013	Griffin, Reece - Plant Mechanic	1.00	Repalced 2 mudguard bolts. / Install UHF aerial.
07/06/2013	Wilde, David - TWC WORKSHOP MANAGER	3.50	20,000HRS service, change drive tyres, lift mudguard.
20/06/2013	Griffin, Reece - Plant Mechanic	0.50	Replace brake light bulb.
05/07/2013	Dawson, Dale - TWC Mechanic	0.50	20219Hrs? :Repair blinker, inspect front tyres for wear./ 20240HRS: Remove front steer tyres, fit 2
06/07/2013	Dawson, Dale - TWC Mechanic	2.50	20219Hrs? :Repair blinker, inspect front tyres for wear./ 20240HRS: Remove front steer tyres, fit 2
08/07/2013	Dawson, Dale - TWC Mechanic	1.50	20219Hrs? :Repair blinker, inspect front tyres for wear./ 20240HRS: Remove front steer tyres, fit 2
15/07/2013	Griffin, Reece - Plant Mechanic	1.00	Adjust clutch.
05/08/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Pick up tyres.
08/08/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Tension wheel nuts.
08/08/2013	Griffin, Reece - Plant Mechanic	1.00	20,491HRS: Go over unit, chk bushes, brakes & air lines. Retention drive tyres./ 20497HRS: Complete
09/08/2013	Griffin, Reece - Plant Mechanic	1.50	20,491HRS: Go over unit, chk bushes, brakes & air lines. Retention drive tyres./ 20497HRS: Complete
20/08/2013	Dawson, Dale - TWC Mechanic	4.00	Complete weed & seed 3.5hrs, remove tyre for repair .5hrs.
08/09/2013	Griffin, Reece - Plant Mechanic	4.00	Remove oil cooler & water pump./ Remove alternator, replace oil cooler & water pump (as per CAT Spe
09/09/2013	Griffin, Reece - Plant Mechanic	7.00	Remove oil cooler & water pump./ Remove alternator, replace oil cooler & water pump (as per CAT Spe

Date	Name	Duration	Notes
10/09/2013	Griffin, Reece - Plant Mechanic	2.50	Remove oil cooler & water pump./ Remove alternator, replace oil cooler & water pump (as per CAT Spe
12/09/2013	Dawson, Dale - TWC Mechanic	1.50	20,709HRS: Fit new alternator, test operation, test charge rate, top up coolant./ Locate air supply
13/09/2013	Dawson, Dale - TWC Mechanic	0.50	20,709HRS: Fit new alternator, test operation, test charge rate, top up coolant./ Locate air supply
14/09/2013	Dawson, Dale - TWC Mechanic	0.50	20,709HRS: Fit new alternator, test operation, test charge rate, top up coolant./ Locate air supply
15/09/2013	Dawson, Dale - TWC Mechanic	1.00	20,709HRS: Fit new alternator, test operation, test charge rate, top up coolant./ Locate air supply
16/09/2013	Dawson, Dale - TWC Mechanic	1.50	20,709HRS: Fit new alternator, test operation, test charge rate, top up coolant./ Locate air supply
19/09/2013	Dawson, Dale - TWC Mechanic	0.50	Organised parts to be sent to jobsite.
19/09/2013	Griffin, Reece - Plant Mechanic	1.00	Install new batteires, temp. sender & temp guage./ Replaced brake booster l/h front drive & 1 diver
22/09/2013	Griffin, Reece - Plant Mechanic	1.50	Install new batteires, temp. sender & temp guage./ Replaced brake booster l/h front drive & 1 diver
24/09/2013	Griffin, Reece - Plant Mechanic	1.00	Install new batteires, temp. sender & temp guage./ Replaced brake booster l/h front drive & 1 diver
01/10/2013	Dawson, Dale - TWC Mechanic	0.50	Locate starting fault - Starter motor unserviceable - parts ordered.
05/10/2013	Griffin, Reece - Plant Mechanic	0.50	Install 3 new batteries & replace starter motor.2.5hrs
14/10/2013	Dawson, Dale - TWC Mechanic	0.10	R & R flat tyre, cap off leaking booster. (1.5hrs)/ 21,000Klm: R 7 R leaking booster on rear left
16/10/2013	Dawson, Dale - TWC Mechanic	1.00	R & R flat tyre, cap off leaking booster. (1.5hrs)/ 21,000Klm: R 7 R leaking booster on rear left
20/10/2013	Griffin, Reece - Plant Mechanic	1.00	Chk for broken wires in ABS lines.
23/10/2013	Dawson, Dale - TWC Mechanic	0.50	Chk over unit & grease.
26/10/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Wash truck. Assist with repairs
28/10/2013	Knapman, Kenneth - TWC MECHANIC	5.50	Fabricate turn table mount bracket. Replace air tank bleed valve & pull. Replace torsion bar rubber
28/10/2013	Wilde, David - TWC WORKSHOP MANAGER	5.50	Wash truck. Assist with repairs
29/10/2013	Griffin, Reece - Plant Mechanic	6.00	Install turbo, replace alternator belts & bearing in clutch linkage.
29/10/2013	Knapman, Kenneth - TWC MECHANIC	6.00	Fabricate turn table mount bracket. Replace air tank bleed valve & pull. Replace torsion bar rubber
29/10/2013	Wilde, David - TWC WORKSHOP MANAGER	5.50	Wash truck. Assist with repairs
30/10/2013	Dawson, Dale - TWC Mechanic	2.00	Chk over unit & grease.
30/10/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Fabricate turn table mount bracket. Replace air tank bleed valve & pull. Replace torsion bar rubber
30/10/2013	Griffin, Reece - Plant Mechanic	6.00	Install turbo, replace alternator belts & bearing in clutch linkage.
30/10/2013	Wilde, David - TWC WORKSHOP MANAGER	6.50	Wash truck. Assist with repairs
04/11/2013	Dawson, Dale - TWC Mechanic	1.00	21089HRS: Grease drive line, locate noise in brakes & repair.
04/11/2013	Knapman, Kenneth - TWC MECHANIC	2.00	21089HRS: Remove t'table mount plate, borrow taper drill to countersink holes.. Fit 5th wheel to mo
05/11/2013	Knapman, Kenneth - TWC MECHANIC	5.50	21089HRS: Remove t'table mount plate, borrow taper drill to countersink holes.. Fit 5th wheel to mo
14/11/2013	Dawson, Dale - TWC Mechanic	1.00	Chk over & commence brake removal.
21/11/2013	Dawson, Dale - TWC Mechanic	1.50	Inspect damaged seat, organise parts for repair.
27/11/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repair seat belt.
29/11/2013	Wilde, David - TWC WORKSHOP MANAGER	3.50	Fit seat belt catch & wash down.
09/12/2013	Knapman, Kenneth - TWC MECHANIC	2.50	Remove seat assy for replacement. Source & order correct parts, return wrong parts, reassemble for
10/12/2013	Wilde, David - TWC WORKSHOP MANAGER	2.00	HVIS inspection. price parts for repairs.
12/12/2013	Griffin, Reece - Plant Mechanic	2.00	Remove sway bars & bushes.
13/12/2013	Wilde, David - TWC WORKSHOP MANAGER	1.50	Fit sway bars & bushes./ Chk & repair auto grease system./ Calibrate speedo.
14/12/2013	Wilde, David - TWC WORKSHOP MANAGER	3.00	Fit sway bars & bushes./ Chk & repair auto grease system./ Calibrate speedo.
17/12/2013	Dawson, Dale - TWC Mechanic	0.50	calibrate speedo.
17/12/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit sway bars & bushes./ Chk & repair auto grease system./ Calibrate speedo.
19/12/2013	Griffin, Reece - Plant Mechanic	1.00	21084HRS: Assist with repairs to auto grease system.
06/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & run machine.
07/01/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Meashure for battery isolator
08/01/2014	Knapman, Kenneth - TWC MECHANIC	3.00	Make battery isolator bracket, purchase steel.
10/01/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Fit battery isolator./ Source Road Train signs.
13/01/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Fit battery isolator./ Source Road Train signs.
15/01/2014	Griffin, Reece - Plant Mechanic	1.50	Collect parts, unblock a/c drainage tube. Replace 2way hand piece.
16/01/2014	Knapman, Kenneth - TWC MECHANIC	6.00	Manufacture hitch for dolly pull, deliver for sandblasting & painting.
16/01/2014	Dawson, Dale - TWC Mechanic	2.00	Remobe rear chassis brace for fitment of tow hitch./ Fit tow hitch bracket to rear chassis 1.5hrs.
20/01/2014	Dawson, Dale - TWC Mechanic	3.00	Remobe rear chassis brace for fitment of tow hitch./ Fit tow hitch bracket to rear chassis 1.5hrs.
30/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk noise in engine.
31/01/2014	Dawson, Dale - TWC Mechanic	2.00	Locate & repair jake brake fault, repair micro switch. Locate cause of turbo whistle & start R & R
31/01/2014	Griffin, Reece - Plant Mechanic	1.50	Remove silicon hoses & replace turbo outlet O rings.
03/02/2014	Dawson, Dale - TWC Mechanic	1.50	Locate & repair jake brake fault, repair micro switch. Locate cause of turbo whistle & start R & R
03/02/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Purchase steel for 5th wheel spacing.
04/02/2014	Dawson, Dale - TWC Mechanic	1.50	Locate & repair jake brake fault, repair micro switch. Locate cause of turbo whistle & start R & R

Date	Name	Duration	Notes
14/02/2014	Dawson, Dale - TWC Mechanic	0.50	Locate & repair indicator fault./ Locate oil leak from hyd. system - found steel tube to ejector r
14/02/2014	Griffin, Reece - Plant Mechanic	3.00	Replace light bulbs. Adjust brakes & S cams, slack adjusters & grease trailers & truck.
14/02/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk brake adjustments & all lights. Chk trailer springs & pivots.
15/02/2014	Dawson, Dale - TWC Mechanic	1.50	Locate & repair indicator fault./ Locate oil leak from hyd. system - found steel tube to ejector r
15/02/2014	Dawson, Dale - TWC Mechanic	0.50	Prestart chk.
16/02/2014	Bell, Daniel - TWC Manager	0.50	FGR
17/02/2014	Dawson, Dale - TWC Mechanic	0.50	Prestart chk.
18/02/2014	Dawson, Dale - TWC Mechanic	0.50	Prestart chk.
19/02/2014	Dawson, Dale - TWC Mechanic	0.50	Prestart chk.
19/02/2014	Dawson, Dale - TWC Mechanic	2.50	Locate & repair indicator fault./ Locate oil leak from hyd. system - found steel tube to ejector r
20/02/2014	Griffin, Reece - Plant Mechanic	1.00	Silastic wheel nut caps onto wheel nuts. Chk all lights including attached hired tippers.
20/02/2014	Dawson, Dale - TWC Mechanic	2.50	R & R reveiver dryer & vac down a/c system, charge & test. Fit truck onto trailer & chk operation o
20/02/2014	Bell, Daniel - TWC Manager	0.00	FGR
26/02/2014	Dawson, Dale - TWC Mechanic	4.00	R & R reveiver dryer & vac down a/c system, charge & test. Fit truck onto trailer & chk operation o
27/02/2014	Knapman, Kenneth - TWC MECHANIC	6.50	Measure flat bar for spacer plates & commence drilling for turntable, cut & drill plates.
27/02/2014	Bell, Daniel - TWC Manager	0.00	FGR
06/03/2014	Bell, Daniel - TWC Manager	0.00	FGR
12/03/2014	Dawson, Dale - TWC Mechanic	0.50	Assist adjust clutch.
12/03/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Cut 5th wheel (turntable) spacers to length, clean & undercoat.
13/03/2014	Dawson, Dale - TWC Mechanic	1.00	Brake adjustment, removed front right hub & reseal./ Chase up clutch parts./ Remove turntable to fi
13/03/2014	Bell, Daniel - TWC Manager	0.00	FGR
18/03/2014	Dawson, Dale - TWC Mechanic	0.50	Brake adjustment, removed front right hub & reseal./ Chase up clutch parts./ Remove turntable to fi
19/03/2014	Dawson, Dale - TWC Mechanic	2.00	Brake adjustment, removed front right hub & reseal./ Chase up clutch parts./ Remove turntable to fi
20/03/2014	Dawson, Dale - TWC Mechanic	6.50	Fit spacers to turntable, remove covers to wash machine, move to shed & place on blocks to remove t
25/03/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit clutch & front springs./ Assist refit gearbox.
26/03/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Refit clutch & front springs./ Assist refit gearbox.
27/03/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Assist with exhaust pipe installation.
27/03/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	21293HRS: Refit gearbox & parts.
05/04/2014	Knapman, Kenneth - TWC MECHANIC	4.50	Measure for oversize sign mount brackets & relocation of No. plate. Draw plans for folding of sheet
07/04/2014	Griffin, Reece - Plant Mechanic	1.00	Hook up trailer & grease trailer.
10/04/2014	Knapman, Kenneth - TWC MECHANIC	3.50	Manufacture Oversize sign mount for front bumper./ Finish oversize sign mount & No. plate mount - d
11/04/2014	Knapman, Kenneth - TWC MECHANIC	7.00	Manufacture Oversize sign mount for front bumper./ Finish oversize sign mount & No. plate mount - d
11/04/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove radiator & chk steering rod. CHK horton fan & price parts.
14/04/2014	Knapman, Kenneth - TWC MECHANIC	5.00	Manufacture Oversize sign mount for front bumper./ Finish oversize sign mount & No. plate mount - d
15/04/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Manufacture Oversize sign mount for front bumper./ Finish oversize sign mount & No. plate mount - d
16/04/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Manufacture Oversize sign mount for front bumper./ Finish oversize sign mount & No. plate mount - d
17/04/2014	Knapman, Kenneth - TWC MECHANIC	3.50	Assist with fan drive assembly. Pick up knuckle plates. Fit o'size sign & assist Gary.
24/04/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Cut knuckle plates for timber block ends
28/04/2014	Wilde, David - TWC WORKSHOP MANAGER	5.00	21,314HRS: Replace temp. guages & 2 diff senders. Chk wiring. Pick up parts. make up blocks.
01/05/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace blown bulb.
07/05/2014	Dawson, Dale - TWC Mechanic	2.00	R & R front diff drive tyres & torque nuts. Hook up float & measure space for toolbox.
08/05/2014	Dawson, Dale - TWC Mechanic	8.50	Repairs: Remove & relocate auto grease cartridge, remove & make up bracket & relocate air couplings
08/05/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Manufacture air line bracket.
22/05/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Weld repair power steering resevoir brackets.
28/05/2014	Dawson, Dale - TWC Mechanic	1.00	Diverted to Lake Cargelligo from trip home: Locate engine start failure - fault in fuel system, ble
05/06/2014	Dawson, Dale - TWC Mechanic	6.50	Install work lights to rear of cab & wire into switch in cab.
06/06/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & replace head light bulb.
17/06/2014	Dawson, Dale - TWC Mechanic	3.00	21,485HRS: Collect parts & complete 500hr service.
08/07/2014	Dawson, Dale - TWC Mechanic	1.50	Fit new park brake air valve (release).
15/07/2014	Dawson, Dale - TWC Mechanic	2.00	21,652HRS: Locate air leak under dash - Air pressure switch leaking, R & R air valve & refit to das
21/07/2014	Dawson, Dale - TWC Mechanic	2.50	Inspect & repair brake boosters on rear axles (going past 90' on full stroke, complete brake adjust
11/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Install head light protectors
21/08/2014	Dawson, Dale - TWC Mechanic	2.50	21742HRS - 1,030,862KLM: Complete engine service , rock clutch adjuster, chk over, download ECM sum
25/08/2014	Knapman, Kenneth - TWC MECHANIC	5.50	Remove battery box for repairs, clean batteries & terminals, deliver box to repairer & collect when
16/09/2014	Dawson, Dale - TWC Mechanic	0.50	Grease trailers, locate & repair leak in grease line.
22/09/2014	Dawson, Dale - TWC Mechanic	0.50	Repair flashing light.

Date	Name	Duration	Notes
29/09/2014	Dawson, Dale - TWC Mechanic	1.00	Locate air leak - R & R leaking air pressure valve.
03/10/2014	Dawson, Dale - TWC Mechanic	5.00	22,000HRS?: R & R power train oils diffs/trans & grease. Inspect a/c, clean out evaporator in cab,
03/10/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	21,961HRS: Change diff & gearbox oils.
09/10/2014	Dawson, Dale - TWC Mechanic	2.50	22,000HRS: 2,000hr service.
16/10/2014	Dawson, Dale - TWC Mechanic	0.50	Refuel./ Repair grease line from grease pot - leaking.
22/10/2014	Dawson, Dale - TWC Mechanic	0.50	Refuel./ Repair grease line from grease pot - leaking.
04/11/2014	Dawson, Dale - TWC Mechanic	1.50	R & R 2way radio & grease trailer./ Inspect 2way aerial - U/S. Arranged batteries for hand held 2wa
05/11/2014	Dawson, Dale - TWC Mechanic	2.00	R & R 2way radio & grease trailer./ Inspect 2way aerial - U/S. Arranged batteries for hand held 2wa
07/11/2014	Dawson, Dale - TWC Mechanic	2.50	22,201HRS: Locate & repair 2way fault - R & R aerial & run new cable.
13/11/2014	Dawson, Dale - TWC Mechanic	1.50	250hr service, inspect seat, organise parts.
14/11/2014	Bell, Daniel - TWC Manager	1.00	FGR
15/11/2014	Bell, Daniel - TWC Manager	3.50	FGR
23/11/2014	Bell, Daniel - TWC Manager	0.50	FGR
26/11/2014	Dawson, Dale - TWC Mechanic	1.50	R & R air ride height control valve & adjust to spec.
28/11/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Purchase new mudguars, brackets & clamps. Locate grease leak./ Replace mudguards.
01/12/2014	Knapman, Kenneth - TWC MECHANIC	2.50	Purchase new mudguars, brackets & clamps. Locate grease leak./ Replace mudguards.
09/12/2014	Dawson, Dale - TWC Mechanic	6.00	Inspect over for rego, adjust brakes, fill grease pod & inspect all grease points for grease, R & R
09/12/2014	Knapman, Kenneth - TWC MECHANIC	2.00	Commence removal of tractor control valve for replacement./ Remove tractor protection valve & remov
10/12/2014	Knapman, Kenneth - TWC MECHANIC	6.00	Commence removal of tractor control valve for replacement./ Remove tractor protection valve & remov
11/12/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Source parts for grease system / Fit elbow to grease system. Replace L/H front mud guard. Adjust R/
15/12/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Source parts for grease system / Fit elbow to grease system. Replace L/H front mud guard. Adjust R/
19/12/2014	Knapman, Kenneth - TWC MECHANIC	0.25	Replace O/six sign push stud.
09/01/2015	Dawson, Dale - TWC Mechanic	2.00	22,462HRS: Locate & repair fault with autogrease system.
09/02/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	22,500HRS service. Repair grease line.
25/02/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Replace muffler mount top rubber support.
05/03/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Purchase grease fittings.
15/04/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Remove air tank mounts for repair.
16/04/2015	Knapman, Kenneth - TWC MECHANIC	4.00	Remove broken air tank mounts & repair. Begin reassembly of batteries. Mount batteries & pack up.
07/05/2015	Dawson, Dale - TWC Mechanic	1.00	Repaired non working PTO buzzer, repair non working lights.
07/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
08/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
09/05/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adjust tyre pressures.
09/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
10/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
11/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
14/05/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	22,750Hrs service.
14/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
14/05/2015	Dawson, Dale - TWC Mechanic	1.50	22,720HRS: 250hr service, t'shoot hour metre, order parts for repairs.
15/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
16/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
16/05/2015	Dawson, Dale - TWC Mechanic	4.00	Fit new hour metre, repair clearance light. Repair dash lights, rivet signs on bumper.
17/05/2015	Bell, Daniel - TWC Manager	0.50	Prestart & FGR
19/05/2015	Knapman, Kenneth - TWC MECHANIC	4.00	Remove grease resevoir mount & weld up crack. make plates to reinforce mount & replace.
19/05/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to grease system bracket.
05/06/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Take for puncture repair. Collect from tyre repair.
02/07/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Remove & remanufacture & replace R/H rear mudguard support.
15/07/2015	Dawson, Dale - TWC Mechanic	1.00	Repair fuel leak - L/H side fuel tank.
16/07/2015	Dawson, Dale - TWC Mechanic	0.50	Inspect diesel tank for leak - none visible, remove machine from shed.
10/08/2015	Dawson, Dale - TWC Mechanic	4.50	22,257HRS: Carry out 250hr service. R & R rear right booster on rear diff assy. Complete clutch & b
14/08/2015	Dawson, Dale - TWC Mechanic	0.50	Repair L/H side window - not going up or down.
19/08/2015	Dawson, Dale - TWC Mechanic	0.50	Connect unit to tipper & test operation.
01/09/2015	Dawson, Dale - TWC Mechanic	2.00	Replace blown bulbs in dash guages.
03/09/2015	Dawson, Dale - TWC Mechanic	0.50	Look up specs for engine jake brake settings.
03/09/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Assist with adjustment of turntable pin.
23/09/2015	Dawson, Dale - TWC Mechanic	1.00	Chk over truck & float - ready for transport job.
23/09/2015	Dawson, Dale - TWC Mechanic	0.50	R & R blown front headlight bulb.

Date	Name	Duration	Notes
02/10/2015	Dawson, Dale - TWC Mechanic	2.00	Repair side clearance light, repair indicator control on side of console - loose. Reseal quick conn
07/10/2015	Dawson, Dale - TWC Mechanic	1.00	R & R trans. temp guage, repair dash light.
16/10/2015	Dawson, Dale - TWC Mechanic	2.00	Inspect engine light o fault. Chk & repair battery terminal/cables.n
21/10/2015	Dawson, Dale - TWC Mechanic	0.50	Fit new diff. temp guage in dash.
27/10/2015	Dawson, Dale - TWC Mechanic	1.00	Repair lights.
16/11/2015	Dawson, Dale - TWC Mechanic	1.50	R & R air hose from compressor to tank air signal
04/12/2015	Wilde, David - TWC WORKSHOP MANAGER	3.00	500hrs service.
07/12/2015	Dawson, Dale - TWC Mechanic	5.50	Finish a/c install, vac down & recharge system, test performance. R & R damaged seal on L/H side fr
04/01/2016	Dawson, Dale - TWC Mechanic	2.50	Rotate drive tyres & tension wheel nuts.
04/01/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Tension wheel nuts.
27/01/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Drain fuel tank & block off.
28/01/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Remove fuel tank & clean inside & out. Drain tank & deliver to repairer for welding (aluminium.) Co
28/01/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	668HRS: Remove fuel tank for repair.
01/02/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Fit fuel tank, staeps & guard. Chk lights & repair fault. Fill fuel. Adjust brakes & grease.
01/02/2016	Wilde, David - TWC WORKSHOP MANAGER	3.50	668HRS: Refit fuel tank. Chk brake adjustment. Chk & adjust tyre pressures. Wash down & gease.
08/02/2016	Dawson, Dale - TWC Mechanic	0.50	677HRS: Fit new rubber guard & new mudguards to R/H side.
19/02/2016	Dawson, Dale - TWC Mechanic	0.50	Chk over truck.
14/03/2016	Knapman, Kenneth - TWC MECHANIC	1.00	R & R pressure protection valve.
15/03/2016	Knapman, Kenneth - TWC MECHANIC	2.00	Grease, totate fuel tank, chk diff & trans fluid levels. Hook up #292 & #284 to unit.
15/03/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	750hrs service. Replace headlight guard. Turn fuel tank, fill out SOS.
22/03/2016	Knapman, Kenneth - TWC MECHANIC	1.75	Purchase air valve & assist with installation. Source battery box & obtain price & availability.
22/03/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk charging system & clean battery terminals. Chk & replace brake valve.
24/03/2016	Dawson, Dale - TWC Mechanic	3.00	Remove battery box for repairs, obtain 2 new batteries, reinstall repaired battery box & install ne
24/03/2016	Knapman, Kenneth - TWC MECHANIC	5.50	Remove battery box for weld repair & organise steel for brace. Weld air tank mount brackets, collec
29/03/2016	Dawson, Dale - TWC Mechanic	2.50	Clean batteries, cables & clamps, fit batteries to unit (2 new, 2 old) test charge rate etc.
29/03/2016	Knapman, Kenneth - TWC MECHANIC	2.00	Drain drivers side fuel tank, rotate tank, clean & glue straps, refit & refill tank.
04/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & repair bonnet hinge.
05/04/2016	Dawson, Dale - TWC Mechanic	1.00	Repair bonnet hinge - fit bolt until parts arrive.
05/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.75	Repairs to bonnet hinge.
07/04/2016	Dawson, Dale - TWC Mechanic	1.00	Fit new mounts to bonnet.
18/04/2016	Dawson, Dale - TWC Mechanic	0.50	Chk tyres, lights etc, grease & fuel up.
06/05/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Change drive tyre, clean deck.
10/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace alternator belts.
10/05/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	1,000hrs - Part service.
12/05/2016	Dawson, Dale - TWC Mechanic	1.50	Finalise 1,000hr service (powertrain)
12/05/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	1,000hr service.
13/05/2016	Dawson, Dale - TWC Mechanic	0.50	Chk grease system & tyre pressures.
16/05/2016	Dawson, Dale - TWC Mechanic	0.50	Fit new ride height control to suspension valve.
16/05/2016	Dawson, Dale - TWC Mechanic	1.50	Rotate tyre & swap tyre with #275
17/05/2016	Dawson, Dale - TWC Mechanic	1.00	Set up float with #298
17/05/2016	Dawson, Dale - TWC Mechanic	2.50	Investigate V belt fault - tension belts & order new matching set of belts & pulley for alternator.
26/05/2016	Knapman, Kenneth - TWC MECHANIC	2.00	Remove batteries, deliver to battery supplier for testing. Collect batteries & fit to truck.
10/06/2016	Dawson, Dale - TWC Mechanic	1.00	Repair L/H side grease line on chassis.
17/06/2016	Dawson, Dale - TWC Mechanic	3.00	Move into shed, remove diesel hoses from tank to cooler in grill & from cooler to engine for replac
20/06/2016	Dawson, Dale - TWC Mechanic	7.00	R & R front diff shocks & remove trans hoses from trans cooler to grill. Take hoses for repair/repl
21/06/2016	Dawson, Dale - TWC Mechanic	7.00	Fit new hoses & clamp in position, install trans. hose, fill trans., prime fuel system. Discharge a
22/06/2016	Dawson, Dale - TWC Mechanic	4.00	Finalise install of a/c compressor, vac down & recharge a/c, test operation, repairs non working li
08/07/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Change out grease line & fill cannister.
14/07/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Repair bracket.Smoko
14/07/2016	Dawson, Dale - TWC Mechanic	1.00	Fit new alternator & temp. guages - test operation.
18/07/2016	Dawson, Dale - TWC Mechanic	1.50	R & R flashing light on roof, locate & repair air leak behind dash sensor.
19/07/2016	Dawson, Dale - TWC Mechanic	0.50	Fit guard inside cab floor. R & R R/H headlight bulb.
01/08/2016	Dawson, Dale - TWC Mechanic	0.50	Repair float air supply hose.
29/08/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	1,250HRS: Service.
06/09/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & set up float.
05/10/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	1,272HRS: Chk & adjust tyr pressures, repair cab lights.

Date	Name	Duration	Notes
16/10/2016	Dawson, Dale - TWC Mechanic	1.50	Investigate coolant leak - top radiator hose U/S. R & R hose & top up coolant.
31/10/2016	Dawson, Dale - TWC Mechanic	4.00	Remove trailer power supply harness & modify to take replaceable wire harness - test operation. Chk
02/11/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Assist Greg Woods with Audit inspection of vehicle.
16/11/2016	Dawson, Dale - TWC Mechanic	2.00	500HR service.
18/11/2016	Dawson, Dale - TWC Mechanic	1.00	Follow up on parts & prices, drop off/pick up from wheel alignment.
30/11/2016	Dawson, Dale - TWC Mechanic	0.50	Organise parts for repairs.
01/12/2016	Dawson, Dale - TWC Mechanic	2.50	Fit 2 new mufflers, clean out radiators.
10/12/2016	Bell, Daniel - TWC Manager	6.00	Freight 261 Belatta to Nullamanna, 270 Workshop to Nullamanna, 265 Belatta to Nullamunna
11/12/2016	Bell, Daniel - TWC Manager	6.00	Freight 261 Belatta to Nullamanna, 270 Workshop to Nullamanna, 265 Belatta to Nullamunna
12/12/2016	Bell, Daniel - TWC Manager	7.00	Freight 261 Belatta to Nullamanna, 270 Workshop to Nullamanna, 265 Belatta to Nullamunna
13/12/2016	Bell, Daniel - TWC Manager	7.00	Freight 261 Belatta to Nullamanna, 270 Workshop to Nullamanna, 265 Belatta to Nullamunna
19/12/2016	Dawson, Dale - TWC Mechanic	1.50	Split truck/road train configuration. Fit air hose.
21/12/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	1,584HRS: Chk a/c operation & blow out coolers.
06/01/2017	Dawson, Dale - TWC Mechanic	1.00	1,588HRS: Test & repair a/c .
18/01/2017	Dawson, Dale - TWC Mechanic	0.50	Tighten V belts.
28/01/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	1,644HRS: Replace alternator belts.
09/02/2017	Dawson, Dale - TWC Mechanic	1.00	Back off leaking booster for repair. order & collect parts for repairs.
10/02/2017	Dawson, Dale - TWC Mechanic	1.50	R & R L/H rear brake booster & hose.
11/02/2017	Dawson, Dale - TWC Mechanic	3.50	1750HRS: Complete 250hr service. R & R brake hose - rear R/H side booster. Chk & clean L/H front hu
10/03/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & charge a/c system.
13/03/2017	Dawson, Dale - TWC Mechanic	2.00	Remove a/c system - damaged compressor thread & leaking hoses.
14/03/2017	Dawson, Dale - TWC Mechanic	5.00	A/c Repairs: Fit new compressor, dryer & 2 new hoses. Vac down system, charge & test. Chk over tyre
20/03/2017	Dawson, Dale - TWC Mechanic	1.50	Chk over - found coolant hose leaking - R & R top radiator hoses & refill coolant.
25/03/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	R & R turntable insert.
28/03/2017	Dawson, Dale - TWC Mechanic	3.00	Hook up #284 & #282. Chk all tyres. R & R flat tyre, fuel & grease.
06/04/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Fuel unit.
11/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Part wash down. Chk & adjust tyre pressures.
18/04/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Chk cooling system leak & pressure test.
01/06/2017	Dawson, Dale - TWC Mechanic	2.50	Inspect & pressure test cooling system. Repair air leak, R & R number plate light. Inspect grease s
07/06/2017	Dawson, Dale - TWC Mechanic	2.00	Investigate & pinpoint coolant leak - radiator hose leaking.
08/06/2017	Dawson, Dale - TWC Mechanic	2.00	R & R coolant hose from tank to water pump. Refill coolant & test operation.
08/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk & adjust tyre pressures.
20/06/2017	Wilde, David - TWC WORKSHOP MANAGER	2.75	Change drive tyres (8), chk pressures & tension wheel nuts.
21/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk all lights. Replace L/H high beam bulb.
22/06/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Wash engine bay.
23/06/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Repair air leaks & chk exhaust leaks.
05/07/2017	Dawson, Dale - TWC Mechanic	1.00	Detach from float & chk over.
21/07/2017	Bell, Daniel - TWC Manager	2.50	Freight scraper to jobsite.
21/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	1,940Hrs: R & R radiator overflow tube. Chk & repair air leaks.
24/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair air system.
26/07/2017	Bell, Daniel - TWC Manager	2.50	Freight scraper to jobsite.
26/07/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Investigate/locate air leak.
26/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R 2 holding valves & test for leaks.
28/07/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk air leaks & return lines.
31/07/2017	Dawson, Dale - TWC Mechanic	1.00	Repair & adjust suspension ride height on cab.
02/08/2017	Dawson, Dale - TWC Mechanic	1.50	Investigate air leak - found valve U/S - parts ordered.
04/08/2017	Dawson, Dale - TWC Mechanic	3.00	R & R park brake control valve in dash.
08/08/2017	Dawson, Dale - TWC Mechanic	1.50	Chk tyre pressures & ensure brake system working ok following repairs.
14/09/2017	Knapman, Kenneth - TWC MECHANIC	3.50	Drain oils. Purchase filters etc & complete 2,000hr service.
14/09/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	2,000Hrs service. Chk rear cab shock absorber.
15/09/2017	Knapman, Kenneth - TWC MECHANIC	3.50	Collect parts & take coolant sample. Fit cab shock, guards & steps. Top up coolant. Pack away tools
23/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	22,010HRS: Chk & replace engine brake switch & 2way hand piece.
26/09/2017	Dawson, Dale - TWC Mechanic	1.00	Prestart etc.
28/09/2017	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
28/09/2017	Dawson, Dale - TWC Mechanic	1.00	Chk over & Grease truck & float.
03/10/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & price parts for engine.

Date	Name	Duration	Notes
10/10/2017	Dawson, Dale - TWC Mechanic	4.00	2,111HRS: Remove a/c condenser & intercooler, clean out intercooler & radiator, refit & pressure test
12/10/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repair wiring to flashing lights & clearance lights.
17/10/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair wiring to reverse lights.
25/10/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & adjust tyre pressures. prestart.
08/11/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Check a/c.
08/11/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk a/c operation & clean out condenser.
09/11/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	2,203HRS: Wash down & repalce air valve.
13/11/2017	Dawson, Dale - TWC Mechanic	6.00	2,215HRS: Investigate air system fault - found air compressor not building up air at idle. R & R co
16/11/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	2,229HRS: Chk for air intake leaks. Replace hoses & gasket. Repair headlights & park lights.
21/11/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	2,257HRS: Service.
05/12/2017	Dawson, Dale - TWC Mechanic	0.50	Move truck & float & set up for greasing.
11/12/2017	Dawson, Dale - TWC Mechanic	1.00	Prestart/FGR & chk over.
14/12/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Prestart, fuel & connect up to dolly & float.
15/12/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart, chk lights. Clean brake light connection.
30/01/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	prestart/
20/02/2018	Dawson, Dale - TWC Mechanic	1.00	Chk over & test cooling system.
21/02/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Look up parts & pricing for engine rebuild.
03/03/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	Prestart. Connect dolly/float. Travel to jobsite. Remove laser mast from #265 & load & secure machi
26/03/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	2,500HRS: Service & chk over.
03/04/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart
04/04/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart
05/04/2018	Dawson, Dale - TWC Mechanic	4.00	Move trailers, hook up road train set up. Repair & mark correct hoses for road train set up - test
17/04/2018	Dawson, Dale - TWC Mechanic	1.50	Remove dolly from float & chk over truck & float.
21/04/2018	Dawson, Dale - TWC Mechanic	1.50	Chk over truck & float. Fuel up.
26/04/2018	Dawson, Dale - TWC Mechanic	1.50	Remove / replace motor
28/04/2018	Dawson, Dale - TWC Mechanic	7.50	Remove / replace motor
01/05/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Radiator repairs
01/05/2018	Dawson, Dale - TWC Mechanic	9.00	Remove / replace motor
03/05/2018	Dawson, Dale - TWC Mechanic	9.00	Remove / replace motor
04/05/2018	Dawson, Dale - TWC Mechanic	6.50	Remove / replace motor
09/05/2018	Dawson, Dale - TWC Mechanic	3.50	Remove / replace motor
29/05/2018	Dawson, Dale - TWC Mechanic	3.50	2,695HRS: R & R engine oil pressure & temp guages in dash.Repair leaking air valve. Test guage oper
02/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart, disconnect from tipper & connect up to float.
04/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,708HRS: Prestart & chk tyre pressures.
05/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,721HRS: Prestart/
06/06/2018	Dawson, Dale - TWC Mechanic	3.50	2,726HRS: R & R a/c compressor, test operation & connect up road train.
07/06/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	2,728HRS: Prestart, chk all lights. Replace reflectors. Chk air leaks & replace pressure switch - T
08/06/2018	Dawson, Dale - TWC Mechanic	1.00	2,733HRS: Repair small coolant leak - hose rubbing against clamp.
13/06/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	2,750HRS: Service.
20/06/2018	Dawson, Dale - TWC Mechanic	1.00	Chk over, prestart & hook up dolly & float.
22/06/2018	Dawson, Dale - TWC Mechanic	0.50	Prestart.
23/06/2018	Dawson, Dale - TWC Mechanic	3.00	Disconnect from float & move into w/shop. R & R bottom radiator hose - rubbing on chassis. Refill c
26/06/2018	Dawson, Dale - TWC Mechanic	1.00	Prestart, disconnect from side tipper, repair light.
30/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,782HRS: Prestart.
09/07/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,788HRS: prestart.
17/07/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,791HRS: Prestart/FGR
20/07/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,807HRS - prestart.
23/07/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	2814HRS: Prestart & chk tyre pressures.
24/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,818HRS: Pre-start & discob-nnect from float.
30/07/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart.
31/07/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,833HRS: Prestart.
01/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,836HRS: Prestart.
02/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,840HRS: Prestart.
03/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,849HRS: Prestart.
04/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,849HRS: Prestart.
06/08/2018	Wilde, David - TWC WORKSHOP MANAGER	3.75	2,861HRS: prestart. Replace power steer res. bracket. Chk & adjust brakes. Chk tyre pressures.

Date	Name	Duration	Notes
07/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,865HRS: Prestart.
08/08/2018	Dawson, Dale - TWC Mechanic	1.00	Prestart & inspect oewr road train set up.
08/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,872HRS: Prestart.
09/08/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	2,884HRS: Replace 2 front shocks.
13/08/2018	Dawson, Dale - TWC Mechanic	2.00	Re-align fuel tank in mounts - moved due to vibrations. Follow up on parts to replace tank retainin
14/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	2,900HRS: Prestart. Replace fuel tank bracket.
14/08/2018	Dawson, Dale - TWC Mechanic	2.00	2,900HRS: Prestart & refuel. R & R fuel tank strap on L/H fuel tank.
15/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,905HRS: Prestart
16/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,912Hrs: Prestart.
17/08/2018	Wilde, David - TWC WORKSHOP MANAGER	2.25	2,918HRS: Prestart, wash down & connect to float.
21/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	2,924HRS: Prestart & fuel up. Connect to tipper.
22/08/2018	Dawson, Dale - TWC Mechanic	4.00	2,926HRS: R & R power steering motor & repair wiring to fron light connector. Follow up on replacem
23/08/2018	Dawson, Dale - TWC Mechanic	1.50	R & R brake air fittings, bleed steer box, R & R bottom tank mounts, grease system, inspect over.
27/08/2018	Dawson, Dale - TWC Mechanic	1.00	R & R fuel tank retaining strap rubbers.
30/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart.
31/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	2,938HRS: Prestart. Chk & repair air leak at autogrease unit.
03/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & fuel up.
05/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace air fitting on grease unit. Test run & chk over.
06/09/2018	Dawson, Dale - TWC Mechanic	1.00	R & R broken fuel tank strap.
07/09/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Deliver to Tyrepower for wheel alignment & steer tyres.
10/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	2,949HRS: Prestart.
11/09/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,958HRS: Prestart & fuel up. Chk front wheel nuts tension. Chk front axle U bolts tension.
11/09/2018	Dawson, Dale - TWC Mechanic	0.50	2,966HRS: Repair coolant hose bracket & retorque front U bolts.
12/09/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,966HRS: Chk front wheel nut tension & U bolts. Prestart.
14/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & fuel.
15/09/2018	Dawson, Dale - TWC Mechanic	1.00	3,000HRS: Finalise 1,000hr service.
15/09/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	3,000HRS: Complete service & fill out SOS. Wash down.
19/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,995HRS: Prestart & refuel.
21/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace bug deflector.
21/09/2018	Dawson, Dale - TWC Mechanic	1.00	3,001HRS: Remove fuel tank straps, rotate tanks & use adhesive to secure in position.
22/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	3,005HRS: Prestart & fuel up.
24/09/2018	Dawson, Dale - TWC Mechanic	0.50	Assist connect dolly to float & truck.
28/09/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Investigate bonnet mount fault - disassemble for access.
28/09/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	3,049HRS: Chk over & repair bonnet.
29/09/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	3,040HRS: Refit bonnet & bumper bar.
04/10/2018	Dawson, Dale - TWC Mechanic	1.00	3,049HRS: R & R headlight bulbs, fit new LED
04/10/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	3,049HRS: Replace headlight bulbs & covers.
08/10/2018	Wilde, David - TWC WORKSHOP MANAGER	0.75	3,049HRS: prestart, fuel up & connect to float.
11/10/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	3,083HRS: Prestart/FGR
13/10/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
16/10/2018	Knapman, Kenneth - TWC MECHANIC	2.00	Repairs as required
29/10/2018	Dawson, Dale - TWC Mechanic	1.00	Fit new mirror to unit & repair mounting bracket.
02/11/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Fuel up & hook up to side tipper.
05/11/2018	Wilde, David - TWC WORKSHOP MANAGER	3.75	3,187HRS: Prestart. Rotate drive tyres & chk pressures. Polish rims. Chk over unit.
06/11/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit wheels 7 tension
06/11/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Assist refit wheels to vehicle.
07/11/2018	Knapman, Kenneth - TWC MECHANIC	3.00	Remove front engine mounts for replacement with mounts from #275
16/11/2018	Dawson, Dale - TWC Mechanic	0.50	Prestart.
19/11/2018	Dawson, Dale - TWC Mechanic	1.50	Investigate lack of brake power - repaired damaged wiring.
23/11/2018	Dawson, Dale - TWC Mechanic	2.50	3,250HRS: Service & adjust brakes. Chk lights.
23/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Unhook dolly.
25/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	3,237HRS: Prestart.
06/12/2018	Dawson, Dale - TWC Mechanic	1.00	Prestart on P/mover & #298
14/12/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	3,300HRS: Chk & clean headlight connectors.
08/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	3371HRS: Wheel alignment chk & adjust tyre pressures.
09/01/2019	Dawson, Dale - TWC Mechanic	1.50	Assist with installation new rear suspension.

Date	Name	Duration	Notes
09/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R part of rear suspension. Chk brakes.
10/01/2019	Dawson, Dale - TWC Mechanic	4.50	3,377HRS: Install new rear suspension torsion bar assy, fit new shocks, repair auto greaser.
12/01/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart, chk lights 7 clean lenses.
14/01/2019	Dawson, Dale - TWC Mechanic	0.50	Repair L/H headlight.
16/01/2019	Dawson, Dale - TWC Mechanic	0.50	Take for fitment of new drive tyres.
16/01/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Get tyre replaced.
17/01/2019	Dawson, Dale - TWC Mechanic	5.00	Investigate possible cooling system fault - clean out radiator & test sensors. Removed damaged wiri
17/01/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to electrical system.
18/01/2019	Dawson, Dale - TWC Mechanic	7.50	3,381HRS: Remove auto grease unit, disassemble & clean, reassemble & test - Investiagate elctrical
19/01/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart.
25/01/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart & connect to dolly & float.
29/01/2019	Dawson, Dale - TWC Mechanic	1.00	Prestart on P/M & float
01/02/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	3,482HRS: Prestart.
04/02/2019	Dawson, Dale - TWC Mechanic	1.00	Prestart & refuel.
11/02/2019	Dawson, Dale - TWC Mechanic	4.00	3,500HRS: Commence R & R of front leaf spring suspension
12/02/2019	Dawson, Dale - TWC Mechanic	6.50	3,500HRS: Finalise install of new front spring packs, repair 2 grease lines, retorque mount bolts f
20/02/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	3,520HRS: Carry out annual inspectiofor NHVAS report.
21/02/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	3,526HRS: R & R 2 x power steering hoses.
22/02/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace 2 x front indicator light assy's. Replace turntable insert.
22/02/2019	Knapman, Kenneth - TWC MECHANIC	1.00	Replace front indicator assy's to LED's
28/02/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart.
18/03/2019	Wilde, David - TWC WORKSHOP MANAGER	0.75	3,562HRS: Prestart & rotate 2 front tyres.
18/03/2019	Dawson, Dale - TWC Mechanic	3.00	R & R a/c hose.
19/03/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
22/03/2019	Knapman, Kenneth - TWC MECHANIC	2.00	Grease machine.
22/03/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	3,600HRS: Prestart, chk & adjust tyre pressures. Wash down.
23/03/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	3,504hrs: Replace bonnet springs.
28/03/2019	Dawson, Dale - TWC Mechanic	0.50	Inspect over & effect temporary repair to a/c.
01/04/2019	Dawson, Dale - TWC Mechanic	3.00	Repair trailer light & indicator light faults. Repair tail light harness. Inspect for air leaks, or
02/04/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart float.
03/04/2019	Dawson, Dale - TWC Mechanic	1.50	Prestart. Hook up float & dolly.
04/04/2019	Dawson, Dale - TWC Mechanic	6.00	Split truck from float, remove guards/panels etc. R & R cab air bag suspension, order new height c
05/04/2019	Dawson, Dale - TWC Mechanic	6.00	Install new ride height control valve & adjust ride height level. Fit new cab airbags & refit guard
08/04/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart
08/04/2019	Dawson, Dale - TWC Mechanic	4.00	Detach float from truck & move truck into shed. R & R fan blower motors.
09/04/2019	Dawson, Dale - TWC Mechanic	6.50	Finish install of a/c box insulation. R & R ride height control valve in seat base. Clean out cab &
10/04/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart & connect float.
29/04/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart on P/M & float.
03/05/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	3,717HRS: Prestart.
06/05/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	3,750HRS: Service, prestart, fit clamp to hoses.
07/05/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart.
09/05/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart & repair air leaks.
09/05/2019	Dawson, Dale - TWC Mechanic	2.50	Investigate & locate air leak - found cab ride height valve faulty - replaced valve.
13/05/2019	Dawson, Dale - TWC Mechanic	1.00	Prestart
14/05/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/chk lights.
20/05/2019	Dawson, Dale - TWC Mechanic	2.50	prestart & repair trailer electrical plug.
31/05/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	3,912HRS: Prestart. Replace loose bolts in suspension, repair broken wire on alternator.
04/06/2019	Wilde, David - TWC WORKSHOP MANAGER	0.75	Prestart & change over trailer.
06/06/2019	Dawson, Dale - TWC Mechanic	3.50	Unload float & investigate a/c fault - pressurised system & loacated gas leak. parts ordered for re
07/06/2019	Dawson, Dale - TWC Mechanic	4.00	R & R a/c hoses. R & R ignition key barrel & door locks - damaged. Repair passenger side window - n
11/06/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Remove broken stud from a/c bracket.
11/06/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	3,955HRS: Dismantle a/c evaporator & chk for leaks. repair mounting box.
12/06/2019	Knapman, Kenneth - TWC MECHANIC	2.00	Make up & fir a/c systen bracket.
12/06/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Re-assemble dash and tighten up all screws. Chk cab for loose screws/panels etc.
14/06/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	3,955HRS: Prestart. Replace batteires (4). Take for wheel alignment & replace steer tyres. Chk door
15/06/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	R & R R/H window regulator.

Date	Name	Duration	Notes
20/06/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	3,961HRS: Prestart
26/06/2019	Dawson, Dale - TWC Mechanic	4.50	Retention front wheel nuts. Retention diff housing to suspension arm mount bolts. Inspect drivers s
04/07/2019	Dawson, Dale - TWC Mechanic	4.50	3,979HRS: Assist carry out 2,000hr service.
05/07/2019	Dawson, Dale - TWC Mechanic	2.00	Complete 2,000hr service.
27/08/2019	Dawson, Dale - TWC Mechanic	1.00	Prestart on P/M & float assy.
11/09/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart
19/09/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart?FGR
23/09/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart.
03/10/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
10/10/2019	Knapman, Kenneth - TWC MECHANIC	3.00	Carry out electrical repairs to wiring/clearance lights. Remove 5th wheel bearing - measurements fo
14/10/2019	Dawson, Dale - TWC Mechanic	2.00	Prestart, chk tyres & grease.
18/10/2019	Dawson, Dale - TWC Mechanic	3.00	4,123HRS: Chk over, repair grease line to front king pin. Grease drive line. Investigate & repair f
21/10/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	4,126HRS: Replace L/H park light bulb.
01/11/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,178HRS: Prestart & have windscreen replaced.
09/12/2019	Wilde, David - TWC WORKSHOP MANAGER	4.50	4,250HRS: Replace grease nipples & chk over machine.
12/12/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	4,282HRS: Prestart.
09/01/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Assist investigate/locate air leaks.
09/01/2020	Wilde, David - TWC WORKSHOP MANAGER	5.00	4,307HRS: 12 months inspection. Chk cooling & a/c operation.
10/01/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	4,307HRS: Replace eng. temp sender unit & test run.
16/01/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,333HRS: prestart & chk tyre pressures. Replace Temp. guage.
21/01/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,361HRS: Prestart and repair CAT data link.
23/01/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Replace engine oil pressure sender
14/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	4,434HRS: R & R steering link. Get front tyre rotated & retension. Refit grease lines.
20/02/2020	Knapman, Kenneth - TWC MECHANIC	3.00	Replace airswitch.
20/02/2020	Wilde, David - TWC WORKSHOP MANAGER	3.50	4,444HRS: Repair air leaks & replace heater valve.
24/02/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,445HRS: Replace heater tap.
16/03/2020	Wilde, David - TWC WORKSHOP MANAGER	0.25	4,456HRS: prestart.
17/03/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	4,457HRS: prestart & chk lights.
19/03/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Assist fit replacement cab mount.
19/03/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	4,481HRS: Chk cab noise & replace front cab mounts.
20/03/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace 2 cab mounts.
23/03/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Replace traction valve. Replace moisture diverter for bonnet/windscreen.
23/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.25	4,481HRS: Prestart. R & R traction valve & diverter under windscreen.
24/03/2020	Wilde, David - TWC WORKSHOP MANAGER	0.25	4,486HRS: Prestart.
06/04/2020	Wilde, David - TWC WORKSHOP MANAGER	2.50	4,500HRS: Service / chk tyre pressures.
07/04/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,500HRS: Chk wiring to oil guage. order parts.
23/04/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,546HRS: Wash down.
07/05/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,553HRS: Chk & adjust tyre pressures.
11/05/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,560HRS: prestart & have drive tyres re-grooved.
12/05/2020	Wilde, David - TWC WORKSHOP MANAGER	0.25	4,560HRS: Prestart.
19/05/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,580HRS: Chk & replace clearance light.
21/05/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,586HRS: Remove, repair & refit tyre.
25/05/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,590HRS: prestart and connect to trailers.
26/05/2020	Wilde, David - TWC WORKSHOP MANAGER	5.00	4,592HRS: remove trailers. Connect to #298. Grease drive shaft.
27/05/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	4,586HRS: Remove & replace E stop assy & test run. Chk over.
01/06/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Connect to side tipper #292
03/06/2020	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart (4,612hrs).
09/06/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Disconnect #292 & connect #298
19/06/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,676HRS: Chk & tighten L/H rear brake booster mount. Grease main rive train. Repair battery lid.
29/06/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR & chk tyre pressure.
03/07/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adjust belts.
17/07/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	4,750HRS: Service. Clean wiring to windscreen washers.
03/08/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,793HRS: Connect to trailers & chk lights.
07/08/2020	Knapman, Kenneth - TWC MECHANIC	3.00	R & R front cab mount.
07/08/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	4,836HRS: Repairs to bonnet mounts.
10/08/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Remove drive wheels & brake shoes etc.

<u>Date</u>	<u>Name</u>	<u>Duration</u>	<u>Notes</u>
10/08/2020	Wilde, David - TWC WORKSHOP MANAGER	5.50	4,836HRS: Reassemble bonnet pivot & bumper. Remove rear wheels & brakes. price parts.
11/08/2020	Knapman, Kenneth - TWC MECHANIC	3.50	Clean brake assemblies & hubs etc.
12/08/2020	Knapman, Kenneth - TWC MECHANIC	4.50	Re-assemblt brake assays.
12/08/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Assist re-assemble brakes etc.
13/08/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Fit new wheel hubs, bearings & refit tyres & axles. tension whddel bearings.
14/08/2020	Knapman, Kenneth - TWC MECHANIC	5.00	Fit slack adjusters, fill diffs & final drive with oil. Adjust brakes & tension wheel nuts. Fit cap
14/08/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Test drive unit.
19/08/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,840HRS: Chk wheel bearings & adjust brakes.
26/08/2020	Wilde, David - TWC WORKSHOP MANAGER	0.25	4,884HRS: Chk fan belts.
03/09/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	4,896HRS: Chk tyre pressures.
21/09/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	4,930HRS: Chk over & have 8 drive tyres replaced.
22/09/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	4,930HRS: Replace exhaust clamps & fit rubber under piping.
13/10/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk tip operation & change air lines.
16/10/2020	Knapman, Kenneth - TWC MECHANIC	1.00	5,000Hrs service.
16/10/2020	Wilde, David - TWC WORKSHOP MANAGER	4.50	5,000Hr service. Repair wiring to gear box sender.
09/11/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Replace stud for oversize sign cover
13/11/2020	Knapman, Kenneth - TWC MECHANIC	4.00	Remove rear light bar/bumper & dismantle. Undo mudguards ready for replacement. Straighten mudguard
16/11/2020	Knapman, Kenneth - TWC MECHANIC	9.50	5,063HRS: Fit replacement mudguards, refit rear bumper & new LED light assemblies. Refit clearance
16/11/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	5,063HRS: R & R mudguards & tail lights. prestart.
17/11/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Prestart & refuel. Connect to side tipper trailers (road train). Chk tyre pressures.
09/12/2020	Knapman, Kenneth - TWC MECHANIC	6.50	5,243HRS: 250hr service. Replace front air system dump valve, grease driveline, investigate a/c duc
04/01/2021	Knapman, Kenneth - TWC MECHANIC	5.00	Disassemble dash to access air con vent adjuster remove and inspect and repair, adjust bonnet
05/01/2021	Knapman, Kenneth - TWC MECHANIC	5.50	Disassemble dash to access air con vent adjuster remove and inspect and repair, adjust bonnet
08/01/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	5,327HRS: Chk & tighten turbo inlet clamps. Replace bolt in alternator bracket. Clean a/c drain lin
03/02/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Deliver to GWS for inspection. Locate air leak & repair.
06/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	5,395HRS: Prestart & chk tyre pressures.
10/02/2021	Knapman, Kenneth - TWC MECHANIC	1.50	5,411HRS Purchase replacement brake booster & fit to front R/H drive wheel
10/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	5,411HRS: Assist replace front brake booster.
19/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	5,420HRS: Adjust brakes. repair grease line. repairs to brake booster.
20/02/2021	Wilde, David - TWC WORKSHOP MANAGER	4.50	repair air leaks & grease lines. Replace mudguard bracket.
24/02/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	5,420HRS: R & R steering linkage.
26/02/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	5,420HRS: Chk & adjust steering wheel alignment. Get steer tyres rotated, wash down.
06/03/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	5434 hrs - Check over
06/04/2021	Wilde, David - TWC WORKSHOP MANAGER	0.25	5,459 hrs - Pre Start
19/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	5500Hrs service
06/05/2021	Knapman, Kenneth - TWC MECHANIC	2.50	Replace warning stickers. Replace reverse alarm (sqarker alarm)
07/05/2021	Knapman, Kenneth - TWC MECHANIC	6.50	Remove and replace air switch; filter and valve assy.
11/05/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Replace LH side ride height leveling valve
		<u>1,154.10</u>	
	<b>TOTAL</b>	<b><u>1,154.10</u></b>	

Total 289 - Kenworth Prime Mover:289E