

275 - Kenworth Truck:275E

| Date       | Name                                | Duration | Notes  |
|------------|-------------------------------------|----------|--|
| 03/09/2010 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Check exhaust brake fault & disconnect switch(Q988C)/ Check eng. misfire, check wiring, remove tapp  |
| 06/09/2010 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | Check exhaust brake fault & disconnect switch(Q988C)/ Check eng. misfire, check wiring, remove tapp  |
| 17/09/2010 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | R & R engine harness & test run.   |
| 30/10/2010 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | Isolate & drain fuel tank, remove old fuel lines.  |
| 09/11/2010 | Wilde, David - TWC WORKSHOP MANAGER | 2.25     | Connect air lines & test run trailer, swap hyd. hoses & test run, repair A/C.                        |
| 13/11/2010 | Wilde, David - TWC WORKSHOP MANAGER | 4.00     | R & R bearings in adjuster, Repalce A/C belt & fan belts, check hyd. problem between truck & traile  |
| 15/11/2010 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | R & R bearings in adjuster, Repalce A/C belt & fan belts, check hyd. problem between truck & traile  |
| 18/11/2010 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Locate air leaks, replace switch, repair bonnet catch & repair broken dash./ Clean out indicator sw  |
| 19/11/2010 | Wilde, David - TWC WORKSHOP MANAGER | 3.50     | Locate air leaks, replace switch, repair bonnet catch & repair broken dash./ Clean out indicator sw  |
| 22/11/2010 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Locate air leaks, replace switch, repair bonnet catch & repair broken dash./ Clean out indicator sw  |
| 26/11/2010 | Wilde, David - TWC WORKSHOP MANAGER | 4.50     | Chk & adjust brakes, chk suspension for worn parts, look up & order parts, repair wiring on L/H hea  |
| 30/11/2010 | Wilde, David - TWC WORKSHOP MANAGER | 7.50     | Chk & adjust brakes, chk suspension for worn parts, look up & order parts, repair wiring on L/H hea  |
| 01/12/2010 | Wilde, David - TWC WORKSHOP MANAGER | 5.50     | Chk & adjust brakes, chk suspension for worn parts, look up & order parts, repair wiring on L/H hea  |
| 06/12/2010 | Wilde, David - TWC WORKSHOP MANAGER | 5.00     | Chk front & rear eng. mounts, R & R oil line from compressor, fit clamps to fuel lines               |
| 15/12/2010 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Replace tail light assy.   |
| 04/01/2011 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Fit window deflector, replace L/H front oil cap, fit air dump valve.                                 |
| 28/01/2011 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | make up trailer to truck electrical & hydraulic leads, test run & load 273 onto float/ Make new el   |
| 31/01/2011 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | make up trailer to truck electrical & hydraulic leads, test run & load 273 onto float/ Make new el   |
| 01/02/2011 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | make up trailer to truck electrical & hydraulic leads, test run & load 273 onto float/ Make new el   |
| 13/04/2011 | Knapman, Kenneth - TWC MECHANIC     | 1.50     | Repair trailer ramp hinge bracket  |
| 28/04/2011 | Knapman, Kenneth - TWC MECHANIC     | 8.50     | Repairs to float trailer   |
| 29/04/2011 | Knapman, Kenneth - TWC MECHANIC     | 8.00     | Repairs to float trailer   |
| 14/07/2011 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Arrange rego inspection & repairs/Repairs  |
| 18/07/2011 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | Chk & repair trailer lights for rego inspec., have windscreen & tyres fitted to truck/ Chk & repair  |
| 19/07/2011 | Knapman, Kenneth - TWC MECHANIC     | 1.50     | Arrange rego inspection & repairs/Repairs  |
| 19/07/2011 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Chk & repair trailer lights for rego inspec., have windscreen & tyres fitted to truck/ Chk & repair  |
| 20/07/2011 | Knapman, Kenneth - TWC MECHANIC     | 2.50     | Arrange rego inspection & repairs/Repairs  |
| 20/07/2011 | Wilde, David - TWC WORKSHOP MANAGER | 4.00     | Chk & repair trailer lights for rego inspec., have windscreen & tyres fitted to truck/ Chk & repair  |
| 25/07/2011 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | Fit air fittings to gate valve./Service air fittings, hook truck to water tanker, modify tool to ti  |
| 25/07/2011 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | Refit bumper bar   |
| 25/07/2011 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Remove gate valve on tanker, fit air valve & refit gate valve.                                       |
| 26/07/2011 | Knapman, Kenneth - TWC MECHANIC     | 8.00     | Fit air fittings to gate valve./Service air fittings, hook truck to water tanker, modify tool to ti  |
| 27/07/2011 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Fit air fittings to gate valve./Service air fittings, hook truck to water tanker, modify tool to ti  |
| 29/07/2011 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Connect to Haddads trailer & fit air lines./Chk gearbox & diff oils, replace clamps on air lines, f  |
| 30/07/2011 | Wilde, David - TWC WORKSHOP MANAGER | 5.00     | Connect to Haddads trailer & fit air lines./Chk gearbox & diff oils, replace clamps on air lines, f  |
| 05/08/2011 | Knapman, Kenneth - TWC MECHANIC     | 2.00     | Drain coolant & replace hose, refill, arrange for body cut & polish.                                 |
| 29/08/2011 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Chk fault codes & prestart   |
| 25/10/2011 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Chk batteries & jump start.  |
| 16/11/2011 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | Unhook tanker & connect to Haddah tippers  |
| 24/11/2011 | Bell, Daniel - TWC Manager          | 7.50     | Carry out RTA inspection checklist & complete repairs where needed. Travel to & from Inverell for R  |
| 06/12/2011 | Griffin, Reece - Plant Mechanic     | 5.00     | Clean & polish   |
| 06/12/2011 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Polish cab   |
| 10/01/2012 | Griffin, Reece - Plant Mechanic     | 2.00     | Wash truck & tanker/Chk over & prep for work.  |
| 11/01/2012 | Griffin, Reece - Plant Mechanic     | 3.25     | Wash truck & tanker/Chk over & prep for work.  |
| 16/03/2012 | Bell, Daniel - TWC Manager          | 8.50     | Carry out 100,000km service & install hour meter. Return to Moree                                    |
| 27/03/2012 | Bell, Daniel - TWC Manager          | 0.50     | Replace fuel priming pump.   |
| 02/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Look up parts etc.   |
| 14/06/2012 | Bell, Daniel - TWC Manager          | 7.50     | Replace starter motor & carry out 250hr service. 250hrs  |
| 14/06/2012 | Griffin, Reece - Plant Mechanic     | 2.00     | 250 hr service./Repair work  |
| 14/06/2012 | Knapman, Kenneth - TWC MECHANIC     | 8.00     | Purchase parts, disassemble hub, clean & reassemble, reassemble brakes on drive./Reassemble final dr |

| Date       | Name                                | Duration | Notes  |
|------------|-------------------------------------|----------|--|
| 14/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 5.00     | 220hrs part service, remove & replace rear brakes./ Repairs to front brakes & wheel bearings./ Wash  |
| 15/06/2012 | Griffin, Reece - Plant Mechanic     | 3.00     | 250 hr service./Repair work  |
| 15/06/2012 | Knapman, Kenneth - TWC MECHANIC     | 9.50     | Purchase parts, disassemble hub, clean & reassemble, reassemble brakes on drive./Reassemble final dr |
| 15/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 6.50     | 220hrs part service, remove & replace rear brakes./ Repairs to front brakes & wheel bearings./ Wash  |
| 16/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 4.50     | 220hrs part service, remove & replace rear brakes./ Repairs to front brakes & wheel bearings./ Wash  |
| 18/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 220hrs part service, remove & replace rear brakes./ Repairs to front brakes & wheel bearings./ Wash  |
| 21/06/2012 | Knapman, Kenneth - TWC MECHANIC     | 2.00     | Start remove transmission./Complete transmission removal & adapt trans. stand./ Replace transmissio  |
| 21/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | Look up & order parts, remove gearbox./Remove gearbox & clutch, replace rear eng. seal & clutch ass  |
| 21/06/2012 | Bell, Daniel - TWC Manager          | 3.00     | Troubleshoot clutch pedal end float. Return truck to Dalby   |
| 22/06/2012 | Bell, Daniel - TWC Manager          | 2.00     | Troubleshoot clutch pedal end float. Return truck to Dalby   |
| 22/06/2012 | Griffin, Reece - Plant Mechanic     | 3.00     | Replace rear engine oil seal & pilot bearing./ Install uni's & drive shafts, check over truck & tes  |
| 22/06/2012 | Knapman, Kenneth - TWC MECHANIC     | 9.50     | Start remove transmission./Complete transmission removal & adapt trans. stand./ Replace transmissio  |
| 22/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 9.50     | Look up & order parts, remove gearbox./Remove gearbox & clutch, replace rear eng. seal & clutch ass  |
| 23/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 7.00     | Look up & order parts, remove gearbox./Remove gearbox & clutch, replace rear eng. seal & clutch ass  |
| 23/06/2012 | Bell, Daniel - TWC Manager          | 3.00     | Troubleshoot clutch pedal end float. Return truck to Dalby   |
| 23/06/2012 | Knapman, Kenneth - TWC MECHANIC     | 7.50     | Start remove transmission./Complete transmission removal & adapt trans. stand./ Replace transmissio  |
| 25/06/2012 | Griffin, Reece - Plant Mechanic     | 8.50     | Replace rear engine oil seal & pilot bearing./ Install uni's & drive shafts, check over truck & tes  |
| 25/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 9.50     | Look up & order parts, remove gearbox./Remove gearbox & clutch, replace rear eng. seal & clutch ass  |
| 26/06/2012 | Bell, Daniel - TWC Manager          | 4.00     | Troubleshoot clutch pedal end float. Return truck to Dalby   |
| 29/06/2012 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | Wash down.   |
| 08/08/2012 | Dawson, Dale - TWC Mechanic         | 1.50     | Carry out 250hr engine service.  |
| 13/08/2012 | Griffin, Reece - Plant Mechanic     | 4.00     | Collected & organised parts for travel to jobsite to carry out repairs, packed ute with required ge  |
| 14/08/2012 | Griffin, Reece - Plant Mechanic     | 7.25     | Collected & organised parts for travel to jobsite to carry out repairs, packed ute with required ge  |
| 14/08/2012 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 512hrs: Replace waterpump & engine oil cooler./ Clean out cooling system.                            |
| 15/08/2012 | Griffin, Reece - Plant Mechanic     | 9.50     | Collected & organised parts for travel to jobsite to carry out repairs, packed ute with required ge  |
| 15/08/2012 | Wilde, David - TWC WORKSHOP MANAGER | 3.50     | 512hrs: Replace waterpump & engine oil cooler./ Clean out cooling system.                            |
| 16/08/2012 | Wilde, David - TWC WORKSHOP MANAGER | 7.50     | Clean & flush cooling system, fill with coolant & shift to jobsite./ Unload waste coolant & oil, c   |
| 17/08/2012 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Clean & flush cooling system, fill with coolant & shift to jobsite./ Unload waste coolant & oil, c   |
| 28/08/2012 | Dawson, Dale - TWC Mechanic         | 2.50     | Travel Dalby to Glendower jobsite .5hrs, drain coolant, refill with new ELC, drain power steer flui  |
| 28/08/2012 | Griffin, Reece - Plant Mechanic     | 2.50     | Travel Dalby to Glendower jobsite, drain coolant & refill with new ELC, drain power steer fluid & r  |
| 18/09/2012 | Wilde, David - TWC WORKSHOP MANAGER | 2.50     | 750hrs service, travel to Tara.  Travel to gravel pit, chk volt meter & oil pressure guages, chk dr  |
| 19/09/2012 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 750hrs service, travel to Tara.  Travel to gravel pit, chk volt meter & oil pressure guages, chk dr  |
| 25/09/2012 | Dawson, Dale - TWC Mechanic         | 3.50     | Complete repairs including; fit new engine fuel primer, engine oil pressure & volt guages, new stee  |
| 25/09/2012 | Griffin, Reece - Plant Mechanic     | 3.50     | Complete repairs including; fit new engine fuel primer, engine oil pressure & volt guages, new stee  |
| 26/09/2012 | Dawson, Dale - TWC Mechanic         | 0.50     | Complete repairs including; fit new engine fuel primer, engine oil pressure & volt guages, new stee  |
| 26/09/2012 | Griffin, Reece - Plant Mechanic     | 0.50     | Complete repairs including; fit new engine fuel primer, engine oil pressure & volt guages, new stee  |
| 04/10/2012 | Dawson, Dale - TWC Mechanic         | 1.00     | Install new radio.   |
| 04/10/2012 | Griffin, Reece - Plant Mechanic     | 1.00     | Install new radio & chk over vehicle.  |
| 12/10/2012 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | 902hrs: Replace gearbox filter & chk over & disconnect trailer.                                      |
| 20/10/2012 | Wilde, David - TWC WORKSHOP MANAGER | 4.00     | 974hrs: Adjust ride height valves, chk engine mounts, travel to Moree                                |
| 22/10/2012 | Griffin, Reece - Plant Mechanic     | 2.50     | Travel to/from jobsite, repair headlight./ Service vehicle, chk brakes & tighten rocker box.         |
| 23/10/2012 | Dawson, Dale - TWC Mechanic         | 2.50     | Effect engine service, chk & adjust brakes & tighten ? rocker shaft bolts                            |
| 23/10/2012 | Griffin, Reece - Plant Mechanic     | 1.50     | Travel to/from jobsite, repair headlight./ Service vehicle, chk brakes & tighten rocker box.         |
| 31/10/2012 | Wilde, David - TWC WORKSHOP MANAGER | 4.50     | R & R bonnet hinge & travel to Tara.   |
| 08/11/2012 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Replace head light bulbs. 1126hrs  |
| 12/11/2012 | Dawson, Dale - TWC Mechanic         | 1.50     | Inspect front king pins for movement all OK. Truck needs wheel alignment & new front tyres. 1150hrs  |
| 24/11/2012 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Look up & pick up parts./ Fill oil bottles.  |
| 26/11/2012 | Dawson, Dale - TWC Mechanic         | 1.00     | Full inspection of trailer due to broken suspension bolts, tighten rocker box bolts./1244hrs: compl  |
| 26/11/2012 | Griffin, Reece - Plant Mechanic     | 1.00     | 1239hrs: Complete visual inspection due to loose suspensionn bolts, tighten rocker box bolts./ 1244  |
| 27/11/2012 | Dawson, Dale - TWC Mechanic         | 1.50     | Full inspection of trailer due to broken suspension bolts, tighten rocker box bolts./1244hrs: compl  |
| 27/11/2012 | Griffin, Reece - Plant Mechanic     | 1.50     | 1239hrs: Complete visual inspection due to loose suspensionn bolts, tighten rocker box bolts./ 1244  |
| 27/11/2012 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Look up & pick up parts./ Fill oil bottles.  |

| Date       | Name                                | Duration | Notes   |
|------------|-------------------------------------|----------|---|
| 28/11/2012 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Look up & pick up parts./ Fill oil bottles.   |
| 16/12/2012 | Griffin, Reece - Plant Mechanic     | 2.00     | Remove idler pulley, install new bearings, replace idler.   |
| 04/01/2013 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 1523hrs: Chk over./ 1500hrs service, replace bolt in alternator bracket & fuel line clamps.         |
| 08/01/2013 | Wilde, David - TWC WORKSHOP MANAGER | 2.50     | 1523hrs: Chk over./ 1500hrs service, replace bolt in alternator bracket & fuel line clamps.         |
| 15/01/2013 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 1597hrs: Chk air to dribble bar.  |
| 17/01/2013 | Wilde, David - TWC WORKSHOP MANAGER | 6.00     | Chk & repair air leak, remove broken shock absorber, travel to Dalby to collect parts & return.     |
| 24/01/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | Locate fault in air supply for water jet - control valve faulty - to be replaced./ Install left rea |
| 24/01/2013 | Griffin, Reece - Plant Mechanic     | 1.00     | Locate air valve problem./ Oush emergency brak off to prevent air from by passing to build up press |
| 25/01/2013 | Dawson, Dale - TWC Mechanic         | 2.50     | Locate fault in air supply for water jet - control valve faulty - to be replaced./ Install left rea |
| 26/01/2013 | Griffin, Reece - Plant Mechanic     | 0.50     | Locate air valve problem./ Oush emergency brak off to prevent air from by passing to build up press |
| 05/02/2013 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | 1,652hrs: Chk rims for correct size, replace 2 switches in dash & test run.                         |
| 14/03/2013 | Griffin, Reece - Plant Mechanic     | 2.00     | Complete 250hrs service & chk all oils.   |
| 19/03/2013 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 1,754Hrs: Chk over.   |
| 30/03/2013 | Griffin, Reece - Plant Mechanic     | 5.00     | 1811Hrs?: Repair starting problem, purchase & install new batteries, adjust bonnet mounts.          |
| 07/04/2013 | Dawson, Dale - TWC Mechanic         | 0.50     | Fit safety strap to bonnet./ R & R ride control valve on/h rear & set ride hight, tighten V belts.  |
| 08/04/2013 | Dawson, Dale - TWC Mechanic         | 1.50     | Fit safety strap to bonnet./ R & R ride control valve on/h rear & set ride hight, tighten V belts.  |
| 09/04/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | Fit safety strap to bonnet./ R & R ride control valve on/h rear & set ride hight, tighten V belts.  |
| 11/04/2013 | Griffin, Reece - Plant Mechanic     | 1.00     | Chk & repair tail lights./ Repair mud guard bracket   |
| 17/04/2013 | Griffin, Reece - Plant Mechanic     | 1.00     | Chk & repair tail lights./ Repair mud guard bracket   |
| 17/04/2013 | Dawson, Dale - TWC Mechanic         | 1.50     | 1889HRS: R & R bolt in mudguard mounts, inspect & pinpoint air leak, order parts for repair.        |
| 18/04/2013 | Dawson, Dale - TWC Mechanic         | 0.50     | Repair flashing light./ Volt guage not working - u/s./ R & R hose clamp on eng. coolant pipe - hose |
| 19/04/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | Repair flashing light./ Volt guage not working - u/s./ R & R hose clamp on eng. coolant pipe - hose |
| 20/04/2013 | Dawson, Dale - TWC Mechanic         | 0.50     | Repair flashing light./ Volt guage not working - u/s./ R & R hose clamp on eng. coolant pipe - hose |
| 21/04/2013 | Dawson, Dale - TWC Mechanic         | 2.00     | Repair flashing light./ Volt guage not working - u/s./ R & R hose clamp on eng. coolant pipe - hose |
| 22/04/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | Repair flashing light./ Volt guage not working - u/s./ R & R hose clamp on eng. coolant pipe - hose |
| 23/04/2013 | Dawson, Dale - TWC Mechanic         | 1.50     | Repair flashing light./ Volt guage not working - u/s./ R & R hose clamp on eng. coolant pipe - hose |
| 04/05/2013 | Dawson, Dale - TWC Mechanic         | 2.00     | 1995HRS: Part engine service R & R alternator belts./ Complete 2000hrs service, R & R diff oils, h  |
| 05/05/2013 | Dawson, Dale - TWC Mechanic         | 3.00     | 1995HRS: Part engine service R & R alternator belts./ Complete 2000hrs service, R & R diff oils, h  |
| 07/05/2013 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Replace compressor oil line.  |
| 09/05/2013 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Repair Navman./ Replace r/h ride height valve & adjust rods. Chk for air leaks, chk maxi brakes.    |
| 10/05/2013 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | Repair Navman./ Replace r/h ride height valve & adjust rods. Chk for air leaks, chk maxi brakes.    |
| 24/05/2013 | Dawson, Dale - TWC Mechanic         | 0.50     | Repair trailer plug./ Locate & repair air leak on gearbox.  |
| 26/05/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | Repair trailer plug./ Locate & repair air leak on gearbox.  |
| 05/06/2013 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | 2100HRS: Chk & repair headlight wiring, chk air bag suspension.                                     |
| 27/06/2013 | Griffin, Reece - Plant Mechanic     | 0.50     | Repair engine oil pressure sensor.  |
| 06/07/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | 2242Hrs: Repair front indicators - both bulbs blown, inspect over unit./ 2251HRS: Complete 250hr se |
| 08/07/2013 | Dawson, Dale - TWC Mechanic         | 1.50     | 2242Hrs: Repair front indicators - both bulbs blown, inspect over unit./ 2251HRS: Complete 250hr se |
| 20/08/2013 | Dawson, Dale - TWC Mechanic         | 0.50     | Locate & repair fault in clearance light.   |
| 17/09/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | Tighten fan/alternator belts.   |
| 17/09/2013 | Dawson, Dale - TWC Mechanic         | 1.50     | Locate fault with parking & tail lights - dead short located in wiring harness to headlight & repai |
| 28/09/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | Loosen fuel tank, jack tank, refit rubber mount to strapping, rebolt tank. 1hr                      |
| 11/10/2013 | Dawson, Dale - TWC Mechanic         | 0.01     | Chk over & grease.5hr   |
| 01/11/2013 | Griffin, Reece - Plant Mechanic     | 5.50     | 2789HRS: Remove & disassemble t'table, clean up parts. R & R diff radius rod bushes & reinstall./ A |
| 01/11/2013 | Knapman, Kenneth - TWC MECHANIC     | 8.50     | Remove mud guards & side panels, remove t'table & disassemble, purchase parts, remove steering shaf |
| 04/11/2013 | Dawson, Dale - TWC Mechanic         | 2.50     | 2789HRS: R & R fuel tank straps, repair fault with windscreen washers./ 2790HRS: Fit new headlight, |
| 04/11/2013 | Griffin, Reece - Plant Mechanic     | 1.50     | 2789HRS: Remove & disassemble t'table, clean up parts. R & R diff radius rod bushes & reinstall./ A |
| 04/11/2013 | Knapman, Kenneth - TWC MECHANIC     | 7.50     | Remove mud guards & side panels, remove t'table & disassemble, purchase parts, remove steering shaf |
| 05/11/2013 | Dawson, Dale - TWC Mechanic         | 3.00     | 2789HRS: R & R fuel tank straps, repair fault with windscreen washers./ 2790HRS: Fit new headlight, |
| 05/11/2013 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | have tyres fitted.  |
| 06/11/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | 2789HRS: R & R fuel tank straps, repair fault with windscreen washers./ 2790HRS: Fit new headlight, |
| 06/11/2013 | Griffin, Reece - Plant Mechanic     | 9.50     | 2789HRS: Remove & disassemble t'table, clean up parts. R & R diff radius rod bushes & reinstall./ A |
| 06/11/2013 | Knapman, Kenneth - TWC MECHANIC     | 5.50     | Remove mud guards & side panels, remove t'table & disassemble, purchase parts, remove steering shaf |

| Date       | Name                                | Duration | Notes   |
|------------|-------------------------------------|----------|---|
| 07/11/2013 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Disconnect from trailer, clean front indicator sockets, adjust brakes.                              |
| 09/11/2013 | Griffin, Reece - Plant Mechanic     | 1.50     | Commence removal of shock absorbers.  |
| 11/11/2013 | Dawson, Dale - TWC Mechanic         | 8.00     | R & R on shock absorber on rear diffs, fit new rubber mounts to shocks, realign & refit steps into  |
| 20/11/2013 | Dawson, Dale - TWC Mechanic         | 1.00     | Complete speedo calibration.  |
| 09/12/2013 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | 2789HRS: Assist with removal of king pins.  |
| 10/12/2013 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Test drive following wheel alignment.   |
| 06/01/2014 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Prestart & run machine.   |
| 23/01/2014 | Dawson, Dale - TWC Mechanic         | 4.00     | Assist detail truck, fit steps to tank, make up new brackets/retainers to hold steps, remove hyd. h |
| 23/01/2014 | Griffin, Reece - Plant Mechanic     | 4.50     | Assist polish/dtail truck.  |
| 23/01/2014 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Fit steps to fuel tanks & polish cab  |
| 16/02/2014 | Bell, Daniel - TWC Manager          | 0.50     | FGR   |
| 17/02/2014 | Dawson, Dale - TWC Mechanic         | 0.50     | Prestart chk.   |
| 18/02/2014 | Dawson, Dale - TWC Mechanic         | 0.25     | Prestart chk.   |
| 19/02/2014 | Griffin, Reece - Plant Mechanic     | 2.00     | Order parts & collect. Grease truck & adjust brakes, replace dash screws.                           |
| 20/02/2014 | Bell, Daniel - TWC Manager          | 0.00     | FGR   |
| 27/02/2014 | Bell, Daniel - TWC Manager          | 0.00     | FGR   |
| 01/03/2014 | Griffin, Reece - Plant Mechanic     | 1.00     | Prestart/FGR  |
| 03/03/2014 | Dawson, Dale - TWC Mechanic         | 1.50     | 2905HRS: R & R worn out tyres & take old one for fitting new tyres.                                 |
| 06/03/2014 | Bell, Daniel - TWC Manager          | 0.00     | FGR   |
| 07/03/2014 | Dawson, Dale - TWC Mechanic         | 2.00     | Chk engine noise - found idler pulley & V belts U/S- remove from vehicle, collect order replacement |
| 08/03/2014 | Dawson, Dale - TWC Mechanic         | 2.00     | Chk engine noise - found idler pulley & V belts U/S- remove from vehicle, collect order replacement |
| 13/03/2014 | Bell, Daniel - TWC Manager          | 0.00     | FGR   |
| 14/03/2014 | Dawson, Dale - TWC Mechanic         | 4.00     | 2984HRS: 1000Hr service, chk over & carry out brake adjustment                                      |
| 18/03/2014 | Dawson, Dale - TWC Mechanic         | 0.50     | Fill out SOS & dispatch.  |
| 02/04/2014 | Dawson, Dale - TWC Mechanic         | 7.00     | 20007HRS: Disengage from trailer, remove guards & wash. Assist with removal of transmission for re  |
| 03/04/2014 | Dawson, Dale - TWC Mechanic         | 6.50     | Organise parts for repairs & collect. R & R cab air bags, R & R cab shock absorbers, bonnet pivot m |
| 04/04/2014 | Dawson, Dale - TWC Mechanic         | 1.00     | Organise parts for repairs & collect. R & R cab air bags, R & R cab shock absorbers, bonnet pivot m |
| 07/04/2014 | Dawson, Dale - TWC Mechanic         | 7.50     | Organise parts for repairs & collect. R & R cab air bags, R & R cab shock absorbers, bonnet pivot m |
| 07/04/2014 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Assist with bush removal & replacement./ Gouge out welds of spring bushes.                          |
| 08/04/2014 | Dawson, Dale - TWC Mechanic         | 9.50     | Organise parts for repairs & collect. R & R cab air bags, R & R cab shock absorbers, bonnet pivot m |
| 08/04/2014 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Assist with bush removal & replacement./ Gouge out welds of spring bushes.                          |
| 09/04/2014 | Dawson, Dale - TWC Mechanic         | 9.50     | Organise parts for repairs & collect. R & R cab air bags, R & R cab shock absorbers, bonnet pivot m |
| 10/04/2014 | Knapman, Kenneth - TWC MECHANIC     | 1.50     | Weld repair fuel tank mount.  |
| 10/04/2014 | Dawson, Dale - TWC Mechanic         | 4.00     | 3007HRS: Finalise install of trans., fuel tank, guards etc. Test operation.                         |
| 28/04/2014 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 3010HRS: Chk buzzer operation & order parts.  |
| 01/05/2014 | Dawson, Dale - TWC Mechanic         | 2.00     | Repair power supply to PTO switch in cab. Fit sound alarm to PTO system./ Remove front diff tyres t |
| 01/05/2014 | Bell, Daniel - TWC Manager          | 0.25     | FGR   |
| 02/05/2014 | Bell, Daniel - TWC Manager          | 0.25     | FGR   |
| 03/05/2014 | Bell, Daniel - TWC Manager          | 1.50     | FGR   |
| 05/05/2014 | Bell, Daniel - TWC Manager          | 0.25     | FGR   |
| 07/05/2014 | Dawson, Dale - TWC Mechanic         | 3.00     | Repair power supply to PTO switch in cab. Fit sound alarm to PTO system./ Remove front diff tyres t |
| 09/05/2014 | Bell, Daniel - TWC Manager          | 0.50     | FGR   |
| 12/05/2014 | Bell, Daniel - TWC Manager          | 1.00     | FGR   |
| 19/05/2014 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Chk air lines for leaks.  |
| 22/05/2014 | Knapman, Kenneth - TWC MECHANIC     | 3.50     | Locate air leak. Remove front engine mount cross brace & condenser. Start removal of heater pipes.  |
| 12/06/2014 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Chk over & repair wiring to air compressor.   |
| 11/07/2014 | Dawson, Dale - TWC Mechanic         | 3.50     | 250Hr service, grease, chk brakes & adjust, repair air leaks.                                       |
| 21/07/2014 | Dawson, Dale - TWC Mechanic         | 3.00     | Inspect & repair brake boosters on rear axles (going past 90' on full stroke, complete brake adjust |
| 12/08/2014 | Dawson, Dale - TWC Mechanic         | 1.00     | R&R cab suspension strut right side due to leaking.   |
| 18/08/2014 | Dawson, Dale - TWC Mechanic         | 2.50     | 3280HRS: Repair wiring harness to head light assy. R & R head light bulbs L & R, R & R non working  |
| 02/09/2014 | Dawson, Dale - TWC Mechanic         | 0.50     | Assit ken with repairs./ Locate & repair air leak - leaking at air pressure switch in trailer circu |
| 02/09/2014 | Knapman, Kenneth - TWC MECHANIC     | 2.50     | Cut off & copy L/H side mirror mount bracket. Make repalcement bracket & weld in place, paint.      |

| Date       | Name                                | Duration | Notes   |
|------------|-------------------------------------|----------|---|
| 03/09/2014 | Dawson, Dale - TWC Mechanic         | 1.50     | Assit ken with repairs./ Locate & repair air leak - leaking at air pressure switch in trailer circu |
| 09/09/2014 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Replace R/H reverse globe.  |
| 19/09/2014 | Dawson, Dale - TWC Mechanic         | 0.50     | Chk a/c gas & performance./ R & R headlight bulb.   |
| 24/09/2014 | Dawson, Dale - TWC Mechanic         | 0.50     | Chk a/c gas & performance./ R & R headlight bulb.   |
| 03/10/2014 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | 24,580HRS: R & R L/H front bogey shock absorber.  |
| 07/10/2014 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Prestart & repair cab lights.   |
| 21/10/2014 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | Refit fire ext. & chk lights. Chk & adjust clutch./ 3500Hrs service. Change trailers.               |
| 22/10/2014 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | Refit fire ext. & chk lights. Chk & adjust clutch./ 3500Hrs service. Change trailers.               |
| 23/10/2014 | Bell, Daniel - TWC Manager          | 0.00     | FGR   |
| 04/11/2014 | Dawson, Dale - TWC Mechanic         | 1.00     | Load tyres & jackes to change tyre - already changed. deliver tyre to be repaired/replaced.         |
| 08/11/2014 | Dawson, Dale - TWC Mechanic         | 2.50     | 3647HRS: R & R front r/h blinker housing & harness assy. R & R low beam R/H head light. R & R torsi |
| 11/11/2014 | Dawson, Dale - TWC Mechanic         | 0.50     | 3647HRS: R & R front r/h blinker housing & harness assy. R & R low beam R/H head light. R & R torsi |
| 19/11/2014 | Dawson, Dale - TWC Mechanic         | 2.00     | 3727HRS: 250hr service, R & R alternator, grease, chk & adjust brakes.                              |
| 20/11/2014 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Replace headlight globe & adjust.   |
| 22/11/2014 | Bell, Daniel - TWC Manager          | 1.50     | FGR   |
| 25/11/2014 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 3756HRS: Chk & replace 2 way aerial.  |
| 27/11/2014 | Dawson, Dale - TWC Mechanic         | 0.50     | Retension wheel nuts.   |
| 08/12/2014 | Dawson, Dale - TWC Mechanic         | 6.00     | Complete full inspection of vehicle ready for Rego inspection. R & R front right inner drive axle t |
| 11/12/2014 | Knapman, Kenneth - TWC MECHANIC     | 3.50     | Move into w/shop & prep for rego inspection. Parts collection./ 3862HRS: R & R tractor protection v |
| 12/12/2014 | Knapman, Kenneth - TWC MECHANIC     | 6.50     | Move into w/shop & prep for rego inspection. Parts collection./ 3862HRS: R & R tractor protection v |
| 12/12/2014 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | 3861HRS: R & R steering rod end. Connect to trailer   |
| 20/02/2015 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Fit bonnet retainer.  |
| 24/02/2015 | Dawson, Dale - TWC Mechanic         | 2.00     | 4,023HRS: Commence 2,000hr service. 2000hr service checks.  |
| 25/02/2015 | Dawson, Dale - TWC Mechanic         | 1.00     | 4,023HRS: Commence 2,000hr service. 2000hr service checks.  |
| 04/03/2015 | Dawson, Dale - TWC Mechanic         | 2.00     | Remove air bags.  |
| 05/03/2015 | Knapman, Kenneth - TWC MECHANIC     | 3.00     | Collectparts, fit air bags & refit mudguards.   |
| 14/04/2015 | Dawson, Dale - TWC Mechanic         | 2.00     | R & R top radiator hoses - split. Fill coolant level & test for leaks. Locate faul in a/c - low on  |
| 15/04/2015 | Dawson, Dale - TWC Mechanic         | 0.50     | R & R top radiator hoses - split. Fill coolant level & test for leaks. Locate faul in a/c - low on  |
| 27/04/2015 | Dawson, Dale - TWC Mechanic         | 1.00     | Repair lights. / Fit new mud guard R/H side rear.   |
| 29/04/2015 | Dawson, Dale - TWC Mechanic         | 0.50     | Repair lights. / Fit new mud guard R/H side rear.   |
| 11/05/2015 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Remove a/c condensor for repair. / 4,232HRS: Refit a/c condensor & charge system. Chk for leaks. 25 |
| 12/05/2015 | Wilde, David - TWC WORKSHOP MANAGER | 7.00     | Remove a/c condensor for repair. / 4,232HRS: Refit a/c condensor & charge system. Chk for leaks. 25 |
| 13/05/2015 | Dawson, Dale - TWC Mechanic         | 0.50     | Complete clutch adjustment.   |
| 13/05/2015 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Chk & adjust clutch. Chk & repair lights, test run.   |
| 25/05/2015 | Dawson, Dale - TWC Mechanic         | 1.00     | Remover cooler for repair.  |
| 28/05/2015 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Make battery cover retainers.   |
| 14/07/2015 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Prestart, fuel up. Chk lights. Remove drive tyre for repair. Refit & tension.                       |
| 30/07/2015 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Check & adjust brakes.4327hrs   |
| 18/09/2015 | Dawson, Dale - TWC Mechanic         | 2.00     | Complete 500hrs service. grease truck & trailer.  |
| 09/10/2015 | Dawson, Dale - TWC Mechanic         | 1.00     | Chk over truck/trailer brakes & tyre pressures etc.   |
| 25/11/2015 | Dawson, Dale - TWC Mechanic         | 0.50     | Inspect a/c fault - located leak around fitting.  |
| 26/11/2015 | Dawson, Dale - TWC Mechanic         | 3.50     | Chk over unit, grease, remove a/c gas, R & R leaking a/c hose, fit new dryer etc.                   |
| 27/11/2015 | Dawson, Dale - TWC Mechanic         | 3.50     | Charge & test a/c operation. Chk over machine trailer assy. Commence washdown of unit.              |
| 27/11/2015 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Part wash down.   |
| 30/11/2015 | Dawson, Dale - TWC Mechanic         | 2.50     | Wash machine, complete reports, wash trailer & park up unit.  |
| 03/12/2015 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | 4,551HRS: Chk & replace air valve. Test run.  |
| 19/01/2016 | Dawson, Dale - TWC Mechanic         | 1.00     | R & R front tyres & load old tyres onto ute.  |
| 20/01/2016 | Dawson, Dale - TWC Mechanic         | 0.50     | Take steer tyre for replacement/repair.   |
| 20/01/2016 | Dawson, Dale - TWC Mechanic         | 0.50     | Fit new tyres to steer & tension wheel nuts.  |
| 21/01/2016 | Dawson, Dale - TWC Mechanic         | 0.50     | Deliver tyre for repair.  |
| 10/03/2016 | Dawson, Dale - TWC Mechanic         | 1.00     | R & R leaking brake valve.  |
| 16/03/2016 | Dawson, Dale - TWC Mechanic         | 5.50     | Wash vehicle, chk over, chk & adjust brakes, grease, repair air leak behind dash. chk tyre pressure |

| Date       | Name                                | Duration | Notes   |
|------------|-------------------------------------|----------|---|
| 22/03/2016 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Replace battery box cover.  |
| 23/03/2016 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | Chk & clean battery terminals.  |
| 24/03/2016 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Prestart/FGR  |
| 15/04/2016 | Dawson, Dale - TWC Mechanic         | 0.50     | Unhitch trailer & move unit.  |
| 18/04/2016 | Dawson, Dale - TWC Mechanic         | 3.00     | Chk over, grease, repair non working lights, inspect brakes, remove 2 tyres from R/H rear for repai |
| 29/04/2016 | Dawson, Dale - TWC Mechanic         | 1.50     | 250hr service & refuel.   |
| 29/04/2016 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | 4,750HR service. Refuel, chk trailer lights.  |
| 11/05/2016 | Dawson, Dale - TWC Mechanic         | 1.00     | R & R blown light bulbs.  |
| 13/05/2016 | Dawson, Dale - TWC Mechanic         | 0.50     | Fit new suspension bracket, adjust ride height.   |
| 16/05/2016 | Dawson, Dale - TWC Mechanic         | 0.50     | Prestart/FGR  |
| 16/05/2016 | Dawson, Dale - TWC Mechanic         | 1.50     | Rotate tyre & swap tyre with #289   |
| 01/08/2016 | Knapman, Kenneth - TWC MECHANIC     | 4.00     | Manufacturekeeps for front springs & fit to spring packs.   |
| 01/08/2016 | Dawson, Dale - TWC Mechanic         | 1.00     | Investiagte/repair PTO buzzer, R & R u/s grease nipples.  |
| 06/09/2016 | Wilde, David - TWC WORKSHOP MANAGER | 5.00     | Prestart & connect to #292. Test tipper. Chk & adjsut tyre pressures. replace handle.               |
| 04/10/2016 | Dawson, Dale - TWC Mechanic         | 1.00     | Part complete 1,000hr service.  |
| 04/10/2016 | Wilde, David - TWC WORKSHOP MANAGER | 3.50     | 5,000HRS: Part service. Chk & adjust tyre pressures, chk front wheel bearings.                      |
| 06/10/2016 | Dawson, Dale - TWC Mechanic         | 1.50     | Investigate Navman problem & repair. Investigate/repair trailer lights.                             |
| 12/10/2016 | Dawson, Dale - TWC Mechanic         | 1.50     | Repair air leak at rear of cab, repair light & chk over unit.                                       |
| 13/10/2016 | Dawson, Dale - TWC Mechanic         | 0.50     | Deliver unit for tyre replacement.  |
| 31/10/2016 | Knapman, Kenneth - TWC MECHANIC     | 3.00     | Replace eng. oil & filters, replace fuel filters, chk lights, adjusty brakes.                       |
| 01/11/2016 | Knapman, Kenneth - TWC MECHANIC     | 8.50     | Fill eng oil to complete 250hr service. Place unit on blocks, remove PTO drive shaft & centre beari |
| 02/11/2016 | Knapman, Kenneth - TWC MECHANIC     | 5.00     | Install tractor protection valve & R/H rwar cab shock absorber. order end yoke & install driveline  |
| 03/11/2016 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | Collect parts, source slinger for yoke & commence reinstall of dash console, purchase & fit speed n |
| 10/11/2016 | Knapman, Kenneth - TWC MECHANIC     | 2.00     | Fit dust slinger to yoke 7 fit yoke to unit. Connect & grease uni. Remove unit from shed.           |
| 28/11/2016 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | Chk U bolt tension.   |
| 29/11/2016 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | Chk front U bolt tension.   |
| 07/12/2016 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | Chk front axle U bolts.   |
| 08/12/2016 | Knapman, Kenneth - TWC MECHANIC     | 1.50     | Assist David with fan repairs.  |
| 08/12/2016 | Wilde, David - TWC WORKSHOP MANAGER | 3.25     | Chk fan hub - R & R hub.  |
| 09/12/2016 | Wilde, David - TWC WORKSHOP MANAGER | 2.50     | Refit fan hub & adjust belts. Test run - prestart.  |
| 11/12/2016 | Dawson, Dale - TWC Mechanic         | 0.50     | Investigate fault in A/c - arrange parts for repair.  |
| 12/01/2017 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 5,145HRS: Grease & chk over. Adjust tyre pressures.   |
| 04/02/2017 | Wilde, David - TWC WORKSHOP MANAGER | 2.50     | Chk speed sensor wiring & replace sensor. Replace fuel filters - test run.                          |
| 07/02/2017 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Chk eng. performance & clean out air filter. Order parts.   |
| 08/02/2017 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Remove turbo & inspect. Look up & order parts.  |
| 09/02/2017 | Dawson, Dale - TWC Mechanic         | 3.00     | 5,172HRS: Install new turbo to eng. & fit new oil supply tube & clamps.                             |
| 21/02/2017 | Dawson, Dale - TWC Mechanic         | 1.00     | Fit new alternator pulley & V belts to engine.  |
| 14/03/2017 | Dawson, Dale - TWC Mechanic         | 2.00     | 250Hr service.  |
| 15/03/2017 | Dawson, Dale - TWC Mechanic         | 3.00     | Finalise 250Hr service; full grease, brakes & clutch.   |
| 20/06/2017 | Wilde, David - TWC WORKSHOP MANAGER | 3.25     | Change drive tyres (8), chk tyre pressures & tension wheel nuts. Chk all lights & replace R/H hih b |
| 31/07/2017 | Dawson, Dale - TWC Mechanic         | 1.00     | Remove dash & fit navman from #270 - test & refit dash.   |
| 11/08/2017 | Dawson, Dale - TWC Mechanic         | 5.00     | Grease truck & side tipper. Adjust brakes. R & R flat drive tyre. Remove tarp from side tipper. Fu  |
| 11/08/2017 | Knapman, Kenneth - TWC MECHANIC     | 2.50     | Chk & adjust brakes. Puncture repair & chk tyre pressures.  |
| 17/10/2017 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Replace bug visor.  |
| 08/11/2017 | Knapman, Kenneth - TWC MECHANIC     | 3.00     | Remount aircon consensor in grill.  |
| 08/11/2017 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | Repairs to grille & condensor mounts.   |
| 21/11/2017 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Prestart & connect to #274.   |
| 22/02/2018 | Dawson, Dale - TWC Mechanic         | 9.50     | Wash down unit & clean engine bay ready for removal of engine. Remove all necessary guards & commen |
| 24/02/2018 | Dawson, Dale - TWC Mechanic         | 2.00     | make up brackets & continue removal of engine.  |
| 26/02/2018 | Dawson, Dale - TWC Mechanic         | 9.50     | Remove engine from unit & strip down for rebuild. Clean, inspect engine parts                       |
| 27/02/2018 | Dawson, Dale - TWC Mechanic         | 4.50     | Remove engine from unit & strip down for rebuild. Clean, inspect engine parts                       |
| 28/02/2018 | Dawson, Dale - TWC Mechanic         | 1.50     | Strip , clean & inspect engine components.  |

| Date       | Name                                | Duration | Notes   |
|------------|-------------------------------------|----------|---|
| 01/03/2018 | Dawson, Dale - TWC Mechanic         | 3.50     | Finish cleaning, inspecting & sorting parts for engine.   |
| 27/03/2018 | Dawson, Dale - TWC Mechanic         | 1.50     | Clean up eng. block & inspect.  |
| 28/03/2018 | Dawson, Dale - TWC Mechanic         | 8.00     | Commence assembly of engine - test & chk crank main bearing clearances, piston big end clearances - |
| 29/03/2018 | Dawson, Dale - TWC Mechanic         | 2.00     | Continue with reassembly of engine.   |
| 09/04/2018 | Dawson, Dale - TWC Mechanic         | 6.50     | Continue with engine rebuild.   |
| 10/04/2018 | Dawson, Dale - TWC Mechanic         | 9.50     | Continue with engine rebuild.   |
| 11/04/2018 | Dawson, Dale - TWC Mechanic         | 8.50     | Continue with engine rebuild.   |
| 12/04/2018 | Dawson, Dale - TWC Mechanic         | 6.50     | Continue with assembly of engine/components. Paint engine & components.                             |
| 16/04/2018 | Dawson, Dale - TWC Mechanic         | 4.50     | Fit new rocker assy to engine & complete valve set. Set jake brakes etc & fit valve covers.         |
| 21/06/2018 | Dawson, Dale - TWC Mechanic         | 1.00     | Wash down motor ready for strip down.   |
| 25/06/2018 | Dawson, Dale - TWC Mechanic         | 3.00     | Commence strip down of engine.  |
| 28/06/2018 | Dawson, Dale - TWC Mechanic         | 1.50     | Disassembly of engine for rebuild.  |
| 09/08/2018 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Charge batteries, replace power steering bracket, clean out bell housing.                           |
| 18/09/2018 | Dawson, Dale - TWC Mechanic         | 1.00     | Organise parts for commencement of engine rebuild.  |
| 19/09/2018 | Dawson, Dale - TWC Mechanic         | 1.50     | Clean engine block ready for assembly.  |
| 20/09/2018 | Dawson, Dale - TWC Mechanic         | 7.50     | Continue with reassembly of engine & components.  |
| 21/09/2018 | Dawson, Dale - TWC Mechanic         | 1.00     | Continue with assembly of engine.   |
| 24/09/2018 | Dawson, Dale - TWC Mechanic         | 5.50     | Continue with engine assembly.  |
| 25/09/2018 | Dawson, Dale - TWC Mechanic         | 10.50    | Continue with assembly of engine to Cat. specs.   |
| 26/09/2018 | Dawson, Dale - TWC Mechanic         | 1.00     | Continue with engine rebuild.   |
| 27/09/2018 | Dawson, Dale - TWC Mechanic         | 2.00     | Continue engine assembly.   |
| 28/09/2018 | Dawson, Dale - TWC Mechanic         | 3.00     | Continue engine assembly.   |
| 29/09/2018 | Dawson, Dale - TWC Mechanic         | 6.50     | Continue assembly of engine/components, paint engine as required & move prime mover into shed ready |
| 02/10/2018 | Dawson, Dale - TWC Mechanic         | 10.50    | prep engine & truck for & install engine into engine bay.   |
| 02/10/2018 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Purchase belts & filters.   |
| 03/10/2018 | Dawson, Dale - TWC Mechanic         | 9.50     | Finish fitting engine into engine bay & plumb up wiring etc. repair minor leaks & investigate start |
| 04/10/2018 | Dawson, Dale - TWC Mechanic         | 8.50     | Finalise engine installation, start engine, R & R starter motor (faulty), refit guards, adjsut brak |
| 05/10/2018 | Dawson, Dale - TWC Mechanic         | 5.50     | Grease unit, refit bonnet & guards, investigate & repair failed Horton Fan. Vac down & recharge a/c |
| 10/10/2018 | Knapman, Kenneth - TWC MECHANIC     | 7.50     | Chk lights for rego. Investigate knocking noise in driveline - drive shaft hitting on chassis. Make |
| 10/10/2018 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Assist with engine mount repair.  |
| 11/10/2018 | Knapman, Kenneth - TWC MECHANIC     | 3.00     | Finish reassembly of front mount systems. Purchase hose & clamps.                                   |
| 15/10/2018 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | Repairs to seat   |
| 17/10/2018 | Dawson, Dale - TWC Mechanic         | 1.00     | Repairs - move PTO bracket assy.  |
| 17/10/2018 | Wilde, David - TWC WORKSHOP MANAGER | 3.50     | Wash down & repair lights.  |
| 18/10/2018 | Dawson, Dale - TWC Mechanic         | 8.00     | Adjust V belts, repair indicator, chk & test a/c, repair dash lights & assist with polishing unit.  |
| 18/10/2018 | Wilde, David - TWC WORKSHOP MANAGER | 6.50     | Assist with Cut & polish unit   |
| 19/10/2018 | Dawson, Dale - TWC Mechanic         | 4.50     | Polish & detail unit.   |
| 25/10/2018 | Dawson, Dale - TWC Mechanic         | 1.50     | Install LED headlights.   |
| 05/11/2018 | Knapman, Kenneth - TWC MECHANIC     | 2.00     | Remove wheels for rotation.   |
| 07/11/2018 | Knapman, Kenneth - TWC MECHANIC     | 3.00     | Remove front engine mounts for replacement with mounts from #289                                    |
| 08/11/2018 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | Organise drivers side steering wheel placement & wheel alignment. Collect vehicle from wheel alignm |
| 16/11/2018 | Dawson, Dale - TWC Mechanic         | 1.50     | Prestart & connect side tipper #292 to truck.   |
| 07/01/2019 | Dawson, Dale - TWC Mechanic         | 0.50     | Repair headlight  |
| 17/01/2019 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Prestart  |
| 18/01/2019 | Dawson, Dale - TWC Mechanic         | 1.00     | R & R flat drive tyre.  |
| 22/01/2019 | Dawson, Dale - TWC Mechanic         | 1.50     | 500hr service, repair oil leak on speed sensor.   |
| 22/01/2019 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 500hr service.  |
| 29/01/2019 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | Investigate electrical fault - found starter motor seized - replaced.                               |
| 01/02/2019 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 5,493HRS: Prestart & tighten guards.  |
| 20/02/2019 | Dawson, Dale - TWC Mechanic         | 1.00     | 5,501HRS: Annual inspection for NVHAS records.  |
| 07/03/2019 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 5,502HRS: Prestart & connect up to float.   |
| 05/05/2019 | Dawson, Dale - TWC Mechanic         | 1.00     | Chk over tyres, fluids etc.   |

| Date       | Name                                | Duration | Notes   |
|------------|-------------------------------------|----------|---|
| 03/06/2019 | Dawson, Dale - TWC Mechanic         | 1.00     | Prestart.   |
| 04/06/2019 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Remove O'size signage & change over trailer.  |
| 18/06/2019 | Dawson, Dale - TWC Mechanic         | 0.50     | Grease.   |
| 20/06/2019 | Dawson, Dale - TWC Mechanic         | 2.00     | #275, #284 & #292: grease units.  |
| 27/06/2019 | Wilde, David - TWC WORKSHOP MANAGER | 0.75     | 5,654HRS: prestart/grease.  |
| 04/07/2019 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 5,679HRS: Prestart, replace dipstick.   |
| 12/07/2019 | Dawson, Dale - TWC Mechanic         | 2.00     | Prestart - chk & adjust brakes on road train assy.  |
| 17/07/2019 | Dawson, Dale - TWC Mechanic         | 1.00     | 5,714HRS: R & R Vee belts fan drive.  |
| 22/07/2019 | Dawson, Dale - TWC Mechanic         | 1.50     | ROADTRAIN: Grease drive train brakes, chk tyres.  |
| 04/08/2019 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 5,729HRS:Chk & adjust fan belts.  |
| 07/08/2019 | Wilde, David - TWC WORKSHOP MANAGER | 0.75     | Remove fencing wire from wheels. Blow out air filter.   |
| 14/08/2019 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | Replace mudflap & reflector.  |
| 02/09/2019 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | 5,766HRS: prestart & chk over.  |
| 02/09/2019 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | Prestart/FGR  |
| 05/09/2019 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Investigate "Chk engine light" fault.   |
| 09/10/2019 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Replace ignition switch.  |
| 13/10/2019 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Replace door locks.   |
| 17/10/2019 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Fit Oversize signage.   |
| 20/10/2019 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Replace speed sensor & test run.  |
| 21/10/2019 | Dawson, Dale - TWC Mechanic         | 1.50     | 5,881HRS: Investigate flashing enginewarning light - found fault for engine timing calibration, res |
| 23/10/2019 | Wilde, David - TWC WORKSHOP MANAGER | 1.50     | 5,904HRS: Replace door lock & get windscreen replaced. Connect up to #274                           |
| 29/10/2019 | Dawson, Dale - TWC Mechanic         | 7.50     | Investigate speedo faulr - reset, replace speed sensors, complete engine speed sensor calibration u |
| 31/10/2019 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 5,944HRS: Remove & replace turntable.   |
| 03/12/2019 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | 5,947HRS: Check engine fault codes.   |
| 04/12/2019 | Dawson, Dale - TWC Mechanic         | 3.00     | Investigate engine fault with ECM - found ECM losing program - flashed ECM but ECM possibly faulty. |
| 11/02/2020 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 5997hrs. 12 Month Inspection . PartsService. Tighten Clamps On HYD Hoses                            |
| 12/02/2020 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | Adjust Brakes   |
| 13/02/2020 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | 6,000HRS: Wash down & connect to trailer.   |
| 14/02/2020 | Wilde, David - TWC WORKSHOP MANAGER | 3.00     | Clean out tail light glasses. Repair wiring to head lights & driving lights.                        |
| 28/02/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 6,003HRS: prestart & connect to trailer.  |
| 21/04/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 6,012HRS: prestart.   |
| 12/05/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | 6,020HRS: Prestart.   |
| 25/05/2020 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Disconnect from trailer & get tyres regrooved.  |
| 26/05/2020 | Knapman, Kenneth - TWC MECHANIC     | 0.50     | Make R/H rear clearance light mounting bracket.   |
| 02/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | Prestart.   |
| 05/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | 6,059HRS: Prestart/FGR / 6,065HRS: / 6,073HRS   |
| 09/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | 6,059HRS: Prestart/FGR / 6,065HRS: / 6,073HRS   |
| 10/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | 6,059HRS: Prestart/FGR / 6,065HRS: / 6,073HRS   |
| 11/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | Prestart/FGR  |
| 12/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | Prestart/FGR  |
| 15/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | Prestart/FGR  |
| 16/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.25     | Prestart/FGR  |
| 17/06/2020 | Knapman, Kenneth - TWC MECHANIC     | 3.00     | Remove wheel to inspect brake linings.  |
| 17/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | prestart/FGR  |
| 18/06/2020 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | Remove, straighten & replace clearance light bracket.   |
| 23/06/2020 | Wilde, David - TWC WORKSHOP MANAGER | 2.00     | Connect to #292, connect #297 & connect #284 (roadtrain arrangement)                                |
| 01/07/2020 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | 51,555HRS: Fit lights & repair wiring.  |
| 08/07/2020 | Wilde, David - TWC WORKSHOP MANAGER | 0.50     | 6,237HRS: Grease & chk over.  |
| 10/07/2020 | Wilde, David - TWC WORKSHOP MANAGER | 1.00     | Chk & tighten alternator wiring. Disconnect from trailers.  |
| 13/07/2020 | Wilde, David - TWC WORKSHOP MANAGER | 2.50     | 6,250HRS: Service.  |
| 14/07/2020 | Knapman, Kenneth - TWC MECHANIC     | 1.00     | Fit ride height valves.   |
| 14/07/2020 | Wilde, David - TWC WORKSHOP MANAGER | 3.50     | Chk & repair light wiring. Replace brake switch & bolt in step. Replace & set ride height valves.   |

| <u>Date</u>                     | <u>Name</u>                         | <u>Duration</u>        | <u>Notes</u>  |
|---------------------------------|-------------------------------------|------------------------|---|
| 15/07/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 2.00                   | 6,250HRS: Replace isolator & connect side tipper trailers for road train.                   |
| 04/08/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 2.00                   | 6,280HRS: Chk radiator mounts & tighten. Repair wiring to Navman, tighten radiator hoses.   |
| 30/09/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 0.50                   | 6,343HRS: Repair door catch & chk fault codes.  |
| 08/10/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 1.00                   | 6,344HRS: Chk over & grease.  |
| 12/10/2020                      | Knapman, Kenneth - TWC MECHANIC     | 4.00                   | Investigate/locate air leak - R & R Horton Fan air line. Connect unit to #274.              |
| 12/10/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 3.00                   | 6,344HRS: Chk for air leaks & replace suzzy hoses.  |
| 16/10/2020                      | Knapman, Kenneth - TWC MECHANIC     | 1.50                   | Repair brace on Driver side cab wing.   |
| 28/10/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 3.50                   | Polish cab  |
| 29/10/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 7.50                   | 6,354HRS: Polish/detail unit.   |
| 30/10/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 7.00                   | 6,354HRS: Polish/detail unit.   |
| 09/11/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 0.50                   | Prestart/FGR  |
| 10/11/2020                      | Wilde, David - TWC WORKSHOP MANAGER | 0.50                   | 6,461HRS: Prestart & chk over.  |
| 18/11/2020                      | Knapman, Kenneth - TWC MECHANIC     | 3.00                   | Remove taillight assemblies for replacement to LED sets                                     |
| 19/11/2020                      | Knapman, Kenneth - TWC MECHANIC     | 4.50                   | Make clearance light mount & fit. Fit light assay & connect clearance light & backup alarm. |
| 24/11/2020                      | Knapman, Kenneth - TWC MECHANIC     | 0.50                   | Move out of storage shed & chk over. Remove light guard to ascertain size of fog light.     |
| 03/02/2021                      | Knapman, Kenneth - TWC MECHANIC     | 0.50                   | Deliver to GWS for inspection & see repairer regarding alloy welding of bumper.             |
| 06/02/2021                      | Knapman, Kenneth - TWC MECHANIC     | 0.50                   | Remove bumper bar & deliver to repairer - aluminium welding.                                |
| 06/02/2021                      | Wilde, David - TWC WORKSHOP MANAGER | 0.50                   | Remove bumper bar for repairs.  |
| 10/02/2021                      | Knapman, Kenneth - TWC MECHANIC     | 1.00                   | Collect repaired bumper bar & refit to vehicle.   |
| 10/02/2021                      | Wilde, David - TWC WORKSHOP MANAGER | 2.00                   | Assist refit repaired bumper & repair wiring to lights.                                     |
| 22/02/2021                      | Wilde, David - TWC WORKSHOP MANAGER | 2.00                   | 6,518HRS: Prestart. Replace 3 air tank bleed valves. Adjust brakes.                         |
| 05/05/2021                      | Wilde, David - TWC WORKSHOP MANAGER | 3.00                   | 6,500Hrs. Service   |
| 06/05/2021                      | Wilde, David - TWC WORKSHOP MANAGER | 1.00                   | 6500Hrs. Check for air leaks and replace 2 valves and recheck                               |
| 18/05/2021                      | Knapman, Kenneth - TWC MECHANIC     | 1.00                   | Source info regards road train rating of unit.  |
| 19/07/2021                      | Knapman, Kenneth - TWC MECHANIC     | 0.50                   | Remove Navman   |
| Total 275 - Kenworth Truck:275E |                                     | 1,075.01               |   |
| <b>TOTAL</b>                    |                                     | <b><u>1,075.01</u></b> |   |