

Date	Name	Duration	Notes
18/09/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	Check & remove/replace blown hose.
21/09/2010	Wilde, David - TWC WORKSHOP MANAGER	0.50	Check & remove/replace blown hose.
22/09/2010	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit spacers to bucket hub.
23/09/2010	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace leaking hoses
03/12/2010	Wilde, David - TWC WORKSHOP MANAGER	4.00	Travel to Tamworth & effect repairs to bonnet catch & replace water pump belt.
09/12/2010	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to A/C over phone & have condensor tested.
05/01/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R seat
10/01/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Have oil cooler repaired./ Remove l/h front wheel & hub, dismantle & clean parts, reassemble./ Refi
11/01/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Have oil cooler repaired./ Remove l/h front wheel & hub, dismantle & clean parts, reassemble./ Refi
12/01/2011	Wilde, David - TWC WORKSHOP MANAGER	6.00	Have oil cooler repaired./ Remove l/h front wheel & hub, dismantle & clean parts, reassemble./ Refi
13/01/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	Wash down, clean out radiator.Refit draw bar, hoses 7 clamps/ Repalce A/C motors, check & repair wi
14/01/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	Wash down, clean out radiator.Refit draw bar, hoses 7 clamps/ Repalce A/C motors, check & repair wi
15/01/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Wash down, clean out radiator.Refit draw bar, hoses 7 clamps/ Repalce A/C motors, check & repair wi
18/01/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	Wash down, clean out radiator.Refit draw bar, hoses 7 clamps/ Repalce A/C motors, check & repair wi
19/01/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Wash down, clean out radiator.Refit draw bar, hoses 7 clamps/ Repalce A/C motors, check & repair wi
08/02/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace seat, chk electrical faults & order parts.
15/02/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace tip cylinder in bucket./ Refit tip cylinder, clean out A/C system, replace hyd. control coi
16/02/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Replace tip cylinder in bucket./ Refit tip cylinder, clean out A/C system, replace hyd. control coi
18/02/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	R & R muffler, repair oil leaks, replace & adjust bonnet cable, adjust latch.
23/02/2011	Bell, Daniel - TWC Manager	1.75	FGR, replace broken seat
24/02/2011	Bell, Daniel - TWC Manager	0.50	FGR
25/02/2011	Bell, Daniel - TWC Manager	0.50	FGR
26/02/2011	Bell, Daniel - TWC Manager	0.50	FGR
28/02/2011	Bell, Daniel - TWC Manager	0.50	FGR
02/03/2011	Bell, Daniel - TWC Manager	0.50	FGR
08/03/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	5498 hrs; chk hitch operation, replace top sensor, test run & adjust sensors./Replace lift cylinder
09/03/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	5498 hrs; chk hitch operation, replace top sensor, test run & adjust sensors./Replace lift cylinder
10/03/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk eng. oil leak, look up & order parts.
16/03/2011	Bell, Daniel - TWC Manager	2.00	Replace bucket tyres & LHS lift cylinder
10/05/2011	Bell, Daniel - TWC Manager	2.00	FGR
11/07/2011	Knapman, Kenneth - TWC MECHANIC	0.50	take bucket tyres for repair
02/08/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Travel to Beela, start tractor & operate systems, return to w'shop.
10/08/2011	Knapman, Kenneth - TWC MECHANIC	3.00	Travel to Beela, chk steering problem, retun to w'shop. Remove steering column from 214 to replace
11/08/2011	Knapman, Kenneth - TWC MECHANIC	2.50	Travel to Beela, R & R steering column, return to w'shop
26/08/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Check/prestart machine, Establish to Livingston Farm
06/09/2011	Knapman, Kenneth - TWC MECHANIC	7.50	Remove centre pivot bar & replace bearings & repalce centre pivot bar.

06/09/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	R & R bushes & reassemble articulation.
06/09/2011	Bell, Daniel - TWC Manager	2.00	Remove draw bar assembly.
11/10/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R windscreen & return to w'shop.
11/10/2011	Bell, Daniel - TWC Manager	4.00	Rebuild final drive
13/10/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Pick up new bucket tyres.
14/10/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Travel to jobsite, replace fuel filter, drain sediment from fuel tank, return to w'shop.
22/10/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Travel to jobsite. 5740 hrs: R & R joy stick switches, return to w'shop./Travel to jobsite, carry o
24/10/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Travel to jobsite. 5740 hrs: R & R joy stick switches, return to w'shop./Travel to jobsite, carry o
27/10/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	Travel to jobsite, refit radiator, fill with coolant & test run.
16/11/2011	Bell, Daniel - TWC Manager	2.00	Travel to & from site from Dalby. Replace step bonnet hinge & spring. 4066hrs
07/01/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	Travel to jobsite, R & R seat damper & return to w'shop.
02/04/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Travel to jobsite (Glen Prairie) to extract bogged machine.
04/04/2012	Wilde, David - TWC WORKSHOP MANAGER	7.00	Travel to from jobsite (Glen Prairie), 6,000hrs service, replace apron stub, unload waste oil & fil
10/04/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Travel to/from jobsite (Glen Prairie), repalce bucket skirts & bolts.
11/04/2012	Griffin, Reece - Plant Mechanic	1.00	Travel to/from jobsite, adjust cap on lift ram.
17/04/2012	Knapman, Kenneth - TWC MECHANIC	3.00	Travel to/from jobsite (Glen Prairie) fit shims to cushion hitch guide plates.
19/04/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Travel to jobsite (Beela), effect weld repair to articulation & replace inner air filter, return to
21/04/2012	Griffin, Reece - Plant Mechanic	2.00	Travel to/from jobsite Beela) & check hubs.
21/04/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Travel to jobsite (beela), 6081hrs: Chk all hub oil levels, chk oil leaks on bucket, oreder parts,
24/04/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Disassemble 2 wheel hubs.
26/04/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Rebuild bucket wheel hubs.
02/05/2012	Griffin, Reece - Plant Mechanic	3.00	Repairs to laser bucket hubs.
02/05/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Travel tofrom jobsite (Beela), R & R 3 bucket hubs.
04/05/2012	Griffin, Reece - Plant Mechanic	4.50	Rebuild laser bucket hubs.
04/05/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Order bearings & seals.
09/05/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Travel to/from jobsite (Beela) chk vibration & noise in machine.
12/05/2012	Bell, Daniel - TWC Manager	0.50	FGR
13/05/2012	Bell, Daniel - TWC Manager	0.50	FGR
13/05/2012	Bell, Daniel - TWC Manager	2.75	Replace pilot hydraulic hose.
15/05/2012	Bell, Daniel - TWC Manager	1.00	Troubleshoot transmission failure.
15/05/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Remove walkinfg frame from spare bucket for a replacement.
15/05/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove cross leveller bar.
16/05/2012	Griffin, Reece - Plant Mechanic	5.00	rebuild seat, install & fix wiring.
16/05/2012	Wilde, David - TWC WORKSHOP MANAGER	0.75	De establish from jobsite.
18/05/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	15,000 klm service.
04/06/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Dismantle transmission.
04/06/2012	Griffin, Reece - Plant Mechanic	9.00	Dismantle transmission.

05/06/2012	Knapman, Kenneth - TWC MECHANIC	8.50	Dismantle transmission.
06/06/2012	Knapman, Kenneth - TWC MECHANIC	3.50	Dismantle transmission.
08/06/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Order transmission parts./ Replace walking beam bearing, gouge off pivot box end bearings for repla
12/06/2012	Knapman, Kenneth - TWC MECHANIC	3.50	Order transmission parts./ Replace walking beam bearing, gouge off pivot box end bearings for repla
14/06/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Collect transmission parts./Chk parts rec'd & begin clutch pack reassembly./ Reassemble clutch pack
19/06/2012	Bell, Daniel - TWC Manager	2.50	Sort & pick up transmission parts.
19/06/2012	Knapman, Kenneth - TWC MECHANIC	7.50	Collect transmission parts./Chk parts rec'd & begin clutch pack reassembly./ Reassemble clutch pack
20/06/2012	Knapman, Kenneth - TWC MECHANIC	8.00	Collect transmission parts./Chk parts rec'd & begin clutch pack reassembly./ Reassemble clutch pack
20/06/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean out bucket walking beam box.
21/06/2012	Knapman, Kenneth - TWC MECHANIC	4.50	Reassemble clutch packs & clean up.
23/07/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Assemble 7" 2nd shaft, fit splash guard & assemble, halves, clean & assemble end shafts, begin seat
24/07/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Assemble 7" 2nd shaft, fit splash guard & assemble, halves, clean & assemble end shafts, begin seat
28/08/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove transmission for repair, charge batteries.
29/08/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove trans & hoses for repair.
30/08/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Gouge cracks in chassis & weld up.
30/08/2012	Wilde, David - TWC WORKSHOP MANAGER	4.50	Remove trans., replace hyd. hoses, remove & clean up & reseal valve bank, refit trans./ Complete re
31/08/2012	Wilde, David - TWC WORKSHOP MANAGER	6.50	Remove trans., replace hyd. hoses, remove & clean up & reseal valve bank, refit trans./ Complete re
03/09/2012	Wilde, David - TWC WORKSHOP MANAGER	6.50	Remove trans., replace hyd. hoses, remove & clean up & reseal valve bank, refit trans./ Complete re
04/09/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Remove trans., replace hyd. hoses, remove & clean up & reseal valve bank, refit trans./ Complete re
17/09/2012	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove, reseal & refit bucket hubs.
18/09/2012	Knapman, Kenneth - TWC MECHANIC	4.50	Repair & replace bucket hubs.
02/10/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Fix/Clear transmission error code.
30/10/2012	Griffin, Reece - Plant Mechanic	0.50	Fit lift cylinder to bucket.
20/11/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Fit 2 front tyres.
20/11/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit 2 tyres to machine, chk 2 rims for cracks.
03/01/2013	Dawson, Dale - TWC Mechanic	1.00	Follow up on new universals for drive shaft./ Fit new batteries, locate repalcement driveshaft in w
03/01/2013	Knapman, Kenneth - TWC MECHANIC	1.00	Replace seat./ Fit driveline to PTO shaft, commence filling tyres with water./ Source laser equipme
04/01/2013	Dawson, Dale - TWC Mechanic	4.00	Follow up on new universals for drive shaft./ Fit new batteries, locate repalcement driveshaft in w
04/01/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Replace seat./ Fit driveline to PTO shaft, commence filling tyres with water./ Source laser equipme
07/01/2013	Knapman, Kenneth - TWC MECHANIC	1.00	Replace seat./ Fit driveline to PTO shaft, commence filling tyres with water./ Source laser equipme
16/01/2013	Dawson, Dale - TWC Mechanic	1.00	Inspect machine, test a/c & clean filters
18/01/2013	Dawson, Dale - TWC Mechanic	0.50	Set up for establishment to jobsite.
26/01/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Fit tyre to bucket.
16/04/2013	Wilde, David - TWC WORKSHOP MANAGER	6.00	6,211Hrs: Travel to/from jobsite x 2, chk & repair laser wiring, fuel up, fit signs.
26/04/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Replace wheel studs for bucket hub.
29/04/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Replace wheel studs for bucket hub.
30/04/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Replace wheel studs for bucket hub.

13/05/2013	Dawson, Dale - TWC Mechanic	1.50	Repairs to a/c system - install new thermo switch & pressure switches.
31/05/2013	Knapman, Kenneth - TWC MECHANIC	0.50	6359HRS": Chk over & run machine./ Load equipment & parts, replace apron pivot beam, unload trailer
01/06/2013	Knapman, Kenneth - TWC MECHANIC	3.50	6359HRS": Chk over & run machine./ Load equipment & parts, replace apron pivot beam, unload trailer
01/06/2013	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove & Replace apron bar.
03/07/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Assist with tilt ram reconditioning.
03/07/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to cross leveller ram.
12/07/2013	Knapman, Kenneth - TWC MECHANIC	3.00	Drill out broken drawbar pin retaining bolt & replace, purchase hose for replacement (header tank
23/07/2013	Wilde, David - TWC WORKSHOP MANAGER	1.50	5045HRS: Fit battery isolator & wiring, replace clamps on bowl piping.
24/07/2013	Griffin, Reece - Plant Mechanic	2.00	Fit hoses onto laser bucket.
01/08/2013	Griffin, Reece - Plant Mechanic	1.50	Obtain seals & reseal ripper ram from laser bucket
14/08/2013	Wilde, David - TWC WORKSHOP MANAGER	3.00	16,460HRS: Chk over & top up oil levels & coolant, grease machine, shift to Haddads yard & set up l
18/09/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk oil & coolant levels, start & run.
01/11/2013	Dawson, Dale - TWC Mechanic	0.50	Chk a/c performance.
07/11/2013	Knapman, Kenneth - TWC MECHANIC	1.00	6478HRS: Fit bonnet latch & catch.
12/11/2013	Griffin, Reece - Plant Mechanic	1.50	6527Hrs: Complete 500hr service & grease bucket.
21/11/2013	Knapman, Kenneth - TWC MECHANIC	0.50	6582HRS: Replace apron bearing bolts.
25/11/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	6608HRS: Chk over machine.
30/11/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	6642HRS: Chk bucket over.
06/12/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R apron roller./ Chk cracks in tyres & chk pressures./ R & R laser leads. Have faulty leads rep
09/12/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R apron roller./ Chk cracks in tyres & chk pressures./ R & R laser leads. Have faulty leads rep
10/12/2013	Wilde, David - TWC WORKSHOP MANAGER	1.50	R & R apron roller./ Chk cracks in tyres & chk pressures./ R & R laser leads. Have faulty leads rep
11/12/2013	Wilde, David - TWC WORKSHOP MANAGER	4.00	R & R apron roller./ Chk cracks in tyres & chk pressures./ R & R laser leads. Have faulty leads rep
16/12/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Part service.
11/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & clean out evap. & condensor, replace alternator belts.
17/01/2014	Dawson, Dale - TWC Mechanic	2.00	R & R bonnet.
17/01/2014	Griffin, Reece - Plant Mechanic	3.00	R & R bonnet of tractor.
18/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R a/c motor & clean out evaporator./ Repair a/c wiring & chk apron pivot.
19/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	R & R a/c motor & clean out evaporator./ Repair a/c wiring & chk apron pivot.
20/01/2014	Knapman, Kenneth - TWC MECHANIC	1.00	BUCKET: Source steel & parts./ Commence manufacture of apron bar./ Finish apron beam, collect parts
21/01/2014	Knapman, Kenneth - TWC MECHANIC	1.50	BUCKET: Source steel & parts./ Commence manufacture of apron bar./ Finish apron beam, collect parts
22/01/2014	Knapman, Kenneth - TWC MECHANIC	2.50	BUCKET: Source steel & parts./ Commence manufacture of apron bar./ Finish apron beam, collect parts
22/01/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Repairs to bonnet
30/01/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Load parts & oils. Change front & rear diff oil./ Have new apron circuit hose made & install
31/01/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	Load parts & oils. Change front & rear diff oil./ Have new apron circuit hose made & install
03/02/2014	Dawson, Dale - TWC Mechanic	1.00	6988HRS: 250hr service./ 6994HRS: Fit tyre to laser bucket, reseal fitting on apron cylinder.
04/02/2014	Dawson, Dale - TWC Mechanic	1.00	6988HRS: 250hr service./ 6994HRS: Fit tyre to laser bucket, reseal fitting on apron cylinder.
06/02/2014	Dawson, Dale - TWC Mechanic	0.50	7017HRS: R & R l/h apron cylinder./ R & R trans oil & filter, drill out retainer bolt for apron pin

06/02/2014	Griffin, Reece - Plant Mechanic	0.50	Replace apron cylinder./ R & R trans oil & filter.
07/02/2014	Dawson, Dale - TWC Mechanic	1.00	7017HRS: R & R l/h apron cylinder./ R & R trans oil & filter, drill out retainer bolt for apron pin
07/02/2014	Griffin, Reece - Plant Mechanic	1.00	Replace apron cylinder./ R & R trans oil & filter.
15/02/2014	Dawson, Dale - TWC Mechanic	1.00	Pre hire check of machine..
24/02/2014	Dawson, Dale - TWC Mechanic	3.50	Carry out repairs on bucket, R & R l/h lift cylinder & reseal, fit rippers, R & R r/h side apron ro
24/02/2014	Knapman, Kenneth - TWC MECHANIC	4.50	Repairs to A frame - Gouge out & weld cracks, cut plates. reinforce frame with plate & weld in plac
25/02/2014	Dawson, Dale - TWC Mechanic	1.50	Remove mast from laser bucket, chk fluids in machine and deliver machine to transport yard.
27/02/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
14/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Blow out radiators & filters.
28/03/2014	Griffin, Reece - Plant Mechanic	1.00	Dig mud out of bucket.
01/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk tilt solenoid./ 7192HRS: Fit chains to bucket wheels & change tyres.
02/04/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk tilt solenoid./ 7192HRS: Fit chains to bucket wheels & change tyres.
03/04/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean out filters & cab & radiator coolers. Repair oil leaks./ Chk & replace joystick switch. Chk &
05/04/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Clean out filters & cab & radiator coolers. Repair oil leaks./ Chk & replace joystick switch. Chk &
07/04/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Clean out filters & cab & radiator coolers. Repair oil leaks./ Chk & replace joystick switch. Chk &
14/04/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Dig mud from bucket.
24/04/2014	Dawson, Dale - TWC Mechanic	1.50	7,240 HRS: Complete 250hr service./ 7,252 HRS: Locate & repair fault with apron open/close failure
26/04/2014	Dawson, Dale - TWC Mechanic	2.50	7,240 HRS: Complete 250hr service./ 7,252 HRS: Locate & repair fault with apron open/close failure
28/04/2014	Dawson, Dale - TWC Mechanic	1.00	7,240 HRS: Complete 250hr service./ 7,252 HRS: Locate & repair fault with apron open/close failure
08/05/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk charging system. R & R battery./ Dig mud from bucket. R & R apron stub, replace bucket grease n
10/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk charging system. R & R battery./ Dig mud from bucket. R & R apron stub, replace bucket grease n
12/05/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk charging system. R & R battery./ Dig mud from bucket. R & R apron stub, replace bucket grease n
13/05/2014	Wilde, David - TWC WORKSHOP MANAGER	6.00	Chk charging system. R & R battery./ Dig mud from bucket. R & R apron stub, replace bucket grease n
22/05/2014	Dawson, Dale - TWC Mechanic	1.00	LASER BUCKET: R & R right lift cylinder./ Fit new water pump belt.
22/05/2014	Wilde, David - TWC WORKSHOP MANAGER	4.00	R & R lift cylinder. Wash down & clean out cab.
26/05/2014	Dawson, Dale - TWC Mechanic	1.00	LASER BUCKET: R & R right lift cylinder./ Fit new water pump belt.
21/07/2014	Knapman, Kenneth - TWC MECHANIC	1.50	BUCKET: Make 2 new corner tips. / Make corner tips. Repair rippers, replace tyne adaptor, build up
22/07/2014	Knapman, Kenneth - TWC MECHANIC	4.00	BUCKET: Make 2 new corner tips. / Make corner tips. Repair rippers, replace tyne adaptor, build up
29/07/2014	Knapman, Kenneth - TWC MECHANIC	6.50	Repair ripper tyne./ Remanufacture-repair ripper tyne./ Gouge apart ripper bars & grind-clean reus
30/07/2014	Knapman, Kenneth - TWC MECHANIC	6.00	Repair ripper tyne./ Remanufacture-repair ripper tyne./ Gouge apart ripper bars & grind-clean reus
09/10/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Repair corner tips.
09/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	7,367HRS: Prestart
15/12/2014	Dawson, Dale - TWC Mechanic	2.00	Dig out mud on laser bucket wheels, fit chain to wheels, chk & fill hubs with oil. / LASER BUCKET:
17/12/2014	Dawson, Dale - TWC Mechanic	1.00	Dig out mud on laser bucket wheels, fit chain to wheels, chk & fill hubs with oil. / LASER BUCKET:
17/12/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Remove seat, weld crack & replace remaot pedestal on seat.
17/12/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	7430HRS: Repair laser bracket, blow out radiator.
18/12/2014	Knapman, Kenneth - TWC MECHANIC	6.50	Disassemble seat. Reassemble fitting damper & retainer. Locate steel for remote pedestal, manufactu

18/12/2014	Dawson, Dale - TWC Mechanic	1.00	Stripped down hydraulic cylinder - found piston rod U/S , new part ordered.
07/01/2015	Dawson, Dale - TWC Mechanic	0.50	LASER BUCKET: R & R tyre.
09/01/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Refit apron pin & retainer.
19/01/2015	Dawson, Dale - TWC Mechanic	1.00	Refit apron pin back into boss, drill out broken bolt & fit new bolt./ 7,579HRS: Complete 500hr ser
20/01/2015	Dawson, Dale - TWC Mechanic	1.00	Refit apron pin back into boss, drill out broken bolt & fit new bolt./ 7,579HRS: Complete 500hr ser
22/01/2015	Dawson, Dale - TWC Mechanic	0.50	BUCKET: Check corner tip on bowl.
27/01/2015	Knapman, Kenneth - TWC MECHANIC	1.50	7,642HRS: Chk belts - order replacements for a/c & water pump. Replace bucket tilt cylinder. Tighte
28/01/2015	Knapman, Kenneth - TWC MECHANIC	0.50	7,642HRS: Chk belts - order replacements for a/c & water pump. Replace bucket tilt cylinder. Tighte
29/01/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	7,644HRS: Remove & replace a/c & water pump belts. Replace seat assy. Test run. / Repair laser cont
02/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	7,644HRS: Remove & replace a/c & water pump belts. Replace seat assy. Test run. / Repair laser cont
06/02/2015	Dawson, Dale - TWC Mechanic	1.00	Reinstall bolts into wheel hub on laser bucket - mounting bolts broken.
12/02/2015	Knapman, Kenneth - TWC MECHANIC	1.00	7,756HRS: 250hr service. Replace walking beam axle hub bolts. / Replace bottom articulation pin. Do
12/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	7,750HRS: Service. / R & R artic pin. Refit laser cable & test run. / Remove rear drive shaft. Repl
13/02/2015	Knapman, Kenneth - TWC MECHANIC	3.00	7,756HRS: 250hr service. Replace walking beam axle hub bolts. / Replace bottom articulation pin. Do
13/02/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	7,750HRS: Service. / R & R artic pin. Refit laser cable & test run. / Remove rear drive shaft. Repl
14/02/2015	Knapman, Kenneth - TWC MECHANIC	3.00	7,756HRS: 250hr service. Replace walking beam axle hub bolts. / Replace bottom articulation pin. Do
14/02/2015	Wilde, David - TWC WORKSHOP MANAGER	3.50	7,750HRS: Service. / R & R artic pin. Refit laser cable & test run. / Remove rear drive shaft. Repl
18/02/2015	Dawson, Dale - TWC Mechanic	0.50	Replace dash with one from #256 to try & rectify fault with engine RPM - guage not working. Repaire
19/02/2015	Dawson, Dale - TWC Mechanic	0.50	Oil up. Chk & top up hubs on laser bucket.
19/02/2015	Knapman, Kenneth - TWC MECHANIC	1.00	LASER BUCKET: Chk & top up oils in hubs. Solde switch connection of bucket control box.
27/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	7,861HRS: Replace overflow tube. Remove flat tyre.
07/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	7,945HRS: Repalce leaking seal on tip ram.
10/03/2015	Dawson, Dale - TWC Mechanic	2.50	R & R 3 hoses - 1 blown, 2 damaged from rubbing. Travel to Mungindii to have made. Locate leak arou
10/03/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Gouge apart ripper bar.
11/03/2015	Dawson, Dale - TWC Mechanic	1.50	R & R 3 hoses - 1 blown, 2 damaged from rubbing. Travel to Mungindii to have made. Locate leak arou
12/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	8,000HRS service. Clean out a/c system. / BUCKET: R & R wheel hub.
13/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	8,000HRS service. Clean out a/c system. / BUCKET: R & R wheel hub.
20/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	BUCKET: R & R tyre.
31/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,127HRS: Tighten radiator clamps & chk over. / Replace radiator cap & bucket mast. Test run.
01/04/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,127HRS: Tighten radiator clamps & chk over. / Replace radiator cap & bucket mast. Test run.
09/04/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace rubber mounts under mast. replace bonnet catch & adjust
20/04/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,223HRS: NChk rear light wiring & replace lights. Adjust bonnet catch.
24/04/2015	Dawson, Dale - TWC Mechanic	0.50	LASER BUCKET: R & R tyre.
24/04/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	8,250HRS: Service. / 8,257HRS: Replace water pump belt.
28/04/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,250HRS: Service. / 8,257HRS: Replace water pump belt.
28/04/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Repair/remanufacture ripper bar.
12/05/2015	Dawson, Dale - TWC Mechanic	1.00	R & R skirts on laser bucket, R & R air & a/c air filters.

02/06/2015	Dawson, Dale - TWC Mechanic	3.50	Split machine from bucket, wash engine & hitch, put machine into w'shop for resealing of rocker box
03/06/2015	Dawson, Dale - TWC Mechanic	8.00	Disassemble engine oil gallery manifolds for resealing. Clean & inspect parts & commenc reassembly.
04/06/2015	Dawson, Dale - TWC Mechanic	6.00	Reassembly of engine, fit hoses, guards, brackets etc. Complete eng. valve set. Fill oil & coolant,
05/06/2015	Dawson, Dale - TWC Mechanic	1.00	Finalise assembly of engine after reseal of top eng. oil housing.
09/06/2015	Dawson, Dale - TWC Mechanic	5.50	Reseal eng. oil leaks around front eng. structure. Remove & reseal oil pump, repair coolant leaks,
22/06/2015	Knapman, Kenneth - TWC MECHANIC	1.50	Remove ripper bar & tyne & commence remanufacture of bar.
23/06/2015	Knapman, Kenneth - TWC MECHANIC	7.50	Repair ripper arm, straighten tyne. Refit both. Acquire steel for tyne locator. Remove blown hose &
24/06/2015	Dawson, Dale - TWC Mechanic	5.50	Drain fill hubs on bucket & chk for movement. R & R leaking hose. Chk & grease all ports, R & R lea
17/08/2015	Dawson, Dale - TWC Mechanic	3.00	Rotate tyres/rimms - front to back. Drain water from rear tyres & fill front.
21/08/2015	Dawson, Dale - TWC Mechanic	1.00	Chk over engine due to noted oil leak & repair leak. Repair laser bucket - not working on apron cir
25/08/2015	Knapman, Kenneth - TWC MECHANIC	3.50	Disassemble lift cylinder. Purchase seals & O rings, reassemble cylinder.
01/09/2015	Knapman, Kenneth - TWC MECHANIC	3.50	Travel to Ski Park, chk fluid levels, belt tensions & chk over bucket. Trace wiring fault in amber
14/09/2015	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
15/09/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
16/09/2015	Wilde, David - TWC WORKSHOP MANAGER	0.75	Prestart/FGR
24/09/2015	Knapman, Kenneth - TWC MECHANIC	6.00	BUCKET: Remove broken stud locating walking beam pin & replace. Clean out grease holes. Remove ripp
24/09/2015	Wilde, David - TWC WORKSHOP MANAGER	4.00	Part wash down & repairs to bucket.
25/09/2015	Wilde, David - TWC WORKSHOP MANAGER	4.50	Part wash down, clean out cab & a/c system.
28/09/2015	Wilde, David - TWC WORKSHOP MANAGER	6.00	Disconnect bucket from machine, remove hitch mount bracket. Chk & reshim artic joint. Clean windows
29/09/2015	Knapman, Kenneth - TWC MECHANIC	4.50	Gouge off cushion hitch cylinder mounts, cut out replacement lugs & deliver to McManus for machinin
01/10/2015	Dawson, Dale - TWC Mechanic	2.00	Evac a/c system, clean Receiver/dryer & recharge system/
06/10/2015	Knapman, Kenneth - TWC MECHANIC	3.00	Weld lugs to cushion hitch cylinder mount & bolt mount to tractor 2.5hrs. BUCKET: Disassemble wheel
06/10/2015	Dawson, Dale - TWC Mechanic	1.50	Fit drawbar hitch to tractor, fit bolts to bonnet- a/c box.
07/10/2015	Dawson, Dale - TWC Mechanic	2.00	Remove R/H front hub for resealing.
07/10/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	Remove R/H front tyre & hub. Look up & price parts.
08/10/2015	Dawson, Dale - TWC Mechanic	5.00	Strip down, clean & inspect parts/gears/bearing from final drive, remove outer bearing cup, centrep
09/10/2015	Dawson, Dale - TWC Mechanic	0.50	Clean up bolts for assembly of final drive.
12/10/2015	Wilde, David - TWC WORKSHOP MANAGER	3.50	Reassemble R/H front hub & wheel. Tension wheel bolts & fill with oil.
13/10/2015	Knapman, Kenneth - TWC MECHANIC	2.00	Connect to cushion hitch & bucket.
28/10/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart, fuel up & fit oversize signs.
25/11/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Prestart/FGR & fit O'size signs.
25/11/2015	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart & run a/c system.
27/11/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,467HRS: R & R hyd. hose, fill hyd. tank & test run.
28/11/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	8,472HRS: Reapir bucket stop mount. R & R tip ram fitting. Replace hyd. hose.
03/12/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	8,512HRS: 500hr service.
10/12/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace bulbs in control box.
15/12/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	R & R switch.

07/01/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Prestart & run a/c. Chk & repair wiring to gear switch. Test run.
18/01/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Chk trans filter for matal
20/01/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Chk pump & shaft pressure on transmission. Remove bucket from machine & move machine into w'shop. R
20/01/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Pressure test trans. Clean up parts, collect parts, disconnect bucket.
21/01/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Chk end cap length. Reassemble trans. components replacing seals etc - Test. Connect drive lines &
11/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
12/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR (350lts diesel supplied by Wilde Civil)
28/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk start fault & clean battery terminals - test run.
02/03/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Check crack in bucket.
05/03/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Weld crack in bucket apron side beam
05/03/2016	Knapman, Kenneth - TWC MECHANIC	0.50	8,774HRS: Replace apron guide bolts, replace alternator belts, 250hr service.
05/03/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	8,750HRS: Service, chk all tyre pressures, clean out radiators & coolers.
14/03/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repairs to fan guard, price parts.
16/03/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Replace U bend & flex pipe on exhaust.
16/03/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace exhaust elbow & tube.
21/03/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Purchase new batteries & fir to unit. Chk into seat power fault.
21/03/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & replace batteries. Test charge, clean all leads. Chk seat compressor.
22/03/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Solder wiring of seat pump motor, reassemble.
22/03/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove, repair & refit seat compressor - test run.
30/03/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Remove fan shroud, measure & order steel for repairs.
30/03/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove fanguard for repairs.
31/03/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Take measurements of broken fan shroud. Mark out sheet metal for manufacture of new shroud.
01/04/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Continue with manufacture of fan shroud. Deliver sheet to Blake Tidmarsh for folding.
08/04/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Continue manufacture of cowling.
08/04/2016	Knapman, Kenneth - TWC MECHANIC	1.50	To jobsite, fit new cowling & return to w'shop.
08/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.25	Refit fan guard & header tank. Chk belts.
13/04/2016	Knapman, Kenneth - TWC MECHANIC	2.00	Collect tools for repairs. Remove broken studs, change fan belts, paint new cowling, fit a/c vac tu
13/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace fan belts & remove broken bolts. R & R radiator hose. Test run.
21/04/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Commence welding fan cowling halves together.
22/04/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Continue welding/manufacture of fan cowling
23/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
23/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,812hrs: Chk & adjust tyre pressures. Clean out cab.
28/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	8,862HRS: Chk over machine.
11/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart & run engine.
18/05/2016	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
24/05/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Paint replacement fan shroud.
24/05/2016	Dawson, Dale - TWC Mechanic	1.00	R & R R/H wheel on pivot frame.

25/05/2016	Knapman, Kenneth - TWC MECHANIC	0.50	R & R 2 way hand piece. Inspect accessory drive oil leak.
27/05/2016	Dawson, Dale - TWC Mechanic	1.00	Strip down & reseal spare apron cylinder.
30/05/2016	Dawson, Dale - TWC Mechanic	0.50	Repaired ripper frame.
07/06/2016	Knapman, Kenneth - TWC MECHANIC	3.75	Replace aux. drive seal, remove radiator for repair, remove water pump for replacement, buff surfac
07/06/2016	Dawson, Dale - TWC Mechanic	0.50	Remove radiator & load onto ute & deliver for repairs.
07/06/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove radiator & water pump, replace acc. drive seal & sleeve.
08/06/2016	Dawson, Dale - TWC Mechanic	1.00	Assist refit radiator.
08/06/2016	Knapman, Kenneth - TWC MECHANIC	5.00	Re install water pump & radiator, chk seat adjuster fault, remove broken tyne on bucket, knock in c
08/06/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Find seat adjuster, repair ripper tyne.
08/06/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	8,9368HRS: Replace water pump & radiator & mounts, remove broken ripper tyne, replace hitch pin.
09/06/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk bolt tension. Ripper bars. Repair pivot grease point.
09/06/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean mud from bucket.
10/06/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Replace bucket hub & ripper bar & tyne. replace fan guard & belts.
11/06/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair gear shift wiring. Replace water pump adjuster pulley.
14/06/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R old clamps on bucket.
16/06/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	8,991HRS: Replace ripper bar & tyne.
17/06/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Carry out partial 1,000hr service.
17/06/2016	Wilde, David - TWC WORKSHOP MANAGER	4.50	9,000Hrs service.
27/06/2016	Knapman, Kenneth - TWC MECHANIC	3.00	Inspect seat pump motor, remove & take to w'shop & repair. Reinstall motor to seat.
30/06/2016	Dawson, Dale - TWC Mechanic	0.50	R & R trans. & oil filters.
30/06/2016	Dawson, Dale - TWC Mechanic	1.00	Fit chains to tyres & dig mud out.
30/06/2016	Knapman, Kenneth - TWC MECHANIC	0.50	9,000HR Service: Change trans. oil.
30/06/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Fit chains to wheels.
01/07/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Inspect bucket for repairs.
01/07/2016	Knapman, Kenneth - TWC MECHANIC	1.50	BUCKET: Clear out mud & replace skirt & spacer.
02/07/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Replace broken ripper bar.
04/07/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Clean mud off bucket.
12/07/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	Part wash down. R & R leaking hose. Repair rear window seal.
13/07/2016	Dawson, Dale - TWC Mechanic	1.50	Assist with fitting of V belts, fan & fan hub, front eng. oil seal, adjust radiator assy for fan cl
13/07/2016	Knapman, Kenneth - TWC MECHANIC	7.50	Seal rear cabin window glass, remove fan to access harmonic balancer, R & R front eng. oil seal, re
13/07/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove seat.
14/07/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Fit new seat, repair steps, cut off bucket skirt.
14/07/2016	Dawson, Dale - TWC Mechanic	3.00	Install new seat.
15/07/2016	Knapman, Kenneth - TWC MECHANIC	3.50	Box up old seat for return to seat supplier for repair quote. Order bonnet latch, collect & fit to
19/07/2016	Dawson, Dale - TWC Mechanic	0.50	Investigate overcharging fault with batteries - found voltmeter faulty - batteries being charged at
20/07/2016	Dawson, Dale - TWC Mechanic	2.00	R & R lift cylinder - split barrel.
21/07/2016	Wilde, David - TWC WORKSHOP MANAGER	4.50	Repair rippers, fit spacers to pivot, remove broken bolts, grease unti.

29/07/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Chk over unit, top up oils, adjust belts, replace coolant overflow hose. Top up coolant.
08/08/2016	Dawson, Dale - TWC Mechanic	1.00	R & R volt meter.
09/08/2016	Dawson, Dale - TWC Mechanic	0.50	Chk over for faults.
10/08/2016	Dawson, Dale - TWC Mechanic	4.00	Effect reapiers to Laser Bucket - reapiir oil leaks, R & R hyd. cylinders from rippers - strip down &
10/08/2016	Knapman, Kenneth - TWC MECHANIC	9.00	BUCKET: Gouge off welds on winged sidesheet, relocate wing & weld in place. Replace leaking lift & t
11/08/2016	Dawson, Dale - TWC Mechanic	4.50	BUCKET: R & R corner tips, repair oil leaks & hoses etc. Chk & change hub oils, grease, repair ungr
11/08/2016	Knapman, Kenneth - TWC MECHANIC	7.50	BUCKET: Locate machine into w'shop. Carry out repairs to ripper bars, R & R ripper hyd. hoses & cla
15/08/2016	Dawson, Dale - TWC Mechanic	1.50	Assemble hyd. cylinders, dig out dirt from bucket bowl.
15/08/2016	Knapman, Kenneth - TWC MECHANIC	2.00	Clean mud from bowl & begin lift cylinder disassembly.
16/08/2016	Knapman, Kenneth - TWC MECHANIC	5.00	Replace ripper rams & adjust ripper bars. Top up tractor trans oil. Make tool & disassemble lift cy
16/08/2016	Dawson, Dale - TWC Mechanic	2.00	Assemble hyd. cylinders & re install into bucket, top up oils, adjust ripper assy - test.
07/09/2016	Dawson, Dale - TWC Mechanic	1.50	Remove seat & control panel bracket & load up to take to Marywinebone site. Unload gear on return.
07/09/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove a/c gas & hose.
09/09/2016	Dawson, Dale - TWC Mechanic	4.00	Repair & reinstall seat in cab. Make up laser control box, mount & paint.
09/09/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Reseal 2 rams.
13/09/2016	Dawson, Dale - TWC Mechanic	2.00	Fit new a/c hose, receiver/dryer, vac down & recharge a/c - test.
14/09/2016	Dawson, Dale - TWC Mechanic	2.00	Remove pins from main pivot, make up shims, fit shims & new pins.
14/09/2016	Wilde, David - TWC WORKSHOP MANAGER	4.50	R & R pivot pins & fit spacers.
19/09/2016	Dawson, Dale - TWC Mechanic	4.50	Laser Bucket: R & R L/H wing. Remove apron for repairs.
19/09/2016	Knapman, Kenneth - TWC MECHANIC	7.50	Laser Bucket: Remove L/H side sheet & apron for repairs. order steel. Replace side sheet, make spac
19/09/2016	Wilde, David - TWC WORKSHOP MANAGER	5.50	R & R L/H bucket side. Clean up bolts.
20/09/2016	Knapman, Kenneth - TWC MECHANIC	7.50	BUCKET: Begin replacement of apron edge. Remanufacture apron.
21/09/2016	Knapman, Kenneth - TWC MECHANIC	7.50	BUCKET: Continue with remanufacture of apron.
22/09/2016	Knapman, Kenneth - TWC MECHANIC	6.50	BUCKET: Refurbish apron.
23/09/2016	Dawson, Dale - TWC Mechanic	2.50	Fit apron to laser bucket, fit hydraulic cylinder & laser frames etc.
23/09/2016	Knapman, Kenneth - TWC MECHANIC	4.00	BUCKET: Finish apron refurbishment & fit to bucket. Clean work area.
26/09/2016	Knapman, Kenneth - TWC MECHANIC	3.00	BUCKET: Commence repairs to sidesheet. Cut off end cap & clean out mud. Press out bent side sheet p
27/09/2016	Knapman, Kenneth - TWC MECHANIC	3.50	BUCKET: Repair side sheet. Straighten side, weld cracks & replace cover plate.
05/10/2016	Dawson, Dale - TWC Mechanic	1.50	Investigate laser failure - fault in harness - repaired.
06/10/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Remove rippers & bar assy for repair.
06/10/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Repair ripper bar assy.
06/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove broken rippers
07/10/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Refit ripper bar & rippers. Fit hyd. lift cylinder.
07/10/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace rippers. R & R lift ram & test run.
13/10/2016	Knapman, Kenneth - TWC MECHANIC	0.50	LASER BUCKET: Replace bar assy, replace O ring on ripper cylinder.
13/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace broken ripper bars.
14/10/2016	Dawson, Dale - TWC Mechanic	0.50	Fit new teeth to laser bucket.

14/10/2016	Knapman, Kenneth - TWC MECHANIC	2.50	BUCKET: Repair bar assy.
14/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	9,188HRS: Replace ripper boots.
14/10/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Change tyre & ripper bar.
24/10/2016	Dawson, Dale - TWC Mechanic	1.00	Rotate cutting edges, R & R corner tips.
26/10/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Repair ripper bar & 2 x corner tips.
27/10/2016	Dawson, Dale - TWC Mechanic	1.50	Strip down, clean & reseal wheel hub.
28/10/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Purchase 250Hr P/M kit.
01/11/2016	Dawson, Dale - TWC Mechanic	2.00	R & R bucket tyre. R & R fuel hoses on machine.
03/11/2016	Knapman, Kenneth - TWC MECHANIC	4.00	Collect W lug, take to jobsite, change out tyres - pairing new & old, deliver tyre for replacement
26/11/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	9,250HRS: Service, fit clamps to fuel lines. Replace bucket ripper points.
28/11/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Change cutting edges & tyne.
30/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace steering hose.
07/12/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	9,314HRS: Tighten apron stub.
08/12/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	9,316HRS: Replace broken bolt in rippers.
10/12/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Change 2 wheel hubs
10/12/2016	Wilde, David - TWC WORKSHOP MANAGER	0.75	R & R 2 x bucket hubs.
04/01/2017	Knapman, Kenneth - TWC MECHANIC	4.00	Remove old seat & fit new seat to machine.
04/01/2017	Wilde, David - TWC WORKSHOP MANAGER	5.00	R & R hyd. hoses, repair bonnet.
05/01/2017	Knapman, Kenneth - TWC MECHANIC	7.50	Check tyre pressures. Locate & repair coolant leak, chk & set intake & exhaust valves. Set injector
05/01/2017	Wilde, David - TWC WORKSHOP MANAGER	6.00	Adjust all tyre pressures. Repair coolant leak. replace spron stub. Grease machine, valve set. Bonn
06/01/2017	Wilde, David - TWC WORKSHOP MANAGER	4.50	Repair oil cooler & replace hoses. Part wash down. Clean out cab & windows.
09/01/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace grease nipples.
23/01/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Locate creeper/clutch adjuster.
25/01/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Blow out radiator & coolers. replace grease nipple.
28/01/2017	Knapman, Kenneth - TWC MECHANIC	1.75	Fit clutch cable, adjust & test.
28/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	9,500HRS: Service & blow out cab filters.
03/02/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Replace leaking seal on tilt cylinder.
03/02/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	9,548HRS: Replace lift ram fitting & tighten pipes.
05/02/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace hyd. hose & test run.
06/02/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace 2 laser cables & test run.
07/02/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace hyd. hose & bonnet catch.
10/02/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Clean out air filters & coolers.
13/02/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Investigate eng. misfire. Chk fuel system. Remove tappet covers & chk for broken parts.
14/02/2017	Dawson, Dale - TWC Mechanic	1.00	Detatch laser bucket from tractor, load tractor onto float.
14/02/2017	Dawson, Dale - TWC Mechanic	5.50	Wash unit & move into w'shop. Commence stripping eng. down to pinpoint failure - found dropped valv
14/02/2017	Bell, Daniel - TWC Manager	3.00	Freight tractors for repairs.
14/02/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Disconnect laser bucket & load onto float.

14/02/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove failed engine.
15/02/2017	Bell, Daniel - TWC Manager	3.00	Freight tractors for repairs.
15/02/2017	Dawson, Dale - TWC Mechanic	9.50	Remove failed engine & move machine out of w'shop. Move 2nd hand tractor into w'shop & remove eng.
15/02/2017	Knapman, Kenneth - TWC MECHANIC	4.00	Assist with R & R of engine.
15/02/2017	Wilde, David - TWC WORKSHOP MANAGER	6.00	Remove eng. from 2nd hand tractor. Install replacement eng.
16/02/2017	Dawson, Dale - TWC Mechanic	3.00	Finish install of engine. Vac down & regas a/c. Remove dual tyres from spare parts tractor & fit to
16/02/2017	Knapman, Kenneth - TWC MECHANIC	6.50	Fill eng. with fluids. Change over tyres. Weld pin & plate on bucket pull.
16/02/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit eng. & repair pin on drewbar.
17/02/2017	Bell, Daniel - TWC Manager	0.25	FGR
17/02/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Blow out radiator & coolers. Chk cross leveller.
18/02/2017	Bell, Daniel - TWC Manager	2.00	Various R&M 252/256
18/02/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Tension wheel studs, chk machines & blow out radiators.
18/02/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk wheel bolt tension & blow out radiator.
19/02/2017	Bell, Daniel - TWC Manager	1.00	Various R&M 252/256
20/02/2017	Bell, Daniel - TWC Manager	0.50	FGR
23/02/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Remove & disassemble tilt cylinder, reseal & reinstall. Clean around accessory drive & wheel seal.
24/02/2017	Dawson, Dale - TWC Mechanic	4.00	Remove l/h rear final drive, strip down, clean & reseal. Refit & set prelaod etc.
24/02/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Replace accessory drive seal.
24/02/2017	Wilde, David - TWC WORKSHOP MANAGER	7.00	R & R L/H rear wheel seal. Clean up parts. Replace accessory drive seal.
03/03/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace tilt valve & test run.
08/03/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Replace pipe storch clamps & adjust chk valve.
08/03/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Repair oil leaks, replace tip cylinder, test run.
09/03/2017	Knapman, Kenneth - TWC MECHANIC	3.50	Make & fit replacement valve mounting bracket. Weld chain half links for o'size & clearance flags.
09/03/2017	Wilde, David - TWC WORKSHOP MANAGER	9.50	Part wash down. Replace leaking hoses. Replace hitch acc. & recharge. Chk bucket for cracks. Clean
10/03/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Replace seals on oil pump. Replace console catches. Repair cushion sensors.
11/03/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean sealant from window & reseal.
13/03/2017	Knapman, Kenneth - TWC MECHANIC	2.00	Make cushion hitch sensor mount & fit to unit.
14/03/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Clean & inspect final drive parts & partial reassembly.
16/03/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to spare hub.
22/03/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Clean up & assemble final drive.
05/04/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Chk fluid levels.
07/04/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Fit grease tube to hitch pivot.
07/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to tow ball, order parts.
20/04/2017	Dawson, Dale - TWC Mechanic	1.00	Investigate & locate coolant leak - repair leak to aftercooler.
24/04/2017	Knapman, Kenneth - TWC MECHANIC	2.00	Chk over machine, grease, fuel & move machine on site.
19/05/2017	Knapman, Kenneth - TWC MECHANIC	2.50	Remove rear driveline for replacement from spares machine. Disassemble driveline, obtain parts & ha
25/05/2017	Knapman, Kenneth - TWC MECHANIC	1.25	Chk over machine & grease.

31/05/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Replace rear diff seal & yoke. Fit new driveline including two new universals. Remove laser frame e
02/06/2017	Dawson, Dale - TWC Mechanic	2.00	Strip down, inspect, clean & fir new shaft to hyd. cylinder.
08/06/2017	Dawson, Dale - TWC Mechanic	1.50	Strip down , clean & inspect hyd. cylinder. Arrange for new rod.
13/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	19,750HRS: Service.
15/06/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace tip cylinder fitting.
19/06/2017	Knapman, Kenneth - TWC MECHANIC	7.50	Clean up engine components in preparation for engine rebuild.
19/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Engine rebuild: Clean up parts.
19/06/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace aftercooler seal, chk bucket.
20/06/2017	Knapman, Kenneth - TWC MECHANIC	4.00	Clean up engine components in preparation for engine rebuild.
21/06/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Unpack & box up core returns.
23/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.25	9,923HRS: Replace door damper & remove broken bolts.
27/06/2017	Knapman, Kenneth - TWC MECHANIC	3.50	R & R steering column, attemp apron stub removal - reassemble as is.
06/07/2017	Knapman, Kenneth - TWC MECHANIC	2.00	Spare Engine: Commence set up for engine rebuild. Chk parts & o'size recommendations.
06/07/2017	Dawson, Dale - TWC Mechanic	1.50	Unpack cylinder & block & crank/parts etc.
11/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	9,969HRS: prestart & run a/c system. Clean out evaporator. Chk bucket & tractor tyre pressures. Rep
17/07/2017	Dawson, Dale - TWC Mechanic	5.00	Wash parts - crank & block after machining. Blow out all galleries & set up block in w/shop. Commen
17/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Auscott N'Bri: Chk a/c operation & add gas. Chk & top up bucket hubs. Replace laser mast.
18/07/2017	Dawson, Dale - TWC Mechanic	6.50	Clean engine components & work area. Continue with assembly of engine & measurment of components fo
18/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Assemble & clean eng. parts.
19/07/2017	Dawson, Dale - TWC Mechanic	7.00	Continue assembly of engine. Install piston skirts, rings etc. Chk bearing clearances, measure up b
19/07/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Look up & price eng. parts. Contine with engine assembly.
24/07/2017	Dawson, Dale - TWC Mechanic	1.50	Repair hyd. leak, fit pins back into hitch cusion.
24/07/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Spare Eng.: Assist Diesel mechanic with parts & timing cams, fit plugs.
24/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.50	Assemble steering column & fit to machine. prestart & run a/c system.
25/07/2017	Dawson, Dale - TWC Mechanic	2.50	Finish making supports for control valve on rear of tractor.
27/07/2017	Knapman, Kenneth - TWC MECHANIC	5.50	Spare Eng.: Commence component reassembly on engine.
27/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Spare Eng.: Clean up parts./Look up & order parts as required. Assist assemble eng.
28/07/2017	Knapman, Kenneth - TWC MECHANIC	6.50	Spare Eng.: Continue with reassembly.
28/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Spare Eng.: Clean up parts./Look up & order parts as required. Assist assemble eng.
31/07/2017	Knapman, Kenneth - TWC MECHANIC	7.50	Spare Eng.: Continue with reassembly.
31/07/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	Spare Eng.: Clean up parts./Look up & order parts as required. Assist assemble eng.
31/07/2017	Dawson, Dale - TWC Mechanic	1.00	Spare Eng.: Assist with eng. assembly.
01/08/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Spare Eng: Continue with assembly.
02/08/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Spare Eng: Continue with assembly.
03/08/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	10,000HRS: part Service.
07/08/2017	Knapman, Kenneth - TWC MECHANIC	5.50	Spare Diff Disassemble planetaries. Source replacement parts. Reassemble one planetary.
07/08/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Spare Eng.: Fit maifold, fuel & oil lines & air con mount bracket.

08/08/2017	Dawson, Dale - TWC Mechanic	0.50	Prestart & fit signs to machine.
09/08/2017	Dawson, Dale - TWC Mechanic	3.00	Remove front L/H hub, re-assemble final drive & retension wheel bearings. Fit dual tyres. Complete
09/08/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Remove front L/H hub, re-assemble final drive & retension wheel bearings. Fit dual tyres. Complete
18/08/2017	Dawson, Dale - TWC Mechanic	1.50	R & R cutting edges , rotate & fit corner tips.
22/08/2017	Wilde, David - TWC WORKSHOP MANAGER	3.50	Remove blown hose. Go to Narrabri & have new hose made, return to site, fit new hose & test.
24/08/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	20,077HRS: Change skirts.
05/09/2017	Dawson, Dale - TWC Mechanic	0.50	Remove alternator from spare eng.
05/09/2017	Dawson, Dale - TWC Mechanic	1.00	Swap over alternator, jump start machine, test cooling system.
18/09/2017	Knapman, Kenneth - TWC MECHANIC	1.00	10,250HRS: Carry out 250hr service.
22/09/2017	Knapman, Kenneth - TWC MECHANIC	4.00	Chk A/c systgem, connect guages, vac down system & recharge.
25/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk wheel hub leak. Replace ripper bar & bolts in skirts.
29/09/2017	Dawson, Dale - TWC Mechanic	1.50	Strip down hud, inspect, clean & commence reassembly with new bearings.
30/09/2017	Dawson, Dale - TWC Mechanic	4.00	10,350HRS: R & R r/h rear final drive assy, tension water pump drive belt. R & R auto control switc
30/09/2017	Knapman, Kenneth - TWC MECHANIC	4.00	10,350HRS: Change out r/h rear final drive, tension water pump belt & pack up gear.
04/10/2017	Dawson, Dale - TWC Mechanic	8.50	Continue work on final drives rebuilds.
30/10/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	10,454HRS: Chk & repair Navman. Replace broken bolts in drawbar.
04/11/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	500Hrs service.
06/11/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk a/c operation. Make up fan speed switch & test run.
10/11/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace bucket tyre.
22/11/2017	Dawson, Dale - TWC Mechanic	1.00	R & R starter motor.
24/11/2017	Dawson, Dale - TWC Mechanic	1.00	R & R R/h side apron cylinder - test.
27/11/2017	Dawson, Dale - TWC Mechanic	1.00	R & R blown hose, refit guards.
05/12/2017	Knapman, Kenneth - TWC MECHANIC	0.75	Chk/fill bucket wheel hubs & clean floor filters.
05/12/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Clean out a/c filters. Chk & adjust tyre pressures. Chk over.
06/12/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace fan speed switch & repair wiring. Chk & adjust tractor tyre pressures.
07/12/2017	Dawson, Dale - TWC Mechanic	0.50	Repair a/c.
09/12/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	R & R broken rippers.
15/12/2017	Dawson, Dale - TWC Mechanic	1.50	250Hr service. Replace exhaust elbow out of turbo.
18/12/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to tyre.
21/12/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk cooling system & fan belts. Replace radiator cap.
08/01/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	20,788HRS: Prestart. Chk & adjust all tyre pressures. Blow out coolers & radiator. Run a/c . Adjust
16/01/2018	Knapman, Kenneth - TWC MECHANIC	0.75	10,814HRS: Change broken rippers & bars.
23/01/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	880Hrs: Replace a/c & water pump belts.
28/01/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	Chk coolant leaks.
05/02/2018	Knapman, Kenneth - TWC MECHANIC	1.25	Drain coolant. Replace O ring seal in rocker box & replace coolant.
05/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk tractor & bucket tyre pressures. Chk bucket hubs, chk belts.
06/02/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Tighten ripper bolts.

09/02/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Carry out 21,000HR service.
09/02/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	21,000HRS: Service.
12/02/2018	Dawson, Dale - TWC Mechanic	0.50	Tension wheel bolts after rims removed.
14/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	21,001HRS: R & R radiator hose & chk wheel tension.
15/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Complete 1,000Hr service. Tighten bucket hyd. pipe.
24/02/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk trans fault. Remove & inspect filter & replace.
27/02/2018	Dawson, Dale - TWC Mechanic	1.00	Unload from float & move into shed fro replacement of transmission.
27/02/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Disconnect tractor from bucket.
27/02/2018	Knapman, Kenneth - TWC MECHANIC	3.50	Remove failed transmission.
28/02/2018	Dawson, Dale - TWC Mechanic	3.00	Repairs to transmission. Set up welder for weld reapirs to chassis cracks. stc.
28/02/2018	Knapman, Kenneth - TWC MECHANIC	5.50	Chk for gaskets & seals on hand. Remove filler screen. Instruct Daniel in vertical welding. Oversee
01/03/2018	Knapman, Kenneth - TWC MECHANIC	4.00	Finish installation of trans. & fit guards.
01/03/2018	Wilde, David - TWC WORKSHOP MANAGER	6.50	Fit replacement trans. & test run, Refit floor plates & clean out cab.
02/03/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/
10/03/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Investigate & repair electrical fault with transmission.
10/03/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & clean trans. fittings.
12/03/2018	Dawson, Dale - TWC Mechanic	2.00	Strip down failed transmission.
14/03/2018	Dawson, Dale - TWC Mechanic	1.00	Investigate & repair hyd. fault with laser bucket.
15/03/2018	Dawson, Dale - TWC Mechanic	1.50	Inspect trans. chk for damaged parts.
15/03/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Chk transmission components.
19/03/2018	Dawson, Dale - TWC Mechanic	3.00	Inspection & make up parts listing required for rebuild of transmission.
21/03/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	21,129HRS: Replace radio & bucket hub.
22/03/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Repair ripper tynes.
23/03/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk & replace bowl switch. Repair trans. wiring - test run.
24/03/2018	Knapman, Kenneth - TWC MECHANIC	5.00	11,048HRS: Repair coolant leaks.
24/03/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	Replace eng. water seals.
27/03/2018	Dawson, Dale - TWC Mechanic	0.50	Clean out air filters.
20/06/2018	Dawson, Dale - TWC Mechanic	1.50	Chk over machine, clean cab & windows.
11/07/2018	Dawson, Dale - TWC Mechanic	0.25	Chk over.
31/07/2018	Dawson, Dale - TWC Mechanic	2.50	21,560HRS: Strip down, inspect & reseal lift ram hyd. cylinder. Remove ripper assy from #250 to fit
31/07/2018	Dawson, Dale - TWC Mechanic	3.25	500hr service, R & R damaged R/H ripper frame. R & R R/H apron cylinder. R & R left hand new wheel
31/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	1,562HRS: Chk over & pick up parts.
03/08/2018	Wilde, David - TWC WORKSHOP MANAGER	5.00	1,566HRS: Chk hyd. fault & clean check valve. Drain & clean out hyd. tank & screen. Refill & test r
06/08/2018	Dawson, Dale - TWC Mechanic	1.50	1,560HRS: Strip down bucket wheel hub, reseal/rerace.
13/08/2018	Dawson, Dale - TWC Mechanic	2.50	Fit ripper frame to bucket. R & R blown hose (obtain new one from Moree), refill hyd. oil & test ru
13/08/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repairs to rippers.
20/08/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	1,595HRS: Chk hyd fault. R & R lift cylinder. Test run.

22/08/2018	Dawson, Dale - TWC Mechanic	3.00	1,610HRS: Investigate hydraulic fault. Remove hyd. pump. Fit replacement pump, refill with fresh oi
22/08/2018	Dawson, Dale - TWC Mechanic	1.00	Remove Hyd. oil pump from tractor #256 in yard as replacement.
04/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	1634HRS: R & R top radiator hose.
05/09/2018	Wilde, David - TWC WORKSHOP MANAGER	7.00	1,634HRS: Repair oil leaks. wash down. Replace tip cylinder & cutting edges.
05/09/2018	Dawson, Dale - TWC Mechanic	2.50	1,634HRS: Repair eng. oil leaks on cam boxes. Repair hyd. leaks.
06/09/2018	Dawson, Dale - TWC Mechanic	0.50	21,634HRS: R & R bucket hub.
06/09/2018	Dawson, Dale - TWC Mechanic	1.50	21,634HRS: Strip down hydraulic cylinders for repair.
10/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Deliver hose for repair.
14/09/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Temporary repairs to bucket - replace lost apron pin & repair rippers.
15/09/2018	Dawson, Dale - TWC Mechanic	2.00	R & R apron rollers, fit new apron pin, fit new ripper bar frame.
19/09/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	1,710HRS: Chk & clean electrical connectors.
21/09/2018	Knapman, Kenneth - TWC MECHANIC	3.50	Drain hyd. tank & replace impement & steering pumps. Fill oil tank. Repair electrical harness - rep
21/09/2018	Wilde, David - TWC WORKSHOP MANAGER	4.50	1,727HRS: R & R hyd. pumps. Replace laser connector. Replace grease nipples - Test run.
26/09/2018	Dawson, Dale - TWC Mechanic	1.00	21,745HRS: Carry out 250hr service.
02/10/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	1,788HRS: R & R bowl switch & repair shorted wires. Test run.
23/11/2018	Dawson, Dale - TWC Mechanic	1.50	Chk over, clean out radiator & air filters. Repair laser
27/11/2018	Dawson, Dale - TWC Mechanic	0.50	1908HRS: Jump start, test & charge system.
28/11/2018	Dawson, Dale - TWC Mechanic	1.00	21,816HRS: Install new batteries.
30/11/2018	Dawson, Dale - TWC Mechanic	1.00	Weld pin into apron & pin into draw bar.
12/12/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	R & R oil cooler.
17/12/2018	Dawson, Dale - TWC Mechanic	1.50	Remove oil from oil cooler, clean cooler & deliver to repairer for repairs.
19/12/2018	Dawson, Dale - TWC Mechanic	2.00	R & R hyd. trans. cooler, wash oil & dirt out of radiators/coolers.
20/01/2019	Dawson, Dale - TWC Mechanic	1.00	R & R bottom radiator hose. Refill engine coolant.
24/01/2019	Dawson, Dale - TWC Mechanic	1.00	Assemble hyd. cylinder.
29/01/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk over unit.
31/01/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	2,000hr service.
04/02/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to oil cooler.
04/02/2019	Dawson, Dale - TWC Mechanic	0.50	Inspect cooling system, adjust V belts.
13/02/2019	Dawson, Dale - TWC Mechanic	2.00	Full wash & clean of radiator.
15/02/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,087HRS: Ripair rippers.
19/02/2019	Knapman, Kenneth - TWC MECHANIC	1.50	Repair ripper bar.
09/03/2019	Wilde, David - TWC WORKSHOP MANAGER	2.50	2,250HRS: Service (250hr?)
16/03/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair bucket tynes.
27/03/2019	Dawson, Dale - TWC Mechanic	3.00	BUCKET: Assemble repaired lift ram, strip down, clean & reseal bowl ram.
01/07/2019	Knapman, Kenneth - TWC MECHANIC	3.50	Commence with transmission disassembly.
15/07/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Chk & adjust tyre pressures. R & R light globe. Repair brackets.
16/07/2019	Knapman, Kenneth - TWC MECHANIC	1.50	Replace bucket lifgting lug - R/H side.

16/07/2019	Wilde, David - TWC WORKSHOP MANAGER	6.00	2,354HRS: Repairs to bucket. Replace fan bearings & idler pulley. Chk over & blow out cab & radiat
17/07/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	2,354HRS: Clean out a/c system. Fix eng. oil leaks.
18/07/2019	Knapman, Kenneth - TWC MECHANIC	1.50	Assemble walking beam/leveller assy.
18/07/2019	Knapman, Kenneth - TWC MECHANIC	3.00	Bucket: Reman apron.
24/07/2019	Dawson, Dale - TWC Mechanic	3.50	BUCKET: Assist with repairs - R & R leaking/damaged hoses, R & R apron & bowl cylinders.
25/07/2019	Dawson, Dale - TWC Mechanic	9.00	BUCKET: Fix oil leaks, reseal pilot control valve, wash bucket, test operation & chk for oil leaks.
29/08/2019	Dawson, Dale - TWC Mechanic	4.50	Reseal 3 hyd. cylinders & reassemble (spares)
14/10/2019	Dawson, Dale - TWC Mechanic	1.50	BUCKET: Rebuild hub & refit.
25/10/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Escort machine to Beela & return to w'shop.
09/12/2019	Dawson, Dale - TWC Mechanic	2.00	Fit pin back into hyd. cylinder head.
31/01/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	2,450HRS: R & R hyd. hose.
05/02/2020	Knapman, Kenneth - TWC MECHANIC	2.00	Repair bucket hub.
30/03/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/chk over.
16/04/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Collate steel list for walking beam & cross leveller manufacture - place order.
29/04/2020	Wilde, David - TWC WORKSHOP MANAGER	2.75	2,500HRS service.
03/06/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Inspect bucket for lug replacements. Repair tractor bonnet latch.
04/06/2020	Knapman, Kenneth - TWC MECHANIC	8.00	BUCKET: Remove bent ripper. Replace R/H side base for router support. Remove R/H cross leveller as
04/06/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repair laser cable.
29/06/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,536HRS: Prestart/FGR & chk tyre pressures.
17/08/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove window for repairs.
02/10/2020	Knapman, Kenneth - TWC MECHANIC	0.50	BUCKET: Weld pin retainer on to lift cylinder rod.
11/11/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,615HRS: R & R hyd. hose. Chk tyre pressures.
11/11/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Replace hyd. hoses.
18/11/2020	Wilde, David - TWC WORKSHOP MANAGER	0.75	2,615HRS: Prestart & run a/c. Chk & adjust tyre pressures.
07/12/2020	Knapman, Kenneth - TWC MECHANIC	0.50	R & R bonnet latch.
11/12/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
12/12/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
12/12/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,666HRS: Return machine to workshop & refuel.
17/12/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace 2 flashing lights.
13/01/2021	Knapman, Kenneth - TWC MECHANIC	6.50	2736HRS: Fit chains to wheels. Purchase hyd. hose & door components & fit to machine.
13/01/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Chk transmission temp. sender unit.
19/01/2021	Knapman, Kenneth - TWC MECHANIC	3.00	12,750HRS: Load materials & equipment, travel to plant site & carry out service. return to w'shop &
19/01/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	12,750HRS: Service & remove wire from front wheel.
20/01/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Investigate electrical fault in transmission. Change bucket tyre.
23/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,760HRS: R & R bucket tyre & fit chain.
17/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,773HRS: Refit tyre & chk for leaks.
18/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk & clean trans. electrical connectors & test run.

14/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	2,816Hrs - Change cutting edges. Remove wire from wheels
15/04/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	2816hrs. Replace corner tips and t/w radio. Replace tilt fitting
20/04/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	Check and repair t/w aerial
30/04/2021	Wilde, David - TWC WORKSHOP MANAGER	2.50	2873Hrs. Remove and replace bucket tyre and chain. Check vibration in drive train. Replace damper u
01/05/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	2887Hrs. Check drive shaft bolt tension. Replace coolant overflow bottle.
03/05/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Flat battery. Jump start and run
05/05/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Repair corner tips and ripper bar
07/05/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	2892Hrs. Check bucket hubs and pins. Check fan belts and oil leaks. Replace ram pins
14/05/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,890HRS: Replace alternator belts.
18/05/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Purchase switches. Chk hyd's for rippers. Adjust control cables - diagnose fault.
19/05/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Replace 2 switches in control panel for bucket. Inspect inverter valve for rippers.
20/05/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Chk ripper rams for function, isolate each. replace diverter valve.
27/05/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Replace apron cylinder console switch. Replace bolts in steering column, endeavour to replace fanbe
28/05/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Purchase parts & load onto ute. Fit new belts to machine.
31/05/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Chk control box gear shift toggle. Solder wired back on switch.
22/06/2021	Knapman, Kenneth - TWC MECHANIC	4.00	Deliver fuel to site. Discover final drive issue. Remove assy. and return to Depot
22/06/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,980Hrs. Remove leaking hub
23/06/2021	Wilde, David - TWC WORKSHOP MANAGER	6.00	2,980Hrs. Clean up parts and reassemble final drive. Top up oil. Check belts and tighten bolt in st
23/06/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Disassemble, clean and reassemble final drive. Replace seal
23/06/2021	Knapman, Kenneth - TWC MECHANIC	4.00	Travel to Jobsite - Horseshoe. Fit final drive, wheeletc. Adjust steering column. Return to depot
30/06/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	3,000Hrs. Part service
23/07/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	Dismantle and inspect and clean up bucket hub. Dismantle and reseal apron cylinder

#REF!

#REF!