

282 - Cat 815F Compactor:282E

Date	Name	Duration	Notes
10/06/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Fit bracket & fire extinguisher.
11/06/2011	Bell, Daniel - TWC Manager	2.00	282 NEW COMPACTOR fit blade etc.
11/06/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	2352.6hrs: Fit blade & flashing light.
27/06/2011	Wilde, David - TWC WORKSHOP MANAGER	0.50	Locate drum scrapers
29/06/2011	Wilde, David - TWC WORKSHOP MANAGER	7.00	replace scraper bars
30/06/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Replace drum scrapers, complete 500hrs service & fill out SOS samples
01/07/2011	Bell, Daniel - TWC Manager	0.50	FGR
02/07/2011	Bell, Daniel - TWC Manager	0.50	FGR
03/07/2011	Bell, Daniel - TWC Manager	0.50	FGR
07/07/2011	Bell, Daniel - TWC Manager	0.00	FGR
12/07/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	2594hrs:Replace flashing light assy, replace bolts on scraper
03/08/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	2750 hrs service.
03/08/2011	Bell, Daniel - TWC Manager	1.50	Carry out 250hr service
08/08/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean out waste oil & refill bottles
25/10/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	780km: Refit mudguard
10/01/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk over & fill tank with water.
30/01/2012	Griffin, Reece - Plant Mechanic	4.50	2950hrs: 1000 hr service (ex engine)
30/01/2012	Knapman, Kenneth - TWC MECHANIC	7.50	2950hrs: Remove transmission guard, clean out mud to remove sump plug & trans screen, assist with s
08/02/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Order plates for wheel pedestals
14/02/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit E stops
17/02/2012	Knapman, Kenneth - TWC MECHANIC	4.00	Manufacture jig for plate press to fir between wheel pedestals./Shape plates & begin welding in pla
18/02/2012	Knapman, Kenneth - TWC MECHANIC	7.50	Manufacture jig for plate press to fir between wheel pedestals./Shape plates & begin welding in pla
18/02/2012	Bell, Daniel - TWC Manager	5.50	Fabricate wheel lug blanks
20/02/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Manufacture jig for plate press to fir between wheel pedestals./Shape plates & begin welding in pla
20/02/2012	Bell, Daniel - TWC Manager	7.50	Fabricate wheel lug blanks
21/02/2012	Griffin, Reece - Plant Mechanic	2.50	Press & bend plates for wheels
21/02/2012	Knapman, Kenneth - TWC MECHANIC	9.50	Manufacture jig for plate press to fir between wheel pedestals./Shape plates & begin welding in pla
22/02/2012	Knapman, Kenneth - TWC MECHANIC	7.50	Manufacture jig for plate press to fir between wheel pedestals./Shape plates & begin welding in pla
23/02/2012	Knapman, Kenneth - TWC MECHANIC	6.00	Welding in filler plates & pedestals.
24/02/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Welding in filler plates & pedestals.
15/03/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Make & painr E stop bracket.
02/05/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Manufacture calibration tool.
04/05/2012	Griffin, Reece - Plant Mechanic	3.00	Prep machine, checked wheel scrapers, order fuel level sender./ Replace fuel sender.
04/05/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk. & adjust wheel scrapers.
05/05/2012	Griffin, Reece - Plant Mechanic	1.00	Prep machine, checked wheel scrapers, order fuel level sender./ Replace fuel sender.
07/08/2012	Dawson, Dale - TWC Mechanic	1.50	Complete 250hr service, inspect engine hrs & trans on laptop.
07/08/2012	Griffin, Reece - Plant Mechanic	1.50	Complete 250hrs service, inspect engine hrs & trans hrs on laptop.
28/08/2012	Dawson, Dale - TWC Mechanic	1.50	Travel to Dalby to collect parts (not ready).
28/08/2012	Griffin, Reece - Plant Mechanic	1.50	Travel to Dalby to collect parts - not ready.
29/09/2012	Griffin, Reece - Plant Mechanic	1.00	Check over machine.
19/10/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	3477hrs: Service & chk fuel priming switch.
21/11/2012	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk over machine.
21/11/2012	Griffin, Reece - Plant Mechanic	0.50	Chk over machine.
29/11/2012	Dawson, Dale - TWC Mechanic	1.50	3759hrs: Complete 250hr service & locate leak in radiator.
19/12/2012	Dawson, Dale - TWC Mechanic	3.00	Remove & clean radiator cores & parts, refit with new seals & hoses, fit guards & test.
19/12/2012	Griffin, Reece - Plant Mechanic	3.50	Install new seal in radiator, fit new rubber mounts, fill with new coolant, fix beacon light.
14/01/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	4004hrs: Chk over machine.
14/01/2013	Griffin, Reece - Plant Mechanic	0.50	Chk over machine./ Remove 2 bent pieces from wheel - scraping on wheel frame.
16/01/2013	Griffin, Reece - Plant Mechanic	1.00	Chk over machine./ Remove 2 bent pieces from wheel - scraping on wheel frame.
22/01/2013	Dawson, Dale - TWC Mechanic	5.00	4,058hrs: Complete 2000hrs service ex diff oil change, repair front lights, fit new bracket to radi
12/02/2013	Dawson, Dale - TWC Mechanic	2.00	4,186hrs: Inspect machine & repair rear light.
06/03/2013	Dawson, Dale - TWC Mechanic	0.50	Inspect machine.

Date	Name	Duration	Notes
23/03/2013	Dawson, Dale - TWC Mechanic	2.50	Commence removal of blade scraper bars & wheels./ Finish removal of wheels./ Fit new wheels & scrap
24/03/2013	Dawson, Dale - TWC Mechanic	3.00	Commence removal of blade scraper bars & wheels./ Finish removal of wheels./ Fit new wheels & scrap
25/03/2013	Dawson, Dale - TWC Mechanic	9.50	Commence removal of blade scraper bars & wheels./ Finish removal of wheels./ Fit new wheels & scrap
25/03/2013	Griffin, Reece - Plant Mechanic	6.00	4222Hrs: 250hrs service, put new wheels on & mount scrapers & blades @ Ostwalds yard.
05/04/2013	Griffin, Reece - Plant Mechanic	4.00	4262Hrs: Tension wheel nuts, replace grease fitting & twoway. Chase cutting edges.
11/04/2013	Knapman, Kenneth - TWC MECHANIC	8.50	Couge off crowns from wheel & weld new crown on./ Weld crowns to pedestals, fit wheel to machine.
12/04/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Couge off crowns from wheel & weld new crown on./ Weld crowns to pedestals, fit wheel to machine.
12/04/2013	Griffin, Reece - Plant Mechanic	4.50	Obtain new cutting edges from Dalby, install on machine, repair steering ram oil leak, repalce seve
15/04/2013	Knapman, Kenneth - TWC MECHANIC	5.00	Couge off crowns from wheel & weld new crown on./ Weld crowns to pedestals, fit wheel to machine.
16/04/2013	Knapman, Kenneth - TWC MECHANIC	3.50	Couge off crowns from wheel & weld new crown on./ Weld crowns to pedestals, fit wheel to machine.
18/04/2013	Knapman, Kenneth - TWC MECHANIC	6.50	Gouge off crowns, clean off welds, begin welding on crowns./ Weld crown to pedestals & bolt wheel t
19/04/2013	Knapman, Kenneth - TWC MECHANIC	9.00	Gouge off crowns, clean off welds, begin welding on crowns./ Weld crown to pedestals & bolt wheel t
30/04/2013	Griffin, Reece - Plant Mechanic	1.50	Chk & diagnose a/c fault - compressor failure.
01/05/2013	Dawson, Dale - TWC Mechanic	1.00	Remove a/c compressor from machine.
02/05/2013	Dawson, Dale - TWC Mechanic	3.50	4400Hrs: Fit new a/c compressor, flush out system, R & R reveiver dryer, vac down & charge system.
02/05/2013	Griffin, Reece - Plant Mechanic	3.00	4,400Hrs: R & R a/c compressor & receiver dryer, clean contamination from lines, vac down & regas.
18/05/2013	Griffin, Reece - Plant Mechanic	1.50	Chk over machine.
25/05/2013	Dawson, Dale - TWC Mechanic	1.00	4460HRS: R & R blade tilt hoses, drill out broken bolts from hose mount clamps./ R & R muffler box.
26/05/2013	Dawson, Dale - TWC Mechanic	2.50	4460HRS: R & R blade tilt hoses, drill out broken bolts from hose mount clamps./ R & R muffler box.
01/06/2013	Griffin, Reece - Plant Mechanic	1.00	Install rear door on machine.
04/06/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	4460HRS: Chk over & price parts.
08/06/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove cover & step from hyd. tank.
11/06/2013	Dawson, Dale - TWC Mechanic	2.50	4460HRS: Fit rear step assy, fit new floor mat to cab.
11/06/2013	Knapman, Kenneth - TWC MECHANIC	9.50	Straighten hyd. tank shroud ladder, cut off top skid plate./ Weld repairs to hyd. tank shroud.
12/06/2013	Knapman, Kenneth - TWC MECHANIC	2.00	Straighten hyd. tank shroud ladder, cut off top skid plate./ Weld repairs to hyd. tank shroud.
18/06/2013	Knapman, Kenneth - TWC MECHANIC	4.50	Repairs to ladder & door of hyd. shroud, deliver to be sand blasted & repainted.
03/07/2013	Griffin, Reece - Plant Mechanic	0.50	Chk lights.
04/07/2013	Dawson, Dale - TWC Mechanic	0.50	Start machine to charge batteries.
14/07/2013	Griffin, Reece - Plant Mechanic	2.00	Install hyd. guard.
29/08/2013	Dawson, Dale - TWC Mechanic	1.50	4527HRS: 500hr service.
29/08/2013	Griffin, Reece - Plant Mechanic	1.50	4527HRS: 500hr service./ Chk over unit.
04/09/2013	Griffin, Reece - Plant Mechanic	1.00	4527HRS: 500hr service./ Chk over unit.
12/09/2013	Dawson, Dale - TWC Mechanic	0.50	Refit pin from blade arm to blade & new retainer.
21/09/2013	Griffin, Reece - Plant Mechanic	1.50	4760HRS: Complete 250hr service.
01/10/2013	Dawson, Dale - TWC Mechanic	0.50	Drillout broken bolts on blade tilt ram cover & refit ram cover to ram & fit new bolts. 1hr
20/10/2013	Griffin, Reece - Plant Mechanic	1.00	5000HRS: Service eng. & hyd system, take SOS's, Replace cab & air filters 2hrs.
04/11/2013	Griffin, Reece - Plant Mechanic	1.00	Drop belly guard.
11/11/2013	Caccianiga, Gary I	5.50	5020HRS: Warm up machine for service and carry out 1,000Hr service..
11/11/2013	Griffin, Reece - Plant Mechanic	1.00	5020Hrs: Assist with service.
11/11/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	5020Hrs: Fit belly guard & load onto float.
25/11/2013	Dawson, Dale - TWC Mechanic	0.50	Locate fault with a/c. Evaporator freezing up - parts ordered./ 5132HRS: R & R receiver dryer & the
25/11/2013	Griffin, Reece - Plant Mechanic	0.50	Locate fault with a/c - freezing up, new thermostat ordered./ Repair a/c - R & R receiver dryer, t
26/11/2013	Dawson, Dale - TWC Mechanic	1.00	Locate fault with a/c. Evaporator freezing up - parts ordered./ 5132HRS: R & R receiver dryer & the
26/11/2013	Griffin, Reece - Plant Mechanic	1.00	Locate fault with a/c - freezing up, new thermostat ordered./ Repair a/c - R & R receiver dryer, t
03/12/2013	Dawson, Dale - TWC Mechanic	0.50	5170HRS: Chk over machine, inspect scraper blade edges.
03/12/2013	Griffin, Reece - Plant Mechanic	0.50	5170HRS: Inspect over machine
17/12/2013	Wilde, David - TWC WORKSHOP MANAGER	5.00	5237HRS: remove guards & wash down./ Part service. Wash down & clean out cab & windows.
18/12/2013	Wilde, David - TWC WORKSHOP MANAGER	5.00	5237HRS: remove guards & wash down./ Part service. Wash down & clean out cab & windows.
06/01/2014	Caccianiga, Gary I	2.50	5238HRS: 250hr service./ Fit up belly guards.
06/01/2014	Griffin, Reece - Plant Mechanic	2.00	5235HRS: Remove & strip down blade tilt ram./ Reseal & refit tilt ram to machine
06/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	5238HRS: Look up & order parts.
07/01/2014	Caccianiga, Gary I	2.00	5238HRS: 250hr service./ Fit up belly guards.
07/01/2014	Griffin, Reece - Plant Mechanic	2.00	5235HRS: Remove & strip down blade tilt ram./ Reseal & refit tilt ram to machine
09/01/2014	Caccianiga, Gary I	2.00	Change over belts, idler pulley & tensioner.

Date	Name	Duration	Notes
26/02/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Chk over machine, set up O'size signage on escort vehicle.
28/02/2014	Dawson, Dale - TWC Mechanic	1.00	5254HRS: Chk eng. fault code - Turbo inlet pressure switch U/S.
01/03/2014	Dawson, Dale - TWC Mechanic	1.00	Chk over, test operation, inspect GET etc.
18/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
19/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
20/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	5327HRS: Clean out air & cab filters.
20/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
21/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
22/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
23/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
23/03/2014	Dawson, Dale - TWC Mechanic	0.50	Tighten loose scraper bar.
24/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
25/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
26/03/2014	Griffin, Reece - Plant Mechanic	0.50	Prestart/FGR
08/04/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	5,500HRS: part service./ Chk & repair fuel leak. Complete 500hrs service.
09/04/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	5,500HRS: part service./ Chk & repair fuel leak. Complete 500hrs service.
15/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Sake SOS front & rear diff & hyd. Fill out forms.
02/07/2014	Caccianiga, Gary I	7.00	5750HRS: 250hr service. R & R rear door handle on engine bay. R & R 2way & radio aerials. R & R air
02/07/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	5750HRS: Service.
23/07/2014	Caccianiga, Gary I	1.00	Remove R/H side hyd. door & remove CH brake light.
23/07/2014	Knapman, Kenneth - TWC MECHANIC	4.50	Remove hyd. tank door hinge & remanufacture hinge.
23/07/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove hyd. tank for repairs. Look up & order parts.
24/07/2014	Caccianiga, Gary I	1.50	5744HRS: Fit R/H side door & new brake light.
10/09/2014	Caccianiga, Gary I	2.00	Repair R/H rear step. Repair lights.
20/10/2014	Dawson, Dale - TWC Mechanic	1.50	5,744HRS: Remove exhaust, complete eng. valve set as per specs./ Finish valve set, fit tappet cover
21/10/2014	Dawson, Dale - TWC Mechanic	2.50	5,744HRS: Remove exhaust, complete eng. valve set as per specs./ Finish valve set, fit tappet cover
21/10/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Refit fire ext. & chk lights.
14/11/2014	Dawson, Dale - TWC Mechanic	0.50	Refit pin into blade arm & refit retainer bolt.
15/11/2014	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
18/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prime fuel system.
26/11/2014	Caccianiga, Gary I	1.00	Take SOS & chk over.
29/11/2014	Caccianiga, Gary I	4.00	5971HRS: 2,000hr service./ R & R hyd., oil, fuel & a/c filters.
01/12/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Take a/c oil sample.
02/12/2014	Caccianiga, Gary I	0.50	5971HRS: 2,000hr service./ R & R hyd., oil, fuel & a/c filters.
02/12/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	6000HRS service - complete service.
04/12/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over & test run./ R & R fuel switch.
05/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk over & test run./ R & R fuel switch.
05/01/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	6107HRS: Refit grille
09/01/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	CHK rear diff isolation bushes. Load onto float. Look up & order parts.
10/01/2015	Dawson, Dale - TWC Mechanic	4.50	Remove belly plates, clean dirt from rear diff. Remove front & rear diff carrier/trunions due to be
15/01/2015	Dawson, Dale - TWC Mechanic	7.00	Remove trunion carrier from diff & strip down, clean all parts, reassemble carrier with new bearing
16/01/2015	Dawson, Dale - TWC Mechanic	5.00	Remove trunion carrier from diff & strip down, clean all parts, reassemble carrier with new bearing
17/01/2015	Dawson, Dale - TWC Mechanic	1.50	Remove trunion carrier from diff & strip down, clean all parts, reassemble carrier with new bearing
31/01/2015	Caccianiga, Gary I	0.50	6,162HRS: Repair fault in a/c.
31/01/2015	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
31/01/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Locate & repair electrical fault in a/c.
10/02/2015	Caccianiga, Gary I	1.00	6254HRS: 250hr service.
10/02/2015	Wilde, David - TWC WORKSHOP MANAGER	3.00	6,2502HRS: Service. Complete SOS & fill oil bottles.
13/02/2015	Dawson, Dale - TWC Mechanic	1.00	Prestart/FGR
14/02/2015	Caccianiga, Gary I	0.50	Repair handrail.
14/02/2015	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
23/02/2015	Knapman, Kenneth - TWC MECHANIC	2.00	Chk cooling system & organise water pump. 6,370HRS: Remove guards & belts etc. to access water pump
23/02/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk coolant leak. Look up & order parts. Remove water pump./ Chk & tighten radiator hoses.
24/02/2015	Knapman, Kenneth - TWC MECHANIC	6.50	Chk cooling system & organise water pump. 6,370HRS: Remove guards & belts etc. to access water pump

Date	Name	Duration	Notes
25/02/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Tighten radiator/water pump hoses.
25/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk coolant leak. Look up & order parts. Remove water pump./ Chk & tighten radiator hoses.
28/02/2015	Caccianiga, Gary I	2.50	Change out radiator hoses
06/03/2015	Caccianiga, Gary I	0.50	R & R flashing light.
06/03/2015	Dawson, Dale - TWC Mechanic	2.00	Instal new flashing light to bar install. / Load frame onto ute, travel to jobsite & fit frame guar
09/03/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Remove hyd. tank guard & blow out radiators.
09/03/2015	Knapman, Kenneth - TWC MECHANIC	3.00	Repair crack in hyd. tank guard.
09/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	CHK & remove hyd. tank guard for repairs.
10/03/2015	Dawson, Dale - TWC Mechanic	1.00	Instal new flashing light to bar install. / Load frame onto ute, travel to jobsite & fit frame guar
17/03/2015	Dawson, Dale - TWC Mechanic	3.00	6,492HRS: 500hr service.
11/05/2015	Caccianiga, Gary I	0.50	R & R batteries.
11/05/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	6,578HRS: R & R batteries, test run.
04/06/2015	Caccianiga, Gary I	1.00	Chk over machine & order parts.
05/06/2015	Caccianiga, Gary I	5.00	Repairing oil leaks, remove steer cylinders & reseal.
05/06/2015	Dawson, Dale - TWC Mechanic	1.00	Remove steer rams.
09/06/2015	Caccianiga, Gary I	5.00	Fit steer cylinders. R & R hyd. hose, clean down machine.
09/06/2015	Wilde, David - TWC WORKSHOP MANAGER	4.50	6,594HRS: R & R leaking hyd. hose. Refit 2 steering cylinders. test run & clean down.
26/08/2015	Caccianiga, Gary I	1.00	6,741HRS: 250hr service & chk over.
26/08/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	6,750HRS: Service.
07/09/2015	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
11/09/2015	Dawson, Dale - TWC Mechanic	4.50	6,8447HRS: T'shoot/locate fault with a/c - R & R dryer, vac down & charge system, test operation. R
04/01/2016	Caccianiga, Gary I	6.50	Wash machine, commence 1,000hr service, repair steps.
04/01/2016	Dawson, Dale - TWC Mechanic	2.00	Repair short circuit in horn.
04/01/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	7,000Hrs service. Chk movement int steering pins. Look up & order parts.
05/01/2016	Caccianiga, Gary I	5.50	Remove air cleaner & refit. Remove broken bolts in belly guard.
05/01/2016	Dawson, Dale - TWC Mechanic	6.00	Repaired install new horn brush assy to teer column. Remove floor mat assy, clean & wash 7 refit. R
05/01/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Fill out SOS's, Clean out belly guards, locate parts.
06/01/2016	Dawson, Dale - TWC Mechanic	1.50	Install new steer rod bushes & pins, clean cab.
07/01/2016	Caccianiga, Gary I	2.00	Fit grease line & repair R/H steering grease pin. Fit belly guard.
05/02/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart & fuel up. Load onto float.
09/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
10/03/2016	Dawson, Dale - TWC Mechanic	1.00	R & R fanbelt on engine.
22/05/2016	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
25/05/2016	Dawson, Dale - TWC Mechanic	1.00	Prestart/FGR
31/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	7,168HRS: Prestart/FGR
02/06/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
28/07/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
29/07/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
30/07/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	7,250HRS: Service & clean out cab.
31/07/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
01/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
09/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
10/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
11/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
12/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
13/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
14/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
15/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
16/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
25/08/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Prestart/FGR
26/08/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Prestart/FGR
27/08/2016	Dawson, Dale - TWC Mechanic	0.50	Repairs to seat - not pumping up.
30/08/2016	Dawson, Dale - TWC Mechanic	0.50	Chk over & grease machine.
26/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR

Date	Name	Duration	Notes
28/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
29/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
30/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
31/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
31/10/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	7,500Hrs service.
01/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
02/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
03/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
04/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
06/11/2016	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
07/11/2016	Dawson, Dale - TWC Mechanic	0.75	Prestart/FGR
09/11/2016	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
10/11/2016	Dawson, Dale - TWC Mechanic	1.00	Prestart/FGR
11/11/2016	Dawson, Dale - TWC Mechanic	1.00	Prestart/FGR
17/11/2016	Knapman, Kenneth - TWC MECHANIC	1.50	Turn cutting edge & replace corner tips. Chk grease line to R/H rear steering cylinder.
20/11/2016	Knapman, Kenneth - TWC MECHANIC	6.50	Change mud scrapers. Change cab filters.
17/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	7,625HRS: Pressure test Trans., chk grease lines.
17/01/2017	Knapman, Kenneth - TWC MECHANIC	1.50	7,625HRS: Transmission pressure checks - all test ok.
18/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.25	Chk & clean out grease points. Blow out a/c filters, cab & coolers.
18/01/2017	Knapman, Kenneth - TWC MECHANIC	3.50	Remove steering pin. Clean bush, grease track & pin. Reassemble & grease machine.
23/01/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Straighten step.
30/03/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	7,634HRS: Replace rear step.
01/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	Chk noise in R/H rear wheel.
03/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
05/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
09/04/2017	Dawson, Dale - TWC Mechanic	1.00	R & R fuel transfer pump - leaking.
11/04/2017	Dawson, Dale - TWC Mechanic	1.00	7,750HRS: 250hr service.
19/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	7,758HRS: Prestart.
20/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
23/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.25	Prestart. Chk low fuel pressure fault.
23/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Compact bank.
24/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
24/04/2017	Wilde, David - TWC WORKSHOP MANAGER	5.50	Chk start fault, chk wiring & remove ECM.
27/04/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Refit ECM & test reun.
02/05/2017	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR.
05/05/2017	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
11/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
12/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
13/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
14/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
15/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
16/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
17/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
17/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	8,000HRS: part service.
25/05/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,000HRS: Part service.
25/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
28/05/2017	Dawson, Dale - TWC Mechanic	3.00	8,000HRS: Complete trans. oil change & all filters, fill out SOS as part of 8,000hr service. Diff o
02/06/2017	Knapman, Kenneth - TWC MECHANIC	2.00	Change diff oils & dispose of used oil.
28/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,250HRS: Partial service.
29/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,250HRS: Complete service.
02/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk trans oil leaks & order parts.
03/07/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace test fittings on Trans. valve.
20/07/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Follow up on seat parts.
21/07/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	110,451Km: Chk & adjust tyre pressures. Chk springs & rockers. Repair 1 tyre. Replace grease nippl

Date	Name	Duration	Notes
23/07/2017	Dawson, Dale - TWC Mechanic	1.00	Chk over machine & chk scraper bars.
04/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk service codes & oil leaks.
02/11/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,412HRS: Remove steering pin & clean out grease track. Refit pin & grease.
13/11/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Blow out coolers & radiator.
14/11/2017	Dawson, Dale - TWC Mechanic	1.50	Investigate a/c fault - found dryer U/S, evac. system, R & R dryer, vac down & charge system - test
24/11/2017	Dawson, Dale - TWC Mechanic	1.00	8,520HRS: Complete 500hr (8,500hr) service.
25/11/2017	Dawson, Dale - TWC Mechanic	1.00	Finalise 500hr service, clean out scraper & chk adjustment.
11/12/2017	Dawson, Dale - TWC Mechanic	0.50	Organise parts for a/c repair.
11/12/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk a/c operation & replace fan motors. Chk wiring to compressor.
12/12/2017	Dawson, Dale - TWC Mechanic	5.50	8,640HRS: Evac a/c, R & R a/c compressor, vac down system & recharge - test ok. A/c failure again -
14/12/2017	Dawson, Dale - TWC Mechanic	4.50	Inspect/investigate a/c failure - found system has blown hose between compressor & condensor. Remov
19/12/2017	Dawson, Dale - TWC Mechanic	2.50	Remove blown hose from blade circuit, take to Narrabri supplier for new hose, return to site & inst
13/01/2018	Dawson, Dale - TWC Mechanic	1.00	8,750HRS: 250hr service.
29/01/2018	Dawson, Dale - TWC Mechanic	2.00	Remove rear diff pivot trunions.
30/01/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts.
30/01/2018	Dawson, Dale - TWC Mechanic	0.50	Remove & inspect diff trunions.
30/01/2018	Dawson, Dale - TWC Mechanic	1.00	Remove drive shafts.
31/01/2018	Knapman, Kenneth - TWC MECHANIC	3.00	Attemp to remove driveline centre bearing.
02/02/2018	Knapman, Kenneth - TWC MECHANIC	8.50	Remove drive line from centre bearing & clean up parts. Remove universals. make plates to press in
06/02/2018	Knapman, Kenneth - TWC MECHANIC	6.00	Assemble front drive shaft centre bearing assy. Fit to machine. Fit front section of drive line to
07/02/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repairs to drive line.
08/02/2018	Knapman, Kenneth - TWC MECHANIC	9.00	Install pinion housing, set pinion backlash. Fit trunion assy.
08/02/2018	Wilde, David - TWC WORKSHOP MANAGER	9.00	Refit pivot cross member & pinion housing. Look up & order parts.
09/02/2018	Dawson, Dale - TWC Mechanic	3.00	Install drive shafts, trunion bolts & tension all bolts.
12/02/2018	Dawson, Dale - TWC Mechanic	1.00	Evac a/c system for replacement of hoses.
12/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R a/c hoses & condensor.
14/02/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Connect a/c guages & refill system with nitrogen to chk for leaks.
14/02/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Evac a/c system. Recharge & test run. Chk for leaks.
16/02/2018	Dawson, Dale - TWC Mechanic	2.50	Pressure test torque converter & test full engine RPM & performance.
16/02/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk trans. leaks & replace seal under valves.
19/02/2018	Dawson, Dale - TWC Mechanic	4.50	Remove fan hub for re-racing. Refit fan & guards.
20/02/2018	Dawson, Dale - TWC Mechanic	4.50	Install guards, panels & belly plates etc. Re-fit cab seat & guards.
21/02/2018	Dawson, Dale - TWC Mechanic	3.00	Remove blade lift hyd. cylinder, strip down & reseal.
14/03/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk brake fault & test hyd. pressures.
16/03/2018	Dawson, Dale - TWC Mechanic	1.50	Investigate park brake fault. Charge service brake system accumulator - test operation.
18/07/2018	Dawson, Dale - TWC Mechanic	2.50	Complete trans. performance test stall & pressure test on t/convertor.
08/10/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Replace fuel bleed switch.
17/10/2018	Dawson, Dale - TWC Mechanic	1.00	9,000HRS: Complete part of 1,000hr service.
19/10/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	9,000HRS: Service & complete SOS.
06/11/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	9,095HRS: Replace steering valve & eng. bay door catch. order parts.
13/11/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Replace door handle & striker.
15/11/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Unload from float & chk for active fault codes.
16/11/2018	Knapman, Kenneth - TWC MECHANIC	7.00	Prep machine for cleaning. Remove rear screper bar assy for weld repair. Repair & replace bar. Chk
21/11/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Collect parts & fit new LED brake light.
14/03/2019	Wilde, David - TWC WORKSHOP MANAGER	3.50	Part wash down.
15/03/2019	Wilde, David - TWC WORKSHOP MANAGER	6.50	9,105HRS: Wash down, clean out cab, repair flashing light wiring.
16/03/2019	Knapman, Kenneth - TWC MECHANIC	3.00	Straighten & fit belly guards.
16/03/2019	Wilde, David - TWC WORKSHOP MANAGER	4.50	9,105HRS: Refit belly guards, chk drive train & prestart.
31/03/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk handbrake control.
11/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk charging system & repalce batteries.
12/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	9,214HRS: Remove alternator, repair & refit to machine. Test run.
15/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	9,250HRS: Service.
14/06/2019	Dawson, Dale - TWC Mechanic	1.00	Partially complete 500hr service.
15/06/2019	Dawson, Dale - TWC Mechanic	2.50	R & R turbo to muffler exhaust pipe adaptor.

Date	Name	Duration	Notes
20/06/2019	Dawson, Dale - TWC Mechanic	1.50	9,551HRS: R & R fuel level tank sensor. Grease unit.
20/06/2019	Dawson, Dale - TWC Mechanic	0.50	Take diff SOS
20/07/2019	Dawson, Dale - TWC Mechanic	2.00	9,707HRS: R & R park brake accumulator.
03/08/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & remove belt tensioner pulleys. Order & pick up parts.
04/08/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	9,744HRS: Replace belt tensioner & idler pulleys & belt. Test run.
04/08/2019	Knapman, Kenneth - TWC MECHANIC	2.00	Replace fan idlers.
05/08/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	9,750HRS: Service.
13/08/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Replace isolator.
22/08/2019	Dawson, Dale - TWC Mechanic	1.50	R & R V belt tensioner.
05/09/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Remove matting & blow out cab.
05/09/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & repair E stop.
18/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
10/10/2019	Wilde, David - TWC WORKSHOP MANAGER	0.25	Prestart/FGR
06/01/2020	Wilde, David - TWC WORKSHOP MANAGER	2.50	10,000HRS: Part service.
15/01/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Move machine to washbay & remove belly guard.
15/01/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove belly guards & part wash down.
17/01/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	Complete service. Chk electrical faults.
20/01/2020	Knapman, Kenneth - TWC MECHANIC	4.00	Remove broken studs. Weld repair to guard. Remove door for weld repair. Take to door Hardmans for f
20/01/2020	Wilde, David - TWC WORKSHOP MANAGER	3.50	10,029HRS: Replace oil pressure sender. Refit belly guards. Blow out radiators & coolers.
21/01/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Weld repair door catch.
06/02/2020	Knapman, Kenneth - TWC MECHANIC	2.50	Remove R/H steer cylinder & replace rear bearing & shaft. Replace cylinder & grease.
06/02/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair to steering pin and ram
15/02/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove a/c compressor & clean out system. Refit compressor, recgarhe & test.
18/02/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Manufacture GPS mounting bracket.
18/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk park & brake specs. Look up & order parts.
19/03/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	10,064HRS: prestart. Chk accumulator pressure, test brakes & park brake. Chk hyd. pressures.
21/03/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Clean dirt from wheels & part wash down.
23/03/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Refit belly guards.
25/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R muffler & brackets.
27/03/2020	Knapman, Kenneth - TWC MECHANIC	6.00	Fit exhaust/turbo systems & air cleaner.
27/03/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	Assemble exhaust system. Clean up parts. Test run.
30/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Adjust wheel scrapers.
31/03/2020	Knapman, Kenneth - TWC MECHANIC	3.00	Remove steering cylinder, remove clean & replace bush with new seals, Weld on tank.
31/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.50	10,062HRS: Remove & clean out steering bush & replace seals. re-assemble & grease. Order parts.
01/04/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	10,062HRS: Prestart & load onto float.
16/07/2020	Wilde, David - TWC WORKSHOP MANAGER	4.00	10,416HRS: R & R front wiper motor. Clean out a/c evaporator.
28/07/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Remove battery cable & replace terminal connection(s).
29/07/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Fit battery lead.
20/08/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Chk for axle pivot mount wear.
21/08/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Acquire fittings for blade cylinder & deliver shaft to McManus for reman.
25/08/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Assist with repairs to fuel tank mount.
02/09/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Fit blade cylinder.
02/09/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit tilt ram & guard.
04/11/2020	Wilde, David - TWC WORKSHOP MANAGER	2.50	10,436HRS: Prestart & grease. Replace speed sensor & down shift switch. Look up & order parts.
05/11/2020	Knapman, Kenneth - TWC MECHANIC	2.00	Replace speed sensors & refuel.
05/11/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	10,436HRS: Look up & order parts, collect. Repair speed sensor threads. test run & clean out cab.
22/03/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Repair door latch & deliver door to Hardmans for window replacement.
29/03/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Replace windscreen wiper and washer pump. Replace battery step. Pick parts up as required
06/05/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Replace warning stickers
10/05/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	10,438Hrs. Check over and grease
11/05/2021	Knapman, Kenneth - TWC MECHANIC	4.50	Prestart. Fuel. Adjust engine bay. Load onto #289 for transport to Gurley Creek. Escort to site. Re
12/05/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove and replace seat belt assem
26/06/2021	Wilde, David - TWC WORKSHOP MANAGER	4.00	10,500Hrs service. Check over and grease. Fill out SOS samples
28/06/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	10,550Hrs. Replace horn button and cab light bulb. Repair wiring.

282 - Service History

<u>Date</u>	<u>Name</u>	<u>Duration</u>	<u>Notes</u>
29/06/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	10,560Hrs. Check fuel fault and test run. Show operator where grease nipples are
10/07/2021	Wilde, David - TWC WORKSHOP MANAGER	4.00	10,500Hrs. Check over and grease. Fill out SOS samples
13/07/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	10,615Hrs. Check fault codes. Check over
17/07/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	10,620Hrs. Check fault and repair e stop. Replace throttle control and test run
		<u>771.50</u>	
	TOTAL	<u><u>771.50</u></u>	

Total 282 - Cat 815F Compactor:282E

TOTAL