2007 Man Truck - Rego VDX431 purchased 23/4/2007 16/06/18 Updated Certificate of Modification. Certificate No. 997327

Maintenance

29/05/18

Normal Hour Service Carried out

Normal Hour	Service Carried out
27/6/2009	24 021 km conord comics
27/6/2008 11/3/2010	24,931km general service
28/3/2011	43,000km general service Front wheel alignment
6/6/2012	Rego check Sheaffe Motors
21/7/2012	76,890km service by Southside Agencies
25/6/2014	101,771km service by Southside Agencies
11/6/2015	Carry out C Service at 110,522km by Southside Truck Centre
15/05/18	Southside Truck Centre - Carry out D Service 160,795
17/06/2019	Ian Huntley – Carry out service
08/09/2020	Ron Southon Pty Ltd – 5000hr Service at 204,142km
00/07/2020	Kon Southon I ty Eta 5000m Service at 201,112km
Repairs	
25/5/2010	Repair fuel leak
28/3/2011	Diff lock switch staying on repaired
21/3/2012	Repair trailer plug wiring and check air conditioning
5/6/2012	Repair auger (Max Graham)
27/6/2012	Supply control module
25/7/2012	Repair wiring, starter motor, alternator
26/7/2012	Fit injector control module
21/8/2012	Make seat cover for centre seat
19/9/2012	New switch box, repair wiring and fix radio
30/10/2012	8 new tyres
11/11/2012	Repair broken uni joint
31/1/2013	New truck isolator
1/6/2013	Repairs to truck Max Grahams
4/7/2013	Repairs to truck Max Grahams
27/8/2013	Repairs to truck Southside Truck Centre
12/9/2013	Repairs to truck Max Grahams
12/10/2013	New foot brake valve
25/10/2013	New clamps and couplings for blow out hose
30/10/2013	Fittings for diesel pump
31/10/2013	New blow out hose clamps
6/11/2013	Fix turbo leak and new fuel tank breathers
7/11/2013	Install new fittings to diesel pump
10/10/2014	Bearings for Auger
12/5/2015	Starter relay repair
22/6/2015	Comfort shift repaired
28/11/2015	Fix noise in engine
30/5/16	New tyres
3/6/2016	Carry out pre rego check over
4/8/16	Remove, extend and refit fuel tank, shock mounts for drive axles and fit new man shocks
5/8/16	Extend chassis approx. 2m double rail and fit ring feeder and lift lazy axle
15/12/16	Supply, fit and plum up oil cooler to truck
23/1/17	Wire up explosive speck cooler fan
24/3/17	Change original spec gel pump
25/5/17	Ian Huntley – pre rego check, fix wiper blade, taillight bulb
C/10/2017	DCI International management of MDII
6/10/2017	DGI International – remove and fit MPU contents gauge
21/05/18	Southside Truck Centre – Check and Repair second steer tyre & Supply and fit new UHF

Southside Truck Centre – Supply 4 x Reflectors

30/05/18	Southside Truck Centre – Supply Red ylw Mark Plts 150x600 Pair
31/05/18	Southside Truck Centre – Syntrax Longlife 75W-90 20L (Gear Oil to go with "D" Service)
18/07/18	Summerland Tool Supplies – Tools for Truck; Drill Set, Hammer Drill Driver Kit, Screwdriver
	Set, Spanner Set & Socket Set
30/07/18	Southside Truck Centre – Check and Repair Exhaust Brake Faults on Dash
21/09/2018	Southside Truck Centre – Check and repair vehicle speedo not working
31/10/2018	Southside Truck Centre – Install new wiper motor, check lighting issues on truck, check and
	replace ABS plug for trailer
01/11/2018	DGI International – Supply pressure comp, flow control valve, free reverse, hyd fitting
14/02/2019	Ian Huntley – Change air-con filter
17/06/2019	Southside – Supply Fuel Filter, Oil Filter, Filter Element, Strainer Jacket Filter, Air Filter
	Element & LED ultima driving light pack
24/06/2019	Southside – Sublet repairs carried out for Tachograph issue, Remove and replace ABS/EBS
	plugs, order new door module for fault codes, check and repair PTO pump leaking, check and
	repair truck and trailer lights not working.
19/08/2019	Southside – Replace ring feeder
19/08/2019	Southside – Check and Repair; low coolant alarm going off, check alternator light on dash still
	charging ok, check and repair cab tilt lock light on dash, check and repair bulbar park lights,
	check out issue with drivers mirror
03/09/2019	Southside – Alternator core depositor
22/10/2019	Acacia Ridge Container Park – Internal wash out
23/10/2019	Nth Coast Dustless Blasting – Abrasive blast of interior of tank
30/10/2019	Staunch Window Tinting – Supply and Fit window tint
31/10/2019	Swift Autoglass – Replace front windscreen
01/11/2019	A Special Touch – Clean and Prepare emulsion tanks for painting inside and out, Prime 1 x coat,
	Paint 2 x coats
11/11/2019	DGI International – Prepare and reweld effected weld joints on the inside and outside of tank,
	Remove and refit belly auger, replace auger bushes.
29/05/2020	Southside Truck Centre – check for coolant leak and fix
26/08/2020	Southside Trucks – Call out for Air supply to cab Issue (Clutch Hard)
27/01/2021	Southside Trucks – Check Issue with Engine Miss
28/05/2021	Southside Trucks – Check and repair defects as per list
24/08/2021	Southside Trucks – Check Oil leak at turbo
26/10/2021	Southside Trucks – Engine oil leaks, turbo and front of engine
12/10/2022	Southside Truck Centre – Check & rectify coolant leak
21/03/2023	Southside Trucks – Repair low pulling power/turbo issue. Replace turbo impeller
18/04/2023	Southside Trucks – Repair exhaust flex pipe leaks
26/06/2023	Southside Trucks – Repair coolant in engine oil issue, check exhaust leaks, fuel leak 6 injector
18/07/2023	Southside Trucks – Defect repairs, axel 4 brakes not working