

Vehicle History Summary



Fleet #	4A
Registration	SY28FK
Make	MAXITRANS
Model	Lead Trailer
VIN / Chassis #	6F8T250001B061543
Build Date	2001

Date	Reading / Units	Type / Repairer Notes	Repairer
		air leak, Air Repairs R-5765	STEFS TRANSPORT
		curtain Damage, Fault R-5897	STEFS TRANSPORT
11/05/2026	3,300,317 kms	curtain Damage, Fault R-5874 Trailer to be sold	STEFS TRANSPORT
05/03/2026	3,300,317 kms	Trailer Inspection Report I-514	STEFS TRANSPORT
24/02/2026	3,300,317 kms	New Tyre T-4340	Azzas Tyres Nhill
17/02/2026	3,300,317 kms	curtain Handle R-5687 Fixed @ S-7360	STEFS TRANSPORT
16/02/2026	4,200,048 kms	B - 40k S-7360 Conducted B Service All checks OK Returned to service	STEFS TRANSPORT
24/12/2025	4,176,172 kms	A - 20k S-7273 Conducted A Service All checks OK Returned to service	Stef's Transport
23/12/2025	3,300,317 kms	Runout, Tyre Repair T-4265 slow leak pos 4 = new valve stem fitted runout fitted to pos 9	STEFS TRANSPORT
28/11/2025	3,300,317 kms	airbags R-5561 ATRailer REGO- SY28FK AIR BAGHANDRICKSON FITTING AIRBAG METAL LABOUR- REMOVE&REFITAIRBAG3RDAXLE Paid on Darryls card	One Stop Auto and Trucks
19/11/2025	3,300,317 kms	New Tyre T-4206 new sailun s637+ fitted to pos 5,6,7,8 854448km	STEFS TRANSPORT
12/11/2025	3,300,317 kms	Heavy Trailer Inspection Checklist I-473	STEFS TRANSPORT
11/11/2025	4,154,765 kms	C - Annual S-7077 Conducted C Service Replaced Pos 4 Shocker Replaced all brakes & Hardware Replaced all wheel bearings & Seals Replaced all pro torque nuts Replaced all hubcap gaskets Replaced 1 X 660 strap Returned to service	Stef's Transport
07/10/2025	4,137,597 kms	A - 20k S-7131 Conducted A Service All checks OK Return to service	STEFS TRANSPORT
30/09/2025	3,300,317 kms	curtain Handle, Curtain straps, Suzi leads R-5428 Replaced 5 curtain straps Repaired airlines to B / Trailer Replaced R/H/Front curtain handle Return to service	STEFS TRANSPORT
18/09/2025	3,300,317 kms	Trailer Inspection Report I-424	Stef's Transport

Date	Reading / Units	Type / Repairer Notes	Repairer
01/09/2025		Registration O-1870	Transport SA
27/08/2025	3,300,317 kms	Inspection T-4089 tyres are all ok	STEFS TRANSPORT
26/08/2025	3,300,317 kms	Trailer Inspection Report I-380	STEFS TRANSPORT
20/08/2025	4,115,021 kms	B - 40k S-7037 Conducted B Service Replaced Pos 5 Air Spring Return to service	STEFS TRANSPORT
20/08/2025	3,300,317 kms	Air Bag R-5297 Completed @ service 20/8/25	STEFS TRANSPORT
21/07/2025	3,300,317 kms	New Tyre T-4045 new doublestar dsr669 fitted to pos 1,2,3,4,11,12 runout fitted to pos 7	STEFS TRANSPORT
03/07/2025	4,086,954 kms	A - 20k S-6949 Conducted A Service Repaired wiring for front top lights Replaced 3 X 660 straps Returned to service	STEFS TRANSPORT
05/06/2025	3,300,317 kms	Trailer Inspection Report I-331	STEFS TRANSPORT
29/05/2025	4,068,171 kms	B - 40k S-6851 Conducted B Service Repaired 3 X Gates Returned to service	Stef's Transport
24/04/2025	3,300,317 kms	New Tyre T-3931 new doublestar dsr669 fitted to pos 9,10 slow leak repaired pos 8 9 x pressure check	STEFS TRANSPORT
26/02/2025	4,049,763 kms	A - 20k S-6716 Conducted A Service Repaired 1 X Gate Replaced Pos 1 & 4 Shocker Returned to service	STEFS TRANSPORT
26/02/2025	3,300,317 kms	Gate Repairs R-4954 Repaired @ Service 6716	STEFS TRANSPORT
31/01/2025	3,300,317 kms	Runout T-3830 runout to pos 12 pos 12 moved to pos 11	STEFS TRANSPORT
31/01/2025	3,300,317 kms	Trailer Inspection Report I-224	Stef's Transport
15/01/2025	3,300,317 kms	Gate Repairs R-4915 Removed 1st gate and replaced bolt in roller head Reinstalled gate, test ok Returned to service	STEFS TRANSPORT
07/01/2025	3,300,317 kms	Cracks R-4892 Removed Pos 1 Guard drilled and welded small crack L/H/Side above Pos 1 Tyres Returned to service	STEFS TRANSPORT
06/01/2025	3,300,317 kms	Runout T-3787 runout fitted to pos 2	STEFS TRANSPORT
06/01/2025	4,029,323 kms	B - 40k S-6640 Conducted B Service Adjusted T/Table Jaw Returned to service	STEFS TRANSPORT
13/11/2024	3,300,317 kms	Impact Damage R-4790 Removed L/H Landing leg bracket Straightened landing leg & welded bracket in place Returned to service	STEFS TRANSPORT
13/11/2024	4,009,327 kms	A - 20k S-6558 Conducted A Service Replaced toolbox latch Replaced 1 X Red/Amber side light Replaced Hazard boards L/H & R/H Sides Replaced 2 X Red Reflectors Repaired 1 X Gate Replaced Pos 1 Shocker Painted Top of Rear wall (Impact damage from B Trailer) Returned to service	STEFS TRANSPORT
21/10/2024	3,300,317 kms	Air Repairs R-4760 Replaced Male & Female bulkhead fittings for B Trailer supply	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
19/09/2024	3,300,317 kms	Runout T-3663 runouts fitted to pos 1,2	STEFS TRANSPORT
06/09/2024	3,989,662 kms	C - Annual S-6446 Conducted C Service Checked all brakes shoes for wear (Shoes are good to reuse) Replaced Brake hardware Replaced 1 X Red/Amber side light Replaced all pro-Torque nuts Replaced all wheel bearings & seals Replaced all hubcap gaskets Replaced Pos 1, 4 & 6 Shockers Replaced 1 X Number plate light Replaced 2.5M 1/2' brake hose Replaced 3 X S/Cams Replaced 3 X Z/Cams Replaced 6 X Cam tube seals Replaced 3 Bolt wear ring & Bolts Replaced 3 X 660 Straps Repaired 3 X Gates Returned to service	STEFS TRANSPORT
06/09/2024	3,300,317 kms	Heavy Trailer Inspection Checklist I-109	STEFS TRANSPORT
03/09/2024		Registration O-1418	Transport SA
15/08/2024	3,300,317 kms	Electrical R-4673 Remove and Replace 7 x Pin Trailer Plug	Callaway Diesel
27/06/2024	3,300,317 kms	New Tyre T-3587 new haulstar ha615 fitted to pos 9,10,11,12	STEFS TRANSPORT
27/06/2024	3,965,998 kms	A - Monthly S-6353 Conducted A Service All checks OK Returned to service	STEFS TRANSPORT
29/04/2024	3,300,317 kms	Air Bag R-4502 We have had to call out a mechanic to 4A this morning as it has done an air bag South of Goulburn (Haven't received invoice for this)	Sidhu Automobile Services
29/04/2024	3,945,259 kms	B - Bi Monthly S-6275 Conducted B Service Replaced Pos 5 shocker Returned to service	STEFS TRANSPORT
29/04/2024	3,300,317 kms	New Tyre T-3513 new doublestar fitted to pos 5,6 10 x pressure check	STEFS TRANSPORT
12/03/2024	3,300,317 kms	New Tyre T-3456 new haulstar ha 107 fitted to pos 3,4,7,8 runout fitted to pos 12 job done by graham	STEFS TRANSPORT
12/03/2024	3,924,818 kms	A - Monthly S-6182 Conducted A Service Replaced 1 X Male bulkhead fitting Returned to service	STEFS TRANSPORT
22/01/2024	3,906,217 kms	B - Bi Monthly S-6099 Conducted B Service All checks OK Returned to service	STEFS TRANSPORT
17/01/2024	3,300,317 kms	Runout T-3374 runout fitted to pos 7	STEFS TRANSPORT
06/12/2023	3,300,317 kms	Electrical R-4241 Replaced 7 Pin Female plug Replaced 1 side light Rewired R/H indicator	STEFS TRANSPORT
15/11/2023	3,887,275 kms	A - Monthly S-5985 Completed A service	STEFS TRANSPORT
10/10/2023	3,300,317 kms	New Tyre T-3223 Pos 7 & 8 NEW	STEFS TRANSPORT
10/10/2023	3,872,872 kms	B - Bi Monthly S-5913 Completed B Service	STEFS TRANSPORT
06/09/2023	3,856,783 kms	A - Monthly S-5787 Conducted A Service No parts required Returned to service	STEFS TRANSPORT
31/08/2023		Registration O-840	Transport SA

Date	Reading / Units	Type / Repairer Notes	Repairer
09/08/2023	3,300,317 kms	New Tyre T-3122 new haulstar ha107 tyres fitted to pos 9,10,11,12	STEFS TRANSPORT
02/08/2023	3,300,317 kms	Tyres R-3890 sorted on T-3122	STEFS TRANSPORT
18/07/2023	3,836,051 kms	C - Annual S-5682 Conducted C Service Replaced all 3 axles drum to drum Replaced all shockers X 6 Replaced O/Take signs replaced 4 red reflectors Repaired L/H/Curtain handle Replaced 3 Bolt wear ring & Bolts in T/Table Replaced 5 air bags Replaced height control valve Replaced 2 X Mud Flaps 13 X 24 replaced Pos 5 black 650 guard Replaced 3M of 1/2" air line Replaced all ply boards (7) Repaired inside front panel Replaced all brake boosters (6) Replaced Tru Shu,s X 6 replaced pro torque nuts X 6 Replaced auto slack adjuster Course Replaced pivot bushes X 6	STEFS TRANSPORT
17/07/2023	3,300,317 kms	Trailer Front & Rear Wall & Door Repairs R-3891 repaired at C service interval.	STEFS TRANSPORT
19/06/2023	3,300,317 kms	Electrical R-3814	D&N Truck Repairs
30/05/2023	3,300,317 kms	Runout T-3064 runout to pos 10	STEFS TRANSPORT
30/05/2023	3,816,971 kms	B - Bi Monthly S-5588 conducted B Service Repaired 1 X Gate latch. trailer Loaded	STEFS TRANSPORT
30/05/2023	3,300,317 kms	Gate Repairs R-3752 repaired at service	STEFS TRANSPORT
19/05/2023	3,300,317 kms	Gate Repairs R-3704 Upon investigation all gates were found to be working correctly. Suggest driver/loader pull the gate out to unlock fully before sliding. Replaced 4 X Ply boards	STEFS TRANSPORT
02/05/2023	3,803,665 kms	A - Monthly S-5441 Rewired RHS tail lights due to wiring failure Serviced, all ok	STEFS TRANSPORT
03/04/2023	3,300,317 kms	Body R-3601 Bar pushed back into position and secured	STEFS TRANSPORT
24/03/2023	3,784,876 kms	B - Bi Monthly S-5356 Conducted B Service Repair roof panel at rear Replace 1 X Hub cap gasket Pos 5 Replaced 1 X Number plate light Adjusted Pos 3, 4, & 5 bearings Repaired 1 X Gate	STEFS TRANSPORT
21/03/2023	3,300,317 kms	New Tyre T-2958 pos 29 (?) - Replaced tyre (Work done at Bridgestone Wingfield)	Trident
20/03/2023	3,300,317 kms	Curtain Repair R-3573 Swapped with second hand handle	STEFS TRANSPORT
27/02/2023	3,772,411 kms	A - Monthly S-5274 Conducted A Service Replaced Pos 3 brake booster	STEFS TRANSPORT
14/02/2023	3,300,317 kms	Gate Repairs R-3496 replaced pins in gate latch	STEFS TRANSPORT
09/01/2023	3,300,317 kms	Air Repairs R-3407 Replaced Pos 1 Brake booster Replaced 1.2 Meters of air line to pos 2 booster	STEFS TRANSPORT
05/01/2023	3,751,762 kms	B - Bi Monthly S-5150 Full rebuild completed - done on R-3376	STEFS TRANSPORT
05/01/2023	3,300,317 kms	New Tyre T-2809 10 x pressure check 2 x new tyres	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
30/12/2022	3,300,317 kms	Brake Repairs R-3376 Replaced all brake shoes (1016 shoes defective) replaced with Textar 1012 shoes Replaced all auto slack adjusters & balanced all boosters replaced Pos 1 s/cam tube Replaced Pos 1 S/Cam Replaced number plate light Replaced all s/cam seals Replaced T/Table wear ring Replaced Pos 2 & 4 Shockers	STEFS TRANSPORT
01/12/2022	3,747,627 kms	B - Bi Monthly S-5052 Conduct B service Replaced Pos 1 Shocker	STEFS TRANSPORT
01/12/2022	3,300,317 kms	New Tyre, Runout T-2760 3 X RUNOUTS POS 8,9,10 2 X TYRES POS 11,12	Goodyear
26/10/2022	3,300,317 kms	Electrical R-3130 Light plug is OK checked at service	STEFS TRANSPORT
26/10/2022	3,726,865 kms	A - Monthly S-4954 Conducted A Service No parts required	STEFS TRANSPORT
10/10/2022	6,600,634 kms	New Tyre T-2709 5 x new tyres	Goodyear
01/10/2022	3,300,317 kms	C Service R-3234 Finished off C Service	Garners Garage
01/10/2022	3,300,317 kms	Bearings R-3233 Replaced with New Bearings Replaced with new bearings Repacked S Cams	Garners Garage
16/09/2022	3,709,434 kms	C - Annual S-4826 conduct C Service Replaced all wheel Bearings Replaced all Pro torque nuts Replaced all hub cap gaskets Replaced all brake shoes Replaced Curtain ratchet gear R/H/Side Trailer height set at 459.3	STEFS TRANSPORT
13/09/2022	3,300,317 kms	Brake Repairs R-3032 In For C Service	STEFS TRANSPORT
30/08/2022		Registration O-535	Transport SA
20/08/2022	3,300,317 kms	Electrical R-3047 Travel to Breakdown at Archerfield BP Inspect leaking airlines Replace RHR booster airlines Diagnose lights not working Replaced A trailer light socket Clean connection 7 pin flat, corrosion on plug pins, secure harness	STT Mechanical
17/08/2022	3,691,100 kms	A - Monthly S-4738 Conduct A Service Replaced Number plate light All other checks OK	STEFS TRANSPORT
08/07/2022	3,673,434 kms	B - Bi Monthly S-4631 Conducted B Service Repaired Tail light wiring Replaced 1 X Number plate light replaced 1 X 24/30 brake booster replaced bulk head air fittings X 2	STEFS TRANSPORT
17/06/2022	3,300,317 kms	Curtain Repair R-2843 1 patching repair to left curtain Supply and fit 1 mounting block	U-Rippa
09/06/2022	3,657,294 kms	A - Monthly S-4535 conducted A service loaded	STEFS TRANSPORT
08/06/2022	3,300,317 kms	Pressure main T-2576	Goodyear
04/05/2022	3,300,317 kms	New Tyre, Runout T-2527	Goodyear
03/05/2022	3,637,028 kms	C - Annual S-4439 Conducted C Service Replaced all Brakes, locking nuts, hub cap gaskets, wheel bearings Repaired wiring rear R/H/Side lights	STEFS TRANSPORT
28/03/2022	3,623,911 kms	B - Bi Monthly S-4345 conducted B service all wheel bearings adjusted	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
28/03/2022	3,300,317 kms	Nose Cone R-2671 No repair required	
09/02/2022	3,602,154 kms	A - Monthly S-4240 conducted A service loaded	STEFS TRANSPORT
08/02/2022	3,300,317 kms	Runout T-2421	Goodyear
03/02/2022	3,300,317 kms	Electrical R-2621 replaced r/H/Rear indicator & replaced 1 X 660 Strap TSR Carry Out Repairs To A Trailer Tail Lamps Rebolt Both LHS And RHS Tail Lamps BAcK Onto Trailer Fit New Indicator Light To RHS Rear Tail Lamp Test All Lights All Test Ok	STEFS TRANSPORT, TSR - Transport Servicing and Repairs
10/01/2022	3,300,317 kms	Gate Repairs R-2576	STEFS TRANSPORT
10/01/2022	3,582,665 kms	B - Bi Monthly S-4155 Conducted B service Repaired 2 X Gates Trailers loaded	STEFS TRANSPORT
10/01/2022	3,300,317 kms	Gate Repairs R-2575	STEFS TRANSPORT
27/12/2021	3,300,317 kms	New Tyre T-2373	Goodyear
01/12/2021	3,561,887 kms	A - Monthly S-4096 Conducted A Service	STEFS TRANSPORT
01/11/2021	3,543,862 kms	B - Bi Monthly S-4013 conducted B service adjusted all wheel bearings found pos 3,4 and 5 lose so did all replaced reflectors x4 amber x1 air bag on poz 5 repaired x2 air lines	STEFS TRANSPORT
14/10/2021	3,300,317 kms	Gate Repairs R-2431 bent gate back to proper position x1 air bag on pos 3 and welded crack in turn table plate	STEFS TRANSPORT
14/10/2021	3,300,317 kms	Air Bag R-2432 Remove and replace Pos 4 air bag repair 1 X gate Weld turn table saddles L&R at front	STEFS TRANSPORT
12/10/2021	3,300,317 kms	Runout T-2262	Goodyear
24/09/2021	3,523,875 kms	A - Monthly S-3939 Carried Out A Service Replaced pos 1 shocker Replaced L/H/Rear mudflap 13X24 Replaced side indicator	STEFS TRANSPORT
03/09/2021	3,300,317 kms	Curtain Repair R-2376 Replaced ratchet gear	
26/08/2021		Registration O-409	Transport SA
19/08/2021		Gate Repairs R-2232 Repaired broken gates	STEFS TRANSPORT
19/08/2021	3,300,317 kms	Runout T-2217	Goodyear
19/08/2021	3,505,683 kms	B - 40k S-3840 Conducted B Service All checks OK	STEFS TRANSPORT
06/08/2021	3,498,128 kms	A - 20k S-3803	TSR - Transport Servicing and Repairs
24/06/2021	3,475,720 kms	C - Annual S-3724 Pos 4-5&6 bearings found to be loose. All brake cams lacked grease, Pos 2 brake defective, (Gone over centre)	Garners Garage
16/06/2021	3,462,165 kms	B - 40k S-3702	TSR - Transport Servicing and Repairs

Date	Reading / Units	Type / Repairer Notes	Repairer
31/05/2021	3,248,233 kms	Curtain Repair R-2167 Complete refurb of curtains, roof, tracks, re-paint and various alterations	Vawdrey Dandenong VIC
06/04/2021	3,445,462 kms	A - 20k S-3675	STEFS TRANSPORT
06/04/2021	3,248,233 kms	Gate Repairs, Ply Boards R-2050 x2 gates patch welded x4 ply boards added x2 660 strap and buckles Small pin for slack adjuster fitted Front panel re-attached RH curtain re-attached	3MP Millicent, STEFS TRANSPORT
02/04/2021	3,429,961 kms	B - 40k S-3678 Number plate light fixed	TSR - Transport Servicing and Repairs
24/03/2021	3,396,625 kms	New Tyre T-2074	Goodyear
22/03/2021	3,248,233 kms	Hose Damage R-2003	Krueger Derrimut Melbourne
11/02/2021	3,378,248 kms	Brake Repairs R-1896 Fitted x1 male/female GP fitting x1 female/male GP fitting	STEFS TRANSPORT
03/02/2021	3,248,233 kms	New Tyre T-2011	Beaurepaires AU
03/02/2021	3,375,289 kms	A - 20k S-3400 LHS middle axle inside needs tyre Repaired broken wire for LHS blinkers Fixed rubber line Welded gates LHS Replaced x2 female fittings	Garners Garage
28/01/2021	3,248,233 kms	New Tyre T-2000	Beaurepaires AU
04/01/2021	3,354,256 kms	B - 40k S-3326 B service C/O all satis P1, P3, P4 & P5 bearings adjsuted P3 airbag replaced P1 shocker replaced as was U/S booster lines to P6 booster replaced RH tail lights & stop lights rewired all satis wiring repaired above P6 booster 2x RH side lights rewired all satis airlines in between A & B repaired	STEFS TRANSPORT
14/12/2020	3,248,233 kms	New Tyre T-1957	Beaurepaires
10/12/2020	3,248,233 kms	New Tyre T-1956	Beaurepaires AU
08/12/2020	3,248,233 kms	Gate Repairs R-1799 gate track repaired by 3mp all satis 3x ply fitted 1x anti luce pin welded on for curtain ratchet handle new 7 pin plug fitted all satis	STEFS TRANSPORT
27/11/2020	3,334,688 kms	A - 20k S-3267 Faults Found On A Unit Air Bag Leaking Badly On RHS First Axle Remove And Replace Air Bag With New Repair Air Leak Between A And B Unit	TSR - Transport Servicing and Repairs
28/10/2020	3,315,644 kms	B - 40k S-3220 B service C/O all satis all bearings checked ok Various booster clamps replaced all satis	STEFS TRANSPORT
16/10/2020		Curtain Repair R-1702 Drivers side curtain slashed, temporarily repaired will need further repair @ Aerial tarps	Aerial Tarps Pty Ltd, STEFS TRANSPORT
21/09/2020	3,297,379 kms	A - 20k S-3161 A service C/O all satis air leaks repaired bronze valve repaired	STEFS TRANSPORT
21/09/2020	3,248,233 kms	New Tyre T-1844 4X 255/70R22.5 (REM) NEW TYRE'S PLACED AT POS 3-4-7-8 REPLACED BY BRENT	Beaurepaires
03/09/2020	3,248,233 kms	New Tyre T-1832 new tyre fitted at Bridgestone mildura	bridgestone
25/08/2020		Registration O-333	Transport SA

Date	Reading / Units	Type / Repairer Notes	Repairer
21/08/2020	3,248,233 kms	Runout T-1810 run out fitted to pos 6	Beaurepaires
21/08/2020	3,248,233 kms	Air Repairs, Gate Repairs R-1625 all tracks lubricated all satis P1 airbag replaced all satis gates repaired	STEFS TRANSPORT
13/08/2020	3,280,279 kms	B - 40k S-3091 B service C/O all satis bearings ok	STEFS TRANSPORT
04/08/2020	3,248,233 kms	T/Table R-1596 turn table jaws adjsusted \ new pull string fitted	STEFS TRANSPORT
21/07/2020	3,267,233 kms	A - 20k S-3030 A service C/O all satis	STEFS TRANSPORT
22/05/2020		Sat Tracker R-1450 New gps sat tracker fitted and old tracker removed all satis Small roof leaks sealed Marker light fitted to Rh rear	STEFS TRANSPORT
20/05/2020	3,248,233 kms	C - Annual S-2901 C service C/O all satis all bearings replaced All shockers replaced All brakes shoes replaced and fitted with tru shus all satis All 6x drums replaced All new bearing nut clips and hub gaskets P1 & P3 s cam's re shimmed and new grease seals fitted Both air lines replaced and GP fittings replaced Floor revealed Small hole in roof sealed	Garners Garage, STEFS TRANSPORT
04/05/2020		B - 40k S-2861 B service C/O all satis. P4 bearing adjusted others ok 1x curtain strap fitted and 1x amber reflector	STEFS TRANSPORT
27/04/2020		New Tyre T-1669 run out to pos 7 new tyres 11-12	
14/04/2020		Runout T-1642 1x 225/7022.5 RUN OUT TYRE PLACED AT POS 6 REPLACED BY BRENT	Beaurepaires
14/04/2020		Gate Repairs R-1376 All gates repaired all satis. Track lubed all satis	STEFS TRANSPORT
09/04/2020		A - 20k S-2790 A service C/O all satis.	STEFS TRANSPORT
11/03/2020		B - 40k S-2719 B service C/O all satis.	STEFS TRANSPORT
12/02/2020		New Tyre T-1554 4 NEW TYRES FITTED	Beaurepaires
11/02/2020		A - 20k S-2651 A service C/O all satis. \ all tyres pressure checked all satis. new 7 pin plug fitted to back of unit. 1x RH side marker light rewired all satis. 2x bolt on feet fitted to gates.	STEFS TRANSPORT
14/01/2020		B - 40k S-2583 B service C/O all satis. all bearings ok P4,P5 &P6 bearings adjusted all satis. marker plate fitted to RH rear of trailer to comply.	STEFS TRANSPORT
13/01/2020		Runout T-1499	Beaurepaires
14/12/2019		A - 20k S-2513 A service C/O all satis. all clamps gone over line between A & B repaired as was about to let go wheel nuts torqued where indicators had moved	STEFS TRANSPORT
22/11/2019		B - 40k S-2473 B service completed by garners all satis	STEFS TRANSPORT
28/10/2019		A - 20k S-2409	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
		A service C/O all satis. 1x side amrker light replaced 1x side marker light re wired all satis. various air leaks repaired & hose clamps ok all satis.	
10/10/2019		New Tyre T-1429	Beaurepaires
24/09/2019		B - 40k S-2350 B service C/O all satis various air leaks repaired	STEFS TRANSPORT
09/09/2019		Registration O-273	Transport SA
27/08/2019		A - 20k S-2277 A service C/O all satis. various air leaks repaired	STEFS TRANSPORT
26/07/2019		B - 40k S-2196 B service C/O all satis (bearings ok) RH stop lights fixed	STEFS TRANSPORT
11/07/2019		Gate Repairs R-964 gate tracks lubricated and roller on gate repaired	STEFS TRANSPORT
19/06/2019		A - 20k S-2105 all fine underneath no cracks washed trailers	NICK, STEFS TRANSPORT
10/06/2019		Gate Repairs R-923 repair curtains as well	TSR - Transport Servicing and Repairs, U-Rippa
08/06/2019		Gate Repairs R-936 Remove all rhs gates out of track, cut aluminium to shape and weld over stuffed part of track and pot rivet new gate stop in top of track, refit all gates.	STEFS TRANSPORT
06/06/2019		Gate Repairs, Tyres R-931 Remove 3 rhsides gates to fit gate and rollersback onto track, remove rhc brake backing platewhich was rubbing on drum,replace leaking air fitting on emergency valve , adjust brakes.	STEFS TRANSPORT
28/05/2019		Electrical R-916 Replace Lhand number plate light	STEFS TRANSPORT
20/05/2019		C - Annual S-2032 Carry out C service, replace king pin, measurements of axles Lhf inner 89.22 outer 66.35, Lhc inner 88.96 outer 66.27, Lhr inner 89.02 outer 65.93 Rhf inner 89.24 outer 66.52 , Rhc inner 89.19 outer 66.24 Rhr inner 89.01 outer 65.97	STEFS TRANSPORT
17/05/2019		Chassis R-899	South East Welding Services Pty Ltd
23/04/2019		B - 40k S-1974 NO faults found	TSR - Transport Servicing and Repairs
12/04/2019		Chassis R-833 grind back welds and weld up cracks,straightern rhr mudgaurd bracket, wash trailers	STEFS TRANSPORT
26/03/2019		A - 20k S-1915 A Trailer Faults LHS Number Plate Light Not Working, Spray Safe Missing Off First Axle RHS Guard, Slight Damage To Guard On Third Axle RHS Guard, Chassis Cracks	TSR - Transport Servicing and Repairs
08/03/2019		Electrical , Gate Repairs, Toolbox R-785 removed and replaced air bags so cookie could weld up cross member. welded up gates, straighten tool box door, straighten locks on gates, refitted lights on back of a trailer.	Garners Garage
04/03/2019		New Tyre T-1342 2 NEW FITTED TO POS 1-2	Beaurepaires
27/02/2019		B - 40k S-1860	TSR - Transport Servicing and Repairs

Date	Reading / Units	Type / Repairer Notes	Repairer
		A Trailer Reflector Missing RHS, LHS Number Plate Not Working, Spray Safe Missing RHS First Axle Guard, First Axle Inside Tyre Getting Low, Chassis Cracks LHS And RHS Front Of First Axle, Slight Wheel Bearing Movement All Axles	
16/02/2019		New Tyre T-1331 4 NEW FITTED	Beaurepaires
13/02/2019		Gate Repairs R-750 wash trailers, welded up broken gate, cut the old door lugs off.	
31/01/2019		A - 20k S-1791	TSR - Transport Servicing and Repairs
01/01/2019		Curtain Repair R-728 patch rip in curtain	U-Rippa
24/12/2018		B - 40k S-1719	TSR - Transport Servicing and Repairs
24/12/2018		Curtain Repair R-727 Travel to United Rocklea, 1 patching repair to right curtain re weld webbing replace part of 1 webbing strap	U-Rippa
27/11/2018		A - 20k S-1653 replace lhs rear air bags repair side light	STEFS TRANSPORT
09/11/2018		Ratchet R-678 replaced sprocket and bolted back together	STEFS TRANSPORT
31/10/2018		Runout T-1263 RUN OUT FITTED TO POS 5	Beaurepaires
22/10/2018		Gate Repairs R-657 repair track runner	STEFS TRANSPORT, TSR - Transport Servicing and Repairs
22/10/2018		B - 40k S-1584	STEFS TRANSPORT
21/09/2018		A - 20k S-1522 grease all point grease turn table check wheel bearings check all curtains check for crack no crack seen during inspection replace curtain buckle	
21/09/2018		Welding R-628	Vawdrey Australia Pty Ltd
23/08/2018		B - 40k S-1456 repaired the cracks in the the turntable , welded new steel bar to chassis and weleded all cracks greased all points required changed tyres replaced third gaurd right side with a second hand one	STEFS TRANSPORT
29/07/2018		Gate Repairs R-592 weld alloy plate to channel	STEFS TRANSPORT
08/07/2018		A - 20k S-1379	STEFS TRANSPORT
23/06/2018		Inspection T-1154 all ok	Beaurepaires
01/06/2018		Curtain Repair, Damage R-551 remove front nose cone to get access to the bottom of the roof, Remove damaged roof skin , prepare the roof frame for new skin to be applied ska flex and double sided tape used to hold roof down , straighten rear tale bar then rivet to back end of roof, secure roof, piut front nose cone back on.	STEFS TRANSPORT
31/05/2018		C - Annual S-1325 replace back wall new brake linings bearings and valve sc110451	Garners Garage, STEFS TRANSPORT
30/05/2018		Defect Notice R-559	Royans Wagga Pty Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
28/05/2018		Trailer Front & Rear Wall & Door Repairs R-574 replaced back wall	STEPS TRANSPORT
26/05/2018		New Tyre, Runout T-1150 2 x 255/70R22.5 NEW tyres pos 1 & 2 (BEAREPAIRES) 1 x runout to pos 4	Beaurepaires
10/05/2018		B - 40k S-1284 Carry out A service on trailers- Follow customers check list that is supplied by customer. List faults found and report to Customer. Customer requests to keep using trailers to return to there depot for repairs to be carried out Faults found Curtin ripped top left hand side B trailer, missing reflector left hand side B trailer, rear doors on B trailer U/S, missing Reflector right hand side B trailer, front right hand side mud flap on B trailer, no number plate lights on B trailer, Left hand side A trailer side marker flashing (wired wrong), chassis cracked on A trailer, Extra one-hour labour to fit new air bag to right hand side rear axle on A trailer	TSR - Transport Servicing and Repairs
07/04/2018		New Tyre T-1079 2 X 255 NEW TYRES POS 8-7 RUNOUT FITTED AT POS 3	Beaurepaires
07/04/2018		A - 20k S-1229 3RD AXLE WEARINGS ADJUSTED	STEPS TRANSPORT
29/03/2018		Runout T-1066 RUN OUT PLACED	Beaurepaires
11/03/2018		B - 40k S-1172 spray safe missing on rhs gaurd chassis cracks tyre wear on lhs and rhs inside tyres	TSR - Transport Servicing and Repairs
13/02/2018		Stock R-477 strap and ratchet allocation	STEPS TRANSPORT
12/02/2018		A - 20k S-1130 new amber clear light fitted A service completed	STEPS TRANSPORT
09/02/2018		Runout T-989 2 x runouts fitted AT POS 7+8 x steps yard	Beaurepaires
21/01/2018		Gate Repairs R-451	STEPS TRANSPORT
12/01/2018		Tyre Repair T-957 repair tyre Paid by credit card	Jerilderie Tyre Service
11/01/2018		Runout T-951 255/70R22.5 1X 255/70R22.5 RUNOUT FROM STEFS RACK FITTED TO POS 9	Beaurepaires
11/01/2018		B - 40k S-1077 Move landing leg handle	STEPS TRANSPORT
12/12/2017		A - 20k S-1041 Carried out Stef's Transport service sheet Remove and replace number plate light Replace missing grease fittings Repair faulty wiring in rear tail light Replace 1 x reflector	Vawdrey QLD
10/11/2017		B - 40k S-985	Garners Garage
30/10/2017		New Tyre, Runout T-825 2x 255/70R22.5 TYRES PLACED AT POS 5 & 6 RUNOUT FITTED AT POS 7	Beaurepaires
26/10/2017		A - 20k S-971 KMS: 090847 JOE 2-340 .50HRS	Garners Garage
29/09/2017		B - 40k S-907 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses and all tyre conditions & pressures 1x 91666BL NARVARA NUMBER PLATE LIGHT	

Date	Reading / Units	Type / Repairer Notes	Repairer
07/09/2017		Registration O-191 12 Month Registration	Transport SA
21/08/2017		C - Annual S-866 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked, checked gates & curtains REBUILD TRAILER 3x AXLES BEARINGS BRAKES & DRUMS CHECKED KING PIN INTOLARANCE LHS REAR AXLE HAS WEAR-STILL ON COOKIE WELDED UP JOE 9-5.30 8HRS MATT - STRIP A TRAILER 3HRS	inhouse, JOE
14/08/2017		Inspection T-425 TYRES ALL GOOD	Beaurepairs
25/07/2017		B - 40k S-825 CARRY OUT 'B' SERVICE AS PER STEF'S FLEET SERVICE SHEET REPLACE MISSING WHEEL NUT INDICATORS REMOVE & REPLACE 7 PIN PLUG ON SUZI REMOVE & REPLACE UH REAR BRAKE SHOES (NOT ALIGNED CORRECTLY) REMOVE & REPLACE PRESSURE PROTECTION VALVE PARTS & MATERIALS - 1 XWORKSHOP CONSUMABLES AND ENVIRONMENTAL CHARGES 1 XVALVE - PPV 1 X WHEEL NUT INDICATOR 32mm 1 X7P PLUG 1 XBENDIX- BRAKE SHOES INCH/WARE Q	Vawdrey Australia Pty Ltd
03/07/2017		New Tyre T-379 2x 255/70R22.5 REMINGTON TYRES FROM STEFS RACK PLACED AT POS 3 & 4	Beaurepairs
29/06/2017		Ratchet R-261 removed handle welded up & grounded JOE 4.30pm TO 5.10pm =	inhouse, JOE
26/06/2017		Runout T-371	Beaurepairs
23/06/2017		A - 20k S-794 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked, checked gates & curtains COOKIE WELDED UP BRAKES LHS REAR OUT OF DRUM	inhouse, JOE
22/06/2017		Chassis R-259 SE WELDING CAME OUT ON THE 23.06.2017 FIXED CRACKS 23/06/17-- REPAIR CRACKS IN "A" TRAILER CHASSIS.278.00156.00	South East Welding Services Pty Ltd
19/05/2017		B - 40k S-744 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked, checked gates & curtains CHECKED BOTH CROSS MEMBERS VAWDREY WELDED IN NO CRACKS ALL BEARINGS ARE RUNNING FINE NICK 1.5hrs	inhouse, nick
28/04/2017		Electrical , Mudguard R-223 REPAIRED DAMAGED RHS REAR MADE NEW PLATES TO BOLTS GUARDS TO JOE 1.1/2HRS	inhouse, JOE
24/04/2017		Electrical , Mudguard R-222 NICK REPAIRED ALL LIGHTS & GUARDS BEAUREPAIRS DONE NEW TYRES	Beaurepairs, inhouse, NICK
24/04/2017		A - 20k S-704 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked, checked gates & curtains JOE .30MINS	inhouse, JOE
24/03/2017		New Tyre, Runout T-287 2x New tyres on Pos 9 &10 1x Runout on Pos 5	Beaurepairs
24/03/2017		B - 40k S-677 Service done by Nick Replaced one buckle on B-Trailer (just worn) tyres replaced by beaurepairs	inhouse
27/02/2017		A - 20k S-626 Serviced by Vawdrey QLD 27.2.17 Carry out A service as per stef's transport fleet service sheet repair air leak at the L/H front brake booster air fitting	Vawdrey Australia Pty Ltd
10/02/2017		B - 40k S-590 Serviced at Vawdrey QLD 6.2.17 Carried out B Service as per stefs Fleet Service Sheet	Vawdrey Australia Pty Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
17/01/2017		A - 20k S-554 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked,curtains Nick 1hr	inhouse, NICK
23/12/2016		B - 40k S-540 Completed on 23/12 by nick. waiting on paperwork Vawdrey Carried out Below work greased and adjustbrakes as per vawdrey fleet service sheet	Vawdrey Australia Pty Ltd
06/12/2016		A - 20k S-512 A Service done by Vawdrey REPAIRS TO TRAILER--DONE IN BRISBANE Greased & Ajust Brakes as per Vawdrey Fleet Sheet Retension all Pivot Bolts	Vawdrey Australia Pty Ltd
25/11/2016		B - 40k S-484 Greased and inspected all brake systems for leaks, Checked Lights, Lenes & Reflectors Curtains, Tyre Pressures all Checked Joe1 to 2pm	inhouse, JOE
10/11/2016		Retrailer Bushes R-124 2x Main Bushes in suspencham replaced 2x Pivot Bolts Nuts & Washers	Inhouse, JOE
06/11/2016		Gate Repairs R-131 fixed by Nick	
31/10/2016		A - 20k S-457 Carried out below work Carried out Minor Service as per Vawdrey Minor Service Sheet Remove & Replace Number Plates Lights Replace 1x Amber Reflector on L/H/S Parts & Materials Used 1x workshop consumables and environmental charges 1x reflector-rectangle amber 1x hell-a-led licence plate lamp	Vawdrey Australia Pty Ltd
21/10/2016		New Tyre T-123 New Tyres Pos on 4 & 3 on trailer A 225 TYRES Tyres from Stefs Rack	Beaurepaires
13/10/2016		Trailer Modifications R-117 Needs to be pop riveted back on. Stef 45Mins	inhouse
10/10/2016		B - 40k S-392 Grease and adjust brakes as per Vawdrey fleet service sheet.	Vawdrey Australia Pty Ltd
19/09/2016		A - 20k S-369 Repair Trailer Greased & Adjust Brakes as per Vawdrey Fleet Service Sheet	Vawdrey Australia Pty Ltd
08/09/2016		Registration O-150	Transport SA
24/08/2016		B - 40k S-347	inhouse
03/08/2016	642,397 kms	C - Annual S-318 Annual C-Service A Trailer HP Brake Linings X 6 B Trailer Bendit Linings X 6 A Trailer replaced all Bearings & Linings A Trailer rear axle badly worn Front 2 axle linings are good B Trailer Replaced all Lining & Wheel Bearings old linings in good order Joe's hours 11 hrs: 8.30 am to 5.00 pm- 02/08/2016 8.00 am to 4.30 pm- 03/08/2016	Inhouse
21/07/2016		B - 40k S-300 Nick completed service	Inhouse
30/06/2016	62,127 kms	A - 20k S-286 Fitted auto slack adjusters to both trailers 4 x 24/30 boosters front axle & middle axle 6 x auto slack adjusters Straightened gate LHS Joe 9.00-2.30	Inhouse
17/06/2016		B - 40k S-269 Replaced tyre A trailer front axle put 2x run out tyres on B trailer gate face catch broken replaced catch with second hand one. Joe 1-3	Inhouse
26/05/2016		A - 20k S-249 nick 1.15-6.30	Inhouse
16/05/2016		New Tyre T-61	Samios Tyres- Brisbane branch

Date	Reading / Units	Type / Repairer Notes	Repairer
		255/70R22.5X16P TR656 Fit tyre truck disposal tyre truck	
09/05/2016		Balance T-509 FITTED BALANCE BEADS TO ALL TYRES	Beaurepaires
03/05/2016		B - 40k S-222 Welded on step to the back of A-Trailer for safe and easy access to air lines. Nick 12-2.15	Inhouse
08/04/2016		A - 20k S-74 Replaced Grease Nipple - RHS Nipple Greased and adjusted brakes checked wheel bearing Joe 9 - 10.15	Inhouse
12/03/2016		B - 40k S-51 Tightened Wheel Bearing, Front Passenger side B Trailer * Note with rear axle B Trailer brake wear Labour Stefan 12.30 - 1.30 1hr	Inhouse
16/02/2016		A - 20k S-3 Straight service, no problems. Nick 2.5hrs	Inhouse
31/01/2016		B - 40k S-145 Grease adjust brakes grease t/t check lights & bearings change tyre pos 6	Inhouse
29/01/2016		Insurance O-27	Global Transport & Automotive Solutions
08/01/2016		A - 20k S-143 Grease adjust brakes grease t/t check lights change tyre pos 3 paint rim	Inhouse
30/11/2015		B - 40k S-141 Grease adjust brakes grease t/t check lights check bearings	Inhouse
09/11/2015		A - 20k S-139 Grease adjust brakes grease t/t check lights wash trailers check bearings	Inhouse
19/10/2015		B - 40k S-137 Grease adjust brakes grease t/t check lights & bearings	Inhouse
28/09/2015		A - 20k S-135 Grease adjust brakes grease t/t check lights	Inhouse
10/09/2015		Registration O-75	Transport SA
07/09/2015		C - Annual S-133 Annual Service; new bearings, new pins, checked swing arm bushes & rear lights, put new ply in, new drop tarps, passed roadworthy inspection.	Inhouse

Signed: _____

Name: _____

Date: _____