

Vehicle History Summary



Fleet #	4B
Registration	SY85FD
Make	MAXITRANS
Model	Semi Trailer
VIN / Chassis #	6F8T250001B061642
Build Date	2001

Date	Reading / Units	Type / Repairer Notes	Repairer
07/03/2026	898,486 kms	Lights R-5779 Call out Found light wiring crushed in behind load restraint Repaired wiring Returned to service	STEFS TRANSPORT
05/03/2026	898,486 kms	Trailer Inspection Report I-515	STEFS TRANSPORT
24/02/2026	898,486 kms	New Tyre T-4341	Azzas Tyres Nhill
16/02/2026	1,798,217 kms	B - 40k S-7361 Conducted B Service All checks OK Returned to service	STEFS TRANSPORT
27/01/2026	898,486 kms	New Tyre T-4288 new nipon at167 fitted to pos 7,8 890195km	STEFS TRANSPORT
24/12/2025	898,486 kms	Damaged Gates R-5601 Repaired @ Service 7272	STEFS TRANSPORT
24/12/2025	898,486 kms	Brakes R-5613 Checked @ Service 7272 No Repair required	
24/12/2025	1,774,341 kms	A - 20k S-7272 Conducted A Service Replaced 1 X Stop/Taillight Replaced 1 X Amber reflector Returned to service	Stef's Transport
23/12/2025	898,486 kms	New Tyre, Pressure main T-4264 new nipon at-167 fitted to pos 11,12 10 x pressure check	STEFS TRANSPORT
19/11/2025	898,486 kms	New Tyre T-4205 new sailun s637+ fitted to pos 1,2,3,4 turn on hub pos 5 854448km	STEFS TRANSPORT
18/11/2025	1,752,934 kms	C - Annual S-7078 Conducted C service Replaced all wheel bearings Replaced all pro torque nuts Replaced all hubcap gaskets Replaced all Brakes & Hardware Replaced 1 X 3/8 X 14bsp straight fitting (airbag Control) Replaced 1 X CA700 service brake valve Replaced 1 X 3/8 X 14 bsp T fitting (Service valve) Replaced Pos 2, 5 & 6 airbags Replaced 1 X Gate latch Replaced Pos 3 & 5 Shockers Return to service	Stef's Transport
18/11/2025	898,486 kms	Damaged Gates R-5513 Repaired @ Service 7078	STEFS TRANSPORT
18/11/2025	898,486 kms	Heavy Trailer Inspection Checklist I-475	STEFS TRANSPORT
07/10/2025	1,735,766 kms	A - 20k S-7132 Conducted A Service Repaired Curtain R/H/S Return to service	STEFS TRANSPORT
18/09/2025	898,486 kms	Trailer Inspection Report I-425	Stef's Transport

Date	Reading / Units	Type / Repairer Notes	Repairer
06/09/2025	898,486 kms	New Tyre T-4153 New Tyre fitted. RGB Paid Invoice 118147. Reimbursed RGB for the cost.	Speedy Automotive and Tyres
01/09/2025		Registration O-1869	Transport SA
27/08/2025	898,486 kms	Inspection T-4090 tyres are all ok	STEFS TRANSPORT
26/08/2025	898,486 kms	Trailer Inspection Report I-381	STEFS TRANSPORT
26/08/2025	898,486 kms	Gate Repairs R-5358 Remove L/H/Rear gates x 3 repair gate head roller Reinstall gates Repair toolbox lid Repair L/H side light Return to service	STEFS TRANSPORT
20/08/2025	1,713,190 kms	B - 40k S-7038 Conducted B Service Replaced Pos 2 Shocker Replaced 4M 1/2" airline (Supply Pos 5 booster) Repaired 2 X Gates Replaced 2 X Ply boards Replaced 2 X Red/Amber side lights Return to service	STEFS TRANSPORT
21/07/2025	898,486 kms	New Tyre T-4046 new doublestar dsr669 fitted to pos 5,6	STEFS TRANSPORT
03/07/2025	1,685,123 kms	A - 20k S-6950 Conducted A Service Removed service valve, cleaned & reinstalled. test OK (Removed air tank to access valve) Replaced 4 X 660 straps Returned to service	STEFS TRANSPORT
29/05/2025	1,666,340 kms	B - 40k S-6866 Conducted B Service Repaired 5 X Gates Replaced 4 X 660 straps Adjusted Pos 2,3- & 6-wheel bearings Returned to service	Stef's Transport
23/04/2025	898,486 kms	Lights R-5105 Repaired & Replaced 13 Red/Amber side lights Replaced 2 X Amber side lights Replaced 6 X Amber reflectors Returned to service	STEFS TRANSPORT
26/02/2025	1,647,932 kms	A - 20k S-6717 Conducted A Service Replaced Pos 1 & 2 Shockers Repaired 2X Gate Replaced 1 X Red/Amber side light Replaced R/H Curtain handle Returned to service	STEFS TRANSPORT
26/02/2025	898,486 kms	Gate Repairs R-4956 Repaired @ Service 6717	STEFS TRANSPORT
31/01/2025	898,486 kms	Trailer Inspection Report I-225	Stef's Transport
07/01/2025	898,486 kms	Rails cracked R-4893 Cleaned crack drilled and welded small crack R/H/Side above Pos 11 & 12 Returned to service	STEFS TRANSPORT
06/01/2025	898,486 kms	Fault T-3781 NEW TRIANGLE TR656 FITTED TO POS 1,2,11,12	STEFS TRANSPORT
06/01/2025	1,627,492 kms	B - 40k S-6641 Conducted B Service Replaced 1 X Red/Amber side light Replaced 1 X 660 strap Returned to service	STEFS TRANSPORT
28/11/2024	898,486 kms	side light R-4802 Replaced 1 X Red/Amber side light Replaced 1 X Amber Reflector Repaired 2 X Holes in curtain Repaired 2 X Gates	STEFS TRANSPORT
27/11/2024	898,486 kms	Fault T-3731 new doublestar dsr669 fitted to pos 9,10	STEFS TRANSPORT
27/11/2024	898,486 kms	Fault T-3730 runout to pos 11	STEFS TRANSPORT
13/11/2024	1,607,496 kms	A - 20k S-6559 Conducted A Service Welde cracks in frame L/H/S Returned to service	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
21/10/2024	898,486 kms	Air Repairs R-4759 Replaced Male & Female bulkhead fittings	STEFS TRANSPORT
03/10/2024	898,486 kms	Brake Repairs R-4739 Travel to site and locate truck. Find LH 1st brake stuck on. Back off, knock brake shoe back into place and readjust brake. Recommend wheel be removed, brake bushings or s-cam bushes may need replacing. Travel back to workshop	Hamilton Diesel
19/09/2024	898,486 kms	New Tyre T-3665 new triangle tr656 fitted to pos 5,6	STEFS TRANSPORT
19/09/2024	898,486 kms	Heavy Trailer Inspection Checklist I-110	STEFS TRANSPORT
19/09/2024	1,587,831 kms	C - Annual S-6447 Conducted C Service Replaced all brakes & Hardware Replaced all pro-Torque nuts Replaced all wheel bearings & seals Replaced all hubcap gaskets Replaced Pos 2 & 4 Shockers Replaced 9.5M 1/2' brake hose Replaced 3 X S/Cams Replaced 3 X Z/Cams Replaced 6 X Cam tube seals Replaced 2 X 18X24 Mudflaps Replaced 7 X 660 Straps & Buckles Repaired 2 X Gates Returned to service	STEFS TRANSPORT
03/09/2024		Registration O-1419	Transport SA
26/07/2024	898,486 kms	Electrical R-4636 Repaired L/H/Rear light wiring Replaced 3 X 660 straps	STEFS TRANSPORT
16/07/2024	898,486 kms	Electrical R-4617 Cut out broken/corroded plugs, soldered wiring as best as could and heat shrunked. Tested operation. All Ok. Secured harness as required.	MISC Repairer
28/06/2024	898,486 kms	Pressure main T-3586 12 x pressure check	STEFS TRANSPORT
27/06/2024	1,564,167 kms	A - Monthly S-6354 Conducted A Service Replaced 2 X 660 straps Removed 3 X Gates R/H Front Repaired roller heads & reinstalled gates Returned to service	STEFS TRANSPORT
27/06/2024	898,486 kms	Gate Repairs R-4595 Repair completed @ Service 6354	STEFS TRANSPORT
29/04/2024	1,543,428 kms	B - Bi Monthly S-6276 Conducted B Service Adjusted Pos 1,3- & 4-wheel bearings Replaced 1 X 660 strap Returned to service	STEFS TRANSPORT
29/04/2024	898,486 kms	New Tyre T-3514 new doublestar fitted to pos 3,4 turn on hub pos 8 10 x pressure check	STEFS TRANSPORT
12/03/2024	898,486 kms	Electrical R-4430 Completed @ service 6181 12/3/24	Stef's Transport
12/03/2024	1,522,987 kms	A - Monthly S-6181 Conducted A Service Replaced 1 X Male bulkhead fitting Repaired Electrical fault (fault inside light causing back feed) 1 X Red/Amber side light Returned to service	STEFS TRANSPORT
22/01/2024	1,504,386 kms	B - Bi Monthly S-6098 Conducted B Service Repaired curtain R/H/S Rear Replaced 1 X Curtain strap & Buckle (2nd Hand) Returned to service	STEFS TRANSPORT
17/01/2024	898,486 kms	New Tyre T-3373 new haulstar ha615 fitted to pos 1,2,9,10,11,12	STEFS TRANSPORT
22/12/2023	898,486 kms	Defect Notice R-4289 Inspect Repairs and clear defect Defect Notice Clearance	Krueger
06/12/2023	898,486 kms	Chassis, Electrical R-4240	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
		Replaced 1 side light (Red/Amber) Replaced 1 x 660 Curtain Strap Grind out & weld crack in chassis. (RHS)	
15/11/2023	1,485,444 kms	A - Monthly S-5984 Completed A service Replaced dock rubber	STEFS TRANSPORT
15/11/2023	1,796,972 kms	Gate Repairs R-4194 Repaired bent gate.	STEFS TRANSPORT
26/10/2023	898,486 kms	Curtain Repair R-4044	STEFS TRANSPORT
10/10/2023	1,471,041 kms	B - Bi Monthly S-5914 Completed B Service	STEFS TRANSPORT
22/09/2023	1,796,972 kms	Electrical R-4089 Repaired on site	STEFS TRANSPORT
06/09/2023	1,454,952 kms	A - Monthly S-5788 Conducted A Service Repaired 3 X Gates Replaced 1 X Stop / tail light Replaced 1 X top marker light Drilled & welded cracks in Chassis R/H/S in front of tri Returned to service	STEFS TRANSPORT
31/08/2023		Registration O-841	Transport SA
09/08/2023	898,486 kms	Runout T-3130 runouts fitted to pos 7,8,12	STEFS TRANSPORT
02/08/2023	898,486 kms	Brake Repairs R-3932 just need to go over brakes when trailer is back BCL Diesel - Found brakes adjusted too tight. Adjust all brakes and test operation. Check wheel bearing - advise John of slight movement there	BCL Diesel , STEFS TRANSPORT
24/07/2023	1,434,220 kms	C - Annual S-5683 Conducted C Service Replaced 1 X Tube seal Replaced 4 X S/Cam tube ,Long Replaced Pos 3 S/Cam Replaced 6 X auto slack adjusters (course)Replaced 2 & 5 shockers Replaced 6 Hub Cap gaskets Replaced R/H/O/Take sign Replaced 2 X Red Reflectors Replaced 2 X 660 straps Replaced 1 X White reflector Replaced 6 X 006 Bearings Replaced 6 X 4743 Nuts Replaced 6 X Brake drums Replaced 1 X air tank drain valve Replaced 1 X 3/8 x 3/8 air line fittings Replaced 6 X 30/30 brake booster Replaced 3 X z/cams Replaced 1 X S/Cam	STEFS TRANSPORT
19/07/2023	1,322,100 kms	A - Monthly S-5710 Conducted A Service Replaced 1 X red/amber side light Replaced 1 X 660 strap Returned to service	STEFS TRANSPORT
19/06/2023	898,486 kms	Electrical R-3813	D&N Truck Repairs
30/05/2023	1,415,140 kms	B - Bi Monthly S-5589 conducted B Service trailer Loaded	STEFS TRANSPORT
30/05/2023	898,486 kms	Electrical R-3753 problem in prime mover not trailers	STEFS TRANSPORT
19/05/2023	898,486 kms	Gate Repairs R-3706 Upon investigation all gates were found to be working correctly. Suggest driver/loader pull the gate out to unlock fully before sliding.	STEFS TRANSPORT
02/05/2023	1,401,834 kms	A - Monthly S-5442 Repaired top front RHS light bracket Serviced, all ok	STEFS TRANSPORT
24/03/2023	1,383,045 kms	B - Bi Monthly S-5358 Conducted B Service Adjusted Pos 3, 4, bearings Replaced 1 X Red / Amber side light Replaced 3 X New ply boards	STEFS TRANSPORT
27/02/2023	1,370,580 kms	A - Monthly S-5275 Conducted A Service Replaced 3 X 660 straps Replaced 1 X red /Amber side light	STEFS TRANSPORT
14/02/2023	898,486 kms	New Tyre T-2928 4 x new tyres pos 1,2,3,4	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
05/01/2023	1,349,931 kms	B - Bi Monthly S-5149 Full Rebuild conducted	STEFS TRANSPORT
05/01/2023	898,486 kms	Brake Repairs R-3389 Replaced all brakes Replaced all auto slack adjusters replaced 2 X L/H cams Replaced 1 X R/H Cam Replaced 1 X Cam tube Replaced 1 X Red /Amber side light Repaired 2 X gates Repaired curtain L & R H sides Replaced Pos 2, 4 5 & 6 shockers	STEFS TRANSPORT
02/12/2022	1,345,796 kms	B - Bi Monthly S-5053 Conduct B service All checks OK No Parts	STEFS TRANSPORT
01/12/2022	898,486 kms	Runout T-2759 1 X RUNOUT POS 1	Goodyear
26/10/2022	1,325,034 kms	A - Monthly S-4955 Conducted A Service Repaired side light wiring No parts required	STEFS TRANSPORT
10/10/2022	1,796,972 kms	New Tyre T-2708 4 x tyres	Goodyear
01/10/2022	898,486 kms	Bearings, Brake Repairs R-3236 Replaced with new bearings Replaced with new brakes Reshimed S Cams	Garners Garage
16/09/2022	1,307,603 kms	C - Annual S-4827 conduct C Service Replaced all wheel Bearings Replaced all Pro torque nuts Replaced all hub cap gaskets Replaced all brake shoes Trailer height set at 459	STEFS TRANSPORT
13/09/2022	898,486 kms	Brake Repairs R-3095 In For C Service	STEFS TRANSPORT
10/09/2022		Registration O-534	Transport SA
22/08/2022	898,486 kms	Electrical R-3048 Fleet Number: 4B Fleet Rego: SY85FD Connect van lights and check indicator fault Found quick crimp terminals to side light and rear indicator module cause for not working Solider wiring and insulate Test ok	STT Mechanical
17/08/2022	898,486 kms	Electrical R-3035 problem was in the truck not trailer	STEFS TRANSPORT
17/08/2022	898,486 kms	Electrical R-3034 problem was in prime mover not trailer	STEFS TRANSPORT
17/08/2022	1,289,269 kms	A - Monthly S-4739 Conduct A Service Indicators working OK problem in Prime Mover Trailers Loaded ply board not checked All other checks OK	STEFS TRANSPORT
17/08/2022	1,289,269 kms	Ply Boards R-3033	STEFS TRANSPORT
17/08/2022	898,486 kms	Electrical R-3022 Problem was in the prime mover not the Trailer repaired the prime mover plug and lights are OK	STEFS TRANSPORT
08/07/2022	1,272,739 kms	B - Bi Monthly S-4632 Conducted B Service Repaired 1 X Side light replaced both rear mudflaps replaced 2 X 255-70R 22.5 Replaced 6 X 660 Straps replaced 2 X Shockers welded cracks in fill plates	STEFS TRANSPORT
08/07/2022	898,486 kms	New Tyre T-2622	Goodyear
07/07/2022	898,486 kms	Defect Notice R-2927 Defect Cleared at Vawdrey Larapinta	Vawdrey Larapinta Brisbane
17/06/2022	898,486 kms	Curtain Repair R-2842	U-Rippa

Date	Reading / Units	Type / Repairer Notes	Repairer
		Remove 3 buckles grind off and remove 1 mounting block to repair curtain replace part of 1 webbing strap refit mounting block and buckles Supply and fit 1 mounting block	
09/06/2022	1,255,463 kms	A - Monthly S-4534 conducted A service replaced king pin	STEFS TRANSPORT
08/06/2022	898,486 kms	Pressure main T-2564	Goodyear
04/05/2022	898,486 kms	Runout T-2526	Goodyear
03/05/2022	1,235,197 kms	C - Annual S-4440 Conducted C Service Replaced all Brakes, locking nuts, hub cap gaskets, wheel bearings	STEFS TRANSPORT
31/03/2022	898,486 kms	Tyre Repair T-2494	Goodyear
28/03/2022	1,222,080 kms	B - Bi Monthly S-4346 conducted B service L/H/S weather strip repaired p3 and p4 wheel bearing adjusted	STEFS TRANSPORT
09/02/2022	1,200,323 kms	A - Monthly S-4241 conducted A service loaded	STEFS TRANSPORT
10/01/2022	1,180,834 kms	B - Bi Monthly S-4156 Conducted B service Repaired 4 X Gates Trailers loaded	STEFS TRANSPORT
01/12/2021	1,160,056 kms	A - Monthly S-4097 Conducted A service	STEFS TRANSPORT
01/11/2021	1,142,031 kms	B - Bi Monthly S-4012 conducted B service adjusted all wheel bearings found pos 3&4 lose so did all replaced some reflectors repaired gates	STEFS TRANSPORT
12/10/2021	898,486 kms	New Tyre T-2261	Goodyear
24/09/2021	1,122,044 kms	A - Monthly S-3940 Conducted A Service Replaced Pos 2 airbag Replaced Pos 3 airbag	STEFS TRANSPORT
26/08/2021		Registration O-408	Transport SA
19/08/2021	1,103,852 kms	B - 40k S-3839 Conducted B service Repaired 2 gates All other checks OK	STEFS TRANSPORT
19/08/2021	898,486 kms	New Tyre T-2218	Goodyear
06/08/2021	1,096,297 kms	A - 20k S-3804	TSR - Transport Servicing and Repairs
24/06/2021	1,073,889 kms	C - Annual S-3723 Pos 2-3&4 bearings found to be loose. All brake cams lacking grease. Pos 2 brake defective (gone over centre)	Garners Garage
24/06/2021		Air Repairs R-2188 Done during Service	STEFS TRANSPORT
15/06/2021	1,071,519 kms	B - 40k S-3701	TSR - Transport Servicing and Repairs
31/05/2021	857,587 kms	Curtain Repair R-2166 Complete refurb of curtains, roof, tracks, re-paint and various alterations	Vawdrey Dandenong VIC
22/04/2021	857,587 kms	Gate Repairs R-2066 Ant cleaned and cut track part, fixed gate and put it back into place Sam Welded track back together	3MP Millicent, STEFS TRANSPORT
22/04/2021	857,587 kms	New Tyre T-2097	Goodyear
06/04/2021	1,054,816 kms	A - 20k S-3676	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
06/04/2021		Gate Repairs, Ply Boards R-2039 x4 ply boards added x4 gates patch welded x2 curtain straps replaced P6 Booster lines repaired	3MP Millicent, STEFS TRANSPORT
31/03/2021		Gate Repairs R-2019	3MP Millicent
24/03/2021	1,005,979 kms	New Tyre, Runout T-2075	Goodyear
23/03/2021	1,005,521 kms	Combing Rail, Curtain Repair, Electrical , Gate Repairs R-2006 All fixed	STEFS TRANSPORT
05/03/2021	857,587 kms	Curtain Repair R-1974	U-Rippa
03/03/2021	1,039,315 kms	B - 40k S-3677	TSR - Transport Servicing and Repairs
26/02/2021		Ply Boards R-1916	
26/02/2021		Curtain Repair R-1950	
03/02/2021	857,587 kms	Electrical R-1874	Garners Garage
03/02/2021	984,643 kms	A - 20k S-3399 Welded x2 gates RHS x2 straps LHS	Garners Garage
03/02/2021	857,587 kms	Brake Repairs R-1874 fixed at service	
02/02/2021	857,587 kms	Electrical R-1876 fixed during service	Garners Garage
11/01/2021		Electrical R-1844 replace trailer plug Carry Out Repairs To Trailer Set 4 4A Rego SY28FK 4B Rego SY86FD Carry Out Repairs To Lights Found To Have Fault With LHS Indicator And Parker Lights Found To Have Damaged Wiring Under Deck Plate Found Wiring From Deck Plate To Trailer Plug Damaged Found Male Plug Broken And Pins Missing Replace Female Plug On Front Of B Trailer With New Repair All Faults And Test Lights System All Test Ok	STEFS TRANSPORT, TSR - Transport Servicing and Repairs
08/01/2021		Gate Repairs R-1841 gate repaired all satis new krueger latch fitted	STEFS TRANSPORT
04/01/2021	963,610 kms	B - 40k S-3327 B service C/O all satis P1,P3,P5 bearings adjusted	STEFS TRANSPORT
27/11/2020	944,042 kms	A - 20k S-3268 no faults found at time of service	TSR - Transport Servicing and Repairs
02/11/2020	857,587 kms	Gate Repairs R-1731 RH gate track repaired by 3MP all satis 1x side marker light replaced	STEFS TRANSPORT
28/10/2020	924,998 kms	B - 40k S-3221 B service C/O all satis bearings checked all satis 6x ply fitted	STEFS TRANSPORT
17/10/2020	857,587 kms	New Tyre T-1885 2X 255/70 NEW TYRE'S PLACED AT PO 5-6 REPLACED BY BRENT	Beaurepaires
16/10/2020		Curtain Repair R-1701 drivers side curtain slashed open, temporarily repaired will need further repair @ Aerial tarps	Aerial Tarps Pty Ltd, STEFS TRANSPORT
21/09/2020	906,733 kms	A - 20k S-3160 A service C/O all satis P5 s cam re shimmed all satis air leaks repaired	STEFS TRANSPORT
25/08/2020		Registration O-334	Transport SA

Date	Reading / Units	Type / Repairer Notes	Repairer
13/08/2020	857,587 kms	Gate Repairs R-1595 see service jobcard for details	STEFS TRANSPORT
13/08/2020	889,633 kms	B - 40k S-3090 B service C/O all satis bearings ok RH gate track repaired by 3mp all satis	STEFS TRANSPORT
29/07/2020	857,587 kms	Brake Repairs, Electrical R-1580 Replaced barke with new shoes fitted all parts ensure fitted correctly, re greased hub and axle adjusted brakes checked all ok. Carry Out Repairs To Trailer Set 4 B trailer Rego SY85FD Reported No Brake Lights Attend Trailers On A Saturday Found Front Plug And B Trailer Faulty As Well As Wiring Fault Remove And Replace Trailer Plug Repair Wiring And Refit Plug Test All Lights All Test Ok GST 1 x Call Out And Repair To Lights (Sub Contractor) \$330.00 GST Attend Trailers On Ipswich Motorway After Hours Reported To Have Brake Smoking Found LHS Rear Axle Brake Brake Failure RTemove Bearings And Hub To Get To Brakes Found Brake Hard wear Had Failed Causing Major Brake Failure GST Remove All Brake And Hard wear Renaming Refit Hub And Bearings And Adjust Bearings Trailer Travelled To Rocklea To Be Repaired The Following Day GST 1 x Callout And Repair After Hours On Motorway 3x Hours Labour - After Hours	STEFS TRANSPORT, TSR - Transport Servicing and Repairs
21/07/2020	876,587 kms	A - 20k S-3031 A service C/O all satis Bearings checked ok	STEFS TRANSPORT
26/05/2020		New Tyre T-1710 2x 255/70R22.5 (REM) PLACED AT POS 1-2 DONE BY BRENT	Beaurepaires
20/05/2020	857,587 kms	C - Annual S-2902 C service C/O all satis all bearings replaced all shockers replaced all brake shoes re used and fitted with tru shus and new hardware water leaks repaired P5 brake booster (24/30) replaced as had internal leak front gp fitting replaced 3x ply fitted 1x rh side marker replaced was dull	Garners Garage, STEFS TRANSPORT
04/05/2020		B - 40k S-2862 B service C/O all satis. P4 bearing adjusted all satis	STEFS TRANSPORT
27/04/2020		New Tyre, Runout T-1679 2x 255/70R22.5 NEW (REM) TYRE'S PLACED AT POS 11-12 1x 255/70R22.5 RUN OUT PLACED AT POS 7 REPLACED & DONE BY BRENT	Beaurepaires
14/04/2020		Gate Repairs R-1377 Broken gates repaired all satis.	STEFS TRANSPORT
09/04/2020		A - 20k S-2791 A service C/O all satis. 2x curtain straps fitted 1x small slack adjuster pin fitted to P1 all satis	STEFS TRANSPORT
01/04/2020		Curtain Repair R-1329 curtain strap replaced @ earlier date all satis	STEFS TRANSPORT
11/03/2020		B - 40k S-2720 B service C/O all satis. all bearings ok.	STEFS TRANSPORT
12/02/2020		New Tyre T-1645 2 new tyres	Beaurepaires
11/02/2020		A - 20k S-2652 A service C/O all satis. all tyres pressure checked split booster line replaced holes in curtains repaired	STEFS TRANSPORT
14/01/2020		B - 40k S-2582 B service C/O all satis P2 & P4 bearings adjusted P4 bearing nut replaced all satis all clamps gone over LED number plate light fitted all satis	STEFS TRANSPORT
14/12/2019		A - 20k S-2514 A service C/O all satis. all clamps gone over all satis. booster lines re routed and fixed as were chaffing all satis 2x rear number plate light inserts replaced all satis. 1x wheel nut indiactor fitted as was missing. various reflectors fitted	STEFS TRANSPORT
22/11/2019		B - 40k S-2474	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
		B service C/O byu Garners all satis	
28/10/2019	A - 20k S-2408	A service C/O all satis. 2x new tyres fitted to LH front axle all torqued all satis. air leaks repaired and some small band hose clamps replaced with proper hose clamps all satis.	STEFS TRANSPORT
24/09/2019	B - 40k S-2351	B service C/O all satis. 2x rear mudflaps cut to size & fitted all satis. both bearings on the rear axle torqued & new hub seals fitted all satis. wheel nut indicators fitted to 2X wheels all satis	STEFS TRANSPORT
09/09/2019	Registration O-274		Transport SA
27/08/2019	A - 20k S-2278	A service C/O all satis various air leaks repaired.	STEFS TRANSPORT
26/07/2019	B - 40k S-2197	B service C/O all satis (bearings checked) P3 bearing re torqued RH number plate light installed	STEFS TRANSPORT
11/07/2019	Electrical R-965	all lights repaired. number plate sealed light replaced	STEFS TRANSPORT
19/06/2019	A - 20k S-2106	all fine underneath, no cracks, washed trailers	NICK, STEFS TRANSPORT
06/06/2019	Gate Repairs, Tyres R-932	Weld up broken gates, remove rhr brake backing plate was rubbing on drum, adjust brakes, panelbeat bent door on toolbox.	STEFS TRANSPORT
28/05/2019	Electrical R-917	Rewire and replace lh number plate light.	STEFS TRANSPORT
20/05/2019	C - Annual S-2033	Carry out C service, make up 3.5 metre cover plate for roof lhs panelbeat and sikaflex into place, fit new number plate lamp, rewire rh side light, replace rhf side light. axle measurements Lhf inner 89.21 outer 66.40, Lhc inner 89.26 outer 66.51, Lhr inner 89.36 outer 66.55 , Rhf inner 89.88 outer 65.45, Rhc inner 89.30, outer 66.28 , Rhr inner 89.35 outer 66.44	STEFS TRANSPORT
18/05/2019	Roof Repairs R-897	repair with cover plate	STEFS TRANSPORT
23/04/2019	B - 40k S-1975	B Trailer Faults LHS Side Light Not Working,	TSR - Transport Servicing and Repairs
26/03/2019	A - 20k S-1914	B Trailer Faults Rear Wall Cracking Slightly, No Reflectors On Rear, No Number Plate Lights Working, Two Side Marker Lights Facing Wrong Way, RHS Side Light Dull, Reflector Missing RHS, RHS Rear Axle Shockie Weeping, Chassis Cracks RHS Rear Third Axle, Chassis Cracks Front Of Axles,	TSR - Transport Servicing and Repairs
15/03/2019	Rotate T-1355	TYRE ROTATION POS 1 DUE TO FLTA SPOT	Beaurepaires
08/03/2019	Welding R-781		South East Welding Services Pty Ltd
27/02/2019	B - 40k S-1859	B Trailer Skid Plate Worn, Chassis Cracks LHS And RHS, Reflector Missing RHS, No Number Plate Lights, Rear Wall Cracked Bottom, Light Holder Broken LHS, 2nd Axle Inside Tyre Wearing Uneven, 2nd Axle Outside Tyre U/S, 2nd And 3RD Axle LHS Slight Bush Wear, 3rd Axle RHS Shock Leak, Rear Cross Member Cracked, Slight Wheel Bearing Movement All Axles	TSR - Transport Servicing and Repairs
13/02/2019	Gate Repairs R-751	replace fittings, welded up gates, wash trailers	NICK, STEFS TRANSPORT
31/01/2019	A - 20k S-1790		TSR - Transport Servicing and Repairs

Date	Reading / Units	Type / Repairer Notes	Repairer
24/12/2018		B - 40k S-1718	TSR - Transport Servicing and Repairs
27/11/2018		A - 20k S-1654 repair lhs side light replace reflector	STEFS TRANSPORT
03/11/2018		New Tyre T-1282	Beaurepaires
22/10/2018		B - 40k S-1583	STEFS TRANSPORT
06/10/2018		New Tyre T-1251 2 255/70/22.5 FITTED TO POS 3-4	Beaurepaires
29/09/2018		New Tyre T-1238 2 X NEW 255/70/22.5 POS 1+2	Beaurepaires
22/09/2018		New Tyre T-1258 2 X 255/70/22.5	Beaurepaires
21/09/2018		A - 20k S-1523 grease all points check wheel bearings check all curtains no crack seen on inspection replace 3 curtain straps	
21/09/2018		Welding R-629	Vawdrey Australia Pty Ltd
23/08/2018		New Tyre T-1206	Beaurepaires
23/08/2018		B - 40k S-1457 greased all points required, crack in chassis right side third axle	STEFS TRANSPORT
15/07/2018		A - 20k S-1399	STEFS TRANSPORT
15/07/2018		B - 40k S-1380	
01/06/2018		Curtain Repair, Damage R-552 Curtains fixed by arial traps 1 x new 22.5 rim and 1 x ne 255/70/22.5 tyre Blacklion	
31/05/2018		New Tyre T-1129 2 X 255/70R22.50 NEW TYRES PLACED AT POS 5+6	Beaurepaires
31/05/2018		C - Annual S-1326 new back wall replace brakes and new bearings	Garners Garage, STEFS TRANSPORT
21/05/2018		Trailer Front & Rear Wall & Door Repairs R-575 replaced back wall	STEFS TRANSPORT
10/05/2018		B - 40k S-1285 Carry out A service on trailers- Follow customers check list that is supplied by customer. List faults found and report to Customer. Customer requests to keep using trailers to return to there depot for repairs to be carried out Faults found Curtin ripped top left hand side B trailer, missing reflector left hand side B trailer, rear doors on B trailer U/S, missing Reflector right hand side B trailer, front right hand side mud flap on B trailer, no number plate lights on B trailer, Left hand side A trailer side marker flashing (wired wrong), chassis cracked on A trailer, Extra one-hour labour to fit new air bag to right hand side rear axle on A trailer	TSR - Transport Servicing and Repairs
07/04/2018		A - 20k S-1230 1ST AND 2ND AXLE WHEEL BEARINGS LOOSE TIGHTENED AND MUST CHECK NEXT SERVICE	STEFS TRANSPORT
11/03/2018		B - 40k S-1171 reflector missing number plate light not working no spare tyre slight rip in curtain top LHS fiut five yellow nut locks	TSR - Transport Servicing and Repairs
27/02/2018		Air Repairs R-498	Vawdrey Australia Pty Ltd
12/02/2018		A - 20k S-1131	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
11/01/2018		B - 40k S-1078 GATE HANDLE BROKEN- REPLACED	STEPS TRANSPORT
12/12/2017		A - 20k S-1042 Carried out service as per Stef's Transport service sheet Repair air leak at park brake valve Replace missing grease fittings	Vawdrey QLD
30/11/2017		Damage R-423 SIKA FLEX AND PATCH	NICK
18/11/2017		New Tyre T-841 2x 255/70R22.5 REMINGTON TYRES PLACED AT POS 7 + 8	Beaurepaires
10/11/2017		New Tyre T-838 4x 255/70R22.5 TYRES PLACED AT POS 1+2 9+10 TYSON & ADAM	Beaurepaires
10/11/2017		Chassis R-400	South East Welding Services Pty Ltd
10/11/2017		B - 40k S-988	Garners Garage
30/10/2017		Runout T-826 RUNOUT PLACED AT POS 8	Beaurepaires
26/10/2017		Gate Repairs R-383	Garners Garage
26/10/2017		A - 20k S-972 KMS:465505 JOE 2-340 .50HRS WELED GATES RHS	Garners Garage
29/09/2017		B - 40k S-899 KMS 453030 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses and all tyre conditions & pressures	JOE
07/09/2017		Registration O-192	Transport SA
22/08/2017		C - Annual S-865 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked, checked gates & curtains JOE 8.30am-5.40pm 8HRS	inhouse, JOE, MATT
14/08/2017		Inspection T-426 TYRES ALL GOOD	Beaurepaires
25/07/2017		B - 40k S-826 CARRY OUT 'B' SERVICE AS PER STE F'S FLEET SERVICE SHEET REMOVE & REPLACE UH MIDDLE SHOCK ABSORBER ADJUST ALL WHEEL BEARINGS REMOVE & REPLACE R/H MIDDLE MUDFLAP PARTS & MATERIALS - 1 X WORKSHOP CONSUMABLES AND ENVIRONMENTAL CHARGES 1 XMUDFLAP -VAWDREY 450x600 1 X HENDRICKSON -SHOCK ABSORBER	Vawdrey QLD
26/06/2017		New Tyre T-372 2 x 255/70R22.5 to Pos 11 & 12	Beaurepaires
23/06/2017		A - 20k S-795 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked, checked gates & curtains JOE 12 TO 1 =1hr	inhouse, JOE
19/05/2017		B - 40k S-745 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked, checked gates & curtains STRAIGHTEN 2 MUDFLAPS FRONT LEFT & RIGHT SIDE OF TRAILER CHECKED BOTH CROSS MEMBERS VAWDREY WELDED IN NO CRACKS ALL BEARINGS ARE RUNNING FINE NICK 1.5hrs	inhouse, nick
19/05/2017		New Tyre T-345 New Tyres Pos 5&6 RSD A375976- See Attached	Beaurepaires

Date	Reading / Units	Type / Repairer Notes	Repairer
02/05/2017		Balance T-510 FITTED BALANCE BEADS TO ALL TYRES	Beaurepairs
24/04/2017		A - 20k S-705 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked, checked gates & curtains	inhouse, JOE
20/04/2017		New Tyre T-312 2 tyres have blown at Brocklehurst	Beaurepairs
13/04/2017		Electrical R-204 PLUG NEED REPAIRS	inhouse
24/03/2017		New Tyre T-564 1x 255/70R22.5 TYRES PLACED AT POS4	Beaurepairs
24/03/2017		New Tyre T-288 2x new tyres on Pos 3&4 255/70R22.5 140/137L REMINGTON R145A & FITTING TRUCK NEW SPARES PUT INTO STEFS RACK 19/5/17	Beaurepairs
24/03/2017		B - 40k S-678 Service done by Nick 24.3.17 Replaced one buckle on B-Trailer (just worn) tyres replaced by beaurepairs	inhouse
27/02/2017		A - 20k S-627 Serviced by Vawdrey 27.2.17 Carry out A service as per Stef's transport fleet service sheet. Remove & Replace L/H Front airbag Remove & Replace R/H Middle airbag Remove & Replace Leaking drain cock Replace 2x missing reflectors Remove & Replace leaking air lines	Vawdrey Australia Pty Ltd
06/02/2017		B - 40k S-591 Serviced at Vawdrey QLD 6.2.17 Vawdrey Carried out Below work for b-service greased and adjustbrakes as per Stef Fleet Sheety fleet service sheet Removed & Replace R/H middle shock mount Removed & Replaced L/H middle upper marker price includes 1x Hella Marker, 1x Hendrickson shock clevis HT230	Vawdrey Australia Pty Ltd
17/01/2017		A - 20k S-555 Greased And checked all lubricate points inspected brakes for leaks checked all lights, lenses & reflectors Tyre pressures checked,curtains Nick 1hr	inhouse, NICK
23/12/2016		B - 40k S-541 Completed on 23/12 by nick. waiting on paperwork Completed on 23/12 by nick. waiting on paperwork Vawdrey Carried out Below work greased and adjustbrakes as per vawdrey fleet service sheet	inhouse
06/12/2016		A - 20k S-513 A Service done by Vawdrey REPAIRS TO TRAILER Greased & Ajust Brakes as per Vawdrey Fleet Sheet Retension all Pivot Bolts	Vawdrey Australia Pty Ltd
26/11/2016		New Tyre T-171 2x 255/70/ Tyres on POS 1 & 2 (done by Craig)	Beaurepairs
25/11/2016		B - 40k S-504 Greased and inspected all brake systems for leaks, Checked Lights, Lenes & Reflectors Curtains, Tyre Pressures all Checked Joe1 to 2pm	inhouse, JOE
07/11/2016		Inspection T-142 Position 1 getting Close	Beaurepairs
31/10/2016		A - 20k S-458 Carry out minor service as per vawdrey minor service sheet remove and replace number plate lights replace 1x amber reflector on L/H/S	Vawdrey Australia Pty Ltd
21/10/2016		New Tyre T-124 New Tyres Pos on 9 & 10 on Trailer B tyres from Stef's Rack	Beaurepairs
10/10/2016		B - 40k S-416	Vawdrey Australia Pty Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out A service as per vawdrey fleet service sheet	
19/09/2016		A - 20k S-368 Repair Trailer Greased & Adjust Brakes as per Vawdrey Fleet Service Sheet	Vawdrey Australia Pty Ltd
14/09/2016		Registration O-76	Transport SA
24/08/2016		B - 40k S-348	inhouse
03/08/2016		C - Annual S-349 Rebuild Trailers,m Brakes & Bearings all parts supplied (Labour 7.5HRS) See attached invoice	inhouse
21/07/2016		B - 40k S-301 nick completed service Check Wheel Bearings -Completed Checked Condition & Security of Spare Wheels & Carrier - Completed Checked Lights, Lenses & Reflectors -Completed Checked Numbers Plate, Rego & NHVAS Label - Completed Curtain Repairs	Inhouse
30/06/2016	199,788 kms	A - 20k S-287 Fitted auto slack adjusters to both trailer 2 x slack adjusters & 2 x boosters rear axle Joe 9.00-2.30	Inhouse
27/06/2016	99 kms	New Tyre T-62 Taken out and fitted to trailer 255/70R22.5 Remington R145A 140/137L TL x3	Beaurepaires
17/06/2016	615,377 kms	B - 40k S-270 Replaced tyre A trailer front axle put 2x run out tyres on B trailer gate face catch broken replaced catch with second hand one. Joe 1-3	Inhouse
26/05/2016		A - 20k S-250 weld air tank back on to chassis on B-Trailer NICK 1.15 pm-6.30pm	Inhouse
03/05/2016		B - 40k S-223 nick 12-2.15	Inhouse
08/04/2016		A - 20k S-75 REPLACED GREASE NIPPLE RHS Joe 9 - 10.15	Inhouse
12/03/2016	135,034 kms	B - 40k S-54 TIGHTENED ALL WHEEL BEARINGS *NOTE WURTH REAR AXLE BRAKE WEAR STEF 12.30-1.30 1hr	Inhouse
15/02/2016		A - 20k S-4 Straight service, no problems. Nick 2.5hrs	Inhouse
31/01/2016		B - 40k S-146 Grease adjust brakes grease t/t check lights & bearings change tyre pos 6	Inhouse
29/01/2016		Insurance O-26	Global Transport & Automotive Solutions
08/01/2016		A - 20k S-144 Grease adjust brakes grease t/t check lights change tyre pos 3 paint rim	Inhouse
30/11/2015		B - 40k S-142 Grease adjust brakes grease t/t check lights check bearings	Inhouse
09/11/2015		A - 20k S-140 Grease adjust brakes grease t/t check lights wash trailers check bearings	Inhouse
19/10/2015		B - 40k S-138 Grease adjust brakes grease t/t check lights & bearings	Inhouse
28/09/2015		A - 20k S-136 Grease adjust brakes grease t/t check lights	Inhouse

Date	Reading / Units	Type / Repairer Notes	Repairer
10/09/2015		Registration O-151	Transport SA
07/09/2015		C - Annual S-134 Annual service; new bearings new king pins checked swing arm bushes & rear lights put new ply in new drop tarps PASSED ROADWORTHY INSPECTION	Inhouse

Signed: _____

Name: _____

Date: _____