

Vehicle History Summary



Fleet #	20B
Registration	0354S6
Make	KREUGER
Model	TRAILER
VIN / Chassis #	6FH8517DD6M011347
Build Date	2006

Date	Reading / Units	Type / Repairer Notes	Repairer
07/04/2026	1,276,281 kms	Trailer Inspection Report I-544	STEFS TRANSPORT
07/04/2026	1,276,281 kms	Broken gates R-5743 Rollers on gate head broken	STEFS TRANSPORT
07/04/2026	1,276,281 kms	Clear Defect R-5838 ADJUST OSF & OSR BRAKES & CLEAR DEFECT DEFECT NOTICE CLEARANCE CA2987719 FOR HVN0751001	Krueger
02/04/2026	1,276,281 kms	New Tyre, Rotate T-4374	Trident Tyre Centre
19/03/2026	1,981,898 kms	B - 40k S-7412 Conducted B Service Trailers Loaded Visual on suspension Return to service	STEFS TRANSPORT
21/01/2026	1,958,799 kms	A - 20k S-7330 Conducted A Service Replaced 1 X Red Side Light Returned to service	STEFS TRANSPORT
19/12/2025	1,276,281 kms	curtain pole R-5580	STEFS TRANSPORT
04/12/2025	1,940,668 kms	C - Annual S-7188 Conducted C Service Replaced 3 X 3/8 straight air joiners Replaced 1 X 3/8 - 1/4 air elbow Replaced 2 X 3/8 air joiners Replaced 1 X Williams control valve Replaced 1 X Brake valve Replaced 1 X Relay valve Replaced all brakes & Hardware Replaced all hubcap gaskets Replaced all prorotque nuts Replaced all bearings & seals Replaced 1 X Red Reflector Replaced 1 X 660 strap and buckle Returned to service	STEFS TRANSPORT
02/12/2025	1,276,281 kms	Heavy Trailer Inspection Checklist I-488	STEFS TRANSPORT
06/11/2025	1,276,281 kms	Fault, Runout T-4195 runout to pos 3 656755km	STEFS TRANSPORT
17/10/2025	1,276,281 kms	New Tyre T-4171 new haulstar ha615 fitted to pos 5,6,9,10 runouts fitted to pos 11,12 649101km	STEFS TRANSPORT
17/10/2025	1,925,382 kms	B - 40k S-7164 Conducted B Service Repair pelmet rubber R/H/S Return to service	STEFS TRANSPORT
11/09/2025	1,905,144 kms	A - 20k S-7103 Conducted A Service Replaced 1 X Red/Amber side light Returned to service	STEFS TRANSPORT
21/08/2025		Registration O-1880	Vic Roads
11/08/2025	1,276,281 kms	Lights R-5145	Stef's Transport
11/08/2025	1,885,943 kms	B - 40k S-7019	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
		Conducted B Service All Checks OK Return to service KLM require update in G.Box	
18/06/2025	1,276,281 kms	Curtain straps R-5229 Replaced 6 X Buckles and straps Ride height @ 4.6	STEFS TRANSPORT
18/06/2025	1,276,281 kms	Runout T-3993 runouts fitted to pos 6,11 turn on rim pos 7	STEFS TRANSPORT
21/05/2025	1,276,281 kms	air leak, Brake adjustment, Hub R-5182	Ferguson's Diesel Services
21/05/2025	1,276,281 kms	curtain pole R-5164 Straightened L/H/Rear curtain pole Replaced 1 X amber reflector Returned to service	STEFS TRANSPORT
21/03/2025	1,276,281 kms	Trailer Inspection Report I-287	STEFS TRANSPORT
05/03/2025	1,276,281 kms	Reflector, Roof Repairs R-4940 Repaired roof L/H/S Weld Lower L/H/S (Crack) Replace top L/H/Rear Light Replace L/H/R Red Reflector Reset trailer height 458	STEFS TRANSPORT
05/03/2025	1,276,281 kms	Trailer Inspection Report I-262	STEFS TRANSPORT
24/01/2025	1,276,281 kms	Trailer Inspection Report I-206	Stef's Transport
29/11/2024	1,276,281 kms	Heavy Trailer Inspection Checklist I-127	STEFS TRANSPORT
29/11/2024	1,276,281 kms	Cracks R-4804 Ground & Welded cracks in R/H/S front frame	STEFS TRANSPORT
29/11/2024	1,786,671 kms	C - Annual S-6585 Conducted C Service Replaced Pos 3 S/Cam Replaced Pos 2 & 4 Z/Cam Replaced Pos 1, 2 & 4 Cam Tubes Replaced 3M 1/2" air line Replaced all brakes & hardware Replaced all wheel bearings & Seals Replaced all hubcap gaskets Replaced all pro torque nuts Replaced Kingpin & Bolts Replaced 2 X Red Reflectors Painted rear of trailer Returned to service	STEFS TRANSPORT
22/11/2024	1,276,281 kms 14 hrs	curtain Handle R-4800 Replaced R/H Curtain handle	STEFS TRANSPORT
28/10/2024	1,276,281 kms	New Tyre T-3702 new sailun s637+ fitted to pos 7,8 turn on rim pos 6 runout to pos 10	STEFS TRANSPORT
28/10/2024	1,776,705 kms	B - Bi Monthly S-6526 Conducted B Service Replaced Female Light plug Replaced Pos 3 & 6 Shockers Replaced 2 X Amber reflectors Adjust all wheel bearings Returned to service	STEFS TRANSPORT
28/10/2024	1,276,281 kms	Electrical R-4765 Repaired @ Service 6526	STEFS TRANSPORT
21/08/2024	1,753,939 kms	A - Monthly S-6430 Conducted A Service (Paperwork is incorrect and was B service label WS) Replaced Pos 3 Shocker Replaced 1 X Amber reflectors Repaired L/H/S wiring for indicator Returned to service	STEFS TRANSPORT
22/07/2024		Registration O-1367	VicRoads
15/07/2024	1,276,281 kms	Gate Repairs R-4629 Repaired L/H/Rear gate & Latch	STEFS TRANSPORT
24/06/2024	1,734,321 kms	B - Bi Monthly S-6346 Conducted B Service (Paperwork is incorrect and labelled A service WS) Repaired Curtain R/H/S Returned to service	STEFS TRANSPORT
05/06/2024	1,276,281 kms	Curtain Repair R-4562 Replaced L/H Curtain handle	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
15/05/2024	1,276,281 kms	Air Repairs R-4524 No air leak found Repaired wiring for top rear lights Repaired roof L/H/S in 2 Places Replaced 1 X Amber side light Replaced 1 X Red/Amber side light Repaired 7 Pin female light plug. Returned to service	STEFS TRANSPORT
30/04/2024	1,276,281 kms	New Tyre T-3517 new haulstar ha109 fitted to pos 1,2,3,4 new haulstar ha615 fitted to pos 11,12 turn on hub pos 5,9 turn on rim pos 7 pressure check x 6	STEFS TRANSPORT
08/04/2024	1,716,053 kms	A - Monthly S-6225 Conducted A Service Replaced Male bulkhead Returned to service	STEFS TRANSPORT
08/04/2024	1,276,281 kms	Runout T-3483 runout to pos 9	STEFS TRANSPORT
20/02/2024	1,698,287 kms	B - Bi Monthly S-6140 Conducted B Service Replaced 1 X Amber reflector Repaired 1 X Gate Repaired 1 X Curtain L/H/S Replaced 4 X 660 straps Returned to service	STEFS TRANSPORT
12/02/2024	1,276,281 kms	Defect Notice R-4363 Cut off damaged outer plate & straightened Guard	STEFS TRANSPORT
12/01/2024	1,276,281 kms	Curtain Repair R-4304 Plated curtain & patched tear	STEFS TRANSPORT
07/12/2023	1,679,328 kms	A - Monthly S-6018 Completed A Service Replaced Shockers Pos 3 & 6 Tightened Nuts on Brake Booster Pos 1	STEFS TRANSPORT
31/10/2023	2,552,562 kms	Curtain Repair R-4164 Replaced curtain tensioner	STEFS TRANSPORT
19/10/2023	1,661,453 kms	C - Annual S-5927 Completed C Service	STEFS TRANSPORT
19/10/2023	1,276,281 kms	New Tyre T-3236 Pos 3, 4, 5, 6, 7 & 8 NEW	STEFS TRANSPORT
09/10/2023	1,658,184 kms	A - Monthly S-5908 A service completed	STEFS TRANSPORT
09/10/2023	1,276,281 kms	New Tyre T-3203 Pos 9 & 10 NEW	STEFS TRANSPORT
31/08/2023	1,643,180 kms	B - Bi Monthly S-5776 Conducted B Service No parts required. Returned to service	STEFS TRANSPORT
21/08/2023		Registration O-838	Vic Roads
09/08/2023	1,276,281 kms	New Tyre T-3113 new haulstar tyres fitted to pos 11,12	STEFS TRANSPORT
19/06/2023	1,625,749 kms	A - Monthly S-5625 Conducted A Service Replaced 1 X red/amber side light Replaced rear left stop /tail	STEFS TRANSPORT
09/05/2023	1,610,224 kms	B - Bi Monthly S-5459 Conducted B Service 4 X Amber reflectors Trailer loaded	STEFS TRANSPORT
09/03/2023	1,589,433 kms	A - Monthly S-5296 Conducted A Service Replaced L/H Indicator Replaced 1 X 660 Strap Repaired 2 X Gate RHR & L/H/Rear No NHVR Sticker present	STEFS TRANSPORT
09/03/2023	1,276,281 kms	Runout T-2951 runouts to pos 7,8 turn on rim pos 3	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
09/03/2023	1,276,281 kms	Electrical R-3501 Carried out on S-5296	STEFS TRANSPORT
12/01/2023	1,576,021 kms	C - Annual S-5167 Conducted C Service Replaced all brake shoes Replaced all bearings Replaced all pro torque nuts Replaced all hub cap gaskets replaced 4 Cam tube kits Replaced 1 X S/Cam Replaced 2 X Z cams Replaced 4 X Auto slack adjusters Replaced 3 X Amber reflectors	STEFS TRANSPORT
30/12/2022	1,276,281 kms	Breakdown R-3374 - Caged out the booster and attempted to move the trailer. - Found the wheels still to be locked on. - Backed off the slack adjuster and retried, no change. - Found the S Cam to be locked on, managed to get the scam loose. - Advised driver to take trailer straight to a tyre repairer. (Which has been undertaken)	Ferguson's Diesel Services
29/12/2022	1,276,281 kms	New Tyre T-2808 2 x new tyres in back 2 positions	Trident
23/12/2022	1,575,991 kms	B - Bi Monthly S-5133 conducted B Service Replaced Pos 4 auto slack adjuster Replaced Pos 1 30/30 brake booster Replaced brake shoes and hardware kit Replaced S/Cam Replaced auto slack adjuster Replaced s/cam tube and kit	
24/10/2022	1,557,888 kms	A - Monthly S-4949 Conducted A Service Replaced Pos 6 shocker Replaced bolts on 2nd air tank replaced 4 X 660 straps	STEFS TRANSPORT
25/08/2022	1,542,254 kms	B - Bi Monthly S-4742 Conduct B service x1 tail light p2 wheel bearing adjusted repaired front marker light wiring loaded	STEFS TRANSPORT
21/08/2022		Registration O-533	Vic Roads
12/08/2022	1,276,281 kms	New Tyre, Runout T-2660	Goodyear
04/08/2022	1,276,281 kms	Tyres R-2993 replaced Pos 11 & 12 tyres Repaired rear wall top panel (made up panel for top of trailers and fitted)	STEFS TRANSPORT
04/08/2022	1,276,281 kms	New Tyre T-2649	Goodyear
04/08/2022	1,276,281 kms	Roof Repairs R-2999 All ready completed	STEFS TRANSPORT
18/07/2022	1,521,101 kms	A - Monthly S-4646 Conducted A Service Replaced Pos 1 auto slack adjuster All checks OK	STEFS TRANSPORT
15/07/2022	1,276,281 kms	Gate Repairs R-2924 Replaced all ply boards Replaced 4 X Gate rollers	STEFS TRANSPORT
24/06/2022	1,276,281 kms	New Tyre T-2595	Goodyear
25/05/2022	1,501,491 kms	B - Bi Monthly S-4486 conducted B service loaded	STEFS TRANSPORT
14/04/2022	1,485,486 kms	A - Monthly S-4392 Conducted A Service Trailers Loaded	STEFS TRANSPORT
11/03/2022	1,467,578 kms	B - Bi Monthly S-4320 Conducted B Service	STEFS TRANSPORT
22/02/2022	1,276,281 kms	New Tyre, Runout T-2442	Goodyear
02/02/2022	1,276,281 kms	Brake Repairs R-2619 Inspected the trailer and found that the female bulk head was leaking and replaced it also found the the trailer supply valve was not opening to allow air to pass, removed the valve and serviced it fitted it back to the trailer and tested OK	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
11/01/2022	1,450,630 kms	A - Monthly S-4164 conducted A service	STEFS TRANSPORT
15/11/2021	1,433,323 kms	B - Bi Monthly S-4046 conducted B service x2 gate repaired x1 front amber marker	STEFS TRANSPORT
11/11/2021	1,276,281 kms	New Tyre T-2346	Goodyear
09/11/2021	1,276,281 kms	New Tyre T-2306	Goodyear
09/11/2021	1,276,281 kms	Gate Repairs R-2469 refitted gate and fitted new stopper in gate track	STEFS TRANSPORT
15/09/2021	1,419,590 kms	C - Annual S-3917 Carried out C service Cleaned all s/cams and slack adjusters Changed out 4 gate rollers	STEFS TRANSPORT
31/08/2021	1,417,209 kms	A - Monthly S-3872 Conducted A service Lubricated all gate and curtain rollers Replaced 1 X 660 strap Some gate rollers require replacement next available slot	STEFS TRANSPORT
21/08/2021		Registration O-425	Vic Roads
23/07/2021	1,276,281 kms	New Tyre, Runout T-2190	Goodyear
23/07/2021	1,276,281 kms	Ratchet R-2289 Replaced Pin in L/H/Side ratchet handle	STEFS TRANSPORT
21/07/2021	1,276,281 kms	Air Bag R-2280 Replaced Pos 2 & 6 air bag	STEFS TRANSPORT
16/07/2021	1,276,281 kms	Water Leak R-2266 Removed old Sikaflex, cleaned area and resealed.	STEFS TRANSPORT
07/07/2021	1,398,169 kms	B - 40k S-3740 Carried out B service Found Pos 4 wheel bearing to be loose, adjusted wheel bearing , Tested OK	STEFS TRANSPORT
07/06/2021	1,276,281 kms	Bearings R-2176 Loose bearings found on Pos 2, 3,4, & 6. All wheel bearings checked and adjusted.	STEFS TRANSPORT
11/05/2021	1,381,341 kms	A - 20k S-3610	STEFS TRANSPORT
09/04/2021	1,276,281 kms	Curtain Repair R-2057	Aerial Tarps Pty Ltd
01/04/2021	1,365,993 kms	B - 40k S-3514 P3 Shock absorber replaced Air leak repaired & P2 brake booster repaired	STEFS TRANSPORT
31/03/2021	1,276,281 kms	Gate Repairs R-2025 Gate roller lubed, working fine	STEFS TRANSPORT
30/03/2021	1,276,281 kms	New Tyre T-2080	Goodyear
09/03/2021	1,355,610 kms	Air Bag R-1982 Call out and travel after hours to replace airbag on trailer	Moore Mechanical
22/02/2021	73,777 kms	Gate Repairs R-1899 repair broken gates	STEFS TRANSPORT
22/02/2021	1,350,058 kms	Runout T-2048	Beaurepaires AU
15/02/2021	1,346,961 kms	A - 20k S-3432	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
09/02/2021	1,276,281 kms	Electrical R-1889 RH tail light insert replaced all satis	STEFS TRANSPORT
05/02/2021	1,276,281 kms	Height Control Valve R-1906 Concern: Supply and fit Ride Height Valve Cause : Valve not opening Correction Marked lines undone lines removed valves fitted Valve , Adjusted Valve,fitted lines Adjusted height of Trailer	Blue Lake
25/01/2021		Electrical R-1854 replace plastic pin holder in centre and rewire plug	STEFS TRANSPORT
08/01/2021	1,276,281 kms	Electrical R-1843 1x RH indicator replaced air tank removed and repaired all satis krueger latch fitted to LH first gate	STEFS TRANSPORT
05/01/2021	1,276,281 kms	Air Repairs R-1819 repaired during service by 3MP all satis	STEFS TRANSPORT
05/01/2021	1,329,725 kms	B - 40k S-3344 A service C/O all satis P1 airbag replaced various booster clamps replaced air tank bracket welded by 3MP all satis	STEFS TRANSPORT
01/12/2020	1,276,281 kms	Skip Plate R-1693	Truck Factory
01/12/2020	1,276,281 kms	Electrical R-1784 tail lights fitted as should all satis 1x LH stop/tail light replaced 1x RH indicator insert fitted fitted all new reflectors as none fitted all ply/ floor tarps put back in all satis	STEFS TRANSPORT
03/09/2020	1,315,475 kms	C - Annual S-3121 C service C/O all satis all hubs replaced with all new bearings all drums replaced all brake shoes replaced all shockers replaced 4x s cam tube repair kits fitted front wall repaired by 3MP all satis	Garners Garage, STEFS TRANSPORT
31/08/2020		Registration O-338	Vic Roads
18/08/2020		Electrical R-1603 rear indicator	STEFS TRANSPORT
17/08/2020	1,311,288 kms	A - 20k S-3079 all ok	TSR - Transport Servicing and Repairs
08/07/2020	1,276,281 kms	New Tyre, Runout T-1740 4x 265/70/19.5 NEW (TRAN) TYRE'S PLACED AT PO'S 5-6-7-8 1x 265/70/19.5 RUN OUT PLACED AT PO'S 4 REPLACED BY BRENT	Beaurepaires
01/07/2020	1,290,651 kms	B - 40k S-2986 B service C/O all satis all RH wheel bearings torqued all satis.\ RH inner indicator replaced all satis landing gear handle re attached	STEFS TRANSPORT
24/06/2020	1,276,281 kms	Air Bag R-1512 P5 airbag replaced all satis Rubber keeper replaced on height control rod as it had split	STEFS TRANSPORT
02/06/2020	1,276,281 kms	Runout T-1721 1x 265/70R19.5 TYRE RUN OUT PLACED AT POS 3 1x 265/70R19.5 TYRE TURNED ON RIM AT POS 7 REPLACED AND DONE BY BRENT	Beaurepaires
01/06/2020	1,276,281 kms	New Tyre T-1717 2x 265/70R19.5 (TRAN) PLACED AT POS 11-12 REPLACED BY BRENT	Beaurepaires
26/05/2020		Electrical R-1446 indicator repaired all satis.	STEFS TRANSPORT
19/05/2020	1,276,281 kms	A - 20k S-2899 A service C/O all satis	STEFS TRANSPORT
08/05/2020		New Tyre T-1689	Beaurepaires

Date	Reading / Units	Type / Repairer Notes	Repairer
		2x 265/70R19.5 NEW TYRE'S PLACED AT POS 9-10 REPLACED BY BRENT	
23/04/2020	1,276,281 kms	B - 40k S-2845 B service C/O all satis Gates repaired all satis	STEFS TRANSPORT
17/04/2020		Gate Repairs R-1383 gate latch replaced all satis	STEFS TRANSPORT
09/04/2020		Runout T-1627 1x 265/7019.5 RUN OUT TYRE PLACED AT POS 11 DONE BY BRENT ORDER No1468	Beaurepaires
26/03/2020		A - 20k S-2754 A service C/O all satis. gates repaired long vehicle sign fitted to back of unit.	STEFS TRANSPORT
26/03/2020		Gate Repairs R-1326 broken gates repaired in service all satis.	STEFS TRANSPORT
26/03/2020		Curtain Repair R-1328 curtain strap fitted at a earlier date. all satis.	STEFS TRANSPORT
24/02/2020		B - 40k S-2676 B service C/O all satis. all bearings checked ok.	STEFS TRANSPORT
20/02/2020		Height Control Valve R-1289 rubber keeper on height control valve rod had split, rubber replaced and all works all satis.	STEFS TRANSPORT
13/02/2020		New Tyre T-1556 2 new tyres	Beaurepaires
28/01/2020		A - 20k S-2612 A service C/O all satis.	STEFS TRANSPORT
14/01/2020		Roof Repairs R-1225 Roof resealed and stuck down all satis pelmut rubber trimmed will need replacing soon (A trailer)	STEFS TRANSPORT
27/12/2019		B - 40k S-2539 B service C/O all satis.	STEFS TRANSPORT
26/11/2019		A - 20k S-2478 A service C/O all satis all clamps gone over all satis 1x front clearance light re fitted all satis.	STEFS TRANSPORT
01/11/2019		Electrical R-1127 new 7 pin base fitted and problem fixed all satis.	STEFS TRANSPORT
24/10/2019		B - 40k S-2404 B service P4 bearing adjusted all others checks ok. all satis went over all clamps all satis tracks for gates and curtains lubed inside cleaned out and decks dropped	STEFS TRANSPORT
25/09/2019		A - 20k S-2345 A service C/O all satis. air leaks repaired all satis RH curtain bottom seal re attached to curtain all curtain and gate tracks lubricated and all stoppers adjusted all satis.	STEFS TRANSPORT
04/09/2019		Registration O-264	
28/08/2019		C - Annual S-2252 C service C/O all satis all bearings replaced all shoes replaced. (replace drums next C service). all s cams re shimmed. all satis all shockers replaced 6x hub gaskets all gates and uprights repaired and lubed	
07/08/2019		Roof Repairs R-1015 Front of roof repaired and sealed. all satis	STEFS TRANSPORT
01/08/2019		Water Leak R-1007	STEFS TRANSPORT

Date	Reading / Units	Type / Repairer Notes	Repairer
		Cracks welded up all satis. gates and curtain tracks lubricated (A trailer as well) trailers cleaned out and decks dropped trailers washed	
23/07/2019		Electrical R-987 top amber clearance light replaced. roof leaks resealed and rivited. all satis	STEFS TRANSPORT
15/07/2019		A - 20k S-2168 A service C/O all satis height control adjusted. decks dropped too.	STEFS TRANSPORT
19/06/2019		B - 40k S-2101 all fine underneath, washed trailers	NICK, STEFS TRANSPORT
30/05/2019		Roof Repairs, Trailer Front & Rear Wall & Door Repairs R-922 Weld up cracks in back walls, rivet pelmut rubber covers back on and sikaflex up holes in roof.	STEFS TRANSPORT
16/05/2019		A - 20k S-2031 Carry out A service	STEFS TRANSPORT
07/05/2019		Air Repairs R-871 Remove and replace one way valve on front air tank, replace relay valve on centre axle (backfeeding into front air tank), replace leaking air fitting on relay valve.	STEFS TRANSPORT
18/04/2019		B - 40k S-1934 carry out b service, adjust all wheel bearings	
06/03/2019		A - 20k S-1878 all good underneath	Garners Garage
20/02/2019		Ratchet R-765 replace broken ratchet handle	kruger
14/02/2019		New Tyre T-1313	
07/02/2019		B - 40k S-1813 two hose clamps loose,	NICK, STEFS TRANSPORT
07/01/2019		A - 20k S-1745 made 2 locking pins for the mezz floor decks checked all hose clamps and washed trailers	STEFS TRANSPORT
11/12/2018		B - 40k S-1689 dropped mezz floors	Garners Garage
15/11/2018		A - 20k S-1635	
23/10/2018		New Tyre T-1260 2 X NEW 265/70/19.5 FITTED	Beaurepaires
19/10/2018		Ratchet R-655 replace handle	kruger
16/10/2018		B - 40k S-1580 repair gates, replace tyres	STEFS TRANSPORT
15/10/2018		Water Leak R-652 reseal the roof	STEFS TRANSPORT
19/09/2018		A - 20k S-1504 check and adjust brake's check wheel bearings adjust gates weld repair to gate	
29/08/2018		New Tyre T-1193 2X NEW TYRES 265/70R19.5 PLACED AT POS 11+12	Beaurepaires

Date	Reading / Units	Type / Repairer Notes	Repairer
20/08/2018		C - Annual S-1454 changed all shocks greased all points replaced all brake linings replaced back wall and painted fixed all lights lube all curtain runners -weld up cracks in the the gates replacedn3 x scam tube kits	STEFS TRANSPORT
29/07/2018		B - 40k S-1403 adjusted brakes and adjusted bearings that were loose, checked all air fittings	STEFS TRANSPORT
25/06/2018		Electrical R-582 Attend B Trailer at BP with No Side Lights	TSR - Transport Servicing and Repairs
07/06/2018		A - 20k S-1339	STEFS TRANSPORT
08/05/2018		New Tyre T-1114 FROM STEFS RACK 2 X 265/70/19.5 NEW TYRES PLACED AT POS 5&6	Beaurepaires
08/05/2018		B - 40k S-1240	
07/05/2018		Electrical R-543 Attend Trailers At BP Rocklea Check Wiring Found Broken Wires To Tail Lights Repaired Wires Test All Light Test OK Found No Number Plate Working On One Side Rear Of B Trailer Found Fuse Box And Rear Of B Trailer To Be Damaged And needing Attention Found One Side Light Out On Lhs Of A trailer	TSR - Transport Servicing and Repairs
07/05/2018		Electrical R-538 Attend Trailers At BP Rocklea Check Wiring Found Broken Wires To Tail Lights Repaired Wires Test All Light Test OK Found No Number Plate Working On One Side Rear Of B Trailer Found Fuse Box And Rear Of B Trailer To Be Damaged And needing Attention Found One Side Light Out On Lhs Of A trailer	TSR - Transport Servicing and Repairs
14/03/2018		A - 20k S-1181 height control valve leaking new one ordered	STEFS TRANSPORT
03/03/2018		Electrical R-510 SIKA FLEX METAL UP AND REPAIR LIGHT	DAMON, STEFS TRANSPORT
05/02/2018		B - 40k S-1119 TIGHTEN WHEEL BEARINGS	Garners Garage
23/12/2017		New Tyre T-943 2 X 265/70R19.5 TYRES PLACED AT POS 9/10	Beaurepaires
20/12/2017		A - 20k S-1072 LHS marker light not working RHSF reflector missing Number plate light not working LHS rear tyre US bearing movement in all axles	TSR - Transport Servicing and Repairs
22/11/2017		New Tyre T-860 2x265/70R19.5 TYRES PLACED AT POS 5 & 6	Beaurepaires
22/11/2017		B - 40k S-1022 GREASED ALL LUBRICATION POINTS INSPECTED BRAKES CHECKED WHEEL BEARINGS CHECKED SPARE WHEEL AND CARRIER CHECKED LIGHT ALL LIGHTING CHECKED TYRE PRESSURES, GREASED TURN TABLE, NUMBER PLATE & NHVAS LABEL CONDITION	Garners Garage
25/10/2017		A - 20k S-970	Garners Garage
28/09/2017		Inspection T-718 TYRES ALL GOOD SERVICER- CRAIG	Beaurepaires
18/09/2017		Inspection T-675 TYRES ALL GOOD	Beaurepaires
15/09/2017		Mezzanie Floors, Sat Tracker R-322 Mezzanine floors adjusted then Sat Tracker added to trailers,	Garners Garage, JOE

Signed: _____

Name: _____

Date: _____