



Vehicle History Detail

Fleet #	
Registration	
Make	VOLVO
Model	FH540
VIN / Chassis #	YV5RG40D5KD209588

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
24/07/2026		DECOMMISSION R-65848			\$154.00
16/09/2025		SEAT BASE R-45123 NOT REPAIRED GONE TO SYDNEY.			\$0.00
16/09/2025	1,184,243 kms	ENGINE DE-RATE, FAULT REPORT R-49284 ADBLUS PUMP NOT REPLACED GONE TO SYDNEY.			\$728.38
16/09/2025		GEARBOX ISSUE R-49095	JT FOSSEY -10		\$0.00
01/09/2025	1,183,010 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-2430 ANNUAL INSPECTION CARRIED OUT BY MICK BRETT KMS 1183010			\$0.00
01/09/2025	1,183,010 kms	TOP LIGHT R-48865			\$510.52
26/08/2025	1,182,855 kms	GEARBOX ISSUE R-48658	JT FOSSEY -10		\$253.00
21/08/2025	1,181,900 kms	GENERAL REPAIRS R-48113			\$1,561.94
18/08/2025	1,181,745 kms	PUNCTURE REPAIR T-13688 TYRE REPAIR CHRIS KMS 1181745			\$154.00
08/08/2025		LIGHT INOP, TAIL LIGHT R-47592			\$562.91
06/08/2025	1,180,125 kms	SUZY AIR FITTING, TURNTABLE R-47648			\$231.00
23/07/2025	1,177,260 kms	B - 20K/180Days S-23766 (B) SERVICE CARRIED OUT BY BRETT JUSTICE COOPER KMS 1177260			\$1,020.00
23/07/2025	1,177,260 kms	NUT, YOKE R-46970			\$223.38
21/07/2025		AIR LEAK, CALL OUT R-46973			\$308.00
03/07/2025	1,172,024 kms	BREAKDOWN R-46084			\$1,683.00
24/06/2025	1,168,343 kms	BREAKDOWN R-45601			\$770.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
23/06/2025	1,165,206 kms	FAN, FAN RESISTOR R-45367			\$1,578.00
13/06/2025	1,167,032 kms	TRAILER PLUG R-45159			\$87.55
03/06/2025	1,163,836 kms	A - 10K/90Days S-22779 (A) SERVICE CARRIED OUT BY JUSTICE COOPER KMS 1163836 C77421 - REPLACED BULB RHS HEADLIGHT.			\$332.02
09/05/2025	1,159,742 kms	AIR LEAK R-43565			\$200.38
09/04/2025	1,154,337 kms	PARK BRAKE ALARM R-42223	JT FOSSEY -10		\$295.35
17/03/2025	1,152,523 kms	B - 20K/180Days S-21242 (B) SERVICE CARRIED OUT BY JUSTICE, PAT KMS 1152523			\$712.00
10/03/2025	1,151,990 kms	BACKING PLATE R-40844			\$77.00
28/02/2025	1,150,874 kms	GEARBOX ISSUE R-40528	JT FOSSEY -10		\$4,153.17
11/02/2025	1,149,811 kms	AIR BAG R-39512			\$323.60
30/01/2025	1,148,202 kms	AIR BAGS R-38841			\$1,730.92
15/01/2025		BLOWN TYRE T-10787 TRAVEL TO LOCATION LIFT AXLE ASSESS DAMAGE REPLACE STEER SHANE, MICK KMS 1143645			\$1,960.00
05/01/2025	1,143,473 kms	A - 10K/90Days S-19863 (A) SERVICE CARRIED OUT BY PAT, JARRAH KMS 1143473 NB: NEEDS 6 AIR BAGS KING PIN HAS MODERATE MOVEMENT LHS			\$308.00
24/12/2024	1,141,131 kms	TYRE PUNCTURED T-10512 REPAIR PUNCTURE SHANE KMS 1141131			\$77.00
22/11/2024	1,135,081 kms	OIL LEAKS R-36144			\$611.99
18/11/2024	1,134,282 kms	FLAT BATTERIES R-35832 REPLACED			\$935.11
08/11/2024	1,132,534 kms	COOLANT LEAK R-34844			\$3,234.27
06/11/2024	1,132,987 kms	C - 100K/365Days S-18865 (C) SERVICE CARRIED OUT BY MICK, BRETT, JARRAH, SHANE KMS 1132987 JARRAH REPLACE BROKEN SPRING FOR FILTER			\$2,512.25
06/11/2024		TURNTABLE R-35422			\$2,591.98
07/09/2024	1,123,843 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-1773 ANNAUL INSPECTION CARRIED OUT BY BRETT KMS 1123843 NO ISSUES RAISED			\$0.00
07/09/2024	1,123,843 kms	A - 10K/90Days S-17538 (A) SERVICE CARRIED OUT BY BRETT KMS 1123843 REMOVE AND REPLACE 3RD AXLE LHS BRAKE CALIPER			\$1,265.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
30/08/2024	1,122,090 kms	NEW TYRE T-9445 TYRE CHANGES STUART KMS 1122090			\$1,335.50
30/08/2024	1,122,134 kms	AIR LEAK R-32445 NO ACTION TAKEN			\$77.00
21/08/2024	1,120,216 kms	AIRBAG R-31916 REPLACED			\$1,485.00
16/08/2024	1,118,281 kms	CLUTCH ISSUE R-32650 FIXED	JT FOSSEY -10		\$13,335.30
25/06/2024	1,112,725 kms	B - 20K/180Days S-15459 (B) SERVICE CARRIED OUT BY EDWIN, PAT ,KMS 1112725 NO ISSUES RAISED			\$712.00
18/06/2024	1,111,396 kms	EXHAUST, TURBO R-28699 REPLACED GASKETS			\$1,927.11
08/05/2024	1,106,789 kms	PUNCTURE REPAIR T-8159 TYRE CHANGE STUART KMS 1106789 REPLACED RHSF INDICATOR BULB			\$119.17
11/04/2024	1,102,422 kms	TAIL LIGHT BAR BENT R-25939 REPAIRED			\$308.00
09/04/2024	1,102,424 kms	A - 10K/90Days S-13565 (A) SERVICE CARRIED OUT BY EDWIN AND JARRAH KMS 1102424 NO ISSUES RAISED			\$308.00
22/02/2024	1,096,325 kms	RUNOUT T-7101 TYRE CHANGES STUAT KMS 1096325			\$38.50
13/02/2024	1,094,395 kms	CLUTCH WORN R-24371 NO ACTION TAKEN			\$77.00
31/01/2024	1,091,391 kms	B - 20K/180Days S-12313 (B) SERVICE CARRIED OUT BY PAT AND EDWIN KMS 1091391 NO ISSUES RAISED			\$1,012.00
25/01/2024	1,090,505 kms	HEADLAMP R-22815 REPLACED			\$1,236.89
23/01/2024	1,089,649 kms	NEW TYRE T-6638 TYRE CHANGES BY STUART KMS 1089649			\$994.00
18/01/2024	1,088,502 kms	BLOWN HEADLIGHTS R-22485 REPLACED & REPAIRED			\$177.01
22/12/2023	1,181,895 kms	SEAT R-21931 NO ACTION TAKEN			\$77.00
19/12/2023	1,080,160 kms	ELECTRIC WINDOW, FUEL FILTER R-23343 REPAIRED			\$154.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/12/2023	1,079,460 kms	A - 10K/90Days S-11627 (A) SERVICE CARRIED OUT BY EDWIN AND PAT KMS 1079460 NO ISSUES RAISED			\$616.00
28/11/2023	1,075,507 kms	AIR FITTING R-20637			\$50.82
23/11/2023	1,074,158 kms	TYRE GOING FLAT T-5912 FIXED PUNCTURE ON TYRE RHSR LAST AXLE OUTER PAT KMS 1074158			\$154.00
18/11/2023	1,072,914 kms	RUNOUT T-5857 MADE CHANGES SHANE KMS 1072914			\$154.00
17/11/2023		REPAIRS R-19837			\$3,748.05
11/11/2023	1,070,838 kms	TAIL LIGHT ASSEMBLY R-20001			\$115.50
01/11/2023	1,069,636 kms	ELECTRICAL PLUG R-19704			\$77.00
31/10/2023	1,069,435 kms	TURNTABLE ADJUSTMENT R-19727			\$77.00
31/10/2023	1,069,435 kms	NEW TYRE T-5670 MADE CHANGES PAT, EDWIN, JUSTICE KMS 1069435			\$1,815.00
26/10/2023	1,068,216 kms	HEADLIGHT R-19900			\$73.83
18/10/2023	1,066,649 kms	B - 20K/180Days S-10274 (B) SERVICE CARRIED OUT BY EDWIN AND JUSTICE KMS 1066649 NO ISSUES RAISED			\$1,285.07
17/10/2023	1,066,190 kms	AIR SYSTEM R-23332			\$77.00
10/10/2023	1,064,496 kms	HEADLIGHT BULB OUT R-23339			\$38.50
13/09/2023	1,052,196 kms	BLIND SPOT MIRROR, BLOWN HEADLIGHTS, DAMAGED LIGHT PLUG, UHF R-17657			\$77.00
13/09/2023	1,052,196 kms	LOOSE STEP, UHF R-15462			\$154.00
08/09/2023	1,058,010 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-1062 ANNUAL INSPECTION CARRIED OUT BY PAT KMS 1058010			\$0.00
30/08/2023	1,055,657 kms	RUNOUTS T-5058 MADE CHANGES SHANE KMS 1055657			\$154.00
25/08/2023	1,054,577 kms	A - 10K/90Days S-9067 (A) SERVICE CARRIED OUT BY EDWIN AND JUSTICE KMS 1054577 NO ISSUES RAISED			\$308.00
14/08/2023	1,052,196 kms	HEADLIGHT BLOWN, SUZI LEAD PLUG R-16727			\$88.73
30/06/2023	1,013,048 kms	LOW BEAM R-15461			\$0.00
29/06/2023	1,040,828 kms	BRAKE CALIPER R-15467 NEED TO ORDER NEW CALIPER OR REKIT CALIPERS.			\$332.82
26/06/2023	1,039,463 kms	EXHAUST PIPE R-15469			\$1,189.94

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
13/06/2023	1,034,940 kms	TURNTABLE R-14915			\$279.71
09/06/2023	1,034,452 kms	BROKEN SUZI LEADS R-14944			\$0.00
09/06/2023	1,034,452 kms	B - 20K/180Days S-8113 (B) SERVICE CARRIE DOUT BY JUSTICE FIXED NEW MUDFLAP FIXED NEW DIM HEAD LIGHT WASHED TRUCK.			\$687.64
09/06/2023	1,034,452 kms	SUZI COIL R-15050			\$0.00
08/06/2023	1,033,802 kms	MUD GUARD R-15043			\$0.00
06/06/2023	1,033,802 kms	FRONT GUARD, MISSING MUDFLAP R-15042			\$0.00
31/05/2023	1,031,304 kms	BRAKE PAD R-15394			\$0.00
15/05/2023	1,027,740 kms	HEADLIGHT R-14056			\$0.00
12/05/2023	1,025,444 kms	MUFFLER, TURNTABLE, UHF R-19568			\$231.00
22/04/2023	1,018,157 kms	DIESEL FUEL TANK R-13401			\$0.00
20/04/2023	10,167,108 kms	UHF R-19585			\$77.00
14/04/2023	1,015,178 kms	CHECK ENGINE LIGHT R-13398 WORK CARRIED OUT BY JT FOSSEYS	JT FOSSEY -10		\$1,958.06
08/04/2023	1,015,880 kms	C - 100K/365Days S-7011 (C) SERVICE CARRIED OUT BY JUSTICE AND EDWIN 8/4/23			\$1,545.34
06/04/2023	1,015,450 kms	AIR SYSTEM R-15475			\$231.00
05/04/2023	1,015,017 kms	SWITCH R-13012			\$309.74
28/03/2023	1,012,609 kms	TURNTABLE R-12699			\$424.26
01/02/2023	992,365 kms	B - 20K/180Days S-6396 Washer bottle has hole, awaiting parts			\$0.00
01/02/2023	992,365 kms	RADIATOR HOSE R-10988 Replaced bottom radiator hose Refill with coolant			\$0.00
12/12/2022	980,402 kms	A - 10K/90Days S-5655 ENGINE OIL LEAK ON LHS OF ENGINE PARK BRAKE SWITCH IS DAMAGED / CRACKED			\$0.00
18/11/2022	970,630 kms	B - 20K/180Days S-5256			\$271.00
28/10/2022	965,629 kms 14,129 hrs	TURNTABLE R-8228 REPLACED			\$373.69
28/10/2022	965,629 kms 14,125 hrs	ENGINE R-8259 Test injector tubes tested OK Found faulty trs sensor replaced and tested OK			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
28/10/2022	965,629 kms	A - 10K/90Days S-4966			\$0.00
19/10/2022	960,221 kms	DASH LIGHTS R-7818 R & R nox sensor Clear all codes Road test			\$39.19
13/10/2022	960,192 kms	REPAIRS R-7847 1. Brake relined 1st, 2nd and 3rd axle.new brakes done 2. Replaced rear axle tyres with new Goodyear tyres done			\$1,228.78
12/10/2022	960,192 kms	C - 100K/365Days S-4661 C SERVICE COMPLETE DONE All axle brakes worn need replace No toll tag No gearbox filter No first aid kit			\$993.39
31/08/2022	928,441 kms	A - 10K/90Days S-4022 928441km			\$220.00
04/08/2022	1 kms	A - 10K/90Days S-4607 MAINTENANCE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$110.00
103 Records				Total:	\$74,085.26