

RITCHIE BROS. Diagnostic Report
 Auctioneers®

2019 Freightliner 106 Medium Duty
Test Information

Engine	Cummins L9 (9.0)
Engine Serial	CMMNS*6L u17D0890000000*74365373*21835
VIN	1FUBCXFE6KHKN4353
Driveline	Class 7 4x2
Body	Truck-Tractor
Test Time	Sept. 9, 2026, 10:29 a.m.
File Length	42.999 s

Usage

Label	Value	Units
Engine Odometer	186,046	mi
Odometer (Instrument Cluster #1)	186,046	mi
Engine Total Hours of Operation	6,910.7	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	8	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Body Controller	Manufacturer Assignable SPN	Voltage Below Normal	1
Previous	Body Controller	Windshield Wiper Motor Speed	Current Below Normal	69
Previous	Body Controller	Engine Starter Motor Relay Control	Current Below Normal	5
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	1
Previous	Body Controller	Source Address 3	Data Error	1
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	22
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	18
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	126
Previous	Body Controller	Front Operator Wiper Switch	Data Error	8
Previous	Body Controller	Front Operator Washer Switch	Data Error	8
Previous	Body Controller	Turn Signal Switch	Data Error	8
Previous	Body Controller	High-Low Beam Switch	Data Error	8
Previous	Proprietary	Source Address 33	Data Error	14
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Erratic, Intermittent, or Incorrect	2