

**KNW Diesel Inc.**  
 Unit C-1 19325 94th Avenue  
 Surrey, BC. V4N4E6  
 Phone: (604)-888-3440 | Fax: (604)-888-6692  
 www.knwdiesel.com | acc@knwdiesel.com

Invoice # **016747**  
 Original Est # 20802  
 GST#102867249  
 www.knwdiesel.com

# Invoice

**Paid** Balance Due: **\$0.00**

|                 |                                |                       |            |
|-----------------|--------------------------------|-----------------------|------------|
| <b>KNWCOV -</b> | <b>2012 Kenworth - T370</b>    | Work Complete:        | 03/31/2025 |
|                 | Paccar PX-6 CM2250 6 CYL       | Service Advisor:      | K C        |
|                 | VIN: 2NKHHM7X6 <b>CM326249</b> | Customer ID:          | 354        |
|                 | Odometer: In 0 Out 571,801     | Printed Date:         | 05/19/2026 |
|                 | Engine Hr: In 0.0 Out 12,222.0 | License Plate: Color: | WHITE      |

| Type                     | Description | Part # | Qty | Sale/Rate | Total         |
|--------------------------|-------------|--------|-----|-----------|---------------|
| <b>6 HOURS SHOP RATE</b> |             |        |     |           | <b>\$0.00</b> |

|       |   |                 |       |             |             |
|-------|---|-----------------|-------|-------------|-------------|
| Note  | CUMMINS (PACCAR) ISB 6.7 SER# 73302090 CPL# 3335  |                 |       |             |             |
| Note  | OIL IN COOLANT  |                 |       |             |             |
| Part  | PX6/ISB 6.7 SHORT BLOCK   | 4299372RX       | 1.00  | \$17,570.07 | \$17,570.07 |
| Part  | 4955523 UPPER GASKET KIT  | 131756          | 1.00  | \$859.28    | \$859.28    |
| Part  | 4955522 LOWER GASKET KIT  | 131854          | 1.00  | \$352.40    | \$352.40    |
| Part  | CYLINDER HEAD BOLT  | 3927063 (040054 | 26.00 | \$6.78      | \$176.28    |
| Part  | INJECTOR SEAL   | 3977393         | 6.00  | \$26.51     | \$159.06    |
| Part  | EXHAUST MANIFOLD GASKET   | 5447591         | 1.00  | \$6.52      | \$6.52      |
| Part  | EXHAUST CONNECTION GASKET   | 4932615         | 1.00  | \$6.89      | \$6.89      |
| Part  | TURBO GASKET  | 5260648 (131843 | 1.00  | \$24.47     | \$24.47     |
| Part  | HYDRAULIC PUMP GASKET   | M154916         | 1.00  | \$3.13      | \$3.13      |
| Part  | O-RING  | M3058653        | 4.00  | \$0.32      | \$1.28      |
| Part  | THERMOSTAT KIT  | 5627589 (181866 | 1.00  | \$36.68     | \$36.68     |
| Part  | OIL COOLER  | 141428          | 1.00  | \$299.80    | \$299.80    |
| Part  | 6.7 OIL PUMP  | M4939588        | 1.00  | \$149.47    | \$149.47    |
| Part  | BLOCK PLUG KIT  | 040107          | 1.00  | \$58.90     | \$58.90     |
| Part  | OIL PRESSURE SWITCH   | 5677803         | 1.00  | \$14.79     | \$14.79     |
| Part  | 3/4" PLUG   | A5142549        | 1.00  | \$2.87      | \$2.87      |
| Part  | HOSE CLAMP  | G710            | 2.00  | \$0.83      | \$1.66      |
| Part  | GLOSS BLACK   | E-117           | 2.00  | \$15.25     | \$30.50     |
| Part  | OIL FILTER  | P550428         | 1.00  | \$23.44     | \$23.44     |
| Part  | FUEL FILTER   | P550880         | 1.00  | \$34.13     | \$34.13     |
| Part  | FUEL WATER SEPARATOR  | P551103         | 1.00  | \$63.03     | \$63.03     |
| Part  | RAD CAP   | 1006-15         | 1.00  | \$17.48     | \$17.48     |
| Part  | 3/8 DRAINCOCK   | V14-1600-06     | 1.00  | \$10.27     | \$10.27     |
| Part  | BATTERY   | 31S-1300        | 3.00  | \$185.69    | \$557.07    |
| Part  | METAL POLISH  | 1000            | 1.00  | \$14.48     | \$14.48     |
| Part  | 15W40 OIL - BULK  | 66GFEC1540B     | 16.00 | \$6.78      | \$108.48    |
| Part  | BULK ELC 50/50 COOLANT  | 227811928       | 32.00 | \$3.84      | \$122.88    |
| Part  | TURN SIGNAL SWITCH  | TL30450         | 1.00  | \$95.55     | \$95.55     |
| Part  | MISC SHIPPING CHARGES   | FRT             | 1.00  | \$48.63     | \$48.63     |
| Labor | 2 HOURS SHOP RATE   |                 |       | \$170.00    | \$340.00    |
|       | DIAGNOSE OIL IN WATER. PRESSURE TEST SYSTEM. TEST FOR HEAD GASKET. #6 CYL HAS KNOCK. INJECTOR DOES CUT. NO SMOKE BUT ENGINE STEAMS                |                 |       |             |             |
| Labor | 4 HOURS SHOP RATE   |                 |       | \$170.00    | \$680.00    |
|       | REMOVE INTAKE, EGR COOLER AND OIL COOLER. PRESSURE TEST - BOTH PASSED. DROP OIL PAN AND REMOVE #6 PISTON COOLING NOZZLE - OK. REMOVE #6 INJECTOR. |                 |       |             |             |
| Labor | 15 HOURS SHOP RATE  |                 |       | \$170.00    | \$2,550.00  |
|       | REMOVE RADIATOR. DISCONNECT AND REMOVE ENGINE.  |                 |       |             |             |

| Type                                 | Description   | Part # | Qty | Sale/Rate | Total         |
|--------------------------------------|---|--------|-----|-----------|---------------|
| <b>6 HOURS SHOP RATE [Continued]</b> |   |        |     |           | <b>\$0.00</b> |
|                                      | DISSEMBLE AND DO REPORT.  |        |     |           |               |
| Labor                                | 6 HOURS SHOP RATE<br>REMOVE TRANS/ CLEAN TRANS, CLEAN AND ORGANIZE PARTS  |        |     | \$170.00  | \$1,020.00    |
| Labor                                | 1 HOUR SHOP RATE<br>CLEAN SURFACES. REMOVE AND CLEAN VALVES   |        |     | \$170.00  | \$170.00      |
| Labor                                | 6.5 HOURS SHOP RATE<br>LAP VALVES. WASH AND DRY CYLINDER HEAD. ASSEMBLE AND<br>PRESSURE TEST. MOVE ENGINE AND BEGIN TO STRIP. CLEAN<br>PARTS.                         |        |     | \$170.00  | \$1,105.00    |
| Labor                                | 4.5 HOURS SHOP RATE<br>FINISH CLEANING PARTS. MATCH UP CYLINDER BLOCK AND<br>PACKAGE CORE,  |        |     | \$170.00  | \$765.00      |
| Labor                                | 5 HOURS SHOP RATE<br>ASSEMBLE   |        |     | \$170.00  | \$850.00      |
| Labor                                | 1.5 HOURS SHOP RATE<br>INSTALL FUEL INJECTORS AND ROCKER GEAR. ADJUST VALVES.   |        |     | \$170.00  | \$255.00      |
| Labor                                | 7.5 HOURS SHOP RATE<br>ASSEMBLE.  |        |     | \$170.00  | \$1,275.00    |
| Labor                                | 13 HOURS SHOP RATE<br>INSTALL ENGINE AND TRANSMISSION. CONNECT RAD HOSES, FAN<br>AND SHROUD.  |        |     | \$170.00  | \$2,210.00    |
| Sublet                               | MAC EXHAUST<br>FABRICATE EXHAUST PIPE   |        |     | \$250.00  | \$250.00      |
| Labor                                | 13 HOURS SHOP RATE<br>FINISH INSTALL. ADD OIL. RUN AND CHECK. ORDER OIL PRESSURE<br>SWITCH. FLUSH COOLING SYSTEM. ADD COOLANT. CHANGE FUEL<br>FILTER. TOUCH UP PAINT. |        |     | \$170.00  | \$2,210.00    |
| Labor                                | 10 HOURS SHOP RATE<br>CHANGE OIL SWITCH. REPLACE BATTERIES. ADAPT BATTERY BOX.<br>POLISH CHROME. CLEAN CAB. ROAD TEST.  |        |     | \$170.00  | \$1,700.00    |
| Labor                                | 8 HOURS SHOP RATE<br>PICK UP PART FROM KENWORTH. REPLACE TURN SIGNAL SWITCH.<br>DIAGNOSE ELECTRICAL ISSUE. POLISH TRUCK.  |        |     | \$170.00  | \$1,360.00    |
| Sublet                               | SUBLET  |        |     |           |               |

### Tax Breakdown

|     |            |
|-----|------------|
| GST | \$1,879.47 |
| PST | \$2,631.26 |

Indebtedness in the amount shown above is acknowledged. Interest at .066% per day (24% per annum) charged on all outstanding balances. All credit card payments will be subject to an additional 2.5% charge. Terms & conditions on reverse of this page have been read & agreed. KNW is not responsible for loss or damage to customer's property from fire, theft, or any other cause.

|                     |                  |
|---------------------|------------------|
| Labor               | \$16,490.00      |
| Parts               | \$20,849.49      |
| <b>Subtotal</b>     | <b>\$250.00</b>  |
| Taxes               | \$4510.13        |
| <b>Order Total:</b> | <b>42,099.62</b> |

Signature \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_