109-3208 8TH AVE NE CALGARY, AB

P: 403-973-0009

F: 403-457-0012



FF08-4

Invoice

Date	Invoice #		
2025-08-08	21348		

Invoice To

FRANCIS LOGISTICS LTD

VEHICLE INFORMATION

2012 JEEP PATRIOT 4WD 2.4L VIN:1C4NJRAB3CD717318 KM:160 659 L/P:CMM-6115

Quantity	Item	Description	Price Each	Amount
8.5	LABOUR	REMOVED AND REPLACED CLUTCH KIT AND FLEX PLATE. Removed engine cover. Released fasteners holding the engine air-box to the front crossmember. Separated engine air-box from the vehicle. Removed battery form the vehicle. Removed battery tray from the vehicle. Removed air box lid and position it out of the way. Loosened engine inlet air tube clamp. Removed lower air cleaner body. Removed bolts and nuts holding the lower air cleaner bracket to the left frame rail. Separated lower air cleaner bracket from the vehicle. Unplugged speed sensor connector. Disconnected back-up lamp switch connector. Removed shift cable-to-bracket clips. Disconnected shift selector and crossover cable from levers. Remove cables and secure out of the way. Removed slave cylinder hose at bracket. Removed air inlet tube by loosing the screw at the throttle body. Removed throttle body support bracket bolts. Removed upper bell housing bolts. Removed starter bolts and slide the starter back. Supported transmission and loosen the left/upper	btotal	1,469.48

Sales Tax Summary

X

I accept the charges and term of this agreement.

AMVIC
ALBERTA MOTOR VEHICLE
INDISTRY COUNCIL

GST/HST No.

841146251

Total

Invoice

109-3208 8TH AVE NE CALGARY, AB

P: 403-973-0009

F: 403-457-0012



Date		Invoice #	
	2025-08-08	21348	

Invoice To 20	VEHICLE INFORMATION
RANCIS LOGISTICS LTD	2012 JEEP PATRIOT 4WD 2.4L VIN:1C4NJRAB3CD717318 KM:160 659 L/P:CMM-6115

Quantity	Item	Description	Price Each	Amount
		transmission mount through bolt. Removed transmission mount bolts. Raised vehicle on hoist. Removed splash shields. Removed transaxle oil drain plug and drain oil. Removed both axle halfshafts. Removed PTU. Supported engine with a screw jack and the transmission with a transmission jack. Removed bell housing dust cover. Removed four modular clutch-to-drive plate bolts. While removing bolts, one tight-tolerance (slotted) drive plate hole will be encountered. When this bolt is removed, mark drive plate and modular clutch assembly at this location. Be sure to align marks upon reassembly. Removed front transmission mount through bolt. Removed transmission crossmember mounting bolts. Removed rear transmission through bolt. Removed rear transmission mount bolts and mount from the frame. Removed rear transmission mount bracket bolts and bracket from transmission. Removed remaining transmission bell housing bolts. Carefully lower engine and transaxle on screw jack and transmission jack until proper removal clearance is obtain until Removed transaxle and engine support bracket from vehicle.	btotal	

Removed remaining transmission bell housing bolts.
Carefully lower engine and transaxle on screw jack and transmission jack until proper removal clearance is obtain transmission jack until proper removal clearance is

Invoice

109-3208 8TH AVE NE CALGARY, AB

P: 403-973-0009

F: 403-457-0012



Date	Invoice #		
2025-08-08	21348		

Invoice To

FRANCIS LOGISTICS LTD

VEHICLE INFORMATION

2012 JEEP PATRIOT 4WD 2.4L VIN:1C4NJRAB3CD717318 KM:160 659 L/P:CMM-6115

Quantity	Item	Description	Price Each	Amount
1 1 3 1	PART PART PART PART SERVICE1 ALIGNMENT SUV ADVANCE FORM Torque wheel SHOPSUP	Removed clutch module from transaxle input shaft. Installed in reverse order. Filled transmission and filled and bleed clutch. 1105173 CLUTCH KIT 4736238AA PLATE (OEM) 4002M ATF FLUID SYN M-0051 80W90 GEAR OIL TINT BOTH FRONT WINDOWS 4 WHEEL ALIGNMENT (MINIVAN/SUV) 313 ADVANCE FORMULA B/K Torque wheel lug nuts to 100ft-lbs *** YOUR WHEELS MUST BE RE-TORQUED AT THE EARLIER OF THE NEXT BUSINESS DAY OR 50KMS FROM THE TIME OF SERVICE. FAILURE TO DO SO COULD RESULT IN DAMAGE TO YOUR VEHICLE OR INJURY** SHOP SUPPLIES will be billed to all repairs to cover partial use of cleaners, degreasers, environmental disposals and other items that are required to complete YOUR repairsIMPORTANT- ALL WHEELS WILL BE RETORQUED TO ITS MANUFACTURES SPECIFICATION IF WHEELS HAVE BEEN REMOVED FOR SERVICE. THANK YOU FOR HAVING YOUR VEHICLE SERVICED AT A&C STARTEK AUTO	948.25 155.00 30.15 20.03 200.00 165.00 6.49	948.25 155.00 90.45 20.03 200.00 165.00 6.49
		Su	btotal	\$3,174.70

I authorize the above repairs and necessary materials. Your employees may operate vehicle for inspection, testing, delivery at my risk. A&C Startek Auto will not be responsible for loss or damage to vehicle or items left in it. Labour is guaranteed 90 days or 5000km whichever occurs first. Warranty is not transferable. All other guarantees are made by the manufacturer. Warranty work based on this bill must be performed at this shop

X.....

I accept the charges and term of this agreement.

AMVIC
ALBERTA MOTOR VEHICLE
INDUSTRY COUNCIL

Sales Tax Summary

GST@5.0%

158.74

Total Tax

158.74

GST/HST No.

841146251

Total

\$3,333.44