Sold to:

Customer Acct # 00-001476

Estate of Don Paulow Box 457 Hafford SK S0J 1A0

PartNumber	Description	Quantity	Unit Cost	Total
	2014 Wilson trailer			
Labour	Labour	1.50	190.00	285.00
	Inspection			
Labour	Labour	1.30	190.00	247.00
	Replaced license plate light wired in, replaced four side marker lights, th glad-hand seal	ree rear tail ligh	ts replaced	
12012	GLADHAND SEAL	1.00	0.84	0.84
43970	rectangular lamp bracket	1.00	5.60	5.60
15208	LICENSE PLATE LAMP	1.00	4.34	4.34
53250	light 10 diode clear lens shines red 4" round	3.00	36.32	108.96
43253	BRACKET-M	1.00	8.30	8.30
Freight		1.00	21.00	21.00

Retorque wheel nuts at 100 km	Sub Total	\$681.04
	Shop Supplies	\$45.00
Thank You!	PST 6%	\$43.56
We appreciate your business!	GST 5%	\$36.30
	Total	\$805.90
	Paid	\$0.00
	Balance	\$805.90