

B35-1
AUG

Sunset Diesel Service Ltd
10701-184 Street
Edmonton, AB
T5S 2T2
(780) 455-1171

INVOICE

INVOICE # 38384

DATE: 02/06/2026

Page 1 of 1

PG#

PMD Trucking Ltd.
Box 401
Seba Beach AB T0E 2B0

Unit No.
Make / Year Cat 1998
Serial No.
Mileage
License No.
Eng. Serial No. 1LW26696

Description	Part Number	Ordered	Shipped	Price	Total Tax
Supply two injectors as per request					
Ex Reman Inj C15	10R0501N	2.00	2.00	749.00	1,498.00
Core Charge	10R0501N	2.00	2.00	500.00	1,000.00
INJECTOR WARRANTY DISCLAIMER	WD 100	1.00	1.00	0.00	0.00

Injector[s] have a 1-year warranty from date of purchase. Warranty covers failure of ~~removal of fuel~~ **workmanship only**. Warranty does NOT cover failure and/or damage from Improper installation, Contamination In Fuel or Any Other External Influences. It is the technician's responsibility to conduct thorough inspection and cleaning of the fuel system on the engine prior to installation of replacement injector[s] to prevent premature/non-warrantable injector failure. **NUMBER ONE CAUSE OF INJECTOR FAILURE IS CONTAMINATED FUEL**. In the event of injector failure while it is still inside the warranty period it is the purchaser's responsibility to first fill out Sunset Diesel Warranty form and then return suspect injector for warranty inspection by Sunset Diesel Service Ltd. Sunset Diesel will NOT process any claim without the warranty form being filled out completely. Purchaser is not to return any/all injectors for Sunset Diesel to determine which one is faulty unless the purchaser is willing to pay Sunset Diesel for diagnostic time in that regard. Should failure of injector[s] be deemed warrantable, only the failed one[s] will be covered. Any additional injector[s] brought in for testing/diagnosis that are found to be OK will have a charge associated with them.

X _____, I hereby acknowledge that I agree with the above statement

GST Number R109185685

I/We hereby acknowledge the indebtedness of this invoice. If the balance due is not paid within Sunset Diesel's credit terms, I agree to pay interest at the rate of 3% per month. Any parts returned that were supplied as ordered maybe subject to a 25% restocking charge. In-house credit only on parts returned in 31-60 days. Any credit issued for warranty returns where replacement part from Sunset Diesel Service Ltd is not accepted will result in account credit only.

Account Terms - Net 30 Days.

Storage charges \$75 per day.

Cores must be returned within 90 days.

Please refer to full warranty policy at: <https://www.sunsetdiesel.ca/SDWP.pdf>

Sub Total	\$2,498.00
GST 5%	\$124.90
Total	\$2,622.90
Balance	\$2,622.90

DATE Feb 6/26 SIGNATURE