

South City Truck Centre Ltd
8625 68 st se
Calgary, ALBERTA. T2C-2R6
(403) 271-2474 Fax: (403) 271-0045
Writer: CORY SPARROW



FE16-1
INVOICE # 28040

southcity@telus.net

GST# 800957946

CITY WIDE RADIATOR	YEAR:	2020	TRANS/DRIVE:	NO DATA/NO DATA
	MAKE/MODEL:	FREIGHTLINER CASCADIA	LICENSE/STATE:	NO PLATE /ALBERTA
	VIN:	3AKJHHDV5LSLT7927	KM'S IN/KM'S OUT:	850000/
	ENGINE:	NO DATA		

In: 3/6/2025 Out: 3/29/2025 Engine Hours Email:

VEHICLE ISSUE #1: CVIP				
TECH REPORT: PERFORMED CVIP.				
JOB:	CVIP	1 @ \$200.00	\$200.00	NEW
Total for "CVIP ": \$200.00				
VEHICLE ISSUE #2: REAR LEFT SIDE MARKER LIGHT NOT WORKING, REPAIR BACK UP ALAM AND NEEDS TO BE SECURED				
TECH REPORT: REPAIR RUBBED WIRES TO THE LAMP AND BACK UP LAMP.				
PART	BUTT CONNECTOR	6 @ \$0.70	\$4.20	NEW
PART	18G SHRINK TUBE	6 @ \$0.90	\$5.40	NEW
PART	ZIP TIE	8 @ \$0.63	\$5.04	NEW
LABOR: TOOR, LA	LABOR	2 hours	\$180.00	LABOR
Total for "REAR LEFT SIDE MARKER LIGHT NOT WORKING, REPAIR BACK UP ALAM AND NEEDS TO BE SECURED ": \$194.64				
VEHICLE ISSUE #3: REPLACE ALL BATTERIES				
TECH REPORT: R/R ALL BATTERIES.				
PART	BATTERY	4 @ \$139.15	\$556.60	NEW
LABOR: TOOR, LA	LABOR	1 hours	\$90.00	LABOR
Total for "REPLACE ALL BATTERIES": \$646.60				
VEHICLE ISSUE #4: CHECK AND REPAIR FOR FRONT R/S BRAKE POT LEAKING				
TECH REPORT: R/R BRAKE POT.				
PART	BRAKE POT	1 @ \$76.95	\$76.95	NEW
LABOR: TOOR, LA	LABOR	1 hours	\$90.00	LABOR
Total for "CHECK AND REPAIR FOR FRONT R/S BRAKE POT LEAKING ": \$166.95				
VEHICLE ISSUE #5: SECURE BOTH SIDE HOOD STRAPS				
TECH REPORT: SECURE BOTH SIDE HOOD STRAPS.				
LABOR: TOOR, LA	LABOR	0.5 hours	\$45.00	LABOR
Total for "SECURE BOTH SIDE HOOD STRAPS": \$45.00				
VEHICLE ISSUE #6: REPLACE ALL DRIVE AXLE SHOCKS.				
TECH REPORT: R/R ALL DRIVE AXLE SHOCKS.				
PART	SHOCK ABSORBER- DRIVE	4 @ \$67.43	\$269.72	NEW
LABOR: TOOR, LA	LABOR	2 hours	\$180.00	LABOR

Recommended Repairs: Warranty: From the date of delivery for a period of [12] months or [160,000] kilometers, whichever comes first, this firm will repair free of charge, not including applicable taxes, fees and non warranty associated parts, any defects in materials and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties. South City Truck Centre will only be liable and responsible for Warranty repairs performed and managed by South City Truck Centre . If the customer has a failure of any component installed and or guaranteed by South City Truck Centre but does not make initial contact before any authorization is given for repair, The customer is	Labor/Jobs	\$4,015.00
	Parts	\$4,058.83
	Sublet	\$0.00
	Total Fees	\$173.25
	Subtotal	\$8,247.08
	Tax @ 5%	\$412.35
	Total	\$8,659.43
	Payments	\$0.00
	Balance	\$8,659.43

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 3/29/2025

South City Truck Centre Ltd
8625 68 st se
Calgary, ALBERTA. T2C-2R6
(403) 271-2474 Fax: (403) 271-0045
Writer: CORY SPARROW



INVOICE # 28040

southcity@telus.net

GST# 800957946

CITY WIDE RADIATOR	YEAR:	2020	TRANS/DRIVE:	NO DATA/NO DATA
	MAKE/MODEL:	FREIGHTLINER CASCADIA	LICENSE/STATE:	NO PLATE /ALBERTA
	VIN:	3AKJHHDV5LSLT7927	KM'S IN/KM'S OUT:	850000/
	ENGINE:	NO DATA		

Total for "REPLACE ALL DRIVE AXLE SHOCKS.": \$449.72				
VEHICLE ISSUE #7: REPLACE ALL DRIVE AXLE BUSHINGS				
TECH REPORT: R/R ALL DRIVE AXLE BUSHINGS.				
PART	POLY AIRLINER BUSHING (RB268) ATRO	4 @ \$116.11	\$464.44	NEW
LABOR: TOOR, LA	LABOR	8 hours	\$720.00	LABOR
Total for "REPLACE ALL DRIVE AXLE BUSHINGS ": \$1,184.44				
VEHICLE ISSUE #8: INSTALL BOTH SIDE REAR AXLE CAGING BOLTS MISSING				
TECH REPORT: INSTALL NEW CAGING BOLTS.				
PART	CAGING BOLT	2 @ \$8.70	\$17.40	NEW
Total for "INSTALL BOTH SIDE REAR AXLE CAGING BOLTS MISSING ": \$17.40				
VEHICLE ISSUE #9: REPLACE STEADY BEARING				
TECH REPORT: R/R STEADY BEARING.				
PART	SELF-ALIGNING CENTER BEARING	1 @ \$128.26	\$128.26	NEW
PART	NUT	1 @ \$12.55	\$12.55	NEW
PART	WASHER-RETAINER	1 @ \$4.76	\$4.76	NEW
LABOR: TOOR, LA	LABOR	2.5 hours	\$225.00	LABOR
Total for "REPLACE STEADY BEARING ": \$370.57				
VEHICLE ISSUE #10: REPLACE BOTH SIDE KING PINS, AND REPLACE STEERING AXLE BOTH SIDE BRAKES AND DRUMS.				
TECH REPORT: R/R BOTH SIDE KING PINS, INSTALL NEW WHEEL SEAL, INSTALL NEW BRAKES AND DRUMS.				
PART	BRAKE SHOE KIT- STEER	2 @ \$107.94	\$215.88	NEW
PART	BRAKE DRUM DOUBLE PILOT	2 @ \$229.70	\$459.40	NEW
PART	KIN PIN KIT	1 @ \$397.76	\$397.76	NEW
PART	WHEEL SEAL- S/A	1 @ \$47.84	\$47.84	NEW
PART	HUB CAP GASKET	2 @ \$4.07	\$8.14	NEW
PART	HUB OIL	2 @ \$15.38	\$30.76	NEW
LABOR: TOOR, LA	LABOR	10 hours	\$900.00	LABOR
Total for "REPLACE BOTH SIDE KING PINS, AND REPLACE STEERING AXLE BOTH SIDE BRAKES AND DRUMS.": \$2,059.78				
VEHICLE ISSUE #11: REPLACE FIFTH WHEEL PINS AND BUSHING KIT				
TECH REPORT: R/R FIFTH WHEELS PINS AND BUSHING KIT.				
PART	PIN/BUSHING KIT	1 @ \$78.25	\$78.25	NEW

Recommended Repairs: Warranty: From the date of delivery for a period of [12] months or [160,000] kilometers, whichever comes first, this firm will repair free of charge, not including applicable taxes, fees and non warranty associated parts, any defects in materials and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties. South City Truck Centre will only be liable and responsible for Warranty repairs performed and managed by South City Truck Centre . If the customer has a failure of any component installed and or guaranteed by South City Truck Centre but does not make initial contact before any authorization is given for repair, The customer is	Labor/Jobs	\$4,015.00
	Parts	\$4,058.83
	Sublet	\$0.00
	Total Fees	\$173.25
	Subtotal	\$8,247.08
	Tax @ 5%	\$412.35
	Total	\$8,659.43
	Payments	\$0.00
	Balance	\$8,659.43

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 3/29/2025

South City Truck Centre Ltd
8625 68 st se
Calgary, ALBERTA. T2C-2R6
(403) 271-2474 Fax: (403) 271-0045
Writer: CORY SPARROW



INVOICE # 28040

southcity@telus.net

GST# 800957946

CITY WIDE RADIATOR	YEAR:	2020	TRANS/DRIVE:	NO DATA/NO DATA
	MAKE/MODEL:	FREIGHTLINER CASCADIA	LICENSE/STATE:	NO PLATE /ALBERTA
	VIN:	3AKJHHDV5LSLT7927	KM'S IN/KM'S OUT:	850000/
	ENGINE:	NO DATA		

PART	POCKET INSTERKIT HOLLAND	1 @ \$45.20	\$45.20	NEW
LABOR: TOOR, LA	LABOR	1.5 hours	\$135.00	LABOR
Total for "REPLACE FIFTH WHEEL PINS AND BUSHING KIT ": \$258.45				
VEHICLE ISSUE #12: REPLACE ALL DRIVE AXLE WHEEL SEALS AND REPLACE FRONT DRIVE AXLE BOTH SIDE BRAKES AND DRUMS				
PART	WHEEL SEAL- D/A	4 @ \$57.54	\$230.16	NEW
PART	AXLE GASKET 8 HOLE 3/4 "	4 @ \$4.06	\$16.24	NEW
PART	HUB OIL PER LITER	6 @ \$11.50	\$69.00	NEW
PART	BRAKE CLEAN	4 @ \$5.87	\$23.48	NEW
PART	BRAKE SHOE KIT W/HDW 16.5 X 8.625 Q PLUS	2 @ \$122.14	\$244.28	NEW
PART	BRAKE DRUMS 16.500IN X7.00IN 3600A	2 @ \$212.50	\$425.00	NEW
LABOR: TOOR, LA	LABOR	8 hours	\$720.00	LABOR
Total for "REPLACE ALL DRIVE AXLE WHEEL SEALS AND REPLACE FRONT DRIVE AXLE BOTH SIDE BRAKES AND DRUMS ": \$1,728.16				
VEHICLE ISSUE #13: FRONT DRIVE AXLE INSIDE RIM CRACKED				
TECH REPORT: CHANGE OVER TIRE AND INSTALL USED RIM FROM THE SHOP.				
PART	WHEEL RIM	1 @ \$100.00	\$100.00	NEW
LABOR: TOOR, LA	LABOR	1 hours	\$90.00	LABOR
Total for "FRONT DRIVE AXLE INSIDE RIM CRACKED ": \$190.00				
VEHICLE ISSUE #14: REPLACE REAR AXLE LEFT SIDE AIR BAG				
TECH REPORT: R/R AIR BAG.				
PART	AIR BAG- D/A	1 @ \$122.12	\$122.12	NEW
LABOR: TOOR, LA	LABOR	1 hours	\$90.00	LABOR
Total for "REPLACE REAR AXLE LEFT SIDE AIR BAG": \$212.12				
VEHICLE ISSUE #15: ALIGNMENT				
TECH REPORT: PERFORMED THREE AXLE ALIGNMENT AND MADE ALL ADJUSTMENTS.				
JOB:	ALIGNMENT	1 @ \$350.00	\$350.00	NEW
				Total for "ALIGNMENT": \$350.00
				SHOP SUPPLIES@ 5% : \$173.25

Recommended Repairs: Warranty: From the date of delivery for a period of [12] months or [160,000] kilometers, whichever comes first, this firm will repair free of charge, not including applicable taxes, fees and non warranty associated parts, any defects in materials and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties. South City Truck Centre will only be liable and responsible for Warranty repairs performed and managed by South City Truck Centre . If the customer has a failure of any component installed and or guaranteed by South City Truck Centre but does not make initial contact before any authorization is given for repair, The customer is	Labor/Jobs	\$4,015.00
	Parts	\$4,058.83
	Sublet	\$0.00
	Total Fees	\$173.25
	Subtotal	\$8,247.08
	Tax @ 5%	\$412.35
	Total	\$8,659.43
	Payments	\$0.00
	Balance	\$8,659.43

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 3/29/2025