

G. FORCE DIESEL SERVICE L

BOX 1040
4403 - 37 AVE
LLOYDMINSTER, SK, S9V 1E9
Phone: (306) 825-2875
Fax: (306) 825-3246



Invoice

Date
Mar 23, 2026

Page
1

Invoice Number
IN0096752

Sold To:

CASH SALE -

CASH SALE

Ship To:

CASH SALE

Order No. ORD099973	Order Date Feb 25, 2026	Truck: 101056947 SK LTD. - 1997 W.STAR 276680KM Serial # 2WKPDDCU9VK946152	PO Number
------------------------	----------------------------	---	-----------

Qty. Ord.	Qty. B/O	Qty. Shp.	Item Number	Description	Unit Price	UOM	Price
1.0	0.0	1.0	SAFETY	TRUCK SAFETY INSPECTION (SK) *WHEELS OFF - NEEDS SUSPENSION WORK - CALL W/ LIST *NOTES: 1. WORK LIGHTS NOT WORKING	450.00	EA	450.00
0.3	0.0	0.3	LAB	SECURE FIRE EXTINGUISHER IN BUNK *WRONG SIZED BRACKET* ~ REPLACED EXTINGUISHER & CLAMP	149.00	HR	44.70
1.0	0.0	1.0	LAB	REPAIR RHS WINDOW NOT ROLLING UP ~ REMOVED PANEL, LUBRICATED WINDOW SLIDE/RAIL ~ TESTED & REASSEMBLED	149.00	HR	149.00
0.8	0.0	0.8	LAB	REPAIR RHS WINDSHIELD WASHER NOT SPRAYING ~ TROUBLESHOOT SYSTEM - PUMP FAILURE - REPLACED PUMP ~ RHS STILL NOT SPRAYING - TROUBLESHOOT FURTHER ~ FOUND DAMAGED LINE - REPAIRED & TESTED - GOOD	149.00	HR	119.20
0.5	0.0	0.5	LAB	REPAIR SEVERAL GAUGE LIGHTS OUT ~ INSTALLED NEW LIGHTS ON 3 GAUGES	149.00	HR	74.50
0.2	0.0	0.2	LAB	REPLACE WIPER BLADES *TORN*	149.00	HR	29.80
2.0	0.0	2.0	LAB	REPAIR TAILLIGHTS NOT WORKING *NO REAR SIGNALS OR BRAKE LIGHTS* ~ CHECKED OVER WIRING - PLUG IS BROKEN & CORRODED ~ REPLACED PLUG & REWIRED - STILL NOT WORKING ~ REPLACED SIGNAL STAT & TESTED	149.00	HR	298.00
0.3	0.0	0.3	LAB	REPAIR RHS SKIRT LIGHT OUT ~ REPLACED LIGHT	149.00	HR	44.70
2.0	0.0	2.0	LAB	REPAIR NO REVERSE LIGHT & ALARM ~ INSTALLED NEW REVERSE LIGHT & PIGTAIL ~ REPLACED REVERSE SWITCH IN TRANSMISSION	149.00	HR	298.00
0.3	0.0	0.3	LAB	REPAIR HEADLIGHTS *ONE LED & ONE HALOGEN* ~ INSTALLED LED ON RHS LOW BEAM TO MATCH LHS	149.00	HR	44.70

Vehicles with emission deletes or tunes will void engine warranty.
All parts & cores must be returned within 30 days to receive credit.
Warranty credits are issued when G Force Diesel receives credit from the manufacturer.

Interest of 3% (36% Per Annum) On Overdue Accounts!!

Invoice continued on next page ...

CASH

Sask E & H Tax

G. FORCE DIESEL SERVICE L

BOX 1040
4403 - 37 AVE
LLOYDMINSTER, SK, S9V 1E9
Phone: (306) 825-2875
Fax: (306) 825-3246



Invoice

Date	Page
Mar 23, 2026	2
Invoice Number IN0096752	

Sold To:

CASH SALE - [REDACTED]

CASH SALE

Ship To:

CASH SALE

Order No. ORD099973	Order Date Feb 25, 2026	Truck: 101056947 SK LTD. - 1997 W.STAR 276680KM Serial # 2WKPDDCU9VK946152 [REDACTED]	PO Number
------------------------	----------------------------	--	-----------

Qty. Ord.	Qty. B/O	Qty. Shp.	Item Number	Description	Unit Price	UOM	Price
0.1	0.0	0.1	LAB	REPLACE LHS HOOD CABLE "FRAYED"	149.00	HR	14.90
0.5	0.0	0.5	LAB	REPLACE CAB SHOCKS	149.00	HR	74.50
5.0	0.0	5.0	LAB	REPLACE REAR AIRBAGS ~ CUT OFF TOP BRACKET BOLTS, DISCONNECTED AIRLINES & CLEANED BASE ~ MODIFY BOTTOM BASE & UPPER BRACKET ~ INSTALLED NEW AIRBAGS	149.00	HR	745.00
0.5	0.0	0.5	LAB	REPLACE AXLE #3 LATERAL TORQUE ARM BUSHINGS ~ REPLACED TORQUE ARM ASSEMBLY	149.00	HR	74.50
1.0	0.0	1.0	LAB	REPAIR AXLE #3 LHS LIMITING CHAIN BRACKET "CRACKED @ WELD" ~ CLEANED & WELDED ~ REMOVED TOP & BOTTOM BOLTS OF LIMITING BRACKETS ~ INSTALLED NEW BOLTS/NUTS & NEW LIMITING CHAIN	149.00	HR	149.00
6.0	0.0	6.0	LAB	REPLACE FRONT & REAR ENGINE MOUNT BUSHINGS	149.00	HR	894.00
6.0	0.0	6.0	LAB	REPLACE AXLE #2 WHEEL SEALS ~ REPLACED WHEEL SEALS ~ REPLACED LHS SHOES	149.00	HR	894.00
2.0	0.0	2.0	LAB	REPAIR AXLE #2 DIFF LEAKING EXCESSIVELY ~ REMOVED CARRIER, CLEANED SURFACES, & RESEALED ~ REASSEMBLED & TOPPED UP OIL	149.00	HR	298.00
1.0	0.0	1.0	LAB	REPLACE ALL 4 REAR SHOCKS	149.00	HR	149.00
0.0	0.0	0.0	LAB	REPLACE BOTH GLADHANDS ~ DONE W/ SAFETY	149.00	HR	0.00
0.3	0.0	0.3	LAB	REPLACE AXLE #1 LHS HUBCAP LENS ~ REPLACED & TOPPED UP OIL	149.00	HR	44.70
0.1	0.0	0.1	LAB	REPAIR HIGH BEAM INDICATOR NOT WORKING ~ REPLACED BULB FOR INDICATOR	149.00	HR	14.90

Vehicles with emission deletes or tunes will void engine warranty.
All parts & cores must be returned within 30 days to receive credit.
Warranty credits are issued when G Force Diesel receives credit from the manufacturer.

Interest of 3% (36% Per Annum) On Overdue Accounts!!

Sask E & H Tax

Invoice continued on next page ...

CASH

G. FORCE DIESEL SERVICE L'

BOX 1040
4403 - 37 AVE
LLOYDMINSTER, SK, S9V 1E9
Phone: (306) 825-2875
Fax: (306) 825-3246

**Invoice**

Date
Mar 23, 2026

Page
3

Invoice Number
IN0096752

Sold To:

CASH SALE [REDACTED]

CASH SALE

Ship To:

CASH SALE

Order No.	Order Date	Truck: 101056947 SK LTD. - 1997 W.STAR 276680KM	PO Number
ORD099973	Feb 25, 2026	Serial 12WKPDDCU9VK946152 [REDACTED]	

Qty. Ord.	Qty. B/O	Qty. Shp.	Item Number	Description	Unit Price	UOM	Price
0.3	0.0	0.3	LAB	INSTALL SILVER REFLECTORS @ REAR CAB CORNERS ~ CLEANED CAB CORNERS & INSTALLED REFLECTORS	149.00	HR	44.70
12.0	0.0	12.0	LAB	REPLACE AXLE #2 & #3 RHS SUSPENSION BUSHINGS "REPLACE ALL?" *AXLE #1 LHS SHOCK ALSO ~ CUT OFF SEIZED COMPONENTS & REPLACED AXLE BUSHINGS (#2 & #3) ~ REASSEMBLED & TORQUED	149.00	HR	1,788.00
0.5	0.0	0.5	LAB	REPLACE AXLE #1 SHOCKS	149.00	HR	74.50
0.3	0.0	0.3	LAB	REPAIR REAR CROSSMEMBER "CRACKED" ~ WELDED CRACK	149.00	HR	44.70
1.0	0.0	1.0	LAB	REPAIR FUEL TANK BOTTOM LINE BRACKET ~ REMOVED CORSS BRACKET & REPAIRED HOLES - EXTENDED ~ REINSTALLED BRACKET & SECURED FUEL LINE	149.00	HR	149.00
3.0	0.0	3.0	LAB	REPAIR 5TH WHEEL SLIDE "RUSTJACKED - FRAME BENT UNDER RAILS" ~ CUT ALL BOLTS & REMOVED 5TH WHEEL ASSEMBLY ~ CLEANED OUT DEBRIS & PAINTED FRAME ~ CLEANED & PAINTED RISER SLIDE ~ REINSTALLED	149.00	HR	447.00
0.3	0.0	0.3	LAB	REPLACE ALL V-BELTS	149.00	HR	44.70
0.1	0.0	0.1	LAB	REPAIR AXLE #2 LHS BRAKEPOT AIRLINE LEAK ~ TIGHTENED AIRLINE FITTING	149.00	HR	14.90
0.5	0.0	0.5	LAB	REPAIR 5TH WHEEL SLIDE LOCK CYLINDER "SEIZED - LOCKS NOT FULLY ENGAGED" - CYLINDER LEAKING THROUGH SHAFT ~ REPLACED CYLINDER	149.00	HR	74.50
1.5	0.0	1.5	LAB	REPLACE AXLE #3 RHS WHEEL SEAL	149.00	HR	223.50
0.3	0.0	0.3	LAB	REPAIR EXHAUST LEAK @ MUFFLER INLET ~ CUT & REPLACED EXHAUST CLAMP	149.00	HR	44.70

Vehicles with emission deletes or tunes will void engine warranty.
All parts & cores must be returned within 30 days to receive credit.
Warranty credits are issued when G Force Diesel receives credit from the manufacturer.

Interest of 3% (36% Per Annum) On Overdue Accounts!!

Sask E & H Tax

Invoice continued on next page ...

CASH

G. FORCE DIESEL SERVICE L

BOX 1040
4403 - 37 AVE
LLOYDMINSTER, SK, S9V 1E9
Phone: (306) 825-2875
Fax: (306) 825-3246



Invoice

Date	Page
Mar 23, 2026	4

Invoice Number
IN0096752

Sold To:

Ship To:

CASH SALE - [REDACTED]

CASH SALE

CASH SALE

Order No. ORD099973	Order Date Feb 25, 2026	Truck: 101056947 SK LTD. - 1997 W.STAR 276680KM Serial #2WKPDCCU9VK946152 [REDACTED]	PO Number
------------------------	----------------------------	---	-----------

Qty. Ord.	Qty. B/O	Qty. Shp.	Item Number	Description	Unit Price	UOM	Price
0.5	0.0	0.5	LAB	REPLACE REAR FUEL TANK STRAP RUBBER	149.00	HR	74.50
12.0	0.0	12.0	LAB	REPAIR BUNK STABILIZER LINKS BEHIND AIRBAGS ROTTED OUT OF UPPER MOUNTS ~ REMOVED BRACKETS & BUILT NEW ~ INSTALLED BRACKETS, AIRBAGS, SHOCKS, & STABILIZER LINK ROD ~ REINSTALLED STEPS	149.00	HR	1,788.00
0.0	0.0	0.0	LAB	INSPECT/ADJUST ALL TIRE PRESSURES & CHECK FOR LEAKS	149.00	HR	0.00
0.3	0.0	0.3	LAB	REPLACE CRACKED AXLE #1 BRAKE DRUM	149.00	HR	44.70
			SS	SHOP SUPPLIES			250.00
1.0	0.0	1.0	12006	GLADHAND-SERVICE - BLUE	4.50	EA	4.50
1.0	0.0	1.0	12008	EMERGENCY GLADHAND - RED	4.50	EA	4.50
2.0	0.0	2.0	60191	19" EXACT FIT WIPER BLADE	17.00	EA	34.00
6.0	0.0	6.0	96900	WEATHERPACK TERM FML	1.50	EA	9.00
6.0	0.0	6.0	96902	16-14GA WEATHERPACK TERM MLE	1.13	EA	6.78
12.0	0.0	12.0	96904	GREEN WEATHERPACK SEAL	1.13	EA	13.56
1.0	0.0	1.0	99254	WEATHERPACK TERM- TOWER	7.15	EA	7.15
1.0	0.0	1.0	99255	WEATHERPACK TERM- SHROUD	5.45	EA	5.45
3.0	0.0	3.0	15001	HEAT SHRINK #1	2.50	EA	7.50
1.0	0.0	1.0	122466296	2.5LB FIRE EXTINGUISHER	65.00	EA	65.00
1.0	0.0	1.0	NKM4707QMV23	NEW 16.5X7 ROCKWELL Q-PLUS BRAKE SHOES W/HARDWARE (NO CORE)	110.40	EA	110.40
3.0	0.0	3.0	3929131	STEMCO DRIVE AXLE WHEEL SEAL (2106)	84.55	EA	253.65
3.0	0.0	3.0	2001	BRAKE & PARTS CLEANER 390G	8.65	EA	25.95
4.0	0.0	4.0	94993	RIGHT ANGLE ST/T PIGTAIL	2.89	EA	11.56
2.0	0.0	2.0	62171	LAMP, TRSN MT LEXAN SLD, BACKUP	8.95	EA	17.90
1.0	0.0	1.0	877002	WIRE, BLACK, 14GA	0.45	FT	0.45
1.0	0.0	1.0	877007	WIRE, WHITE, 14GA	0.35	FT	0.35
1.0	0.0	1.0	877000	WIRE, RED, 14 GA,	0.45	FT	0.45
1.0	0.0	1.0	15003	HEAT SHRINK #3	3.38	EA	3.38
3.0	0.0	3.0	838003	1/4" WIRE LOOM (BY FOOT)	0.85	FT	2.55

Vehicles with emission deletes or tunes will void engine warranty.
All parts & cores must be returned within 30 days to receive credit.
Warranty credits are issued when G Force Diesel receives credit from the manufacturer.

Interest of 3% (36% Per Annum) On Overdue Accounts!!

Sask E & H Tax

Invoice continued on next page ...

CASH

G. FORCE DIESEL SERVICE L'

BOX 1040
4403 - 37 AVE
LLOYDMINSTER, SK, S9V 1E9
Phone: (306) 825-2875
Fax: (306) 825-3246



Invoice

Date	Page
Mar 23, 2026	5
Invoice Number	
IN0096752	

Sold To:

CASH SALE - [REDACTED]

CASH SALE

Ship To:

CASH SALE

Order No.	Order Date	Truck: 101056947 SK LTD. - 1997 W.STAR 276680KM	PO Number
ORD099973	Feb 25, 2026	Serial #2WKPDDCU9VK946152 [REDACTED]	

Qty. Ord.	Qty. B/O	Qty. Shp.	Item Number	Description	Unit Price	UOM	Price
1.0	0.0	1.0	561	MINIATURE LAMP 39746	3.05	EA	3.05
1.0	0.0	1.0	WWF	SUMMER WINDSHIELD WASHER FLUID (4L. JUG)	6.95	EA	6.95
1.0	0.0	1.0	066011A	WINDSHIELD WASHER PUMP	34.79	EA	34.79
2.0	0.0	2.0	66568240Y	SHOCK	92.35	EA	184.70
4.0	0.0	4.0	9009996	W.STAR TOP ENGINE MOUNT	29.85	EA	119.40
2.0	0.0	2.0	M80870NR	W.STAR REAR ENGINE MOUNT	21.50	EA	43.00
2.0	0.0	2.0	CB11252	FRONT ENGINE MOUNT	71.72	EA	143.44
1.0	0.0	1.0	A1719013000	CABLE HOOD STOP 1200MM	29.50	EA	29.50
1.0	0.0	1.0	432053411280	FUEL TANK STRAP ISOLATOR	50.65	EA	50.65
3.0	0.0	3.0	3303106	AXLE SHAFT GASKET 5/8 HOLE	4.35	EA	13.05
17.0	0.0	17.0	E5980	CONE WEDGE 5/8	2.25	EA	38.25
1.0	0.0	1.0	22940	REVERSE SWITCH/ W SCREW IN TERMINAL	31.81	EA	31.81
1.0	0.0	1.0	SSD5421	15" X 4" 10 HOLE STEER AXLE BRAKE DRUM	235.80	EA	235.80
2.0	0.0	2.0	129132	AXLE TANGD LOCK WASHER	7.95	EA	15.90
1.0	0.0	1.0	TMR527	22.5" TORQUE ROD WESTERN STAR	395.16	EA	395.16
4.0	0.0	4.0	A83635	SHOCK	95.35	EA	381.40
2.0	0.0	2.0	A83022	SHOCK	98.05	EA	196.10
4.0	0.0	4.0	TRB8165	PIVOT CONNECTING BUSHING	63.36	EA	253.44
6.0	0.0	6.0	TRB8172	AXLE CONNECTION BUSHING FRONT	141.35	EA	848.10
2.0	0.0	2.0	TRB8169	AXLE CONNECTION BUSHING REAR	195.79	EA	391.58
			FIN	FREIGHT INBOUND			80.00
1.0	0.0	1.0	3404024	STEMCO HUB CAP W/GASKET	75.87	EA	75.87
1.0	0.0	1.0	9807	5" LAP JOINT EXHAUST CLAMP	17.00	EA	17.00
2.0	0.0	2.0	259570	BELT	48.12	EA	96.24
2.0	0.0	2.0	2522625	W.STAR FAN DRIVE BELT	69.75	EA	139.50
1.0	0.0	1.0	TLEDH12	4" X 6" LED HEADLIGHT LOW BEAM	315.00	EA	315.00
20.0	0.0	20.0	78SNC	7/8" NC STOVER LOCKNUT	1.48	ea	29.60
20.0	0.0	20.0	78FL8	GR 8 FLAT WASHER /C	2.10	ea	42.00
1.0	0.0	1.0	X107B	FITTING	4.55	EA	4.55
1.0	0.0	1.0	918Y994	TURN SIGNAL SWITCH	98.50	EA	98.50
8.0	0.0	8.0	PC194CP	MINITURE BULB 14V	2.28	EA	18.24
16.0	0.0	16.0	NII	7/8" SUSPENSION BOLTS 12.5	27.50	ea	440.00

Vehicles with emission deletes or tunes will void engine warranty.
All parts & cores must be returned within 30 days to receive credit.
Warranty credits are issued when G Force Diesel receives credit from the manufacturer.

Interest of 3% (36% Per Annum) On Overdue Accounts!!

Invoice continued on next page ...

CASH

Sask E & H Tax

G. FORCE DIESEL SERVICE L'

BOX 1040
4403 - 37 AVE
LLOYDMINSTER, SK, S9V 1E9
Phone: (306) 825-2875
Fax: (306) 825-3246



Invoice

Date	Page
Mar 23, 2026	6

Invoice Number
IN0096752

Sold To:

CASH SALE - [REDACTED]

CASH SALE

Ship To:

CASH SALE

Order No. ORD099973	Order Date Feb 25, 2026	Truck: 101056947 SK LTD. - 1997 W.STAR 276680KM Serial 12WKPDDCU9VK946152 [REDACTED]	PO Number
------------------------	----------------------------	---	-----------

Qty. Ord.	Qty. B/O	Qty. Shp.	Item Number	Description	Unit Price	UOM	Price
4.0	0.0	4.0	NII	7/8" SUSPENSION BOLTS 7.5	7.50	ea	30.00
4.0	0.0	4.0	AB1DK23H8204	AIR SPRING ROLLING LOBE	116.99	EA	467.96
4.0	0.0	4.0	AB9375P	AIR SPRING BRACKET	27.75	EA	111.00
1.0	0.0	1.0	14626	UNION, 3/8	4.62	EA	4.62
1.0	0.0	1.0	14624	UNION, 1/4	3.50	EA	3.50
2.0	0.0	2.0	NII	7/16" SHACKLE ANCHOR	6.38	ea	12.76
1.0	0.0	1.0	XA11699B	HOLLAND 5TH WHEEL AIR CYLINDER	205.00	EA	205.00
1.0	0.0	1.0	3303106	AXLE SHAFT GASKET 5/8 HOLE	4.35	EA	4.35
7.0	0.0	7.0	75W90SYN	75W90 SYNTHETIC GL-5 GEAR OIL (Includes enviro fee's)	13.80	L	96.60
4.0	0.0	4.0	7006298	RADIATOR MOUNT BUSHING	29.50	EA	118.00
			FIN	FREIGHT INBOUND			35.00
1.0	0.0	1.0	NII	CUSTOM MADE BUNK BRACKETS	365.20	ea	365.20
1.0	0.0	1.0	34X312NC8	GR 8 CAPSCREW /C	3.12	EA	3.12
4.0	0.0	4.0	34FL8	3/4" GRADE 8 FLAT WASHER	0.58	EA	2.32
1.0	0.0	1.0	34SNC	3/4" NC STOVER LOCKNUT	1.20	EA	1.20
7.0	0.0	7.0	12SNC	1/2" NC STOVER LOCKNUT	0.65	EA	4.55
22.0	0.0	22.0	12FL8	1/2" NC GR 8 FLAT WASHER	0.30	EA	6.60
8.0	0.0	8.0	12L8	1/2" GRADE 8 LOCK WASHER	0.35	EA	2.80
3.0	0.0	3.0	12X4NC8	GR 8 CAPSCREW /C	1.72	EA	5.16
3.0	0.0	3.0	58X234NC8	5/8" x 2 3/4" GR 8 CAPSCREW	1.75	EA	5.25
40.0	0.0	40.0	58FL8	5/8" GR 8 FLAT WASHER	0.55	EA	22.00
1.0	0.0	1.0	58X234NC8	5/8" x 2 3/4" GR 8 CAPSCREW	1.75	EA	1.75
13.0	0.0	13.0	58X214NC8	5/8 x 2.25" GR 8 CAPSCREW NC	1.62	EA	21.06
14.0	0.0	14.0	58SNC	5/8" NC STOVER LOCKNUT	0.89	EA	12.46
1.2	0.0	1.2	FLA188 X 2	3/16" x 2" FLAT BAR	3.15	FT	3.78
2.0	0.0	2.0	516X114NC8	5/16" x 1 1/4" GR 8 NC CAPSCREW	0.30	EA	0.60
0.8	0.0	0.8	FLA250 X 6	1/4" X 6" FLAT BAR	12.00	FT	9.60

Comments:

Vehicles with emission deletes or tunes will void engine warranty.
All parts & cores must be returned within 30 days to receive credit.
Warranty credits are issued when G Force Diesel receives credit from the manufacturer.

Interest of 3% (36% Per Annum) On Overdue Accounts!!

Subtotal 16,925.39

GST# 873838528 846.27

Sask E & H Tax 0.00

CASH

Total amount 17,771.66